

Brocade[®] Fabric OS[®] Message Reference Manual, 9.0.x

Technical Reference Manual 30 April 2021

FOS-90x-Message-RM103 Broadcom

Copyright © 2020–2021 Broadcom. All Rights Reserved. Broadcom, the pulse logo, Brocade, the stylized B logo, and Fabric OS are among the trademarks of Broadcom in the United States, the EU, and/or other countries. The term "Broadcom" refers to Broadcom Inc. and/or its subsidiaries.

Broadcom reserves the right to make changes without further notice to any products or data herein to improve reliability, function, or design. Information furnished by Broadcom is believed to be accurate and reliable. However, Broadcom does not assume any liability arising out of the application or use of this information, nor the application or use of any product or circuit described herein, neither does it convey any license under its patent rights nor the rights of others.

The product described by this document may contain open source software covered by the GNU General Public License or other open source license agreements. To find out which open source software is included in Brocade products, to view the licensing terms applicable to the open source software, and to obtain a copy of the programming source code, please download the open source disclosure documents in the Broadcom Customer Support Portal (CSP). If you do not have a CSP account or are unable to log in, please contact your support provider for this information.

Table of Contents

Chap	pter 1: Introduction	14
1.1	About This Document	14
1.2	2 Supported Hardware and Software	14
	1.2.1 Brocade Gen 7 (64G) Fixed-Port Switches	14
	1.2.2 Brocade Gen 7 (64G) Directors	14
	1.2.3 Brocade Gen 6 (32G) Fixed-Port Switches	14
	1.2.4 Brocade Gen 6 (32G) Directors	14
1.3	3 Contacting Technical Support for Your Brocade® Product	14
1.4	Document Feedback	15
Chap	pter 2: Overview of System Messages	16
2.1	System Message Types	16
	2.1.1 Log Messages	16
	2.1.2 Audit Messages	16
	2.1.2.1 Audit Log Enhancements	17
	2.1.2.2 Audit Messages Related to SSH	19
	2.1.2.3 Audit Messages Related to TLS	19
	2.1.2.4 Audit Messages Related to Certificate Validation	20
	2.1.2.5 Audit Messages Related to When Unsecure Protocols Are Allowed or Secure Protocols Are Disabled	21
	2.1.3 FFDC Messages	21
2.2	2 Message Severity Levels	22
2.3	System Error Message Logging	22
2.4	Configuring Syslog Message Destinations	22
	2.4.1 System Logging Daemon	
	2.4.1.1 Configuring a Syslog Server	23
	2.4.2 System Console	
	2.4.2.1 Setting the System Console Severity Level	
	2.4.3 SNMP Trap Recipient	
	2.4.3.1 Configuring the SNMPv1 Trap Recipient	
	2.4.3.2 Configuring the SNMPv3 Trap Recipient	
	2.4.4 SNMP Inform Recipient	
	2.4.4.1 Configuring the SNMPv3 Inform Recipient	
	2.4.5 Port Logs	
	5 Changing the swEventTrap Severity Level	
	Commands for Displaying and Configuring System Message Logs	
	7 Displaying Message Content on the Switch	
2.8	3 Configuring System Messages and Attributes	
	2.8.1 Configuring Event Auditing	33

2.8.2 Disabling a RASLog Message or Module	33
2.8.3 Enabling a RASLog Message or Module	34
2.8.4 Setting the Severity Level of a RASLog Message	34
2.8.5 Enabling Quiet Time for a Specified Message Type	34
2.8.6 Disabling Quiet Time for a Specified Message Type	35
2.9 Displaying System Message Logs and Attributes	35
2.9.1 Displaying RASLog Messages	35
2.9.2 Displaying RASLog Messages One Message at a Time	36
2.9.3 Displaying Audit Messages	36
2.9.4 Displaying FFDC Messages	36
2.9.5 Displaying the Status of System Messages	37
2.9.6 Displaying the Severity Level of RASLog Messages	37
2.9.7 Displaying the Configured Quiet Time	38
2.9.8 Displaying RASLog Messages by Severity Level	38
2.9.9 Displaying RASLog Messages by Message ID	38
2.9.10 Displaying Messages on a Slot	39
2.9.11 Viewing RASLog Messages from Web Tools	39
2.10 Clearing System Message Logs	39
2.10.1 Clearing the System Message Log	39
2.10.2 Clearing the Audit Message Log	40
2.11 Reading System Messages	40
2.11.1 Reading a RAS System Message	40
2.11.2 Reading an Audit Message	41
2.12 Responding to System Messages	43
2.12.1 Looking Up a System Message	43
2.12.2 Gathering Information about the Problem	
2.12.3 Troubleshooting Files for Support Personnel	44
2.12.3.1 Panic Dump and Core Dump Files	44
2.12.3.2 Trace Dumps	44
2.12.3.3 supportSave Command	
2.13 System Module Descriptions	45
Chapter 3: Audit Messages	54
3.1 AG Messages	54
3.2 AN Messages	55
3.3 AUTH Messages	56
3.4 BCM Messages	56
3.5 BCMG Messages	56
3.6 BLS Messages	56
3.7 BLZ Messages	56
3.8 CCFG Messages	57

3.9 CH Messages	57
3.10 CHS Messages	57
3.11 CNM Messages	57
3.12 CONF Messages	57
3.13 EM Messages	58
3.14 ESM Messages	58
3.15 ESS Messages	59
3.16 FABR Messages	60
3.17 FCR Messages	60
3.18 FICU Messages	60
3.19 FV Messages	61
3.20 HAM Messages	61
3.21 HTTP Messages	61
3.22 IPAD Messages	62
3.23 IPS Messages	62
3.24 LFM Messages	62
3.25 LIC Messages	62
3.26 LOG Messages	63
3.27 MAPS Messages	63
3.28 MS Messages	65
3.29 PMGR Messages	65
3.30 PORT Messages	65
3.31 PSWP Messages	67
3.32 RAS Messages	67
3.33 SEC Messages	68
3.34 SLNK Messages	71
3.35 SNMP Messages	71
3.36 SPM Messages	71
3.37 SRM Messages	73
3.38 SULB Messages	73
3.39 SWCH Messages	74
3.40 SYSM Messages	75
3.41 TS Messages	75
3.42 UCID Messages	75
3.43 UCST Messages	77
3.44 ZONE Messages	77
Chapter 4: FFDC Messages	80
4.1 AUTH Messages	80
4.2 BCM Messages	80
4.3 BCMG Messages	80

4.4 BL Messages	80
4.5 BLS Messages	80
4.6 BLZ Messages	80
4.7 BM Messages	81
4.8 C4 Messages	81
4.9 C5 Messages	81
4.10 CHS Messages	81
4.11 EM Messages	81
4.12 ERCP Messages	82
4.13 FABR Messages	82
4.14 FABS Messages	83
4.15 FCMC Messages	83
4.16 FCPH Messages	83
4.17 FCR Messages	83
4.18 FLOD Messages	83
4.19 FSS Messages	83
4.20 FSSM Messages	83
4.21 HAM Messages	83
4.22 HAMK Messages	84
4.23 HIL Messages	84
4.24 HLO Messages	85
4.25 HMON Messages	85
4.26 KSWD Messages	85
4.27 LACP Messages	85
4.28 LFM Messages	85
4.29 LSDB Messages	85
4.30 MQ Messages	85
4.31 NBFS Messages	85
4.32 PDM Messages	85
4.33 PLAT Messages	85
4.34 PS Messages	86
4.35 RAS Messages	86
4.36 RCS Messages	86
4.37 RTWR Messages	86
4.38 SCN Messages	86
4.39 SNMP Messages	86
4.40 SULB Messages	
4.41 SYSC Messages	86
4.42 SYSM Messages	87
4.43 TRCE Messages	87

4.44 TS Messages	87
4.45 UCST Messages	87
4.46 WEBD Messages	87
4.47 ZONE Messages	87
Chapter 5: Log Messages	88
5.1 AG Messages	88
5.2 AMPM Messages	90
5.3 AN Messages	90
5.4 ASVR Messages	90
5.5 AUTH Messages	90
5.6 BCM Messages	92
5.7 BCMG Messages	92
5.8 BL Messages	92
5.9 BLS Messages	95
5.10 BLZ Messages	95
5.11 BM Messages	95
5.12 C4 Messages	96
5.13 C5 Messages	97
5.14 CAL Messages	99
5.15 CCFG Messages	99
5.16 CFS Messages	99
5.17 CHS Messages	100
5.18 CNM Messages	100
5.19 CNMC Messages	102
5.20 CONF Messages	103
5.21 DIAG Messages	103
5.22 DOT1 Messages	103
5.23 ECC Messages	104
5.24 EM Messages	104
5.25 ERCP Messages	106
5.26 ESM Messages	106
5.27 ESS Messages	109
5.28 ESW Messages	109
5.29 EVMD Messages	110
5.30 FABR Messages	110
5.31 FABS Messages	112
5.32 FBC Messages	112
5.33 FCMC Messages	112
5.34 FCOE Messages	113
5.35 FCPD Messages	114

5.36	FCPH Messages	114
5.37	FCR Messages	114
5.38	FICN Messages	118
5.39	FICU Messages	123
5.40	FKLB Messages	124
5.41	FLOD Messages	124
5.42	FSPF Messages	124
5.43	FSS Messages	125
5.44	FSSM Messages	125
5.45	FTC Messages	125
5.46	FV Messages	125
5.47	HAM Messages	126
5.48	HAMK Messages	127
5.49	HIL Messages	127
5.50	HLO Messages	130
5.51	HMON Messages	130
5.52	HSL Messages	130
5.53	HTTP Messages	130
5.54	IPAD Messages	130
5.55	IPS Messages	131
5.56	ISNS Messages	131
5.57	KAC Messages	132
5.58	KSWD Messages	132
5.59	KTRC Messages	132
5.60	L2SS Messages	133
5.61	L3SS Messages	133
5.62	LACP Messages	133
5.63	LFM Messages	133
5.64	LIC Messages	133
5.65	LOG Messages	134
5.66	LSDB Messages	134
5.67	MAPS Messages	135
5.68	MCST Messages	146
5.69	MFIC Messages	147
5.70	MM Messages	147
5.71	MPTH Messages	147
5.72	MQ Messages	147
5.73	MS Messages	148
5.74	MSTP Messages	148
5.75	NBFS Messages	149

5.76 NS Messages	149
5.77 NSM Messages	
5.78 ONMD Messages	
5.79 PDM Messages	
5.80 PDTR Messages	
5.81 PLAT Messages	
5.82 PMGR Messages	
5.83 PORT Messages	
5.84 PS Messages	
5.85 PSWP Messages	
5.86 QOSD Messages	154
5.87 RAS Messages	154
5.88 RCS Messages	155
5.89 RMON Messages	156
5.90 RPCD Messages	156
5.91 RTE Messages	156
5.92 RTWR Messages	156
5.93 SCN Messages	156
5.94 SEC Messages	157
5.95 SFLO Messages	165
5.96 SLNK Messages	165
5.97 SNMP Messages	165
5.98 SPM Messages	165
5.99 SRM Messages	167
5.100 SS Messages	167
5.101 SSLP Messages	168
5.102 SSMD Messages	168
5.103 SULB Messages	169
5.104 SWCH Messages	171
5.105 SYSC Messages	173
5.106 SYSM Messages	173
5.107 TRCE Messages	173
5.108 TS Messages	174
5.109 UCID Messages	174
5.110 UCST Messages	174
5.111 UFCS Messages	175
5.112 UPTH Messages	175
5.113 VS Messages	175
5.114 WEBD Messages	175
5.115 XTUN Messages	176

5.116 ZONE Messages	177
Chapter 6: Fabric OS System Messages	181
6.1 AG Messages	181
6.2 AMPM Messages	206
6.3 AN Messages	206
6.4 ASVR Messages	209
6.5 AUTH Messages	209
6.6 BCM Messages	228
6.7 BCMG Messages	230
6.8 BL Messages	232
6.9 BLS Messages	251
6.10 BLZ Messages	253
6.11 BM Messages	256
6.12 C4 Messages	262
6.13 C5 Messages	276
6.14 CAL Messages	289
6.15 CCFG Messages	289
6.16 CFS Messages	292
6.17 CH Messages	292
6.18 CHS Messages	293
6.19 CNM Messages	294
6.20 CNMC Messages	311
6.21 CONF Messages	311
6.22 DIAG Messages	318
6.23 DOT1 Messages	318
6.24 ECC Messages	321
6.25 EM Messages	321
6.26 ERCP Messages	345
6.27 ESM Messages	346
6.28 ESS Messages	364
6.29 ESW Messages	368
6.30 EVMD Messages	370
6.31 FABR Messages	371
6.32 FABS Messages	390
6.33 FBC Messages	395
6.34 FCMC Messages	395
6.35 FCOE Messages	396
6.36 FCPD Messages	403
6.37 FCPH Messages	404
6.38 FCR Messages	408

6.39	FICN Messages	440
6.40	FICU Messages	481
6.41	FKLB Messages	489
6.42	FLOD Messages	490
6.43	FSPF Messages	492
6.44	FSS Messages	497
6.45	FSSM Messages	500
6.46	FTC Messages	501
6.47	FV Messages	502
6.48	HAM Messages	510
6.49	HAMK Messages	516
6.50	HIL Messages	517
6.51	HLO Messages	542
6.52	HMON Messages	543
6.53	HSL Messages	544
6.54	HTTP Messages	546
6.55	IPAD Messages	548
6.56	IPS Messages	550
6.57	ISNS Messages	553
6.58	KAC Messages	556
6.59	KSWD Messages	560
6.60	KTRC Messages	561
6.61	L2SS Messages	562
6.62	L3SS Messages	564
6.63	LACP Messages	565
6.64	LFM Messages	566
6.65	LIC Messages	567
6.66	LOG Messages	571
6.67	LSDB Messages	574
6.68	MAPS Messages	576
6.69	MCST Messages	666
6.70	MFIC Messages	671
6.71	MM Messages	673
6.72	MPTH Messages	673
6.73	MQ Messages	673
	MS Messages	
	MSTP Messages	
	NBFS Messages	
6.77	NS Messages	687
6.78	NSM Messages	695

6.79 ONMD Messages	700
6.80 PDM Messages	702
6.81 PDTR Messages	709
6.82 PLAT Messages	710
6.83 PMGR Messages	714
6.84 PORT Messages	718
6.85 PS Messages	734
6.86 PSWP Messages	736
6.87 QOSD Messages	738
6.88 RAS Messages	739
6.89 RCS Messages	748
6.90 RMON Messages	753
6.91 RPCD Messages	753
6.92 RTE Messages	755
6.93 RTWR Messages	757
6.94 SCN Messages	759
6.95 SEC Messages	761
6.96 SFLO Messages	846
6.97 SLNK Messages	848
6.98 SNMP Messages	849
6.99 SPM Messages	852
6.100 SRM Messages	863
6.101 SS Messages	863
6.102 SSLP Messages	868
6.103 SSMD Messages	868
6.104 SULB Messages	880
6.105 SWCH Messages	900
6.106 SYSC Messages	916
6.107 SYSM Messages	917
6.108 TRCE Messages	920
6.109 TS Messages	924
6.110 UCID Messages	927
6.111 UCST Messages	941
6.112 UFCS Messages	944
6.113 UPTH Messages	947
6.114 VS Messages	948
6.115 WEBD Messages	950
6.116 XTUN Messages	951
6.117 ZONE Messages	964
Chapter 7: MAPS Monitoring Systems and RASLog IDs	997

Chapter 1: Introduction

1.1 About This Document

This manual supports Fabric OS® 9.0.x and later and documents system messages that can help you diagnose and fix problems with a switch or fabric. The messages in this manual are organized alphabetically by module name. A *module* is a subsystem in the Fabric OS software. Each module generates a set of numbered messages. For each message, this manual provides the message text, message type, severity level, probable cause, and recommended action. There may be more than one cause and more than one recommended action for any given message. This manual discusses the most probable cause and the typical recommended action.

1.2 Supported Hardware and Software

The following hardware platforms are supported by Brocade Fabric OS 9.0.x.

1.2.1 Brocade Gen 7 (64G) Fixed-Port Switches

■ Brocade G720 Switch

1.2.2 Brocade Gen 7 (64G) Directors

For ease of reference, Brocade chassis-based storage systems are standardizing on the term *director*. The legacy term *backbone* can be used interchangeably with the term *director*.

- Brocade X7-4 Director
- Brocade X7-8 Director

1.2.3 Brocade Gen 6 (32G) Fixed-Port Switches

- Brocade G610 Switch
- Brocade G620 Switch
- Brocade G630 Switch
- Brocade 7810 Extension Switch
- Brocade G648 Blade Server SAN I/O Module
- Brocade MXG610 Blade Server SAN I/O Module

1.2.4 Brocade Gen 6 (32G) Directors

- Brocade X6-4 Director
- Brocade X6-8 Director

1.3 Contacting Technical Support for Your Brocade® Product

For product support information and the latest information on contacting the Technical Assistance Center, go to https://www.broadcom.com/support/fibre-channel-networking/. If you have purchased Brocade[®] product support directly from Broadcom, use one of the following methods to contact the Technical Assistance Center 24x7.

Online **Telephone** For nonurgent issues, the preferred method is to log in to Required for Severity 1 (critical) issues: myBroadcom at https://www.broadcom.com/mybroadcom. (You Please call Fibre Channel Networking Global Support at one of the must initially register to gain access to the Customer Support numbers listed at /.https://www.broadcom.com/support/fibre-Portal.) Once there, select Customer Support Portal > Support channelnetworking Portal. You will now be able to navigate to the following sites: Knowledge Search: Clicking the top-right magnifying glass brings up a search bar. Case Management: The legacy MyBrocade case management tool (MyCases) has been replaced with the Fibre Channel Networking case management tool. DocSafe: You can download software and documentation. Other Resources: Licensing Portal (top), SAN Health (top) and bottom), Communities (top), Education (top).

If you purchased Brocade product support from a Broadcom OEM/solution provider, contact your OEM/solution provider for all your product support needs.

- OEM/solution providers are trained and certified by Broadcom to support Brocade products.
- Broadcom provides backline support for issues that cannot be resolved by the OEM/solution provider.
- Brocade Supplemental Support augments your existing OEM support contract, providing direct access to Brocade expertise. For more information, contact Broadcom or your OEM.
- For questions regarding service levels and response times, contact your OEM/solution provider.

1.4 Document Feedback

Quality is our first concern. We have made every effort to ensure the accuracy and completeness of this document. However, if you find an error or an omission or if you think that a topic needs further development, we want to hear from you. Send your feedback to documentation.pdl@broadcom.com. Provide the publication title, publication number, topic heading, page number, and as much detail as possible.

Chapter 2: Overview of System Messages

2.1 System Message Types

Fabric OS supports three types of system messages. A system message can be one or more of the following types:

- Log Messages
- Audit Messages
- FFDC Messages

Fabric OS supports a different methodology for storing and accessing each type of message.

2.1.1 Log Messages

RASLog messages report significant information or system events (failures, errors, or critical conditions) and are also used to show the status of high-level, user-initiated actions. RASLog messages are forwarded to the console, to the configured syslog servers, and to the SNMP management station through Simple Network Management Protocol (SNMP) traps or informs.

The following is an example of a RASLog system message.

```
2019/10/25-17:51:05, [C3-1001], 937, CHASSIS, ERROR, switch, Port 18 failed due to SFP validation failure. Check if the SFP is valid for the configuration.
```

For information on displaying and clearing RASLog messages, see "Displaying System Message Logs and Attributes" on page 35.

NOTE: The *Recommended Action* field has been removed for messages that do not require any action from the user.

2.1.2 Audit Messages

Event auditing is designed to support post-event audits and problem determination based on high-frequency events of certain types such as security violations, zoning configuration changes, firmware downloads, and certain types of fabric events. Audit messages that are flagged only as AUDIT are not saved in the switch error logs. The switch can be configured to stream audit messages to the switch console and to forward the messages to specified syslog servers. Audit log messages are not forwarded to an SNMP management station. There is no limit to the number of audit events.

The following is an example of an audit message.

```
0 AUDIT, 2019/10/14-06:07:33 (UTC), [SULB-1003], INFO, FIRMWARE, admin/admin/192.0.2.2/telnet/CLI ad 0/switch, , Firmwarecommit has started.
```

For any given event, audit messages capture the following information:

- User Name: The name of the user who triggered the action.
- User Role: The access level of the user, such as root or admin.
- Event Name: The name of the event that occurred.
- Event Information: Information about the event.

The event classes described in Table 1 can be audited.

Table 1: Event Classes

Operand	Event Class	Description
1	Zone	You can audit zone event configuration changes, but not the actual values that were changed. For example, you may receive a message that states "Zone configuration has changed," but the message does not display the actual values that were changed.
2	Security	You can audit any user-initiated security event for all management interfaces. For events that have an impact on the entire fabric, an audit is generated only for the switch from which the event was initiated.
3	Configuration	You can audit configuration downloads of existing SNMP configuration parameters. Configuration uploads are not audited.
4	Firmware	You can audit configuration downloads of existing SNMP configuration parameters. Configuration uploads are not audited.
5	Fabric	You can audit changes related to the Administration Domain.
7	LS	You can audit changes related to Virtual Fabrics (logical switches)
8	CLI	You can audit the CLI commands issued on the switch.
9	MAPS	You can audit changes related to Monitoring and Alerting Policy Suite (MAPS).
N/A	RAS	The RAS class is used to audit or track the RASLog messages or modules that are enabled or disabled using the rasAdmin command.
		NOTE: The RAS class is not configurable, and it is always enabled internally.

Fabric OS® 9.0.0 generates component-specific audit messages.

Event auditing is a configurable feature, that is enabled by default. You can also enable event auditing using the <code>auditCfg--enable</code> command to send events to a configured remote host. The system logging daemon (Syslogd) must be configured for logging audit messages. You can set up filters to screen out particular classes of events using the <code>auditCfg</code> command. The defined set of audit messages is sent to the configured remote host in the audit message format so that they are easily distinguishable from other syslog events that may occur in the network. For details on how to configure event auditing, see "Configuring Event Auditing" on page 33. For more details, see "Displaying Audit Messages" on page 36 and "Reading an Audit Message" on page 41.

2.1.2.1 Audit Log Enhancements

Following are the audit logs that have been enhanced or added for security events:

- Failure to establish an HTTPS connection along with the reason for the failure.
- Failure to establish an HTTPS connection if a peer presents an invalid certificate with an appropriate reason statement.
- Failure to establish an SSH session when a switch acts as a client (SSH/SCP/SFTP) including details of the reason for the failure and the remote IP to which the connection was attempted.
- Failure to establish an SSH session due to a cipher configuration mismatch or invalid ciphers when a switch acts as an SSH server including details of the reason for the failure and the remote IP to which the connection was attempted. (Use of ciphers that are not compliant with CC are discouraged but not enforced by the code. Hence, an SSH session will not fail if a valid cipher configuration is used, even though it is not compliant with CC.)
- Failure to establish an SSH session due to a supported public key algorithm mismatch or an invalid public key algorithm configuration when a switch acts as an SSH server including details of the reason for the failure and the remote IP to which the connection was attempted. (Use of public key algorithms that are not compliant with CC are discouraged but not enforced by the code. Hence, an SSH session will not fail if a valid public key algorithm is used even though it is not compliant with CC.)

- Failure to establish an SSH session due to a supported MAC mismatch or an invalid MAC configuration when the switch acts as an SSH server including details of the reason for the failure and the remote IP to which the connection was attempted. (Uses of MAC that are not compliant with CC are discouraged but not enforced by the code. Hence, the SSH session will not fail if a valid MAC configuration is used even though it is not compliant with CC.)
- Failure to establish an SSH session due to a supported key exchange algorithm mismatch or an invalid key exchange algorithm configuration when switch acts as an SSH server including details of the reason for the failure and the remote IP to which the connection was attempted. (Use of key exchange algorithms that are not compliant with CC are discouraged but not enforced by code. Hence, the SSH session will not fail if a valid key exchange algorithm configuration is used even though it is not compliant with CC.)
- Failure to establish a TLS session due to a cipher configuration mismatch or invalid ciphers when the switch acts as a TLS client (RADIUS, LDAP, SYSLOG) including details of the reason for the failure. (Use of ciphers that are not compliant with CC are discouraged but not enforced by the code. Hence, the TLS session will not fail if a valid cipher configuration is used even though it is not compliant with CC.)
- Failure to establish a TLS connection when a switch acts as a TLS client (RADIUS, LDAP, SYSLOG) if a peer presents an invalid certificate with an appropriate reason statement.
- Failure to establish a TLS connection when a switch acts as a TLS client (RADIUS, LDAP, SYSLOG) due to a mutual authentication failure (using X509v3 certificates) with an appropriate reason statement.
- Failure to establish a TLS session due to a cipher configuration mismatch or invalid ciphers when a switch acts as a TLS server (HTTPS) including details of the reason for the failure. (Use of ciphers that are not compliant with CC are discouraged but not enforced by the code. Hence, the TLS session will not fail if a valid cipher configuration is used even though it is not compliant with CC.)
- Failure to establish a TLS session due to TLS protocol version configuration mismatch or an invalid TLS protocol version when a switch acts as a TLS server (HTTPS) including details of the reason for the failure. (Use of TLS protocol versions that are not compliant with CC are discouraged but not enforced by the code. Hence, the TLS session will not fail if a valid cipher configuration is used even though it is not compliant with CC.)
- Failure to establish a TLS connection when a switch acts as a TLS server (HTTPS) due to a mutual authentication failure (using X509v3 certificates) with an appropriate reason statement.
- Failure to establish a TLS connection when a switch acts as a TLS server (HTTPS) if a peer presents an invalid certificate with an appropriate reason statement.
- Failure to establish a TLS connection when a switch acts as a TLS server (HTTPS) and the distinguished name (DN) or subject alternative name (SAN) of the peer does not match the expected identifier for the peer with an appropriate reason statement.
- Successful user authentication including details of the username, the interface used for login (SSH/Telnet/console/Web Tools), the remote IP address from which the user has connected, and the authentication mechanism used (RADIUS/LDAP/TACACS+/local).
- Failure to validate an X509v3 certificate including details of the reason for the failure.
- Failure to validate a CA certificate when the Basic Constraints extension is not present or when the CA flag is not set to true including details of the reason for the failure.
- Change of date on the switch.
- Query for the existing firmware version or the latest installed firmware version by the administrator.
- Firmware signature verification status (success or failure) before the firmware download process.
- Timeout expiry and session logout due to session inactivity of a remote interactive session (SSH/Telnet/Web Tools).
- Timeout expiry and session logout due to session inactivity of a local interactive session (console).
- User-initiated logout of session.
- Successful or failed attempt to establish a TLS client connection and to terminate an existing TLS session (SYSLOG) including details of the peer to which the connection was made.
- Successful or failed attempt to establish a TLS server connection or SSH connection and to terminate an existing TLS session (HTTPS) or SSH session including details of the peer to which the connection was made.

- If the certificate public key size is less than 2048 in the case of TLS, an event is audit-logged (although the connection is allowed).
- If certificate validation fails for the "Basic Constraints" field, an event is audit-logged and the connection is not allowed.
- If certificate validation fails for the "CN" (common name) field, an event is audit-logged and the connection is not allowed.
- If certificate validation fails for the "Extended Key Usage" field, an event is audit-logged and the connection is not allowed.

2.1.2.2 Audit Messages Related to SSH

These messages are used for:

- Key mismatch
- Cipher mismatch
- Key algorithm mismatch
- MAC mismatch

Message template:

```
<Message Number="3076" Audit="YES" Log="YES" Class="SECURITY" Severity="INFO">
<Text>Event: %s, %s, Info: %s.</Text>
<Args>
<Arg>Event Name</Arg>
<Arg>Event action</Arg>
<Arg>Even specific info </Arg>
</Args>
<Cause>
Indicates a failure to establish an SSH session.
</Cause>
<Action>
Verify the security event was planned.
If the security event was planned, no action is required. If the security event was not planned, take
appropriate action as defined by your enterprise security policy. 
</Action>
</Message>
```

Example message:

```
63 AUDIT, 2019/03/20-18:14:00 (UTC), [SEC-3076], INFO, SECURITY, NONE/NONE/NONE/None/CLI, None/sw0/FID
128, , Event: SSH, Status: failed, Info: SSH Session establishment failed. Reason: no matching cipher found., IP Addr:10.70.12.112
```

2.1.2.3 Audit Messages Related to TLS

These messages are used for:

- Wrong protocol version
- Wrong ciphers
- Wrong CA certificate
- Server keys less than 2048

Message template:

```
<Message Number="3077" Audit="YES" Log="YES" Class="SECURITY" Severity="INFO">
<Text>Event: %s, %s, Info: %s.</Text>
<Args>
<Arg>Event Name</Arg>
<Arg>Event action</Arg>
<Arg>Even specific info </Arg>
```

```
</Arqs>
<Cause>
Indicates a failure to establish a TLS session.
</Cause>
<Action>
Verify the security event was planned. If the security event was planned, no
action is required.
If the security event was not planned, take appropriate action as defined by your enterprise
security
policy. 
</Action>
</Message>
Example message:
84 AUDIT, 2019/03/20-18:33:13 (UTC), [SEC-3077], INFO, SECURITY,
root/root/NONE/console/CLI, ad 0/sw0/FID 128, , Event: TLS SESSION,
TLS handshake failed, Info: Wrong Protocol version number..
```

2.1.2.4 Audit Messages Related to Certificate Validation

These messages are used for all types of certification validation failure: key usage, extended key usage, self-signed certificates, login with

importing CA cert, CN mismatch and so on. Open SSL errors are presented in the info section as is.

Message template:

```
<Message Number="3081" Audit="YES" Log="YES" Class="SECURITY" Severity="INFO">
<Text>Event: %s, %s, Info: %s.</Text>
<Args>
<Arg>Event Name</Arg>
<Arg>Event action</Arg>
<Arg>Even specific info </Arg>
</Arqs>
<Cause>
Indicates that TLS Certificate Validation failed.
</Cause>
<Action>
Verify the security event was planned.
If the security event was planned, no action is required.
If the security event was not planned, take appropriate action as defined by your enterprise
security
policy. 
</Action>
</Message>
Example message:
94 AUDIT, 2019/03/20-18:37:04 (UTC), [SEC-3081], INFO, SECURITY,
swadmin/admin/10.252.200.228/ssh/CLI, ad 0/sw0/FID 128, , Event: TLS
SESSION, Certificate Validation failed, Info: Reason = unable to get local issuer certificate
Example messages for TLS initiation and termination:
INFO, pizzabox12,2019/04/13-12:19:45, [SEC-3078], 54908, FID 3, INFO, pizzabox12,
Event: TLS SESSION, TLS handshake, Info: Establishing TLS connection. Host=10.38.37.161.
2019/04/13-12:19:46, [SEC-3078], 54909, FID 3,
Event: TLS SESSION, TLS handshake, Info: Terminating TLS connection. Host=10.38.37.161
```

2.1.2.5 Audit Messages Related to When Unsecure Protocols Are Allowed or Secure Protocols Are Disabled

These messages are used in the following cases:

- When an ipfilter policy that has HTTP port (80) enabled is activated.
- When an ipfilter policy that has Telnet port (80) enabled is activated.
- When an ipfilter policy that has HTTPS port (443) disabled is activated.

Message template:

```
<Message Number="3075" Audit="YES" Log="YES" Class="SECURITY" Severity="INFO">
<Text>Event: %s, %s, Info: %s.</Text>
<Arg>Event Name</Arg>
<Arg>Event action</Arg>
<Arg>Even specific info </Arg>
</Args>
<Cause>
Indicates that unsecure communication service is activated.
</Cause>
<Action>
Verify the security event was planned.
If the security event was planned, no action is required.
If the security event was not planned, take appropriate action as defined by your enterprise
security
policy. 
</Action>
</Message>
```

Example messages for each of the above cases:

```
3 AUDIT, 2019/02/21-19:39:35 (UTC), [SEC-3075], INFO, SECURITY, root/root/NONE/console/CLI, ad_0/sw0/FID 128, , Event: ipfilter,
HTTP PORT STATE: ACTIVE, Info: Activated ipfilter policy <policy_name> has activated HTTP port.
4 AUDIT, 2019/02/21-19:39:35 (UTC), [SEC-3075], INFO, SECURITY,
root/root/NONE/console/CLI, ad_0/sw0/FID 128, , Event: ipfilter,
TELNET PORT STATE: ACTIVE, Info: Activated ipfilter policy <policy_name> has activated Telnet port.
3 AUDIT, 2019/02/21-19:27:56 (UTC), [SEC-3075], INFO, SECURITY,
root/root/NONE/console/CLI, ad_0/sw0/FID 128, , Event: ipfilter,
HTTPS PORT STATE: DROP, Info: Activated ipfilter policy <policy_name> has blocked HTTPS port.
```

2.1.3 FFDC Messages

First Failure Data Capture (FFDC) is used to capture failure-specific data when a problem or failure is noted for the first time and before the switch reboots or the trace and log buffer is wrapped. All subsequent iterations of the same error are ignored. This critical debug information is saved in nonvolatile storage and can be retrieved using the supportSave command. The FFDC data is used for debugging or analyzing the problem. FFDC is intended for use by Brocade technical support.

FFDC is enabled by default. Enter the supportFfdc command to enable or disable FFDC. If FFDC is disabled, the FFDC daemon does not capture any data, even when a message with an FFDC attribute is logged.

The following is an example of an FFDC message.

```
2019/12/17-08:30:13, [SS-1000], 88, SLOT 6 | FFDC | CHASSIS, INFO, DCX, supportSave has uploaded support information to the host with IP address 192.0.2.2.
```

2.2 Message Severity Levels

Table 2 shows the four levels of severity for system messages, ranging from CRITICAL (1) to INFO (4). In general, the definitions are wide ranging and are to be used as general guidelines for troubleshooting. For all cases, you must look at each specific error message description thoroughly before taking action.

Table 2: Severity Levels of a Message

Severity Level	Description
1 = CRITICAL	Critical-level messages indicate that the software has detected serious problems that will cause a partial or complete failure of a subsystem if not corrected immediately; for example, a power supply failure or a rise in temperature must receive immediate attention.
2 = ERROR	Error-level messages represent an error condition that does not impact overall system functionality significantly. For example, error-level messages might indicate timeouts on certain operations, failures of certain operations after retries, invalid parameters, or failure to perform a requested operation.
3 = WARNING	Warning-level messages highlight a current operating condition that should be checked or it may lead to a failure in the future. For example, a power supply failure in a redundant system relays a warning that the system is no longer operating in redundant mode unless the failed power supply is replaced or fixed.
4 = INFO	Info-level messages report the current non-error status of the system components: for example, detecting the Online and off line status of a fabric port.

2.3 System Error Message Logging

The RASLog service generates and stores messages related to abnormal or erroneous system behavior. It includes the following features:

- All RASLog error messages are saved to nonvolatile storage by default.
- The system error message log can save a maximum of 8196 messages in random access memory (RAM).
- The system message log is implemented as a circular buffer. When more than the maximum entries are added to the log file, old entries are overwritten by new entries.
- Messages are numbered sequentially from 1 to 2,147,483,647 (0x7ffffff). The sequence number will continue to increase beyond the storage limit of 1024 messages. The sequence number can be reset to 1 using the errclear command. The sequence number persists across power cycles and switch reboots.
- The RASLog message text can be up to 256 characters long.
- Trace dump, FFDC, and core dump files can be uploaded to the FTP server using the supportsave command.
- Configure the syslogd facility as a management tool for error logs. This is particularly important for dual-domain switches because the syslogd facility saves messages from two logical switches as a single file and in sequential order. For more information, see "System Logging Daemon" on page 23.
- RASLog messages are streamed to the console and are forwarded to the configured syslog servers and to the SNMP management station through SNMP traps (in SNMPv1 and SNMPv3) or through informs (in SNMPv3). Use the snmpconfig command to configure the SNMPv1 and SNMPv3 hosts.
- Audit messages are streamed to the switch console and are forwarded to the configured syslog servers. The audit log
 messages are not forwarded to an SNMP management station.

2.4 Configuring Syslog Message Destinations

You can configure Fabric OS to send syslog messages to the following output locations:

- Syslog daemon
- System console
- SNMP management station

2.4.1 System Logging Daemon

The system logging daemon (syslogd) is a process on UNIX, Linux, and some Windows systems that reads and logs messages as specified by the system administrator.

Fabric OS can be configured to use a UNIX-style syslogd process to forward system events and error messages to log files on a remote host system. The host system can be running UNIX, Linux, or any other operating system that supports standard syslogd functionality. Configuring syslogd involves configuring the host, enabling syslogd on the Brocade model, and optionally setting the facility level.

2.4.1.1 Configuring a Syslog Server

To configure the switch to forward all system events and error messages to the syslogd of one or more servers, perform the following steps.

- 1. Log in to the switch as admin.
- 2. Use the syslogadmin --set -ip ip_address | hostname [-port port_num] command to configure a secure and nonsecure syslog server to which system messages are forwarded. Secure syslog mode is disabled by default.

The following example configures an IPv4 nonsecure syslog server:

```
switch:admin> syslogadmin --set -ip 172.26.26.173
```

The following example configures an IPv4 secure syslog server:

```
switch:admin> syslogadmin --set -ip 172.26.26.173 -secure -port 2000
```

The following example configures a nonsecure syslog server using a hostname.

```
switch:admin> syslogadmin --set -ip win2k8-58-113
```

You can configure up to six syslog servers to receive syslog messages.

3. Enter the syslogadmin --show -ip command to verify the syslog configuration on the switch.

```
switch:admin> syslogadmin --show -ip
syslog.1 172.26.26.173
syslog.2 win2k8-58-113
```

You can remove a configured syslog server using the syslogadmin --remove -ip ip_address | hostname command.

2.4.2 System Console

The system console displays RASLog messages, audit messages (if enabled), and panic dump messages. These messages are mirrored to the system console in addition to being saved in one of the system logs.

The system console displays messages only through the serial port. If you log in to a switch through the Ethernet port or modem port, you will not receive system console messages.

You can filter messages that display on the system console by severity using the errFilterSet command. All messages are still sent to the system message log and syslogd (if configured).

2.4.2.1 Setting the System Console Severity Level

You can limit the types of messages that are logged to the console using the errFilterSet command. This command allows you to set the minimum severity level to be logged to the console. All error messages at that level or higher will be logged; all error messages below that level will not be displayed, but they will still be recorded. You can choose one of the following severity levels: INFO, WARNING, ERROR, or CRITICAL.

To set the severity levels for the system console, perform the following steps.

- 4. Log in to the switch as admin.
- 5. Use the errFilterSet [-d console -v severity] command to set the console severity level. The severity can be one of the following: INFO, WARNING, ERROR, or CRITICAL. The severity values are not case-sensitive.

For example, to set the filter severity level for the console to ERROR, enter the following command.

```
switch:admin> errfilterset -d console -v error
```

6. Enter the errFilterSet command to verify the configured filter settings.

```
switch:admin> errfilterset
console: filter severity = ERROR
```

2.4.3 SNMP Trap Recipient

An unsolicited message that comes to the management station from the SNMP agent on the device is called a *trap*. When an event occurs and if the event severity level is at or below the set severity level, the SNMP trap notification, swEventTrap, is sent to the configured trap recipients. The VarBind in the Trap Data Unit contains the corresponding instance of the event index, time information, event severity level, repeat count, and description. The following severity levels are possible:

- None (0)
- Critical (1)
- Error (2)
- Warning (3)
- Informational (4)
- Debug (5)

By default, the severity level is set to None, implying that all traps are filtered and therefore no event traps are received. When the severity level is set to Informational, all traps with the severity level of Informational, Warning, Error, and Critical are received. For more information on changing the severity level of swEvent Audit messages are not converted into swEventTrap.

SNMP traps are unreliable because the trap recipient does not send any acknowledgment when it receives a trap. Therefore, the SNMP agent cannot determine if the trap was received.

Brocade switches send traps on UDP port 162. To receive traps, the management station IP address must be configured on the switch. You can configure SNMPv1 and SNMPv3 hosts to receive traps.

For more information on the swEventTrap, refer to the *Brocade*[®] Fabric OS[®] MIB Reference Manual.

2.4.3.1 Configuring the SNMPv1 Trap Recipient

The snmpConfig --set snmpv1 command allows you to specify the SNMP trap recipient. To configure the SNMPv1 host to receive the trap, perform the following steps.

- 1. Log in to the switch as admin.
- 2. Enter the snmpConfig --set snmpvl command to configure the SNMP trap recipient.

```
switch:admin> snmpconfig --set snmpv1

SNMP community and trap recipient configuration:
Community (rw): [Secret COde]
Trap Recipient's IP address : [192.0.2.2]
Trap recipient Severity level : (0..5) [4]
Trap recipient Port : (0..65535) [162]
Community (rw): [OrigEquipMfr]
```

```
Trap Recipient's IP address : [fec0:60:22bc:200:313:72ff:fe64:78b2]
```

NOTE: To receive the traps, the management station IP address must be configured on the switch.

3. Enter the snmpconfig --show snmpv1 command to verify the SNMPv1 agent configuration.

```
switch:admin> snmpconfig --show snmpv1
SNMPv1 community and trap recipient configuration:
 Community 1: Secret COde (rw)
   Trap recipient: 192.0.2.2
   Trap port: 162
   Trap recipient Severity level: 5
 Community 2: OrigEquipMfr (rw)
   Trap recipient: fec0:60:22bc:200:313:72ff:fe64:78b2
   Trap port: 162
   Trap recipient Severity level: 5
  Community 3: private (rw)
   Trap recipient: tools.lab.brocade.com
   Trap port: 162
   Trap recipient Severity level: 5
  Community 4: public (ro)
   Trap recipient: 192.0.10.10
   Trap port: 65530
   Trap recipient Severity level: 1
 Community 5: common (ro)
   Trap recipient: fec0:60:69bc:200:213:72ff:fe64:069f
   Trap port: 11
   Trap recipient Severity level: 2
 Community 6: FibreChannel (ro)
   Trap recipient: WT.org.brocade.com
   Trap port: 65521
   Trap recipient Severity level: 2
SNMPv1:Enabled
```

2.4.3.2 Configuring the SNMPv3 Trap Recipient

To configure the SNMPv3 host to receive traps, perform the following steps.

- 1. Log in to the switch as admin.
- 2. Enter the snmpConfig --set snmpv3 command to configure the SNMP trap recipient. Ignore the step to enable the SNMP informs: SNMP Informs Enabled.

```
switch:admin> snmpconfig --set snmpv3

SNMP Informs Enabled (true, t, false, f): [true]

SNMPV3 Password Encryption Enabled (true, t, false, f): [false] t
Warning: The encrypted password cannot be decrypted. Do you want to continue? (yes, y, no, n): [no] y

SNMPv3 user configuration(snmp user not configured in FOS user database will have physical AD and admin role as the default):
User (rw): [snmpadmin1]
Auth Protocol [MD5(1)/SHA(2)/noAuth(3)]: (1..3) [3]
Priv Protocol [DES(1)/noPriv(2)/3DES(3)/AES128(4)/AES192(5)/AES256(6)]): (2..2) [2]
User (rw): [snmpadmin2]
Auth Protocol [MD5(1)/SHA(2)/noAuth(3)]: (1..3) [3]
Priv Protocol [DES(1)/noPriv(2)/3DES(3)/AES128(4)/AES192(5)/AES256(6)]): (2..2) [2]
User (rw): [snmpadmin3]
```

```
Auth Protocol [MD5(1)/SHA(2)/noAuth(3)]: (1..3) [3]
Priv Protocol [DES(1)/noPriv(2)/3DES(3)/AES128(4)/AES192(5)/AES256(6)]): (2..2) [2]
User (ro): [snmpuser1]
Auth Protocol [MD5(1)/SHA(2)/noAuth(3)]: (1..3) [3]
Priv Protocol [DES(1)/noPriv(2)/3DES(3)/AES128(4)/AES192(5)/AES256(6)]): (2..2) [2]
User (ro): [snmpuser2]
Auth Protocol [MD5(1)/SHA(2)/noAuth(3)]: (1..3) [3]
Priv Protocol [DES(1)/noPriv(2)/3DES(3)/AES128(4)/AES192(5)/AES256(6)]): (2..2) [2]
User (ro): [snmpuser3]
Auth Protocol [MD5(1)/SHA(2)/noAuth(3)]: (1..3) [3]
Priv Protocol [DES(1)/noPriv(2)/3DES(3)/AES128(4)/AES192(5)/AES256(6)]): (2..2) [2]
SNMPv3 trap recipient configuration:
Trap Recipient's IP address: [192.0.2.2]
UserIndex: (1..6) [1]
Trap recipient Severity level: (0..5) [1]
Trap recipient Port : (0..65535) [35432]
Trap Recipient's IP address : [192.0.10.10]
UserIndex: (1..6) [2]
Trap recipient Severity level: (0..5) [5]
Trap recipient Port : (0..65535) [162]
Trap Recipient's IP address: [192.0.20.20]
[...]
```

NOTE: To receive the SNMP traps, the username, the authentication protocol, the UDP port number, and the privacy protocol must match between the switch and the management station.

3. Enter the snmpConfig --show snmpv3 command to verify the SNMP agent configuration.

```
switch:admin> snmpconfig --show snmpv3
SNMP Informs = 0 (OFF)
SNMPV3 user password encrypted = 0 (OFF)
SNMPv3 USM configuration:
User 1 (rw): snmpadmin1
Auth Protocol: noAuth
Priv Protocol: noPriv
User 2 (rw): snmpadmin2
Auth Protocol: MD5
Priv Protocol: noPriv
User 3 (rw): snmpadmin3
Auth Protocol: MD5
Priv Protocol: DES
User 4 (ro): snmpuser1
Auth Protocol: noAuth
Priv Protocol: noPriv
User 5 (ro): snmpuser2
Auth Protocol: noAuth
Priv Protocol: noPriv
User 6 (ro): snmpuser3
Auth Protocol: noAuth
Priv Protocol: noPriv
SNMPv3 Trap configuration:
Trap Entry 1: 192.0.2.2
Trap Port: 162
Trap User: snmpadmin1
Trap recipient Severity level: 1
Trap Entry 2: fe80::224:1dff:fef6:0f21
Trap Port: 162
[...]
```

2.4.4 SNMP Inform Recipient

The SNMP inform notification is similar to the SNMP trap except that the management station that receives an SNMP inform acknowledges the system message with an SNMP response packet data unit (PDU). If the sender does not receive the SNMP response PDU, the inform request can be sent again. An SNMP inform request is saved in the switch memory until a response is received or the request times out. Informs are more reliable than traps, but they consume more resources in the device and in the network. Use SNMP informs only if it is important that the management station receives all event notifications. Otherwise, use SNMP traps.

2.4.4.1 Configuring the SNMPv3 Inform Recipient

To configure an SNMPv3 host to receive SNMP informs, perform the following steps.

- 1. Log in to the switch as admin.
- 2. Enter the snmpConfig --set snmpv3 command to configure the inform recipient. When prompted to enable the SNMP informs, enter true or t. SNMP informs are disabled by default.

```
switch:admin> snmpconfig --set snmpv3
SNMP Informs Enabled (true, t, false, f): [true]
SNMPV3 Password Encryption Enabled (true, t, false, f): [false] t
Warning: The encrypted password cannot be decrypted. Do you want to continue? (yes, y, no, n): [no] y
SNMPv3 user configuration(snmp user not configured in FOS user database will have physical AD and
admin role as the default):
User (rw): [snmpadmin1]
Auth Protocol [MD5(1)/SHA(2)/noAuth(3)]: (1..3) [3]
Priv Protocol [DES(1)/noPriv(2)/3DES(3)/AES128(4)/AES192(5)/AES256(6)]): (2..2) [2]
Engine ID: [0:0:0:0:0:0:0:0:0]
User (rw): [snmpadmin2]
Auth Protocol [MD5(1)/SHA(2)/noAuth(3)]: (1..3) [3] 1
New Auth Passwd:
Verify Auth Passwd:
Priv Protocol [DES(1)/noPriv(2)/3DES(3)/AES128(4)/AES192(5)/AES256(6)]):
(1...6) [2] 1
New Priv Passwd:
Verify Priv Passwd:
Engine ID: [0:0:0:0:0:0:0:0:0] 80:00:05:23:01:0A:23:34:1B
User (rw): [snmpadmin3]
Auth Protocol [MD5(1)/SHA(2)/noAuth(3)]: (1..3) [3]
Priv Protocol [DES(1)/noPriv(2)/3DES(3)/AES128(4)/AES192(5)/AES256(6)]):
(2..2) [2]
Engine ID: [0:0:0:0:0:0:0:0:0]
User (ro): [snmpuser1]
Auth Protocol [MD5(1)/SHA(2)/noAuth(3)]: (1..3) [3]
Priv Protocol [DES(1)/noPriv(2)/3DES(3)/AES128(4)/AES192(5)/AES256(6)]):
(2..2) [2]
Engine ID: [0:0:0:0:0:0:0:0:0]
User (ro): [snmpuser2]
Auth Protocol [MD5(1)/SHA(2)/noAuth(3)]: (1..3) [3]
Priv Protocol [DES(1)/noPriv(2)/3DES(3)/AES128(4)/AES192(5)/AES256(6)]):
(2..2) [2]
Engine ID: [0:0:0:0:0:0:0:0:0]
User (ro): [snmpuser3]
Auth Protocol [MD5(1)/SHA(2)/noAuth(3)]: (1..3) [3]
Priv Protocol [DES(1)/noPriv(2)/3DES(3)/AES128(4)/AES192(5)/AES256(6)]):
```

```
(2..2) [2]
Engine ID: [0:0:0:0:0:0:0:0:0]
SNMPv3 trap recipient configuration:
Trap Recipient's IP address: [0.0.0.0] 192.0.2.2
UserIndex: (1..6) [1]
Trap recipient Severity level: (0..5) [0] 4
Trap recipient Port : (0..65535) [162]
Trap Recipient's IP address : [0.0.0.0] 192.0.10.10
UserIndex: (1..6) [2]
Trap recipient Severity level: (0..5) [0] 4
Trap recipient Port : (0..65535) [162]
Trap Recipient's IP address : [0.0.0.0]
Committing configuration....done.
```

NOTE: To receive the SNMP informs, the username, the authentication protocol, the privacy protocol, the UDP port number, and the engine ID must match between the switch and the management station.

3. Enter the snmpConfig --show snmpv3 command to verify the SNMP agent configuration.

```
switch:admin> snmpconfig --show snmpv3
SNMP Informs = 1 (ON)
SNMPV3 user password encrypted = 0 (OFF)
SNMPv3 USM configuration:
User 1 (rw): snmpadmin1
Auth Protocol: noAuth
Priv Protocol: noPriv
Engine ID: 80:00:05:23:01:0a:23:34:21
User 2 (rw): snmpadmin2
Auth Protocol: MD5
Priv Protocol: DES
Engine ID: 80:00:05:23:01:0a:23:34:1b
User 3 (rw): snmpadmin3
Auth Protocol: noAuth
Priv Protocol: noPriv
Engine ID: 00:00:00:00:00:00:00:00
User 4 (ro): snmpuser1
Auth Protocol: noAuth
Priv Protocol: noPriv
Engine ID: 00:00:00:00:00:00:00:00
User 5 (ro): snmpuser2
Auth Protocol: noAuth
Priv Protocol: noPriv
Engine ID: 00:00:00:00:00:00:00:00
User 6 (ro): snmpuser3
Auth Protocol: noAuth
Priv Protocol: noPriv
Engine ID: 00:00:00:00:00:00:00:00
SNMPv3 Trap configuration:
Trap Entry 1: 192.0.2.2
Trap Port: 162
Trap User: snmpadmin1
Trap recipient Severity level: 4
Trap Entry 2: 192.0.10.10
Trap Port: 162
Trap User: snmpadmin2
Trap recipient Severity level: 4
```

```
Trap Entry 3: No trap recipient configured yet
Trap Entry 4: No trap recipient configured yet
Trap Entry 5: No trap recipient configured yet
```

2.4.5 Port Logs

Fabric OS maintains an internal log of all port activity, with each switch or logical switch maintaining a log file for each port. Port logs are circular buffers that can save up to 8000 entries per logical switch. When the log is full, the newest log entries automatically overwrite the oldest log entries. Port logs capture switch-to-device, device-to-switch, switch-to-switch, some device-A-to-device-B, and control information. Port logs are not persistent and are lost over power cycles and reboots. Port log functionality is completely separate from the system message log. Port logs are typically used to troubleshoot device connections.

To display the port logs for a particular port, enter the portLogShow command.

To display the specific events logged for each port, enter the portLogEventShow command.

2.5 Changing the swEventTrap Severity Level

When an event occurs and the event severity level is at or below the set severity level, the SNMP event trap notification, swEventTrap, is sent to the configured trap recipients. By default, the severity level is set at 0 (None), resulting in all event traps being sent. Use the snmpConfig --set mibCapability command to modify the severity level of swEventTrap.

To change the severity level of swEventTrap, perform the following steps.

- 1. Log in to the switch as admin.
- 2. Enter the snmpConfig --set mibCapability command to configure MIBs interactively. All supported MIBs and associated traps are displayed. You can change the desired severity for swEventTrap to 1 (Critical), 2 (Error), 3 (Warning), or 4 (Informational). The default value is 0.

```
switch:admin> snmpconfig --set mibcapability
FE-MIB: YES
SW-MIB: YES
FA-MIB: YES
FICON-MIB: YES
HA-MIB: YES
FCIP-MIB: YES
ISCSI-MIB: YES
IF-MIB: YES
BD-MIB: YES
SW-TRAP: YES
                swFault: YES
                swSensorScn: YES
                swFCPortScn: YES
                swEventTrap: YES
                                 DesiredSeverity:Informational
                swFabricWatchTrap: YES
                                 DesiredSeverity:None
                swTrackChangesTrap: YES
                swIPv6ChangeTrap: YES
                swPmgrEventTrap: YES
                swFabricReconfigTrap: YES
                swFabricSegmentTrap: YES
                swExtTrap: NO
                swStateChangeTrap: NO
```

```
swPortMoveTrap: NO
                   swBrcdGenericTrap: YES
   ... <lines omitted for brevity>
   SW-TRAP (yes, y, no, n): [yes]
                   swFault (yes, y, no, n): [yes]
                   swSensorScn (yes, y, no, n): [yes]
                   swFCPortScn (yes, y, no, n): [yes]
   swEventTrap (yes, y, no, n): [yes]
   DesiredSeverity: (0..4) [4] 3
                   swFabricWatchTrap (yes, y, no, n): [yes]
                                    DesiredSeverity: (0..4) [0] 2
                   swTrackChangesTrap (yes, y, no, n): [yes]
                   swIPv6ChangeTrap (yes, y, no, n): [yes]
                   swPmgrEventTrap (yes, y, no, n): [yes]
   [...]
3. Enter the snmpConfig --show mibCapability command to verify the severity level of swEventTrap.
   switch:admin> snmpconfig --show mibcapability
   FE-MIB: YES
   SW-MIB: YES
   FA-MIB: YES
   FICON-MIB: YES
   HA-MIB: YES
   FCIP-MIB: YES
   ISCSI-MIB: YES
   IF-MIB: YES
   BD-MIB: YES
   SW-TRAP: YES
              swFault: YES
              swSensorScn: YES
```

DesiredSeverity:Informational

swFabricWatchTrap: YES
DesiredSeverity:Critical
swTrackChangesTrap: YES
swIPv6ChangeTrap: YES
swPmgrEventTrap: YES
swFabricReconfigTrap: YES

swFCPortScn: YES
swEventTrap: YES

[...]

2.6 Commands for Displaying and Configuring System Message Logs

Table 3 describes commands that you can use to view or configure the system message logs. Most commands require admin-level access privileges. For detailed information on required access levels and commands, refer to the *Brocade*[®] Fabric OS[®] Command Reference Manual.

Table 3: Commands for Viewing or Configuring System Parameters and Message Logs

Command	Description
auditCfg	Configures the audit message log.
auditDump	Displays or clears the audit log.
errClear	Clears all error log messages for all switch instances on this control processor (CP).

Table 3: Commands for Viewing or Configuring System Parameters and Message Logs (Continued)

Command	Description
errDelimiterSet	Sets the error log start and end delimiter for messages pushed to the console.
errDump	Displays the entire error log, without page breaks. Use the -r option to show the messages in reverse order, from newest to oldest.
errFilterSet	Sets an error severity filter for the system console.
errModuleShow	Displays all defined error log modules.
errShow	Displays the entire error log, with page breaks. Use the -r option to show the messages in reverse order, from newest to oldest.
pdShow	Displays the contents of the panic dump and core dump files.
portErrShow	Displays the port error summary.
portLogClear	Clears the port log. If the port log is disabled, this command enables it.
portLogDisable	Disables the port log facility.
portLogDump	Displays the port log, without page breaks.
portLogDumpPort	Displays the port log of the specified port, without page breaks.
portLogEnable	Enables the port log facility.
portLogEventShow	Displays which port log events are currently being reported.
portLoginShow	Displays port logins.
portLogPdisc	Sets or clears the debug pdisc_flag.
portLogReset	Enables the port log facility.
portLogResize	Resizes the port log to the specified number of entries.
portLogShow	Displays the port log, with page breaks.
portLogShowPort	Displays the port log of the specified port, with page breaks.
portLogTypeDisable	Prevents an event from being reported in the port log. Port log events are described by the portLogEventShow command.
portLogTypeEnable	Configures an event to be reported in the port log. Port log events are described by the portLogEventShow command.
rasAdmin	Used to enable or disable logging for selected messages or modules, to change the default severity level for a specified message, to display configured RASLog message settings, and to enable or disable quiet time.
rasMan	Displays message documentation on the switch.
setVerbose	Sets the verbose level of a particular module within the Fabric OS.
snmpConfig	Manages the SNMP agent configuration.
supportFfdc	Enables and disables FFDC.
supportFtp	Sets, clears, or displays support FTP parameters or a time interval to check the FTP server.
supportSave	Collects RASLog, trace files, and supportShow (active CP only) information for the local CP and then transfers the files to an FTP server. The operation can take several minutes.

Table 3: Commands for Viewing or Configuring System Parameters and Message Logs (Continued)

Command	Description
supportShow	Issues a list of diagnostic and error display commands. This output is used by your switch service provider to diagnose and correct problems with the switch. The output from this command is very long. Refer to the following related commands:
	supportShowCfgShow—Displays the groups of commands enabled for display by the supportShow command.
	supportShowCfgEnable—Enables a group of commands to be displayed under the supportShow command.
	supportShowCfgDisable—Disables a group of commands under the supportShow command.
syslogadminset - facility	Changes the syslogd facility.
syslogadminset - ip	Adds an IP address as a recipient of system messages.
syslogadmin remove -ip	Removes an IP address as a recipient of system messages.
syslogadminshow -	Displays the currently configured IP addresses that are recipients of system messages.
traceDump	Displays, initiates, or removes a Fabric OS module trace dump.

2.7 Displaying Message Content on the Switch

You can view the message documentation such as the message text, message type, class (for audit messages), message severity, cause, and action on the switch console by using the rasMan message ID command.

To display the message documentation on the switch, perform the following steps.

- 4. Log in to the switch as admin.
- 5. Use the rasMan message_ID command to display the message documentation. The message_ID values are case-sensitive.

The following example displays the documentation for the PS-1007 message.

```
switch:admin> rasman PS-1007
Log Messages
    PS-1007 (7m)
MESSAGE
     PS-1007 - Failed to add Fabricmode
                                                Top
                                                      Talker
                                                               on
     domain=<domain id>. <function name>.
MESSAGE TYPE
     LOG
SEVERITY
     WARNING
PROBABLE CAUSE
     Indicates that FC Routing (FCR) is enabled on the specified
     fabric.
RECOMMENDED ACTION
```

Top Talker cannot be installed on a fabric with FCR service enabled. In case Top Talker must be installed on a fabric, disable FCR using the fosconfig --disable fcr command.

2.8 Configuring System Messages and Attributes

This section provides information on configuring the system message logs and attributes. All admin-level commands mentioned in this section are used to enable or disable only the external messages.

2.8.1 Configuring Event Auditing

To configure event auditing, perform the following steps.

- 1. Log in to the switch as admin.
- 2. Enter the auditCfg --enable command to enable the audit feature.

```
switch:admin> auditcfg --enable
Audit filter is enabled.
```

3. Enter the auditcfg --class command to configure the event classes that you want to audit.

```
switch:admin> auditcfg --class 1,2,3,4,5,6,7,8,9
Audit filter is configured.
```

NOTE: The RAS audit class is not configurable, and it is always enabled internally.

4. Use the auditCfg --severity severity-level command to set the audit severity level. By default, all messages are logged. When the severity is set, only messages with the configured severity and higher are displayed. Valid values for severity-level are INFO, WARNING, ERROR, and CRITICAL

```
switch:admin> auditcfg --severity ERROR
```

5. Enter the auditCfg --show command to verify the configuration.

```
switch:admin> auditcfg --show
Audit filter is enabled.
1-ZONE
2-SECURITY
3-CONFIGURATION
4-FIRMWARE
5-FABRIC
7-LS
8-CLI
9-MAPS
Severity level: ERROR
```

You must configure the syslog daemon to send audit events to a configured remote host using the syslogdlpAdd command. For more information on configuring the syslog server, see "Configuring a Syslog Server" on page 23.

2.8.2 Disabling a RASLog Message or Module

To disable a single RASLog message or all messages in a module, perform the following steps.

- 1. Log in to the switch as admin.
- 2. Use the following commands to disable a single RASLog message or all messages that belong to a module:
 - The rasadmin --show -log message_ID command disables a RASLog message. The following example disables the BL-1001 message.

switch:admin> rasadmin --disable -log BL-1001

2017/07/20-13:30:41, [LOG-1005], 378, SLOT 4 | CHASSIS, INFO, switch, Log message NSM-1009 has been disabled.

Use the rasadmin --show -log message ID command to verify the status of the message.

The rasadmin --disable -module module_ID command disables all messages in a module. The following example disables all messages that belong to the BL module.

```
switch:admin> rasadmin --disable -module BL 2017/07/20-13:28:37, [LOG-1007], 375, SLOT 4 | CHASSIS, INFO, switch, Log Module BL has been disabled.
```

Use the rasadmin --show -module module ID command to verify the status of the messages that belong to a module.

NOTE: You cannot disable audit and FFDC messages using the rasadmin command.

2.8.3 Enabling a RASLog Message or Module

To enable a single RASLog message or all messages in a module that were previously disabled, perform the following steps.

- 1. Log in to the switch as admin.
- 2. Use the following commands to enable a single RASLog message or all messages that belong to a module:
 - The rasadmin --enable -log message_ID command enables a single RASLog message that has been disabled.
 The following example enables the BL-1001 message, which was previously disabled.

```
switch:admin > rasadmin --enable -log BL-1001
```

2017/10/15-13:24:30, [LOG-1006], 373, SLOT 4 | CHASSIS, INFO, switch, Log message BL-1001 has been enabled.

Use the rasadmin --show -log message ID command to verify the status of the message.

- The rasadmin --enable -module module_ID command enables all messages in a module. The following example enables all previously disabled BL messages.

```
switch:admin> rasadmin --enable -module BL
```

2017/10/15-13:28:37, [LOG-1007], 375, SLOT 4 | CHASSIS, INFO, switch, Log Module BL has been enabled.

Use the rasadmin --show -module module ID command to verify the status of the messages that belong to a module.

2.8.4 Setting the Severity Level of a RASLog Message

To change the default severity level of a RASLog message, perform the following steps.

- 1. Log in to the switch as admin.
- 2. Use the rasadmin --set -log message_ID -severity [DEFAULT | INFO | WARNING | ERROR | CRITICAL] command to change the severity level of a message. The following example changes the severity level of the C2-1004 message to WARNING.

```
switch:admin> rasadmin --set -log C2-1004 -severity WARNING
```

3. Use the rasadmin --show -severity message_ID command to verify the severity level of the message.

2.8.5 Enabling Quiet Time for a Specified Message Type

To enable quiet time for a specified message type, perform the following steps.

1. Log in to the switch as admin.

2. Use the rasadmin --quiet -enable log_type [-stime HH:MM] [-etime HH:MM] [-dow day_of_week] command to enable quiet time for the specified message type.

The following example enables quiet time for audit messages for a duration of forever.

```
switch:admin> rasadmin --quiet -enable 1
```

The following example enables quiet time for audit messages at 22:00 daily and turns it off the next day at 02:00.

```
switch:admin> rasadmin --quiet -enable 1 -stime 22:00 -etime 02:00
```

The following example enables quiet time for RASLog messages on Monday and Wednesday at 07:00 and turns off at 12:00

```
switch:admin> rasadmin --quiet -enable 2 -stime 07:00 -etime 12:00 -dow 1,3
```

The following example enables quiet time for both audit and RASlog messages for a duration of forever.

```
switch:admin> rasadmin --quiet -enable 3
```

2.8.6 Disabling Quiet Time for a Specified Message Type

To disable quiet time for a specified message type, perform the following steps.

- 1. Log in to the switch as admin.
- 2. Use the rasadmin --quiet -disable log_type command to disable quiet time for the specified message type.

The following example disables quiet time for audit messages.

```
switch:admin> rasadmin --quiet -disable 1
```

2.9 Displaying System Message Logs and Attributes

This section provides information on displaying system message logs. These procedures are valid for all supported platforms.

2.9.1 Displaying RASLog Messages

To display the system message log on a switch with no page breaks, perform the following steps. You can display the messages in reverse order using the reverse option. To display message logs in all switches (logical switches), use the all option.

- 1. Log in to the switch as admin.
- 2. Enter the errDump command.

```
switch:admin> errdump
Version: 8.2.0

2017/12/17-05:54:30, [HAM-1004], 1, CHASSIS, INFO, switch, Processor rebooted - Reset

2017/12/17-05:55:04, [ZONE-1034], 2, FID 128, INFO, switch, A new zone database file is created.

2017/12/17-05:55:04, [FCR-1069], 3, FID 128, INFO, switch, The FC Routing service is enabled.

2017/12/17-05:55:04, [FCR-1068], 4, FID 128, INFO, switch, The FC Routing service is disabled.

2017/12/17-05:55:11, [EM-1034], 5, CHASSIS, ERROR, switch, PS 2 set to faulty, rc=2000e.
```

[...]

2.9.2 Displaying RASLog Messages One Message at a Time

To display the system message log one message at a time, perform the following steps.

- 1. Log in to the switch as admin.
- 2. Enter the errshow command.

```
switch:admin> errShow
Version: 8.2.0a

2018/02/07-18:28:33, [SULB-1044], 3, CHASSIS, INFO, switch, Firmwaredownload to secondary partition
has completed successfully.

Type <CR> to continue, Q<CR> to stop:

2018/02/07-18:28:36, [FSSM-1002], 4, CHASSIS, INFO, switch, HA State is in sync.

Type <CR> to continue, Q<CR> to stop:

2018/02/07-18:28:39, [RAS-1007], 6, CHASSIS, INFO, switch, System is about to reload.

Type <CR> to continue, Q<CR> to stop:
[...]
```

2.9.3 Displaying Audit Messages

To display the audit messages, perform the following steps. The RAS-3005 message is generated for each CLI command issued on the switch and is saved in the audit message log.

- 1. Log in to the switch as admin.
- 2. Enter the auditDump -s command.

```
switch:admin> auditdump -s

938 AUDIT, 2018/02/22-10:58:01 (UTC), [MAPS-1020], WARNING, MAPS, NONE/root/NONE/None/CLI, ad_0/switch/FID 128, , Switch wide status has changed from HEALTHY to CRITICAL.

939 AUDIT, 2018/02/22-11:00:00 (UTC), [SULB-1004], INFO, FIRMWARE, NONE/root/NONE/None/CLI, ad_0/switch/CHASSIS, , Firmwarecommit has completed.

940 AUDIT, 2018/02/22-11:00:00 (UTC), [SULB-1002], INFO, FIRMWARE, NONE/root/NONE/None/CLI, ad_0/switch/CHASSIS, , Firmwaredownload command has completed successfully.

941 AUDIT, 2018/02/22-11:02:00 (UTC), [PORT-1008], INFO, CONFIGURATION, NONE/root/NONE/None/CLI, ad_0/switch/FID 128, , GigE Port (ID: 0) has been enabled.

942 AUDIT, 2018/02/22-11:06:29 (UTC), [SULB-1055], WARNING, FIRMWARE, NONE/root/NONE/None/CLI, ad_0/switch/FID 128, , Firmware upgrade on the blade in slot 0 has completed
[...]
```

2.9.4 Displaying FFDC Messages

To display the saved FFDC messages, perform the following steps.

1. Log in to the switch as admin.

2. Enter the errDump --attribute FFDC command.

```
switch:admin> errDump --attribute FFDC
Fabric OS: 8.2.0

2017/10/15-10:39:02, [LOG-1002], 4496, FFDC, WARNING, switch, A log
message was not recorded.

2017/10/15-10:39:18, [RAS-1001], 4496, FFDC, WARNING, switch, First
failure data capture (FFDC) event occurred.
[...]
```

2.9.5 Displaying the Status of System Messages

To display the status of system messages, perform the following steps.

- 1. Log in to the switch as admin.
- 2. Use the following commands to display the status of all messages in the log, the status of a specific message, or the status of all messages belonging to a module:
 - Enter the rasadmin --show -all command to display the status of all RASLog messages in the system log.

- Use the rasadmin --show -log message_ID command to display the status of a specified RASLog message.

```
switch:admin> rasadmin --show -log IPAD-1002
Message Status Default Severity Current Severity
    IPAD-1002 DISABLED INFO INFO
```

 Use the rasadmin --show -module module_ID command to display the status of all messages belonging to a specified module.

```
switch:admin> rasadmin --show -module ECC
Message Status Default Severity Current Severity
ECC-1000 ENABLED ERROR ERROR
ECC-1001 DISABLED ERROR WARNING
```

- Enter the rasadmin --show -disabled command to list all disabled RASLog messages.

```
switch:admin> rasadmin --show -disabled
Message
                      Status
CDR-1001
                      DISABLED
CDR-1003
                      DISABLED
              :
CDR-1004
              :
                      DISABLED
             :
ECC-1001
                      DISABLED
IPAD-1002
             :
                     DISABLED
```

2.9.6 Displaying the Severity Level of RASLog Messages

To display the severity level of a RASLog message, perform the following steps.

- 1. Log in to the switch as admin.
- 2. Use the rasadmin --show -severity message_ID command to display the severity level of a RASLog message. The following example displays the status of the PS-1007 message.

2.9.7 Displaying the Configured Quiet Time

To display the configured quiet time, perform the following steps.

- 3. Log in to the switch as admin.
- 4. Use the rasadmin --quiet -show command to display the configured quiet time.

2.9.8 Displaying RASLog Messages by Severity Level

To display RASLog messages based on the severity level, perform the following steps.

- 1. Log in to the switch as admin.
- 2. Use the <code>errdump --severity</code> [DEFAULT | INFO | WARNING | ERROR | CRITICAL] command. For more information on message severity levels, see "Message Severity Levels" on page 22. You can set the number of messages to display using the <code>count</code> option. The following example filters messages by the severity level of INFO.

```
switch:admin> errdump --count 4 --severity INFO
Fabric OS: 8.2.0a
2018/02/07-18:19:47, [LOG-1003], 1, CHASSIS, INFO, switch, The log has been cleared.

2018/02/07-18:28:33, [SULB-1044], 3, CHASSIS, INFO, switch, Firmwaredownload to secondary partition has completed successfully.

2018/02/07-18:28:36, [FSSM-1002], 4, CHASSIS, INFO, switch, HA State is in sync.

2018/02/07-18:28:39, [RAS-1007], 6, CHASSIS, INFO, switch, System is about to reload.
```

2.9.9 Displaying RASLog Messages by Message ID

To display RASLog messages based on message ID, perform the following steps.

- 1. Log in to the switch as admin.
- 2. Use the <code>errdump --message message_ID</code> command. The following example displays all instances of the message HAM-1004.

```
switch:admin> errdump --message HAM-1004
Fabric OS: 8.2.0a
2018/02/07-18:29:59, [HAM-1004], 7, CHASSIS, INFO, switch, Processor rebooted - FirmwareDownload.
2018/02/09-12:37:38, [HAM-1004], 58, CHASSIS, INFO, switch, Processor rebooted - FirmwareDownload.
2018/02/14-11:38:35, [HAM-1004], 167, CHASSIS, INFO, Switch, Processor rebooted - FirmwareDownload.
[...]
```

2.9.10 Displaying Messages on a Slot

To display the saved messages for a specific slot, perform the following steps.

- 1. Log in to the switch as admin.
- 2. Use the errdump --slot slot num command.

```
switch:admin> errdump --slot 2
Fabric OS: 8.2.0a

2018/02/14-15:42:27, [HAM-1004], 85, SLOT 2 | CHASSIS, INFO, switch, Processor rebooted -
HaFailover.

2018/02/14-15:42:27, [IPAD-1000], 86, SLOT 2 | CHASSIS, INFO, switch, SW/O Ether/O IPv6 manual
2620:100:0:f804:227:f8ff:fef2:c2a8/64 DHCP Off.

2018/02/14-15:42:27, [IPAD-1001], 88, SLOT 2 | CHASSIS, INFO, switch, CP/O IPv6 manual
fe80::21b:edff:fe0f:b600 DHCP Off.

2018/02/14-15:42:27, [IPAD-1001], 89, SLOT 2 | CHASSIS, INFO, switch, CP/O IPv6 manual
fe80::21b:edff:fe0c:bc00 DHCP Off.
[...]
```

NOTE: The slot option is not supported on non-bladed systems.

2.9.11 Viewing RASLog Messages from Web Tools

To view the system message log for a switch from Web Tools, perform the following steps.

- 1. Launch Web Tools.
- 2. Select the desired switch from the Fabric Tree. The Switch View displays.
- 3. Click the Switch Events tab. You can view the switch events and messages in the Switch Events Report displayed.

In dual-domain switches, an Event button exists for each logical switch. Only messages relating to that switch (and chassis) will be displayed.

2.10 Clearing System Message Logs

This section provides information on clearing system message logs. These procedures are valid for all supported platforms.

2.10.1 Clearing the System Message Log

To clear the system message log for a particular switch instance, perform the following steps.

- 1. Log in to the switch as admin.
- 2. Enter the errclear command to clear all messages from memory.

NOTE: For products that have a single processor, all error log messages are cleared. For products that have multiple processors, this command clears the error logs of only the processor from which it is issued.

2.10.2 Clearing the Audit Message Log

To clear the audit message log for a particular switch instance, perform the following steps.

- 1. Log in to the switch as admin.
- 2. Enter the auditDump -c command to clear all audit messages from memory.

2.11 Reading System Messages

This section provides information about reading the RASLog and audit messages.

2.11.1 Reading a RAS System Message

This section provides information about reading RAS system messages.

The following example shows the format of a RAS system error message.

<timestamp>, [<Event ID>], <Sequence Number>, <Flags>, <Severity>, <Switch name>, <Event-specific information>

The following example shows a sample message from the error log.

2018/02/27-15:36:22, [SS-1000], 629, CHASSIS, INFO, switch, supportSave has uploaded support information to the remote host.

2018/02/27-17:00:02, [SS-1001], 631, CHASSIS, WARNING, switch, supportSave's upload operation to remote host has been aborted.

The fields in the error message are described in Table 4.

Table 4:	System Message Field Description	

Variable Name	Description		
Timestamp	The system time (UTC) when the message was generated on the switch. The RASLog subsystem supports an international timestamp format based on the "LOCAL" setting.		
Event ID	The message module and number. These values uniquely identify each message in the Fabric OS and refer to the cause and recommended actions in this manual. Note that not all message numbers are used; there can be gaps in the numeric message sequence.		
Sequence Number	The error message position in the log. When a new message is added to the log, this number is incremented by 1.		
	The message sequence number starts at 1 after a firmwareDownload and will increase up to a value of 2,147,483,647 (0x7ffffff).		
	The sequence number continues to increase after the message log wraps around; that is, the oldest message in the log is deleted when a new message is added. The sequence number can be reset to 1 using the errclear command. The sequence number persists across power cycles and switch reboots.		

Table 4: System Message Field Description (Continued)

Variable Name	Description			
Flags	For most messages, this field contains a space character (null value) indicating that the message is neither an AUDIT message nor an FFDC message. Messages may contain the following values: FFDC—Indicates that additional First Failure Data Capture information has also been generated for this event. FID—The fabric ID, which can range from 0 to 128. FID 128 means that the message was generated by the default switch instance. CHASSIS—The message that was generated by the chassis instance. SLOT number—Indicates that the message was generated from the slot # blade main CPU. SLOT #/1—Indicates that the message was generated from the slot # blade Co-CPU.			
Severity	The severity of the error, which can be one of the following: 1 - CRITICAL 2 - ERROR 3 - WARNING 1 4 - INFO			
Switch name	The defined switch name or the chassis name of the switch depending on the action; for example, high availability (HA) messages typically show the chassis name, and login failures show the logical switch name. This variable takes only the first 16 characters and truncates the rest if it exceeds 16 characters in length. Run either the chassisName command to name the chassis or the switchName command to rename the logical switch.			
Event-specific information	A text string that explains the error encountered and provides parameters supplied by the software at runtime.			

2.11.2 Reading an Audit Message

Compared to RASLog error messages, messages flagged as AUDIT provide additional user and system-related information of interest for post-event auditing and troubleshooting.

The following example shows the format of an audit event message.

<Sequence Number> AUDIT, <timestamp>, [<Event ID>], <Severity>, <Event Class>, <User ID>/<Role>/
<IP address>/<Interface>/<Application Name>, <Admin Domain>/<Switch name>, <Reserved field for
future expansion>, <Event-specific information>

For syslog audit messages, the Fabric OS version and six reserved fields are displayed in the message.

The following is a sample audit event message.

0 AUDIT, 2005/12/10-09:54:03, [SEC-1000], WARNING, SECURITY, JohnSmith/root/192.0.2.2/Telnet/CLI, Domain A/JohnsSwitch, Incorrect password during login attempt.

The fields in the error message are described in Table 5. Table 5: Audit Message Field Description

Variable Name	Description		
Sequence Number	The error message position in the log.		
Audit flag	Identifies the message as an audit message.		
Timestamp	The system time (UTC) when the message was generated on the switch. The RASLog subsystem supports an international timestamp format based on the "LOCAL" setting. The message module and number. These values uniquely identify each message in the Fabric OS and refer to the cause and recommended actions in this manual. Note that not all message numbers are used; there can be gaps in the numeric message sequence.		
Event ID			
Severity	The severity of the error, which can be one of the following: 1 - CRITICAL 2 - ERROR 3 - WARNING 4 - INFO		
Event Class	The event class, which can be one of the following: CFG CLI FABRIC FIRMWARE LS MAPS RAS SECURITY ZONE		
User ID	The user ID.		
Role	The role of the user.		
IP address	The IP address.		
Interface	The interface being used.		
Application Name	The application name being used on the interface.		
Admin Domain	The admin Domain, if there is one.		
Switch name	The defined switch name or the chassis name of the switch depending on the action; for example, HA messages typically show the chassis name, and login failures show the logical switch name. This variable takes only the first 16 characters and truncates the rest if it exceeds 16 characters in length. Use the chassisName command to name the chassis or the switchName command to rename the logical switch.		
Reserved field for future expansion	This field is reserved for future use and contains a space character (null value).		
Event-specific information	A text string that explains the error encountered and provides parameters supplied by the software at runtime.		

2.12 Responding to System Messages

This section provides procedures on gathering information about system messages.

2.12.1 Looking Up a System Message

Messages documented in this manual are arranged alphabetically by module ID and then numerically within a given module. To look up a message, copy down the module (see Table 6) and the error code and compare this information with the table of contents or lookup lists to determine the location of the information for that message.

The following information is provided for each message:

- Module and code name for the error
- Message text
- Message type
- Class (for audit messages only)
- Message severity
- Probable cause
- Recommended action

2.12.2 Gathering Information about the Problem

Ask yourself the following questions when troubleshooting a system message:

- What is the current Fabric OS level?
- What is the switch hardware version?
- Is the switch operational?
- Assess the impact and urgency:
 - Is the switch down?
 - Is it a standalone switch?
 - How large is the fabric?
 - Is the fabric redundant?
- Document the sequence of events:
 - What happened just prior to the problem?
 - Is the problem repeatable?
 - If so, what are the steps to reproduce the problem?
 - What configuration was in place when the problem occurred?
- Did a failover occur?
- Was security enabled?
- Was POST enabled?
- Are serial port (console) logs available?
- Which CP was the master?
- What and when were the last actions or changes made to the system?

Common steps to follow when troubleshooting a system message:

- Use the errDump command on each logical switch.
- Use the supportFtp command (as needed) to set up automatic FTP transfers, and then run the supportSave command.

2.12.3 Troubleshooting Files for Support Personnel

Fabric OS creates a number of files that can help support personnel troubleshoot and diagnose a problem. This section describes those files and how to access or save the information for support personnel.

2.12.3.1 Panic Dump and Core Dump Files

Fabric OS creates panic dump files and core dump files when there are problems in the Fabric OS kernel. You can view panic dump files using the pdshow command. These files can build up in the kernel partition (typically because of failovers) and might need to be periodically deleted or downloaded using the supportSave command.

The software watchdog process (SWD) is responsible for monitoring daemons that are critical to the function of a healthy switch. The SWD holds a list of critical daemons that ping the SWD periodically at a predetermined interval defined for each daemon. The ping interval is set at 133 seconds, with the exception of the Fabric Watch daemon and the IP Storage daemon, which ping the SWD every 333 seconds. (For a complete list of daemons, see KSWD entry in Table 6.)

If a daemon fails to ping the SWD within the defined interval or if the daemon terminates unexpectedly, the SWD dumps information to the panic dump files, which help to diagnose the root cause of the unexpected failure.

Enter the pdshow command to view these files or the supportsave command to send them to a host workstation using FTP. The panic dump files and core dump files are intended for support personnel use only.

2.12.3.2 Trace Dumps

Fabric OS produces trace dumps when problems are encountered within Fabric OS modules. These files are intended for support personnel use only. You can use the <code>supportSave</code> or <code>supportFTP</code> commands to collect and send trace dump files to a specified remote location to provide to support when requested. Trace dumps must be enabled and set up on the switch to detect the first event. Note that there is only one trace buffer on a switch.

2.12.3.3 supportSave Command

The supportSave command can be used to send the output of the system messages (RASLog), the trace files, and the supportShow command to an off-switch storage location through FTP. Before running the supportSave command, you can optionally set up the FTP parameters using the supportFtp command. The supportShow command runs a large number of dump and show commands to provide global output of the status of the switch. After the supportSave operation is completed, you must enter the supportSave -r command to remove all unwanted files. Refer to the Brocade® Fabric OS® Command Reference Manual for more information on these commands.

2.13 System Module Descriptions

Table 6 provides a summary of the system modules for which messages are documented in this manual; the system modules are listed alphabetically by name. A module is a subsystem in the Fabric OS. Each module generates a set of numbered messages.

Table 6: System Module Descriptions

System Module	Description				
AG	Access Gateway (AG) allows multiple hosts (or HBAs) to access the fabric using fewer physical ports. Access Gateway mode transforms Brocade switches and embedded switches into a device management tool that is compatible with different types of fabrics, including Brocade-, Cisco-, and McDATA-based fabrics.				
AMPM	AMPM RASLog messages indicate notifications from the Multipath module on the DP of the Analytics Monitoring Platform.				
AN	Error or warning messages from the Bottleneck Detection module, including notification of detected bottlenecks.				
ASVR	The ASVR module messages indicate any problems associated with the application server, including issues with registration of virtual machines and/or containers within the fabric.				
AUTH	Authentication error messages indicate problems with the authentication module of the Fabric OS.				
BCM	The BCM kernel module is a Linux driver that manages and indicates any problems associated with the Broadcom Ethernet switch for 10G/40G ports.				
BL	BL error messages are a result of faulty hardware, transient out-of-memory conditions, ASIC errors, or inconsistencies in the software state between a blade and the environment monitor (EM) module.				
BLS	Fibre Channel over IP port configuration messages over the Brocade 7800 and FX8-24 blade				
BLZ	BLZ module messages indicate any problems associated with Fibre Channel over IP (FCIP) datapath processing and configurations.				
ВМ	Blade management error messages are a result of autoleveling firmware upgrades performed by the control processor (CP).				
C2	C2 error messages indicate problems with the 8Gb/s-capable FC module of the Fabric OS.				
C3	C3 error messages indicate problems with the 16Gb/s-capable FC module of the Fabric OS.				
C4	C4 error messages indicate problems with the 32Gb/s-capable FC module of the Fabric OS.				
CAL	Common Access Layer (CAL) provides an XML interface for configuring switch parameters in an object model.				
CCFG	CCFG error messages indicate problems with the Converged Enhanced Ethernet (CEE) configuration module of the Fabric OS.				
CDR	Driver error messages.				
CFS	Congestion Free SAN is used by the Traffic Optimizer feature to optimize SAN traffic by isolating traffic into different performance groups. Performance groups are automatically determined based on predefined attributes such as destination speed and priority, and they use a dedicated resource path within the fabric.				
CH	Command history messages indicate when the clihistory command changes the behavior of recording the command line interface (CLI) session.				
CHS	Error messages reporting the problems in the management of blades in different slots of the chassis.				

System Module	Description			
CNM	Cluster Node Manager (CNM) is a software daemon module of Fabric OS. The messages from CNM indicate problems encountered by CNM, warnings, or information to the user of events.			
CNMC	Controller Area Network Management Interface Controller (CANMIC) module is a software daemon module of Fabric OS. This module interacts with the Enclosure Manager through the CANMIC and reports information and error messages to the user.			
CONF	Status messages for configupload and configDownload operations.			
СТАР	A user-space daemon that forwards non-performance-critical messages from the TAPE driver to the Crypto Virtual LUN Controller (CVLC) and Security Processor (SP), and vice versa. This module also maintains a cache of recently acquired keys, reducing requests to the key vault itself.			
CVLM	Crypto Virtual LUN Manager (CVLM) is a software module of Fabric OS. CVLM messages indicate problems encountered by CVLM, warnings to alert the user, or information to the user			
DOT1	DOT1 error messages indicate problems with the 802.1x authentication module of Fabric OS.			
ECC	Error Checking and Correction (ECC) error messages indicate single-bit and multiple-bit errors in dynamic random access memory (DRAM) devices. ECC is a technology that helps to correct memory errors.			
EM	The Environmental Monitor (EM) manages and monitors the various field-replaceable units (FRUs), including the port cards, control processor (CP) blades, blower assemblies, power supplies, and World Wide Name (WWN) cards. The EM controls the state of the FRUs during system startup, hot-plug sequences, and fault recovery. The EM provides access to and monitors the sensor and status data from the FRUs and maintains the integrity of the system using the environmental and power policies. The EM reflects system status by CLI commands, system light-emitting diodes (LEDs), and status and alarm messages. The EM also manages some component-related data.			
ERCP	Error Reporting Control Process (ERCP) messages capture the corenet and memory subsystem errors.			
ESM	The Extension Services Module (ESM) provides management control and reporting for extension features such as FCIP and IPEX as well as their associated configurations.			
ESS	Exchange Switch Support (ESS) error messages indicate problems with the ESS module of Fabric OS. ESS is an SW_ILS mechanism used by switches to exchange vendor and support information.			
ESW	ESW error messages indicate problems with the Ethernet switch module of Fabric OS.			
EVMD	EVMD is the event management module.			
FABR	FABRIC refers to a network of Fibre Channel switches. The FABR error messages come from the fabric daemon. The fabric daemon follows the FC-SW-3 standard for the fabric initialization process, such as determining the E_Ports, assigning unique domain IDs to switches, creating a spanning tree, throttling the trunking process, and distributing the domain and alias lists to all switches in the fabric.			
FABS	Fabric OS system driver module.			
FBC	Firmware blade compatibility errors with the control processor (CP).			
FCMC	Fibre Channel miscellaneous messages relate to problems with the physical layer used to send Fibre Channel traffic to and from the switch.			

Table 6: System Module Descriptions (Continued)

System Module	Description
FCPD	The Fibre Channel Protocol daemon is responsible for probing the devices attached to the loop port. Probing is a process that the switch uses to find the devices attached to the loop ports and to update the Name Server with the information.
FCPH	The Fibre Channel Physical Layer module is used to send Fibre Channel traffic to and from the switch.
FCR	Fibre Channel router-related traffic and activity on the fabric or back-end fabric.
FICN	The FICN messages are generated during FICON emulation processing on an FCIP tunnel.
FICU	The FICON-CUP daemon handles communication with fibre connectivity (FICON) on IBM FICON storage devices. Errors to this module are usually initiation errors or indications that FICON-CUP prerequisites have not been met, such as a license key, core process ID (PID), and secure mode on the fabric.
FKLB	Fabric OS I/O kernel library module.
FLOD	FLOD is a part of the Fabric Shortest Path First (FSPF) protocol that handles synchronization of the link state database (LSDB) and propagation of the link state records (LSRs).
FSPF	Fabric Shortest Path First (FSPF) is a link state routing protocol that is used to determine how frames should be routed. These messages are about protocol errors.
FSS	The Fabric OS state synchronization framework provides facilities by which the active control processor (CP) can synchronize with the standby CP, enabling the standby CP to take control of the switch nondisruptively during failures and software upgrades. These facilities include version negotiation, state information transfer, and internal synchronization functions, enabling the transition from standby to active operation.
	FSS is defined both as a component and a service. A <i>component</i> is a module in the Fabric OS that implements a related set of functionality. A <i>service</i> is a collection of components grouped together to achieve a modular software architecture.
FSSM	The Fabric OS State Synchronization Management module is defined both as a component and a service. A <i>component</i> is a module in Fabric OS, that implements a related set of functionality. A <i>service</i> is a collection of components grouped together to achieve a modular software architecture.
FTC	Fabric Traffic Controller is the module responsible for traffic feedback to and from the fabric and connected devices. It handles the registration and delivery of Fabric Performance Impact Notifications (FPINs) and hardware congestion signals.
FV	Flow Vision provides end-to-end visibility into fabric performance. SAN administrators can monitor, troubleshoot, and identify problems in the traffic without disrupting the data path.
HAM	HAM is a user-space daemon responsible for high availability management.
HAMK	This is the kernel module for the High Availability Management (HAM) daemon.
HIL	Hardware independent layer.
HLO	HLO is a part of the Fabric Shortest Path First (FSPF) protocol that handles the HELLO protocol between adjacent switches. The HELLO protocol is used to establish connectivity with a neighbor switch, to establish the identity of the neighbor switch, and to exchange FSPF parameters and capabilities.
HMON	Health monitor.
HSL	HSL error messages indicate problems with the Hardware Subsystem Layer of Fabric OS.
HTTP	HTTP error messages.

Table 6: System Module Descriptions (Continued)

System Module	Description
IPAD	System messages generated by the IP admin demon.
IPS	Fibre Channel over IP license, tunneling, and port-related messages.
ISNS	ISNS server and client status messages.
KAC	KAC error messages indicate problems associated with Fabric OS and external key vaults.

Table 6: System Module Descriptions (Continued)

System Module

Description

KSWD

The kernel software watchdog (KSWD) watches daemons for unexpected terminations and "hang" conditions and informs the HAM module to take corrective actions such as failover or reboot.

The following daemons are monitored by KSWD:

- Access Gateway daemon (agd)
- Alias Server daemon (asd)
- ARR daemon (arrd)
- Authentication daemon (authd)
- Blade Manager daemon (bmd)
- Cluster Node Manager daemon (cnmd)
- Common Access Layer daemon (cald)
- DAUTH daemon (dauthd)
- Diagnostics daemon (diagd)
- Environment Monitor daemon (emd)
- Event Manager daemon (evmd)
- Exchange Switch Support daemon (essd)
- FA-API rpc daemon (rpcd)
- Fabric daemon (fabricd)
- Fabric Device Management Interface daemon (fdmid)
- Fibre Channel Protocol daemon (fcpd)
- FICON CUP daemon (ficud)
- FSPF daemon (fspfd)
- IGMP daemon (igmpd)
- IMI daemon (imid)
- Inter-fabric Routing daemon (iswitchd)
- IP Storage daemon (ipsd)
- ISNS Client daemon on CP (isnscd)
- KAC daemon (kacd)
- Layer 2 System daemon (I2sysd)
- LFM daemon (Ifmd)
- Link Aggregation Control Protocol daemon (lacpd)
- Management Server daemon (msd)
- MM daemon (mmd)
- Multicast Sub-System daemon (mcast ssd)
- Multiple Spanning Tree Protocol daemon (mstpd)
- Name Server daemon (nsd)
- NSM daemon (nsmd)
- ONM daemon (onmd)
- Parity Data Manager daemon (pdmd)
- Proxy daemon (proxyd)
- PS daemon (psd)
- RASLOG daemon (raslogd)
- RCS daemon (rcsd)
- RM daemon (rmd)
- RMON daemon (rmond)
- Security daemon (secd)
- Sigma daemon (sigmad)
- SNMP daemon (snmpd)

System				
Module	Description			
KSWD	 SP Management daemon (spmd) SVP daemon (svpd) System Services Module daemon (ssmd) Time Service daemon (tsd) TRACE daemon (traced) Traffic daemon (trafd) UFCS daemon (ufcsd) VS daemon (vsd) Web Linker daemon (weblinkerd) Web Tools daemon (webd) ZONE daemon (zoned) 			
KTRC	Kernel RAS trace module.			
L2SS	L2SYS error messages indicate problems with the Layer 2 system manager that controls the Layer 2 forwarding engine and the learning/aging/forwarding functionality.			
L3SS	L3SYS error messages indicate problems with the Layer 3 system manager that controls the IP routing table in hardware and Linux IP stack.			
LACP	LACP error messages indicate problems with the Link Aggregation Control Protocol module of Fabric OS.			
LFM	LFM error messages indicate problems with the Logical Fabric Manager module, which is responsible for making a logical switch use XISLs. This involves creating and managing LISLs in a logical fabric.			
LIC	The License module indicated the problem with license installation and removal operations			
LOG	RASLog subsystem.			
LSDB	The link state database is a part of the FSPF protocol that maintains records on the status of port links. This database is used to route frames.			
MAPS	The MAPS module identifies and reports anomalies associated with the various error counters, thresholds, and resources monitored on the switch.			
MCAST_SS	The Multicast Sub-System messages indicate problems associated with the Layer 2 and Layer 3 multicast platform support, including allocation of global platform resources such as MGIDs, hardware acceleration resources for multicast, and route programming into the hardware (Layer 2 EXM for IGMP looping).			
MFIC	MS-FICON messages relate to Fibre Connection (FICON) installations. Fibre Connection control unit port (FICON-CUP) messages are displayed under the FICU module.			
MM	MM messages indicate problems with the management modules.			
MPTH	Multicast path uses the shortest Path First (SPF) algorithm to dynamically compute a broadcast tree.			
MQ	Message queues are used for interprocess communication. Message queues allow many messages, each of variable length, to be queued. Any process or interrupt service routine (ISR) can write messages to a message queue. Any process can read messages from a message queue.			

Table 6:	System M	Iodule Descri	ptions	(Continued)	

System Module	Description				
MS	The Management Service (MS) enables the user to obtain information about the Fibre Channel fabric topology and attributes by providing a single management access point. MS provides for both monitoring and control of the following servers:				
	 Fabric Configuration Server: Provides for the configuration management of the fabric. 				
	 Unzoned Name Server: Provides access to Name Server information that is not subject to zone constraints. 				
	 Fabric Zone Server: Provides access to and control of zone information. 				
MSTP	MSTP error messages indicate problems with Multiple Spanning Tree Protocol modules of Fabric OS.				
NBFS	NBFSM is a part of the Fabric Shortest Path First (FSPF) protocol that handles a neighboring or adjacent switch's finite state machine (FSM).				
	Input to the FSM changes the local switch from one state to another, based on specific events. For example, when two switches are connected to each other using an inter-switch link (ISL) cable, they are in the Init state. After both switches receive HELLO messages, they move to the Database Exchange state, and so on. NBFSM states are Down (0), Init (1), Database Exchange (2), Database Acknowledge Wait (3),				
	Database Wait (4), and Full (5).				
NS	Indicates problems with the simple Name Server module.				
NSM	NSM error messages indicate problems with the Interface Management and VLAN Management module of Fabric OS.				
ONMD	ONMD error messages indicate problems with the Operation, Administration and Maintena module of Fabric OS.				
PDM	Parity Data Manager (PDM) is a user-space daemon responsible for the replication of persiste configuration files from the primary partition to the secondary partition and from the active Cl blade to the standby CP blade.				
PDTR	PDTR messages indicate that panic dump trace files have been created.				
PLAT	PLAT messages indicate hardware problems.				
PMGR	A group of messages that relate to logical switch creation, deletion, and configuration.				
PORT	PORT error messages refer to the front-end user ports on the switch. Front-end user ports directly accessible by users to connect end devices or connect to other switches.				
PS	The Performance Server daemon measures the amount of traffic between endpoints or traffic with particular frame formats, such as SCSI frames, IP frames, and customer-defined frames.				
PSWP	The portswap feature and associated commands generate these error messages.				
QOSD	Quality of Service daemon (QOSD) maintains the CEE-map configuration and applies it to port in the ASIC. QoS specifies a priority value between 0 and 7 (inclusive) that can be used differentiate the traffic.				
RAS	Informational messages when First Failure Data Capture (FFDC) events are logged to the FFDC log or when there is a roll-over warning.				
RCS	The Reliable Commit Service daemon generates log entries when it receives a request from the zoning, security, or management server for passing data messages to switches in the fabric. RCS then requests reliable transport write and read (RTWR) to deliver the message. RCS also acts as a gatekeeper, limiting the number of outstanding requests for the Zoning, Security, or Management Server modules.				
RMON	RMON messages are error or informational messages pertaining to the RMOND daemon.				

Table 6: System Module Descriptions (Continued	Table 6:	System Mo	dule Descri	ptions (Continued
--	----------	-----------	-------------	----------	-----------

System Module	Description				
RPCD	The Remote Procedure Call daemon (RPCD) is used by Fabric Access for API-related tasks.				
RTE	RTE is responsible for determining the correct paths for each ingress frame and populating routing tables in the ASICs with this information. The ASICs then use the information available in the routing tables to determine the path that a particular ingress frame needs to take be it exits the switch.				
RTWR	The Reliable Transmit With Response service helps deliver data messages to specific switches in the fabric or to all switches in the fabric. For example, if some switches are not reachable or are off line, RTWR returns an "unreachable" message to the caller, allowing the caller to take the appropriate action. If a switch is not responding, RTWR retries 100 times.				
SCN	The internal State Change Notification daemon is used for state change notifications from the kernel to the daemons within Fabric OS.				
SEC	The Security daemon generates security errors, warnings, or information during security-related data management or fabric merge operations. Administrators should watch for these message to distinguish between internal switch and fabric operation errors and external attacks.				
SFLO	sFlow is a standard-based sampling technology embedded within switches and routers that is used to monitor high-speed network traffic for Data Center Ethernet (DCE) and Converged Enhanced Ethernet (CEE) platforms. sFlow uses two types of sampling:				
	 Statistical packet-based sampling of switched or routed packet flows Time-based sampling of interface counters SFLO messages indicate errors or information related to the sflowd daemon. 				
SLNK	Brocade Support Link (BSL) automates many support and troubleshooting activities for customer environments and provides additional insight through reports and analysis. When enabled, a switch automatically gathers and sends the encrypted Brocade device configuration event information, and health and performance metrics to the Brocade Support Link Server (SLS) on a regular basis.				
SNMP	Simple Network Management Protocol (SNMP) is a universally supported low-level protocol that allows simple get, get next, and set requests to go to the switch (acting as an SNMP agent). It also allows the switch to send traps to the defined and configured management station. Brocade switches support six management entities that can be configured to receive these traps.				
SPM	Error messages that indicate problems with key or SP management.				
SS	The supportSave command generates these error messages if problems are encountered.				
SSLP	The SSLP module messages indicate problems associated with the launch of open SLP processes in the switch.				
SSMD	SSMD error messages indicate problems with the System Services Module of the Fabric OS.				
SULB	The software upgrade library provides the firmwareDownload command capability, which enables firmware upgrades to both CP blades with a single command and nondisruptive code load to all Fabric OS switches. These messages might display if there are problems during the firmwareDownload procedure. Most messages are informational only and are generated every during successful firmware download. For additional information, refer to the Brocade® Fabric OS® Administration Guide.				
SWCH	These messages are generated by the switch driver module that manages a Fibre Chanr switch instance.				

Table 6: System Module Descriptions (Continued)

System Module	Description		
SYSC	System Controller is a daemon that starts up and shuts down all Fabric OS modules in the proper sequence.		
SYSM	General system messages.		
TRCE	RAS TRACE error messages.		
TS	Time Service provides fabric time synchronization by synchronizing all clocks in the fabric to the clock time on the principal switch.		
UCID	The UCID (Unified Configuration Infrastructure Daemon) module manages all the configurations of FCoE and Layer 2 protocols.		
UCST	UCST is a part of the Fabric Shortest Path First (FSPF) protocol that manages the unicast routing table.		
UFCS	The UFCS (Universal Fabric Configuration Service) module manages the distribution and merging of data for its client.		
UPTH	UPATH is a part of the FSPF protocol that uses the SPF algorithm to dynamically compute a unicast tree.		
VS	The VS module messages indicate problems or information associated with the Dynamic Fabric Provisioning feature, including commands associated with the fapwwn command and configurations.		
WEBD	WEBD module messages indicate problems with the Web Tools module.		
XTUN	XTUN messages are generated by the FCIP tunnel implementation. These messages indicate the status of FCIP tunnels, FCIP emulation events for FCP traffic, or FCIP debug information (FTRACE buffer status changes).		
ZONE	Zone module messages indicate problems associated with the zoning features, including commands associated with aliases, zones, and configurations.		

Chapter 3: Audit Messages

3.1 AG Messages

AG-1006

AG-1033

AG-1034

AG-1035

AG-1036

AG-1037

AG-1046

AG-1047

AG-1048

AG-1049

AG-1050

AG-1051

AG-1052

AG-1053

AG-1054

AG-1055

AG-1056

AG-1057

AG-1058

AG-1059

AG-1060

AG-1061

AG-1062

AG-1063

AG-1064

FOS-90x-Message-RM103 Broadcom

AG-1065

AG-1066

AG-1067

AG-1068

AG-1069

AG-1070

AG-1071

AG-1072

AG-1073

AG-1074

AG-1075

AG-1076 AG-1077

AG-1078

AG-1079

AG-1080

AG-1081

AG-1082

AG-1083

AG-1084

AG-1091

3.2 AN Messages

AN-1010

AN-1011

AN-1012

AN-1013

AN-1014

3.3 AUTH Messages

AUTH-1045

AUTH-1046

AUTH-1047

AUTH-1048

AUTH-3001

AUTH-3002

AUTH-3003

AUTH-3004

AUTH-3005

AUTH-3006

AUTH-3007

AUTH-3008

3.4 BCM Messages

BCM-1002

BCM-1003

3.5 BCMG Messages

BCMG-1002

BCMG-1003

3.6 BLS Messages

BLS-1002

BLS-1003

3.7 BLZ Messages

BLZ-1002

BLZ-1003

3.8 CCFG Messages

CCFG-1002

CCFG-1003

3.9 CH Messages

CH-1001

CH-1002

3.10 CHS Messages

CHS-1006

CHS-1007

CHS-1008

3.11 CNM Messages

CNM-3001

CNM-3002

CNM-3003

CNM-3004

CNM-3005

CNM-3006

CNM-3007

CNM-3008

CNM-3009

CNM-3010

CNM-3011

CNM-3012

3.12 CONF Messages

CONF-1000

CONF-1001

CONF-1020

CONF-1022

CONF-1032

CONF-1033

CONF-1042

CONF-1043

CONF-1044

CONF-1045

CONF-1046

CONF-1047

CONF-1048

CONF-1049

CONF-1050

CONF-1051

CONF-1052

CONF-1053

3.13 EM Messages

EM-1223

EM-1224

EM-1225

EM-1226

3.14 ESM Messages

ESM-1103

ESM-1104

ESM-1105

ESM-2000

ESM-2001

ESM-2002

ESM-2010

ESM-2011

ESM-2012

ESM-2100

ESM-2101

ESM-2102

ESM-2103

ESM-2200

ESM-2201

ESM-2202

ESM-2203

ESM-2300

ESM-2301

ESM-2302

ESM-2303

ESM-2329

ESM-2400

ESM-2700

ESM-2701

ESM-2702

ESM-2703

ESM-2801

ESM-2802

ESM-2803

3.15 ESS Messages

ESS-1008

ESS-1009

ESS-1010

ESS-1011

3.16 FABR Messages

FABR-1051

FABR-1062

FABR-3000

3.17 FCR Messages

FCR-1068

FCR-1069

FCR-1071

FCR-1072

FCR-1088

FCR-1089

FCR-1091

FCR-1114

FCR-1119

FCR-1120

FCR-1121

FCR-1122

FCR-1123

FCR-1124

3.18 FICU Messages

FICU-1011

FICU-1012

FICU-1019

FICU-1020

FICU-1021

FICU-1035

3.19 FV Messages

FV-3000

FV-3001

FV-3002

FV-3003

FV-3004

FV-3005

FV-3006

FV-3007

FV-3008

FV-3009

FV-3010

FV-3011

FV-3012

FV-3013

FV-3014

FV-3015

FV-3016

FV-3017

3.20 HAM Messages

HAM-1015

HAM-1017

HAM-1018

3.21 HTTP Messages

HTTP-1002

HTTP-1003

HTTP-3001

HTTP-3002

HTTP-3003

HTTP-3004

HTTP-3005

HTTP-3006

3.22 IPAD Messages

IPAD-1000

IPAD-1001

IPAD-1002

IPAD-1003

IPAD-1004

IPAD-1005

IPAD-1006

3.23 IPS Messages

IPS-1008

IPS-1009

IPS-1010

3.24 LFM Messages

LFM-1007

3.25 LIC Messages

LIC-1000

LIC-1001

LIC-2000

LIC-2001

LIC-2002

LIC-2003

3.26 LOG Messages

LOG-1003

LOG-1005

LOG-1006

LOG-1007

LOG-1008

LOG-1009

LOG-1010

LOG-1011

LOG-1012

LOG-1013

3.27 MAPS Messages

MAPS-1015

MAPS-1016

MAPS-1017

MAPS-1018

MAPS-1020

MAPS-1021

MAPS-1100

MAPS-1101

MAPS-1102

MAPS-1110

MAPS-1111

MAPS-1112

MAPS-1113

MAPS-1114

MAPS-1115

MAPS-1116

MAPS-1120

MAPS-1121

MAPS-1122

MAPS-1123

MAPS-1124

MAPS-1125

MAPS-1130

MAPS-1131

MAPS-1132

MAPS-1133

MAPS-1134

MAPS-1135

MAPS-1136

MAPS-1137

MAPS-1140

MAPS-1141

MAPS-1142

MAPS-1143

MAPS-1144

MAPS-1145

MAPS-1146

MAPS-1147

MAPS-1148

MAPS-1201

MAPS-1202

MAPS-1203

MAPS-1206

MAPS-1207

MAPS-1208

MAPS-1209

MAPS-1210

3.28 MS Messages

MS-1027

MS-1028

MS-1029

MS-1030

3.29 PMGR Messages

PMGR-1001

PMGR-1003

PMGR-1005

PMGR-1007

PMGR-1009

PMGR-1011

PMGR-1012

PMGR-1013

3.30 PORT Messages

PORT-1006

PORT-1007

PORT-1008

PORT-1009

PORT-1012

PORT-1013

PORT-1014

PORT-1015

PORT-1016

PORT-1017

PORT-1018

PORT-1019

PORT-1020

PORT-1021

PORT-1022

PORT-1023

PORT-1024

PORT-1025

PORT-1026

PORT-1027

PORT-1028

PORT-1029

PORT-1030

PORT-1031

PORT-1032

PORT-1033

PORT-1034

PORT-1035

PORT-1036

PORT-1037

PORT-1038

PORT-1039

PORT-1040

PORT-1041

PORT-1042

PORT-1043

PORT-1044

PORT-1045

PORT-1046

PORT-1047

PORT-1048

PORT-1049

PORT-1050

PORT-1051

PORT-1052

PORT-1053

PORT-1054

PORT-1055

PORT-1056

PORT-1057

PORT-1059

PORT-1060

PORT-1061

PORT-1062

3.31 PSWP Messages

PSWP-1004

PSWP-1008

3.32 RAS Messages

RAS-1007

RAS-1009

RAS-1010

RAS-1011

RAS-1012

RAS-1013

RAS-1014

RAS-1015

RAS-1016

RAS-2001

RAS-2002

RAS-2003

RAS-2004

RAS-2005

RAS-2006

RAS-2007

RAS-2008

RAS-2009

RAS-2010

RAS-2011

RAS-2012

RAS-2013

RAS-2014

RAS-2015

RAS-3005

RAS-3006

RAS-3007

RAS-3008

3.33 SEC Messages

SEC-1113

SEC-1114

SEC-1337

SEC-1341

SEC-1344

SEC-1346

SEC-3001

SEC-3002

SEC-3003

SEC-3004

SEC-3005

SEC-3006

SEC-3007

SEC-3008

SEC-3009

SEC-3010

SEC-3011

SEC-3012

SEC-3013

SEC-3014

SEC-3015

SEC-3016

SEC-3018

SEC-3019

SEC-3020

SEC-3021

SEC-3022

SEC-3023

SEC-3024

SEC-3025

SEC-3026

SEC-3027

SEC-3028

SEC-3029

SEC-3030

SEC-3031

SEC-3032

SEC-3033

SEC-3034

SEC-3035

SEC-3036

SEC-3037

SEC-3038

SEC-3039

SEC-3043

SEC-3044

SEC-3045

SEC-3046

SEC-3047

SEC-3048

SEC-3049

SEC-3050

SEC-3051

SEC-3061

SEC-3062

SEC-3063

SEC-3064

SEC-3065

SEC-3066

SEC-3067

SEC-3068

SEC-3069

SEC-3070

SEC-3071

SEC-3072

SEC-3073

SEC-3074

SEC-3075

SEC-3076

SEC-3077

SEC-3078

SEC-3079

SEC-3080

SEC-3081

SEC-3082

SEC-3083

SEC-3084

SEC-3085

SEC-3086

3.34 SLNK Messages

SLNK-1001

SLNK-1002

SLNK-1003

SLNK-1005

3.35 SNMP Messages

SNMP-1004

SNMP-1005

SNMP-1006

SNMP-1009

SNMP-1011

SNMP-1012

SNMP-3020

3.36 SPM Messages

SPM-3001

SPM-3002

SPM-3003

SPM-3004

SPM-3005

SPM-3006

SPM-3007

SPM-3008

SPM-3009

SPM-3010

SPM-3011

SPM-3012

SPM-3013

SPM-3014

SPM-3015

SPM-3016

SPM-3017

SPM-3018

SPM-3019

SPM-3020

SPM-3021

SPM-3022

SPM-3023

SPM-3024

SPM-3025

SPM-3026

SPM-3027

SPM-3028

SPM-3029

3.37 SRM Messages

SRM-1001

SRM-1002

3.38 SULB Messages

SULB-1001

SULB-1002

SULB-1003

SULB-1004

SULB-1009

SULB-1010

SULB-1017

SULB-1018

SULB-1020

SULB-1021

SULB-1023

SULB-1024

SULB-1026

SULB-1030

SULB-1031

SULB-1032

SULB-1033

SULB-1034

SULB-1035

SULB-1037

SULB-1039

SULB-1040

SULB-1041

SULB-1042

SULB-1050

SULB-1051

SULB-1052

SULB-1053

SULB-1054

SULB-1055

SULB-1056

SULB-1060

SULB-1061

3.39 SWCH Messages

SWCH-1012

SWCH-1013

SWCH-1014

SWCH-1029

SWCH-1030

SWCH-1032

SWCH-1033

SWCH-1034

SWCH-1035

SWCH-1036

SWCH-1037

SWCH-1038

SWCH-1039

SWCH-1040

SWCH-1042

SWCH-1043

SWCH-1050

SWCH-1051

SWCH-1052

SWCH-1060

3.40 SYSM Messages

SYSM-1008

3.41 TS Messages

TS-1002

TS-1009

TS-1010

TS-1011

TS-1012

TS-1013

3.42 UCID Messages

UCID-3001

UCID-3002

UCID-3003

UCID-3004

UCID-3005

UCID-3006

UCID-3007

UCID-3008

UCID-3009

UCID-3010

UCID-3011

UCID-3012

UCID-3013

UCID-3014

UCID-3015

UCID-3016

UCID-3017 UCID-3018 UCID-3019 UCID-3020 UCID-3021 UCID-3022 UCID-3023 UCID-3025 UCID-3026 UCID-3027 UCID-3028 UCID-3029 UCID-3030 UCID-3031 UCID-3032 UCID-3033 UCID-3034 UCID-3035 UCID-3036 UCID-3037 UCID-3038 UCID-3039 UCID-3040 UCID-3041 UCID-3042 UCID-3043

UCID-3044

UCID-3045

UCID-3046

FOS-90x-Message-RM103 Broadcom

UCID-3047

UCID-3048

UCID-3049

UCID-3050

UCID-3051

UCID-3052

UCID-3053

UCID-3054

UCID-3055

3.43 UCST Messages

UCST-1021

UCST-1022

UCST-1023

UCST-1024

UCST-1026

UCST-1027

UCST-1028

UCST-1029

UCST-1030

UCST-1031

UCST-1032

UCST-1033

3.44 ZONE Messages

ZONE-1024

ZONE-1043

ZONE-1044

ZONE-3001

ZONE-3002

ZONE-3003

ZONE-3004

ZONE-3005

ZONE-3006

ZONE-3007

ZONE-3008

ZONE-3009

ZONE-3010

ZONE-3011

ZONE-3012

ZONE-3013

ZONE-3014

ZONE-3015

ZONE-3016

ZONE-3017

ZONE-3018

ZONE-3019

ZONE-3020

ZONE-3021

ZONE-3022

ZONE-3023

ZONE-3024

ZONE-3025

ZONE-3026

ZONE-3027

ZONE-3028

ZONE-3029

ZONE-3030

ZONE-3031

ZONE-3032

ZONE-3033

ZONE-3034

Chapter 4: FFDC Messages

4.1 AUTH Messages

AUTH-1044

4.2 BCM Messages

BCM-1000

BCM-1001

4.3 BCMG Messages

BCMG-1000

BCMG-1001

4.4 BL Messages

BL-1002

BL-1003

BL-1004

BL-1008

BL-1009

BL-1011

BL-1016

BL-1020

BL-1081

4.5 BLS Messages

BLS-1000

BLS-1001

4.6 BLZ Messages

BLZ-1000

BLZ-1001

4.7 BM Messages

BM-1003

BM-1053

4.8 C4 Messages

C4-1002

C4-1048

C4-1049

C4-1050

C4-1051

C4-1052

C4-1054

4.9 C5 Messages

C5-1002

C5-1048

C5-1049

C5-1050

C5-1051

C5-1052

C5-1054

4.10 CHS Messages

CHS-1002

4.11 EM Messages

EM-1001

EM-1002

EM-1003

EM-1004

EM-1005

EM-1006

EM-1008

EM-1009

EM-1010

EM-1011

EM-1012

EM-1018

EM-1020

EM-1028

EM-1068

EM-1071

EM-1072

EM-1073

EM-1074

EM-1100

EM-1134

4.12 ERCP Messages

ERCP-1000

ERCP-1001

ERCP-1002

4.13 FABR Messages

FABR-1011

FABR-1013

FABR-1019

FABR-1020

FABR-1021

FABR-1022

FABR-1031

FABR-1054

4.14 FABS Messages

FABS-1001

4.15 FCMC Messages

FCMC-1001

4.16 FCPH Messages

FCPH-1001

FCPH-1007

FCPH-1008

4.17 FCR Messages

FCR-1048

4.18 FLOD Messages

FLOD-1004

4.19 FSS Messages

FSS-1009

4.20 FSSM Messages

FSSM-1005

4.21 HAM Messages

HAM-1001

HAM-1006

HAM-1007

HAM-1008

HAM-1009

HAM-1011

HAM-1016

4.22 HAMK Messages

HAMK-1001

4.23 HIL Messages

HIL-1107

HIL-1108

HIL-1502

HIL-1503

HIL-1506

HIL-1507

HIL-1508

HIL-1509

HIL-1513

HIL-1514

HIL-1515

HIL-1518

HIL-1602

HIL-1603

HIL-1611

HIL-1621

HIL-1624

HIL-1625

HIL-1654

HIL-1660

4.24 HLO Messages

HLO-1001

HLO-1002

4.25 HMON Messages

HMON-1001

4.26 KSWD Messages

KSWD-1001

KSWD-1002

4.27 LACP Messages

LACP-1003

4.28 LFM Messages

LFM-1004

4.29 LSDB Messages

LSDB-1003

4.30 MQ Messages

MQ-1005

MQ-1007

4.31 NBFS Messages

NBFS-1002

4.32 PDM Messages

PDM-1017

4.33 PLAT Messages

PLAT-1000

PLAT-1003

PLAT-1004

PLAT-1010

PLAT-1011

PLAT-1072

4.34 PS Messages

PS-1000

4.35 RAS Messages

RAS-1004

RAS-1005

4.36 RCS Messages

RCS-1012

RCS-1013

RCS-1014

4.37 RTWR Messages

RTWR-1004

4.38 SCN Messages

SCN-1001

SCN-1002

4.39 SNMP Messages

SNMP-1004

4.40 SULB Messages

SULB-1037

4.41 SYSC Messages

SYSC-1001

SYSC-1002

4.42 SYSM Messages

SYSM-1001

SYSM-1005

SYSM-1006

4.43 TRCE Messages

TRCE-1008

4.44 TS Messages

TS-1011

4.45 UCST Messages

UCST-1007

4.46 WEBD Messages

WEBD-1008

4.47 ZONE Messages

ZONE-1087

ZONE-1088

ZONE-1089

ZONE-1090

ZONE-1094

Chapter 5: Log Messages

5.1 AG Messages

AG-1001

AG-1002

AG-1003

AG-1004

AG-1005

AG-1006

AG-1007

AG-1008

AG-1009

AG-1010

AG-1011

AG-1012

AG-1013

AG-1014

AG-1015

AG-1016

AG-1017

AG-1018

AG-1019

AG-1020

AG-1021

AG-1022

AG-1023

AG-1024

AG-1025

AG-1026

AG-1027

AG-1028

AG-1029

AG-1030

AG-1031

AG-1032

AG-1033

AG-1034

AG-1035

AG-1036

AG-1037

AG-1038

AG-1039

AG-1040

AG-1041

AG-1042

AG-1043

AG-1044

AG-1045

AG-1046

AG-1047

AG-1048

AG-1085

AG-1086

AG-1087

AG-1088

AG-1089

AG-1090

AG-1091

5.2 AMPM Messages

AMPM-1000

AMPM-1001

5.3 AN Messages

AN-1001

AN-1002

AN-1010

AN-1011

AN-1012

AN-1013

AN-1014

5.4 ASVR Messages

ASVR-1001

5.5 AUTH Messages

AUTH-1001

AUTH-1002

AUTH-1003

AUTH-1004

AUTH-1005

AUTH-1006

AUTH-1007

AUTH-1008

AUTH-1010

AUTH-1011

AUTH-1012

AUTH-1013

AUTH-1014

AUTH-1016

AUTH-1017

AUTH-1018

AUTH-1020

AUTH-1022

AUTH-1023

AUTH-1025

AUTH-1026

AUTH-1027

AUTH-1028

AUTH-1029

AUTH-1030

AUTH-1031

AUTH-1032

AUTH-1033

AUTH-1034

AUTH-1035

AUTH-1036

AUTH-1037

AUTH-1038

AUTH-1039

AUTH-1040

AUTH-1041

AUTH-1042

AUTH-1043

AUTH-1044

AUTH-1045

AUTH-1046

AUTH-1047

AUTH-1048

AUTH-1049

AUTH-1050

AUTH-3009

5.6 BCM Messages

BCM-1000

BCM-1001

BCM-1002

BCM-1003

BCM-1004

BCM-1005

BCM-1006

5.7 BCMG Messages

BCMG-1000

BCMG-1001

BCMG-1002

BCMG-1003

BCMG-1004

BCMG-1005

5.8 BL Messages

BL-1000

BL-1001

BL-1002

BL-1003

BL-1004

BL-1006

BL-1007

BL-1008

BL-1009

BL-1010

BL-1011

BL-1012

BL-1013

BL-1014

BL-1015

BL-1016

BL-1017

BL-1018

BL-1019

BL-1020

BL-1021

BL-1022

BL-1023

BL-1024

BL-1025

BL-1026

BL-1027

BL-1028

BL-1029

BL-1030

BL-1031

BL-1032

BL-1033

BL-1034

BL-1035

BL-1036

BL-1037
BL-1038
BL-1039
BL-1040
BL-1041
BL-1045
BL-1046
BL-1047
BL-1048
BL-1049

BL-1052 BL-1053

BL-1050

BL-1054

BL-1055

BL-1056

BL-1057

BL-1058

BL-1061

BL-1062

BL-1063

BL-1064

BL-1065

BL-1080

BL-1081

BL-1082

BL-1083

BL-1084

BL-1085

5.9 BLS Messages

BLS-1000

BLS-1001

BLS-1002

BLS-1003

BLS-1004

BLS-1005

5.10 BLZ Messages

BLZ-1000

BLZ-1001

BLZ-1002

BLZ-1003

BLZ-1004

BLZ-1005

BLZ-1006

BLZ-1007

BLZ-1008

5.11 BM Messages

BM-1001

BM-1002

BM-1003

BM-1004

BM-1005

BM-1006

BM-1007

BM-1008

BM-1009

BM-1010

BM-1053

BM-1054

BM-1055

BM-1056

BM-1058

5.12 C4 Messages

C4-1001

C4-1002

C4-1004

C4-1006

C4-1007

C4-1008

C4-1009

C4-1010

C4-1011

C4-1012

C4-1013

C4-1014

C4-1015

C4-1016

C4-1017

C4-1018

C4-1019

C4-1020

C4-1023

C4-1028

C4-1030

C4-1031 C4-1032 C4-1033 C4-1034 C4-1035 C4-1036 C4-1037 C4-1038 C4-1039 C4-1040 C4-1041 C4-1042 C4-1043 C4-1044 C4-1045 C4-1046 C4-1047 C4-1048 C4-1049 C4-1050

5.13 C5 Messages

C5-1001

C4-1051

C4-1052

C4-1054

C5-1002

C5-1004

C5-1006

C5-1007

C5-1008

C5-1009

C5-1010

C5-1011

C5-1012

C5-1013

C5-1014

C5-1015

C5-1016

C5-1017

C5-1018

C5-1019

C5-1020

C5-1023

C5-1028

C5-1030

C5-1031

C5-1032

C5-1033

C5-1034

C5-1035

C5-1036

C5-1037

C5-1038

C5-1039

C5-1040

C5-1041

C5-1042

C5-1043

C5-1044

C5-1045

C5-1046

C5-1048

C5-1049

C5-1050

C5-1051

C5-1052

C5-1053

C5-1054

5.14 CAL Messages

CAL-1001

5.15 CCFG Messages

CCFG-1001

CCFG-1002

CCFG-1003

CCFG-1004

CCFG-1005

CCFG-1006

CCFG-1007

CCFG-1008

CCFG-1009

CCFG-1010

CCFG-1011

CCFG-1012

5.16 CFS Messages

CFS-1001

5.17 CHS Messages

CHS-1002

CHS-1003

CHS-1004

CHS-1005

5.18 CNM Messages

CNM-1001

CNM-1002

CNM-1003

CNM-1004

CNM-1005

CNM-1006

CNM-1007

CNM-1008

CNM-1009

CNM-1010

CNM-1011

CNM-1012

CNM-1013

CNM-1014

CNM-1015

CNM-1016

CNM-1017

CNM-1018

CNM-1019

CNM-1020

CNM-1021

CNM-1022

CNM-1023

CNM-1024

CNM-1025

CNM-1026

CNM-1027

CNM-1028

CNM-1029

CNM-1030

CNM-1031

CNM-1032

CNM-1033

CNM-1034

CNM-1035

CNM-1036

CNM-1037

CNM-1038

CNM-1039

CNM-1040

CNM-1041

CNM-1042

CNM-1043

CNM-1044

CNM-1045

CNM-1046

CNM-1047

CNM-1048

CNM-1049

CNM-1050

CNM-1051

CNM-1052

CNM-1053

CNM-1054

CNM-1055

CNM-1056

CNM-1057

CNM-1058

CNM-1059

CNM-1060

CNM-1061

CNM-1062

CNM-3001

CNM-3002

CNM-3003

CNM-3004

CNM-3005

CNM-3006

CNM-3007

CNM-3008

CNM-3009

CNM-3010

CNM-3011

CNM-3012

5.19 CNMC Messages

CNMC-1001

CNMC-1002

CNMC-1003

5.20 CONF Messages

CONF-1000

CONF-1001

CONF-1021

CONF-1023

CONF-1024

CONF-1030

CONF-1031

CONF-1032

CONF-1033

CONF-1040

CONF-1041

CONF-1042

CONF-1043

CONF-1044

CONF-1045

CONF-1047

CONF-1048

CONF-1054

CONF-1055

5.21 DIAG Messages

DIAG-1000

5.22 DOT1 Messages

DOT1-1001

DOT1-1002

DOT1-1003

DOT1-1004

DOT1-1005

DOT1-1006

DOT1-1007

DOT1-1008

DOT1-1009

DOT1-1010

5.23 ECC Messages

ECC-1000

ECC-1001

5.24 EM Messages

EM-1001

EM-1002

EM-1003

EM-1004

EM-1005

EM-1006

EM-1008

EM-1009

EM-1010

EM-1011

EM-1012

EM-1013

EM-1014

EM-1015

EM-1016

EM-1017

EM-1018

EM-1019

EM-1020

EM-1028

EM-1029

EM-1031

EM-1033

EM-1034

EM-1035

EM-1036

EM-1037

EM-1042

EM-1043

EM-1044

EM-1045

EM-1046

EM-1047

EM-1048

EM-1049

EM-1050

EM-1051

EM-1057

EM-1058

EM-1059

EM-1060

EM-1061

EM-1062

EM-1063

EM-1064

EM-1065

EM-1066

EM-1067

EM-1068

EM-1069

EM-1070

EM-1071

EM-1072

EM-1073

EM-1074

EM-1075

EM-1100

EM-1101

EM-1134

EM-1220

EM-1221

EM-1222

EM-1223

EM-1227

EM-1228

EM-1229

EM-1230

EM-2003

EM-2004

5.25 ERCP Messages

ERCP-1000

ERCP-1001

ERCP-1002

5.26 ESM Messages

ESM-1000

ESM-1001

ESM-1002

ESM-1003

ESM-1004

ESM-1005

ESM-1010

ESM-1011

ESM-1012

ESM-1013

ESM-1100

ESM-1101

ESM-1102

ESM-1103

ESM-1104

ESM-1105

ESM-2000

ESM-2001

ESM-2002

ESM-2010

ESM-2011

ESM-2012

ESM-2100

ESM-2101

ESM-2102

ESM-2103

ESM-2104

ESM-2105

ESM-2106

ESM-2200

ESM-2201

ESM-2202

ESM-2203

ESM-2300

ESM-2301

ESM-2302

ESM-2303

ESM-2310

ESM-2311

ESM-2312

ESM-2313

ESM-2314

ESM-2315

ESM-2316

ESM-2317

ESM-2318

ESM-2319

ESM-2320

ESM-2321

ESM-2322

ESM-2323

ESM-2324

ESM-2325

ESM-2326

ESM-2327

ESM-2328

ESM-2329

ESM-2400

ESM-2700

ESM-2701

ESM-2702

ESM-2703

ESM-2801

ESM-2802

ESM-2803

ESM-3000

ESM-3001

ESM-3002

ESM-3003

ESM-3004

ESM-3005

ESM-3006

ESM-3007

ESM-3008

5.27 ESS Messages

ESS-1001

ESS-1002

ESS-1003

ESS-1004

ESS-1005

ESS-1008

ESS-1009

ESS-1010

ESS-1011

ESS-2001

ESS-2002

5.28 ESW Messages

ESW-1001

ESW-1002

ESW-1003

ESW-1004

ESW-1005

ESW-1006

ESW-1007

ESW-1008

5.29 EVMD Messages

EVMD-1001

5.30 FABR Messages

FABR-1001

FABR-1002

FABR-1003

FABR-1004

FABR-1005

FABR-1006

FABR-1007

FABR-1008

FABR-1009

FABR-1010

FABR-1011

FABR-1012

FABR-1013

FABR-1014

FABR-1015

FABR-1016

FABR-1017

FABR-1018

FABR-1019

FABR-1020

FABR-1021

FABR-1022

FABR-1023

FABR-1024

FABR-1029

FABR-1030

FABR-1031

FABR-1032

FABR-1034

FABR-1035

FABR-1036

FABR-1037

FABR-1038

FABR-1039

FABR-1040

FABR-1041

FABR-1043

FABR-1044

FABR-1045

FABR-1046

FABR-1047

FABR-1048

FABR-1049

FABR-1050

FABR-1051

FABR-1052

FABR-1053

FABR-1054

FABR-1055

FABR-1056

FABR-1057

FABR-1058

FABR-1059

FABR-1060

FABR-1061

5.31 FABS Messages

FABS-1001

FABS-1002

FABS-1004

FABS-1005

FABS-1006

FABS-1007

FABS-1008

FABS-1009

FABS-1010

FABS-1011

FABS-1013

FABS-1014

FABS-1015

5.32 FBC Messages

FBC-1001

5.33 FCMC Messages

FCMC-1001

5.34 FCOE Messages

FCOE-1001

FCOE-1002

FCOE-1003

FCOE-1004

FCOE-1005

FCOE-1006

FCOE-1007

FCOE-1008

FCOE-1009

FCOE-1010

FCOE-1011

FCOE-1019

FCOE-1022

FCOE-1023

FCOE-1024

FCOE-1029

FCOE-1030

FCOE-1032

FCOE-1033

FCOE-1034

FCOE-1037

FCOE-1038

FCOE-1039

FCOE-1040

FCOE-1041

FCOE-1042

FCOE-1043

FCOE-1044

5.35 FCPD Messages

FCPD-1001

FCPD-1002

FCPD-1003

5.36 FCPH Messages

FCPH-1001

FCPH-1002

FCPH-1003

FCPH-1004

FCPH-1005

FCPH-1006

FCPH-1007

FCPH-1008

FCPH-1009

FCPH-1010

FCPH-1011

FCPH-1012

FCPH-1013

FCPH-1014

5.37 FCR Messages

FCR-1001

FCR-1002

FCR-1003

FCR-1004

FCR-1005

FCR-1006

FCR-1007

FCR-1008

FCR-1010

FCR-1011

FCR-1012

FCR-1013

FCR-1015

FCR-1016

FCR-1018

FCR-1019

FCR-1020

FCR-1021

FCR-1022

FCR-1023

FCR-1024

FCR-1025

FCR-1026

FCR-1027

FCR-1028

FCR-1029

FCR-1030

FCR-1031

FCR-1032

FCR-1033

FCR-1034

FCR-1035

FCR-1036

FCR-1037

FCR-1038

FCR-1039

FCR-1041

FCR-1042

FCR-1043

FCR-1048

FCR-1049

FCR-1053

FCR-1054

FCR-1055

FCR-1056

FCR-1057

FCR-1058

FCR-1059

FCR-1060

FCR-1061

FCR-1062

FCR-1063

FCR-1064

FCR-1065

FCR-1066

FCR-1067

FCR-1068

FCR-1069

FCR-1070

FCR-1071

FCR-1072

FCR-1073

FCR-1074

FCR-1075

FCR-1077

FCR-1078

FCR-1079

FCR-1080

FCR-1081

FCR-1082

FCR-1083

FCR-1084

FCR-1085

FCR-1086

FCR-1087

FCR-1088

FCR-1089

FCR-1091

FCR-1092

FCR-1093

FCR-1094

FCR-1095

FCR-1096

FCR-1097

FCR-1098

FCR-1099

FCR-1100

FCR-1101

FCR-1102

FCR-1103

FCR-1104

FCR-1105

FCR-1107

FCR-1108

FCR-1109

FCR-1110

FCR-1111

FCR-1112

FCR-1113

FCR-1115

FCR-1116

FCR-1117

FCR-1118

5.38 FICN Messages

FICN-1003

FICN-1004

FICN-1005

FICN-1006

FICN-1007

FICN-1008

FICN-1009

FICN-1010

FICN-1011

FICN-1012

FICN-1013

FICN-1014

FICN-1015

FICN-1016

FICN-1017

FICN-1018

FICN-1020

FICN-1021

FICN-1022

FICN-1023

FICN-1024

FICN-1025

FICN-1026

FICN-1027

FICN-1028

FICN-1029

FICN-1030

FICN-1031

FICN-1032

FICN-1033

FICN-1034

FICN-1035

FICN-1036

FICN-1037

FICN-1038

FICN-1039

FICN-1040

FICN-1041

FICN-1042

FICN-1043

FICN-1044

FICN-1045

FICN-1046

FICN-1047

FICN-1049

FICN-1050

FICN-1051

FICN-1052

FICN-1053

FICN-1054

FICN-1055

FICN-1056

FICN-1057

FICN-1058

FICN-1059

FICN-1060

FICN-1061

FICN-1062

FICN-1063

FICN-1064

FICN-1065

FICN-1066

FICN-1067

FICN-1068

FICN-1069

FICN-1070

FICN-1071

FICN-1072

FICN-1073

FICN-1074

FICN-1075

FICN-1076

FICN-1078

FICN-1079

FICN-1080

FICN-1081

FICN-1082

FICN-1083

FICN-1084

FICN-1085

FICN-1086

FICN-1087

FICN-1088

FICN-1089

FICN-1090

FICN-1091

FICN-1092

FICN-1093

FICN-1094

FICN-1095

FICN-1096

FICN-1097

FICN-1098

FICN-1099

FICN-1100

FICN-1101

FICN-1102

FICN-1103

FICN-1104

FICN-1105

FICN-1107

FICN-1108

FICN-1109

FICN-1110

FICN-1111

FICN-1112

FICN-1113

FICN-1114

FICN-1115

FICN-1116

FICN-1117

FICN-1118

FICN-1119

FICN-1120

FICN-1121

FICN-1122

FICN-1123

FICN-2005

FICN-2006

FICN-2064

FICN-2065

FICN-2066

FICN-2082

FICN-2083

FICN-2085

FICN-2086

FICN-2087

5.39 FICU Messages

FICU-1001

FICU-1002

FICU-1003

FICU-1004

FICU-1005

FICU-1006

FICU-1007

FICU-1008

FICU-1009

FICU-1010

FICU-1011

FICU-1012

FICU-1013

FICU-1017

FICU-1018

FICU-1019

FICU-1020

FICU-1021

FICU-1022

FICU-1025

FICU-1026

FICU-1030

FICU-1031

FICU-1032

FICU-1033

FICU-1035

FICU-1036

5.40 FKLB Messages

FKLB-1001

5.41 FLOD Messages

FLOD-1001

FLOD-1003

FLOD-1004

FLOD-1005

FLOD-1006

FLOD-1007

5.42 FSPF Messages

FSPF-1001

FSPF-1002

FSPF-1003

FSPF-1005

FSPF-1006

FSPF-1007

FSPF-1008

FSPF-1009

FSPF-1010

FSPF-1011

FSPF-1012

FSPF-1013

FSPF-1014

FSPF-1015

FSPF-1016

FSPF-1017

FSPF-1018

5.43 FSS Messages

FSS-1001

FSS-1002

FSS-1003

FSS-1004

FSS-1005

FSS-1006

FSS-1007

FSS-1008

FSS-1009

FSS-1010

FSS-1011

5.44 FSSM Messages

FSSM-1002

FSSM-1003

FSSM-1004

FSSM-1005

5.45 FTC Messages

FTC-1001

FTC-1002

5.46 FV Messages

FV-1001

FV-1002

FV-1003

FV-1004

FV-1005

FV-1006

FV-1007

FV-1008

FV-1009

FV-1010

FV-1011

FV-1012

FV-3005

FV-3015

FV-3016

FV-3017

FV-3018

FV-3019

FV-3020

FV-3021

5.47 HAM Messages

HAM-1001

HAM-1002

HAM-1004

HAM-1005

HAM-1006

HAM-1007

HAM-1008

HAM-1009

HAM-1010

HAM-1011

HAM-1013

HAM-1014

HAM-1016

HAM-1019

5.48 HAMK Messages

HAMK-1001

HAMK-1002

HAMK-1003

HAMK-1004

5.49 HIL Messages

HIL-1101

HIL-1102

HIL-1103

HIL-1104

HIL-1105

HIL-1106

HIL-1107

HIL-1108

HIL-1109

HIL-1201

HIL-1202

HIL-1203

HIL-1204

HIL-1206

HIL-1207

HIL-1208

HIL-1301

HIL-1302

HIL-1303

HIL-1304

HIL-1305

HIL-1306

HIL-1307

HIL-1308

HIL-1309

HIL-1310

HIL-1311

HIL-1312

HIL-1401

HIL-1402

HIL-1403

HIL-1404

HIL-1405

HIL-1501

HIL-1502

HIL-1503

HIL-1504

HIL-1505

HIL-1506

HIL-1507

HIL-1508

HIL-1509

HIL-1510

HIL-1511

HIL-1512

HIL-1513

HIL-1514

HIL-1515

HIL-1516

HIL-1517

HIL-1518

HIL-1519

HIL-1601

HIL-1602

HIL-1603

HIL-1605

HIL-1610

HIL-1611

HIL-1612

HIL-1613

HIL-1614

HIL-1615

HIL-1621

HIL-1623

HIL-1624

HIL-1625

HIL-1626

HIL-1627

HIL-1628

HIL-1629

HIL-1630

HIL-1650

HIL-1651

HIL-1652

HIL-1653

HIL-1654

HIL-1655

HIL-1656

HIL-1657

HIL-1658

HIL-1659

HIL-1660

5.50 HLO Messages

HLO-1001

HLO-1002

HLO-1003

5.51 HMON Messages

HMON-1001

5.52 HSL Messages

HSL-1000

HSL-1001

HSL-1002

HSL-1003

HSL-1004

HSL-1005

HSL-1006

HSL-1007

5.53 HTTP Messages

HTTP-1001

HTTP-1002

HTTP-1003

HTTP-3005

5.54 IPAD Messages

IPAD-1000

IPAD-1001

IPAD-1002

IPAD-1003

IPAD-1004

IPAD-1005

IPAD-1006

5.55 IPS Messages

IPS-1001

IPS-1002

IPS-1003

IPS-1004

IPS-1005

IPS-1006

IPS-1007

IPS-1008

IPS-1009

IPS-1010

IPS-2000

IPS-2001

5.56 ISNS Messages

ISNS-1001

ISNS-1002

ISNS-1003

ISNS-1004

ISNS-1005

ISNS-1006

ISNS-1008

ISNS-1009

ISNS-1010

ISNS-1011

ISNS-1013

ISNS-1014

5.57 KAC Messages

KAC-1002

KAC-1004

KAC-1006

KAC-1007

KAC-1008

KAC-1009

KAC-1010

KAC-1011

KAC-1012

KAC-1013

KAC-1014

KAC-1015

KAC-1016

KAC-1017

KAC-1018

5.58 KSWD Messages

KSWD-1001

KSWD-1002

5.59 KTRC Messages

KTRC-1001

KTRC-1002

KTRC-1003

KTRC-1004

KTRC-1005

5.60 L2SS Messages

L2SS-1001

L2SS-1002

L2SS-1003

L2SS-1004

L2SS-1005

L2SS-1006

L2SS-1007

L2SS-1008

5.61 L3SS Messages

L3SS-1004

5.62 LACP Messages

LACP-1001

LACP-1002

LACP-1003

5.63 LFM Messages

LFM-1001

LFM-1002

LFM-1003

LFM-1004

LFM-1005

LFM-1006

LFM-1007

5.64 LIC Messages

LIC-1000

LIC-1001

LIC-1002

LIC-1003

LIC-1004

LIC-1005

LIC-1009

LIC-1010

5.65 LOG Messages

LOG-1000

LOG-1001

LOG-1002

LOG-1003

LOG-1004

LOG-1005

LOG-1006

LOG-1007

LOG-1008

LOG-1009

LOG-1010

LOG-1011

LOG-1012

LOG-1013

5.66 LSDB Messages

LSDB-1001

LSDB-1002

LSDB-1003

LSDB-1004

LSDB-1005

5.67 MAPS Messages

MAPS-1001 to MAPS-1004

MAPS-1005

MAPS-1010

MAPS-1011

MAPS-1012

MAPS-1013

MAPS-1014

MAPS-1015

MAPS-1016

MAPS-1017

MAPS-1018

MAPS-1020

MAPS-1021

MAPS-1022

MAPS-1023

MAPS-1024

MAPS-1025

MAPS-1026

MAPS-1100

MAPS-1101

MAPS-1102

MAPS-1110

MAPS-1111

MAPS-1112

MAPS-1113

MAPS-1114

MAPS-1115

MAPS-1116

MAPS-1120

MAPS-1121

MAPS-1122

MAPS-1123

MAPS-1124

MAPS-1125

MAPS-1126

MAPS-1127

MAPS-1130

MAPS-1131

MAPS-1132

MAPS-1133

MAPS-1134

MAPS-1135

MAPS-1136

MAPS-1137

MAPS-1138

MAPS-1139

MAPS-1140

MAPS-1141

MAPS-1142

MAPS-1143

MAPS-1144

MAPS-1145

MAPS-1146

MAPS-1147

MAPS-1148

MAPS-1201

MAPS-1202

MAPS-1203

MAPS-1204

MAPS-1205

MAPS-1206

MAPS-1207

MAPS-1208

MAPS-1209

MAPS-1210

MAPS-1211

MAPS-1213

MAPS-1214

MAPS-1215

MAPS-1216

MAPS-1301

MAPS-1302

MAPS-2000

MAPS-2001

MAPS-2002

MAPS-2003

MAPS-2004 to MAPS-2007

MAPS-2008 to MAPS-2011

MAPS-2012 to MAPS-2015

MAPS-2016 to MAPS-2019

MAPS-2020 to MAPS-2023

MAPS-2024 to MAPS-2027

MAPS-2028 to MAPS-2031

MAPS-2032 to MAPS-2035

MAPS-2036 to MAPS-2039

MAPS-2040 to MAPS-2043

MAPS-2044 to MAPS-2047

MAPS-2048 to MAPS-2051

MAPS-2052 to MAPS-2055

MAPS-2056 to MAPS-2059

MAPS-2060 to MAPS-2063

MAPS-2064 to MAPS-2067

MAPS-2068 to MAPS-2071

MAPS-2072 to MAPS-2075

MAPS-2076 to MAPS-2079

MAPS-2080 to MAPS-2083

MAPS-2084 to MAPS-2087

MAPS-2088 to MAPS-2091

MAPS-2092 to MAPS-2095

MAPS-2096 to MAPS-2099

MAPS-2100 to MAPS-2103

MAPS-2104 to MAPS-2107

MAPS-2108 to MAPS-2111

MAPS-2112 to MAPS-2115

MAPS-2116 to MAPS-2119

MAPS-2120 to MAPS-2123

MAPS-2124 to MAPS-2127

MAPS-2128 to MAPS-2131

MAPS-2132 to MAPS-2135

MAPS-2136 to MAPS-2139

MAPS-2140 to MAPS-2143

MAPS-2144 to MAPS-2147

MAPS-2148 to MAPS-2151

MAPS-2152 to MAPS-2155

MAPS-2156 to MAPS-2159

MAPS-2160 to MAPS-2163

MAPS-2164 to MAPS-2167

MAPS-2168 to MAPS-2171

MAPS-2172 to MAPS-2175

MAPS-2176 to MAPS-2179

MAPS-2180 to MAPS-2183

MAPS-2184 to MAPS-2187

MAPS-2188 to MAPS-2191

MAPS-2192 to MAPS-2195

MAPS-2196 to MAPS-2199

MAPS-2200 to MAPS-2203

MAPS-2204 to MAPS-2207

MAPS-2208 to MAPS-2211

MAPS-2212 to MAPS-2215

MAPS-2216 to MAPS-2219

MAPS-2220 to MAPS-2223

MAPS-2224 to MAPS-2227

MAPS-2228 to MAPS-2231

MAPS-2232 to MAPS-2235

MAPS-2236 to MAPS-2239

MAPS-2240 to MAPS-2243

MAPS-2244 to MAPS-2247

MAPS-2248 to MAPS-2251

MAPS-2252 to MAPS-2255

MAPS-2256 to MAPS-2259

MAPS-2260 to MAPS-2263

MAPS-2264 to MAPS-2267

MAPS-2268 to MAPS-2271

MAPS-2272 to MAPS-2275

MAPS-2276 to MAPS-2279

MAPS-2280 to MAPS-2283

MAPS-2284 to MAPS-2287

MAPS-2288 to MAPS-2291

MAPS-2292 to MAPS-2295

MAPS-2296 to MAPS-2299

MAPS-2300 to MAPS-2303

MAPS-2304 to MAPS-2307

MAPS-2308 to MAPS-2311

MAPS-2312 to MAPS-2315

MAPS-2316 to MAPS-2319

MAPS-2320 to MAPS-2323

MAPS-2324 to MAPS-2327

MAPS-2328 to MAPS-2331

MAPS-2332 to MAPS-2335

MAPS-2336 to MAPS-2339

MAPS-2340 to MAPS-2343

MAPS-2344 to MAPS-2347

MAPS-2348 to MAPS-2351

MAPS-2352 to MAPS-2355

MAPS-2356 to MAPS-2359

MAPS-2360 to MAPS-2363

MAPS-2364 to MAPS-2367

MAPS-2368 to MAPS-2371

MAPS-2372 to MAPS-2375

MAPS-2376 to MAPS-2379

MAPS-2380 to MAPS-2383

MAPS-2384 to MAPS-2387

MAPS-2388 to MAPS-2391

MAPS-2392 to MAPS-2395

MAPS-2396 to MAPS-2399

MAPS-2400 to MAPS-2403

MAPS-2404 to MAPS-2407

MAPS-2408 to MAPS-2411

MAPS-2412 to MAPS-2415

MAPS-2416 to MAPS-2419

MAPS-2420 to MAPS-2423

MAPS-2424 to MAPS-2427

MAPS-2428 to MAPS-2431

MAPS-2432 to MAPS-2435

MAPS-2436 to MAPS-2439

MAPS-2440 to MAPS-2443

MAPS-2444 to MAPS-2447

MAPS-2448 to MAPS-2451

MAPS-2452 to MAPS-2455

MAPS-2456 to MAPS-2459

MAPS-2460 to MAPS-2463

MAPS-2464 to MAPS-2467

MAPS-2468 to MAPS-2471

MAPS-2472 to MAPS-2475

MAPS-2476 to MAPS-2479

MAPS-2480 to MAPS-2483

MAPS-2484 to MAPS-2487

MAPS-2488 to MAPS-2491

MAPS-2492 to MAPS-2495

MAPS-2496 to MAPS-2499

MAPS-2500 to MAPS-2503

MAPS-2504 to MAPS-2507

MAPS-2508 to MAPS-2511

MAPS-2512 to MAPS-2515

MAPS-2516 to MAPS-2519

MAPS-2520 to MAPS-2523

MAPS-2524 to MAPS-2527

MAPS-2528 to MAPS-2531

MAPS-2532 to MAPS-2535

MAPS-2536 to MAPS-2539

MAPS-2540 to MAPS-2543

MAPS-2544 to MAPS-2547

MAPS-2548 to MAPS-2551

MAPS-2552 to MAPS-2555

MAPS-2556 to MAPS-2559

MAPS-2560 to MAPS-2563

MAPS-2564 to MAPS-2567

MAPS-2568 to MAPS-2571

MAPS-2572 to MAPS-2575

MAPS-2576 to MAPS-2579

MAPS-2580 to MAPS-2583

MAPS-2584 to MAPS-2587

MAPS-2588 to MAPS-2591

MAPS-2592 to MAPS-2595

MAPS-2596 to MAPS-2599

MAPS-2600 to MAPS-2603

MAPS-2604 to MAPS-2607

MAPS-2608 to MAPS-2611

MAPS-2612 to MAPS-2615

MAPS-2616 to MAPS-2619

MAPS-2620 to MAPS-2623

MAPS-2624 to MAPS-2627

MAPS-2628 to MAPS-2631

MAPS-2632 to MAPS-2635

MAPS-2636 to MAPS-2639

MAPS-2640 to MAPS-2643

MAPS-2644 to MAPS-2647

MAPS-2648 to MAPS-2651

MAPS-2652 to MAPS-2655

MAPS-2656 to MAPS-2659

MAPS-2660 to MAPS-2663

MAPS-2664 to MAPS-2667

MAPS-2668 to MAPS-2671

MAPS-2672 to MAPS-2675

MAPS-2676 to MAPS-2679

MAPS-2680 to MAPS-2683

MAPS-2684 to MAPS-2687

MAPS-2688 to MAPS-2691

MAPS-2692 to MAPS-2695

MAPS-2696 to MAPS-2699

MAPS-2700 to MAPS-2703

MAPS-2704 to MAPS-2707

MAPS-2708 to MAPS-2711

MAPS-2712 to MAPS-2715

MAPS-2716 to MAPS-2719

MAPS-2720 to MAPS-2723

MAPS-2724 to MAPS-2727

MAPS-2728 to MAPS-2731

MAPS-2732 to MAPS-2735

MAPS-2736 to MAPS-2739

MAPS-2740 to MAPS-2743

MAPS-2744 to MAPS-2747

MAPS-2748 to MAPS-2751

MAPS-2752 to MAPS-2755

MAPS-2756 to MAPS-2759

MAPS-2760 to MAPS-2763

MAPS-2764 to MAPS-2767

MAPS-2768 to MAPS-2771

MAPS-2772 to MAPS-2775

MAPS-2776 to MAPS-2779

MAPS-2780 to MAPS-2783

MAPS-2784 to MAPS-2787

MAPS-2788 to MAPS-2791

MAPS-2792 to MAPS-2795

MAPS-2796 to MAPS-2799

MAPS-2800 to MAPS-2803

MAPS-2804 to MAPS-2807

MAPS-2808 to MAPS-2811

MAPS-2812 to MAPS-2815

MAPS-2816 to MAPS-2819

MAPS-2820 to MAPS-2823

MAPS-2824 to MAPS-2827

MAPS-2828 to MAPS-2831

MAPS-2832 to MAPS-2835

MAPS-2836 to MAPS-2839

MAPS-2840 to MAPS-2843

MAPS-2844 to MAPS-2847

MAPS-2848 to MAPS-2851

MAPS-2852 to MAPS-2855

MAPS-2856 to MAPS-2859

MAPS-2860 to MAPS-2863

MAPS-2864 to MAPS-2867

MAPS-2868 to MAPS-2871

MAPS-2872 to MAPS-2875

MAPS-2876 to MAPS-2879

MAPS-2880 to MAPS-2883

MAPS-2884 to MAPS-2887

MAPS-2888 to MAPS-2891

MAPS-2892 to MAPS-2895

MAPS-2896 to MAPS-2899

MAPS-2900 to MAPS-2903

MAPS-2904 to MAPS-2907

MAPS-2908 to MAPS-2911

MAPS-2912 to MAPS-2915

MAPS-2916 to MAPS-2919

MAPS-2920 to MAPS-2923

MAPS-2924 to MAPS-2927

MAPS-2928 to MAPS-2931

MAPS-2932 to MAPS-2935

MAPS-2936 to MAPS-2939

MAPS-2940 to MAPS-2943

MAPS-2944 to MAPS-2947

MAPS-2948 to MAPS-2951

MAPS-2952 to MAPS-2955

MAPS-2956 to MAPS-2959

MAPS-2960 to MAPS-2963

MAPS-2964 to MAPS-2967

MAPS-2968 to MAPS-2971

MAPS-2972 to MAPS-2975

MAPS-2976 to MAPS-2979

MAPS-2980 to MAPS-2983

MAPS-2992 to MAPS-2995

MAPS-2996 to MAPS-2999

MAPS-3000 to MAPS-3003

MAPS-3004 to MAPS-3007

MAPS-3012 to MAPS-3015

MAPS-3016 to MAPS-3019

MAPS-3020 to MAPS-3023

MAPS-3024 to MAPS-3027

MAPS-3028 to MAPS-3031

MAPS-3032 to MAPS-3035

MAPS-3036 to MAPS-3039

MAPS-3040 to MAPS-3043

MAPS-3044 to MAPS-3047

MAPS-3048 to MAPS-3051

MAPS-3052 to MAPS-3055

MAPS-3056 to MAPS-3059

MAPS-3060 to MAPS-3063

5.68 MCST Messages

MCST-1001

MCST-1002

MCST-1003

MCST-1004

MCST-1005

MCST-1006

MCST-1007

MCST-1008

MCST-1009

MCST-1010

MCST-1011

MCST-1012

MCST-1013

MCST-1014

MCST-1015

MCST-1016

MCST-1017

MCST-1018

MCST-1019

MCST-1020

5.69 MFIC Messages

MFIC-1001

MFIC-1002

MFIC-1003

5.70 MM Messages

MM-1001

5.71 MPTH Messages

MPTH-1003

5.72 MQ Messages

MQ-1004

MQ-1005

MQ-1006

MQ-1007

5.73 MS Messages

MS-1001

MS-1002

MS-1003

MS-1004

MS-1005

MS-1006

MS-1008

MS-1009

MS-1021

MS-1022

MS-1023

MS-1024

MS-1025

MS-1026

MS-1027

MS-1028

MS-1029

MS-1030

MS-1031

5.74 MSTP Messages

MSTP-1001

MSTP-1002

MSTP-1003

MSTP-2001

MSTP-2002

MSTP-2003

MSTP-2004

MSTP-2005

MSTP-2006

5.75 NBFS Messages

NBFS-1001

NBFS-1002

NBFS-1003

NBFS-1004

NBFS-1005

NBFS-1006

5.76 NS Messages

NS-1001

NS-1002

NS-1003

NS-1004

NS-1005

NS-1006

NS-1007

NS-1008

NS-1009

NS-1010

NS-1011

NS-1012

NS-1013

NS-1014

NS-1015

NS-1016

NS-1017

NS-1018

NS-1019

NS-1020

NS-1021

NS-1022

NS-1023

NS-1024

NS-1025

NS-1026

NS-1027

5.77 NSM Messages

NSM-1001

NSM-1002

NSM-1003

NSM-1004

NSM-1005

NSM-1006

NSM-1007

NSM-1008

NSM-1009

NSM-1010

NSM-1011

NSM-1012

NSM-1013

NSM-1014

NSM-1015

NSM-1016

NSM-1017

NSM-1018

NSM-1019

NSM-1020

5.78 ONMD Messages

ONMD-1000

ONMD-1001

ONMD-1002

ONMD-1003

ONMD-1004

ONMD-1005

5.79 PDM Messages

PDM-1001

PDM-1002

PDM-1003

PDM-1004

PDM-1005

PDM-1006

PDM-1007

PDM-1008

PDM-1009

PDM-1010

PDM-1011

PDM-1012

PDM-1013

PDM-1014

PDM-1017

PDM-1019

PDM-1020

PDM-1021

PDM-1022

PDM-1023

PDM-1024

PDM-1025

PDM-1026

PDM-1027

PDM-1028

5.80 PDTR Messages

PDTR-1001

PDTR-1002

5.81 PLAT Messages

PLAT-1000

PLAT-1001

PLAT-1002

PLAT-1003

PLAT-1004

PLAT-1005

PLAT-1006

PLAT-1007

PLAT-1008

PLAT-1009

PLAT-1010

PLAT-1011

PLAT-1072

PLAT-1100

PLAT-2000

PLAT-2001

5.82 PMGR Messages

PMGR-1001

PMGR-1002

PMGR-1003

PMGR-1004

PMGR-1005

PMGR-1006

PMGR-1007

PMGR-1008

PMGR-1009

PMGR-1010

PMGR-1011

PMGR-1012

PMGR-1013

PMGR-1014

5.83 PORT Messages

PORT-1003

PORT-1004

PORT-1005

PORT-1006

PORT-1007

PORT-1008

PORT-1009

PORT-1010

PORT-1011

PORT-1012

PORT-1054

PORT-1055

PORT-1058

5.84 PS Messages

PS-1000

PS-1001

PS-1002

PS-1009

5.85 PSWP Messages

PSWP-1001

PSWP-1002

PSWP-1003

PSWP-1004

PSWP-1005

PSWP-1006

PSWP-1007

5.86 QOSD Messages

QOSD-1000

QOSD-1001

QOSD-1005

QOSD-1006

5.87 RAS Messages

RAS-1001

RAS-1002

RAS-1003

RAS-1004

RAS-1005

RAS-1006

RAS-1007

RAS-1008

RAS-2001

RAS-2002

RAS-2003

RAS-2004

RAS-2005

RAS-2008

RAS-2009

RAS-2012

RAS-2013

RAS-2014

RAS-2015

RAS-3001

RAS-3002

RAS-3003

RAS-3004

5.88 RCS Messages

RCS-1001

RCS-1002

RCS-1003

RCS-1004

RCS-1005

RCS-1006

RCS-1007

RCS-1008

RCS-1009

RCS-1011

RCS-1012

RCS-1013

RCS-1014

5.89 RMON Messages

RMON-1001

RMON-1002

5.90 RPCD Messages

RPCD-1001

RPCD-1002

RPCD-1003

RPCD-1004

RPCD-1005

RPCD-1006

RPCD-1007

5.91 RTE Messages

RTE-1001

RTE-1002

RTE-1003

RTE-1004

RTE-1005

5.92 RTWR Messages

RTWR-1001

RTWR-1002

RTWR-1003

RTWR-1004

5.93 SCN Messages

SCN-1001

SCN-1002

5.94 SEC Messages

SEC-1001

SEC-1002

SEC-1003

SEC-1005

SEC-1006

SEC-1007

SEC-1008

SEC-1009

SEC-1010

SEC-1016

SEC-1022

SEC-1024

SEC-1025

SEC-1026

SEC-1028

SEC-1029

SEC-1030

SEC-1031

SEC-1032

SEC-1033

SEC-1034

SEC-1035

SEC-1036

SEC-1037

SEC-1038

SEC-1039

SEC-1040

SEC-1041

SEC-1043

SEC-1044

SEC-1045

SEC-1046

SEC-1049

SEC-1050

SEC-1051

SEC-1052

SEC-1053

SEC-1054

SEC-1055

SEC-1056

SEC-1057

SEC-1059

SEC-1062

SEC-1063

SEC-1064

SEC-1065

SEC-1069

SEC-1071

SEC-1072

SEC-1073

SEC-1074

SEC-1075

SEC-1076

SEC-1077

SEC-1078

SEC-1079

SEC-1081

SEC-1082

SEC-1083

SEC-1084

SEC-1085

SEC-1086

SEC-1087

SEC-1088

SEC-1089

SEC-1090

SEC-1091

SEC-1092

SEC-1093

SEC-1094

SEC-1095

SEC-1096

SEC-1097

SEC-1098

SEC-1099

SEC-1100

SEC-1101

SEC-1102

SEC-1104

SEC-1105

SEC-1106

SEC-1107

SEC-1108

SEC-1110

SEC-1112

SEC-1113

SEC-1114

SEC-1115

SEC-1116

SEC-1117

SEC-1118

SEC-1119

SEC-1121

SEC-1122

SEC-1123

SEC-1124

SEC-1126

SEC-1130

SEC-1135

SEC-1136

SEC-1137

SEC-1138

SEC-1139

SEC-1142

SEC-1145

SEC-1146

SEC-1153

SEC-1154

SEC-1155

SEC-1156

SEC-1157

SEC-1158

SEC-1160

SEC-1163

SEC-1164

SEC-1165

SEC-1166

SEC-1167

SEC-1168

SEC-1170

SEC-1171

SEC-1172

SEC-1173

SEC-1174

SEC-1175

SEC-1176

SEC-1180

SEC-1181

SEC-1182

SEC-1183

SEC-1184

SEC-1185

SEC-1186

SEC-1187

SEC-1188

SEC-1189

SEC-1190

SEC-1191

SEC-1192

SEC-1193

SEC-1195

SEC-1196

SEC-1197

SEC-1198

SEC-1199

SEC-1200

SEC-1201

SEC-1202

SEC-1203

SEC-1250

SEC-1251

SEC-1253

SEC-1300

SEC-1301

SEC-1302

SEC-1303

SEC-1304

SEC-1305

SEC-1306

SEC-1307

SEC-1308

SEC-1309

SEC-1310

SEC-1311

SEC-1312

SEC-1313

SEC-1314

SEC-1315

SEC-1317

SEC-1318

SEC-1319

SEC-1320

SEC-1321

SEC-1322

SEC-1323

SEC-1324

SEC-1325

SEC-1326

SEC-1327

SEC-1328

SEC-1329

SEC-1330

SEC-1331

SEC-1332

SEC-1333

SEC-1334

SEC-1335

SEC-1336

SEC-1337

SEC-1338

SEC-1339

SEC-1340

SEC-1341

SEC-1342

SEC-1343

SEC-1344

SEC-1346

SEC-1347

SEC-3035

SEC-3036

SEC-3037

SEC-3038

SEC-3039

SEC-3050

SEC-3051

SEC-3061

SEC-3062

SEC-3063

SEC-3064

SEC-3065

SEC-3066

SEC-3067

SEC-3068

SEC-3069

SEC-3070

SEC-3072

SEC-3073

SEC-3074

SEC-3075

SEC-3076

SEC-3077

SEC-3079

SEC-3080

SEC-3081

5.95 SFLO Messages

SFLO-1001

SFLO-1002

SFLO-1003

SFLO-1004

SFLO-1005

SFLO-1006

SFLO-1007

SFLO-1008

5.96 SLNK Messages

SLNK-1001

SLNK-1002

SLNK-1003

SLNK-1005

5.97 SNMP Messages

SNMP-1001

SNMP-1002

SNMP-1003

SNMP-1004

SNMP-1005

SNMP-1006

SNMP-1009

SNMP-1010

SNMP-1011

SNMP-1012

5.98 SPM Messages

SPM-1001

SPM-1002

SPM-1003

SPM-1004

SPM-1005

SPM-1006

SPM-1007

SPM-1008

SPM-1009

SPM-1010

SPM-1011

SPM-1012

SPM-1013

SPM-1014

SPM-1015

SPM-1016

SPM-3001

SPM-3002

SPM-3003

SPM-3004

SPM-3005

SPM-3006

SPM-3007

SPM-3008

SPM-3009

SPM-3010

SPM-3011

SPM-3012

SPM-3013

SPM-3014

SPM-3015

SPM-3016

SPM-3017

SPM-3018

SPM-3019

SPM-3020

SPM-3021

SPM-3022

SPM-3023

SPM-3024

SPM-3025

SPM-3026

SPM-3027

SPM-3028

SPM-3029

5.99 SRM Messages

SRM-1002

5.100 SS Messages

SS-1000

SS-1001

SS-1002

SS-1003

SS-1004

SS-1005

SS-1006

SS-1007

SS-1008

SS-1009

SS-1010

SS-1011

SS-1012

SS-1013

SS-1014

SS-1015

SS-1016

5.101 SSLP Messages

SSLP-1001

5.102 SSMD Messages

SSMD-1001

SSMD-1002

SSMD-1003

SSMD-1004

SSMD-1005

SSMD-1006

SSMD-1007

SSMD-1008

SSMD-1200

SSMD-1201

SSMD-1202

SSMD-1203

SSMD-1204

SSMD-1205

SSMD-1206

SSMD-1207

SSMD-1208

SSMD-1209

SSMD-1210 SSMD-1211 SSMD-1212 SSMD-1213 SSMD-1214 SSMD-1215 SSMD-1216 SSMD-1217 SSMD-1300 SSMD-1301 SSMD-1302 SSMD-1303 SSMD-1304 SSMD-1305 SSMD-1306 SSMD-1307 SSMD-1308 SSMD-1309 SSMD-1310 SSMD-1311 SSMD-1312 SSMD-1313 SSMD-1314 SSMD-1315 SSMD-1316 SSMD-1317

5.103 SULB Messages

SULB-1001

SSMD-1318

SULB-1002

SULB-1003

SULB-1004

SULB-1005

SULB-1006

SULB-1007

SULB-1008

SULB-1009

SULB-1010

SULB-1011

SULB-1017

SULB-1018

SULB-1020

SULB-1021

SULB-1022

SULB-1023

SULB-1024

SULB-1025

SULB-1026

SULB-1030

SULB-1031

SULB-1032

SULB-1033

SULB-1034

SULB-1035

SULB-1036

SULB-1037

SULB-1039

SULB-1040

SULB-1041

SULB-1042

SULB-1043

SULB-1044

SULB-1050

SULB-1051

SULB-1052

SULB-1053

SULB-1054

SULB-1055

SULB-1056

SULB-1060

SULB-1061

5.104 SWCH Messages

SWCH-1001

SWCH-1002

SWCH-1003

SWCH-1004

SWCH-1005

SWCH-1006

SWCH-1007

SWCH-1008

SWCH-1009

SWCH-1010

SWCH-1011

SWCH-1012

SWCH-1013

SWCH-1014

SWCH-1015

SWCH-1016

SWCH-1017

SWCH-1018

SWCH-1019

SWCH-1020

SWCH-1021

SWCH-1022

SWCH-1023

SWCH-1024

SWCH-1025

SWCH-1026

SWCH-1027

SWCH-1028

SWCH-1031

SWCH-1032

SWCH-1033

SWCH-1041

SWCH-1044

SWCH-1045

SWCH-1046

SWCH-1047

SWCH-1048

SWCH-1049

SWCH-1051

SWCH-1052

SWCH-1053

SWCH-1060

SWCH-1061

SWCH-1062

SWCH-1063

SWCH-1064

5.105 SYSC Messages

SYSC-1001

SYSC-1002

SYSC-1004

SYSC-1005

5.106 SYSM Messages

SYSM-1001

SYSM-1002

SYSM-1003

SYSM-1004

SYSM-1005

SYSM-1006

SYSM-1007

5.107 TRCE Messages

TRCE-1001

TRCE-1002

TRCE-1003

TRCE-1004

TRCE-1005

TRCE-1006

TRCE-1007

TRCE-1008

TRCE-1009

TRCE-1010

TRCE-1011

TRCE-1012

TRCE-1013

5.108 TS Messages

TS-1001

TS-1002

TS-1006

TS-1007

TS-1008

TS-1009

TS-1010

TS-1011

TS-1012

TS-1013

5.109 UCID Messages

UCID-1001

5.110 UCST Messages

UCST-1003

UCST-1007

UCST-1020

UCST-1021

UCST-1022

UCST-1023

UCST-1024

UCST-1026

UCST-1027

UCST-1028

UCST-1029

UCST-1030

UCST-1031

UCST-1032

UCST-1033

5.111 UFCS Messages

UFCS-1001

UFCS-1002

UFCS-1003

UFCS-2004

UFCS-2005

UFCS-2006

5.112 UPTH Messages

UPTH-1001

UPTH-1002

5.113 VS Messages

VS-1001

VS-1002

VS-1003

VS-1004

VS-1005

VS-1006

VS-1007

VS-1008

5.114 WEBD Messages

WEBD-1001

WEBD-1002

WEBD-1004

WEBD-1005

WEBD-1006

WEBD-1007

WEBD-1008

WEBD-1009

5.115 XTUN Messages

XTUN-1000

XTUN-1001

XTUN-1002

XTUN-1003

XTUN-1004

XTUN-1005

XTUN-1006

XTUN-1007

XTUN-1008

XTUN-1009

XTUN-1010

XTUN-1011

XTUN-1012

XTUN-1996

XTUN-1997

XTUN-1998

XTUN-1999

XTUN-2000

XTUN-2001

XTUN-2002

XTUN-2003

XTUN-2004

XTUN-2005

XTUN-2006 XTUN-2007 XTUN-2008 XTUN-2009 XTUN-2010 XTUN-2011 XTUN-2012 XTUN-2020 XTUN-2021 XTUN-2022 XTUN-2023 XTUN-2024 XTUN-2025 XTUN-2026 XTUN-3000 XTUN-3001 XTUN-3002 XTUN-3003 XTUN-3004 XTUN-3005 XTUN-3006

XTUN-3007

XTUN-3008

XTUN-3009

XTUN-3100

XTUN-3101

XTUN-3102

5.116 ZONE Messages

ZONE-1002

ZONE-1003

ZONE-1004

ZONE-1007

ZONE-1010

ZONE-1013

ZONE-1015

ZONE-1017

ZONE-1019

ZONE-1022

ZONE-1023

ZONE-1024

ZONE-1026

ZONE-1027

ZONE-1028

ZONE-1029

ZONE-1034

ZONE-1036

ZONE-1037

ZONE-1038

ZONE-1039

ZONE-1040

ZONE-1041

ZONE-1042

ZONE-1043

ZONE-1044

ZONE-1045

ZONE-1046

ZONE-1048

ZONE-1049

ZONE-1054

ZONE-1057

ZONE-1058

ZONE-1059

ZONE-1060

ZONE-1061

ZONE-1062

ZONE-1064

ZONE-1065

ZONE-1066

ZONE-1067

ZONE-1068

ZONE-1069

ZONE-1070

ZONE-1071

ZONE-1072

ZONE-1073

ZONE-1074

ZONE-1075

ZONE-1076

ZONE-1077

ZONE-1078

ZONE-1079

ZONE-1080

ZONE-1081

ZONE-1082

ZONE-1083

ZONE-1084

ZONE-1085

ZONE-1086

ZONE-1087

ZONE-1088

ZONE-1089

ZONE-1090

ZONE-1091

ZONE-1092

ZONE-1093

ZONE-1094

ZONE-3027

ZONE-3028

ZONE-3032

ZONE-3033

ZONE-3034

Chapter 6: Fabric OS System Messages

6.1 AG Messages

AG-1001

Message

 $\mbox{N_Port ID}$ virtualization (NPIV) is not supported by fabric port connected to port cport number>.

Message Type

LOG

Severity

ERROR

Probable Cause

Indicates that the N_Port ID virtualization (NPIV) capability is not supported by the fabric port to which the Access Gateway is connected.

Recommended Action

- Execute the portCfgNpivPort command to enable NPIV capability on the port connected to the Access Gateway.
- Some blades and ports in a switch may not support NPIV. NPIV functionality cannot be enabled on such ports, and they will not respond to NPIV requests. Refer to the *Brocade Fabric OS Access Gateway Administration Guide* for specific AG-compatibility requirements.
- On non-Brocade switches, refer to the manufacturer's documentation to determine whether the switch supports NPIV and how to enable NPIV on these types of switches.

AG-1002

Message Unable to find alternate N_Port during failover for N_Port <port number>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that no other N Port is configured or that the fabric was unstable during failover.

Recommended Check whether an alternate N_Port is configured using the **portCfgShow** command.

Action If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the supportSave command and contact your switch service provider.

AG-1003

Message Unable to failover N Port <port number>. Failover across different fabric is not

supported.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the failover does not get blocked between two fabrics, although it is not a supported

configuration.

Recommended Configure two or more N_Ports to connect to the same fabric; then execute the ag --failoverenable

command to enable failover on these N_Ports.

AG-1004

Message Invalid response to fabric login (FLOGI) request from the fabric for N_Port <port

number> wwn <port wwn>.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the fabric sent an invalid response to the FLOGI Extended Link Service (ELS) for the

specified N Port.

Recommended Check the configuration of the fabric switch.

Action

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

AG-1005

Message FDISC response was dropped because F_Port <port number> is offline.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the F Port connected to the host is offline, which caused the Fabric Discovery (FDISC)

response to drop.

Recommended

Action

Check the configuration of the host connected to the specified F Port.

AG-1006

Message Access Gateway mode has been <message>.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that Access Gateway mode has been enabled or disabled.

Recommended Execute the **ag --modeshow** command to verify the current status of Access Gateway mode.

Action

AG-1007

Message FLOGI response not received for the N Port <port number> connected to the fabric.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the N Port connected to the fabric switch is not online. The specified N Port has been

disabled.

Recommended Check the connectivity between the Access Gateway N_Port and the fabric switch port.

Action

AG-1008

 $\begin{tabular}{ll} \textbf{Message} & \textbf{Invalid Port Login (PLOGI) response from the fabric on the $N_{\tt Port < port number>.}$ \end{tabular}$

Message Type LOG

Severity WARNING

Probable Cause Indicates that the fabric switch management server did not accept the N_Port Login (PLOGI) request

sent by the Access Gateway.

Recommended Action Check the configuration of the fabric switch connected to the Access Gateway.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

AG-1009

Message Sending FLOGI failed on N_Port <port number>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that there was a failure sending a Fabric Login (FLOGI) request from the Access Gateway to

the fabric switch.

Recommended

Action

Check the configuration of the fabric switch connected to the Access Gateway.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

AG-1010

Message Sending PLOGI failed on N Port <port number>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that there was a failure sending an N_Port Login (PLOGI) request from the Access Gateway

to the fabric switch.

Recommended

Action

Check the configuration of the fabric switch connected to the Access Gateway.

If the message persists, execute the ${\it supportFtp}$ command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

AG-1011

Message Sending FDISC failed on N_Port <port number>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that there was a failure sending a discover F Port service parameter request from the

Access Gateway to the fabric switch.

Recommended Check the con

Action

Check the configuration of the fabric switch connected to the Access Gateway.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the supportSave command and contact your switch service provider.

AG-1012

Message Sending logout (LOGO) request failed on N Port <port number>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that there was a failure sending an N_Port logout request from the Access Gateway to the

fabric switch.

Recommended

Action

Check the configuration of the fabric switch connected to the Access Gateway.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

AG-1013

Message F Ports mapped to N Port <port number> failed over to other N Port(s).

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified N Port is failing over to other N Ports connected to the same fabric.

Recommended Execute the **ag --mapshow** command to display the updated F_Port-to-N_Port mapping.

Action

AG-1014

Message Failing back F Ports mapped to N Port <port number>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified N_Port is failing back F_Ports mapped to it.

Recommended Execute the ag --mapshow command to display the updated F Port-to-N Port mapping.

Action

AG-1015

Message Unable to find online N Ports to connect to the fabric.

Message Type LOG

Severity WARNING

Probable Cause Indicates that no other N_Port is configured or that all N_Ports are currently offline.

Recommended

Action

Check whether any other N_Port is configured using the **portCfgShow** command.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

AG-1016

Message Failing over F Ports mapped to N Port <port number> to other N Port(s).

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified N Port has failed to come online. All F Ports mapped to this N Port are

failing over to other active N Ports.

Recommended Execute the ag --mapshow command to display the updated F Port-to-N Port mapping.

Action

AG-1017

Message No N Port(s) are currently Online.

Message Type LOG

Severity WARNING

Probable Cause Indicates that no N Ports are currently configured in the system or that all configured N Ports have

failed to come online.

Recommended Ex

Action

Execute the **switchShow** command to display the status of all ports in the system. Execute the

portCfgShow command to display the list of ports currently configured as N_Ports.

AG-1018

 $\begin{tabular}{ll} \textbf{Message} & \textbf{Host port should not be connected to port <port number> which is configured as $N_Port.$ \\ \end{tabular}$

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that an initiator or target port is erroneously connected to a port configured for N_Port

operation.

Recommended Execute the **switchShow** command to display the status of all ports in the system. Execute the

portCfgShow command to display the list of ports currently configured as N Ports. Make sure that the

host is connected to an F Port.

AG-1019

Message Unable to failover N_Port <port number>. No other N_Port in port group:<pgid> is

online.

Message Type LOG

Severity WARNING

Probable Cause Indicates that failover across port groups is not supported.

Recommended Check whether an alternate N_Port is configured in the specified port group using the ag --pgshow

Action command.

AG-1020

Message F Ports to N Ports route/mapping has been changed.

Message Type LOG

Severity INFO

Probable Cause Indicates that the F Port-to-N Port mapping has been changed because the switch has come online

or some new N Ports or F Ports have come online.

Recommended Execute the ag --mapshow command to display the updated F Port-to-N Port mapping.

Action

AG-1021

Message Unable to do Preferred-Failover of F Port <port number>. Failover across different

fabric is not supported.

Message Type LOG

Severity WARNING

Probable Cause Indicates that failover across N_Ports connected to different fabrics is not supported.

Recommended Change the preferred N_Port settings of the specified F_Port using the ag --prefset command.

Action

Choose the preferred N_{port} so that it is in the same fabric as the primary N_{port} of this F_{port} .

Execute the **ag** --show command to check the fabric connectivity of the N_Ports.

AG-1022

Message F_Port <f_port> is failed over to its preferred N_Port <n_port>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified F_Port is failing over to its preferred N_Port.

Recommended Execute the ag --mapshow command to display the updated F Port-to-N Port mapping.

Action

AG-1023

Message F Port <f port> mapped to offline N Port <n port> is failed over to its preferred

N Port preferred port>.

Message Type LOG

> INFO Severity

Probable Cause Indicates that the specified N Port has failed to come online. The F Port mapped to this N Port had

its preferred set and is online.

Execute the ag --mapshow command to display the updated F Port-to-N Port mapping. Recommended

Action

AG-1024

Message F Port <f port> is failed back to its preferred N Port <n port>.

Message Type LOG

> Severity **INFO**

Probable Cause Indicates that the specified N Port is failing back F Ports, which are failed over to some other N Port.

Recommended Execute the ag --mapshow command to display the updated F Port-to-N Port mapping.

Action

AG-1025

Message Port group of Slave N Port <port number> is different than its Master N Port <n port>.

Message Type LOG

> **ERROR** Severity

Probable Cause Indicates that the port groups of the master and slave N_Ports are different, while the trunk area

assigned to the attached F Ports on the edge switch is the same.

Execute the porttrunkarea --show command on the attached switch to verify that the trunk area is Recommended Action

assigned to all ports in the system, and execute the porttrunkarea --enable command to reconfigure

the trunk area.

AG-1026

FOS-90x-Message-RM103 Broadcom

Message Unable to handle the login request on port <port number> due to insufficient

resources.

Message Type LOG

Severity WARNING

Probable Cause Indicates that there are insufficient resources to accept the login request.

Recommended Execute the configure command on the Access Gateway switch and increase the number of allowed

Action logins on the specified port.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the supportSave command and contact your switch service provider.

AG-1027

Message Unable to handle this login request on port <port number> because NPIV capability is

not enabled on this port.

Message Type LOG

Severity WARNING

Probable Cause Indicates that N Port ID virtualization (NPIV) is not enabled on the specified port.

Recommended Execute the **portCfgNpivPort** command on the Access Gateway switch to enable the NPIV capability

Action on the port.

AG-1028

Message Device with Port WWN <port name> tried to perform fabric login through port <f port>,

without having access permission.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the device does not have login access for the specified port as per the Advanced Device

Security (ADS) policy set by the user.

Recommended Add the device to the ADS allow list for the specified port using the **ag --adsadd** command.

Action

AG-1029

Message Port Group (ID: <pqid>) has ports going to different fabrics.

Message Type LOG

Severity WARNING

Probable Cause Indicates a misconfiguration.

Recommended

Action

Connect all ports in the port group to the same fabric.

AG-1030

Message N Port (ID: <port number>) has been determined to be unreliable.

LOG Message Type

> Severity WARNING

Probable Cause Indicates that the port goes online and offline often, and therefore the port is marked as unreliable.

Recommended No action is required. The port will automatically be marked as reliable after a certain interval of time if Action

the port toggling remains within the threshold limit.

AG-1031

Message Loop Detected for device with Port WWN <port name> connected to port <port number>.

Message Type LOG

> Severity WARNING

Probable Cause Indicates that a routing loop is detected for the device connected to the specified port.

Recommended Check the device configuration.

Action

AG-1032

Message N Port (ID: <port number>) has recovered from an unreliable state.

Message Type LOG

> Severity INFO

Probable Cause Indicates that the port state has been stable for the last 5 minutes.

AG-1033

Message F Port to N Port mapping has been updated for N Port (<n port>).

Message Type AUDIT | LOG

> Class **CFG**

Severity INFO

Probable Cause Indicates that the F_Ports mapped to an N_Port have changed and that the configuration file has been

updated.

AG-1034

Message F Port cannot accept any more logins (<f port>).

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the F Port has already logged in the maximum number of devices.

AG-1035

Message Device (<wwn>) connected to F-port (<f_port>) cannot login as ALPA value is not

available (<alpa>).

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that a device has already used the specified arbitrated loop physical address (ALPA) value.

AG-1036

Message Port <port number> is connected to a non-Brocade fabric with Persistent ALPA enabled.

Check the admin guide for supported configuration.

Message Type AUDIT | LOG

Class CFG

Severity WARNING

Probable Cause Indicates that one of the ports is connected to a non-Brocade fabric.

Recommended Refer to the Brocade Fabric OS Access Gateway Administration Guide for the supported

Action configuration.

AG-1037

Message Trunked N_Port (<n_port>) going offline. If switchshow CLI for the connected fabric

switch port displays Persistently disabled: Area has been acquired, then check

cabling: all trunked ports should be in same ASIC Port Group.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates incorrect cabling.

Recommended If the **switchShow** command on the connected fabric switch port displays **Persistently disabled**:

Area has been acquired, then check cabling on the Access Gateway. All trunked ports in a single

trunk must belong to the same application-specific integrated circuit (ASIC) port group.

AG-1038

Message Brocade 8000 ports are going to different fabrics, check N Port (<n port>).

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates a misconfiguration.

Recommended Connect all ports in the port group to the same fabric.

Action

AG-1039

Message F_Port <Port that was reset> was reset because a WWN mapped device using it, through

N Port <Port who's state change caused the reset>, went offline.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified F Port was reset because an N Port went offline and the changes need to

be propagated to all involved devices.

Recommended No action is required. This port reset was not an error.

Action

AG-1040

Message PID of the devices connected to Port <port number> may have changed, as the port was

toggled. Check EE monitor <Truncated message>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that N_Port ID virtualization (NPIV) assigns a new port ID (PID) each time the same port is

disabled and then re-enabled. As the PID has changed, the end-to-end (EE) monitors installed with the

previous PID stop functioning.

Recommended Action Install new EE monitors with the new PID of the port to be monitored by using the **perfAddEEMonitor** command.

AG-1041

 $\begin{tabular}{ll} \textbf{Message} & \textbf{Static F_Ports mapped to N_Port <port number> are disabled as Trunking is enabled on the state of the state of$

the N Port.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a trunk is enabled on the specified N_Port, and therefore the F_Port static mapping is

disabled.

Recommended Delete the static mapping on the Access Gateway using the ag --staticdel command or disable the

Action trunk on the N_Port using the **switchCfgTrunkPort** command.

AG-1042

Message Sending ELS_PORT_OPEN failed on N_Port <port number>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that there was a failure sending an ELS_PORT_OPEN request from the Access Gateway to

the fabric switch.

Recommended Check the configuration of the fabric switch connected to the Access Gateway.

Action ____

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportFsys** command and centest your switch convice provider.

transfers; then execute the **supportSave** command and contact your switch service provider.

AG-1043

Message Authentication cannot be negotiated with the connected switch/HBA and therefore

disabling the Port <port number>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that authentication has failed on the specified port. A possible reason could be that the edge

switch connected to Access Gateway is using firmware earlier than Fabric OS 7.1.0.

Recommended Check the authentication configuration of the edge switch using the **authutil --show** command.

Action

AG-1044

Message Port <Port Number> has been disabled because switch requires authentication when

device authentication policy is set to ON.

Message Type LOG

> Severity **WARNING**

Probable Cause Indicates that a device that does not support authentication has tried to log in to the switch when the

device authentication policy is in the ON state on the switch.

Enable authentication on the device or set the device authentication state to PASSIVE/OFF on the Recommended Action

switch if it is not mandatory. Use the authUtil command to change the device authentication policy.

AG-1045

Message New port <nport> has same Port WWN as old port <fport> as part of duplicate Port WWN

detection policy.

Message Type LOG

> WARNING Severity

Probable Cause Indicates that the specified new port has the same Port World Wide Name (PWWN) as the old port.

AG-1046

Message D Port test will not start due to error in removing mapping for the F Port <port>.

Retry after sometime.

Message Type AUDIT | LOG

> Class **CFG**

Severity INFO

Probable Cause Indicates that there is an error in removing the mapping for the specified port and that consequently

there was a failure in starting the D Port test.

Recommended Retry the D Port test after some time.

Action

AG-1047

Message Error in restoring one or all the mappings for the F Port <port>. Add the mappings

manually. Configured <Configured N-port>, Static <Static N-port> and Preferred

<Preferred N-port>.

Message Type AUDIT | LOG

> **CFG** Class

Severity INFO

Probable Cause Indicates that there is an error in restoring the mapping for the specified port.

Recommended Add the mappings to the port manually.

Action

AG-1048

Message Invalid N Port online SCN on port <port>. Port state is already active.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the N_port online state change notification (SCN) has been received on the port, which

has already logged in.

Recommended If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

AG-1049

Message Name of the port group <pgid> has been changed to <pgname> from <old_pgname>.

Message Type AUDIT

Action

Class CFG

Severity INFO

Probable Cause Indicates that the name of the Port Group has been changed.

AG-1050

Message N-Ports <nports> are added to the Port Group <pgid>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the N_Port(s) have been added to the port group.

AG-1051

Message N-Ports <nports> are deleted from the Port Group <pgid>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the N Port(s) have been deleted from the port group.

AG-1052

Message User defined Port Group <pgid> has been created with name <pgname> and <mode> mode> mode.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that a user-defined port group has been created.

AG-1053

Message User defined Port Group <pgid> has been deleted.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that a user-defined port group has been deleted.

AG-1054

Message Operational mode <mode> has been enabled for Port Group <pgid>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the operational mode has been enabled for the port group.

AG-1055

Message Operational mode <mode> has been disabled for Port Group <pgid>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the operational mode has been disabled for the port group.

AG-1056

Message Device PWWN <wwn> has been cleared from the ALPA login table.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the device Port World Wide Name (PWWN) entry has been cleared from the arbitrated

loop physical address (ALPA) login table.

AG-1057

Message Persistent ALPA has been enabled with <mode> mode.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the persistent arbitrated loop physical address (ALPA) has been enabled with stringent/

flexible mode.

AG-1058

Message Persistent ALPA has been disabled.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the Persistent arbitrated loop physical address(ALPA) has been disabled.

AG-1059

Message Automap balance has been enabled for <port type> in Port Group <pgid>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the automap balance has been enabled for N_Ports/F_Ports in the port group.

AG-1060

Message Automap balance has been disabled for <port type> in Port Group <pgid>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the automap balance has been disabled for N_Ports/F_Ports in the port group.

AG-1061

Message Automap balance has been enabled for <port type> in Auto Policy.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the automap balance has been enabled for N_Ports/F_Ports in the Auto Policy.

AG-1062

Message Automap balance has been disabled for <port type> in Auto Policy.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the automap balance has been disabled for N_Ports/F_Ports in the Auto Policy.

AG-1063

Message Failover has been enabled for N-Port <nport> in the Port Group <pgid>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that failover has been enabled for the N Port in the switch.

AG-1064

Message Failover has been disabled for N-Port <nport> in the Port Group <pgid>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that failover has been disabled for the N_Port in the switch.

AG-1065

Message Failback has been enabled for N-Port <nport> in the Port Group <pgid>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that failback has been enabled for the N Port in the switch.

AG-1066

Message Failback has been disabled for N-Port <nport> in the Port Group <pgid>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that failback has been disabled for the N Port in the switch.

AG-1067

Message N-Port <nport> has been set as Preferred N-Port for F-Port <fport>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the N_Port has been set as the preferred N_Port for the F_Port.

AG-1068

Message N-Port <nport> has been deleted as Preferred N-Port for F-Port <printf>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the N_Port has been deleted as the preferred N_Port for the F_Port.

AG-1069

Message Port <nport> has been configured as Primary N-Port (Device Mappings) for the device

with WWN <wwn>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the port is configured as primary N Port for the device.

AG-1070

Message N-Port <nport> has been removed as Primary N-Port (Device Mappings) for the device

with WWN <wwn>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the N Port has been removed as primary N Port for the device.

AG-1071

Message Device with WWN <wwn> (Device Mappings) has been added to the Port Group <pgid>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the device has been added to the port group.

AG-1072

Message Device with WWN <wwn> (Device Mappings) has been removed from the Port Group <pgid>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the device has been removed from the port group.

AG-1073

Message Static device mapping(s) are enabled for WWN <wwn>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the static device mappings are enabled for the given World Wide Name (WWN).

AG-1074

Message Static device mapping(s) are disabled for WWN <wwn>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the static device mappings are disabled for the given World Wide Name (WWN).

AG-1075

Message Port <nport> has been configured as Failover N-Port (Device Mappings) for the device

with WWN <wwn>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the port is configured as a failover N_Port for the device.

AG-1076

Message N-Port <nport> has been removed as Failover N-Port (Device Mappings) for the device

with WWN <wwn>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the N_Port has been removed as a failover N_Port for the device.

AG-1077

Message Fabric Name Monitoring timeout value has been changed to (<seconds>) seconds.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the Fabric Name Monitoring timeout value changed.

AG-1078

Message <wwn> devices are allowed on the Port <fport>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that all the devices or no devices are allowed on the port.

AG-1079

 $\begin{tabular}{ll} \textbf{Message} & \textbf{Device <wwn> is added to the allowed list on Port <fport>.} \end{tabular}$

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the device has been added to the allowed list on the port.

AG-1080

Message Device <wwn> is deleted from the allowed list on the Port <fport>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the device has been deleted from the allowed list on the port.

AG-1081

Message The reliability counter value has been changed to <value>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the reliability counter value has been changed.

AG-1082

Message The configured, static and preferred mappings for the N-Port <nport> have been saved.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the configured, static, and preferred mappings for the N_Port have been saved.

AG-1083

Message The backed up mappings for the N-Port <nport> have been deleted.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the backed-up mappings for the N_Port have been deleted.

AG-1084

Message <policy name> policy is <policy status>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause The user has changed the policy.

Recommended Run ag --policyshow to display the current policy.

Action

AG-1085

Message Message received on unexpected port -- iu sid=0x<source id> iu port=<port in frame>

msg_port=<port_in_msg> l_fport=<fport_in_login_table>

l alpa=0x<alpa in login table> l nport=<nport in login table>.

Message Type LOG

Severity WARNING

Probable Cause A frame was received on an unexpected port.

Recommended Collect a supportsave as soon as possible and notify the device vendor.

Action

AG-1086

Message Slow drain device 0x<PID of slow drain device> connected to F-port (<Fport>) have

been quarantined.

Message Type LOG

Severity INFO

Probable Cause Indicates that all devices that are zoned with the slow-drain device have been quarantined.

Recommended To check all affected devices zoned to the slow- drain device, use the nszonemember command in the

Action edge fabric.

AG-1087

Message Slow drain device 0x<PID of slow drain device> connected to F-port (<Fport>) have

been unquarantined.

Message Type LOG

Severity INFO

Probable Cause Indicates that all the devices that are zoned with the slow-drain device have been unquarantined.

Recommended Action To check all affected devices zoned to the slow-drain device, use the nszonemember command in the edge fabric.

AG-1088

Message N Port <port number> failed to login due to D Port Configuration mismatch.

Message Type LOG

Severity ERROR

Probable Cause N_Port fail to come up due to D_Port Configuration mismatch Between the Access Gateway and

Fabric Switch.

Recommended Please configure N Port as static D Port in Access Gateway or Clear the Static D Port configuration

Action from the Fabric Switch.

AG-1089

Message No N Port(s) are currently Online in Port Group (<Port Group ID>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that no N Ports are currently configured in the given Port Group or all configured N Ports in

given Port Group have failed to come online.

Recommended Execute the **switchShow** command to display the status of all ports in the system. Execute the

portCfgShow command to display the list of ports currently configured as N Ports.

AG-1090

Message use count of the IU that is received by AG port = <port>.

Message Type LOG

Action

Severity ERROR

Probable Cause To find the use count of the IU that is received by AG.

Recommended Please execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then

Action execute the **supportSave** command and contact your switch service provider.

AG-1091

Message Invalid AC port SCN received on Port (<port>) which is not part of Trunk

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the AC Master port scn which is not in Trunk state.

Recommended None.

Action

6.2 AMPM Messages

AMPM-1000

Message AMP MP:Slot=<Slot Number(0 for 7840)> DP=<DP ID>:Reached maximum flow entries

limit: < Maximum Supported Flow Count>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the maximum number of supported LU WWN entries in the hash table has been

reached.

Recommended Make sure not to initiate new flows.

Action

AMPM-1001

Message AMP MP:Slot=<Slot Number(0 for 7840)> DP=<DP ID>:Reached maximum default LU WWN

entries limit: < Maximum Supported Default Flow Count>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the maximum number of supported default LU WWN entries in hash table has been

reached.

Recommended Make sure not to initiate new flows.

Action

6.3 AN Messages

AN-1001

Message Failed to allocate memory: (<function name>).

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified function has failed to allocate memory.

Recommended Check memory usage on the switch using the **memShow** command. Restart or power-cycle the

Action switch.

AN-1002

Message Failed to initialize; rc = <error>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the initialization of the "trafd" daemon has failed.

Recommended Download a new firmware version using the **firmwareDownload** command.

Action

AN-1010

Message Severe latency bottleneck detected at <Port Type> <slotport string>.

Message Type LOG | AUDIT

Class FABRIC

Severity WARNING

Probable Cause Indicates credit loss at the specified port, a downstream port, or a very high latency device at the edge

of the fabric.

Recommended Contact your switch service provider for assistance.

Action

AN-1011

Message Could not distinguish between primary and dependent severe latency bottleneck on port

<slotport string> because port mirroring is enabled on this port.

Message Type LOG | AUDIT

Class FABRIC

Severity WARNING

Probable Cause Indicates that resources that are needed to determine whether there is complete credit loss on a virtual

channel (VC) at the specified port are used by port mirroring.

Recommended

Contact your switch service provider for assistance.

Action

AN-1012

Message Credits did not return from other end. Complete loss of credits on a VC on port

<slotport string>.

Message Type LOG | AUDIT

Class FABRIC

Severity WARNING

Probable Cause Indicates a credit loss.

Recommended If this message is not followed by the AN-1013 message, contact your switch service provider for

Action assistance.

AN-1013

Message Performed link reset to recover the port credits on port <slotport string>.

Message Type LOG | AUDIT

Class FABRIC

Severity INFO

Probable Cause Indicates a credit loss.

Recommended The port is recovered. No action is required.

Action

AN-1014

Message Frame <frametype> detected, tx port <tx slotport string> rx port <rx slotport string>,

sid <sid>, did <did>, timestamp <timestamp>.

Message Type LOG | AUDIT

Class FABRIC

Severity INFO

Probable Cause Indicates a C3 discard frame.

Recommended Check the Brocade Fabric OS Troubleshooting and Diagnostics User Guide for troubleshooting

Action information or contact your switch service provider if the message persists.

6.4 ASVR Messages

ASVR-1001

Message Maximum VM registrations exceeded for PID 0x<pid>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the host adapter has attempted to register a greater number of virtual machines than is

supported.

Recommended Configure fewer virtual machines on the host at the specified port ID (PID).

Action

6.5 AUTH Messages

AUTH-1001

Message <Operation type> has been successfully completed.

Message Type LOG

Severity INFO

Probable Cause Indicates that the secret database operation has been updated using the **secAuthSecret** command.

The values for the operation type can be "set" or "remove".

AUTH-1002

Message <Operation type> has failed.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified action has failed to update the secret database using the secAuthSecret

command. The values for the operation type can be "set" or "remove".

Recommended Execute the **secAuthSecret** command again.

Action

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

AUTH-1003

Message <data type> type has been successfully set to <setting value>.

Message Type LOG

Severity INFO

Probable Cause Indicates that an authentication configuration value was set to a specified value. The data type is

authentication type, DH group type, hash type, or policy type.

AUTH-1004

Message Failed to set <data type> type to <setting value>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the authUtil command has failed to set the authentication configuration value. The data

type can be authentication type, DH group type, hash type, or policy type.

Recommended Execute the **authUtil** command again.

Action

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

AUTH-1005

Message Authentication file does not exist: <error code>.

Message Type LOG

Severity ERROR

Probable Cause Indicates an authentication file corruption.

Recommended Execute the **firmwareDownload** command to reinstall the firmware.

Action

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

AUTH-1006

Message Failed to open authentication configuration file.

Message Type LOG

Severity WARNING

Probable Cause Indicates an internal problem with the Secure Fabric OS.

Recommended Reinitialize authentication using the portDisable and portEnable commands or the switchDisable

Action and switchEnable commands.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

AUTH-1007

Message The proposed authentication protocol(s) are not supported: port <port number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the proposed authentication protocol types are not supported by the specified local port.

Recommended Execute the **authUtil** command to make sure that the local switch supports the Fibre Channel Action Authentication Protocol (FCAP) or Diffie-Hellman Challenge Handshake Protocol (DHCHAP)

protocols.

AUTH-1008

Message No security license, operation failed.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the switch does not have a security license.

Recommended Verify that the security license is installed using the **licenseShow** command. If necessary, reinstall the

license using the licenseAdd command.

AUTH-1010

Message Failed to initialize security policy: switch <switch number>, error <error code>.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates an internal problem with the Secure Fabric OS.

Recommended Reboot or power-cycle the switch.

Action

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the supportSave command and contact your switch service provider.

AUTH-1011

Message Failed to register for failover operation: switch <switch number> error <error code>.

Message Type LOG

Severity WARNING

Probable Cause Indicates an internal problem with the Secure Fabric OS.

Recommended

Action

Reinitialize authentication using the **portDisable** and **portEnable** commands or the **switchDisable** and **switchEnable** commands.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

AUTH-1012

Message Authentication <code> is rejected: port <port number> explain <explain code> reason

<reason code>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified authentication is rejected because the remote entity does not support

authentication.

Recommended Verify the hash type, protocol, group, and authentication policy using the **authutil --show** command.

Action

AUTH-1013

Message Cannot perform authentication request message: port port number>, message code

<message code>.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that the system is running low on resources when receiving an authentication request.

Usually this problem is transient. The authentication may fail.

Recommended Reinitialize authentication using the portDisable and portEnable commands or the switchDisable

and switchEnable commands.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

AUTH-1014

Message Invalid port value to <operation>: port <port number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates an internal problem with the Secure Fabric OS.

Recommended F

Action

Reinitialize authentication using the **portDisable** and **portEnable** commands or the **switchDisable** and **switchEnable** commands.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

Copy the message and collect the switch information using the **supportShow** command, and contact

AUTH-1016

Message Invalid value to start HBA authentication port: <port number>, pid <pid>.

Message Type LOG

Severity ERROR

Probable Cause Indicates an internal failure.

Action your switch service provider.

AUTH-1017

Recommended

Message Invalid value to start authentication request: port port number>, operation code

<operation code>.

Message Type LOG

Severity ERROR

Probable Cause Indicates an internal problem with the Secure Fabric OS.

Action and switchEnable commands.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

Reinitialize authentication using the portDisable and portEnable commands or the switchDisable

AUTH-1018

Recommended

Message Invalid value to check protocol type: port <port number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates an internal problem with the Secure Fabric OS.

Recommended Reinitialize authentication using the **portDisable** and **portEnable** commands or the **switchDisable**

Action and switchEnable commands.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

AUTH-1020

Message Failed to create timer for authentication: port <port number>.

Message Type LOG

Severity INFO

Probable Cause Indicates that an authentication message timer was not created. Usually this problem is transient. The

authentication may fail.

Recommended Reinitialize authentication using the portDisable and portEnable commands or the switchDisable

Action and switchEnable commands.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

AUTH-1022

Message Failed to extract <data type> from <message> payload: port <port number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the authentication process failed to extract a particular value from the receiving payload.

Usually this problem is transient. The authentication may fail.

Recommended Reinitialize authentication using the portDisable and portEnable commands or the switchDisable

Action and switchEnable commands.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

AUTH-1023

Message Failed to operation type> during <authentication phase>: port <port number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that an authentication operation failed for a certain authentication phase. The operation type

varies depending on authentication type:

■ Some operations for Switch Link Authentication Protocol (SLAP): certificate retrieve, certificate verification, signature verification, or nonce signing.

- Some operations for Fibre Channel Authentication Protocol (FCAP): certificate retrieve, certificate verification, signature verification, or nonce signing.
- Some operations for Diffie-Hellman Challenge Handshake Authentication Protocol (DHCHAP): response calculation, challenge generation, or secret retrieve.

The authentication phase specifies which phase of a particular authentication protocol failed.

A nonce is a single-use, usually random value used in authentication protocols to prevent replay attacks.

Recommended Action

The error may indicate that an invalid entity tried to connect to the switch. Check the connection port for a possible unauthorized access attack.

It may indicate that the public key infrastructure (PKI) object for SLAP or FCAP or the secret value for DHCHAP on the local entity is not set up properly. Reinstall all PKI objects or reset the secret value for DHCHAP properly.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

AUTH-1025

Message Failed to get <data type> during <authentication phase>: port <port number>.

Message Type LOG

Severity ERROR

Indicates that the authentication process failed to get expected information during the specified authentication phase. Usually this problem is transient. The authentication may fail.

Recommended Action

Probable Cause

Reinitialize authentication using the **portDisable** and **portEnable** commands or the **switchDisable** and **switchEnable** commands.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

AUTH-1026

Message Failed to <Device information> during negotiation phase: port <port number>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the authentication failed to get device or host bus adapter (HBA) information due to an

internal failure. Usually this problem is transient. If the authentication failed, retry the login.

Recommended Action Reinitialize authentication using the **portDisable** and **portEnable** commands or the **switchDisable** and **switchEnable** commands.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

AUTH-1027

Message Failed to select <authentication value> during <authentication phase>: value <value>

port <port number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the authentication process failed to select an authentication value (DH group, hash

value, or protocol type) from a receiving payload for a particular authentication phase. This indicates

that the local switch does not support the specified authentication value.

Recommended

Check the authentication configuration and reset the supported value if needed using the authUtil

Action command.

Reinitialize authentication using the **portDisable** and **portEnable** commands or the **switchDisable**

and switchEnable commands.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

AUTH-1028

Message Failed to allocate <data type> for <operation phase>: port <port number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the authentication process failed because the system is low on memory. Usually this

problem is transient. The authentication may fail.

The data type is the payload or structure that failed to get memory. The operation phase specifies

which operation of a particular authentication phase failed.

Recommended

Action

Reinitialize authentication using the **portDisable** and **portEnable** commands or the **switchDisable**

and switchEnable commands.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the supportSave command and contact your switch service provider.

AUTH-1029

Message Failed to get <data type> for <message phase> message: port <port number>, retval

<error code>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the authentication process failed to get a particular authentication value at a certain

phase. Usually this problem is transient. The authentication may fail.

The data type is the payload or structure that failed to get memory.

Recommended Action

Reinitialize authentication using the **portDisable** and **portEnable** commands or the **switchDisable** and **switchEnable** commands.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

AUTH-1030

Message Invalid message code for <message phase> message: port <port number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the receiving payload does not have a valid message code for a particular authentication

phase. Usually this problem is transient. The authentication may fail.

Recommended

nended Reinitialize authentication using the **portDisable** and **portEnable** commands or the **switchDisable**Action and **switchEnable** commands.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

AUTH-1031

Message Failed to retrieve secret value: port <port number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the secret value was not set properly for the authenticated entity.

Recommended

Reset the secret value using the **secAuthSecret** command.

Action

Reinitialize authentication using the **portDisable** and **portEnable** commands or the **switchDisable**

and **switchEnable** commands.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

AUTH-1032

Message Failed to generate <data type> for <message payload> payload: length <data length>,

error code <error code>, port <port number>.

Message Type LOG

Severity ERROR

Probable Cause

Indicates that the authentication process failed to generate specific data (challenge, nonce, or response data) for an authentication payload. This usually relates to an internal failure.

A nonce is a single-use, usually random value used in authentication protocols to prevent replay

attacks.

Usually this problem is transient. The authentication may fail.

Recommended

Action

Reinitialize authentication using the **portDisable** and **portEnable** commands or the **switchDisable** and **switchEnable** commands.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

AUTH-1033

Message

Disable port <port number> due to unauthorized switch <switch WWN value>.

Message Type

LOG

Severity

ERROR

Probable Cause

Indicates that an entity was not configured in the Switch Connection Control (SCC) policy and tried to connect to the port.

Recommended

Action

Add the World Wide Name (WWN) of the entity to the SCC policy and reinitialize authentication by using the **portDisable** and **portEnable** commands or the **switchDisable** and **switchEnable** commands.

AUTH-1034

Message

Failed to validate name <entity name> in <authentication message>: port <port number>.

Message Type

LOG

Severity

ERROR

Probable Cause

Indicates that the specified entity name in the payload is not in the correct format.

Recommended

Action

Reinitialize authentication using the **portDisable** and **portEnable** commands or the **switchDisable**

and switchEnable commands.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

AUTH-1035

Message

Invalid <data type> length in <message phase> message: length <data length>, port
<port number>.

Message Type LOG

Severity **ERROR**

Probable Cause Indicates that a particular data field in the authentication message has an invalid length field. This error

usually relates to an internal failure. Usually this problem is transient. The authentication may fail.

Recommended Action

Reinitialize authentication using the portDisable and portEnable commands or the switchDisable and switchEnable commands.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

AUTH-1036

Message Invalid state <state value> for <authentication phase>: port <port number>.

Message Type LOG

> **ERROR** Severity

Probable Cause Indicates that the switch received an unexpected authentication message. Usually this problem is

transient. The authentication may fail.

Recommended Reinitialize authentication using the portDisable and portEnable commands or the switchDisable Action

and switchEnable commands.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the supportSave command and contact your switch service provider.

AUTH-1037

Message Failed to <operation type> response for <authentication message>: init len <data

length>, resp len <data length>, port <port number>.

Message Type LOG

> **ERROR** Severity

Probable Cause Indicates that a Diffie Hellman - Challenge Handshake Authentication Protocol (DH-CHAP)

authentication operation failed on the specified port due to mismatched response values between two

entities or due to same secret in all the entities.

The error may indicate that an invalid entity tried to connect to the switch. Check the connection port

for a possible security attack.

Recommended Reinitialize authentication using the portDisable and portEnable commands or the switchDisable Action

and switchEnable commands.

If the message persists, execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

AUTH-1038

Message Failed to retrieve certificate during <authentication phase>: port <port number>.

LOG Message Type

> **ERROR** Severity

Probable Cause Indicates that the public key infrastructure (PKI) certificate is not installed properly.

Recommended Action

Reinstall the PKI certificate using the **secCertMgmt** command.

Reinitialize authentication using the portDisable and portEnable commands or the switchDisable

and switchEnable commands.

If the message persists, execute the supportFtp command (as needed) to set up automatic FTP

transfers; then execute the supportSave command and contact your switch service provider.

AUTH-1039

Message Neighboring switch has conflicting authentication policy: Port <Port Number>

disabled.

LOG Message Type

> Severity **ERROR**

Probable Cause Indicates that the neighboring switch has a conflicting authentication policy enabled. The E Port has

been disabled because the neighboring switch has rejected the authentication negotiation, and the

local switch has a strict switch authentication policy.

Recommended

Action

Correct the switch policy configuration on either of the switches using the authUtil command, and then

enable the port using the portEnable command.

AUTH-1040

Message Reject authentication on port <Port Number>, because switch authentication policy is

set to OFF.

Message Type LOG

> **INFO** Severity

Probable Cause Indicates that the local switch has rejected the authentication because the switch policy is turned off. If

the neighboring switch has a strict (ON) switch policy, the port will be disabled due to conflicting

configuration settings. Otherwise, the E_Port will form without authentication.

Recommended

If the port is disabled, correct the switch policy configuration on either of the switches using the Action

authUtil command, and then enable the port on the neighboring switch using the portEnable

command. If the E Port has formed, no action is required.

AUTH-1041

FOS-90x-Message-RM103 Broadcom

Message Port <port number> has been disabled, because an authentication-reject was received

with code '<Reason String>' and explanation '<Explanation String>'.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified port has been disabled because it received an authentication-reject

response from the connected switch or device. The error may indicate that an invalid entity tried to

connect to the switch.

Recommended Check the connection port for a possible security attack.

Action

Check the shared secrets using the **secAuthSecret** command, and reinitialize authentication using

the **portDisable** and **portEnable** commands.

If the message persists, execute the supportFtp command (as needed) to set up automatic FTP

transfers; then execute the supportSave command and contact your switch service provider.

AUTH-1042

Message Port <port number> has been disabled, because authentication failed with code '<Reason

String>' and explanation '<Explanation String>'.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified port has been disabled because the connecting switch or device failed to

authenticate. The error may indicate that an invalid entity attempted to connect to the switch.

Recommended Check the connection port for a possible security attack.

Action

Check the shared secrets using the **secAuthSecret** command, and reinitialize authentication using

the portDisable and portEnable commands.

If the message persists, execute the supportFtp command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

AUTH-1043

Message Failed to enforce device authentication mode: < Device Auth Policy > (error: < Reason

Code>).

Message Type LOG

Severity ERROR

Probable Cause Indicates that the Kernel mode setting for F Port authentication failed. Device authentication will be

defaulted to OFF, and the switch will not participate in Diffie-Hellman Challenge Handshake

Authentication Protocol (DHCHAP) authentication with other devices.

Recommended Action Set the device authentication policy manually using the authUtil command.

AUTH-1044

Message Authentication <Reason for disabling the port>. Disabling the port <port number>.

Message Type LOG | FFDC

Severity ERROR

Probable Cause Indicates that authentication has timed out after multiple retries. The specified port has been disabled

as a result. This problem may be transient due to the system CPU load. In addition, a defective small

form-factor pluggable (SFP) transceiver or faulty cable may have caused the failure.

Recommended

Action

Check the SFP transceiver and the cable; then enable the port using the **portEnable** command.

AUTH-1045

Message Certificate not present in this switch in <authentication phase> port <port number>.

Message Type AUDIT | LOG

Class SECURITY

Severity WARNING

Probable Cause Indicates that the public key infrastructure (PKI) certificate is not installed in this switch.

Recommended

Action

If DHCHAP authentication is also configured and the port is authenticated, no action is needed. Otherwise, check the certificate availability using the **secCertMgmt show -cert fcap** command.

Install the certificate and reinitialize authentication using the portDisable and portEnable commands

or the switchDisable and switchEnable commands.

If the message persists, execute the supportFtp command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

AUTH-1046

Message <Operation type> has been successfully completed.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates that the certificate database operation has been updated using the secAuthCertificate

command. The values for operation type can be "set" or "remove".

AUTH-1047

Message <Operation type> has failed.

Message Type AUDIT | LOG

Class SECURITY

Severity ERROR

Probable Cause Indicates that the specified action has failed to update the certificate database using the

secAuthCertificate command. The values for operation type can be "set" or "remove".

Recommended Execute the **secAuthCertificate** command again.

Action

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

AUTH-1048

Message Stopping synchronization of the system due to <Operation type> incompatibility with

standby CP.

Message Type AUDIT | LOG

Class SECURITY

Severity ERROR

Probable Cause Indicates that the software version on the standby control processor (CP) is incompatible with this

software feature enabled in the Fabric OS firmware version because the in-flight encryption feature

supports both DHCHAP and FCAP protocols.

Recommended Upgrade the software on the standby CP or disable the software feature on this CP.

Action

To allow standby synchronization, use the DHCHAP protocol only for in-flight encryption, and disable

the FCAP protocol in authutil. Use the **authutil --set -a "protocol type"** command to configure the

DHCHAP protocol.

AUTH-1049

Broadcom

Message Slave port <Slave port number> has been disabled, as Master port <Master port number>

was disabled because of authentication failure/rejection.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified slave port has been disabled because it received an authentication-reject

Trobable Gause Indicates that the specified slave port has been disabled because it received an admentication-reject

response from the connected switch or device. The error informs that the slave port is disabled due to a master port authentication failure or rejection.

Recommended Action

Check the connection port for a possible security attack.

Check the shared secrets using the **secAuthSecret** command, or check the certificates using the **secCertMgmt** command, and reinitialize authentication using the **authutil** --authinit command.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

AUTH-1050

Message Port <port number> has been reset, because authentication stage is conflicted with

the peer.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified port has been reset because there is a conflicting authentication stage with

the connected switch or device. The error may indicate that an invalid entity attempted to connect to

the switch.

Recommended

nended Check the connection port for a possible security attack.

Action

If the message persists, execute the ${\it supportFtp}$ command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

AUTH-3001

Message Event: <Event Name>, Status: success, Info: <Data type> type has been changed from

[<Old value>] to [<New value>].

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that an authentication configuration value was set to a specified value. The data type can be

authentication type, DH group type, hash type, or policy type.

AUTH-3002

Message Event: <Event Name>, Status: success, Info: <Event Related Info>.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that the secret database operation has been updated using the **secAuthSecret** command.

AUTH-3003

Message Event: <Event Name>, Status: success, Info: <Operation type> the PKI objects.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that the public key infrastructure (PKI) objects were created using the secCertUtil command

or that the PKI objects were removed using the secCertUtil delete -fcapall command. The operation

type can be either "Created" or "Removed".

AUTH-3004

Message Event: <Event Name>, Status: failed, Info: Neighboring switch has a conflicting

authentication policy; Port <Port Number> disabled.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that the specified E Port was disabled because the neighboring switch rejected the

authentication negotiation, and the local switch has a strict switch authentication policy.

Recommended Correct the switch policy configuration on either of the switches using the **authUtil** command, and then

Action enable the port using the **portEnable** command.

AUTH-3005

Message Event: <Event Name>, Status: failed, Info: Rejecting authentication request on port

<Port Number> because switch policy is turned OFF.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that the local switch has rejected the authentication request, because the switch policy is

turned off. If the neighboring switch has a strict (ON) switch policy, the port will be disabled due to

conflicting configuration settings. Otherwise, the E Port will form without authentication.

Recommended

Action

If the specified port is disabled, correct the switch policy configuration on either of the switches using the **authUtil** command, and then enable the port on the neighboring switch using the **portEnable** command. If the E_Port formed, no action is required.

AUTH-3006

Message Event: <Event Name>, Status: failed, Info: Authentication failed on port <port number>

due to mismatch of DHCHAP shared secrets.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that a Diffie-Hellman Challenge Handshake Authentication Protocol (DHCHAP)

authentication operation failed on the specified port due to mismatched response values between two

entities.

The error may indicate that an invalid entity tried to connect to the switch.

Recommended

Action

Check the connection port for a possible security attack.

Check the shared secrets using the **secAuthSecret** command and reinitialize authentication using the

portDisable and portEnable commands.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

AUTH-3007

Message Event: <Event Name>, Status: failed, Info: Port <port number> disabled due to

receiving an authentication reject with code '<Reason String>' and Explanation

'<Explanation String>'.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that the specified port was disabled because it received an authentication-reject response

from the connected switch or device.

The error may indicate that an invalid entity tried to connect to the switch.

Recommended Action Check the connection port for a possible security attack.

Check the shared secrets using the **secAuthSecret** command and reinitialize authentication using the

portDisable and portEnable commands.

If the message persists, execute the supportFtp command (as needed) to set up automatic FTP

transfers; then execute the supportSave command and contact your switch service provider.

AUTH-3008

Message Event: <Event Name>, Status: failed, Info: Port <port number> has been disabled due

to authentication failure with code '<Reason String>' and explanation '<Explanation

String>'.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that the specified port has been disabled because the connecting switch or device failed to

authenticate.

The error may indicate that an invalid entity tried to connect to the switch.

Recommended Check the connection port for a possible security attack.

Action

Check the shared secrets using the **secAuthSecret** command, and reinitialize authentication using

the portDisable and portEnable commands.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

transfers, their excepts the **supportents** command and co

AUTH-3009

Message Verification failed for certificate: <Certificate name>, error=<OpenSSL error string

for verification error> at depth=<Depth of the error>.

Message Type LOG

Severity ERROR

Probable Cause Indicates an issue with the certificate.

Action command.

If the issue persists, check with the certificate authority to examine the invalid certificate.

6.6 BCM Messages

BCM-1000

Recommended

Message <command name> of GE <port number> failed. Please retry the command. Data: inst=<ASIC

 $\verb|instance| st=<ASIC initializing state| rsn=<reason code| fn=<message function| \\$

Check the time validity and correctness from the import time of the certificate using the seccertmgmt

oid=<ASIC ID>.

Message Type LOG | FFDC

Severity ERROR

Probable Cause Indicates that the hardware is not responding to a command request, possibly because it is busy.

Recommended

Retry the command.

Action

BCM-1001

Message FIPS <FIPS Test Name> failed; algo=<algorithm code> type=<algorithm type> slot=<Slot

Number>.

Message Type LOG | FFDC

Severity CRITICAL

Probable Cause Indicates that a Federal Information Protection Standard (FIPS) failure has occurred and requires

faulting the blade or switch.

Recommended

BCM-1002

ended Retry the command.

Action

Message An IPsec/IKE policy was added.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that an Internet Protocol Security (IPsec) or Internet Key Exchange (IKE) policy was added

and the configuration file was updated.

BCM-1003

Message An IPsec/IKE policy was deleted.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that an Internet Protocol Security (IPsec) or Internet Key Exchange (IKE) policy was deleted

and the configuration file was updated.

BCM-1004

Message Tape Read Pipelining is being disabled slot (<slot number>) port (<user port index>)

tunnel (<The configured tunnel ID (0-7)>).

Message Type LOG

> Severity INFO

Probable Cause Indicates that the Fabric OS version on the remote end of the tunnel does not support Tape Read

Pipelining.

BCM-1005

Message S<slot number>, P<user port index>(<blade index>) [OID 0x<port OID>]: <string name of

ge>: port faulted due to SFP validation failure. Please check if the SFP is valid for

the configuration.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates a deteriorated small form-factor pluggable (SFP) transceiver, an incompatible SFP

transceiver pair, or a faulty cable between the peer ports.

Recommended Verify that compatible SFP transceivers are used on the peer ports (execute the sfpShow command Action

on each side to verify a matched pair), that the SFP transceivers have not deteriorated, and that the

Fibre Channel cable is not faulty. Replace the SFP transceivers or the cable if necessary.

BCM-1006

Message SLOT <slot number> UNIT <unit> [OID 0x<OID>]:<chip error string>.

Message Type LOG

> Severity **ERROR**

Probable Cause

Recommended

Action

6.7 BCMG Messages

BCMG-1000

Message <command name> of GE <port number> failed. Please retry the command. Data: inst=<ASIC</pre>

instance> st=<ASIC initializing state> rsn=<reason code> fn=<message function>

oid=<ASIC ID>.

Message Type LOG | FFDC

Severity ERROR

Probable Cause Indicates that the hardware is not responding to a command request, possibly because it is busy.

Recommended Retry the command.

Action

BCMG-1001

Message FIPS <FIPS Test Name> failed; algo=<algorithm code> type=<algorithm type> slot=<Slot

Number>.

Message Type LOG | FFDC

Severity CRITICAL

Probable Cause Indicates that a Federal Information Protection Standard (FIPS) failure has occurred and requires

faulting the blade or switch.

Recommended

Action

Retry the command.

BCMG-1002

Message An IPsec/IKE policy was added.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that an Internet Protocol Security (IPsec) or Internet Key Exchange (IKE) policy was added

and the configuration file was updated.

BCMG-1003

Message An IPsec/IKE policy was deleted.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that an Internet Protocol Security (IPsec) or Internet Key Exchange (IKE) policy was deleted

and the configuration file was updated.

BCMG-1004

Message Tape Read Pipelining is being disabled slot (<slot number>) port (<user port index>)

tunnel (<The configured tunnel ID (0-7)>).

Message Type LOG

Severity INFO

Probable Cause Indicates that the Fabric OS version on the remote end of the tunnel does not support Tape Read

Pipelining.

BCMG-1005

Message S<slot number>,P<user port index>(<blade index>) [OID 0x<port OID>]: <string name of

ge>: port faulted due to SFP validation failure. Please check if the SFP is valid for

the configuration.

Message Type LOG

Severity ERROR

Probable Cause Indicates a deteriorated small form-factor pluggable (SFP) transceiver, an incompatible SFP

transceiver pair, or a faulty cable between the peer ports.

Recommended Verify that compatible SFP transceivers are used on the peer ports(execute the **sfpShow** command on

each side to verify a matched pair), that the SFP transceivers have not deteriorated, and that the Fibre

Channel cable is not faulty. Replace the SFP transceivers or the cable if necessary.

6.8 BL Messages

Action

BL-1000

Message Initializing ports...

Message Type LOG

Severity INFO

Probable Cause Indicates that the switch has started initializing the ports.

BL-1001

Message Port initialization completed.

Message Type LOG

Severity INFO

Probable Cause Indicates that the switch has completed initializing the ports.

BL-1002

Message Init Failed: slot <slot number> DISABLED because internal ports were not ONLINE, <list

of internal port number not ONLINE>.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the blade initiation failed because one or more of the internal ports were not online. The

blade is faulted.

Recommended Make sure that the blade is seated correctly.

Action

If the blade is seated correctly, execute the **diagPost** command to make sure that power-on self-test (POST) is enabled; then power-cycle the blade using the **slotPowerOff** and **slotPowerOn** commands or have the blade's ejector switch cycled to run POST and verify that the blade does not have any hardware problems.

Additional blade fault massages presede

Additional blade fault messages precede and follow this error, providing more information. Refer to

other error messages for the recommended action.

If the message persists, replace the blade.

BL-1003

Message Faulting blade in slot <slot number>.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates a faulty blade in the specified slot.

Recommended

Make sure that the blade is seated correctly.

Action

If the blade is seated correctly, execute the **diagPost** command to make sure that power-on self-test (POST) is enabled; then power-cycle the blade using the **slotPowerOff** and **slotPowerOn** commands or have the blade's ejector switch cycled to run POST and verify that the blade does not have any

hardware problems.

If the message persists, replace the blade.

BL-1004

Message Suppressing blade fault in slot <slot number>.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the specified blade experienced a failure but was not faulted due to a user setting.

Recommended Action

Execute the diagPost command to make sure that power-on self-test (POST) is enabled; then powercycle the blade using the slotPowerOff and slotPowerOn commands or have the blade's ejector switch cycled to run POST and verify that the blade does not have any hardware problems.

If the message persists, replace the blade.

BL-1006

Message Blade <slot number> NOT faulted. Peer blade <slot number> experienced abrupt failure.

Message Type LOG

> Severity **INFO**

Probable Cause Indicates that the errors (mostly synchronization errors) on the specified blade are harmless. Probably,

the standby control processor (CP) blade that is connected to the active CP blade has experienced

transitory problems.

Recommended Action Execute the haShow command to verify that the standby CP is healthy. If the problem persists,

remove and reinstall the faulty blade.

If the standby CP was removed or faulted by user intervention, no action is required.

BL-1007

Message blade #<blade number>: blade state is inconsistent with EM. bl cflags 0x<blade control

flags>, slot on <slot on flag>, slot off <slot off flag>, faulty <faulty flag>,

status <blade status>.

LOG Message Type

> Severity WARNING

Probable Cause Indicates that a failover occurred while a blade was initializing on the previously active control

processor (CP).

Recommended No action is required. The blade is reinitialized. Because reinitializing a blade is a disruptive operation

Action

and can stop I/O traffic, you may need to stop and restart the traffic during this process.

BL-1008

Message Slot <slot number> control-plane failure. Expected value: 0x<value 1>, Actual:

0x < value 2>.

Message Type FFDC | LOG

> Severity **CRITICAL**

Probable Cause Indicates that the blade has experienced a hardware failure or was removed without following the

recommended removal procedure.

Recommended Action Make sure that the blade is seated correctly.

If the blade is seated correctly, execute the **diagPost** command to make sure that power-on self-test (POST) is enabled; then power-cycle the blade using the **slotPowerOff** and **slotPowerOn** commands or have the blade's ejector switch cycled to run POST and verify that the blade does not have any hardware problems.

If the message persists, replace the blade.

BL-1009

Message Blade in slot <slot number> timed out initializing the chips.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the blade has failed to initialize the application-specific integrated circuit (ASIC) chips.

Recommended Make sure that the blade is seated correctly.

Action

If the blade is seated correctly, execute the **diagPost** command to make sure that power-on self-test (POST) is enabled; then power-cycle the blade using the **slotPowerOff** and **slotPowerOn** commands or have the blade's ejector switch cycled to run POST and verify that the blade does not have any hardware problems.

If the message persists, replace the blade.

BL-1010

Message Blade in slot <slot number> inconsistent with the hardware settings.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that a failover occurred while some hardware changes (such as changing the domain ID)

were being made on the previously active control processor (CP).

Recommended No action is required. This blade has been reinitialized. Because reinitializing a blade is a disruptive

operation and can stop I/O traffic, you may need to stop and restart the traffic during this process.

BL-1011

Message Busy with emb-port int. for chip <chip number> in minis <minis number> on blade <slot

number>, chip int. is disabled. interrupt status=0x<interrupt status>.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause

Indicates that too many interrupts in the embedded port caused the specified chip to be disabled. The probable cause is too many abnormal frames; the chip is disabled to prevent the control processor (CP) from becoming too busy.

Recommended Action

Make sure to capture the console output during this process.

Check for a faulty cable, small form-factor pluggable (SFP) transceiver, or device attached to the specified port.

On a bladed switch, execute the **diagPost** command to make sure that power-on self-test (POST) is enabled; then power-cycle the blade using the **slotPowerOff** and **slotPowerOn** commands or have the blade's ejector switch cycled to run POST and verify that the blade does not have any hardware problems.

On a nonbladed switch, reboot or power cycle the switch.

If the message persists, replace the blade or the (nonbladed) switch.

BL-1012

Message

bport <port number> port int. is disabled. status=0x<interrupt status> Port <port number> will be re-enabled in 1 minute.

Message Type

LOG

Severity

ERROR

Probable Cause

Indicates that the port generated an excessive number of interrupts that may prove unrecoverable to the switch operation. The port is disabled to prevent the control processor (CP) from becoming too busy. The bport is the blade port; this number may not correspond to a user port number.

Recommended Action

Make sure to capture the console output during this process.

Check for a faulty cable, small form-factor pluggable (SFP) transceiver, or device attached to the specified port.

On a bladed switch, run the **slotPowerOff** and **slotPowerOn** commands to power-cycle the blade.

On a nonbladed switch, reboot or power-cycle the switch.

If the message persists, replace the blade or the (nonbladed) switch.

BL-1013

Message

bport <port number> port is faulted. status=0x<interrupt status> Port <port number> will be re-enabled in 1 minute.

Message Type LOG

Severity ERROR

Probable Cause

Indicates that the port generated an excessive number of interrupts that may prove fatal to the switch operation. The port is disabled to prevent the control processor (CP) from becoming too busy. The

bport number displayed in the message is the blade port; this number may not correspond to a user port number.

Recommended Action

Make sure to capture the console output during this process.

Check for a faulty cable, small form-factor pluggable (SFP) transceiver, or device attached to the specified port.

On a bladed switch, run the slotPowerOff and slotPowerOn commands to power-cycle the blade.

On a nonbladed switch, reboot or power-cycle the switch.

If the message persists, replace the blade.

BL-1014

Message bport <port number> port int. is disabled. status=0x<interrupt status>.

Message Type LOG

Severity ERROR

Probable Cause

Indicates that the port generated an excessive number of interrupts that may prove fatal to the switch operation. The port is disabled to prevent the control processor (CP) from becoming too busy. The bport number displayed in the message is the blade port; this number may not correspond to a user port number.

Recommended Action

Make sure to capture the console output during this process.

On a bladed switch, execute the **diagPost** command to make sure that power-on self-test (POST) is enabled; then power-cycle the blade using the **slotPowerOff** and **slotPowerOn** commands or have the blade's ejector switch cycled to run POST and verify that the blade does not have any hardware problems.

On a nonbladed switch, execute the **reboot** command to restart the switch.

If there is a hardware error, if **slotPowerOff** or **slotPowerOn** fails on the bladed switch, or if errors are encountered again, replace the blade or the (nonbladed) switch.

BL-1015

Message bport <port number> port is faulted. status=0x<interrupt status>.

Message Type LOG

Severity ERROR

Probable Cause

Indicates that the port generated an excessive number of interrupts that may prove fatal to the switch operation. The port is disabled to prevent the control processor (CP) from becoming too busy. The bport number displayed in the message is the blade port; this number may not correspond to a user port number.

Recommended Action

Make sure to capture the console output during this process.

On a bladed switch, execute the **diagPost** command to make sure that power-on self-test (POST) is enabled; then power-cycle the blade using the **slotPowerOff** and **slotPowerOn** commands or have the blade's ejector switch cycled to run POST and verify that the blade does not have any hardware problems.

On a nonbladed switch, execute the **reboot** command to restart the switch.

If there is a hardware error, if **slotPowerOff** or if **slotPowerOn** fails on the bladed switch, or errors are encountered again, replace the blade or the (nonbladed) switch.

BL-1016

Message Blade port <port number> in slot <slot number> failed to enable.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the specified blade port could not be enabled.

Recommended Action Make sure that the blade is seated correctly.

If the blade is seated correctly, execute the **diagPost** command to make sure that power-on self-test (POST) is enabled; then power-cycle the blade using the **slotPowerOff** and **slotPowerOn** commands or have the blade's ejector switch cycled to run POST and verify that the blade does not have any hardware problems.

If the message persists, replace the blade.

BL-1017

Message Slot <slot number> Initializing...

Message Type LOG

Severity INFO

Probable Cause Indicates that the slot has started initializing the ports.

BL-1018

Message Slot <slot number> Initialization completed.

Message Type LOG

Severity INFO

Probable Cause Indicates that the slot has completed initializing the ports.

BL-1019

Message Slot <Slot number>, retry <Retry Number>, internal port retry initialization, <List

of internal ports retrying initialization>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the slot had internal ports that are not online. Initiated a retry on the ports that failed to go

online.

BL-1020

Message Switch timed out initializing the chips.

Message Type LOG | FFDC

Severity CRITICAL

Probable Cause Indicates that the switch has failed to initialize the application-specific integrated circuit (ASIC) chips.

Recommended Reboot or power-cycle the switch. If the message persists, replace the switch.

Action

BL-1021

Message Retry <Retry Number>, internal port retry initialization, <List of internal ports

retrying initialization>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the switch had internal ports that are not online. Initiated a retry on the ports that failed to

go online.

BL-1022

Message Init Failed: Switch DISABLED because internal ports were not ONLINE, <list of internal

port number not ONLINE>.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the switch initiation failed because one or more of the internal ports were not online. The

switch is faulted.

Recommended Reboot or power-cycle the switch.

Action
Additional fault messages precede and follow this error, providing more information. Refer to other

error messages for the recommended action.

If the message persists, replace the switch.

BL-1023

Message Blade in slot <slot number> was reset before blade init completed. As a result the

blade is faulted.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the blade was reset before the initialization completed.

Recommended Reboot or power-cycle the blade using the **slotPowerOff** and **slotPowerOn** commands.

Action If the message persists, replace the blade.

BL-1024

Message All ports on the blade in slot <slot number> will be reset as part of the firmware

upgrade.

Message Type LOG

Severity INFO

Probable Cause Indicates that a recent firmware upgrade caused the blade firmware to be upgraded and resulted in a

cold upgrade. As part of the upgrade, all datapath elements were reset.

BL-1025

Message All GigE/FCIP/Virtualization/FC Fastwrite ports on the blade in slot <slot number>

will be reset as part of the firmware upgrade.

Message Type LOG

Severity INFO

Probable Cause Indicates that a recent firmware upgrade caused the blade's firmware to be upgraded and resulted in a

cold upgrade. As part of the upgrade, all the Gigabit Ethernet, Fibre Channel over IP (FCIP),

virtualization data elements, and FC Fastwrite ports were reset.

BL-1026

Message Internal port offline during warm recovery, state <port state> (0x<port ID>).

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that an internal port went offline during warm recovery of the switch. The switch will reboot

and start a cold recovery.

Recommended

Execute the **supportSave** command and then reboot switch. If the problem persists, replace the

switch.

BL-1027

Message Blade in slot <slot number> faulted, boot failed; status 0x<boot status> 0x<1250 0

boot status> 0x<1250 1 boot status>.

Message Type LOG

Action

Severity CRITICAL

Probable Cause Indicates that the blade failed to boot properly.

Recommended Reboot or power-cycle the blade using the **slotPowerOff** and **slotPowerOn** commands.

Action If the message persists, replace the blade.

BL-1028

Message Switch faulted; internal processor was reset before switch init completed.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the switch internal processor was reset before the initialization completed.

Recommended Reboot or power-cycle the switch using the **slotPowerOff** and **slotPowerOn** commands.

Action

If the message persists, replace the switch.

BL-1029

Message All ports on the switch will be reset as part of the firmware upgrade.

Message Type LOG

Severity INFO

Probable Cause Indicates that a recent firmware upgrade caused the switch internal processor firmware to be

upgraded and resulted in a cold upgrade. As part of the upgrade, all the datapath elements were reset.

BL-1030

Message All GigE/FCIP/Virtualization/FC Fastwrite ports on the switch will be reset as part

of the firmware upgrade.

Message Type LOG

Severity INFO

Probable Cause Indicates that a recent firmware upgrade caused the switch internal processor firmware to be

upgraded and resulted in a cold upgrade. As part of the upgrade, all Gigabit Ethernet, Fibre Channel

over IP (FCIP), virtualization data elements, and FC Fastwrite ports were reset.

BL-1031

Message Link timeout in internal port (slot <slot number>, port <port number>) resulted in

blade fault. Use slotpoweroff/slotpoweron to recover the blade.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the link timeout occurred in one of the back-end internal ports.

Recommended Power-cycle the blade using the **slotPowerOff** and **slotPowerOn** commands.

Action

BL-1032

Message (slot <slot number>,bitmap 0x<object control flags(bitmap)>) ports never came up

ONLINE (reason <reason for port disable>, state <status of the blade>). Disabling

slot.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that back-end (nonuser) ports have not come online within the time limit.

Recommended Execute the **diagPost** command to make sure that power-on self-test (POST) is enabled; then power-on self-test (POST) is enabled; the power-on self-test (POST) is enabled; the power-on self-test (POST) is enabled; the power-on s

switch cycled to run POST and verify that the blade does not have any hardware problems.

If the message persists, replace the blade.

BL-1033

Message (slot <slot number>,bitmap 0x<object control flags(bitmap)>) No disable

acknowledgment from ports (state <status of the blade>). Disabling slot.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the system has timed out waiting for the disable messages from the user ports after

disabling the ports.

Recommended

Action

Execute the **diagPost** command to make sure that power-on self-test (POST) is enabled; then power-cycle the blade using the **slotPowerOff** and **slotPowerOn** commands or have the blade's ejector switch cycled to run POST and verify that the blade does not have any hardware problems.

If the message persists, replace the blade.

BL-1034

Message Slot <slot number> FC Initialization completed.

Message Type LOG

Severity INFO

Probable Cause Indicates that the slot has completed initializing the Fibre Channel (FC) ports.

BL-1035

Message Slot <slot number> iSCSI port <iscsi port number> Initialization completed.

Message Type LOG

Severity INFO

Probable Cause Indicates that the slot has completed initializing the specified iSCSI port.

BL-1036

Message Faulting 8G blade in slot = <slot number> due to incompatible stag mode. All EX/VEX

ports must be disabled in order to enable the 8G blade in the chassis.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the 8Gb/s blade with legacy mode (EX_Port having stag) will be disabled.

Recommended Disable all EX Ports and VEX Ports and execute the slotPowerOff or slotPowerOn commands on

Action the 8Gb/s blade. All EX Ports and VEX Ports can be re-enabled.

BL-1037

Message Faulting chip in slot = <slot number>, miniS = <miniS number>,port = <port number>

due to BE/BI port fault.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that all ports on the chip have been disabled due to a fault on the chip.

Recommended Action Make sure that the blade is seated correctly.

If the blade is seated correctly, execute the **diagPost** command to make sure that power-on self-test (POST) is enabled; then power-cycle the blade using the **slotPowerOff** and **slotPowerOn** commands or have the blade's ejector switch cycled to run POST and verify that the blade does not have any hardware problems.

Additional blade fault messages precede and follow this error, providing more information. Refer to other error messages for the recommended action.

If the message persists, replace the blade.

BL-1038

Message Inconsistent FPGA image version detected, please reboot the switch for recovery.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the field-programmable gate array (FPGA) image version is incompatible with the

software version.

Recommended Reboot the switch. If the message persists, replace the switch.

Action

BL-1039

Message Inconsistent FPGA image version detected, faulting the blade in slot <slot number>.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the field-programmable gate array (FPGA) image version is incompatible with the

software version.

Recommended Power-cycle the blade using the **slotPowerOff** and **slotPowerOn** commands.

Action

If the message persists, replace the blade.

BL-1040

Message Inconsistent FPGA image version detected for blade in slot <slot number>. Current

FPGA ver=0x<current FPGA version major> <current FPGA version minor> Upgrade to FPGA

ver=0x<new FPGA version major>_>_<new FPGA version minor>

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the field-programmable gate array (FPGA) image version is incompatible with the

software version.

Recommended

Power-cycle the blade using the **slotPowerOff** and **slotPowerOn** commands.

Action

If the message persists, replace the blade.

BL-1041

Message Dynamic area mode is enabled on default switch, Faulting the blade w/ ID <Blade ID

of blade that has the mini SFP+ that does not support it> in slot <slot number> as

it does not support this mode.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the blade does not support dynamic area mode on the default switch.

Recommended Turn off the dynamic area mode using the **configure** command.

Action

BL-1045

Message mini SFP+ (SN: <mini SFP+ serial number>) is only supported in certain high port count

blades, not blade in slot <slot number of blade that has the mini SFP+> $\rm w/\ ID\ <Blade$

ID of blade that has the mini SFP+ that does not support it>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that mini-SFP+ is supported only by a certain type of blade (FC8-64), but it can be inserted in

other blades

Recommended

Action

Replace the mini-SFP+ with an SFP or SFP+.

BL-1046

Message <Slot number of blade that has the SFP> error on SFP in Slot <Port number into which

the SFP is inserted>/Port <The type of error "checksum" or "data access" for general problems accessing the i2c accessible data> (<A detailed error code>). Try reseating

or replacing it.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the checksum in an area on the small form-factor pluggable (SFP) transceiver does not

match with the computed value, or there is problem accessing the data.

Recommended Action Reseat the SFP transceiver. If the problem persists, replace the SFP transceiver.

BL-1047

Message Buffer optimized mode is turned <buffer optimized mode> for slot <slot number>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the buffer optimized mode is changed for the specified slot.

BL-1048

Message FCOE Blade in slot <Slot> failed because the Interop mode is enabled on the switch.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the interop mode is turned on in the default switch while powering on the FCoE blade.

Recommended Disable the interop mode using the **interopmode** command; then execute the **slotPowerOff** and **slotPowerOn** commands on the FCoE blade.

BL-1049

Message Serdestunemode: <serdestuning mode>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the SerDes tuning mode has changed for the slot.

BL-1050

Message Incompatible Blade Processor FPGA version with current FOS firmware in slot=<slot

number> on FX8-24. Contact support for upgrade instructions.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the blade processor field-programmable gate array (FPGA) version with current Fabric

OS firmware is incompatible on the FX8-24 blade.

Recommended Contact your switch service provider for upgrade instructions.

Action

BL-1052

Message Link Reset threshold exceeded in the internal port (slot <slot number>, port <port

number>). No core blade has been faulted because it has only one active core blade.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the internal port in the core blade exceeded the link reset threshold level. Faulting the

peer edge blade because there is only one active core blade.

Recommended Replace the core blade.

Action

BL-1053

Message Invalid E_Port credits <credits> configured for slot <slot number>, port <port

number>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that invalid E Port credits are configured. The old credit model will be retained.

Recommended Disable the E_Port credits using the **portcfgeportcredits --disable** command.

Action

BL-1054

Message QSFP (SN: <QSFP serial number>) is not supported on blade in slot <slot number of

blade that has the QSFP> with ID <Blade ID of blade that has the QSFP that does not

support it>. Check for compatibility of QSFP with this core or port blade.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the current quad small form-factor pluggable (QSFP) is not supported by this particular

type of blade (core or port), but it can be inserted in other blades. Core blades and port blades have

their own supported versions of QSFPs.

Recommended Replace the QSFP with one that is compatible with the blade.

Action

BL-1055

Message The octet mode of user port (<Port Number>) in slot:<Slot Number of blade that has

the QSFP>, blade ID <Blade ID of blade that has the QSFP that does not support it>

is not supported.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the quad small form-factor pluggable (QSFP) supports only octet combo 1. If the port is

configured in the other two modes (2 and 3), there is a mismatch in capabilities.

Recommended

Action

Set the correct octet combo by using the portCfgOctetSpeedCombo command.

BL-1056

Message Tunable SFP user port (<Port Number>) in slot:<Slot Number of blade that has the

TSFP>, blade ID <Blade ID of blade that has the TSFP that does not support it> detected with not a valid channel <Channel Number> configured. Configure valid channel range

1-102.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the user port is not configured with a valid tunable small form-factor pluggable (TSFP)

channel ID. The valid range is 1 through 102.

Recommended Set the

Action

Set the correct channel by using the portcfgge command.

BL-1057

Message FIPS failure detected, blade

blade instance> will be faulted.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that Federal Information Protection Standard (FIPS) failure is detected in one or more chips

on the switch.

Recommended Reboot or power-cycle the switch.

Action

BL-1058

Message Chip <chip instance> Restarted on BP slot <blade instance>

Message Type LOG

Severity INFO

Probable Cause Indicates that the data processor (DP) has detected a PCI Express (PCIE) error.

BL-1061

Message port speed(<port speed>G) and sfp speed(<sfp speed>G) mismatch in port(ge<port

number>) slot number(<slot number>). Insert sfp matching port speed.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the port speed and the SFP speed do not match.

Recommended Insert an SFP that matches the port speed.

Action

BL-1062

Message Unsupported sfp present in port(ge<ge port number>) in slot(<slot number>).

Message Type LOG

Severity ERROR

Probable Cause Indicates that an unsupported SFP is present.

Recommended Insert a supported SFP.

Action

BL-1063

Message Port <User port number> has 16G QSFP and AN speed configuration is not supported.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the port number is configured for AN and installed with a 16G quad small form-factor

pluggable (QSFP) in a X6 chassis.

Recommended Change the port configuration to fixed 16G.

Action

BL-1064

Message Chip (<Chip number>) on slot (<slot number>) going for reset to recover FPGA.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the FPGA reported errors that require a reboot to recover.

BL-1065

Message Internal port offline during warm recovery, state <port state> bl cflags 0x<blade

control flags> (0x<port ID>).

Message Type LOG

Severity INFO

Probable Cause Indicates that an internal port went offline before HA failover.

Recommended Execute slotpoweroff-on to recover.

Action

BL-1080

Message User port (<Port Number>) in slot:<Slot Number of blade that has the non qualified

optic> (blade ID <Blade ID of blade that has the invalid SFP/QSFP module>) faulted

due to detection of non qualified optic.

Message Type LOG

Severity ERROR

Probable Cause Indicates that a nonqualified optic was detected and shut off to prevent unexpected behavior.

Recommended Replace with an officially supported optic.

Action

BL-1081

Message Current sysfpga version is (0x<current sysfpga version>).Please upgrade to latest

sysfpga version(0x<latest sysfpga version>).

Message Type LOG | FFDC

Severity ERROR

Probable Cause Indicates that the current sysfpga version is not the latest.

Recommended Upgrade to the latest sysfpga version.

Action

BL-1082

Message media <partno> port <port> has temperature <temperature> above the limit.

Message Type LOG

Severity ERROR

Probable Cause The optic temperature is above the limit.

Recommended Check the optic and the fans.

Action

BL-1083

Message Slot <Slot> Blade ID 0x<Blade ID> Ver 0x<printf> has port SerDes data available in FRU

SEEPROM.

Message Type LOG

Severity INFO

Probable Cause Indicates that new SerDes data is available for some of the ports in the slot.

BL-1084

Message Optical Module reset detected on slot <Slot> port <Port number> MCU version 0x<Current

MCU version>(0x<Saved MCU version>) reset-count <Current reset counter>(<Saved reset

counter>) reset-reason <Current reset reason>(<Saved reset reason>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Optical Module on this port has undergone a reset and FOS software will initiate a

recovery.

BL-1085

Message Optical Module reset recovery <Slot> on slot <Port number> port <action taken on the

port>.

Message Type LOG

Severity WARNING

Probable Cause Indicates the Optical Module recovery status. Frames in transit will be dropped during recovery.

6.9 BLS Messages

BLS-1000

Message <command name> of GE <port number> failed. Please retry the command. Data: inst=<ASIC

instance> st=<ASIC initializing state> rsn=<reason code> fn=<message function>

oid=<ASIC ID>.

Message Type LOG | FFDC

Severity ERROR

Probable Cause Indicates that the hardware is not responding to a command request, possibly because it is busy.

Recommended Retry the command.

Action

BLS-1001

Message FIPS <FIPS Test Name> failed; algo=<algorithm code> type=<algorithm type> slot=<Slot

Number>.

Message Type LOG | FFDC

Severity CRITICAL

Probable Cause Indicates that a Federal Information Protection Standard (FIPS) failure has occurred and requires

faulting the blade or switch.

Recommended

Action

Retry the command.

BLS-1002

Message An IPsec/IKE policy was added.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that an Internet Protocol Security (IPsec) or Internet Key Exchange (IKE) policy was added

and the configuration file was updated.

BLS-1003

Message An IPsec/IKE policy was deleted.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that an Internet Protocol Security (IPsec) or Internet Key Exchange (IKE) policy was deleted

and the configuration file was updated.

BLS-1004

Message Tape Read Pipelining is being disabled slot (<slot number>) port (<user port index>)

tunnel (<The configured tunnel ID (0-7)>).

Message Type LOG

Severity INFO

Probable Cause Indicates that the Fabric OS version on the remote end of the tunnel does not support Tape Read

Pipelining.

BLS-1005

Message S<slot number>, P<user port index>(<blade index>) [OID 0x<port OID>]: <string name of

ge>: port faulted due to SFP validation failure. Please check if the SFP is valid for

the configuration.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates a deteriorated small form-factor pluggable (SFP) transceiver, an incompatible SFP

transceiver pair, or a faulty cable between the peer ports.

Recommended Verify that compatible SFP transceivers are used on the peer ports, that the transceivers have not

deteriorated, and the that Fibre Channel cable is not faulty. Replace the SFP transceivers or the cable

if necessary.

6.10 BLZ Messages

BLZ-1000

Message <command name> of GE <port number> failed. Please retry the command. Data: inst=<ASIC

 $\verb|instance|| st = < ASIC initializing state|| rsn = < reason code|| fn = < message function|| state|| rsn = < reason code|| fn = < message function|| state|| rsn = < reason code|| fn = < message function|| state|| state|$

oid=<ASIC ID>.

Message Type LOG | FFDC

Severity ERROR

Probable Cause Indicates that the hardware is not responding to a command request, possibly because it is busy.

Recommended Retry the command.

Action

BLZ-1001

Message FIPS <FIPS Test Name> failed; algo=<algorithm code> type=<algorithm type> slot=<Slot

Number>.

Message Type LOG | FFDC

Severity CRITICAL

Probable Cause Indicates that a Federal Information Protection Standard (FIPS) failure has occurred and requires

faulting the blade or switch.

Recommended I

Action

Retry the command.

BLZ-1002

Message An IPsec/IKE policy was added.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that an Internet Protocol Security (IPsec) or Internet Key Exchange (IKE) policy was added

and the configuration file was updated.

BLZ-1003

Message An IPsec/IKE policy was deleted.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that an Internet Protocol Security (IPsec) or Internet Key Exchange (IKE) policy was deleted

and the configuration file was updated.

BLZ-1004

Message Tape Read Pipelining is being disabled slot (<slot number>) port (<user port index>)

tunnel (<The configured tunnel ID (0-7)>).

Message Type LOG

Severity INFO

Probable Cause Indicates that the Fabric OS version on the remote end of the tunnel does not support Tape Read

Pipelining.

BLZ-1005

Message Datapath Slot: <slot number> Chip: <Chip number> reset during HAreboot.

LOG Message Type

> Severity **ERROR**

Probable Cause Indicates that a datapath chip reset happened during a high availability (HA) reboot. Traffic may be

disrupted.

Recommended

Reboot to recover.

Action

BLZ-1006

Message Slot <Slot number>, Port <Port number>(<blade index>), DP <DP id>: Multi Frame Loss

detected on internal port. VC no: <vc number>.

Message Type LOG

> WARNING Severity

Probable Cause Indicates that frames/credits were lost on an internal port and the link must be reset to recovery.

Recommended Turn on back-end credit recovery to reset the link and recover the lost credits. If credit recovery has Action

already been turned on, the link will be reset to recover the credits and no action is required.

BLZ-1007

Message Slot <Slot number>, Port <Port number>(<blade index>), DP <DP id>: Multi Ready Loss

detected on internal port. VC no: <vc number>, credits lost: <Credits lost>.

LOG Message Type

Action

Severity WARNING

Probable Cause Indicates that frames/credits were lost on an internal port and the link must be reset to recovery.

Recommended Turn on the back-end credit recovery to reset the link and recover the lost credits. If credit recovery has

already been turned on, the link will be reset to recover the credits and no action is required.

BLZ-1008

Message Datapath Slot <slot number> Chip <Chip number>: fault received due to link level CRC

errors on internal port.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates that CRC errors were received on an internal port of the datapath chip.

Recommended

Action Contact your equipment vendor's support.

6.11 BM Messages

BM-1001

Message BM protocol version <Protocol version> in slot <Slot number>.

Message Type LOG

Severity ERROR

Probable Cause

Indicates that the firmware running on the control processor (CP) cannot communicate with the application processor (AP) blade in the indicated slot and determine the AP blade's firmware version. The reason can be one of the following:

- The CP blade is running a later version of firmware than the AP blade.
- The CP blade is running an earlier version of firmware than the AP blade.

Recommended Action

The problem can be corrected by changing the firmware version on either the CP or on the AP blade. You can modify the firmware version on the CP blade by using the **firmwareDownload** command. Refer to the release notes to determine whether a nondisruptive firmware download is supported between the revisions. Because the AP and CP blades cannot communicate, it is not possible to load new firmware on the AP blade. If necessary, send the AP blade back to the factory for a firmware update.

BM-1002

Message Connection established between CP and blade in slot <Slot number>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the control processor (CP) has established a connection to the blade processor (BP)

and can communicate.

BM-1003

Message Failed to establish connection between CP and blade in slot <Slot number>. Faulting

blade.

Message Type LOG | FFDC

Severity WARNING

Probable Cause Indicates that the control processor (CP) could not establish a connection to the blade processor (BP)

to communicate.

Recommended

Action

Execute the slotPowerOff and slotPowerOn commands or reseat the affected blade.

BM-1004

Message Blade firmware <Blade firmware> on slot <Slot> is not consistent with system firmware

<System firmware>. Auto-leveling blade firmware to match system firmware.

Message Type LOG

Severity INFO

Probable Cause Indicates that the policy of the specified blade is to auto-level the blade firmware to the system firmware. This may be due to one of the following reasons:

■ The blade firmware was detected to be different from the control processor (CP) firmware due to a firmware upgrade.

■ The blade was recently inserted and had a different version of the firmware loaded.

Recommended Action

No action is required. The blade will automatically download the updated firmware.

BM-1005

Message Firmwaredownload timed-out for blade in slot <Slot>. Faulting blade.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the **firmwareDownload** command failed for the blade in the specified slot.

Recommended Execute the **slotPowerOff** and **slotPowerOn** commands or reseat the affected blade.

Action

BM-1006

Message Blade is not configured. Persistently disabling all ports for blade in slot <Slot

number>.

Message Type LOG

Severity INFO

Probable Cause

Indicates that the policy of the specified blade is set to persistently disable all ports the first time that the blade is detected. The message indicates either of the following:

- The blade was detected in this slot for the first time.
- The blade was configured under a different mode.

Recommended

Configure the blade so that it will persistently enable the ports.

BM-1007

Message If set, clear EX/VEX/FC Fastwrite configuration for all ports for blade in slot <Slot

number>.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the specified blade was detected for the first time after an FR4-18i was previously

configured in the same slot. The new blade requires the specified port configurations to be cleared.

Recommended

Action

No action is required. The blade ports are cleared automatically.

BM-1008

Message Download of blade firmware failed for blade in slot <slot>. Reissue firmwaredownload

to recover.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the automatic firmware upgrade on the blade failed because the blade firmware version

was detected to be different from the control processor (CP) firmware version.

Recommended

Action

Execute the **firmwareDownload** command to recover the blade.

BM-1009

Message Firmwaredownload timed-out for application processor. Faulting switch.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the firmware download on the application processor (AP) blade failed.

Recommended Execute the **slotPowerOff** and **slotPowerOn** commands or reseat the affected blade.

Action

BM-1010

Message Resetting port configuration and linkcost for all ports for blade in slot <Slot

number>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified blade was detected for the first time after an FC10-6 was previously

configured in the same slot. The new blade requires resetting the port configuration and link cost.

Recommended

Action

No action is required. The blade ports are cleared automatically.

BM-1053

Message Failed to establish connection between CP and Application Processor. Faulting switch.

Message Type LOG | FFDC

Severity WARNING

Probable Cause Indicates that the control processor (CP) could not establish a connection with the application

processor (AP) to communicate.

Recommended Execute the **slotPowerOff** and **slotPowerOn** commands or reseat the affected blade.

Action

BM-1054

Message AP firmware <Blade firmware> is not consistent with system firmware <System firmware>.

Auto-leveling AP firmware to match system firmware.

Message Type LOG

Severity INFO

Probable Cause

Indicates that the policy of the specified blade is set to auto-level the blade firmware to the system firmware. This may be due to one of the following reasons:

- The blade firmware was detected to be different from the control processor (CP) firmware due to a firmware upgrade.
- The blade was recently inserted and had a different version of the firmware loaded.

Recommended Action

No action is required. The blade will automatically download the updated firmware.

BM-1055

Message Firmwaredownload timed-out for AP. Faulting switch.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the firmware download on the application processor (AP) blade has failed.

Recommended Execute the **slotPowerOff** and **slotPowerOn** commands or reseat the affected blade.

Action

BM-1056

Message AP is not configured. Persistently disabling all ports on the switch.

Message Type LOG

Severity INFO

Probable Cause

Indicates that the policy of the specified switch is to persistently disable all ports the first time the AP is detected. This may be caused by one of the following reasons:

- The AP was detected for the first time on this switch.
- The switch was configured under a different mode.

Recommended Action Configure the switch to persistently enable all ports.

BM-1058

Message

Download of AP firmware failed for the switch. Reissue firmwaredownload to recover.

Message Type

LOG

Severity

WARNING

Probable Cause

Indicates that the automatic firmware upgrade on the application processor (AP) failed because the firmware version running on the AP was detected to be different from the system firmware.

Recommended

Execute the firmwareDownload command to recover the AP.

Action

6.12 C4 Messages

C4-1001

S<slot number>, P<port number>(Bp<blade port number>) user_idx:<User port index> [PID Message

0x<24 bit FC address>] faulted due to invalid SFP, conflicting speed or laser fault.

<error message>

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates a deteriorated small form-factor pluggable (SFP) transceiver, an incompatible SFP

transceiver pair, or a faulty cable between the peer ports.

Recommended Verify that compatible SFP transceivers are used on the peer ports, that the SFP transceivers have not Action

deteriorated, and that the Fibre Channel cable is not faulty. Replace the SFP transceivers or the cable

if necessary.

C4-1002

Message Port <port number> chip failed due to an internal error.

LOG | FFDC Message Type

> Severity **ERROR**

Probable Cause Indicates an internal error. All ports on the blade or switch will be disrupted.

Recommended To recover a bladed system, execute the slotPowerOff and slotPowerOn commands on the blade. To

Action recover a nonbladed system, execute the fastBoot command on the switch.

C4-1004

Message S<slot number>, C<chip index>: Invalid DMA ch pointer, chan:<Channel number>,

good addr:0x<Good address> bad addr:0x<Bad address>.

Message Type LOG

Severity ERROR

Probable Cause Indicates an internal error in the application-specific integrated circuit (ASIC) hardware that may

degrade the data traffic.

Recommended Reboot the system at the next maintenance window. If the problem persists, replace the blade.

Action

C4-1006

Message S<slot number>, C<chip index>: Various non-critical hardware errors were observed:

fault1:0x<fault1_cnt>, fault2:0x<fault2_cnt> thresh1:0x<threshold_used>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that some errors were found in the hardware that may or may not impact the data traffic.

Recommended No action is required. Usually these errors are transient.

Action

C4-1007

Message S<slot number>, P<port number>(<blade port number>): best effort QoS will be turned

off at next port state change as it is not supported under this configuration.

Message Type LOG

Severity WARNING

Probable Cause Indicates that Quality of Service (QoS) will be turned off automatically at the next port state change

because best effort QoS is no longer supported on 4Gb/s or 8Gb/s platform long-distance ports.

C4-1008

Message S<slot number>, P<port number> (<blade port number>): QoS overwrites

portcfglongdistance vc_translation_link_init. ARB will be used on the link.

Message Type LOG

Severity WARNING

Probable Cause Indicates that Quality of Service (QoS) has overwritten the fill word IDLE used on the long- distance

links. Arbitrated loop (ARB) will be used on the link.

C4-1009

Message S<slot number>, P<port number>(<blade port number>): portcfglongdistance

vc translation link init = 1 overwrites fill word IDLE. ARB will be used on the link.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the portcfglongdistance vc_translation_link_init 1 command has overwritten the fill

word IDLE. Arbitrated loop (ARB) will be used on the link.

C4-1010

Message S<slot number>, C<chip index>: Above normal hardware errors were observed:

fault1:0x<fault1 cnt>, fault2:0x<fault2 cnt> thresh2:0x<threshold used>.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that above-normal errors were observed in the hardware that may or may not impact the data

traffic.

Recommended When this error is observed persistently, power-cycle the specified blade using the **slotPowerOff** and

slotPowerOn commands. If the problem persists, replace the blade.

C4-1011

Message Detected a complete loss of credit on internal back-end VC: Slot <slot number>, Port

<port number>(<blade port number>) vc no=<vc number> crd(s)lost=<Credit(s) lost>.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that all credits have been lost on the specified virtual channel (VC) and port.

Recommended Turn on the back-end credit recovery to reset the link and recover the lost credits. If credit recovery has

Action already been turned on, the link will be reset to recover the credits and no action is required.

C4-1012

Message S<slot number>, P<port number>(<blade port number>): Link Timeout on internal port

ftx=<frame transmitted> tov=<real timeout value> (><expected timeout value>)
vc no=<vc number> crd(s)lost=<Credit(s) lost> complete loss:<Complete credit loss>.

ve_no-vve number/ crd(s) lost-vereart(s) lost/ complete_loss:\complete creart loss/.

Message Type LOG

Severity WARNING

Probable Cause Indicates that one or more credits have been lost on a back-end port, and that there has been no traffic

on that port for two seconds.

Recommended

Action

Turn on the back-end credit recovery to reset the link and recover the lost credits. If credit recovery has already been turned on, the link will be reset to recover the credits and no action is required.

C4-1013

Message Multi RDY/Frame Loss detected on internal port of Slot <slot number>, Port <port

number>(<blade port number>) m rdy(0x<Multiple Credit(s) Lost>)/m_frame(0x<Multiple</pre>

Frame(s) Lost>).

Message Type LOG

> Severity WARNING

Probable Cause Indicates that wait cycles to recover the lost frame or credit have been exceeded on the specified port.

Recommended Turn on back-end credit recovery to reset the link and recover the lost credits. If credit recovery has Action

already been turned on, the link will be reset to recover the credits and no action is required.

C4-1014

Message Link Reset on Port S<slot number>, P<port number>(<blade port number>) vc no=<vc

number> crd(s)lost=<Credit(s) lost> <Source of link reset > trigger.

Message Type LOG

> Severity WARNING

Probable Cause Indicates that one or more credits were lost and that the link has been reset.

When this error is observed persistently on a back-end link, power-cycle the specified blade using the Recommended Action slotPowerOff and slotPowerOn commands. If the problem persists, replace the blade. When this

error is observed persistently on a user port, check the physical layer errors on this port and peer port using portStatsShow command. If there are some physical layer errors, change the small form-factor

pluggable (SFP) transceiver or the cable on the port and peer port to which this port is connected.

C4-1015

Message Port re-initialized due to Link Reset failure on internal Port S<slot number>, P<port

number > (<blade port number>).

Message Type LOG

> WARNING Severity

Probable Cause Indicates that the specified port has re-initialized due to a link reset failure.

Recommended Action When this error is observed persistently, power-cycle the specified blade using the slotPowerOff and slotPowerOn commands. If the problem persists, replace the blade.

C4-1016

Message Port is faulted due to a port re-initialization failure on internal Port S<slot

number>, P<port number>(<blade port number>) with reason <port fault reason>.

Message Type LOG

> **ERROR** Severity

Probable Cause Indicates that the specified port failed due to port re-initialization failure.

Recommended When this error is observed persistently, power-cycle the specified blade using the slotPowerOff and

Action slotPowerOn commands. If the problem persists, replace the blade.

C4-1017

Message Blade in Slot-<slot number> failed due to unavailability of ports in the internal

trunk.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates that the specified blade failed because of the unavailability of the ports in the internal trunk.

Recommended When this error is observed persistently, power-cycle the specified blade using the slotPowerOff and Action

slotPowerOn commands. If the problem persists, replace the blade.

C4-1018

Message Link reset threshold value exceeded in the link S<slot number>,P<port number>(<blade

port number>).

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates that the specified blade has faulted because the link reset threshold value was exceeded.

Recommended When this error is observed persistently, power-cycle the specified blade using the slotPowerOff and Action

slotPowerOn commands. If the problem persists, replace the blade.

C4-1019

Message S<slot number>, C<chip index>: HW ASIC Chip TXQ FID parity error threshold reached

type = 0x < chip error type > .

Message Type LOG

Severity WARNING

Probable Cause Indicates that an internal error has been observed in the application-specific integrated circuit (ASIC)

hardware that may degrade the data traffic.

Recommended

Action

Restart the system at the next maintenance window.

C4-1020

Message S<slot number>, P<port number> (<blade port number>): Internal CRC with good EOF errors

were observed, continuing monitoring. current:0x<last crc good eof cnt>,

last:0x<total crc good eof cnt> thresh1:0x<threshold used>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that some CRC errors were detected on a back-end link by the hardware. Typically

applications are not affected at this low count.

C4-1023

Message Single RDY/Frame Loss detected and recovered on Slot <slot number>, Port <port

number>(<blade port number>) rdy(0x<Credit Lost>)/frame(0x<Frame Lost>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that above-normal errors have been observed in the hardware that may or may not impact

the data traffic.

Recommended When this error is observed persistently, power-cycle the specified blade using the slotPowerOff and

Action **slotPowerOn** commands. If the problem persists, replace the blade.

C4-1028

Message Detected excessive Link resets on the port in a second. Slot <slot number>, Port <port

number>(<blade port number>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the port received excessive link resets from the peer port within 1 second and that

exceeded the threshold.

Recommended Action When this error is observed persistently, change the small form-factor pluggable (SFP) transceiver or the cable on the peer port to which this port is connected.

C4-1030

Message

S<slot number>, P<port number>(<blade port number>): Internal CRC with good EOF errors exceeded threshold, tuning is required. current:0x<last crc good eof cnt>, last:0x<total crc good eof cnt> thresh2:0x<threshold used>.

LOG Message Type

> Severity WARNING

Probable Cause Indicates that some CRC errors were detected on a back-end link by the hardware; applications may

Recommended If a core blade reset or auto tuning or manual tuning does not resolve the issue, replace the blade.

Action

C4-1031

Message LOSYNC timeout occurred on Slot <slot number>, Port <port number>(<blade port

number>).

Message Type LOG

> INFO Severity

Probable Cause Indicates that loss of synchronization has occurred on the BE port and that a link reset was invoked on

this port by the blade driver.

C4-1032

Message S<slot number>, P<port number> (<blade port number>): Required buffer unavailable for

the port. req buf:<required buffer> port buf:<port buffer> unused buf:<Unused buffer>

est buf: <Estimated buffer>.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that free buffers in the chip are not sufficient to bring the port online in fully operational mode.

The port may not come online or may operate in a degraded buffer mode.

Recommended If one or more ports that are configured as long distance in the chip are unused, reset these ports to

normal distance. If the problem persists, move the affected port to a different blade or chip.

C4-1033

Message S<slot number>, P<port number>(<blade port number>): FEC TTS is only supported on

F_Port.

Message Type LOG

Severity WARNING

Probable Cause Indicates that Forward Error Correction (FEC) TTS is enabled on the specified port. The FEC TTS

option is supported only on F_Ports.

Recommended Disable the FEC TTS option using the **portcfgfec --disable -TTS** command.

Action

C4-1034

Message S<slot number>, P<port number>(<blade port number>): FEC is Enabled but FEC is

Inactive. Check peer port's FEC configurations.

Message Type LOG

Severity INFO

Probable Cause Indicates that Forward Error Correction (FEC) is enabled but is inactive on the specified port.

Recommended Check the local and peer port's FEC configurations using the **portcfgfec --show** command.

Action

C4-1035

Message Credit Recovery disabled on Slot <slot number>, Port <port number>(<blade port

number>) because of HW error.

Message Type LOG

Severity WARNING

Probable Cause Indicates that credit recovery logic has failed.

Recommended Disable and enable the port, and if the error persists, disable credit recovery for the port.

Action

C4-1036

Message Buffer sharing unfairness issue on Slot <slot number>, Port <port number>(<blade port

number>).

Message Type LOG

Severity WARNING

Probable Cause
Indicates buffer sharing unfairness and port starvation.

C4-1037

Message S<slot number>, C<chip index>: IOS Error, block 1st = 0x<Top level first error value>,

intr_cause = 0x<IOS error intr cause>, ios_int_en_set = 0x<IOS intr status> single

bit error <Single bit error count>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the hardware parity error has been detected in the Condor 4 Inter-network Operating

System (IOS) block.

Recommended IOS counters may have been corrupted; ignore IOS flow counters in the last polling cycle.

Action

C4-1038

Message Slow drain device quarantine (SDDQ) or Restore action is not completed for the sid

0x<Source ID>, did 0x<Destination ID>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the Frame Transformation Block (FTB) entry has not been added.

C4-1039

Message S<slot number>, C<chip index>: Temperature is <current temperature>, maximum threshold

is <Maximum operating temperature>. If it exceeds threshold, the unit will be

shutdown.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the operating environment conditions are causing the application-specific integrated

circuit (ASIC) to overheat.

Recommended

Action

Make sure that the area is well ventilated and that the room temperature is within the operational range

of your switch. Refer to the hardware reference manual for your switch for the operational temperature

range.

C4-1040

Message Multi RDY/Frame Loss detected on Slot <slot number>, Port <port number>(<blade port

number>) m_rdy(0x<Multiple Credit(s) Lost>)/m_frame(0x<Multiple Frame(s) Lost>).

Link Reset done.

Message Type LOG

Severity WARNING

Probable Cause Indicates that multiple credits and frames were lost on the specified port, and that the link has reset.

C4-1041

Message Encryption block error event detected on Slot <slot number>, Port <port number>(<blade

port number>), err count:<error counter>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that encryption block errors have been detected.

Recommended Disable and enable the port, and if the problem persists, replace the blade.

Action

C4-1042

Message Port in Slot <slot number>, Port <port number>(<blade port number>) getting faulted

because of encryption block error.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the port has faulted because of encryption block errors.

Recommended Disable and enable the port, and if the problem persists, replace the blade.

Action

C4-1043

Message Encryption enabled Port S<slot number>, P<port number> (<blade port number>) faulted

due to link initialization failure.

Message Type LOG

Severity WARNING

Probable Cause Indicates that an encryption-configured port failed because of a link initialization failure.

Recommended Disable and enable the port, and if the problem persists, replace the blade.

Action

C4-1044

Message Trunk performance impact on port (<port number>) due to high deskew value.

[TRUNK PERF:<perf> percent, Deskew:<deskew>]

Message Type LOG

INFO Severity

Probable Cause Indicates a high deskew value on the port.

Recommended Check for physical cable length differences among physical ports of the trunk. If there are cable length

differences then fix them with the same cable length link. Otherwise replace the cable if the problem

persists.

C4-1045

Message Single parity error detected in ftb statistics memory, slot <slot> index <index>

LOG Message Type

Action

Severity INFO

Probable Cause A parity error was detected in FTB statistics memory; a Flow Vision flow monitor may show incorrect

statistics.

Recommended Reset the Flow Vision flow monitor flow that is showing abnormal statistics.

Action

C4-1046

Message Multiple parity errors detected in ftb statistics memory, slot <slot> indexes <index>

<index> <index> <index>

LOG Message Type

> Severity INFO

Probable Cause A parity error was detected in FTB statistics memory; a Flow Vision flow monitor may show incorrect

statistics.

Recommended Reset the Flow Vision flow monitor flow that is showing abnormal statistics.

Action

C4-1047

Message Slot <slot number>, Port <port number> (<blade port number>) is getting faulted because

another Encryption and Trunking configured <port type getting faulted>-port (<Already

present Encryption and Trunking configured port>) is already present.

LOG Message Type

> **WARNING** Severity

Probable Cause Indicates that the port has faulted because another type of encryption- and trunking- configured port is

already present in the chip.

FOS-90x-Message-RM103 Broadcom

Recommended Action Disable the other type of encryption- and trunking- configured port, and enable the port that is getting the hard fault.

C4-1048

Message

S<Slot number>,C<Chip Index>: Maximum possible buffers (<Maximum possible buffers>) exceeded; total desired:<Total Number of buffers desired>; port <Port with high desired count> has high desired count:<Desired buffer count on the one port>

Message Type

LOG | FFDC

Severity

ERROR

Probable Cause

More buffers have been requested/desired than exist on the ASIC. This will cause traffic disruption in the fabric

Recommended

Action

If the port is a frontend port, toggle the identified port using portdisable, portenable, portcfgpersistentdisable, or portcfgpersistentenable. If that doesn't work, or if the port is a backend port, use slotpoweroff and slotpoweron on the identified blade. If this message appears again for the

same blade, replace the blade.

C4-1049

Message

S<Slot number>,P<User port index>(<Blade port number>): Port faulted at <String to identify location>. Requested <Desired buffer count on the one port> buffers; ASIC buffers: current=<Total Number of buffers desired on ASIC> max=<Maximum possible buffers>

Message Type

LOG | FFDC

Severity

ERROR

Probable Cause

More buffers have been requested/desired than exist on the ASIC. This will cause traffic disruption in the fabric.

Recommended

Action

First, collect a supportsave and contact the switch vendor for analysis. If the number of requested buffers by the port is unexpectedly large, and if the port is a frontend port, toggle the identified port using portdisable, portenable, portcfgpersistentdisable, or portcfgpersistentenable. If that doesn't work, or if the port is a backend port, use slotpoweroff and slotpoweron on the identified blade. If the number of requested buffers makes sense and the current total ASIC buffers is very close to the ASIC maximum, contact the switch vendor to analyze switch data for possible ports to toggle and the next actions to take on the switch.

actions to take on the switch.

C4-1050

Message

S<Slot number>,C<Chip index>: No buffers allocated to <String to specify type of port> port. Requested <Desired buffer count on the one port> buffers; ASIC buffers: current=<Total Number of buffers desired on ASIC> max=<Maximum possible buffers>

Message Type

LOG | FFDC

Severity ERROR

Probable Cause More buffers have been requested/desired than exist on the ASIC. This will cause traffic disruption in

the fabric.

Recommended

Action

First, take a supportsave and contact the switch vendor for analysis. If the number of requested buffers by the port is unexpectedly large, or if the number of requested buffers makes sense and the current total ASIC buffers is very close to the ASIC maximum, contact the switch vendor to analyze switch data for possible ports to toggle and the next actions to take on the switch.

C4-1051

Message S<Slot number>, P<User port index>(<Blade port number>): Port desired buffer mismatch.

actual: <Actual desired buffer count on the port> expected: <Expected desired buffer

count on the port>

Message Type LOG | FFDC

Severity ERROR

Probable Cause The number of buffers requested by a port does not match the number of buffers this port is supposed

to request.

Recommended First, collect a supportsave and contact the switch vendor. If the number of requested buffers by the

Action port is unexpectedly large, and if the port is a frontend port, toggle the identified port using portdisable,

portenable, portcfgpersistentdisable, or portcfgpersistentenable. If that doesn't work, or if the port is a

backend port, use slotpoweroff and slotpoweron on the identified blade.

C4-1052

Message S<Slot number>, C<Chip index>: <String to specify type of port> port desired buffer

mismatch. actual: <Actual desired buffer count on the port> expected: <Expected

desired buffer count on the port>

Message Type LOG | FFDC

Severity ERROR

Action

Probable Cause The number of buffers requested by a port does not match the number of buffers this port is supposed

to request.

Recommended First, take a supportsave and contact the switch vendor for analysis. If the number of requested buffers

by the port is unexpectedly large, contact the switch vendor to analyze switch data for the next actions

to take on the switch.

C4-1054

Message S<slot number>, P<port number>(<blade port number>): Media initialization fault;

please reseat or replace media rtryctr:<retries left>/<max retries > rate:<High(2)/</pre>

Low rate(1)> failure:<failure code>.

Message Type LOG | FFDC

Severity ERROR

Probable Cause A Media initialization fault occurs because the media is not seated properly or the SFP is faulty.

Actions such as media plug-out/plug-in and switch power-cycle can cause this fault.

Recommended Action

Follow these steps:

1. Disable the port, and then enable it.

- 2. Reseat the media.
- 3. If reseating does not recover the module, replace the module.

6.13 C5 Messages

C5-1001

Message S<slot number>, P<port number> (Bp<blade port number>) user idx:<User port index> [PID

0x<24 bit FC address>] faulted due to invalid SFP, conflicting speed or laser fault.

<error message>

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates a deteriorated small form-factor pluggable (SFP) transceiver, an incompatible SFP

transceiver pair, or a faulty cable between the peer ports.

Recommended Verify that compatible SFP transceivers are used on the peer ports, that the SFP transceivers have not

deteriorated, and that the Fibre Channel cable is not faulty. Replace the SFP transceivers or the cable

if necessary.

C5-1002

Message Port <port number> chip failed due to an internal error.

Message Type LOG | FFDC

Severity ERROR

Probable Cause Indicates an internal error. All ports on the blade or switch will be disrupted.

Recommended To recover a bladed system, execute the **slotPowerOff** and **slotPowerOn** commands on the blade. To

recover a nonbladed system, execute the **fastBoot** command on the switch.

C5-1004

Message S<slot number>, C<chip index>: Invalid DMA ch pointer, chan:<Channel number>,

good addr:0x<Good address> bad addr:0x<Bad address>.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates an internal error in the application-specific integrated circuit (ASIC) hardware that may

degrade the data traffic.

Recommended Reboot the system at the next maintenance window. If the problem persists, replace the blade.

Action

C5-1006

Message S<slot number>, C<chip index>: Various non-critical hardware errors were observed:

 $fault1:0x<fault1_cnt>, \ fault2:0x<fault2_cnt> \ thresh1:0x<threshold_used>.$

Message Type LOG

Severity WARNING

Probable Cause Indicates that some errors were found in the hardware that may or may not impact the data traffic.

Recommended No action is required. Usually these errors are transient.

Action

C5-1007

Message S<slot number>,P<port number>(<blade port number>): best effort QoS will be turned

off at next port state change as it is not supported under this configuration.

Message Type LOG

Severity WARNING

Probable Cause Indicates that Quality of Service (QoS) will be turned off automatically at the next port state change

because best effort QoS is no longer supported on 8Gb/s platform long-distance ports.

C5-1008

Message S<slot number>, P<port number> (<blade port number>): QoS overwrites

portcfglongdistance vc translation link init. ARB will be used on the link.

Message Type LOG

Severity WARNING

Probable Cause Indicates that Quality of Service (QoS) has overwritten the fill word IDLE used on the long-distance

links. Arbitrated loop (ARB) will be used on the link.

C5-1009

Message S<slot number>, P<port number>(<blade port number>): portcfqlongdistance

vc translation link init = 1 overwrites fill word IDLE. ARB will be used on the link.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the portcfglongdistance vc_translation_link_init 1 command has overwritten the fill

word IDLE. Arbitrated loop (ARB) will be used on the link.

C5-1010

Message S<slot number>, C<chip index>: Above normal hardware errors were observed:

fault1:0x<fault1 cnt>, fault2:0x<fault2 cnt> thresh2:0x<threshold used>.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that above-normal errors were observed in the hardware that may or may not impact the data

traffic.

Recommended When this error is observed persistently, power-cycle the specified blade using the slotPowerOff and

slotPowerOn commands. If the problem persists, replace the blade.

C5-1011

Message Detected a complete loss of credit on internal back-end VC: Slot <slot number>, Port

<port number>(<blade port number>) vc no=<vc number> crd(s)lost=<Credit(s) lost>.

Message Type LOG

Action

Action

Severity WARNING

Probable Cause Indicates that all credits have been lost on the specified virtual channel (VC) and port.

Recommended Turn on back-end credit recovery to reset the link and recover the lost credits. If credit recovery has

already been turned on, the link will be reset to recover the credits and no action is required.

C5-1012

Message S<slot number>, P<port number> (<blade port number>): Link Timeout on internal port

ftx=<frame transmitted> tov=<real timeout value> (><expected timeout value>)

vc_no=<vc number> crd(s)lost=<Credit(s) lost> complete_loss:<Complete credit loss>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that one or more credits have been lost on a back-end port and that there has been no traffic

on that port for two seconds.

Recommended Turn on back-end credit recovery to reset the link and recover the lost credits. If credit recovery has

already been turned on, the link will be reset to recover the credits and no action is required.

C5-1013

Message Multi RDY/Frame Loss detected on internal port of Slot <slot number>, Port <port

number>(<blade port number>) m_rdy(0x<Multiple Credit(s) Lost>)/m_frame(0x<Multiple</pre>

Frame(s) Lost>).

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that wait cycles to recover the lost frame or credit have been exceeded on the specified port.

Recommended

Action

Action

Turn on back-end credit recovery to reset the link and recover the lost credits. If credit recovery has already been turned on, the link will be reset to recover the credits and no action is required.

C5-1014

Message Link Reset on Port S<slot number>, P<port number> (<blade port number>) vc_no=<vc

number> crd(s)lost=<Credit(s) lost> <Source of link reset > trigger.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that one or more credits were lost and that the link has been reset.

Recommended When this error is observed persistently on back-end link, power-cycle the specified blade using the

slotPowerOff and **slotPowerOn** commands. If the problem persists, replace the blade. When this error is observed persistently on a user port, check the physical layer errors on this port and peer port using **portStatsShow** command. If there are some physical layer errors, change the small form-factor

pluggable (SFP) transceiver or the cable on the port and peer port to which this port is connected.

C5-1015

Message Port re-initialized due to Link Reset failure on internal Port S<slot number>, P<port

number>(<blade port number>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified port has re-initialized due to a link reset failure.

Recommended When this error is observed persistently, power-cycle the specified blade using the slotPowerOff and

Action **slotPowerOn** commands. If the problem persists, replace the blade.

C5-1016

Message Port is faulted due to port re-initialization failure on internal Port S<slot

number>, P<port number>(<blade port number>) with reason <port fault reason>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified port failed due to a port re-initialization failure.

Recommended When this error is observed persistently, power-cycle the specified blade using the slotPowerOff and

Action **slotPowerOn** commands. If the problem persists, replace the blade.

C5-1017

Message Blade in Slot-<slot number> failed due to unavailability of ports in the internal

trunk.

Message Type LOG

> **ERROR** Severity

Probable Cause Indicates that the specified blade failed because of the unavailability of the ports in the internal trunk.

Recommended When this error is observed persistently, power-cycle the specified blade using the slotPowerOff and Action

slotPowerOn commands. If the problem persists, replace the blade.

C5-1018

Message Link reset threshold value exceeded in the link S<slot number>,P<port number>(<blade

port number>).

Message Type LOG

> **ERROR** Severity

Probable Cause Indicates that the specified blade has faulted because the link reset threshold value was exceeded.

Recommended When this error is observed persistently, power-cycle the specified blade using the slotPowerOff and Action

slotPowerOn commands. If the problem persists, replace the blade.

C5-1019

Message S<slot number>, C<chip index>: HW ASIC Chip TXQ FID parity error threshold reached

type = 0x<chip error type>.

Message Type LOG

> Severity WARNING

Probable Cause Indicates that an internal error has been observed in the application-specific integrated circuit (ASIC)

hardware that may degrade the data traffic.

Recommended Restart the system at the next maintenance window.

Action

C5-1020

Message S<slot number>, P<port number>(<blade port number>): Internal CRC with good EOF errors

were observed, continuing monitoring. current:0x<last crc good eof cnt>,

last:0x<total_crc_good_eof_cnt> thresh1:0x<threshold_used>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that some CRC errors were detected on a back-end link by the hardware. Typically

applications are not affected at this low count.

C5-1023

Message Single RDY/Frame Loss detected and recovered on Slot <slot number>, Port <port

number>(<blade port number>) rdy(0x<Credit Lost>)/frame(0x<Frame Lost>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that above-normal errors have been observed in the hardware that may or may not impact

the data traffic.

Recommended When this error is observed persistently, power-cycle the specified blade using the slotPowerOff and

slotPowerOn commands. If the problem persists, replace the blade.

C5-1028

Message Detected excessive Link resets on the port in a second. Slot <slot number>, Port <port

number>(<blade port number>).

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that the port received excessive link resets from the peer port within 1 second and that

exceeded the threshold.

Recommended When this error is observed persistently, change the small form-factor pluggable (SFP) transceiver or

the cable on the peer port to which this port is connected.

C5-1030

Message S<slot number>, P<port number>(<blade port number>): Internal CRC with good EOF errors

exceeded threshold, tuning is required. current:0x<last_crc_good_eof_cnt>,

last:0x<total crc good eof cnt> thresh2:0x<threshold used>.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that some CRC errors have been detected on back-end link by hardware; applications may

be affected.

Recommended If a core blade reset or auto tuning or manual tuning does not resolve the issue, replace the blade.

Action

C5-1031

Message LOSYNC timeout occurred on Slot <slot number>, Port <port number>(<blade port

number>).

Message Type LOG

Severity INFO

Probable Cause Indicates that loss of synchronization has occurred on the BE port and that a link reset was invoked on

this port by the blade driver.

C5-1032

Message S<slot number>, P<port number>(<blade port number>): Required buffer unavailable for

the port. req_buf:<required buffer> port_buf:<port buffer> unused_buf:<Unused buffer>

est buf: <Estimated buffer>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that free buffers in the chip are not sufficient to bring the port online in fully operational mode.

The port may not come online or may operate in a degraded buffer mode.

Recommended If one or more ports that are configured as long distance in the chip are unused, reset these ports to

normal distance. If the problem persists, move the affected port to a different blade or chip.

C5-1033

Message S<slot number>, P<port number>(<blade port number>): FEC TTS is only supported on

F_Port.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that Forward Error Correction (FEC) TTS is enabled on the specified port. The FEC TTS

option is supported only on F Ports.

Recommended Disable the FEC TTS option using the portcfgfec --disable -TTS command.

Action

C5-1034

Message S<slot number>, P<port number>(<blade port number>): FEC is Enabled but FEC is

Inactive. Check peer port's FEC configurations.

Message Type LOG

Severity INFO

Probable Cause Indicates that Forward Error Correction (FEC) is enabled but is inactive on the specified port.

Recommended Check the local and peer port's FEC configurations using the **portcfgfec --show** command.

Action

C5-1035

Message Credit Recovery disabled on Slot <slot number>, Port <port number>(<blade port

number>) because of HW error.

Message Type LOG

Severity WARNING

Probable Cause Indicates that credit recovery logic has failed.

Recommended Disable and enable the port, and if the error persists, disable credit recovery for the port.

Action

C5-1036

Message Buffer sharing unfairness issue on Slot <slot number>, Port <port number>(<blade port

number>).

Message Type LOG

Severity WARNING

Probable Cause Indicates buffer sharing unfairness and port starvation.

C5-1037

Message S<slot number>, C<chip index>: DAE Error, first error top = 0x<first error top>,

intr cause = 0x<intr cause>, first err = 0x<first error> first err info 0x<first

error info>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that a hardware parity error has been detected in the Condor5 DAE block.

Recommended DAE counters may have been corrupted; ignore DAE flow counters in the last polling cycle.

Action

C5-1038

Message Slow drain device quarantine (SDDQ) or Restore action is not completed for the sid

0x<Source ID>, did 0x<Destination ID>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the Frame Transformation Block (FTB) entry has not been added.

C5-1039

Message S<slot number>, C<chip index>: Temperature is <current temperature>, maximum threshold

is <Maximum operating temperature>. If it exceeds threshold, the unit will be

shutdown.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the operating environment conditions are causing the application-specific integrated

circuit (ASIC) to overheat.

Recommended Make sure that the area is well ventilated and that the room temperature is within the operational range

of your switch. Refer to the hardware reference manual for your switch for the operational temperature

range.

C5-1040

Message Multi RDY/Frame Loss detected on Slot <slot number>, Port <port number>(<blade port

 $\label{loss} \verb|number>| m_rdy(0x<Multiple Credit(s) Lost>)/m_frame(0x<Multiple Frame(s) Lost>).$

Link Reset done.

Message Type LOG

Severity WARNING

Probable Cause Indicates that multiple credits and frames were lost on the specified port and that the link has reset.

C5-1041

Message Encryption block error event detected on Slot <slot number>, Port <port number>(<blade

port number>), err count:<error counter>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that encryption block errors have been detected.

Recommended Disable and enable the port, and if the problem persists, replace the blade.

Action

C5-1042

Message Port in Slot <slot number>, Port <port number>(<blade port number>) getting faulted

because of encryption block error.

Message Type LOG

> Severity **WARNING**

Probable Cause Indicates that the port has faulted because of encryption block errors.

Recommended Disable and enable the port, and if the problem persists, replace the blade.

Action

C5-1043

Message Encryption enabled Port S<slot number>, P<port number> (<blade port number>) faulted

due to link initialization failure.

LOG Message Type

> WARNING Severity

Probable Cause Indicates that an encryption-configured port failed because of a link initialization failure.

Recommended Disable and enable the port, and if the problem persists, replace the blade.

Action

C5-1044

Message Trunk performance impact on port (<port number>) due to high deskew value.

[TRUNK PERF:<perf> percent, Deskew:<deskew>]

LOG Message Type

Action

Severity INFO

Probable Cause Indicates a high deskew value on the port.

Recommended Check for physical cable length differences among physical ports of the trunk. If there are cable length

differences, fix them with the same cable length link. Otherwise replace the cable if the problem

persists.

C5-1045

Broadcom

Message Single parity error detected in ftb statistics memory, slot <slot> index <index>

Message Type LOG

> **INFO** Severity

Probable Cause A parity error was detected in FTB statistics memory; a Flow Vision flow monitor may show incorrect

statistics.

Recommended

Reset the Flow Vision flow monitor flow that is showing abnormal statistics.

C5-1046

Message Multiple parity errors detected in ftb statistics memory, slot <slot> indexes <index>

<index> <index> <index>

Message Type LOG

Action

Severity INFO

Probable Cause A parity error was detected in FTB statistics memory; a Flow Vision flow monitor may show incorrect

statistics.

Recommended

Action

Reset the Flow Vision flow monitor flow that is showing abnormal statistics.

C5-1048

Message S<Slot number>, C<Chip Index>: Maximum possible buffers (<Maximum possible buffers>)

exceeded; total desired:<Total Number of buffers desired>; port <Port with high desired count> has high desired count:<Desired buffer count on the one port>

Message Type LOG | FFDC

Severity ERROR

Probable Cause More buffers have been requested/desired than exist on the ASIC. This will cause traffic disruption in

the fabric.

Recommended

Action

First, collect a supportsave and contact the switch vendor for analysis. If the number of requested buffers by the port is unexpectedly large, and if the port is a frontend port, toggle the identified port using portdisable, portenable, portefgpersistentdisable, or portefgpersistentenable. If that doesn't work, or if the port is a backend port, use slotpoweroff and slotpoweron on the identified blade. If the number of requested buffers makes sense and the current total ASIC buffers is very close to the ASIC maximum, contact the switch vendor to analyze switch data for possible ports to toggle and the next

actions to take on the switch.

C5-1049

Message S<Slot number>, P<User port index>(<Blade port number>): Port faulted at <String to

identify location>. Requested <Maximum possible buffers> buffers; ASIC buffers: current=<Desired buffer count on the one port> max=<Total Number of buffers desired

on ASIC>

Message Type LOG | FFDC

Severity ERROR

Probable Cause More buffers have been requested/desired than exist on the ASIC. This will cause traffic disruption in

the fabric.

Recommended if the number of requested buffers by the port is unexpectedly large, and if the port is a frontend port,

Action toggle the identified port using portdisable, portenable, portcfgpersistentdisable, or

portcfgpersistentenable. If that doesn't work, or if the port is a backend port, use slotpoweroff and slotpoweron on the identified blade. If the number of requested buffers makes sense and the current total ASIC buffers is very close to the ASIC maximum, contact the switch vendor to analyze switch

data for possible ports to toggle and the next actions to take on the switch.

C5-1050

Message S<Slot number>, C<Chip index>: No buffers allocated to <String to specify type of port>

port. Requested <Maximum possible buffers> buffers; ASIC buffers: current=<Desired

buffer count on the one port> max=<Total Number of buffers desired on ASIC>

Message Type LOG | FFDC

Severity ERROR

Action

Probable Cause More buffers have been requested/desired than exist on the ASIC. This will cause traffic disruption in

the fabric.

Recommended First, take a supportsave and contact the switch vendor for analysis. If the number of requested buffers

by the port is unexpectedly large, or if the number of requested buffers makes sense and the current total ASIC buffers is very close to the ASIC maximum, contact the switch vendor to analyze switch

data for possible ports to toggle and the next actions to take on the switch.

C5-1051

Message S<Slot number>, P<User port index>(<Blade port number>): Port desired buffer mismatch.

actual: <Actual desired buffer count on the port> expected: <Expected desired buffer

count on the port>

Message Type LOG | FFDC

Severity ERROR

Action

Probable Cause The number of buffers requested by a port does not match the number of buffers this port is supposed

to request.

Recommended First, collect a supportsave and contact the switch vendor. If the number of requested buffers by the

port is unexpectedly large, and if the port is a frontend port, toggle the identified port using portdisable, portenable, portcfgpersistentdisable, or portcfgpersistentenable. If that doesn't work, or if the port is a

backend port, use slotpoweroff and slotpoweron on the identified blade.

C5-1052

Message S<Slot number>, C<Chip index>: <String to specify type of port> port desired buffer

mismatch. actual: <Actual desired buffer count on the port> expected: <Expected

desired buffer count on the port>

Message Type LOG | FFDC

Severity ERROR

Probable Cause The number of buffers requested by a port does not match the number of buffers this port is supposed

to request.

Recommended First, take a supportsave and contact the switch vendor for analysis. If the number of requested buffers

by the port is unexpectedly large, contact the switch vendor to analyze switch data for the next actions

to take on the switch.

C5-1053

Message S<slot number>, P<port number>(<blade port number>): 4G Speed is supported for F-Port

only.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that the E-Port is operating at 4G speed. The 4G speed is supported only on F Ports.

Recommended

Action

C5-1054

Message S<slot number>, P<port number>(<blade port number>): Media initialization fault;

please reseat or replace media rtryctr:<retries left>/<max retries > rate:<High(2)/</pre>

Low rate(1) > failure: <failure code >.

Message Type LOG | FFDC

Severity ERROR

Probable Cause A Media initialization fault occurs because the media is not seated properly or the SFP is faulty.

Actions such as media plug-out/plug-in and switch power-cycle can cause this fault.

Recommended Follow Action

Follow these steps:

1. Disable the port, and then enable it.

2. Reseat the media.

3. If reseating does not recover the module, replace the module.

6.14 CAL Messages

CAL-1001

Message Switch offline requested by remote domain <domain number>.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the specified remote domain requested the local domain to be disabled.

Recommended

Check the error message log on the remote domain using the **errShow** command to find the reason.

6.15 CCFG Messages

CCFG-1001

Message Failed to initialize <module>, rc = <error>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the initialization of a module within the Converged Enhanced Ethernet (CEE)

configuration management daemon has failed.

Recommended Down

Action

Download a new firmware version using the firmwareDownload command.

CCFG-1002

Message Started loading CEE system configuration.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the Converged Enhanced Ethernet (CEE) system configuration has started loading.

CCFG-1003

Message System is ready to accept CEE user commands.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the Converged Enhanced Ethernet (CEE) shell is ready to accept configuration

commands.

CCFG-1004

Message Configuration replay failed due to missing system startup configuration file.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the startup configuration file has been moved or deleted and that therefore replaying the

system configuration has failed.

Recommended Execute the copy file startup-config command to restore the startup configuration file from any

Action backup retrieved on the server.

CCFG-1005

Message Startup configuration file is updated.

Message Type LOG

Severity INFO

Probable Cause Indicates that the startup configuration file has been updated.

CCFG-1006

Message Current system running configuration file is updated.

Message Type LOG

Severity INFO

Probable Cause Indicates that the current running configuration file has been updated.

CCFG-1007

Message Startup configuration is deleted.

Message Type LOG

Severity INFO

Probable Cause Indicates that the startup configuration file has been moved or deleted.

CCFG-1008

Message CMSH init failed: <msg>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the CEE Management Shell (CMSH) initialization has failed.

CCFG-1009

Message Successfully copied to <destination>.

Message Type LOG

Severity INFO

Probable Cause Indicates that a configuration file has been copied to the specified destination.

CCFG-1010

Message Current system running configuration file is updated partially.

Message Type LOG

Severity INFO

Probable Cause Indicates that the current running configuration file has been partially updated.

CCFG-1011

Message Linecard configuration mismatch on slot <slot>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the inserted linecard is different from the preconfigured linecard on the specified slot.

Recommended Execute the **no linecard** command to remove the linecard configuration.

Action

CCFG-1012

Message Blade in slot <slot> failed to reach ONLINE state within <timeout> seconds after

receiving system ready.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the blade in the specified slot has failed to come online within the specified timeout

interval after receiving the system ready event.

Recommended Execute the slotPowerOff and slotPowerOn commands on the specified slot to bring the blade

Action online.

6.16 CFS Messages

CFS-1001

Message Initialization of CFSd failed in <File Name>:<Line Number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the CFS daemon has failed initialization due to internal error.

Recommended Contact Brocade Support team.

Action

6.17 CH Messages

CH-1001

Message CLI history shell CLI buffer is disabled.

Message Type AUDIT

Class CLI

Severity INFO

Probable Cause Indicates that the CLI history shell CLI buffer has been disabled.

CH-1002

Message CLI history shell CLI buffer is enabled.

Message Type AUDIT

Class CLI

Severity INFO

Probable Cause Indicates that the CLI history shell CLI buffer has been enabled.

6.18 CHS Messages

CHS-1002

Message ki gd register action failed with rc = <return val>.

Message Type LOG | FFDC

Severity ERROR

Probable Cause Indicates an internal error.

Recommended To recover a bladed system, execute the **slotPowerOff** and **slotPowerOn** commands on the blade. To

recover a non-bladed system, execute the **fastBoot** command on the switch.

CHS-1003

Message Slot ENABLED but Not Ready during recovery, disabling slot = <slot number> rval =

<return value>.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the slot state has been detected as inconsistent during failover or recovery.

Recommended For a bladed switch, execute the **slotPowerOff** and **slotPowerOn** commands to power cycle the

Action blade.

For a non-bladed switch, restart or power cycle the switch.

CHS-1004

Message Blade attach failed during recovery, disabling slot = <slot number>, rval = <return

value>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified blade has failed during failover or recovery.

Recommended For a bladed switch, execute the **slotPowerOff** and **slotPowerOn** commands to power cycle the

Action blade.

For a non-bladed switch, restart or power cycle the switch.

CHS-1005

Message Diag attach failed during recovery, disabling slot = <slot number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the diagnostic blade attach operation has failed during failover or recovery.

Recommended For a bladed switch, execute the slotPowerOff and slotPowerOn commands to power cycle the

Action blade.

For a non-bladed switch, restart or power cycle the switch.

CHS-1006

Message Chassis has been enabled.

Message Type AUDIT

Class CLI

Severity INFO

Probable Cause Indicates that the chassis is being intentionally enabled.

CHS-1007

Message Chassis has been disabled.

Message Type AUDIT

Class CLI

Severity INFO

Probable Cause Indicates that the chassis is being intentionally disabled.

CHS-1008

Message Chassis beacon has been <printf>.

Message Type AUDIT

Class CLI

Severity INFO

Probable Cause Indicates that the chassis beaconing is being enabled/disabled.

6.19 CNM Messages

CNM-1001

Message Failed to allocate memory: (<function name>).

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified function has failed to allocate memory.

Recommended Check memory usage on the switch using the **memShow** command.

Action Restart or power-cycle the switch.

CNM-1002

Message Failed to initialize <module> rc = <error>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the initialization of a module within the Cluster Node Manager (CNM) has failed.

Recommended Download a new firmware version using the **firmwareDownload** command.

Action

CNM-1003

Message Crypto device cfg between local switch (<local domain id>) and peer (<peer domain

id>) out of sync. New encryption session not allowed.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the encryption engine nodes in the cluster encryption group have different

configurations.

Recommended Synchronize the configuration in the cluster group using the **cryptocfg** command.

Action

CNM-1004

Message iSCSI service is <status> on the switch.

Message Type LOG

Severity INFO

Probable Cause Indicates that the crypto service has been enabled or disabled on the switch.

CNM-1005

Message Posting event CNM_EVT_GRP_LEADER_ELECTED Name [<nodeName>], WWN [<WWN>].

Message Type LOG

Severity INFO

Probable Cause Indicates that the cluster Encryption Group (EG) leader has been elected.

CNM-1006

Message Posting event CNM_EVT_NODE_JOIN nodeName [<nodeName>], WWN [<WWN>], ipaddress [<IP

address>].

Message Type LOG

Severity INFO

Probable Cause Indicates that the member node has joined.

CNM-1007

Message Posting event CNM EVT GRP LEADER FAILED Name [<nodeName>]

Message Type LOG

Severity INFO

Probable Cause Indicates that the Encryption Group (EG) leader has failed.

CNM-1008

Message Posting event CNM EVT NODE EJECT nodeName [<nodeName>], WWN [<WWN>].

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified node has been ejected from the Encryption Group (EG).

CNM-1009

Message Posting event CNM EVT STANDALONE MODE.

Message Type LOG

Severity INFO

Probable Cause Indicates that the node is in standalone mode.

CNM-1010

Message Posting event CNM_EVT_CLUSTER_UDATA_UPDATE cid [<client id>], ulen [<udata len>].

Message Type LOG

Severity INFO

Probable Cause Indicates the client data update.

CNM-1011

Message Posting event CNM_EVT_NODE_JOIN_TIMEOUT nodeName [<nodeName>], WWN [<wwn>], ipaddress

[<ipAddr>].

Message Type LOG

Severity INFO

Probable Cause Indicates the node join timeout.

Recommended Take the peer node offline, and rejoin the node to the Encryption Group (EG).

Action

CNM-1012

Message Posting event CNM EVT EG DELETED.

Message Type LOG

Severity INFO

Probable Cause Indicates that the Encryption Group (EG) has been deleted.

CNM-1013

Message Posting event GL Node Split condition, isolating peer GL node <nodeName>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the Encryption Group (EG) has been split.

CNM-1014

Message Posting event Node Admission Control passed, admitting node [<nodeName>].

Message Type LOG

Severity INFO

Probable Cause Indicates that the node admission control was successful.

CNM-1015

Message Posting event Potential Cluster Split condition.

Message Type LOG

Severity INFO

Probable Cause Indicates a Potential Cluster Split condition.

CNM-1016

Message Posting event Detected a EG degrade condition.

Message Type LOG

Severity INFO

Probable Cause Indicates an Encryption Group (EG) degrade condition.

CNM-1017

Message Got JOIN REQUEST from un-recognized GL node [<rxglname>], configured GL node is

[<glname>].

Message Type LOG

Severity INFO

Probable Cause Indicates that a join request was received from an invalid group leader (GL) node.

CNM-1018

Message Got CNM FSM EVT JOIN REQ when already a member, My assigned name [<nodename>],

dropping request.

Message Type LOG

Severity INFO

Probable Cause Indicates that the node is already a member of the Encryption Group (EG).

CNM-1019

Message Join Rejected by GL node, fix certificate and later add member node from GL node, or

reboot the member node.

Message Type LOG

Severity INFO

Probable Cause Indicates an invalid member node certificate.

Recommended Install a valid certificate and add a member node to the group leader (GL) node, or reboot the member

Action node.

CNM-1020

Message Node Admission Control failed due to mismatch in certificates, rejecting node

[<nodename>].

Message Type LOG

Severity INFO

Probable Cause Indicates that node admission control has failed.

CNM-1021

Message Failed to sign the node authentication message, admission control might fail.

Message Type LOG

Severity INFO

Probable Cause Indicates that node admission control has failed.

CNM-1022

Message Operation not allowed on GL Node.

Message Type LOG

Severity INFO

Probable Cause Indicates that an operation is not allowed on a group leader (GL) node.

CNM-1023

Message Group Leader node eject is not allowed.

Message Type LOG

Severity INFO

Probable Cause Indicates that an eject operation is not allowed on a group leader (GL) node.

CNM-1024

Message Operation not required on GL node.

Message Type LOG

Severity INFO

Probable Cause Indicates that an operation is not required on a group leader (GL) node.

CNM-1025

Message Operation not allowed, as member is active with the Cluster. Eject member node and

retry.

Message Type LOG

Severity INFO

Probable Cause Indicates that an operation is not allowed on a member node.

Recommended Eject the member node and retry the operation.

Action

CNM-1026

Message Recvd HBT Msg with version mismatch, Recvd Hdr version 0x<received hardware version>

Exp Hdr version 0x<expected hardware version> Node <WWN>.

Message Type LOG

Severity INFO

Probable Cause Indicates that a version mismatch has occurred.

Recommended Upgrade the firmware or delete the node from the Encryption Group (EG).

Action

CNM-1027

Message Received HBT from non-Group Member Node [<WWN>].

Message Type LOG

Severity INFO

Probable Cause Indicates that an operation is not allowed on a nongroup member node.

CNM-1028

Message Certfile <certificate file name> already exists. No need to sync up.

Message Type LOG

Severity INFO

Probable Cause Indicates that the certificate file for the node already exists.

CNM-1029

Message Certfile <certificate file name> content does not match the cert sent by GL.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the contents of the node's certificate file are different from the certificate file sent by the

group leader (GL) node.

CNM-1030

Message Certfile <certificate file name> read less number of bytes <nbytes>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the read operation of the certificate file returned fewer bytes than expected.

CNM-1031

Message Certfile <certificate file name> open failed with errno <error num>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that an attempt to open the certificate file has failed.

CNM-1032

Message Certfile <certificate file name> size <file size> does not match cert file size

<length> sent by GL.

Message Type LOG

Severity WARNING

Probable Cause Indicates that there is a size mismatch between a node's certificate file and the certificate file received

from the group leader (GL).

CNM-1033

Message Some of the defined nodes in the Encryption Group are not ONLINE. Encryption Group

is in degraded state.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the cluster is in a degraded state.

CNM-1034

Message All the defined nodes in the Encryption Group are ONLINE. Cluster is in converged

state.

Message Type LOG

Severity INFO

Probable Cause Indicates that the cluster is in a converged state.

CNM-1035

Message Cluster is in degraded state. Posting degrade event.

Message Type LOG

Severity WARNING

Probable Cause Indicates that an event is being posted to specify that the cluster is in a degraded state.

CNM-1036

Message All the active nodes of the cluster are in ONLINE state. Posting converged event.

Message Type LOG

Severity INFO

Probable Cause Indicates that an event is being posted to specify that the cluster is in a converged state.

CNM-1037

Message Split-Brain Arbitration lost, minority GL Node, remote:local

[<remote_count>:<local_gl_ncount>].

Message Type LOG

Severity INFO

Probable Cause Indicates that split-brain arbitration has been lost.

CNM-1038

Message Split-Brain Arbitration won, majority GL Node, remote:local

[<remote_count>:<local_gl_ncount>].

Message Type LOG

Severity INFO

Probable Cause Indicates that split-brain arbitration has been won.

CNM-1039

Message Split-Brain Arbitration lost, Minority WWN/GL Node, remote WWN:local WWN <wbuf>.

Message Type LOG

Severity INFO

Probable Cause Indicates that split-brain arbitration has been lost.

CNM-1040

Message Split-Brain Arbitration won, Majority WWN/GL Node, remote WWN:local WWN < WWN>.

Message Type LOG

Severity INFO

Probable Cause Indicates that split-brain arbitration has been won.

CNM-1041

Message Updating persistent Cluster DB, please avoid powering off the switch.

Message Type LOG

Severity INFO

Probable Cause Indicates that the system is updating the persistent database.

CNM-1042

Message Completed updating persistent Cluster DB.

Message Type LOG

Severity INFO

Probable Cause Indicates that the persistent database update is complete.

CNM-1043

Message Received HBT from undefined node IpAddress [<ip>], WWN [<wwn>]. Possible

configuration error.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the remote node's WWN may have changed.

CNM-1044

Message Cluster Create Failed as the Certificate files not found, Please do the initnode.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the initnode has not been invoked.

Recommended Execute the **cryptocfg** --initnode command.

Action

CNM-1045

Message Member node [<wwn>] is having dual IP stack. Registering member node with dual IP in

an EG with only IPv6 is not allowed.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the member node with the dual IP stack was registered with the IPv6 Encryption Group

(EG).

CNM-1046

Message Posting event CNM EVT NODE LEAVE nodeName [<nodeName>], WWN [<wwn>].

Message Type LOG

Severity INFO

Probable Cause Indicates that the node has decided to leave the Encryption Group (EG).

CNM-1047

Message Network Interface to Remote Node [<ip>] is [<string>].

Message Type LOG

Severity INFO

Probable Cause Indicates that the status of the network interface is up or down.

CNM-1048

Message Posting <string>.

Message Type LOG

Severity INFO

Probable Cause Indicates the event that is posted.

CNM-1049

Message Failed to define node, Node Name [<string>].

Message Type LOG

Severity ERROR

Probable Cause Indicates the failure to define the node object.

CNM-1050

Message Node Admission Control failed due to mismatch in Access Gateway Daemon (AGD) mode

settings, rejecting node [<nodename>].

Message Type LOG

Severity ERROR

Probable Cause Indicates a mode mismatch between the switches, such as an Access Gateway mode mismatch.

CNM-1051

Message Join Rejected by GL Node due to Access Gateway Daemon mode mismatch, ensure mode

settings are same across all nodes in EG.

Message Type LOG

Severity ERROR

Probable Cause Indicates a mode mismatch between the switches, such as an Access Gateway mode mismatch.

CNM-1052

Message Member node registered with another Encryption Group. To proceed eject the member

node [<nodename>] from other EG.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the member node is registered with another Encryption Group (EG).

CNM-1053

Message Node is already a registered member of another EG. First eject the current node

[<nodename>] from the existing EG and then try.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the node is already a registered member of another Encryption Group (EG).

Recommended Eject the specified node from the EG and retry the operation.

Action

CNM-1054

Message Encryption Group database state [<state>] with node IP [<node>], WWN [<wwn>].

Message Type LOG

Severity INFO

Probable Cause Indicates the status of the cluster database.

CNM-1055

Message Got CNM FSM EVT JOIN REQ when already a member from same GL node, rejoining EG with

GL [<glname>].

Message Type LOG

Severity INFO

Probable Cause Indicates that the node is rejoining the Encryption Group (EG).

CNM-1056

Message Posting event CNM EVT EE INITIALIZING Slot [<slot>], WWN [<wwn>], IP [<ip>], flags

[<flags>].

Message Type LOG

Severity INFO

Probable Cause Indicates that the encryption engine has been added into the Encryption Group (EG).

CNM-1057

Message Posting event CNM_EVT_ONLINE Slot [<slot>], WWN [<wwn>], IP [<ip>], flags [<flags>].

Message Type LOG

Severity INFO

Probable Cause Indicates that the encryption engine is online in the Encryption Group (EG).

CNM-1058

Message Posting event CNM EVT OFFLINE Slot [<slot>], WWN [<wwn>], IP [<ip>], flags [<flags>].

Message Type LOG

Severity INFO

Probable Cause Indicates that the encryption engine has been removed from the Encryption Group (EG).

CNM-1059

Message Local Node CP certificate pair mismatch detected, re-initialize the node.

Message Type LOG

Severity INFO

Probable Cause Indicates that the certificate pair is mismatched.

CNM-1060

Message Local Node CP certificate pair match detected.

Message Type LOG

Severity INFO

Probable Cause Indicates that the certificate pair is matched.

CNM-1061

Message IP of the switch changed from [<old_ip_address>] to [<new_ip_address>].

Message Type LOG

Severity INFO

Probable Cause Indicates that the switch IP address has changed.

CNM-1062

Message Copied certificate to [<ofname>] due to change in IP.

Message Type LOG

Severity INFO

Probable Cause Indicates that the certificate was copied to the file with a new IP name.

CNM-3001

Message Event: cryptocfg Status: success, Info: encryption group \"<encryption group name>\"

created.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates that the specified encryption group was created.

CNM-3002

Message Event: cryptocfg Status: success, Info: encryption group deleted.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates that an encryption group was deleted.

CNM-3003

Message Event: cryptocfg Status: success, Info: Membernode \"<member node WWN>\" added to

encryption group.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates that the specified member node was added to an encryption group.

CNM-3004

Message Event: cryptocfg Status: success, Info: Membernode \"<member node WWN>\" ejected from

encryption group.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates that the specified member node was ejected from an encryption group.

CNM-3005

Message Event: cryptocfg Status: success, Info: Membernode \"<member node WWN>\" left

encryption group.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates that the specified member node left an encryption group.

CNM-3006

Message Event: cryptocfg Status: success, Info: Heartbeat miss count set to

<heartbeat misses>.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates that the heartbeat miss value was set.

CNM-3007

Message Event: cryptocfg Status: success, Info: Heartbeat timeout set to <heartbeat timeout>.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates that the heartbeat timeout value was set.

CNM-3008

Message Event: cryptocfg Status: success, Info: Routing mode of EE in slot <slot> set to

<routingmode>.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates that the encryption engine routing mode was set.

CNM-3009

Message Event: cryptocfg Status: success, Info: <nodeType> <nodeWWN> registered.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates that the specified member node was registered.

CNM-3010

Message Event: cryptocfg Status: success, Info: Membernode <membernodeWWN> unregistered.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates that the specified member node was unregistered.

CNM-3011

Message Event: cryptocfg Status: success, Info: Encryption group synchronized.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates that an encryption group was synchronized.

CNM-3012

Message Deleting an EG with LUNs setup for encryption can lead to LUNs being disabled if

Encryption Group name is not preserved (<egName>).

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates that the Encryption Group (EG) was deleted. Re-create the EG with the same name if LUNs

are set up for encryption.

Recommended

Preserve the EG name when the EG is re-created if LUNs are set up for encryption.

Action

6.20 CNMC Messages

CNMC-1001

Message Switch reset to default configuration due to movement detection.

Message Type LOG

Severity INFO

Probable Cause Indicates that a movement of the switch has occurred.

CNMC-1002

Message Switch reset to default configuration upon receiving a request from Enclosure Manager.

Message Type LOG

Severity INFO

Probable Cause Indicates that the switch has received a reset to default configuration request from the Enclosure

Manager.

CNMC-1003

Message Switch reset to default configuration failed (<Error code.>).

Message Type LOG

Severity INFO

Probable Cause Indicates that the reset to default configuration request from the Enclosure Manager failed.

6.21 CONF Messages

CONF-1000

Message configDownload completed successfully <Info about the parameters and AD.>.

Message Type LOG | AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the **configDownload** operation was initiated and completed successfully. The

information about the parameters and AD variable is the description of the classes of configuration parameters that were downloaded. If Admin Domain (AD) is enabled, the AD number is specified in the

description.

CONF-1001

Message configUpload completed successfully <Info about the parameters and AD>.

Message Type LOG | AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the **configUpload** operation was initiated and completed successfully. The *information*

about the parameters and AD variable is the description of the classes of configuration parameters that

were uploaded. If Admin Domain (AD) is enabled, the AD number is specified in the description.

CONF-1020

Message configDownload not permitted <AD Number if AD is configured on the system>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that a **configDownload** operation was not permitted. There are many possible causes.

Recommended Execute the **errShow** command to view the error log. Correct the error and execute the

Action configDownload command again.

CONF-1021

Message configupload not permitted <AD Number if AD is configured on the system>.

Message Type LOG

Severity INFO

Probable Cause Indicates that a **configUpload** operation was not permitted. There are many possible causes.

Recommended

Action Execute the errShow command to view the error log. Correct the error and execute the configUpload

command again.

CONF-1022

Message Downloading configuration without disabling the switch was unsuccessful.

Message Type AUDIT

Class CFG

Severity WARNING

Probable Cause Indicates that an attempt to download the configuration without disabling the switch was unsuccessful

because there are one or more parameters that require the switch to be disabled.

Recommended Disable the switch using the **switchDisable** command and download the configuration.

Action

CONF-1023

Message configDownload failed <Message>.

Message Type LOG

Severity INFO

Probable Cause Indicates that a **configDownload** operation has failed.

Recommended Execute the **errShow** command to view the error log. Correct the error and execute the

Action configDownload command again.

CONF-1024

Message configUpload failed <Message>.

Message Type LOG

Severity INFO

Probable Cause Indicates that a **configUpload** operation has failed.

Recommended Execute the **errShow** command to view the error log. Correct the error and execute the **configUpload**

Action command again.

CONF-1030

Message Configuration database full, data not committed (key: <Key of failed configuration

data>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the previous configuration commands have resulted in a database full condition.

Configuration changes associated with the specified key were not applied.

Recommended Use the **configure** command and various other commands to erase configuration parameters that are

Action no longer required. As a last resort, execute the **configDefault** command and reconfigure the system.

CONF-1031

Message configDefault completed successfully <Message>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the **configDefault** command was initiated and completed successfully.

CONF-1032

Message configRemove completed successfully <Message>.

Message Type LOG | AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the **configRemove** command was initiated and completed successfully.

CONF-1033

Message Factoryreset operation is completed successfully.

Message Type LOG | AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the **factoryreset** was initiated and completed successfully.

CONF-1040

Message configDefault Failed. <Message>.

Message Type LOG

Severity INFO

Probable Cause Indicates that an error occurred while executing the configDefault command.

Recommended Execute the **errShow** command to view the error log. Correct the error and execute the **configDefault**

Action command again.

CONF-1041

Message configRemove Failed. <Message>.

Message Type LOG

Severity INFO

Probable Cause Indicates that an error occurred while issuing the **configRemove** command.

Recommended Execute the errShow command to view the error log. Correct the error and execute the

Action configRemove command again.

CONF-1042

Message Fabric Configuration Parameter <Parameter> changed to <Value>

Message Type LOG | AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the fabric configuration parameter value has been changed.

CONF-1043

Message Fabric Configuration Parameter <Parameter> changed to <Value>

Message Type LOG | AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the fabric configuration parameter value has been changed.

CONF-1044

Message Fabric Configuration Parameter <Parameter> changed from <Old Location> to

<New_Location>

Message Type LOG | AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the fabric configuration parameter value has been changed by a user.

CONF-1045

Message Dynamic port name is <Value>.

Message Type LOG | AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the dynamic port name has been enabled or disabled.

CONF-1046

Message <Parameter> changed to <Value>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the configure command configuration value has been changed.

CONF-1047

Message Aptpolicy is updated to <Value>.

Message Type LOG | AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the Advanced Performance Tuning policy has been updated successfully.

CONF-1048

Message Dynamic port name format is set to <Value>.

Message Type LOG | AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the dynamic port name format has been changed.

CONF-1049

Message Chassis CSCTL mode changed to <printf>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause The user changed the CSCTL mode by the CLI.

CONF-1050

Message Chassis configuration - Secure config upload/download <Parameter>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause CLI: configurechassis

CONF-1051

Message Chassis configure - Uploaded file suffix <Parameter>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause CLI: configurechassis

CONF-1052

Message Chassis configure - Auto firmware sync <Parameter>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause CLI: configurechassis

CONF-1053

Message Eth Rate Limiting feature is turned <Value>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause CLI: Configure

CONF-1054

Message VF has been enabled.

Message Type LOG

Severity INFO

Probable Cause Indicates that the Virtual Fabric has been enabled.

CONF-1055

Message VF has been disabled.

Message Type LOG

Severity INFO

Probable Cause Indicates that the Virtual Fabric has been disabled.

6.22 DIAG Messages

DIAG-1000

Message <Part1 of diag err string>

Message Type LOG

Severity ERROR

Probable Cause Indicates diagnostic errors on the console.

6.23 DOT1 Messages

DOT1-1001

Message 802.1X is enabled globally.

Message Type LOG

Severity INFO

Probable Cause Indicates that 802.1X is enabled globally.

DOT1-1002

Message 802.1X is disabled globally.

Message Type LOG

Severity INFO

Probable Cause Indicates that 802.1X is disabled globally.

DOT1-1003

Message 802.1X is enabled for port <port_name>.

Message Type LOG

Severity INFO

Probable Cause Indicates that 802.1X is enabled on the specified port.

DOT1-1004

Message Port <port_name> is forcefully unauthorized.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified port has been forcefully unauthorized using the dot1x port-control force-

unauthorized command.

DOT1-1005

Message 802.1X authentication is successful on port <port name>.

Message Type LOG

Severity INFO

Probable Cause Indicates that 802.1X authentication has succeeded on the specified port.

DOT1-1006

Message 802.1X authentication has failed on port <port_name>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that 802.1X authentication has failed on the specified port due to incorrect credentials or that

the Remote Authentication Dial-In User Service (RADIUS) server is not functioning properly.

Recommended Check the credentials configured with the supplicant and the RADIUS server.

Action

DOT1-1007

Message No RADIUS server available for authentication.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that there is no Remote Authentication Dial-In User Service (RADIUS) server available for

authentication.

Recommended Execute the **aaaConfig --show** command to verify that the configured RADIUS servers are reachable

Action and functioning.

DOT1-1008

Message Port <port name> is forcefully authorized.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified port has been forcefully authorized using the dot1x port-control forced-

authorized command.

DOT1-1009

Message 802.1X is disabled for port <port name>.

Message Type LOG

Severity INFO

Probable Cause Indicates that 802.1X is disabled on the specified port.

DOT1-1010

Message Port <port_name> is set in auto mode.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified port is set to auto mode.

6.24 ECC Messages

ECC-1000

Message ECC Error <Multiple or single occurrence of errors of a given type detected>

occurrence of <Automatic calibration error detected><Multiple bit error detected><Single bit error detected><Memory select error detected>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the processor memory controller has detected one of the several types of double data

rate (DDR) memory errors. Single bit errors are corrected, but other errors indicate either software errors or problems with the target system DRAM. Single bit errors can be expected to occur

infrequently and can be caused by uncontrollable external events like cosmic rays, but frequent single

bit errors can be indications of a degrading DRAM device.

Recommended Frequent single bit errors and all other error types should be reported to technical support for further

action.

ECC-1001

Message ECC Error <Multiple or single occurrence of multiple bit ECC error detected><Multiple

or single occurrence of single bit ECC error detected><Multiple of single occurrence

of access outside the defined physical memory space detected> detected.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the processor memory controller has detected one of the several types of double data

rate (DDR) memory errors. Single bit errors are corrected, but other errors indicate either software

errors or problems with the target system DRAM. Single bit errors can be expected to occur infrequently and can be caused by uncontrollable external events like cosmic rays, but frequent single

bit errors can be indications of a degrading DRAM device.

Recommended Frequent single bit errors and all other error types should be reported to technical support for further

Action action.

6.25 EM Messages

EM-1001

Message <FRU ID> is shutting down due to environmental limits.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the specified field-replaceable unit (FRU) is shutting down because it exceeded an

environmental policy threshold or limit. This event is typically a result of the FRU exceeding allowable

operational thermal ranges or as a result of component failures.

Recommended

Action

Verify that the location temperature is within the operational range of the switch. Refer to the *hardware*

reference manual for the environmental temperature range of your switch.

Execute the fanShow command to verify that all fans are running at normal speeds. If any fans are

missing or not performing at a high enough speed, they should be replaced.

Refer to the hardware reference manual for more information about the operational environmental

limits and related policies.

EM-1002

Message System fan(s) status <fan FRU>.

Message Type LOG | FFDC

Severity INFO

Probable Cause Indicates that a nonbladed system has overheated and may shut down. All fan speeds are dumped to

the console.

Recommended

Action

Verify that the location temperature is within the operational range of the switch. Refer to the *hardware*

reference manual for the environmental temperature range of your switch.

Execute the fanShow command to verify that all fans are running at normal speeds. If any fans are

missing or are not performing at a high enough speed, they should be replaced.

EM-1003

Message <FRU ID> has unknown hardware identifier: FRU faulted.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that a field-replaceable unit (FRU) header could not be read or is not valid. The FRU is

faulted.

Recommended

Action

Execute the **diagPost** command to ensure that the power-on self-test (POST) is enabled; then power-cycle the blade by using the **slotPowerOff** and **slotPowerOn** commands or have the blade's ejector switch cycled to run the POST and verify that the blade does not have any hardware problems.

For the Brocade 300 and 6510, replace the switch.

EM-1004

Message <FRU ID> failed to power on.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the specified field-replaceable unit (FRU) failed to power on and is not being used.

The FRU ID value is composed of an FRU type string and an optional number to identify the unit, slot,

or port.

The Brocade 300 Switch has four fans and one power supply, but these parts cannot be replaced: the

entire switch is an FRU.

Recommended

Action

Reseat the FRU. If the problem persists, replace the FRU.

EM-1005

Message <FRU Id> has faulted. Sensor(s) above maximum limits.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that a blade in the specified slot or the switch (for nonbladed switches) is shut down for

environmental reasons; its temperature or voltage is out of range.

Recommended

Action

Check the environment and ensure the room temperature is within the operational range of the switch. Execute the **fanShow** command to verify that the fans are operating properly. Ensure that there are no

blockages of the airflow around the chassis. If the temperature problem is isolated to the blade itself,

replace the blade.

Voltage problems on a blade are likely a hardware problem on the blade itself; replace the blade.

EM-1006

Message <FRU Id> has faulted. Sensor(s) below minimum limits.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the voltage on the switch is below minimum limits. The switch or specified blade is being

shut down for environmental reasons; the voltage is too low.

Recommended

Action

If this problem occurs on a blade, it usually indicates a hardware problem on the blade; replace the blade.

If this problem occurs on a switch, it usually indicates a hardware problem on the main board; replace the switch.

EM-1008

Message Unit in <Slot number or Switch> with ID <FRU Id> is faulted, it is incompatible with

the <type of incompatibility> configuration, check FOS firmware version as a possible

cause.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that a blade inserted in the specified slot or switch (for nonbladed switches) is not compatible

with the platform configuration (includes the firmware version) or the switch configuration. The blade is

faulted.

Recommended If the blade is incompatible, upgrade the firmware or replace the blade and ensure that the

Action replacement blade is compatible with your control processor (CP) type and firmware.

If the incompatibility is with the logical switch configuration, change the configuration by using the

Iscfg command to be consistent with the blade type, or remove the blade.

EM-1009

Message <FRU Id> powered down unexpectedly.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the environmental monitor (EM) received an unexpected power-down notification from

the specified field-replaceable unit (FRU). This may indicate a hardware malfunction in the FRU.

Recommended Reseat the FRU. If the problem persists, replace the FRU.

Action

EM-1010

Message Received unexpected power down for <FRU Id> But <FRU Id> still has power.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the environmental monitor (EM) received an unexpected power-down notification from

the specified field-replaceable unit (FRU). However, the specified FRU still appears to be powered up

after four seconds.

Recommended

Action

Reseat the blade. If the problem persists, replace the blade.

EM-1011

Message Received unexpected power down for <FRU Id>, but cannot determine if it has power.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the environmental monitor (EM) received an unexpected power-down notification from

the specified field-replaceable unit (FRU). However, after four seconds, it cannot be determined if it

has powered down or not.

Recommended Action Reseat the blade. If the problem persists, replace the blade.

EM-1012

Message <FRU Id> failed <state> state transition, unit faulted.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that a switch blade or nonbladed switch failed to transition from one state to another. It is

faulted. The specific failed target state is displayed in the message. There are serious internal Fabric

OS configuration or hardware problems on the switch.

Recommended Action Reseat the specified field-replaceable unit (FRU).

If the problem persists, restart or power cycle the switch.

Execute the **diagPost** command to make sure that power-on self-test (POST) is enabled; then power-cycle the blade by using the **slotPowerOff** and **slotPowerOn** commands or have the blade's ejector

switch cycled to run POST and verify that the blade does not have any hardware problems.

If the problem still persists, replace the FRU.

EM-1013

Message Failed to update FRU information for <FRU Id>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the environmental monitor (EM) was unable to update the time alive or original

equipment manufacturer (OEM) data in the memory of a field-replaceable unit (FRU).

Recommended

If you executed the **fruInfoSet** command, execute the command again; otherwise, the update is

automatically attempted again. If it continues to fail, reseat the FRU.

If the problem persists, replace the FRU.

EM-1014

Message Unable to read sensor on <FRU Id> (<Return code>).

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the environmental monitor (EM) was unable to access the sensors on the specified field-

replaceable unit (FRU).

Recommended Reseat the F

Action

Reseat the FRU. If the problem persists, replace the FRU.

EM-1015

Message Warm recovery failed (<Return code>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that a problem was discovered when performing consistency checks during a warm boot.

Recommended Monitor the switch. If the problem persists, restart or power-cycle the switch.

Action

EM-1016

Message Cold recovery failed (<Return code>).

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that a problem was discovered when performing consistency checks during a cold boot.

Recommended Monitor the switch.

If the problem persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

EM-1017

Message Uncommitted WWN change detected. Cold reboot required.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a user did not commit a changed World Wide Name (WWN) value before performing a

system restart, power cycle, or firmware download operation.

Recommended Change and commit the new WWN value.

Action

EM-1018

Message CP blade in slot <slot number> failed to retrieve current chassis type (<return code>/

<error code>/0x<unit number>).

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that there was a failure to read the chassis type from the system.

Recommended Verify that the control processor (CP) blade is operational and is properly seated in its slot.

Action

EM-1019

Message Current chassis configuration option (<Chassis config option currently in effect>)

is not compatible with standby firmware version (Pre 4.4), cannot allow HA Sync.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the current chassis configuration option is not supported by the firmware on the standby

control processor (CP). This is true even if the standby CP comes up and is operational. High

availability (HA) synchronization of the CPs will not be allowed.

Recommended Change the chassis configuration option to 1 using the chassisConfig command, or upgrade the

Action firmware on the standby CP to the version running on the active CP.

EM-1020

Message Unit in <Slot number> with ID <FRU Id> is faulted, it's an FCoE blade and the Ethernet

switch service is not enabled. Please run <fosconfig --enable ethsw>.

Message Type FFDC | LOG

Severity ERROR

Probable Cause Indicates that a blade inserted in the specified slot requires the Ethernet switch service, which is not

enabled. The blade is faulted.

Recommended Action Execute the **fosconfig --enable ethsw** command to enable the Ethernet switch service. Note that this is a disruptive command, which requires the system to be restarted. Otherwise, remove the blade.

EM-1028

Message HIL Error: <function> failed to access history log for FRU: <FRU Id> (rc=<return

code>).

Message Type FFDC | LOG

Severity WARNING

Probable Cause Indicates a problem accessing the data on the World Wide Name (WWN) card field-replaceable unit

(FRU) or on the WWN card storage area on the main logic board.

The problems were encountered when the software attempted to write to the history log storage to record an event for the specified FRU. The return code is for internal use only. This can indicate a

significant hardware problem.

The FRU ID value is composed of an FRU type string and an optional number to identify the unit, slot,

or port.

Recommended If the problem persists, restart or power-cycle the switch.

Action

If the problem still persists, replace the WWN card, or the switch (for nonbladed switches).

EM-1029

Message <FRU Id>, a problem occurred accessing a device on the I2C bus (<error code>).

Operational status (<state of the FRU when the error occurred>) not changed, access

is being retried.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that the Inter-Integrated Circuit (I2C) bus had problems and a timeout occurred.

Recommended This is often a transient error.

Watch for the EM-1048 message, which indicates that the problem has been resolved.

If the problem persists, check for loose or dirty connections. Remove all dust and debris before

reseating the field-replaceable unit (FRU). If it continues to fail, replace the FRU.

EM-1031

Message <FRU Id> ejector not closed.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the environmental monitor (EM) has found a switch blade that is inserted, but at least

one ejector switch is not latched. The blade in the specified slot is treated as not inserted.

Recommended

Action

Close the ejector switch (raise the slider in most blades or completely screw in the upper thumbscrew) if the field-replaceable unit (FRU) is intended for use. Refer to the appropriate *hardware reference*

manual for instructions on inserting the switch blades.

EM-1033

Message CP in <FRU Id> set to faulty because CP ERROR asserted.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the standby control processor (CP) has been detected as faulty. The high availability

(HA) feature will not be available. This message occurs every time the other CP restarts, even as part of a clean warm failover. In most situations, this message is followed by the EM-1047 message, and

no action is required for the standby CP; however, find the reason for the failover.

Recommended

Action

If the standby CP was restarted, wait for the error to clear (execute the **slotShow** command to determine if it has cleared). Watch for the EM-1047 message to verify that this error has cleared.

If the standby CP continues to be faulty or if it was not intentionally restarted, check the error logs on the other CP (using the **errDump** command) to determine the cause of the error state.

Reseat the field-replaceable unit (FRU). If the problem persists, replace the FRU.

EM-1034

Message <FRU Id> set to faulty, rc=<return code>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified field-replaceable unit (FRU) has been marked as faulty for the specified

reason.

Recommended

Reseat the FRU.

Action

Execute the **diagPost** command to ensure that power-on self-test (POST) is enabled; then power-cycle the blade by using the **slotPowerOff** and **slotPowerOn** commands or have the blade's ejector switch cycled to run the POST and verify that the blade does not have any hardware problems.

If the problem persists, replace the FRU.

EM-1035

Message 2 circuit paired Power Supplies are faulty, please check the <Switch side> AC main

switch/circuit to see if it has power.

Message Type LOG

Severity ERROR

Probable Cause

Indicates that both power supplies associated with one of the two main circuits are present but faulty, that the circuit's switch may have been turned off, or that the AC power source has been interrupted for that circuit.

The *switch side* value designates the circuit switch facing the cable side of the chassis, and is one of the following values:

- left Controls the odd-numbered power supply units.
- right Controls the even-numbered power supply units.

Recommended Action Verify that the identified AC circuit switch is turned on, that the power cord is properly attached and undamaged, and that the power source is operating properly.

EM-1036

Message <FRU Id> is not accessible.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified field-replaceable unit (FRU) is not present on the switch.

If the FRU is a World Wide Name (WWN) card, the default WWN and IP addresses are used for the

switch.

Recommended

Action

Reseat the FRU.

If the problem persists, restart or power-cycle the switch.

Execute the **diagPost** command to ensure that power-on self-test (POST) is enabled; then power-cycle the blade by using the **slotPowerOff** and **slotPowerOn** commands or have the blade's ejector switch cycled to run the POST and verify that the blade does not have any hardware problems.

If the problem still persists, replace the FRU.

EM-1037

Message <FRU Id> is Ok.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified power supply is OK and no longer marked faulty; probably because its AC

power supply has been turned on.

EM-1042

Message Important FRU header data for <FRU Id> is not valid.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified field-replaceable unit (FRU) has an incorrect number of sensors in its FRU

header-derived information. This could mean that the FRU header was corrupted or read incorrectly, or

corrupted in the object database, which contains information about all FRUs.

Recommended

Action

Reseat the FRU. If the problem persists, replace the FRU.

EM-1043

Message Can't power <FRU Id> <state (on or off)>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified field-replaceable unit (FRU) cannot be powered on or off.

Recommended The specified FRU is not responding to the commands and should be replaced.

Action

EM-1044

Message Can't power on <FRU Id>, its logical switch is shut down.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified field-replaceable unit (FRU) cannot be powered on because the associated

logical switch is shut down.

Recommended Execute the **switchStart** command on the associated logical switch.

Action

EM-1045

Message <FRU Id> is being powered <new state>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that an a

Indicates that an automatic power adjustment is being made because of the (predicted) failure of a power supply or the insertion or removal of a port blade. The *new state* value can be one of the following values:

- On A port blade is being powered on because the power is available (a power supply was inserted or a port blade was removed or powered down).
- Off A port blade has been powered down because of the (predicted) failure of the power supply.
- Down A newly inserted port blade was not powered on because there was not enough power available.

Recommended Action For a fully populated chassis, you must always operate the system with at least two power supplies for redundancy.

EM-1046

Message

Error status received for blade ID <id value> for the blade in slot <slot number>, <blade incompatibility type: platform, backplane, or switch configuration>.

Message Type

LOG

Severity

WARNING

Probable Cause

Indicates that the specified blade is incompatible.

Recommended

Action

If the listed blade ID is incorrect, the field-replaceable unit (FRU) header for the blade is corrupted and the blade must be replaced.

If the error is due to the platform, the listed blade ID is not supported for that platform (CP) type.

Remove the blade from the chassis.

If the error is due to the backplane, the CP type (CP256) is not supported on that chassis (backplane revision D2). Remove the blade from the chassis.

If the error is due to the switch configuration, the logical switch configuration of the blade is incorrect. Execute the **lscfg** command to correct the switch or port configuration for the ports on the blade.

EM-1047

Message CP in slot <slot number> not faulty, CP ERROR deasserted.

Message Type LOG

Severity INFO

Probable Cause

Indicates that the control processor (CP) is no longer faulted. This message usually follows the EM-1033 message. The new standby CP is in the process of restarting and has turned off the CP_ERR signal.

EM-1048

Message <FRU Id> I2C access recovered: state <current state>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the Inter-Integrated Circuit (I2C) bus problems have been resolved and I2C access to

the field-replaceable unit (FRU) has become available again.

Recommended

Action

No action is required. The EM-1048 message is displayed when the EM-1029 error is resolved.

EM-1049

Message FRU <FRU Id> insertion detected.

Message Type LOG

Severity INFO

Probable Cause Indicates that a field-replaceable unit (FRU) of the type and location specified by the FRU ID value was

detected as having been inserted into the chassis.

EM-1050

Message FRU <FRU Id> removal detected.

Message Type LOG

Severity INFO

Probable Cause Indicates that a field-replaceable unit (FRU) of the type and location specified by the FRU ID value was

removed from the chassis.

Recommended Verify that the FRU was intended to be removed. If not, replace the FRU as soon as possible.

Action

EM-1051

Message <FRU Id>: Inconsistency detected, FRU reinitialized.

Message Type LOG

Severity INFO

Probable Cause Indicates that an inconsistent state was found in the field-replaceable unit (FRU). This occurs if the

state of the FRU was changing during a failover. The FRU is reinitialized, and the traffic may have

been disrupted.

EM-1057

Message Blade: <Slot Id> is getting reset: <Fault reason>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the blade is being automatically reset because of known resetable transient errors such

as an ASIC parity error.

Recommended No action is required if the switch does not reach the reset threshold for the switch or blade. If the reset

Action

threshold is reached on the switch or blade, the switch or blade will be faulted and should be replaced.

EM-1058

Message Switch gets reset: < Fault reason >.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the switch is being automatically reset because of a known resetable transient problem

such as an ASIC parity error.

Recommended No action is required if the switch does not reach the reset threshold for the switch or blade. If the reset

threshold is reached on the switch or blade, the switch or blade will be faulted and should be replaced.

EM-1059

Message <Slot number or Switch> with ID <Blade Id> may not be supported on this platform,

check FOS firmware version as a possible cause.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that a a blade inserted in the specified slot or switch (for nonbladed switches) is incompatible

with the switch configuration software. The blade will not be completely usable.

The blade may be supported only by a later (or earlier) version of the firmware.

Recommended Change the control processor (CP) firmware or replace the blade. Ensure the replacement is

Action compatible with your switch type and firmware.

EM-1060

Message Stopping synchronization of the system due to blade incompatibility with software

version on standby CP.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a blade in the system is not supported by the firmware on the standby control processor

(CP).

Recommended Remove all blades of this type or upgrade the standby CP. After appropriate action is taken, restart the

Action standby CP or execute the haSyncStart command to enable high availability (HA) state

synchronization. Until this is done, the system will remain out of synchronization.

EM-1061

Message Synchronization halted. Remove all blades of type <Blade Type Id> or upgrade your

standby CP, then reboot or run haSyncStart.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the blade in the system is not supported by the firmware on the standby control

processor (CP).

Recommended Remove all blades of the specified type or upgrade the standby CP. After appropriate action is taken,

restart the standby CP or execute the haSyncStart command to enable high availability (HA) state

synchronization. Until this is done, the system will remain out of synchronization.

EM-1062

Message Blade in slot <Slot Id> faulted as it exceeds the maximum support limit of <Limit>

blades with Blade ID <Blade Type Id> in the chassis.

Message Type LOG

Action

Severity CRITICAL

Probable Cause Indicates that too many blades of a particular type are in the system.

Recommended Remove the faulted blade.

Action

EM-1063

Message Blade in slot <Slot Id> faulted because it exceeds the maximum support limit of

<Limit> blades with Blade IDs <Applicable blade Type IDs> in the chassis.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that too many blades of a set of particular types are in the system.

Recommended Remove the faulted blade.

Action

EM-1064

Message Blade: < Slot Id > is being powered off (based on user configuration) upon receiving a

HW ASIC ERROR, reason: <Fault reason>.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the blade is being powered off because a hardware (HW) ASIC error was detected and

that you have selected to power off the problem blade when such a condition occurred.

Recommended Action Contact your switch service provider for assistance.

EM-1065

Message SAS Virtualization Services are not available due to incompatibility between the FOS

and SAS versions<Slot number or blank for single board systems>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the version of the control processor firmware (CFOS) or blade processor firmware

(BFOS) is not compatible with the Storage Application Services (SAS) or other application firmware

versions.

Recommended Upgrade the Fabric OS firmware or the SAS firmware by using the **firmwareDownload** command.

Refer to the release notes for a compatible version of firmware.

EM-1066

Message SAS Virtualization Services are now available <Slot number or blank for single board

systems>.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the previously incompatible Fabric OS or Storage Application Services (SAS) firmware

has been upgraded and is now compatible.

EM-1067

Message Stopping synchronization of the system due to <version> incompatibility with standby

CP.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the software version on the standby control processor (CP) is incompatible with the

software feature enabled on this Fabric OS firmware version.

Recommended Upgrade the software on the standby CP or disable the software feature on this CP.

Action

To disable the Ethernet switch service, execute the **fosconfig --disable ethsw** command.

To view the buffer optimization mode for the slots, execute the bufopmod --showall command, and

then execute the **bufopmode** --resets/ot command to disable the feature for those slots before downgrading.

To disable FC8-16 Serdes tuning mode, execute the **serdestunemode --reset** command.

EM-1068

Message High Availability Service Management subsystem failed to respond. A required

component is not operating.

Message Type FFDC | LOG

Severity ERROR

Probable Cause Indicates that the high availability (HA) subsystem has not returned a response within four minutes of

the request from the environmental monitor (EM). It usually indicates that some component has not started properly or has terminated. The specific component that has failed may be indicated in other messages or debug data. There are serious internal Fabric OS configuration or hardware problems on

the switch.

Recommended

Restart or power-cycle the switch.

Action

If the problem persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

EM-1069

Message Slot <FRU slot number> is being powered off.

Message Type LOG

Severity INFO

Probable Cause Indicates that the blade in the specified slot is being intentionally powered off.

EM-1070

Message Slot <FRU slot number> is being powered on.

Message Type LOG

Severity INFO

Probable Cause Indicates that the blade in the specified slot is being intentionally powered on.

EM-1071

Message Unit in <Slot number> with ID <FRU Id> is faulted, it is incompatible with the

following blade id(s): <blade incompatibility list>.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that a blade inserted in the specified slot is incompatible with another blade in the system.

Recommended Determine which blade is essential to your configuration and remove blades that are incompatible with Action if

EM-1072

Message Chassis cannot become ready since no Core Blades are available.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that all core blades are missing, faulted, or powered off. There must be at least one core

blade in the enabled state for the chassis to be considered ready.

Recommended Insert and close the ejector switch on missing core blades. Reseat or replace core blades that are

Action faulted or powered off.

EM-1073

Message Blade devices cannot be accessed. The blade in slot <FRU slot number> is being moved

to ABSENT state.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the devices on the blade were not accessible. The blade is being transitioned to the

ABSENT state.

Recommended Reseat or replace the affected blade.

Action

EM-1074

Message The ASIC in <FRU ID> is overheating: Shutting down.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the ASIC present in switch is overheating and is beyond the thermal operating range.

This event is typically due to a faulty fan and can also be caused by the switch environment.

Recommended Verify that the location temperature is within the operational range of the switch. Refer to the *hardware*

Action reference manual for the environmental temperature range of your switch.

Execute the **fanShow** command to verify that all fans are running at normal speeds. If any fans are missing or not performing at a high enough speed, they should be replaced.

EM-1075

Message <FRU Id> poweron was attempted while it was being powered off. The slot will remain

powered off.

Message Type LOG

Severity WARNING

Probable Cause The previous slot poweroff is yet to be completed and hence cannot process poweron of the slot. So

the slot remains to be powered off. Wait till the slot poweroff process is complete.

Recommended Wait till the slot poweroff process is complete

Action

EM-1100

Message Unit in <Slot number or Switch> with ID <FRU Id> is faulted(<Fault>). <Current attempt

number> of <Total number of attempts> total attempt(s) at auto-recovery is being made.

Delay is <Delay time in seconds> seconds.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause A fault that has been determined to be auto-recoverable has happened and recovery is being

attempted.

Recommended If auto-recovery does not happen gracefully within a reasonable time frame, follow the user guide to

Action recover the blade.

EM-1101

Message Unit in <Slot number or Switch> with ID <FRU Id> is faulted(<Fault>). <Current attempt

number> attempt(s) at auto-recovery were made without success.

Message Type LOG

Severity CRITICAL

Probable Cause A fault that has been determined to be auto-recoverable has happened, but recovery failed.

Recommended Follow the user guide to recover the blade.

Action

EM-1134

Message <FRU Id> set to faulty, rc=<return code>.

Message Type LOG | FFDC

Severity ERROR

Probable Cause Indicates that the specified field-replaceable unit (FRU) has been marked as faulty for the specified

reason.

Recommended Reseat the FRU.

Action

Execute the **diagPost** command to ensure that power-on self-test (POST) is enabled; then power-cycle the blade by using the **slotPowerOff** and **slotPowerOn** commands or have the blade's ejector switch cycled to run the POST and verify that the blade does not have any hardware problems.

If the problem persists, replace the FRU.

EM-1220

Message A problem (Error: <The return code is for internal use only>) has been detected on one

or both WWN cards. Please run the wwnrecover tool to get more information and recovery

options.

Message Type LOG

Severity ERROR

Probable Cause Indicates that a problem was found accessing one (or both) of the WWN cards or with the content of

the data stored there. The content problem could be a corrupted data set or a mismatch between the

two WWN cards.

Recommended

Action

Execute the wwnrecover command to get details of the problems found and how to recover.

EM-1221

Message A WWN card insertion has been detected. WWN verification audit will be run to ensure

no mismatches or other problems.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the second WWN card was enabled. Because the data may not match, the WWN

verification audit will be run.

Recommended If an EM-1220 follows, execute the wwnrecover command to get details of the problems found and

how to recover. If an EM-1220 message does not follow, no action is required.

EM-1222

Message A WWN card access problem has been encountered. Please run the wwnrecover tool to get

more information and recovery options.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a problem was encountered while accessing one (or both) of the WWN cards or with the

content of the data stored there.

Recommended Execute the **wwnrecover** command to get details of the problems found and how to recover.

Action

EM-1223

Message Slot <FRU slot number> has been powered on.

Message Type AUDIT | LOG

Class CLI

Severity INFO

Probable Cause Indicates that the blade in the specified slot is being intentionally powered on.

EM-1224

Message Slot <FRU slot number> has been powered off.

Message Type AUDIT

Class CLI

Severity INFO

Probable Cause Indicates that the blade in the specified slot is being intentionally powered off.

EM-1225

Message Slot <FRU slot number> has been persistently powered off.

Message Type AUDIT

Class CLI

Severity INFO

Probable Cause Indicates that the blade in the specified slot is being intentionally powered off.

EM-1226

Message Fan-<Fan unit number> has been <Enable config>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified fan unit is being enabled/disabled.

EM-1227

Message Slot <FRU slot number> is being powered off as it was detected as faulty during

previous INIT.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the blade was detected as faulty in a previous reboot and that it is being intentionally

powered off.

Recommended Contact switch vendor or remove the faulty blade and run the slotpoweron command on the new

Action blade.

EM-1228

Message <FRU Id> sensor 0x<Sensor Code> value out of range: <Raw Sensor Value>/<Retry Count>:

Excessive power consumption detected. Power down and replace this switch

Message Type LOG

Severity CRITICAL

Probable Cause The brocade 6520 is consuming excessive power.

Recommended Power down and replace this switch.

Action

EM-1229

Message Excessive power usage (<Total Power Consumed >W) detected (PS1=<PS 1 Power Consumed

>W, PS2=<PS 2 Power Consumed >W). Monitor closely and power down/replace switch if

this persists

Message Type LOG

Severity CRITICAL

Probable Cause This Switch is reporting excessive power power consumption.

Recommended Action This may be a spurious occurrence. Please monitor the switch closely. If this persists then power down and replace this switch.

EM-1230

Message

Excessive power usage (<Total Power Consumed >W) detected (PS1=<PS 1 Power Consumed >W, PS2=<PS 2 Power Consumed >W). System is shutting down. Please replace switch if this persists

Message Type LOG

Severity CRITICAL

Probable Cause This Switch is reporting excessive power power consumption.

Recommended This may be a spurious occurrence. Switch is being shutdown. If this persists following powering back up, then replace this switch.

EM-2003

Message <Slot Id or Switch> has failed the POST tests. FRU is being faulted.

Message Type LOG

Severity ERROR

Probable Cause

Indicates that a field-replaceable unit (FRU) has failed the power-on self-test (POST). Refer to the / tmp/post[1/2].slot#.log file for more information on the faults. To view this log file, you must be logged in at the root level. The ID will be Switch for nonbladed systems.

Recommended Action On bladed systems, reseat the specified FRU.

On nonbladed switches, restart or power-cycle the switch.

If the problem persists, perform the following actions:

- Execute the **diagPost** command to ensure that power-on self-test (POST) is enabled; then power-cycle the blade by using the **slotPowerOff** and **slotPowerOn** commands or have the blade's ejector switch cycled to run the POST and verify that the blade does not have any hardware problems.
- On bladed systems, replace the specified FRU; otherwise, replace the switch.

EM-2004

Message <FRU id>

Message Type LOG

Severity WARNING

Probable Cause Indicates that the user has set the blade to persistently disable mode.

6.26 ERCP Messages

ERCP-1000

Message Multiple DDR ECC errors are detected and the system will reload automatically.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that error checking and correction (ECC) errors occurred due to multi-bit corruption.

Recommended No action is required. The system will reload automatically to recover from the error.

Action

ERCP-1001

Message Multiple CCF ECC errors are detected and the system will reload automatically.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that error checking and correction (ECC) errors occurred due to multi-bit corruption.

Recommended No action is required. The system will reload automatically to recover from the error.

Action

ERCP-1002

Message Multiple CPC ECC errors are detected and the system will reload automatically.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that error checking and correction (ECC) errors occurred due to multi-bit corruption.

Recommended

Action No action is required. The system will reload automatically to recover from the error.

6.27 ESM Messages

ESM-1000

Message ESMd <Module Name> initialization complete rc:<Return Code>.

Message Type LOG

Severity INFO

Probable Cause Indicates that ESMd module initialization phase has completed.

ESM-1001

Message ESMd <Module Name> uninitialization complete rc:<Return Code>.

Message Type LOG

Severity INFO

Probable Cause Indicates that ESMd module uninitialization phase has completed.

ESM-1002

Message ESMd initialization done for service <Service Name>:<Instance Number>.

Message Type LOG

Severity INFO

Probable Cause Indicates that ESMd service has initialized.

ESM-1003

Message ESMd uninitialization called for service <Service Name>:<Instance Number>.

Message Type LOG

Severity INFO

Probable Cause Indicates that ESMd service uninitialization phase has completed.

ESM-1004

Message ESMd failed to initialize <Module Name> rc:<Return Code>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified module has failed to initialize.

Recommended If the message persists, execute the supportFtp command (as needed) to set up automatic FTP

Action transfers; then execute the **supportSave** command and contact your switch service provider.

ESM-1005

Message Configuration (<Configuration>) replay failed - <Failure Reason>.

Message Type LOG

Severity ERROR

Probable Cause Indicates the specified configuration failed to be reapplied during config replay.

Recommended Use the portCfg, portShow, and portCfgShow commands to correct the cause of the failure.

Action

ESM-1010

Message DP<DP ID> is OFFLINE.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified Data Processor (DP) has went offline.

Recommended If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

Action transfers; then execute the **supportSave** command and contact your switch service provider.

ESM-1011

Message DP<DP ID> is ONLINE.

Message Type LOG

Severity INFO

Probable Cause Indicates that specified Data Processor (DP) has come online.

ESM-1012

Message DP<DP ID> Configuration replay has started.

Message Type LOG

Severity INFO

Indicates that Data Processor (DP) configuration replay has started. **Probable Cause**

ESM-1013

Message DP<DP ID> Configuration replay has completed.

Message Type LOG

> Severity INFO

Probable Cause Indicates that Data Processor (DP) configuration replay has completed.

ESM-1100

Message <Warning message string.>

Message Type LOG

> Severity WARNING

Probable Cause Internal warning occurred as indicated by the warning message.

Recommended If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP Action

transfers; then execute the supportSave command and contact your switch service provider.

ESM-1101

Message <Error message string.>

Message Type LOG

> **ERROR** Severity

Probable Cause Internal error occurred as indicated by the error message.

Recommended If the message persists, execute the supportFtp command (as needed) to set up automatic FTP

Action transfers; then execute the supportSave command and contact your switch service provider.

ESM-1102

Message Unable to post DP<DP ID> ras evt:0x<Event ID> siq:<Event Signature> recv ver:0x<Event

Version> due to CP/DP code mismatch.

Message Type LOG

> Severity INFO

Probable Cause Indicates a different version in Remote Access Service (RAS) event message due to mismatch

between the control processor (CP) and data processor (DP) versions.

Recommended

Action

This is normal during extension Hot Code Load (HCL) and can be ignored if seen during the extension HCL process. If the message persists or is seen when not performing an extension HCL, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

ESM-1103

Message Extension configurations for <Slot> have all been cleared.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates all extension configurations for slot(s) have been cleared.

ESM-1104

Message Extension configuration default for <Slot> completed.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates extension configurations for slot(s) have been reset to defaults.

ESM-1105

Message <Type of stats> reset completed.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that reset has completed.

ESM-2000

Message IP Interface <GE Port>.dp<DP ID> created <Address>/<Mask> vlan: <Vlan ID> mtu: <MTU>

[<Originator>].

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the specified IP interface has been added.

ESM-2001

Message IP Interface <GE Port>.dp<DP ID> deleted <Address>/<Mask> [<Originator>].

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the specified IP interface has been removed.

ESM-2002

Message IP Interface <GE Port>.dp<DP ID> modified: <Address>/<Mask> vlan: <Vlan ID> mtu: <MTU>

[<Originator>].

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the specified IP interface has been modified.

ESM-2010

gate:<gateway address> [<Originator>].

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the specified IP route has been created.

ESM-2011

gate:<gateway address> [<Originator>].

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the specified IP route has been deleted.

ESM-2012

Message IProute <GE Port>.dp<DP ID> modified dest:<destination address>/<dest address prefix>

gate:<gateway address> [<Originator>].

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the specified IP route has been modified.

ESM-2100

Message VE tunnel <VE-Port> created [<Originator>].

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the specified VE tunnel has been created.

ESM-2101

Message VE tunnel <VE-Port> deleted [<Originator>].

Message Type AUDIT | LOG

Class CFG

Severity INFO

ESM-2102

Message VE Tunnel <VE-Port> modified [<Originator>].

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the specified VE Tunnel has been modified.

ESM-2103

Message VE Tunnel < VE-Port > MODATTR (< Attribute change description >).

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that an attribute has been changed for the specified VE Tunnel.

ESM-2104

Message VE Tunnel <VE-Port> is OFFLINE.

Message Type LOG

Severity INFO

Probable Cause Indicates that the operational status of the specified tunnel is offline.

Recommended If the tunnel is not administratively down, a network error or disruption may have occurred.

Action

ESM-2105

Message VE Tunnel <VE-Port> is DEGRADED.

Message Type LOG

Severity INFO

Probable Cause Indicates that the operational status of the specified tunnel has degraded.

Recommended If the tunnel is not administratively down, a network error or disruption may have occurred.

Action

ESM-2106

Message VE Tunnel <VE-Port> is ONLINE.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified VE Tunnel is online.

ESM-2200

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the specified circuit has been created.

ESM-2201

Message VE Circuit <VE Port>.<Circuit ID> deleted [<Originator>].

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the specified circuit has been deleted.

ESM-2202

Message VE Circuit <VE Port>.<Circuit ID> modified [<Originator>].

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the specified circuit has been modified.

ESM-2203

Message VE Circuit <VE Port>.<Circuit ID> MODATTR (<Attribute change description>).

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates an attribute changed for the specified VE circuit.

ESM-2300

Message IPsec policy <Policy Name> added [<Originator>].

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the specified Internet Protocol security (IPsec) policy has been added.

ESM-2301

Message IPsec policy <Policy Name> deleted [<Originator>].

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the specified Internet Protocol security (IPsec) policy has been deleted.

ESM-2302

Message IPsec policy <Policy Name> modified [<Originator>].

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the specified Internet Protocol security (IPsec) policy has been modified.

ESM-2303

Message IPsec policy <Policy Name> MODATTR (<Attribute change description>).

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates an attribute changed for the specified Internet Protocol security (IPsec) policy.

ESM-2310

Message IKE Session Policy <IPSec Policy Name> dp<DP ID>.<IKE Session ID> created <Local IP

Address> - <Remote IP Address>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified Internet Key Exchange (IKE) session has been created for the specified

Internet Protocol security (IPsec) policy.

ESM-2311

Message IKE Session Policy <IPSec Policy Name> dp<DP ID>.<IKE Session ID> deleted <Local IP

Address> - <Remote IP Address>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified Internet Key Exchange (IKE) session has been deleted for the specified

Internet Protocol security (IPsec) policy.

ESM-2312

Message Continuous health check failed on DP<DP ID>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that Federal Information Processing Standards (FIPS) continuous health check failure is

detected by Internet Protocol Security (IPsec).

Recommended Execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the

supportSave command and contact your switch service provider.

ESM-2313

Message On-demand health check failed on DP<DP ID>.

Message Type LOG

Action

Action

Severity ERROR

Probable Cause Indicates that Federal Information Processing Standards (FIPS) on-demand health check failure is

detected by Internet Protocol Security (IPsec).

Recommended Execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the

supportSave command and contact your switch service provider.

ESM-2314

Message DP<DP ID> initiated data-plane zeroization.

Message Type LOG

Severity ERROR

Probable Cause Indicates that Federal Information Processing Standards (FIPS) failure is detected by Internet Protocol

Security (IPsec).

Recommended Execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the

Action **supportSave** command and contact your switch service provider.

ESM-2315

Message POST failure detected on DP<DP ID>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that Federal Information Processing Standards (FIPS) Power-On Self-Test (POST) failure is

detected by Internet Protocol Security (IPsec).

Recommended Execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the

Action **supportSave** command and contact your switch service provider.

ESM-2316

Message Running self test on DP<DP ID>.

Message Type LOG

Severity INFO

Probable Cause Indicates that Federal Information Processing Standards (FIPS) self test is being run on a data

processor (DP).

Recommended Execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the

supportSave command and contact your switch service provider.

ESM-2317

Message Extension IPSEC verify operation for Session: <Session ID> Peer

Certificate: <Certificate Name> failed.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the verify request from a data processor (DP) has failed on the control plane (CP).

Recommended Action Execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

ESM-2318

Message Extension IPSEC verify operation for Session: <Session ID> could not locate Peer

Certificate: < Certificate Name > .

Message Type LOG

Severity ERROR

Probable Cause Indicates that the verify request could not be serviced because the certificate was missing.

Recommended Execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the

Action **supportSave** command and contact your switch service provider.

ESM-2319

Message Extension IPSEC sign operation for Session: <Session ID> Keypair: <Keypair Name>

failed.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the sign request from a data processor (DP) has failed on the control plane (CP).

Recommended Execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the

Action **supportSave** command and contact your switch service provider.

ESM-2320

Message Extension IPSEC sign operation for Session: <Session ID> could not locate

Keypair: < Keypair Name > .

Message Type LOG

Severity ERROR

Probable Cause Indicates that the sign request could not be serviced because the keypair was missing or incomplete.

Recommended Execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the

Action **supportSave** command and contact your switch service provider.

ESM-2321

Message Extension IPSEC verify operation for Session: <Session ID> failed since Peer

Certificate: < Certificate Name > expired .

LOG Message Type

> Severity **ERROR**

Indicates that the verify request could not be serviced because the certificate has expired. Probable Cause

Recommended Execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the Action

supportSave command and contact your switch service provider.

ESM-2322

Message Extension IPSEC sign operation for Session: Session ID> failed since Keypair: Keypair

Name> certificate expired .

LOG Message Type

> Severity **ERROR**

Probable Cause Indicates that the sign request could not be serviced because the keypair was missing or incomplete.

Recommended Execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the Action

supportSave command and contact your switch service provider.

ESM-2323

Message IPSec Self test run failed on DP<DP ID>.

LOG Message Type

> Severity **INFO**

Probable Cause Indicates that Federal Information Processing Standards (FIPS) self test is failed on a data processor

Recommended Execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the

supportSave command and contact your switch service provider.

ESM-2324

Message Extension IPSEC verify operation for Session: <Session ID> found tampered Peer

Certificate: < Certificate Name > .

Message Type LOG

Action

ERROR Severity

Probable Cause Indicates that the verify request could not be serviced because the certificate was tampered.

Recommended Execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the

Action supportSave command and contact your switch service provider.

ESM-2325

Message Extension IPSEC sign operation for Session: <Session ID> found tampered

Keypair: < Keypair Name > .

Message Type LOG

Severity ERROR

Probable Cause Indicates that the sign request could not be serviced because the keypair was tampered.

Recommended Execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the

supportSave command and contact your switch service provider.

ESM-2326

Message Extension IPSEC verify operation for Session: <Session ID> found hash mismatch for

Peer Certificate: < Certificate Name > .

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the verify request could not be serviced because the certificate did not match.

Recommended Execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the

Action **supportSave** command and contact your switch service provider.

ESM-2327

Message Extension IPSEC sign operation for Session: <Session ID> found hash mismatch for

Keypair: < Keypair Name > .

Message Type LOG

Severity ERROR

Probable Cause Indicates that the sign request could not be serviced because the certificate did not match.

Recommended Execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the

Action **supportSave** command and contact your switch service provider.

ESM-2328

Message Extension IPsec Certificate: <Certificate Name> for Keypair: <Keypair Name> certificate

has expired .

Message Type LOG

Severity ERROR

Probable Cause Indicates that the Internet Protocol security (IPsec) certificate has expired.

Recommended Execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the

Action **supportSave** command and contact your switch service provider.

ESM-2329

Message Restart authentication for IKE sessions on IPsec policy <IPsec Policy Name>.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that IPsec policy has restarted authentication on all faulty IKE sessions.

ESM-2400

Message Blade configuration for slot <Slot> set to APP-Mode: <App-Mode> VE-Mode: <VE-Mode> GE-

Mode:<GE-Mode> [<Originator>].

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the blade configuration has been set to the specified App/VE/GE modes.

ESM-2700

Message TCL <TCL Name> created [<Originator>].

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that a Traffic Control List (TCL) has been created.

ESM-2701

Message TCL <TCL Name> Modified [<Originator>].

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that a Traffic Control List (TCL) has been modified.

ESM-2702

Message TCL <TCL Name> deleted [<Originator>].

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that a Traffic Control List (TCL) has been deleted.

ESM-2703

Message TCL <TCL Name> admin status changed [<TCL Admin status>].

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that a Traffic Control List (TCL) Internal admin status has changed.

ESM-2801

Message Port <Port Name> speed set to <Port Speed>, auto negotiation <Autonegotiation state>

[<App>].

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that a GiGE port speed and/or autonegotiation has changed.

ESM-2802

Message Port <Port Name> protocol is set to <FCIP/LAN> [<App>].

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that a GiGE port has been changed to FCIP/LAN.

ESM-2803

Message Port <Port Name> channel ID is set to <channel ID> [<App>].

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that a GiGE port channel id has changed.

ESM-3000

Message <Boot Stage> starting.

Message Type LOG

Severity INFO

Probable Cause Indicates the specific bootup recovery stage has started.

ESM-3001

Message <Boot Stage> complete.

Message Type LOG

Severity INFO

Probable Cause Indicates the specific bootup recovery stage has completed.

ESM-3002

Message DP<DP ID>-<HA Stage> starting.

Message Type LOG

Severity INFO

Probable Cause Indicates the specific HA recovery stage has started for the specified Data Processor (DP).

ESM-3003

Message DP<DP ID>-<HA Stage> ending: <Recovery Status>.

Message Type LOG

Severity INFO

Probable Cause Indicates the specific HA recovery stage has completed for the specified Data Processor (DP).

ESM-3004

Message DP<DP ID> VE-<HA Operation> Tunnel <VE Port> failed (<Reason>). Will retry.

Message Type LOG

Severity WARNING

Probable Cause Indicates the specific HA operation has failed for the specified VE port but will be retried later.

ESM-3005

Message DP<DP ID> VE-<HA Operation> Tunnel <VE Port> failed (<Reason>). Not retriable.

Message Type LOG

Severity ERROR

Probable Cause Indicates the specific HA operation has failed for the specified VE port and traffic will be disrupted on

this port.

ESM-3006

Message <Boot Stage> failed (<Reason>).

Message Type LOG

Severity ERROR

Probable Cause Indicates that a critical failure has occurred during the boot process..

Recommended If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

ESM-3007

Message DP<DP ID> VE Tunnel <VE Port> <HA Operation>.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates the status of the specified data processor (DP), virtual expansion (VE) port, and high

availability (HA).

ESM-3008

Message Standby CP has mismatched mode for slot <Slot>.

Message Type LOG

Severity ERROR

Probable Cause Indicates a synchronization problem between active and standby CPs for a blade mode configuration.

Recommended

Reboot the standby CP to synchronize the blade mode.

Action

6.28 ESS Messages

ESS-1001

Message A few switches in the fabric do not support the Coordinated HotCode protocol.

Message Type LOG

Severity WARNING

Probable Cause Indicates one or more switches in the fabric do not support the Coordinated HotCode protocol.

Continuing with the firmware download may cause data traffic disruption.

Recommended

Action

Discontinue the firmware download, identify the down-level switch or switches that do not support the Coordinated HotCode protocol, and upgrade the down-level switches. Then, restart the firmware

download on this switch. Note that upgrading a down-level Brocade switch in a mixed interop fabric

may still cause data traffic disruption.

ESS-1002

Message The pause message is rejected by the domain <domain id>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that during the Coordinated HotCode protocol, a switch in the fabric has rejected the pause

message which prevented the protocol from completing. Any data traffic disruption observed during

the firmware download may have been due to the rejected pause message.

ESS-1003

Message The pause retry count is exhausted for the domain <domain id>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that during the Coordinated HotCode protocol, a switch in the fabric did not accept the pause

message which prevented the protocol from completing. Any data traffic disruption observed during the firmware download may have been due to this issue.

ESS-1004

Message The resume message is rejected by the domain <domain id>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that during the Coordinated HotCode protocol, a switch in the fabric has rejected the resume

message which prevented the protocol from completing. Any data traffic disruption observed during

the firmware download may have been due to the rejected resume message.

ESS-1005

Message The resume retry count is exhausted for the domain <domain id>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that during the Coordinated HotCode protocol, a switch in the fabric did not accept the

resume message which prevented the protocol from completing. Any data traffic disruption observed

during the firmware download may have been due to this issue.

ESS-1008

Message Fabric Name - <fabric_name> configured (received from domain <domain id>).

Message Type AUDIT | LOG

Class FABRIC

Severity INFO

Probable Cause Indicates that the fabric name is configured or renamed.

ESS-1009

Message Fabric Name Mismatch - local(<fabric_name>) remote(<r_fabric_name> - received from

domain <domain id>).

Message Type AUDIT | LOG

Class FABRIC

Severity WARNING

Probable Cause Indicates that the specified fabric name is not unique for this fabric.

Recommended Select an appropriate fabric name and set it again from any switch.

Action

ESS-1010

Message Duplicate Fabric Name - <fabric name> matching with FID <Fabric ID>.

Message Type AUDIT | LOG

Class FABRIC

Severity WARNING

Probable Cause Indicates that the configured fabric name is already used for another partition.

Recommended Select a different fabric name and reconfigure.

Action

ESS-1011

Message Unable to retrieve local Fabric Name configuration. Remote name <r_fabric_name> from

domain <domain id>

Message Type AUDIT | LOG

Class FABRIC

Severity WARNING

Probable Cause Indicates that there has been a Fabric name configuration retrieval failure from local database which

has resulted in Fabric Name from the specified remote domain to be inherited.

Recommended Select an appropriate fabric name and set it again from local switch.

Action

ESS-2001

Message Fabric Hello Timeout: Inter-switch Frame Delivery problem - remote Switch Domain

<Remote Domain>, port <Port>.

Message Type LOG

Severity WARNING

Probable Cause Indicates failure to send or receive frames to the specified remote switch domain even after several

retry attempts. The following are the possible failure reasons:

7 - Routing Problem

■ 14 - Reliable Transmit With Response (RTWR) send failure

Recommended

Check the status of fabric and the specified remote switch domain.

Action

If the problem persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

ESS-2002

Message Recover from Fabric Hello Timeout - remote Switch domain <Remote Domain>, port <Port>,

failure cnt <Failure Count>.

Message Type LOG

Severity INFO

Probable Cause Indicates recovery from previously detected problem with sending frames to the specified remote

switch domain.

6.29 ESW Messages

ESW-1001

Message Switch is not in ready state - Switch enable failed, switch status= 0x<switch status>,

c flags = 0x<switch control flags>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the switch enable operation has failed.

Recommended If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

ESW-1002

Message Security violation: Unauthorized device <wwn name of device> tries to FLOGI to port

<port number>.

Message Type LOG

Action

Action

Severity INFO

Probable Cause Indicates that the specified device is not present in the authorized profile list.

Recommended Verify that the device is authorized to log in to the switch. If the device is authorized, execute the

secPolicyDump command to verify whether the World Wide Name (WWN) of the specified device is

listed. If it is not listed, execute the **secPolicyAdd** command to add this device to an existing policy.

ESW-1003

Message Slot ENABLED but Not Ready during recovery, disabling slot = <slot number>(<return

value>).

Message Type LOG

Severity ERROR

Probable Cause Indicates that the slot state has been detected as inconsistent during failover or recovery.

Recommended For a bladed switch, execute the slotPowerOff and slotPowerOn commands to power cycle the

Action blade.

For a non-bladed switch, restart or power cycle the switch.

ESW-1004

Message Blade attach failed during recovery, disabling slot = <slot number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified blade has failed during failover or recovery.

Recommended For a bladed switch, execute the **slotPowerOff** and **slotPowerOn** commands to power cycle the

Action blade.

For a non-bladed switch, restart or power cycle the switch.

ESW-1005

Message Diag attach failed during recovery, disabling slot = <slot number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the diagnostic blade attach operation has failed during failover or recovery.

Recommended For a bladed switch, execute the slotPowerOff and slotPowerOn commands to power cycle the

Action blade.

For a non-bladed switch, restart or power cycle the switch.

ESW-1006

Message HA state out of sync: Standby CP (ver = <standby SWC version>) does not support NPIV

functionality. (active ver = <active SWC version>, NPIV devices = <'1' if NPIV devices

exist; Otherwise '0'>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the standby control processor (CP) does not support N_Port ID Virtualization (NPIV)

functionality, but the switch has some NPIV devices logged in to the fabric.

Recommended Load a firmware version on the standby CP that supports NPIV functionality using the

Action **firmwareDownload** command.

ESW-1007

Message Switch port <port number> disabled due to \"<disable reason>\".

Message Type LOG

Severity WARNING

Probable Cause Indicates that the switch port is disabled due to the reason displayed in the message.

Recommended Based on the disable reason displayed, take appropriate action to restore the port.

Action

If the disable reason is "Insufficient frame buffers", reduce the distance or speed settings for the port to reduce the buffer requirement of the link. Alternatively, one or more ports in the port group must be

disabled to make more buffers available for the link.

Refer to the Fabric OS Administrator's Guide for more information.

ESW-1008

Message <area string> are port swapped on ports that do not support port swap. Slot <slot

number> will be faulted.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the blade is enabled with the port configuration that already has the area swapped.

Recommended Replace the blade with ports that support port swap. Then swap ports back to the port's default area.

Action Refer to the *Fabric OS Administrator's Guide* for more information.

6.30 EVMD Messages

EVMD-1001

Message Event could not be sent to remote proxy = <Remote proxy switch id>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the event could not be sent to remote proxy. This could happen if the remote proxy

switch cannot be reached through in-band.

Recommended Action

Make sure that the specified remote domain is present in the fabric.

6.31 FABR Messages

FABR-1001

Message port <port number>, <segmentation reason>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified switch port is isolated because of a segmentation resulting from

mismatched configuration parameters.

Recommended Based on the segmentation reason displayed with the message, look for a possible mismatch of

Action relevant configuration parameters in the switches at both ends of the link.

Run the configure command to modify the appropriate switch parameters on both the local and

remote switch.

FABR-1002

Message fabGaid: no free multicast alias IDs.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the fabric does not have any available multicast alias IDs to assign to the alias server.

Recommended Verify alias IDs using the **fabricShow** command on the principal switch.

Action

FABR-1003

Message port <port number>: ILS <command> bad size <payload size>, wanted <expected payload

size>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that an internal link service (ILS) information unit of invalid size has been received. The

neighbor switch has sent a payload with an invalid size.

Recommended Action

Investigate the neighbor switch for problems. Run the **errShow** command on the neighbor switch to view the error log for additional messages.

Check for a faulty cable or deteriorated small form-factor pluggable (SFP). Replace the cable or the SFP if necessary.

Run the portLogDumpPort command on both the receiving and transmitting ports.

Run the fabStatsShow command on both the receiving and transmitting switches.

If the message persists, run the **supportFtp** command (as needed) to set up automatic FTP transfers; then run the **supportSave** command and contact your switch service provider.

FABR-1004

Message

port: <port number>, req iu: 0x<address of IU request sent>, state: 0x<command sent>, resp iu: 0x<address of response IU received>, state 0x<response IU state>, <additional description>.

Message Type

LOG

Severity

WARNING

Probable Cause

Indicates that the information unit response was invalid for the specified command sent. The fabric received an unknown response. This message is rare and usually indicates a problem with the Fabric OS kernel.

Recommended Action If this message is due to a one-time event because of the incoming data, the system will discard the frame. If it is due to problems with the kernel, the system will recover by performing a failover.

If the message persists, run the **supportFtp** command (as needed) to set up automatic FTP transfers; then run the **supportSave** command and contact your switch service provider.

FABR-1005

Message

<command sent>: port <port number>: status 0x<reason for failure> (<description of failure reason>) xid = 0x<exchange ID of command>.

Message Type

LOG

Severity

WARNING

Probable Cause

Indicates that the application failed to send an async command for the specified port. The message provides additional details regarding the reason for the failure and the exchange ID of the command. This can happen if a port is about to go down.

Recommended

Action

This message is often transitory.

If the message persists, run the **supportFtp** command (as needed) to set up automatic FTP transfers; then run the **supportSave** command and contact your switch service provider.

FABR-1006

Message Node free error, caller: <error description>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Fabric OS is trying to free or deallocate memory space that has already been

deallocated. This message is rare and usually indicates a problem with the Fabric OS.

Recommended

Action

In case of severe memory corruption, the system may recover by performing an automatic failover.

If the message persists, run the ${\it supportFtp}$ command (as needed) to set up automatic FTP transfers;

then run the supportSave command and contact your switch service provider.

FABR-1007

Message IU free error, caller: <function attempting to de-allocate IU>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a failure occurred when deallocating an information unit. This message is rare and

usually indicates a problem with the Fabric OS.

Recommended

Action

In case of severe memory corruption, the system may recover by performing an automatic failover.

If the message persists, run the **supportFtp** command (as needed) to set up automatic FTP transfers;

then run the **supportSave** command and contact your switch service provider.

FABR-1008

Message <error description>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that errors occurred during the request domain ID state; the information unit cannot be

allocated or sent. If this message occurs with FABR-1005, the problem is usually transitory. Otherwise, this message is rare and usually indicates a problem with the Fabric OS. The error descriptions are as

follows:

FAB RDI: cannot allocate IUFAB RDI: cannot send IU

Recommended

If the message appears with the FABR-1005 message.

Action

If the message persists, run the **supportFtp** command (as needed) to set up automatic FTP transfers; then run the **supportSave** command and contact your switch service provider.

FABR-1009

Message <error description>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that errors were reported during the exchange fabric parameter state; cannot allocate

domain list due to a faulty exchange fabric parameter (EFP) type. This message is rare and usually

indicates a problem with the Fabric OS.

Recommended

Action

The fabric daemon will discard the EFP. The system will recover through the EFP retrial process.

If the message persists, run the **supportFtp** command (as needed) to set up automatic FTP transfers;

then run the **supportSave** command and contact your switch service provider.

FABR-1010

Message <error description>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that errors occurred while cleaning up the request domain ID (RDI). The error description

provides further details. This message is rare and usually indicates a problem with the Fabric OS.

Recommended

Action

If the message persists, run the **supportFtp** command (as needed) to set up automatic FTP transfers;

then run the **supportSave** command and contact your switch service provider.

FABR-1011

Message <error description>.

Message Type LOG | FFDC

Severity ERROR

Probable Cause Indicates that the Fabric OS is unable to inform the Fabric OS State Synchronization Management

module (FSSME) that the fabric is stable or unstable. This message is rare and usually indicates a

problem with the Fabric OS.

Recommended

Action

If the message persists, run the ${\it supportFtp}$ command (as needed) to set up automatic FTP transfers;

then run the **supportSave** command and contact your switch service provider.

FABR-1012

Message <function stream>: no such type, <invalid type>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the fabric is not in the appropriate state for the specified process. This message is rare

and usually indicates a problem with the Fabric OS.

Recommended The fabric daemon will take proper action to recover from the error.

Action

If the message persists, run the **supportFtp** command (as needed) to set up automatic FTP transfers;

then run the **supportSave** command and contact your switch service provider.

FABR-1013

Message No Memory: pid=<fabric process id> file=<source file name> line=<line number within

the source file>.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that there is not enough memory in the switch for the fabric module to allocate. This message

is rare and usually indicates a problem with the Fabric OS.

Recommended The system will recover by failing over to the standby CP.

Action

If the message persists, run the **supportFtp** command (as needed) to set up automatic FTP transfers;

then run the **supportSave** command and contact your switch service provider.

FABR-1014

Message Port <port number> Disabled: Insistent Domain ID < Domain ID > could not be obtained.

Principal Assigned Domain ID = <Domain ID>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified port received a request domain ID (RDI) accept message containing a

principal-switch-assigned domain ID that is different from the insistent domain ID (IDID). Fibre connectivity (FICON) mode requires an insistent domain ID. If an RDI response has a different domain

ID, then the port is disabled.

Recommended Run the **configShow** command to view the fabric ididmode. A 0 means the IDID mode is disabled; a 1

Action means it is enabled.

Set the switch to insistent domain ID mode. This mode is set under the **configure** command or in Web

Tools on the **Switch Admin > Configure** window.

FABR-1015

Message FICON Insistent DID max retry exceeded: All E_Ports will be disabled. Switch is

isolated.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the application exceeded request domain ID (RDI) requests for the insistent domain ID.

All E_Ports are disabled; isolating the specified switch from the fabric.

Recommended Verify that the insistent domain ID is unique in the fabric and then re-enable the AE_Ports. Run the

fabricShow command to view the domain IDs across the fabric and the **configure** command to change the insistent domain ID mode. Refer to the *Brocade Analytics Monitoring Platform Command*

Reference for more information on these commands.

FABR-1016

Message ficonMode is enabled.

Message Type LOG

Severity WARNING

Probable Cause Indicates that FICON mode is enabled on the switch through a user interface command.

FABR-1017

Message ficonMode is disabled.

Message Type LOG

Severity WARNING

Probable Cause Indicates that FICON mode is disabled on the switch through a user interface command.

FABR-1018

Message PSS principal failed (<reason for not becoming the principal switch>: <WWN of new

principal switch>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that a failure occurred when trying to set the principal switch using the **fabricPrincipal**

command. The message notifies you that the switch failed to become the principal switch because of

one of the following reasons:

- The switch joined an existing fabric and bypassed the F0 state.
- The fabric already contains a principal switch that has a lower World Wide Name (WWN).

Recommended Action Make sure that no other switch is configured as the principal switch. Force a fabric rebuild by using the **switchDisable** and **switchEnable** commands.

Refer to the *Brocade Analytics Monitoring Platform Command Reference* for more information about the **fabricPrincipal** command.

FABR-1019

Message Critical fabric size (<current domains>) exceeds supported configuration (<supported

domains>).

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that this switch is a value-line switch and has exceeded the limited fabric size: that is, a

specified limit to the number of domains. This limit is defined by your specific value-line license key. The fabric size has exceeded this specified limit, and the grace period counter has started. If the grace period is complete and the size of the fabric is still outside the specified limit, Web Tools is disabled.

Recommended Action Bring the fabric size within the licensed limits. Either a full fabric license must be added or the size of the fabric must be changed to within the licensed limit. Contact your switch provider to obtain a full

fabric license.

FABR-1020

Message Web Tools will be disabled in <days> days <hours> hours and <minutes> minutes.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that this switch has a value-line license and has a limited number of domains. If more than

the specified number of domains are in the fabric, a counter is started to disable Web Tools. This message displays the number of days left in the grace period. After this time, Web Tools is disabled.

Recommended

Action

Bring the fabric size within the licensed limits. Either a full fabric license must be added or the size of the fabric must be changed to within the licensed limit. Contact your switch provider to obtain a full

fabric license.

FABR-1021

Message Web Tools is disabled.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that this switch has a value-line license and has a limited number of domains. If more than

the specified number of domains are in the fabric, a counter is started to disable Web Tools. This grace period has expired and Web Tools has been disabled.

Recommended Action

Bring the fabric size within the licensed limits. Either a full fabric license must be added or the size of the fabric must be changed to within the licensed limit. Contact your switch provider to obtain a full fabric license.

FABR-1022

Message Fabric size (<actual domains>) exceeds supported configuration (<supported domains>). Fabric limit timer (<type>) started from <grace period in seconds>.

FFDC | LOG Message Type

> Severity **CRITICAL**

Probable Cause Indicates that the fabric size has exceeded the value-line limit, and the grace period counter has

started. If the grace period is complete and the size of the fabric is still outside the specified limit, Web

Tools is disabled.

Recommended

Bring the fabric size within the licensed limits. Either a full fabric license must be added or the size of Action

the fabric must be changed to within the licensed limit. Contact your switch provider to obtain a full

fabric license.

FABR-1023

Message Fabric size is within supported configuration (<supporteddomains>). Fabric limit

timer (<type>) stopped at <grace period in seconds>.

Message Type LOG

> INFO Severity

Probable Cause Indicates that the fabric size is within specified limits. Either a full fabric license was added or the size

of the fabric was changed to within the licensed limit.

FABR-1024

Message Initializing fabric size limit timer <grace period>.

Message Type LOG

> INFO Severity

Probable Cause Indicates that the fabric size has exceeded the limit set by your value-line switches. Value-line

> switches have a limited fabric size (for example, a specified limit on the number of domains). This value is defined by your specific value-line license key. The fabric size has exceeded this specified limit. The grace period timer has been initialized. If the grace period is complete and the size of the

fabric is still outside the specified limit, Web Tools is disabled.

Recommended Action

Bring the fabric size within the licensed limits. Either a full fabric license must be added or the size of the fabric must be changed to within the licensed limit. Contact your switch provider to obtain a full fabric license.

FABR-1029

Message

Port <port number> negotiated <flow control mode description> (mode = <received flow control mode>).

Message Type

LOG

Severity

INFO

Probable Cause

Indicates that a different flow control mode, as described in the message, is negotiated with the port at the other end of the link. The flow control is a mechanism of throttling the transmitter port to avoid buffer overrun at the receiving port. There are three types of flow control modes:

- VC_RDY mode: Virtual-channel flow control mode. This is a proprietary protocol.
- R_RDY mode: Receiver-ready flow control mode. This is the Fibre Channel standard protocol, that uses R_RDY primitive for flow control.
- DUAL_CR mode: Dual-credit flow control mode. In both of the previous modes, the buffer credits
 are fixed, based on the port configuration information. In this mode, the buffer credits are
 negotiated as part of exchange link parameter (ELP) exchange. This mode also uses the R_RDY
 primitive for flow control.

FABR-1030

Message fabric: Domain <new domain ID> (was <old domain ID>).

Message Type LOG

Severity INFO

Probable Cause Indicates that the domain ID has changed.

FABR-1031

Message Maximum number of retries sending ILS from port <port number> exceeded.

Message Type LOG | FFDC

Severity WARNING

Probable Cause Indicates the fabric exhausted the maximum number of retries sending internal link service (ILS) to the

iswitch daemon on the specified E_Port.

Recommended Run the **top** command to see if iswitchd is extremely busy or if another process is using excessive

Action CPU resources.

FABR-1032

Message Remote switch with domain ID < Domain ID > and switchname < Switchname > running an

unsupported FOS version v2.x has joined the fabric.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a switch with an unsupported Fabric OS version 2.x has joined the fabric.

Recommended Remove the switch with the unsupported Fabric OS version 2.x from the fabric

Action

FABR-1034

Message Area <Area that has already been acquired> have been acquired by port <Port that has

already acquired the area>. Persistently disabling port <Port that is being disabled>.

Message Type LOG

Severity INFO

Probable Cause Indicates you must enable Trunk Area on a port for another port to use the same area.

Recommended

Action

Move the cable to a port area that is not in use, or disable Trunk Area. You must manually enable the port or the port remains disabled forever.

Refer to the Fabric OS Administrator's Guide for more information.

FABR-1035

Message

Slave area <Area that does not match Master port's area> does not match Master port <Master port >. Persistently disabling port <Port that is being disabled>.

Message Type

LOG

Severity

INFO

Probable Cause

Indicates the Slave port's Trunk Area differs from that of the Master port.

Recommended

Action

Move the cable to a port to match with the same Master Trunk Area, or disable Trunk Area. You must

manually enable the port or the port remains disabled forever.

Refer to the Fabric OS Administrator's Guide for more information.

FABR-1036

Message

F Port trunks are only allowed on Trunk Area enabled port. Persistently disabling port <Port that is being disabled>.

Message Type

LOG

Severity

INFO

Probable Cause

Indicates the specified port is being disabled because when the port on a switch is Trunk Areaenabled, it does not allow other devices like Access Gateway (AG) or HBA that are not Trunk Areaenabled.

Recommended

Move the cable to a port that does not have Trunk Area enabled.

Action

FABR-1037

Message

Port configuration incompatible with Trunk Area enabled port. Persistently disabling port <Port that is being disabled>.

Message Type

LOG

Severity

INFO

Probable Cause

Indicates the specified port is being disabled because when the port attempts to go online, the switch finds the Trunk Area enabled is incompatible with port configurations such as long distance, port mirror, fast write, or EX Port.

Recommended

FOS-90x-Message-RM103 Broadcom

Action Check the port configurations to disable long distance, port mirror, fast write, or EX_Port.

FABR-1038

Message Trunking license not present with F port trunking enabled. Persistently disabling

port <Port that is being disabled>.

Message Type LOG

Severity INFO

Probable Cause Indicates the specified port is being disabled because F Port trunking is enabled without a trunking

license being present.

Recommended Install a trunking license or disable F_Port trunking on the port.

Action

FABR-1039

Message Invalid domain ID zero received from principal switch(domain id=<Principal domain

id>).

Message Type LOG

Severity WARNING

Probable Cause Indicates an invalid domain ID zero has been received.

Recommended Check the principal switch for the invalid domain ID zero.

Action

FABR-1040

Message Speed is not 2G, 4G, or 8G with F Port trunking enabled. Persistently disabling port

<Port that is being disabled>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the speed is not compatible for F Port trunks.

Recommended Change the speed for the port or disable F_Port trunking on the port.

Action

FABR-1041

Message Port <Port that is being disabled is disabled due to trunk protocol error.

Message Type LOG

Severity ERROR

Probable Cause Indicates a link reset was received before the completion of the trunking protocol on the port.

Recommended Enable the port by running the **portEnable** command.

Action

The port may recover by re-initialization of the link.

If the message persists, run the **supportFtp** command (as needed) to set up automatic FTP transfers;

then run the supportSave command and contact your switch service provider.

FABR-1043

Message Detected Fabric ID conflict with remote (not neighbor) switch <Switchname> (domain

<Domain ID>), FID <Fabric ID>. No local E Ports disabled.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the remote switch has a Fabric ID (FID) conflict with the local switch. But no ports are

disabled because the remote switch is not an adjacent to the local switch.

Recommended Make sure that all the switches in the fabric have the same FID or upgrade the switch firmware to a

Action VF-capable firmware.

FABR-1044

Message Detected Fabric ID conflict with neighbor switch <Switchname> (domain <Domain ID>),

FID <Fabric ID>. E Ports (<Number of E Ports disabled>) connected to the switch are

disabled.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the neighbor switch has a Fabric ID (FID) conflict with the local switch. All E_Ports

directly connected to the conflicting switch are disabled.

Recommended Make sure that all the switches in the fabric have the same FID or upgrade the switch firmware to a

Action VF-capable firmware.

FABR-1045

Message Detected Base Switch conflict with remote (not neighbor) switch <Switchname> (domain

<Domain ID>), BS <Base Switch Mode>. No local E Ports disabled.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the remote switch has a Base Switch attribute conflict with the local switch. But no ports

are disabled because the remote switch is not an adjacent to the local switch.

Recommended Action

Make sure that all the switches in the fabric have the same Base Switch attribute or disable VF mode for the conflicting switch using the **fosconfig --disable vf** command.

FABR-1046

Message Detected Base Switch conflict with neighbor switch <Switchname> (domain <Domain ID>),

BS <Base Switch Mode>. E Ports (<Number of E Ports disabled>) connected to the switch

are disabled.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the remote switch has a Base Switch attribute conflict with the local switch. All the

E_Ports directly connected to the conflicting switch are disabled.

Recommended Make sure that all the switches in the fabric have the same Base Switch attribute or upgrade the switch

firmware to a VF-capable firmware.

FABR-1047

Message Area unavailable to assign to the port. Persistently disabling port <Port that is

being disabled>.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that there are no areas available to assign to the port during port creation.

Recommended Move some ports out of the default switch to make areas available.

Action

FABR-1048

Message Detected Fabric ID (FID <InheritedFID> inherited) conflict with switch <Switchname>

(domain <Domain ID>, FID <Fabric ID>).

Message Type LOG

Severity ERROR

Probable Cause Indicates that a switch in the fabric has a Fabric ID (FID) conflict with the inherited FID of the local

switch.

Recommended Make sure that all the switches in the fabric have the same FID or upgrade the switch firmware to a

Action VF-capable firmware.

FABR-1049

Message Detected Fabric ID (FID <InheritedFID> inherited) conflict with neighbor switch

<Switchname> (domain <Domain ID>, FID <Fabric ID>). E_Ports (<Number of E_Ports

disabled>) connected to the switch are disabled.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the neighbor switch has a Fabric ID (FID) conflict with the inherited FID of the local

switch. All E_Ports directly connected to the conflicting switch are disabled.

Recommended Make sure that all the switches in the fabric have the same FID or upgrade the switch firmware to a

Action VF-capable firmware.

FABR-1050

Message <License license not present. F Port trunking cannot be enabled on port(<Port>).

Message Type LOG

Severity INFO

Probable Cause Indicates that the trunking or Server Application Optimization (SAO) license is not installed.

Recommended Install the license required.

Action

FABR-1051

Message D-Port <Testname> test failed for slot <Slot> and port <Port>.

Message Type LOG | AUDIT

Class FABRIC

Severity ERROR

Probable Cause Indicates that the D Port test failed for the given slot and port due to one of the following reasons:

The small form-factor pluggable (SFP) fault detected by electrical loopback test failure.

- The cable fault detected by optical loopback test failure.
- An application-specific integrated circuit (ASIC) issue detected by link traffic test failure.

Recommended Action Replace the faulty SFPs, cables, or blade.

FABR-1052

Message The configured port speed is invalid. Persistently disabling port <Port that is being

disabled>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the configured speed for the specified port is invalid.

Recommended Execute the **portCfgSpeed** command to change the port speed.

Action

FABR-1053

Message The switch is disabled due to an inconsistency found in the interop config parameters.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the configuration keys have interopmode parameters such as switch.interopMode and

switch.mcdtFabricmode set.

Recommended Execute the **interopmode** command to reset the parameters.

Action

FABR-1054

Message Rebooting the standby as it received an update before port [<Port Number>] is

expanded.

Message Type LOG | FFDC

Severity INFO

Probable Cause Indicates that the standby control processor (CP) did not have the port because the port expand

operation is still in progress and the standby CP has received a port update. The standby CP reboots

automatically to ensure sync and attain the normal state. This is a rare occurrence.

FABR-1055

Message F Port trunking cannot be enabled on the slot <Slot Number> port <Port Number> due

to inconsistent port configuration.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified F_Port is unable to join its assigned trunk area group because of mismatch

in the port configuration with the other trunk area members.

Recommended

Action

Check the configuration of the port with all other ports intended to be part of the same trunk group. Use the **porttrunkarea --show** to identify the trunk members of the specified F Port and the **portcfgshow**

command to identify the conflicting configuration between the trunk members.

FABR-1056

Message Check trunking license validity and trunk port configuration on remote switch.

Persistently disabling port <Port that is being disabled>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified port on a trunk area-enabled switch is being disabled. Make sure that the

remote switch such as Access Gateway (AG) or Host Bus Adapter (HBA) device has the valid trunking

license and trunk port configuration.

Recommended

Action

Install trunking license and enable trunk port configuration on the remote switch.

FABR-1057

Message Failed to set default domain for AMP switch

Message Type LOG

Severity WARNING

Probable Cause Indicates that the failure happened when trying to set default domain (150) for AMP switch.

Recommended

Action

Collect supportsave using the **supportsave** command.

FABR-1058

Message Failed to set default principal switch priority for AMP switch

Message Type LOG

Severity WARNING

Probable Cause Indicates that the failure happened when trying to set default principal switch priority (0xFF) for AMP

switch.

Recommended Action Collect supportsave using the **supportsave** command.

FABR-1059

Message Detected local Domain ID change from <Old Domain ID> to <New Domain ID>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the local domain ID changed while the switch is still online. The switch will be toggled to

recover from the domain ID change.

Recommended

Action

This message is often transitory.

If the message persists, run the **supportFtp** command (as needed) to set up automatic FTP transfers;

then run the supportSave command and contact your switch service provider.

FABR-1060

Message Detected local Domain ID change from <Old Domain ID> to <New Domain ID>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the local domain ID changed while the switch is still online.

Recommended

Action

This message is often transitory.

If the message persists, run the ${\it supportFtp}$ command (as needed) to set up automatic FTP transfers;

then run the **supportSave** command and contact your switch service provider.

FABR-1061

Message F-Port trunking is not supported with the HBA on this platform. Persistently disabling

port <Port that is being disabled>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified port on a trunk area-enabled switch is being disabled. Make sure that the

remote Host Bus Adapter (HBA) device is supported with this platform.

Recommended

Action

Connect HBA supported with this platform and enable the port

FABR-1062

Message Fabric reconfiguration triggered in the fabric

Message Type AUDIT

Class FABRIC

Severity INFO

Probable Cause User has initiated build fabric operation in the current fabric.

FABR-3000

Message D-Port test <Start, Restart or Stop D-Port request> request initiated for <Port/Ports

for which the D-Port test request initiated>

Message Type AUDIT

Class FABRIC

Severity INFO

Probable Cause User has either started, restarted or stopped D-Port test on specific port

6.32 FABS Messages

FABS-1001

Message <Function name> <Description of memory need>.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the system is low on memory and cannot allocate more memory for new operations. This

is usually an internal Fabric OS problem or file corruption. The Description of memory need variable

specifies the memory size that was being requested. The value can be any whole number.

Recommended Reboot or power cycle the switch.

Action

FABS-1002

Message <Function name> <Description of problem>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that an internal problem has been detected by the software. This is usually an internal Fabric

OS problem or file corruption.

Recommended

Reboot or power cycle the switch.

Action

If the message persists, run the firmwareDownload command to update the firmware.

FABS-1004

Message <Function name and description of problem> process <Process ID number> (<Current

command name>) <Pending signal number>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that an operation has been interrupted by a signal. This is usually an internal Fabric OS

problem or file corruption.

Recommended

Action

Reboot or power cycle the switch.

FABS-1005

Message <Function name and description of problem> (<ID type>= <ID number>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that an unsupported operation has been requested. This is usually an internal Fabric OS

problem or file corruption. The following is a possible value for function name and description of

problem variable:

fabsys write: Unsupported write operation: process xxx

In this value, xxx is the process ID (PID), which could be any whole number.

Recommended

Action

Reboot or power cycle the active CP (for modular systems) or the switch (for single-board systems).

If the message persists, run the **firmwareDownload** command to update the firmware.

FABS-1006

Message <Function name and description of problem>: object <object type id> unit <slot>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that there is no device in the slot with the specified object type ID in the system module

record. This could indicate a serious Fabric OS data problem on the switch. The possible values for

function name and description of problem variable are:

setSoftState: bad object

■ setSoftState: invalid type or unit

media_sync: Media oid mapping failed

■ fabsys_media_i2c_op: Media oid mapping failed

■ fabsys_media_i2c_op: obj is not media type

media_class_hndlr: failed sending media state to blade driver

Recommended Action If the message is isolated, monitor the error messages on the switch. If the error is repetitive or if the

fabric failed, failover or reboot the switch.

If the message persists, run the firmwareDownload command to update the firmware.

FABS-1007

Message <Function name>: Media state is invalid - status=<Status value>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Fabric OS has detected an invalid value in an object status field. This is usually an

internal Fabric OS problem or file corruption.

Recommended Reboot or power cycle the switch.

Action

If the message persists, run the **firmwareDownload** command to update the firmware.

FABS-1008

Message <Function name>: Media oid mapping failed.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Fabric OS was unable to locate a necessary object handle. This is usually an internal

Fabric OS problem or file corruption.

Recommended Reboot or power cycle the switch.

Action

FABS-1009

Message Type LOG

Message

Severity WARNING

Probable Cause Indicates that the Fabric OS was unable to locate an appropriate object handle. This is usually an

internal Fabric OS problem or file corruption.

<Function name>: type is not media.

Recommended Reboot or power cycle the switch.

Action

FABS-1010

Message <Function name>: Wrong media event <Event number>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Fabric OS detected an unknown event type. This is usually an internal Fabric OS

problem or file corruption.

Recommended Reboot or power cycle the switch.

Action

If the message persists, run the **firmwareDownload** command to update the firmware.

FABS-1011

Message <Method name>[0x<Method tag number>]:Invalid input state 0x<Input state code>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that an unrecognized state code was used in an internal Fabric OS message for a field-

replaceable unit (FRU).

Recommended Reboot or power cycle the CP or system.

Action

If the message persists, run the **firmwareDownload** command to update the firmware.

FABS-1013

Message <Method name>[0x<Method tag number>]:Unknown blade type 0x<Blade type>.

Message Type LOG

Severity ERROR

Probable Cause Indicates an unrecognized type of blade has been discovered in the system.

This may be caused by an incorrect field-replaceable unit (FRU) header, inability to read the FRU

header, or the blade may not be supported by this platform or Fabric OS version.

Recommended Verify that the blade is valid for use in this system and this version of Fabric OS.

Action Reseat the blade.

If this is a valid blade and reseating does not solve the problem, replace the blade.

FABS-1014

Message <Method name>[0x<Method tag number>]:Unknown FRU type 0x<FRU Object type>.

Message Type LOG

Severity ERROR

Probable Cause Indicates an unrecognized type of field-replaceable unit (FRU) has been discovered in the system.

This may be caused by an incorrect FRU header, inability to read the FRU header, or the FRU may not

be supported by this platform or Fabric OS version.

Recommended Action Verify that the FRU is valid for use in this system and this version of Fabric OS.

Reseat the FRU.

If this is a valid FRU and reseating does not solve the problem, replace the FRU

FABS-1015

Message <Method name>[0x<Method tag number>]:Request to enable FRU type 0x<FRU Object type>,

unit <Unit number> failed. err code <Error code>.

Message Type LOG

Severity ERROR

Probable Cause Indicates the specified FRU could not be enabled. This is usually an internal Fabric OS problem.

Recommended Remove and reinsert the FRU.

Action

Reboot or power cycle the CP or system.

If the message persists, run the **firmwareDownload** command to update the firmware.

6.33 FBC Messages

FBC-1001

Message Firmware version on AP blade is incompatible with that on the CP.

Message Type LOG

Severity ERROR

Probable Cause Indicates the control processor (CP) blade determined that the firmware version running on the

application processor (AP) blade is not compatible with that running on CP. The AP and CP blades

cannot communicate.

Recommended

Action

The problem can be corrected by changing the firmware version on either the CP or on the AP blade. You can modify the firmware version on the CP blade by using the **firmwareDownload** command. Refer to the release notes to determine whether a non-disruptive firmware download is supported between the revisions. Because the AP and CP blades cannot communicate, it is not possible to load new firmware on the AP blade. If necessary, send the AP blade back to the factory for a firmware update.

6.34 FCMC Messages

FCMC-1001

Message System is low on memory and has failed to allocate new memory.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the switch is low on memory and failed to allocate new memory for an information unit

Check the memory usage on the switch using the memShow command. Execute the supportsave

(IU).

Recommended A non-bladed switch will automatically reboot. For a bladed switch, the active CP blade will

Action automatically fail over and the standby CP will become the active CP.

6.35 FCOE Messages

FCOE-1001

Message malloc failed for <Message>.

Message Type LOG

Severity ERROR

Probable Cause Indicates a memory allocation failure.

Action and contact customer support.

FCOE-1002

Recommended

Message Max logingroup limit reached at <limit>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that too many login groups have been added.

Recommended Check the maximum login group value displayed in the message.

Action

FCOE-1003

Message <device>: member in another logingroup <lg> being removed.

Message Type LOG

Severity INFO

Probable Cause Indicates that the device World Wide Name (WWN) you are trying to add is present in some other login

group, and therefore it will be removed from that login group and added to the new login group.

Recommended Action Check the login group changes using the **fcoelogincfg** --show command.

FCOE-1004

Message <device>: removing member from <lg> failed.

Message Type LOG

Severity ERROR

Probable Cause Indicates that removing a device from the login group has failed.

Recommended Execute the **supportSave** command and restart the system. If the problem persists, contact your

Action switch service provider.

FCOE-1005

Message <device>: membership check failed in logingroup: <lg>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the membership check for the device has failed.

Recommended Check the device for failed membership using the **fcoelogincfg** --show command.

Action

FCOE-1006

Message file operation failed on <filename> for <operation> operation: errno:<error>.

Message Type LOG

Severity ERROR

Probable Cause Indicates a file operation failure.

Recommended Check the error code for the file operation failure and contact your switch service provider for

Action assistance.

FCOE-1007

Message Rejecting new FCoE login from interface <Interface info> [MAC <Device MAC>] due to

duplicate Port WWN [<Port WWN>] with interface <Interface info> [pid:<Device PID>,

MAC <Device MAC>].

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified new FCoE login has the same Port World Wide Name (PWWN) as an

existing FCoE login.

Recommended Check if the new FCoE device login is intended. If so, manually remove the old FCoE login using fcoe

Action --clear -login.

FCOE-1008

Message Rejecting new FCoE NPIV login from interface <Interface info> [MAC <Device MAC>] due

to duplicate Port WWN [<Port WWN>] with interface <Interface info> [pid:<Device PID>,

MAC <Device MAC>].

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified new FCoE N Port ID virtualization (NPIV) login has the same Port World

Wide Name (PWWN) as an existing FCoE login.

Recommended Check if the new FCoE NPIV login is intended. If so, manually remove the old FCoE login using fcoe -

Action -clear -login.

FCOE-1009

Message Addition of N_Port mapping failed. Max N_Port mapping limit reached: <max n_port>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the N_Port mapping has reached its maximum limit.

Recommended Remove unwanted N Port mappings using the **fcoelogingroup --remove** command and try adding

Action N Port mapping using the **fcoelogingroup --add** command.

FCOE-1010

Message fcoed: FSS Registration or Trace initialization failed.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the Fabric OS state synchronization (FSS) registration or initialization of the FCoE trace

has failed.

Recommended

Execute the **supportSave** command and restart the system. If the problem persists, contact your

Action switch service provider.

FCOE-1011

Message <Message>.

Message Type LOG

Severity ERROR

Probable Cause Indicates an errror.

Recommended

Execute the **supportsave** and contact customer support.

Action

FCOE-1019

Message FLOGI ignored as FCMAP is not configured on FCoE VLAN.

Message Type LOG

Severity WARNING

Probable Cause Indicates that FCMAP has not been configured on FCoE VLAN.

Recommended Configure FCMAP on the FCoE VLAN using the **fcoe --fcmapset** command.

Action

FCOE-1022

Message Login from interface <Interface info> [WWN <Device WWN>] failed. Max. FCoE device

login limit [<Max. device limit>] reached.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the switch has reached its maximum allowed FCoE device limit. Hence the new device

cannot be logged in

Recommended Do not add any more FCoE devices to the switch.

Action

FCOE-1023

Message Too many logins on FCoE VF Port <FCoE VF Port number> [WWN <Device WWN>, interface

<Interface info>]; max allowed <Max. device limit per VF-Port>.

Message Type LOG

WARNING Severity

Probable Cause Indicates that the VF-Port has reached its maximum allowed FCoE login limit.

If possible logout some of the logged-in devices using the portdisable> or fcoe --clear -login Recommended

Action command and then log in the new device. You can view the list of logged-in devices using the fcoe --

show -login command.

FCOE-1024

Message Received FDISC from interface <Interface info> [Enode MAC <Enode MAC>] without prior

FLOGI.

Message Type LOG

> Severity WARNING

Probable Cause Indicates that a FDISC frame is received from the end node that has not logged in. The end node must

send a fabric login (FLOGI) before it can send an FDISC. This may be due to a CNA or target driver

issue.

Recommended Contact CNA or Target driver support team for assistance.

Action

FCOE-1029

Message FIP version mismatch between FDISC [version <FDISC FIP version>, Port WWN <FDISC

Device Port WWN>] and Base VN Port login [version <Base VN Port (FLOGI) FIP version>,

MAC <Base VN Port MAC>].

Message Type LOG

> Severity WARNING

Probable Cause Indicates a FIP version mismatch between the fabric login (FLOGI) and FDISC device. This may be

due to a CNA or Target driver issue.

Recommended

Action

Contact CNA or Target driver support team for assistance.

FCOE-1030

Message FIP version mismatch between FIP LOGO [version <FIP LOGO version>, WWN <Device WWN>]

and Base VN Port login [version <Base VN Port (FLOGI) FIP version>, MAC <Base VN Port

MAC >].

Message Type LOG

> Severity WARNING

Probable Cause Indicates a FIP version mismatch between the FCoE initialization protocol (FIP) logout and the base

fabric login (FLOGI). This may be due to a CNA or Target driver issue.

Recommended

Action

Contact CNA or Target driver support team for assistance.

FCOE-1032

Message We are in WARM RECOVERING state...

Message Type LOG

> Severity WARNING

Probable Cause Indicates that high availability (HA) failover or switch reboot may be in progress.

Recommended Wait until the chassis has fully recovered before you perform any operations.

Action

FCOE-1033

Message FIP v1 FLOGI received on interface <interface info> [WWN <device WWN>] but VF port

<FCoE VF Port number> has pending logins[Current devices <Current devices>, Pending

devices <Pending devices>].

Message Type LOG

> Severity INFO

Probable Cause Indicates that a device is trying to log in to a port that already has a device logged in.

FCOE-1034

Message Frame [type 0x<Frame type>] received on PFC disabled priority <priority> on interface

<interface info> from device <string displaying WWN/MAC> <device WWN/MAC>

Message Type LOG

> Severity WARNING

Probable Cause Indicates that a frame is received on the specified priority, for which priority-based flow control (PFC)

or FCoE is disabled.

Recommended Check FCoE priority on the device or the FSB through which the device is logged in (if applicable) and Action

make sure it matches with the FCoE priority on the switch. In case the FCoE priority on the switch

needs to be changed, use fcoe --config -priority

FCOE-1037

Message Logingroup dropped for switch WWN: <switch WWN>, due to name conflict while merging.

Message Type LOG

Severity WARNING

Probable Cause Indicates that same login group name exists for two different switches that have different

organizationally unique identifiers (OUIs), but the last three bytes are same.

Recommended Create the login group for the switch World Wide Name (WWN) with another name that will not lead to

Action a name conflict.

FCOE-1038

Message logingroup#<logingroup number> (<logingroup name>) created.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified login group is added to the switch login group table.

FCOE-1039

Message Login rejected for interface <interface info> [Device MAC <Device MAC>, WWN <Device

WWN>]. No VF Ports available for login.

Message Type LOG

Severity WARNING

Probable Cause Indicates that there are no VF ports available for login, hence the logins are rejected.

Recommended If the max number of VF_Ports for the chassis has not reached, create more FCoE VF_Ports using

Action fcoe --config -endoes.

FCOE-1040

Message Logingroup name changed from <old logingroup name> to <new logingroup name>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the login group has been renamed.

FCOE-1041

Message Transaction aborted.

Message Type LOG

Severity INFO

Probable Cause Indicates that the ongoing FCoE login configuration transaction is aborted.

FCOE-1042

Message FCoE login configuration transaction saved fabric-wide.

Message Type LOG

Severity INFO

Probable Cause Indicates that the FCoE login configuration transaction is saved fabric-wide.

FCOE-1043

Message FCoE login configuration management disabled.

Message Type LOG

Severity INFO

Probable Cause Indicates that the FCoE login configuration management is disabled.

FCOE-1044

Message FCoE login configuration management enabled.

Message Type LOG

Severity INFO

Probable Cause Indicates that the FCoE login configuration management is enabled.

6.36 FCPD Messages

FCPD-1001

Message Probing failed on <error string>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a Fibre Channel Protocol (FCP) switch probed devices on a loop port, and probing failed

on the L_Port, arbitrated loop physical address (AL_PA), or the F_Port. For ALPA, the valid range is

0x00 through 0xFF. The *error* variable can be either of the following:

• L_Port port_number ALPA alpa_number

F_Port port_number

This could happen due to some firmware issue with the device controller on the specified port.

Recommended Action Contact the device vendor for any firmware-related issues. Also, consider upgrading the device firmware.

FCPD-1002

Message port <port number>, bad R CTL for fcp probing: 0x<R CTL value>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the response frame received on the specified port for an inquiry request contains an

invalid value in the routing control field. This could happen due to some firmware issue with the device

controller on the specified port.

Recommended Contact the device vendor for any firmware-related issues. Also, consider upgrading the device

Action firmware.

FCPD-1003

Message Probing failed on <error string> which is possibly a private device which is not

supported in this port type.

Message Type LOG

Severity INFO

Probable Cause Indicates that device probing has failed because private devices will not respond to the switch port

login (PLOGI) during probing.

Recommended The Brocade 4100, 4900, 5000, 7500, and AP 7600 do not support private loop devices. Refer to the

Action switch vendor for a list of other port types that support private devices for inclusion into the fabric.

6.37 FCPH Messages

FCPH-1001

Message <function>: <failed function call> failed, out of memory condition.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the switch is low on memory and failed to allocate new memory for a Fibre Channel

driver instance.

The function value can only be fc create. This function creates a Fibre Channel driver instance.

The failed function call can only be kmalloc_wrapper, which has failed. This function call is for kernel memory allocation.

Recommended Action A non-bladed switch will automatically reboot. For a bladed switch, the active CP blade will automatically fail over and the standby CP will become the active CP.

FCPH-1002

Message Port <Port Number> has been disabled since switch requires authentication when device

authentication policy is set to ON.

Message Type

Severity WARNING

Indicates a device that does not support authentication has tried to log in to the switch when the device **Probable Cause**

authentication policy is in ON status on the switch.

Recommended Enable the authentication on the device or set the device authentication status to PASSIVE/OFF on Action

the switch if it is not mandatory. Use the authUtil command to change the device authentication policy.

FCPH-1003

Message Logging out new port <Port Number> with same Port WWN [<Port WWN>] as old port <Port

Number>[pid: <Device PID>] due to duplicate Port WWN detection policy.

Message Type LOG

> **WARNING** Severity

Probable Cause Indicates that the specified new port has the same Port World Wide Name (PWWN) as the old port.

FCPH-1004

Message Logging out new NPIV port <Port Number> with same Port WWN [<Port WWN>] as old port

<Port Number>[pid:<Port PID>] due to duplicate Port WWN detection policy.

LOG Message Type

> WARNING Severity

Indicates that the specified N_Port ID virtualization (NPIV) port has the same Port World Wide Name **Probable Cause**

(PWWN) as the old port.

FCPH-1005

Message FDISC exch=0x<ExchangeId> sid=0x<SourceID> did=0x<DestinationID> on port <Port>

rejected; temporary mem alloc error. Please bounce port of affected device.

Message Type LOG

Severity WARNING

Probable Cause Indicates that in busy login conditions, the buffer used for quick memory allocations (known as *atomic*

malloc) can be quickly depleted and not replenished before the next allocation occurs.

Recommended

Reset the specified port using the **portDisable** and **portEnable** commands.

FCPH-1006

Message Core blade ICL port <Port Number> not permitted to come online as its connected to

device.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that F_ports were connected to the Core blades.

Recommended Do not attempt to connect devices to the Core blades.

Action

FCPH-1007

Message IU is freed. fc(<fc instance>), pt:<port>, frm:<frames left>, s id:0x<seq id>,

s_xid:0x<seq_xid>, s_state:0x<seq_state>, s_flags:0x<seq_flags>,
s lst cnt:0x<seq last count>, s cls:0x<seq class>, x pid:<x x xid>,

x_seq_xid:<x_seq_xid>, x_seq_state:0x<x_seq_state>.

Message Type FFDC | LOG

Severity WARNING

Probable Cause Indicates that the sequence memory is already freed.

Recommended If the message persists, execute the **supportSave** command.

Action

FCPH-1008

Message Indicates that an exchange does not exist while handling an Abort Sequence frame.

fc(<fc instance>), pt:<port>, iu refcnt:<iu refcnt> sid:0x<sid> did:0x<did>

two abts:<two abts>.

Message Type FFDC | LOG

Severity WARNING

Probable Cause Indicates that an exchange does not exist while handling an Abort Sequence frame.

Recommended

Action If the message persists, execute the **supportSave** command.

FCPH-1009

Message Sequence incomplete and dropped - fc=<fc>, seqid=<Sequence ID>

seq_frames=<Num_Frames_in_Sequence> seq_iu=0x<First_IU_In_Sequence>
iu_seq_id=<IU_Sequence_ID> xid=0x<Exchange_ID> sid=0x<Source_ID>

did=0x<Destination ID>

Message Type LOG

Severity WARNING

Probable Cause A new sequence is received before a previous sequence is complete. This is likely caused by dropped

frames.

Recommended Monitor links for dropped frames due to congestion (class 3 timeouts) and work with device vendor to

Action alleviate the congestion.

FCPH-1010

Message Logging out old port <Port Number> with same Port WWN [<Port WWN>] as new port <Port

Number> due to duplicate Port WWN detection policy.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified new port has the same Port World Wide Name (PWWN) as the old port.

FCPH-1011

Message Logging out old NPIV port <Port Number>[pid:<Device PID>] with same Port WWN [<Port

WWN>] as new port <Port Number> due to duplicate Port WWN detection policy.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified new port has the same Port World Wide Name (PWWN) as the old N Port

ID virtualization (NPIV) port.

FCPH-1012

Message Logging out old port <Port Number> with same Port WWN [<Port WWN>] as new NPIV port

<Port Number> due to duplicate Port WWN detection policy.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified N_Port ID virtualization (NPIV) new port has the same Port World Wide

Name (PWWN) as the old port.

FCPH-1013

Message Logging out old NPIV port <Port Number>[pid:<Device PID>] with same Port WWN [<Port

WWN>] as new NPIV port <Port Number> due to duplicate Port WWN detection policy.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified N_Port ID virtualization (NPIV) new port has the same Port World Wide

Name (PWWN) as the old NPIV port.

FCPH-1014

Message FC Protocol Error: <Protocol Error> - fc(<fc instance>) port=<Port Number>

iu=0x<IU pointer> nfr=<Num Frames in Sequence> tp=0x<FC Type> fctl=0x<Frame Control>

seqid=<IU_Sequence_ID> seqc=<IU_Sequence_Count> xid=0x<IU_Exchange_ID>
oxrxid=0x<Originator Exchange ID Responder Exchange ID> sid=0x<Source ID>

did=0x<Destination_ID>

Message Type LOG

Severity WARNING

Probable Cause A frame has been received which does not follow the FC Standard Protocol.

Recommended Contact the end device vendor to investigate the condition.

Action

6.38 FCR Messages

FCR-1001

Message FC router proxy device in edge created at port <port number>.

Message Type LOG

Severity INFO

Probable Cause Indicates that a proxy device at a port in the edge fabric has been imported at the specified port.

FCR-1002

Message FC router proxy device in edge deleted at port <port number>.

Message Type LOG

Severity INFO

Probable Cause Indicates that a proxy device at a port in the edge fabric has been deleted at the specified port.

FCR-1003

Message FC router physical DEVICES newly exported at port <port number>.

Message Type LOG

Severity INFO

Probable Cause Indicates that one or more physical devices have been newly exported through the specified port.

FCR-1004

Message FC router physical devices offline at port <port number>.

Message Type LOG

Severity INFO

Probable Cause Indicates that one or more physical devices connected to the specified port have gone offline.

Recommended

Action

Verify that the devices were intended to be taken offline. If not, verify that the devices are functioning properly. Verify that all small form-factor pluggables (SFPs) are seated correctly. Check for faulty cables, deteriorated SFPs, or dirty connections. Replace the cables and the SFPs if necessary.

FCR-1005

Message FC router LSAN zone device removed at port <port number>.

Message Type LOG

Severity INFO

Probable Cause Indicates that a device is removed from the logical storage area network (LSAN) zone in the edge

fabric.

FCR-1006

Message FC router LSAN zone device added at port <port number>.

Message Type LOG

Severity INFO

Probable Cause Indicates that a device is added to a logical storage area network (LSAN) zone in the edge fabric.

FCR-1007

Message FC router LSAN zone deleted at port <port number>.

Message Type LOG

Severity INFO

Probable Cause Indicates that a logical storage area network (LSAN) zone attached to the specified port was deleted in

the edge fabric.

FCR-1008

Message FC router LSAN zone created at port <port number>.

Message Type LOG

Severity INFO

Probable Cause Indicates that a logical storage area network (LSAN) zone was created at the specified port in the edge

fabric.

FCR-1009

Message FC router LSAN zone enabled at port <port number>: <enabled name>.

Message Type LOG

Severity INFO

Probable Cause Indicates that a logical storage area network (LSAN) zone was enabled in the edge fabric attached to

the specified port. The enabled LSAN zone configuration is listed.

FCR-1010

Message FC router LSAN zone disabled at port <port number>.

Message Type LOG

Severity INFO

Probable Cause Indicates that a logical storage area network (LSAN) zone is disabled in the edge fabric attached to the

specified port.

FCR-1011

Message Remote LSAN zone updated in domain <domain ID>.

Message Type LOG

Severity INFO

Probable Cause Indicates that a logical storage area network (LSAN) zone update was received from another domain.

FCR-1012

Message FC Router fabric build completed on port <port number>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the Fibre Channel router has completed a fabric build at the specified port.

FCR-1013

Message Phantom FSPF database exchange completed on port port number>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified EX_Port has completed the fabric shortest path first (FSFP) database

exchange.

FCR-1015

Message New EX_Port added on port <port number> in domain <domain ID>.

Message Type LOG

Severity INFO

Probable Cause Indicates that an EX Port was created on the specified port in the specified domain.

FCR-1016

Message FCR fabric no longer reachable at port id <port number> (0x<port number (hex)>) fabric

ID <fabric ID>.

Message Type LOG

Severity INFO

Probable Cause Indicates that a fabric is no longer accessible through the backbone fabric. This may be caused by a

link or switch failure.

FCR-1018

Message FC router proxy device entries exhausted on port <port number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the number of proxy devices is greater than allowed by the port resource.

Recommended Action Remove excess logical storage area network (LSAN) zones or devices until the number of proxy devices exported is within the range allowed by the port resource. Use the **fcrResourceShow** command to view resources including LSAN zone resources, LSAN device resources, and proxy device port resources. Use the **fcrProxyDevshow** command to view how many proxy devices are created in the fabric with the port resource problem. LSAN zones are removed using standard zoning commands such as **zoneShow**, **zoneRemove**, **zoneDelete**, **cfgDelete**, and **cfgDisable** in the edge fabric. Proxy devices can be removed by zoning operations or by bringing physical devices offline (for example, disabling the port that a device is attached to, and then disconnecting the cable or disabling the device.

FCR-1019

Message EX_Port entries exhausted at port <port number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the number of EX_Port entries being created is greater than allowed by the port

resource.

Recommended Disable EX_Ports until the number of ports is within the range allowed by the port resource. The

EX_Port limit is displayed using the **fcrRouteShow** command. Use the **portDisable** command to

disable EX Ports.

FCR-1020

Message Local LSAN zone entries for FC router exhausted; max limit: <LSAN zone limit>; dropped

zone: <Zone name>.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that the number of LSAN zones created within a MetaSAN exceeds the local LSAN zone

database limitations.

Recommended Remove excess LSAN zones so that the number of LSAN zones created is within the range of the Action local database limitations. To do that, perform the following steps:

1. Use the **portDdisable** command to disable all the EX Ports that received this error message.

1. Use the **portDdisable** command to disable all the other EX_Ports on that FCR connected to the same edge fabrics to which the EX_Ports disabled in step 1 are connected.

4. Use zoning commands on the edge fabrics, to reduce the LSAN zone entries on the edge fabrics.

1. Use the portEnable command on each EX Port, one at a time, and verify that this error is not reported again.

FCR-1021

Message Local LSAN device entries exhausted while updating LSAN zone <zone name> device

entries.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the number of devices created through logical storage area network (LSAN) zones

within the MetaSAN exceeds the local LSAN zone database limitations.

Recommended Remove excess device entries within LSAN zones so that the number of devices is within the range of

the local zone database limitations.

FCR-1022

Message Local proxy device slot entries exhausted.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that resources to persistently store the proxy device slot to the remote world wide name

(WWN) have been consumed.

Recommended Remove the proxy device slots by using the **fcrProxyConfig** command or limit proxy devices by

removing logical storage area network (LSAN) zone entries.

FCR-1023

Message Local phantom port WWN entries exhausted.

Message Type LOG

Action

Action

Severity WARNING

Probable Cause Indicates that the number of port World Wide Names (WWNs) detected to be in use exceeds the local

port WWN resources.

Recommended Limit the number of port WWNs required by limiting the remote edge fabric connectivity (which limits

the number of translate domains). You can also limit the number of proxy devices for a translate domain (which limits the number of translate domain ports required) by limiting the devices specified in

logical storage area network (LSAN) zones.

FCR-1024

Message Local LSAN zone <zone name> device entries for edge LSAN exhausted; max entries: <Max

LSAN zone entries>.

Message Type LOG

> Severity WARNING

Probable Cause Indicates that the number of devices in a logical storage area network (LSAN) defined in the edge

fabric is greater than allowed by the local LSAN zone database limitations.

Recommended Remove excess device entries from this LSAN zone until the number of devices is within the range of Action

the local LSAN zone database limitations.

FCR-1025

Message Local phantom node WWN entries exhausted.

Message Type LOG

> **WARNING** Severity

Probable Cause Indicates that the number of node World Wide Names (WWNs) detected to be in use exceeds the local

node WWN resources.

Recommended Reduce the number of node WWNs required by limiting the remote edge fabric connectivity (which

limits the number of translate domains).

FCR-1026

Message In slot <slot number>, Node WWN roll over.

Message Type LOG

Action

Severity **INFO**

Probable Cause Indicates that the node World Wide Name (WWN) pool has rolled over in the specified slot, and WWN

entries not detected to be in use are reused as needed.

Recommended It is unlikely that WWN conflicts will occur as a result of pool rollover unless the switch is deployed in a

Action very large MetaSAN environment with a large number of logical storage area network (LSAN) devices

and fabrics, or there are highly dynamic changes to EX_Port connectivity. WWN conflicts might cause unpredictable behavior in management applications. To avoid WWN conflicts, all EX Ports attached to

fabrics with highly dynamic changes to EX Port connectivity should be disabled and then re-enabled.

FCR-1027

Message In slot <slot number>, Port WWN roll over.

Message Type LOG

Severity INFO

Probable Cause Indicates that the port World Wide Name (WWN) pool has rolled over in the specified slot, and WWN

entries not detected to be in use are reused as needed.

Recommended Action It is unlikely that WWN conflicts will occur as a result of pool rollover unless the switch is deployed in a very large MetaSAN environment with a large number of logical storage area network (LSAN) devices and fabrics, or there are highly dynamic changes to EX_Port connectivity. WWN conflicts might cause unpredictable behavior in management applications. To avoid WWN conflicts, all EX_Ports attached to fabrics with highly dynamic changes to EX_Port connectivity should be disabled and then re-enabled.

FCR-1028

Message In slot <slot number>, node WWN pool 95 percent allocated.

Message Type LOG

Severity INFO

Probable Cause Indicates that the node World Wide Name (WWN) pool is close to rollover in the specified slot, and that

the WWN entries not detected to be in use will be reused as needed.

Recommended Action It is unlikely that WWN conflicts will occur as a result of pool rollover unless the switch is deployed in a very large MetaSAN environment with a large number of logical storage area network (LSAN) devices and fabrics, or there are highly dynamic changes to EX_Port connectivity. WWN conflicts might cause unpredictable behavior in management applications. To avoid WWN conflicts, all EX_Ports attached to fabrics with highly dynamic changes to EX_Port connectivity should be disabled and then re-enabled.

FCR-1029

Message In slot <slot number>, Port WWN pool 95 percent allocated.

Message Type LOG

Severity INFO

Probable Cause Indicates that the port World Wide Name (WWN) pool has rolled over in the specified slot, and WWN

entries not detected to be in use are reused as needed.

Recommended

Action

It is unlikely that WWN conflicts will occur as a result of pool rollover unless the switch is deployed in a very large MetaSAN environment with a large number of logical storage area network (LSAN) devices and fabrics, or there are highly dynamic changes to EX_Port connectivity. WWN conflicts might cause unpredictable behavior in management applications. To avoid WWN conflicts, all EX_Ports attached to fabrics with highly dynamic changes to EX_Port connectivity should be disabled and then re-enabled.

FCR-1030

Message Physical device <device WWN> came online at fabric <fabric ID>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the physical device World Wide Name (WWN) came online in the specified fabric.

FCR-1031

Message Physical device <device WWN> went offline in fabric <fabric ID>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the physical device World Wide Name (WWN) went offline in the specified fabric.

FCR-1032

Message Edge fabric enabled security on port <port number> in fabric <fabric ID>.

Message Type LOG

Severity INFO

Probable Cause Indicates that Secure mode was turned on in the edge fabric.

FCR-1033

Message Edge fabric disabled security on port <port number> in fabric <fabric ID>.

Message Type LOG

Severity INFO

Probable Cause Indicates that Secure mode was turned off in the edge fabric.

FCR-1034

Message LSAN zone added in backbone fabric.

Message Type LOG

Severity INFO

Probable Cause Indicates that a new logical storage area network (LSAN) zone was added to the backbone fabric.

FCR-1035

Message LSAN zone device <device WWN> added in the backbone fabric.

Message Type LOG

Severity INFO

Probable Cause Indicates that a new device to a logical storage area network (LSAN) zone was added to the backbone

fabric.

FCR-1036

Message LSAN zone <zone name> enabled in the backbone fabric.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified logical storage area network (LSAN) zone was enabled in the backbone

fabric. The enabled LSAN zone configuration is listed.

FCR-1037

Message LSAN zone disabled in the backbone fabric.

Message Type LOG

Severity INFO

Probable Cause Indicates that a logical storage area network (LSAN) zone is disabled in the backbone fabric.

FCR-1038

Message Total zone entries exceeded local fabric limits by <overflow> entries, in zone: <zone

name>, zone limit: <LSAN zone limit>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the number of cfg, zone, or alias entries created in a local fabric is greater than the local

switch's zone database limitations.

Recommended Remove excess cfg, zone, or alias entries so that the number of logical storage area network (LSAN)

zones created is within the range of the local database limitations.

FCR-1039

Message Local LSAN zone <zone name> device entries for backbone LSAN exhausted.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the number of devices in the specified logical storage area network (LSAN) defined in

the backbone fabric is greater than allowed by the local LSAN zone database limitations.

Recommended Action Remove excess device entries from this LSAN zone until the number of devices is within the range of the local LSAN zone database limitations.

FCR-1040

Message Proxy device deleted in the backbone fabric.

Message Type LOG

Severity INFO

Probable Cause Indicates that a proxy device created in the backbone fabric was deleted.

FCR-1041

Message LSAN zone device removed in the backbone fabric.

Message Type LOG

Severity INFO

Probable Cause Indicates that a logical storage area network (LSAN) zone device within the backbone fabric was

removed.

FCR-1042

Message LSAN zone removed in the backbone fabric.

Message Type LOG

Severity INFO

Probable Cause Indicates that a logical storage area network (LSAN) zone within the backbone fabric was removed.

FCR-1043

Message Proxy device created in the backbone fabric.

Message Type LOG

Severity INFO

Probable Cause Indicates that a proxy device was created in the backbone fabric.

FCR-1048

Message On EX port (<port number>) setting port <credit type> credits failed.

Message Type LOG | FFDC

Severity ERROR

Probable Cause Indicates that the indicated credit type was not set. Setting port credits failed.

Recommended Send the First Failure Data Capture (FFDC) log to the support.

Action

FCR-1049

Message EX Port (<port number>) received an ELP command that is not supported.

Message Type LOG

Severity ERROR

Probable Cause Indicates an incoming exchange link parameter (ELP) command that is not supported.

Recommended Use the **portEnable** and **portDisable** to enable or disable the port.

Action

If the problem persists, contact your switch service provider.

FCR-1053

Message Port <port number> was disabled, <disable reason>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified port was disabled because of a mismatched configuration parameter.

Recommended Use the specified disable reason to identify a possible configuration parameter mismatch between the

Action EX_Port and the switch at the other end of the link.

FCR-1054

Message Port <port number> received ILS <command> of incorrect size (<actual payload size>);

valid ILS size is <expected payload size>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that an internal link service (ILS) IU of invalid size was received from the switch on the other

end of the link.

Recommended Check the error message log on the other switch using the **errShow** command for additional

Action messages.

Check for a faulty cable or deteriorated small form-factor pluggable (SFP). Replace the cable or the SFP if necessary.

Run the **portLogDumpPort** command on both the receiving and transmitting ports.

Run the **fabStatsShow** command on the transmitting switch.

If the message persists, collect switch information using the supportSave command, and contact your switch service provider.

FCR-1055

Message Switch with domain ID <domain ID> does not support backbone to edge imports.

Message Type LOG

> INFO Severity

Probable Cause Indicates that a switch that does not support backbone-to-edge routing was detected in the backbone.

Edge-to-edge routing will work, but backbone-to-edge routing may fail.

Recommended No action is required if backbone-to-edge routing is not required. Otherwise, replace the switch with Action

one that supports backbone-to-edge routing.

FCR-1056

Message Switch <switch WWN> with front domain ID <domain ID> does not support backbone to

edge imports.

Message Type LOG

> Severity **INFO**

Probable Cause Indicates that a switch that does not support backbone-to-edge routing is running in the MetaSAN.

Recommended No action is required if backbone-to-edge routing is not needed. Otherwise, replace the switch with

Action one that supports backbone-to-edge routing.

FCR-1057

Message EX Port(<port number>) incompatible long distance parameters on link.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates that the port, which is configured in long distance mode, has incompatible long distance

parameters.

Recommended Check the port configuration on both sides of the link using the portCfgShow command.

Action

Investigate the other switch for more details. Run the **errShow** command on the other switch to view the error log for additional messages.

FCR-1058

Message Port <port number> isolated due to mismatched configuration parameter; <segmentation

reason>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified port was isolated after segmentation caused by mismatched configuration

parameters or by a domain ID assigned by the principal switch that did not match the insistent domain

ID of this port.

Recommended Action Check the switches on both ends of the link for a possible mismatch in switch or port configuration

parameters such as Operating Mode, E_D_TOV, R_A_TOV, Domain ID Offset, and so on.

Run the **portCfgExport** command to modify the appropriate parameters on the local switch.

Run the appropriate configuration command to modify the switch or port parameters on the remote

switch.

FCR-1059

Message EX_Port <port number> was disabled due to an authentication failure.

Message Type LOG

Severity INFO

Probable Cause Indicates that the authentication, which uses the Diffie Hellman - Challenge Handshake Authentication

Protocol (DH-CHAP), failed on the EX_Port.

Recommended Verify that the shared secrets on both sides of the link match.

Action
Disable and enable the ports by using the **portDisable** and the **portEnable** commands to restart

authentication.

FCR-1060

Message EX_Port(<port number>) has an incompatible configuration setting.

Message Type LOG

Severity WARNING

Probable Cause Indicates that virtual channel (VC) Link Init is enabled on the local switch and the remote switch is

negotiating in R_RDY mode. The fabric might not form properly.

Recommended Action

Check the configuration on the local switch using the **portCfgShow** command to verify that the VC Link Init is disabled, if the remote switch is configured in R_RDY mode or only capable of R_RDY mode.

- VC_RDY mode: Virtual channel flow control mode. This is a proprietary protocol.
- R_RDY mode: Receiver-ready flow control mode. This is the Fibre Channel standard protocol, that uses R_RDY primitive for flow control.

FCR-1061

Message Backbone fabric created on port <port number>.

Message Type LOG

Severity INFO

Probable Cause Indicates that a backbone fabric was built on the specified port.

FCR-1062

Message Port <port number> disabled, system only supports <maximum ports> EX Ports.

Message Type LOG

Severity INFO

Probable Cause Indicates that the maximum number of supported EX_Ports was exceeded. To enable the specified

port, disable any other operational port and then re-enable the port.

FCR-1063

Message Fabric <fabric ID> for switch with domain ID: <domain ID> mismatch with local fabric

ID <local fabric ID>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the fabric ID of the switch does not match the local switch.

Recommended Run the **switchShow** command to display the fabric ID. Change the fabric ID to match on both ends

Action by modifying either the local or remote host using the **fcrConfigure** command.

FCR-1064

Message Fabric ID of backbone FC-Routers mismatch or overlap with <overlapping fabric

principle wwn>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that either a backbone fabric split and both are connected to a common edge fabric, or the

fabric ID of two backbone fabrics connected to an edge fabric are the same.

Recommended If the backbone fabric split, merge the fabrics.

If two (or more) backbone fabrics have the same IDs, make the fabric IDs unique using the

fcrConfigure command.

FCR-1065

Message Fabric on port <port number> was assigned two different fabric IDs<fabric message>

Message Type LOG

Severity ERROR

Probable Cause Indicates that another port on the switch is connected to the same edge fabric with a different fabric ID

assignment.

Recommended Change the port fabric ID to the same value as the other ports connected to the edge fabric using the

Action **portCfgExport** command.

FCR-1066

Message Fabric on port <port number> has the same fabric ID as in another fabric switch

<Conflict switch wwn>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that either the fabric split, or there is another fabric (possibly the backbone) that has the

same fabric ID as the fabric connected to the specified port.

Recommended If the fabric split, merge the fabrics and manually re-enable the port.

Action

If there is another fabric with the same ID, change the fabric ID for the port using the **portCfgExport**

command.

FCR-1067

Message Zone configurations, total LSAN zones and aliases, exceeded on port <port number> by

<overflow> entries; max entries: <LSAN zone limit>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the total number of zone configurations created in connected fabric exceeds the

maximum number supported by the Fibre Channel.

The limit includes both active and configured information that is part of be zoning database in the edge

fabric. Non-LSAN zones are not counted in the limit.

Recommended Limit the logical storage area network (LSAN) zoning-related zone configuration in the edge fabric

Action connected to this port.

FCR-1068

Message The FC Routing service is disabled.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the FC Routing service is disabled. This is caused by issuing the **fosconfig --disable**

fcr, configDefault, or the configDownload command with the fcrState set to 2 (disabled). Note that

the FC Routing service is disabled by the factory.

FCR-1069

Message The FC Routing service is enabled.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the FC Routing service is enabled. This is caused by the fosconfig --enable fcr or the

configDownload command with the fcrState set to 1 (enabled). Note that the FC Routing service is

disabled by the factory.

FCR-1070

Message The FC Routing configuration is set to default.

Message Type LOG

Severity INFO

Probable Cause Indicates that the FC Routing configuration is set to the default by the user. This removes all prior FC

Routing configurations.

FCR-1071

Message Port <port number> is changed from non FCR port to FCR port.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the port became an EX_Port.

FCR-1072

Message Port <port number> is changed from FCR port to non FCR port.

Message Type AUDIT | LOG

> Class **CFG**

Severity INFO

Probable Cause Indicates that the port is no longer an EX Port.

FCR-1073

Message Switch with domain ID <domain ID> in fabric <fabric ID> has lower limit of LSAN Zones

supported.

Message Type LOG

> INFO Severity

Probable Cause Indicates that an older version switch in the backbone or edge that supports a different limit of logical

storage area network (LSAN) zones was detected.

Recommended Use the fcrResourceShow command on all Fibre Channel Routers in the Meta-SAN to find lowest

supported LSAN zone limits. Ensure the total number of LSAN zones in the Meta-SAN are within the

lowest supported limit of LSAN zones.

FCR-1074

Message HA sync lost as remote CP supports only <LSAN Count> LSAN Zones.

Message Type LOG

Action

Severity **ERROR**

Probable Cause Indicates that the remote control processor (CP) has older firmware, which supports a lower number of

logical storage area network (LSAN) zones. This is causing the loss of high availability (HA) sync.

Recommended Keep the number of LSAN zones to the lower limit of the two CPs or upgrade the remote CP.

Action

FCR-1075

Message Zone Name configuration is larger than <Zone Name Limit> characters in the edge fabric

connected to port <port number>.

Message Type LOG

FOS-90x-Message-RM103 Broadcom

Severity ERROR

Probable Cause Indicates that the zone name configuration size created in the connected fabric exceeds the maximum

supported by the FC Router. This size is equal to the total number of characters used by all the zone

names in the edge fabric zoning database.

The limit includes both LSAN and non-LSAN zone names defined in the zoning name database of the

edge fabric.

Recommended

Action

Limit the zone configuration size in the edge fabric connected to this port by either reducing the

number of zones or changing the zone names to smaller names.

FCR-1076

Message Port <port number> disabled, system only supports <maximum fds> front domains.

Message Type LOG

Severity INFO

Probable Cause Indicates that the maximum number of supported front domains was exceeded. To enable the

specified port, disable any other operational front domain and then re-enable the port.

Recommended

Action

Make sure to remain within the maximum number of supported front domains.

FCR-1077

Message Port <port number> rejected fabric binding request/check from the M-Model switch;

<Fabric ID>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that an M-Model edge switch attempted to either activate or check the fabric binding. This

port will be disabled if this event occurred during a check of fabric binding and not during failure to activate fabric binding. The error is caused when the binding list details configured on the M-Model switch do not match with the currently configured front port domain ID and WWN of the EX_Port on

which this operation was attempted.

Recommended Ensure that the M-Model switch has the same currently configured details such as the front port

Action domain ID and WWN of the EX Port on which this operation was attempted.

FCR-1078

Message LSAN name <LSAN name> is too long. It is dropped.

Message Type LOG

Severity WARNING

Probable Cause Indicates the length of the logical storage area network (LSAN) name exceeds the limit of 64

characters.

Recommended

Change the name and reactivate the zone database.

Action

FCR-1079

Message Domain <Domain> has conflict matrix database with local domain.

Message Type LOG

Severity WARNING

Probable Cause Indicates the specified domain has a different matrix database from the local domain.

Recommended Change the matrix database.

Action

FCR-1080

Message The pause response timer for domain <Domain> expired.

Message Type LOG

Severity WARNING

Probable Cause Indicates that during the Coordinated HotCode protocol, a switch in the fabric has not responded to the

pause message which prevented the protocol from completing. Any data traffic disruption observed

during the firmware download may have been the result of the rejected pause message.

FCR-1081

Message The pause message is rejected by the domain <Domain>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that during the Coordinated HotCode protocol, a switch in the fabric has rejected the pause

message which prevented the protocol from completing. Any data traffic disruption observed during

the firmware download may have been the result of the rejected pause message.

FCR-1082

Message The pause retry count is exhausted for the domain < Domain >.

Message Type LOG

Severity WARNING

Probable Cause Indicates that during the Coordinated HotCode protocol, a switch in the fabric did not accept the pause

message which prevented the protocol from completing. Any data traffic disruption observed during

the firmware download may have been the result of this issue.

FCR-1083

Message The resume message is rejected by the domain <Domain>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that during the Coordinated HotCode protocol, a switch in the fabric has rejected the pause

message which prevented the protocol from completing. Any data traffic disruption observed during

the firmware download may have been the result of the rejected resume message.

FCR-1084

Message The resume retry count is exhausted for the domain <Domain>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that during the Coordinated HotCode protocol, a switch in the fabric did not accept the

resume message which prevented the protocol from completing. Any data traffic disruption observed

during the firmware download may have been the result of this issue.

FCR-1085

Message HA sync lost as remote CP does not support FCR based matrix.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the remote control processor (CP) has older firmware, which does not support the FCR-

based matrix while the local CP has the feature enabled. This is causing the loss of the high availability

(HA) synchronization.

Recommended Disable the FCR-based matrix or upgrade the remote CP.

Action

FCR-1086

Message HA sync lost as remote CP does not support 8Gb/s-capable FC based EX Ports.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the remote control processor (CP) has older firmware, which does not support 8Gb/s-

capable FC based EX_Port. This is causing the loss of the high availability (HA) synchronization.

Recommended

Disable 8Gb/s-capable FC based EX_Ports or upgrade the remote CP.

FCR-1087

Message ExPort <ExPort > connects to fabric <fabric > with capability to use XISL domain

<Domain >.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the EX_Port connects to the logical fabric containing a domain that has the capability to

use extended ISL (XISL).

Recommended Disable "Allow to use XISL" mode of the domain by using the **configure** command.

Action

FCR-1088

Message LSAN <Enforce/Speed> tag <Tag Name> added.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the user has added a LSAN tag.

FCR-1089

Message LSAN <Enforce/Speed> tag <Tag Name> removed.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the user has removed a LSAN tag.

FCR-1091

Message Backbone Fabric ID changed to <Tag>.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the backbone fabric ID has been changed.

FCR-1092

Message FCR ELS trap entries exhausted.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the FCR ELS trap entries are exhausted.

Recommended Execute the **supportSave** command and contact your switch service provider.

Action

FCR-1093

Message <Message> <Master or Slave> interopmode conflicts with <Master or Edge fabric>.

Disabling the port.

Message Type LOG

Severity INFO

Probable Cause Indicates that the EX Port (master or slave in case of a trunk) is disabled due to interop mode conflict

with either trunk master or edge fabric.

Recommended Configure the master or slave EX Port with the trunk master or edge fabric interop mode.

Action

FCR-1094

Message No Integrated Routing license present. EX-Port <ExPort> will not perform device

sharing with other Brocade Native mode fabric(s).

Message Type LOG

Severity WARNING

Probable Cause Indicates that an EX Port has been configured in Brocade Native mode. Device sharing will not occur

with other Brocade Native mode fabrics because the Integrated Routing license is not installed.

Recommended Install Integrated Routing license if device sharing is needed with other Brocade Native mode fabrics.

Action

FCR-1095

Message The EX-Port <ExPort> is configured in '<ExPortMode>' mode which is no longer

supported, hence will be disabled.

Message Type LOG

Severity WARNING

Probable Cause Indicates that an EX Port has been configured in 'McData/Open/NOS' mode. During HA failover, the

EX Port will be disabled.

Recommended

Action

Remove the 'McData/Open/NOS' interop modes in all EX_Ports

FCR-1096

Message Failed to allocate <data type> for <operation phase>: port <port number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the authentication process failed because the system is low on memory.

Data type is the payload or structure that failed to get memory.

Operation phase specifies which operation of a particular authentication phase failed.

Recommended

Action

Usually this problem is transient. The authentication may fail.

Reinitialize authentication using the portDisable and portEnable commands or the switchDisable

and switchEnable commands.

If the message persists, run the **supportFtp** command (as needed) to set up automatic FTP transfers;

then run the supportSave command and contact your switch service provider.

FCR-1097

Message Failed to get <data type> for <message phase> message: port <port number>, retval

<error code>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the authentication process failed to get a particular authentication value at certain phase.

Data type is the payload or structure that failed to get memory.

Recommended Usually this problem is transient. The authentication may fail.

Action
Reinitialize authentication using the **portDisable** and **portEnable** commands or the **switchDisable**

and switchEnable commands.

If the message persists, run the **supportFtp** command (as needed) to set up automatic FTP transfers; then run the **supportSave** command and contact your switch service provider.

FCR-1098

Message Invalid message code for <message phase> message: port <port number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates the receiving payload does not have valid message code for a particular authentication

phase.

Recommended

Action

Usually this problem is transient. The authentication may fail.

Reinitialize authentication using the **portDisable** and **portEnable** commands or the **switchDisable**

and switchEnable commands.

If the message persists, run the **supportFtp** command (as needed) to set up automatic FTP transfers;

then run the **supportSave** command and contact your switch service provider.

FCR-1099

Message HA sync lost as remote CP does not support Inter Chassis Link EX Ports.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the remote control processor (CP) has older firmware that does not support inter-chassis

link (ICL) EX_Ports. This is causing loss of the high availability (HA) synchronization.

Recommended

Action

Disable EX Ports on ICL links or upgrade the firmware on remote CP to v7.2.0 or later.

FCR-1100

Message 16G EX_Port ICL topology for fabric <Fabric ID> is unbalanced.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the current configuration of the EX Port inter-chassis link (ICL) paths are unbalanced.

Recommended

Action

Investigate the current EX_Port ICL configuration to ensure that all recommendations for cabling are satisfied. Once cabling recommendations are satisfied, FCR-1101 message will be generated

confirming ICL paths are balanced.

FCR-1101

Message 16G EX Port ICL topology for fabric <Fabric ID> is balanced.

Message Type LOG

Severity INFO

Probable Cause Indicates that the existing EX_Port inter-chassis link (ICL) configuration that was resulting in an

unbalanced topology for the corresponding fabric has been corrected.

FCR-1102

Message ICL EX Port <Port Numbers> need to be present in base switch to make a recommended

topology.

Message Type LOG

Severity WARNING

Probable Cause Indicates that some of the ICL ports in a quad small form-factor pluggable (QSFP) are not present in

the base switch. Ideally, all ports in the QSFP group should be present in the base switch.

Recommended Move the specified ICL EX Ports of the QSFP group into the base switch using the Iscfg --config

Action command.

FCR-1103

Message EX Port <Port Number> ELS PLOGI from did <DID> to sid <SID> wwn <device wwn> NOT ZONED

Message Type LOG

Severity WARNING

Probable Cause Indicates that FCR has received an ELS request for unzoned devices

Recommended Send the First Failure Data Capture (FFDC) log to the support.

Action

FCR-1104

Message In Edge fabric <Fabric-id> EX-Port <EX-Port>, domain-id <old_did> changes to

<new did>

Message Type LOG

Severity INFO

Probable Cause Indicates that Phantom domain-id got changed in edge fabric

FCR-1105

Message FIPS mode is enabled. SHA-1 hash type is not recommended in edge fabric <edge_fabric>

connected to EX-Port <port number>.

Message Type LOG

Severity WARNING

Probable Cause Indicates the received authentication payload from edge fabric contains SHA-1 hash type.

Recommended SHA-1 is not a recommended setting when FIPS is enabled in edge fabric.

Action

FCR-1106

Message HA sync lost as remote CP does not support 4K proxy devices on EX Ports.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the active control processor (CP) has more than 2000 proxies downloaded per EX_Port

but the remote CP does not support the same.

Recommended Remote CP needs to be upgraded to v7.4.0 or later firmware version to support the same.

Action

FCR-1107

Message EICL License is not present and the port <Port Number> will be disabled.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Enterprise inter-chassis link (EICL) license is absent and the maximum number of

directly connected chassis allowed is three.

Recommended Install EICL license.

Action

FCR-1108

Message EICL License limit is exceeded and the port <Port Number> will be disabled.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Enterprise inter-chassis link (EICL) license is present and the number of directly

connected chassis has exceeded the maximum allowable limit of nine.

Recommended

Disable unwanted directly connected ICL links.

Action

FCR-1109

Message Either domain <Domain> in BB fabric has PRE 7.4 build or EX-Port with RFID is disabled,

which will restrict the Location embedded zone feature to work as expected. Dropped

LSAN <ZoneName>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that some of the switches in the backbone fabric have pre v7.4 build.

Recommended Upgrade all switches in the backbone fabric to 7.4 or above version.

Action

FCR-1110

Message EX Port Integrated Routing Port on Demand License limit <limit > is exceeded and the

port <Port Number> will be disabled.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the user exceeded the number of licensed EX port limit.

Recommended Disable unwanted port to enable this port or get Integrated Routing Port on Demand (PoD) license to

Action get more links.

FCR-1111

Message License not Installed for Integrated Routing and the port <Port Number> will be

disabled.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the license not installed to enable EX port.

Recommended Install Licence for Integrated Routing.

Action

FCR-1112

Message EX-Port is not supported when it is connected to the Analytics Monitoring Platform

(AMP). Disabling port <Port Number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that Fibre Channel Routing (FCR) feature is not supported with Analytics Monitoring

Platform.

Recommended

Action

Not a supported configuration when EX-Port is connected to Brocade Analytics Monitoring Platform.

FCR-1113

Message HA sync lost as remote CP supports only <Device Count> devices.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the remote control processor (CP) has older firmware, which supports a lower number of

devices. This is causing the loss of high availability (HA) sync.

Recommended Keep the number of devices to the lower limit of the two CPs or upgrade the remote CP.

Action

FCR-1114

Message FCR router port <port number> cost changed to <cost>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that router port cost has been changed.

FCR-1115

Message FID <FID>: The QSFP connection topology on core chip is not recommended

Message Type LOG

Severity WARNING

Probable Cause Indicates that the current QSFP connection topology is not recommended.

Recommended

Use the switchShow, isIShow, and IsdbShow commands to identify the QSFP connectivity to Action

ensure that all recommendations for cabling is satisfied.

FCR-1116

Message FID <FID>: The existing QSFP connections causing core-edge-core routing have been

corrected

Message Type LOG

> Severity INFO

Probable Cause Indicates that the current QSFP connection that was resulting in unbalanced topology has been

corrected.

FCR-1117

Message Switch internal lookup got failed, for may lose the EX Port data

Message Type LOG

> Severity **ERROR**

Probable Cause Logical fabric lookup would have got failed

Recommended Reboot the switch or disable/enable all the EX_port configuration

Action

FCR-1118

Message No Integrated Routing license present. EX-Port will not perform device sharing with

other Brocade Native mode fabric(s).

Message Type LOG

> Severity WARNING

Probable Cause Indicates that an EX Port has been configured in Brocade Native mode. Device sharing will not occur

with other Brocade Native mode fabrics because the Integrated Routing license is not installed.

Recommended Install Integrated Routing license if device sharing is needed with other Brocade Native mode fabrics.

Action

FCR-1119

Message The EX-Port <PORT> is set to Fabric ID <FID>

AUDIT Message Type

> Class **CFG**

FOS-90x-Message-RM103 Broadcom

Severity INFO

Probable Cause Indicates that the edge fabric id has been changed.

FCR-1120

Message The EX-Port <PORT> is set to Front Domain ID <DOMID>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the Front domain id has been changed.

FCR-1121

Message Alias <ALIASNAME> is set for FID <FID>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the FID alias has been configured.

FCR-1122

Message Alias is deleted for FID <FID>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the FID alias has been deleted.

FCR-1123

Message Max LSAN count set to <LSANCOUNT>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the max Isan count is changed.

FCR-1124

Message Shortest IFL mode <SIFLMODE>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the shortest IFL mode is changed.

6.39 FICN Messages

FICN-1003

Message FICON Tape Emulation License Key is not installed.

Message Type LOG

Severity WARNING

Probable Cause Indicates FICON Tape Emulation requires a License Key.

Action

FICN-1004

Message FICON XRC Emulation License Key is not installed.

Message Type LOG

Severity WARNING

Probable Cause Indicates FICON eXtended Remote Copy (XRC) Emulation requires a License Key.

Recommended Use the appropriate License Key.

Action

FICN-1005

Message FICON GEPort <GE port number> TID <Tunnel number> Feature Change verified Xrc <1 or

0 - XRC Emulation Enabled or Disabled> TapeWrt <1 or 0 - Tape Write Emulation Enabled or Disabled> TapeRd <1 or 0 - FICON Tape Read Emulation Enabled or Disabled> TinTir

<1 or 0 - FICON TIN/TIR Emulation Enabled or Disabled> DvcAck <1 or 0 - FICON Device</pre> Level Ack Emulation Enabled or Disabled> RdBlkId <1 or 0 - FICON Write Emulation Read Block ID Emulation Enabled or Disabled>.

Message Type LOG

> Severity **INFO**

Probable Cause Indicates the configuration was changed manually.

FICN-1006

Message

FICON GEPort <GE port number> TID <Tunnel number> Feature Change failed Xrc < 1 or 0 - XRC Emulation Enabled or Disabled> TapeWrt <1 or 0 - Tape Write Emulation Enabled or Disabled> TapeRd <1 or 0 - FICON Tape Read Emulation Enabled or Disabled> TinTir

<1 or 0 - FICON TIN/TIR Emulation Enabled or Disabled> DvcAck <1 or 0 - FICON Device Level Ack Emulation Enabled or Disabled> RdBlkId <1 or 0 - FICON Write Emulation Read Block ID Emulation Enabled or Disabled>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the feature change has failed because the FCIP tunnel ID associated with the FICON

tunnel is still active.

Recommended Disable the applicable FCIP tunnel to make the feature change effective.

Action

FICN-1007

Message DevDiskEgr:FICON Selective Reset:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> State=0x<Current Emulation State>

stat array=0x<the Last 4 Status values that were received from the device>.

Message Type LOG

Severity ERROR

Probable Cause Indicates a Selective Reset from the channel was received as either a normal part of path recovery or

the starting sequence in an error case.

Recommended If there was a job failure associated with this event, contact your vendor's customer support.

Action

FICN-1008

Message DevDiskEgr:FICON Purge Path received Path=0x<VEPortNumber HostDomain HostPort

DeviceDomcontactain><DevicePort LPAR CUADDR DeviceAddr>.

Message Type LOG

Severity ERROR

Probable Cause Indicates a FICON Purge Path was received from the channel as a part of path recovery.

Recommended If there was a job failure associated with this event, contact your vendor's customer support for

Action assistance.

FICN-1009

Message DevIng:CmdReject Sense Data rcvd:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> LastCmds=0x<the Last 4 commands issued to the device> Sense Data:Bytes0-0xB=0x

bytes 0-3 of sense data from the device><bytes 4-7 of sense data from the device><bytes 8-0x0b of sense data from the

device>.

Message Type LOG

Severity INFO

Probable Cause Indicates a Unit Check status was received from a device and a sense command was issued to read

the sense data.

Recommended If there was a job failure associated with this event, contact your vendor's customer support for

Action assistance.

FICN-1010

Message DevDiskEgr:Device level exception flag found for Path=0x<VEPortNumber HostDomain

HostPort DeviceDomain><DevicePort LPAR CUADDR DeviceAddr>: Oxid=0x<The OXID that was

reported in the Device Level Exception Frame>.

Message Type LOG

Severity INFO

Probable Cause Indicates a Device Level Exception frame was received from the FICON channel.

Recommended If there was a job or I/O failure associated with this event, contact your vendor's customer support for

Action assistance.

FICN-1011

Message DevDiskIng:XRC Incorrect RRS SeqNum Rcvd Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> Expected=0x<The RRS Sequence number that was expected from the device> Received=0x<The RRS Sequence number that was

actually received from the device> Oxid=0x<The data frame's OXID>.

Message Type LOG

Severity ERROR

Probable Cause Indicates the Control unit or device presented a Read Record Set Sequence number different from the

SDM's expected sequence number.

Recommended If there was an XRC volume or session suspended associated with this event, contact your vendor's

Action customer support for assistance.

FICN-1012

Message DevDiskIng: Device level exception found for Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr>: Oxid=0x<The OXID that was reported

in the Device Level Exception Frame>.

Message Type LOG

Severity ERROR

Probable Cause Indicates a Device Level Exception frame received from the FICON direct attached storage device

(DASD) Control Unit.

Recommended

Action

If there was a job or I/O failure associated with this event, contact your vendor's customer support for

assistance.

FICN-1013

Message DevDiskIng:Status=0x<Status that was received from the DASD device in an odd state>

received in odd state=0x<The current emulation state> from Path=0x<VEPortNumber HostDomain HostPort DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> sent LBY.

Message Type LOG

Severity INFO

Probable Cause Indicates that when the device sent the status in an incorrect state, the emulation processing rejected

the status with an LBY frame.

Recommended If there was a job or I/O failure associated with this event, contact your vendor's customer support for

assistance.

FICN-1014

Message DevEgr:Device level exception flag found for Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr>: Oxid=0x<The OXID used to deliver

the non-AS Device Level Exception>.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates a frame was received that indicated a device level exception.

Recommended If there was an I/O failure associated with this event, contact your vendor's customer support for

Action assistance.

FICN-1015

Message DevEgr:cuPath=0x<VEPortNumber HostDomain HostPort DeviceDomain>*****:Discarding

Invalid LRCd SOF=0x<The invalid Frame's SOF value (SOFiX or SOFnx)> count=<The total number of frames that have been received from the peer with incorrect FICON LRC

values>.

Message Type LOG

Severity ERROR

Probable Cause Indicates a frame was received from the peer emulation processing with an invalid Longitudinal

Redundancy Checking (LRC) values. This indicates data corruption between the emulation processing

components.

Recommended

Contact your vendor's customer support for assistance.

FICN-1016

Message DevIng: Received Logical Path Removed response: Path=0x<VEPortNumber HostDomain

HostPort DeviceDomain><DevicePort LPAR><CUADDR>**.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates the FICON Control Unit sent a Logical Path Removed (LPR) frame to the FICON channel.

FICN-1017

Message DevIng: Received Logical Path Established response: Path=0x<VEPortNumber HostDomain

HostPort DeviceDomain><DevicePort LPAR><CUADDR>**.

Message Type LOG

Severity INFO

Probable Cause Indicates the FICON Control Unit sent an Logical Path Established (LPE) frame to the FICON channel.

FICN-1018

Message DevIng:FCUB Lookup failed for Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR>*****.

Message Type LOG

Severity ERROR

Probable Cause Indicates the FICON Control Unit sent a frame that cannot be associated with a FICON Control Unit

number (CUADDR).

Recommended Contact your vendor's customer support for assistance.

Action

FICN-1019

Message DevTapeEgr:AS Link Level Reject (LRJ) from Chan on Path=0x<VEPortNumber HostDomain

HostPort DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> LastCmd=0x<the Last 4 commands issued to the device> LastStatus=0x<the Last 4 status values received from

the device>.

Message Type LOG

Severity ERROR

Probable Cause Indicates the FICON channel indicated in the path issued a Link Level Reject (LRJ) frame for a

sequence from the device.

Recommended If there was a job failure associated with this event, contact your vendor's customer support for

Action assistance.

FICN-1020

Message DevTapeEgr:FICON Cancel received Path=0x<VEPortNumber HostDomain HostPort

sflags=0x<the current emulation status control flags for the device>.

Message Type LOG

Severity WARNING

Probable Cause Indicates the FICON channel issued a Cancel sequence for a device in emulation.

Recommended If there was an unexpected job failure associated with this event, contact your vendor's customer

Action support for assistance.

FICN-1021

Message DevTapeEgr:FICON Tape Cancel:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> Elapsed Time=<the current SIO time in seconds for the device>.<the current SIO time in milliseconds for the device>

seconds.

Message Type LOG

Severity WARNING

Probable Cause Indicates the FICON channel issued a Cancel sequence for a device in emulation.

Recommended If there was an unexpected job failure associated with this event, contact your vendor's customer

Action support for assistance.

FICN-1022

Message DevTapeEgr:FICON Selective Reset:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> State=0x<the current state of the device that received the selective reset> statArray=0x<the last 4 status values

received from the device> cmdArray=0x<the last 4 commands that were issued to the device> tflags=0x<the current emulation tape control flags for the device> sflags=0x<the current emulation status control flags for the device>.

Message Type LOG

Severity ERROR

Probable Cause Indicates the FICON channel issued a Selective Reset for a device that was active in emulation.

Recommended If there was an unexpected job failure associated with this event, contact your vendor's customer Action support for assistance.

FICN-1023

Message DevTapeEgr:FICON Selective Reset:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> Elapsed Time=<the current SIO time in seconds for the device>.<the current SIO time in milliseconds for the device>

seconds.

Message Type LOG

Severity ERROR

Probable Cause Indicates the FICON channel issued a Selective Reset sequence for a device.

Recommended If there was an unexpected job failure associated with this event, contact your vendor's customer

support for assistance.

FICN-1024

Message DevTapeEgr:FICON Purge received Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr>.

Message Type LOG

Action

Action

Severity ERROR

Probable Cause Indicates the FICON channel issued a Purge Path command sequence for a device.

Recommended If there was an unexpected job failure or I/O error associated with this event, contact your vendor's

customer support for assistance.

FICN-1025

Message DevTapeIng:Auto Sense Data received on Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> Bytes0-0xB=0x
bytes 0-3 of sense data from the device><bytes 4-7 of sense data from the device><bytes 8-0x0b of sense

data from the device>.

Message Type LOG

WARNING Severity

Probable Cause Indicates the FICON Tape Write Pipelining processed sense data from a FICON device.

Recommended If there was an unexpected job failure or I/O error associated with this event, contact your vendor's Action

customer support for assistance.

FICN-1026

Message DevTapeIng:UnusualStatus:WriteCancelSelr:Generating Final Ending Status

Path=0x<VEPortNumber HostDomain HostPort DeviceDomain><DevicePort LPAR CUADDR

DeviceAddr>.

Message Type LOG

> Severity INFO

Probable Cause Indicates the FICON Tape Write Pipelining is completing an emulated Selective Reset sequence.

Recommended If there was an unexpected job failure or I/O error associated with this event, contact your vendor's

Action customer support for assistance.

FICN-1027

Message DevTapeIng: Device level exception found for Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr>: Oxid=0x<The OXID of the frame that

included the Device Level Exception>.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates an active emulation device delivered a Device Level Exception frame to the emulation

processing.

Recommended If there was an unexpected job failure or I/O error associated with this event, contact your vendor's

Action customer support for assistance.

FICN-1028

Message HostDiskIng:FICON Cancel received Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> state=0x<The current emulation state

of the device>.

Message Type LOG

> WARNING Severity

Probable Cause Indicates an active emulation device received a cancel operation from the FICON channel.

Recommended Action If there was an unexpected job failure or I/O error associated with this event, contact your vendor's customer support for assistance.

FICN-1029

Message HostDiskIng:FICON Selective Reset:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> state=0x<The current emulation state of the device> LastCmds=0x<The last 4 commands received from the channel for this device> LastStatus=0x<The last 4 status values presented to the channel for this

device>.

Message Type LOG

Severity ERROR

Probable Cause Indicates an active disk emulation device received a Selective Reset from the FICON channel.

Recommended If there was an unexpected job failure or I/O error associated with this event, contact your vendor's Action customer support for assistance.

FICN-1030

Message HostDiskIng:FICON Purge received:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr>.

Message Type LOG

Severity ERROR

Probable Cause Indicates an active disk emulation device received a FICON Purge Path from the channel.

Recommended If there was an unexpected job failure or I/O error associated with this event, contact your vendor's

Action customer support for assistance.

FICN-1031

Message HostDiskIng:FICON System Reset received on Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR><CUADDR>**.

Message Type LOG

Severity WARNING

Probable Cause Indicates the FICON channel sent a System Reset to the disk control unit.

Recommended No action is required. The MVS system was either set to initial program load (IPL) or performing error

Action recovery.

FICN-1032

Message HostDiskIng:XRC Read Channel Extender Capabilities detected on Path: 0x<VEPortNumber

HostDomain HostPort DeviceDomain > DevicePort LPAR CUADDR DeviceAddr >.

Message Type LOG

Severity INFO

Probable Cause Indicates the eXtended Remote Copy (XRC) System Data mover was restarted to discover the

capabilities of the channel extension equipment.

Recommended

Action

No action is required. This is a part of the XRC initialization.

FICN-1033

Message HostEgr:Logical Path Established on Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR><CUADDR>**.

Message Type LOG

Severity INFO

Probable Cause Indicates the peer-side FICON Control Unit has accepted a logical path establishment command

sequence with the FICON channel.

Recommended

Action

No action is required. This is a part of the FICON path initialization.

FICN-1034

Message HostEgr:Discarding Invalid LRCd Frame on Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort>***** count=<The total number of frames that have been

received with an invalid LRC.>.

Message Type LOG

Severity ERROR

Probable Cause Indicates the channel emulation processing received a frame with an invalid FICON LRC from the

peer. This indicates that the channel side noted corruption from the Control Unit- or device-side

processing.

Recommended Contact your vendor's customer support for assistance.

Action

FICN-1035

Message HostIng:FICON System Reset received on Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort><LPAR><CUADDR>**.

Message Type LOG

Severity WARNING

Probable Cause Indicates a locally connected FICON channel issued a System Reset to the specified FICON Control

Unit.

Recommended

Action

No action is required. This is a part of the FICON path initialization.

FICN-1036

Message HostIng:FICON RLP Request on Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort><LPAR><CUADDR>**.

Message Type LOG

Severity INFO

Probable Cause Indicates a locally connected FICON channel issued a Remove Logical Path sequence to the specified

FICON Control Unit.

Recommended No action is required. This is a part of the FICON path deactivation.

Action

FICN-1037

Message Hosting: FICON ELP Request on Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort><LPAR><CUADDR>**.

Message Type LOG

Severity INFO

Probable Cause Indicates a locally connected FICON channel issued an Establish Logical Path sequence to the

specified FICON Control Unit.

Recommended No action is required. This is a part of the FICON path activation.

Action

FICN-1038

Message fcFicIngHost:FDCB Lookup failed for Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort>*****.

Message Type LOG

Severity ERROR

Probable Cause Indicates a locally connected FICON channel sent a frame that could not be associated with a FICON

device.

Recommended

Contact your vendor's customer support for assistance.

Action

FICN-1039

Message HostIng: FCUB Lookup failed for Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR>******.

Message Type LOG

Severity ERROR

Probable Cause Indicates a locally connected FICON channel sent a frame that could not be associated with a FICON

Control Unit.

Recommended

Action

Contact your vendor's customer support for assistance.

FICN-1040

Message HostTapeEgr:Tape:CmdReject Sense Data Rcvd:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> LastCmds=0x<Last 4 commands received from the channel for this device> SenseData:Bytes0-0xB=0x<Bytes 0-3 of sense data from the device><Bytes 4-7 of sense data from the device><Bytes 8-0x0b of sense data

from the device>.

Message Type LOG

Severity ERROR

Probable Cause Indicates an active disk emulation device received a FICON Purge Path from the channel.

Action

Recommended

If there was an unexpected job failure or I/O error associated with this event, contact your vendor's

customer support for assistance.

FICN-1041

Message HostTapeEgr: AS Link Level Reject (LRJ) from CU Rx Path=0x<VEPortNumber HostDomain

 $\label{loss_port_def} \begin{tabular}{ll} HostPort\ DeviceDomain><DevicePort\ LPAR\ CUADDR\ DeviceAddr>\ LastCmd=0x<Last\ 4\ commands issued to this device from the channel>\ LastStatus=0x<Last\ 4\ status\ values\ sent\ to the channel is to the channel is the$

the channel from this device>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that a Link Level Reject (LRJ) received from a device indicates that the Control Unit has lost

the logical path to the Logical Partition (LPAR).

Recommended If this was an unexpected event, contact your vendor's customer support for assistance.

Action

FICN-1042

Message HostTapeIng:FICON Cancel received Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> state=0x<the current emulation state

for this device>.

Message Type LOG

Severity WARNING

Probable Cause Indicates a job was canceled during a Tape Write Pipelining.

Recommended If this was an unexpected event (cancel is normally an operator event), contact your vendor's customer

Action support for assistance.

FICN-1043

Message HostTapeIng::FICON Selective Reset:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> state=0x<the current emulation state for this device> LastCmds=0x<the last 4 commands received from the channel for this device> LastStatus=0x<the last 4 status values presented to the channel for this

device>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that protocol errors in emulation in the Control Unit or network errors can cause a Selective

Reset.

Recommended If this was an unexpected event, contact your vendor's customer support for assistance.

Action

FICN-1044

Message HostTapeIng:FICON Selective Reset:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> Elapsed Time=<the number of seconds since the last IO started for this device>.<the number of milliseconds since the last

IO started for this device> seconds.

Message Type LOG

Severity ERROR

Probable Cause Indicates that protocol errors in emulation in the Control Unit or network errors can cause a Selective

Reset.

Recommended If this was an unexpected event, contact your vendor's customer support for assistance.

Action

FICN-1045

Message HostTapeIng:FICON Purge received:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr>.

Message Type LOG

Severity WARNING

Probable Cause Indicates a Purge Path was received from the locally connected FICON channel. This is performed

during the path recovery.

Recommended If this was an unexpected event, contact your vendor's customer support for assistance.

Action

FICN-1046

Message HostTapeIng:LRJ received on Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> lastCmds=0x<Last 4 commands received from the channel for this device> lastStatus=0x<Last 4 status values presented to the

channel for this device> treating as system reset event.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a Link Level Reject (LRJ) from a FICON channel indicates that the channel no longer

has a path established to the Control Unit.

Recommended This is normally an unexpected event; contact your vendor's customer support for assistance.

Action

FICN-1047

Message fcFicSetEmulation:Path=0x<VEPortNumber HostDomain HostPort DeviceDomain><DevicePort

state=0x<The new state to which the device is transitioning>.

Message Type LOG

Severity ERROR

Probable Cause Indicates there is an internal emulation error. This message should not be encountered.

Recommended This is an unexpected event; contact your vendor's customer support for assistance.

Action

FICN-1048

Message DevDiskEgr:FICON Cancel received Path=0x<VEPortNumber HostDomain HostPort

the FICON device> sflags=0x<The current emulation status flags>.

LOG Message Type

> Severity WARNING

Probable Cause Indicates the operator has canceled a read or write job.

Action

Recommended

FICN-1049

Message ProcessIngTirData:Lost Logical Path for Path=0x<VEPortNumber HostDomain HostPort

This is an unexpected event; contact your vendor's customer support for assistance.

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr><CUADDR>** Index=<Current processing

index in the TIR data from the locally connected channel or control unit>.

Message Type LOG

> Severity WARNING

Probable Cause Indicates a TIR received from a FICON endpoint indicates that it no longer has an established path to

its peer.

Recommended This is an unexpected event; contact your vendor's customer support for assistance.

Action

FICN-1050

Message ProcessEgrTirData:Lost Logical Path for Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr><CUADDR>** Index=<Current processing

index in the TIR data from the remotely connected channel or control unit>.

Message Type LOG

> Severity WARNING

Probable Cause Indicates a TIR received from a far-side FICON endpoint indicates that it no longer has an established

path to its peer.

Recommended This is an unexpected event; contact your vendor's customer support for assistance.

Action

FICN-1051

Message XRC Session Established: SessID=<SDM Assigned Session ID>, Path=0x<VEPortNumber

HostDomain HostPort DeviceDomain><DevicePort LPAR CUADDR DeviceAddr>

Message Type LOG

> INFO Severity

Probable Cause Indicates a PSF command has been received to initiate an eXtended Remote Copy (XRC) session

with the extended direct attached storage device (DASD) device.

Recommended

No action is required. This is a part of the XRC session establishment.

FICN-1052

Message XRC Session Terminated: SessID=<SDM Assigned Session ID>, Path=0x<VEPortNumber

HostDomain HostPort DeviceDomain > DevicePort LPAR CUADDR DeviceAddr >.

Message Type LOG

Action

INFO Severity

Probable Cause Indicates a PSF command has been received to break an eXtended Remote Copy (XRC) session with

the extended direct attached storage device (DASD) device.

If this was an unexpected event, contact your vendor's customer support for assistance. Recommended

Action

FICN-1053

Message XRC Withdraw From Session: SessID=<SDM Assigned Session ID>, Path=0x<VEPortNumber

HostDomain HostPort DeviceDomain > DevicePort LPAR CUADDR DeviceAddr >.

Message Type LOG

> Severity INFO

Probable Cause Indicates a PSF command has been received to withdraw from the eXtended Remote Copy (XRC)

session with the extended direct attached storage device (DASD) device.

Recommended If this was an unexpected event, contact your vendor's customer support for assistance.

Action

FICN-1054

Message XRC Device Suspended: SessID=<SDM Assigned Session ID>, Path=0x<VEPortNumber

HostDomain HostPort DeviceDomain > DevicePort LPAR CUADDR DeviceAddr >.

Message Type LOG

> WARNING Severity

Probable Cause Indicates a PSF command has been received to suspend an eXtended Remote Copy (XRC) session

with the extended direct attached storage device (DASD) device.

Recommended If this was an unexpected event, contact your vendor's customer support for assistance.

Action

FICN-1055

Message XRC All Devices Suspended: SessID=<SDM Assigned Session ID>, Path=0x<VEPortNumber

HostDomain HostPort DeviceDomain > DevicePort LPAR CUADDR DeviceAddr >.

Message Type LOG

Severity WARNING

Probable Cause Indicates a PSF command has been received to suspend all extended direct attached storage device

(DASD) devices from the eXtended Remote Copy (XRC) session.

Recommended If this was an unexpected event, contact your vendor's customer support for assistance.

Action

FICN-1056

Message FICON Emulation Error Error Code=<The internal emulation error code value>,

Path=0x<VEPortNumber HostDomain HostPort DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> LastStates=0x<The 4 oldest emulation states for this device><The prior emulation state for this device><The current emulation state for this device>.

Message Type LOG

Severity ERROR

Probable Cause Indicates an internal coding error within emulation processing.

Recommended This is an unexpected event; contact your vendor's customer support for assistance.

Action

FICN-1057

Message Error return from frame generation processing for a FICON device:

Path=0x<VEPortNumber HostDomain HostPort DeviceDomain><DevicePort LPAR CUADDR

DeviceAddr>.

Message Type LOG

Severity ERROR

Probable Cause Indicates an internal resource shortage caused an error so that an emulation frame could not be

created and sent to a device.

Recommended This is an unexpected event; contact your vendor's customer support for assistance.

Action

FICN-1058

Message Error return from frame generation processing for a FICON control unit:

Path=0x<VEPortNumber HostDomain HostPort DeviceDomain><DevicePort><LPAR><CUADDR>.

LOG Message Type

> Severity **ERROR**

Probable Cause Indicates an internal resource shortage caused an error so that an emulation frame could not be

created and sent to a Control Unit.

Recommended

Action

This is an unexpected event; contact your vendor's customer support for assistance.

FICN-1059

Message Error return from frame generation for a FICON Image: Path=0x<VEPortNumber HostDomain

HostPort DeviceDomain><DevicePort><LPAR>.

Message Type LOG

> **ERROR** Severity

Probable Cause Indicates an internal resource shortage caused an error so that an emulation frame could not be

created and sent to an Logical Partition (LPAR).

This is an unexpected event; contact your vendor's customer support for assistance. Recommended

Action

FICN-1060

Message Error return from fcFwdPrcEgressFrame: Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr>.

Message Type LOG

> **ERROR** Severity

Probable Cause Indicates an internal resource shortage caused an error so that an emulation frame could not be

created and sent to a device.

Recommended

Action

This is an unexpected event; contact your vendor's customer support for assistance.

FICN-1061

Message Error return from fcFwdRemoveEmulHashEntry: Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort>.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates an internal issue has been encountered in the removal of an existing fast path hash table

entry.

Recommended Action This is an unexpected event; contact your vendor's customer support for assistance.

FICN-1062

Message Ingress Abort:Oxid=Ox<the OXID of the aborted exchange>:Path=Ox<VEPortNumber

HostDomain HostPort DeviceDomain><DevicePort LPAR CUADDR

DeviceAddr>:LastStates=0x<prior emulation state array><previous emulation

state><current emulation state>.

Message Type LOG

Severity ERROR

Probable Cause Indicates an abort operation has been received from the local FC interface for an active emulation

exchange.

Recommended

Action

This is an unexpected event; contact your vendor's customer support for assistance.

FICN-1063

Message Egress Abort:Oxid=0x<the OXID of the aborted exchange>:Path=0x<VEPortNumber

HostDomain HostPort DeviceDomain><DevicePort LPAR CUADDR

DeviceAddr>:LastStates=0x<prior emulation state array><previous emulation

state><current emulation state>.

Message Type LOG

Severity ERROR

Probable Cause Indicates an abort operation has been received from a peer FC interface for an active emulation

exchange.

Recommended

Action

This is an unexpected event; contact your vendor's customer support for assistance.

FICN-1064

Message Ingress Abort:Oxid=Ox<the OXID of the aborted exchange>:Unknown Path on

GEPort=<GEPortNumber> VEPort=<VEPortNumber> from SID=0x<Source Domain><Source Port>

to DID=0x<Destination Domain><Destination Port>.

Message Type LOG

Severity INFO

Probable Cause Indicates an abort operation has been received from a local FC interface for an exchange.

Recommended Action If there were associated I/O errors at the same time as this event, contact your vendor's customer support for assistance.

FICN-1065

Message Egress Abort:Oxid=0x<the OXID of the aborted exchange>:Unknown Path on

GEPort=<GEPortNumber> VEPort=<VEPortNumber> from SID=0x<Source Domain ><Source Port>

to DID=0x<Destination Domain><Destination Port>.

Message Type LOG

Severity INFO

Probable Cause Indicates an abort operation has been received from a peer FC interface for an exchange.

Recommended If there were associated I/O errors at the same time as this event, contact your vendor's customer

Action support for assistance.

FICN-1066

Message MemAllocFailed for GEPort=<VEPortNumber> VEport=<GEO or GE1 number> could not create

required structure.

Message Type LOG

Severity WARNING

Probable Cause Indicates an internal resource limit has been encountered so that additional control block memory

could not be allocated.

Recommended This is an unexpected event; either the maximum number of emulation devices are already in use or

Action there is an internal memory leak. Contact your vendor's customer support for assistance.

FICN-1067

Message Ingress Abort: Oxid=0x<the OXID of the aborted exchange>: Abort for CH=0x<VEPortNumber

HostDomain HostPort DeviceDomain><DevicePort LPAR>****.

Message Type LOG

Severity ERROR

Probable Cause Indicates an abort operation has been received from a local FC interface for an emulation CH

exchange.

Recommended If there were associated I/O errors at the same time as this event, contact your vendor's customer

Action support for assistance.

FICN-1068

Message Ingress Abort:Oxid=Ox<the OXID of the aborted exchange>:Abort for CU=Ox<VEPortNumber

HostDomain HostPort DeviceDomain><DevicePort LPAR><CUADDR>**.

Message Type LOG

Severity ERROR

Probable Cause Indicates an abort operation has been received from a local FC interface for an emulation Control Unit

exchange.

Recommended If there were associated I/O errors at the same time as this event, contact your vendor's customer

Action support for assistance.

FICN-1069

Message Emulation Configuration Error on TunnelId <Tunnel ID>:.

Message Type LOG

Severity ERROR

Probable Cause Indicates an error has been noted in the FICON configuration. Refer to the string for the nature of the

configuration issue.

Recommended If resolution of the configuration issue cannot be completed, contact your vendor's customer support

Action for assistance.

FICN-1070

Message DevTapeIngr:Exceptional Status rovd on Path=0x<VEPortNumber HostDomain HostPort

 ${\tt DeviceDomain}{\small {\small >}} {\tt CUADDR} \ \, {\tt DeviceAddr}{\small >} \ \, {\tt state=0x<} {\tt current \ emulation \ state}{\small >} \\$

status=0x<the exceptional status value>.

Message Type LOG

Severity INFO

Probable Cause Indicates the normal end of tape status (0x0D or 0x05) is received from the device or error status

(including Unit Check 0x02) is received from an active emulation device.

Recommended The end of tape is a normal event during pipelining and not the unit check. If there are associated I/O

error messages with this event, contact your vendor's customer support for assistance.

FICN-1071

Message HostTapeIngr:Tape Loaded on Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr>.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates the tape I/Os are processed from a locally connected Logical Partition (LPAR), which

indicates that a tape is loaded on a device.

FICN-1072

Message DevTapeEgr:Tape Loaded on Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr>.

Message Type LOG

Severity INFO

Probable Cause Indicates the tape I/Os are processed from a locally connected Logical Partition (LPAR), which

indicates that a tape is loaded on a device.

FICN-1073

Message HostTapeIngr:Unloaded:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr>:states=0x<4 prior emulation states>current emulation state>:cmds=0x<1ast 4 commands received from the channel for this device>:status=0x<1ast 4 status values sent to the channel for this device>:flags=0x<1ape report bit flags (0x80-1ape Loaded, 0x40-1ape Loaded, 0x40

WriteEmul, 0x20-RdBlkEmul, 0x10-RdCpEmul) >.

Message Type LOG

Severity INFO

Probable Cause Indicates a Rewind and Unload I/O has been processed from a locally connected Logical Partition

(LPAR), which indicates that a tape should be unloaded on a device.

FICN-1074

Message HostTapeIngr:WriteReport:Path=0x<VEPortNumber HostDomain HostPort

emulated host write commands processed while this tape was loaded>:Chains=0x<the number of emulated host chains processed while this tape was loaded>:MBytes=<the number of emulated write Kilobytes processed while this tape was loaded>.

Message Type LOG

Severity INFO

Probable Cause Indicates a Rewind and Unload I/O has been processed from a locally connected Logical Partition

(LPAR) and Tape Write Pipelining was performed on the currently loaded tape.

FICN-1075

Message HostTapeIngr:ReadBlkReport:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr>:Emuls=0x<the number of idle state to non-idle state transitions while this tape was loaded>:Cmds=0x<the number of emulated host read commands processed while this tape was loaded>:Chains=0x<the number of emulated host chains processed while this tape was loaded>:MBytes=<the number of emulated read Kilobytes processed while this tape was loaded>.

Message Type LOG

Severity INFO

Probable Cause Indicates a Rewind and Unload I/O has been processed from a locally connected Logical Partition

(LPAR) and Read Block pipelining was performed on the currently loaded tape.

FICN-1076

Message HostTapeIngr:ReadCpReport:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr>:Emuls=0x<the number of idle state to non-idle state transitions while this tape was loaded>:Cmds=0x<the number of emulated host read commands processed while this tape was loaded>:Chains=0x<the number of emulated host chains processed while this tape was loaded>:MBytes=<the

number of emulated read Kilobytes processed while this tape was loaded>.

Message Type LOG

Severity INFO

Probable Cause Indicates a Rewind and Unload I/O has been processed from a locally connected Logical Partition

(LPAR) and Read Channel Program pipelining was performed on the currently loaded tape.

FICN-1077

Message DevTapeEgr:Unloaded:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr>:states=0x<4 prior emulation states>states>ox<4 prior emulation</pre>

received from the channel for this device>:status=0x<last 4 status values received from the channel for this device>:flags=0x<tape report bit flags (0x80-Tape Loaded, 0x40-WriteEmul, 0x20-RdBlkEmul, 0x10-RdCpEmul)>.

Message Type LOG

Severity INFO

Probable Cause Indicates a Rewind and Unload I/O has been processed from a remotely connected Logical Partition

(LPAR), which indicates that a tape should be unloaded on a device.

FICN-1078

Message DevTapeEgr:WriteReport:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr>:Emuls=0x<the number of idle state to non-idle state transitions while this tape was loaded>:Cmds=0x<the number of emulated host write commands processed while this tape was loaded>:Chains=0x<the number of emulated host chains processed while this tape was loaded>:MBytes=<the number of emulated write Kilobytes processed while this tape was loaded>.

Message Type LOG

Severity INFO

Probable Cause Indicates a Rewind and Unload I/O has been processed from a remotely connected Logical Partition

(LPAR) and Write Tape Pipelining was performed on the currently loaded tape.

FICN-1079

Message DevTapeEgr:ReadBlkReport:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr>:Emuls=0x<the number of idle state to non-idle state transitions while this tape was loaded>:Cmds=0x<the number of emulated host read commands processed while this tape was loaded>:Chains=0x<the number of emulated host chains processed while this tape was loaded>:MBytes=<the

number of emulated read Kilobytes processed while this tape was loaded>.

Message Type LOG

Severity INFO

Probable Cause Indicates a Rewind and Unload I/O has been processed from a remotely connected Logical Partition

(LPAR) and Read Block pipelining was performed on the currently loaded tape.

FICN-1080

Message DevTapeEgr:ReadCpReport:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr>:Emuls=0x<the number of idle state to non-idle state transitions while this tape was loaded>:Cmds=0x<the number of

emulated host read commands processed while this tape was loaded>:Chains=0x<the number of emulated host chains processed while this tape was loaded>:MBytes=<the number of emulated read Kilobytes processed while this tape was loaded>.

Message Type LOG

Severity INFO

Probable Cause Indicates a Rewind and Unload I/O has been processed from a remotely connected Logical Partition

(LPAR) and Read Channel Program pipelining was performed on the currently loaded tape.

FICN-1081

Message DevTapeIng:LRJ received on Path=0x<VEPortNumber HostDomain HostPort

 $\label{lem:deviceDomain} $$ \end{substitute} $$ DevicePort\ LPAR\ CUADDR\ DeviceAddr> \ lastCmds=0x<Last\ 4\ commands\ received\ from\ the\ channel\ for\ this\ device> \ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \ lastStatus=0x<Last\ 4\ status\ values\ presented\ the\ device> \ lastStatus=0x<Last\ 4\ status=0x<Last\ 4\ statu$

channel for this device> treating as system reset event.

Message Type LOG

Severity WARNING

Probable Cause Indicates a Link Level Reject (LRJ) from a FICON channel indicates that the channel does not have a

path established to the Control Unit.

Recommended This is normally an unexpected event; contact your vendor's customer support for assistance.

Action

FICN-1082

Message EmulEls:CSWR RSCN received on GEPort=<GEPortNumber> VEPort=<VEPortNumber>

Domain=0x<Domain> Port=0x<Port Host/Device Side>.

Message Type LOG

Severity WARNING

Probable Cause Indicates an attached port which had a FICON emulated path established has logged out from the

switch.

Recommended This may be an unexpected event; contact your vendor's customer support for assistance.

Action

, teller.

FICN-1083

Message EmulEls:SW_RSCN received on GEPort=<GEPortNumber> VEPort=<VEPortNumber>

Domain=0x<Domain> Port=0x<Port Host/Device Side>.

Message Type LOG

Severity WARNING

Probable Cause Indicates an attached port with the established FICON emulated path has logged out from the switch.

Recommended This may be an unexpected event; contact your vendor's customer support for assistance.

Action

FICN-1084

Message fcFicInit: No DRAM2 memory available, FICON emulation is disabled.

Message Type LOG

Severity ERROR

Probable Cause Indicates a faulty DRAM2 was detected and access to its address range is prohibited.

Recommended This is an unexpected event; contact your vendor's customer support for assistance.

Action

FICN-1085

Message FICON FCIP Tunnel is Up on GE<Either geO or ge1>, tunnel Id=<The configured tunnel ID

(0-7) > .

Message Type LOG

Severity INFO

Probable Cause Indicates a FICON FCIP tunnel has been established successfully to the peer switch.

FICN-1086

Message FICON FCIP Tunnel is Down on GE<Either ge0 or ge1>, tunnel Id=<The configured tunnel

ID (0-7) > .

Message Type LOG

Severity ERROR

Probable Cause Indicates a FICON FCIP tunnel to the peer switch has been terminated.

Recommended This is an unexpected event; contact your vendor's customer support for assistance.

Action

FICN-1087

Message DevTeraEgr:AS Link Level Reject (LRJ) from Chan on Path=0x<VEPortNumber HostDomain

 $\label{lostPortDevicePortLPARCUADDRDeviceAddr} LastCmd=0x<the\ Last\ 4 \\ commands\ issued\ to\ the\ device>\ LastStatus=0x<the\ Last\ 4\ status\ values\ received\ from \\ \end{tabular}$

the device>.

Message Type LOG

Severity ERROR

Probable Cause Indicates the FICON channel indicated in the path issued an Link Level Reject (LRJ) frame for a

sequence from the device.

Recommended If there was a job failure associated with this event, contact your vendor's customer support for

Action assistance.

FICN-1088

Message DevTeraEgr:FICON Cancel received Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> state=0x<the current emulation state for the device> tflags=0x<the current emulation tera control flags for the device>

sflags=0x<the current emulation status control flags for the device>.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates the FICON channel issued a Cancel sequence for a device in emulation.

Recommended If there was an unexpected job failure associated with this event, contact your vendor's customer

support for assistance.

FICN-1089

Message DevTeraEgr:FICON Tera Cancel:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> Elapsed Time=<the current SIO time in seconds for the device>.<the current SIO time in milliseconds for the device>

seconds.

Message Type LOG

Severity WARNING

Probable Cause Indicates the FICON channel issued a Cancel sequence for a device in emulation.

Recommended If there was an unexpected job failure associated with this event, contact your vendor's customer

Action support for assistance.

FICN-1090

Message DevTeraEgr:FICON Selective Reset:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> State=0x<the current state of the device that received the selective reset> statArray=0x<the last 4 status values

received from the device> cmdArray=0x<the last 4 commands that were issued to the device> tflags=0x<the current emulation tera control flags for the device> sflags=0x<the current emulation status control flags for the device>.

Message Type LOG

Severity ERROR

Probable Cause Indicates the FICON channel issued a Selective Reset for a device that was active in emulation.

Recommended If there was an unexpected job failure associated with this event, contact your vendor's customer Action support for assistance.

FICN-1091

Message DevTeraEgr:FICON Selective Reset:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> Elapsed Time=<the current SIO time in seconds for the device>.<the current SIO time in milliseconds for the device>

seconds.

Message Type LOG

Severity ERROR

Probable Cause Indicates the FICON channel issued a Selective Reset sequence for a device.

Recommended If there was an unexpected job failure associated with this event, contact your vendor's customer

support for assistance.

FICN-1092

Message DevTeraEgr:FICON Purge received Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr>.

Message Type LOG

Action

Action

Severity ERROR

Probable Cause Indicates the FICON channel issued a Purge Path command sequence for a device.

Recommended If there was an unexpected job failure or I/O error associated with this event, contact your vendor's

customer support for assistance.

FICN-1093

Message DevTeraIng:Auto Sense Data received on Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> Bytes0-0xB=0x
bytes 0-3 of sense data from the device><bytes 4-7 of sense data from the device><bytes 8-0x0b of sense

data from the device>.

Message Type LOG

WARNING Severity

Probable Cause Indicates the FICON tera write pipelining processed sense data from a FICON device.

Recommended If there was an unexpected job failure or I/O error associated with this event, contact your vendor's Action

customer support for assistance.

FICN-1094

Message DevTeraIng:UnusualStatus:WriteCancelSelr:Generating Final Ending Status

Path=0x<VEPortNumber HostDomain HostPort DeviceDomain><DevicePort LPAR CUADDR

DeviceAddr>.

Message Type LOG

> Severity INFO

Probable Cause Indicates the FICON tera write pipeline is completing an emulated Selective Reset sequence.

Recommended If there was an unexpected job failure or I/O error associated with this event, contact your vendor's Action

customer support for assistance.

FICN-1095

Message DevTeraIng: Device level exception found for Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr>: Oxid=0x<The OXID of the frame that

included the Device Level Exception>.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates an active emulation device delivered a Device Level Exception frame to the emulation

processing.

Recommended If there was an unexpected job failure or I/O error associated with this event, contact your vendor's

Action customer support for assistance.

FICN-1096

Message HostTeraEgr:CmdReject Sense Data Rcvd:Path=0x<VEPortNumber HostDomain HostPort

> DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> LastCmds=0x<Last 4 commands received from the channel for this device> SenseData:Bytes0-0xB=0x<Bytes 0-3 of sense data from the device><Bytes 4-7 of sense data from the device><Bytes 8-0x0b of sense data

from the device>.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates an active Teradata emulation sequence received a Command Reject Sense from the device.

Recommended Action If there was an unexpected job failure or I/O error associated with this event, contact your vendor's customer support for assistance.

FICN-1097

Message

 $\label{lostTeraEgr:AS Link Level Reject (LRJ) from CU Rx Path=0x<VEPortNumber HostDomain} \\ HostPort DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> LastCmd=0x<Last 4 commands issued to this device from the channel> LastStatus=0x<Last 4 status values sent to the channel from this device>.$

Message Type

Severity ERROR

LOG

Probable Cause In

Action

Indicates a Link Level Reject (LRJ) received from a device indicates that the Control Unit has lost the logical path to the Logical Partition (LPAR).

Recommended

If this was an unexpected event; contact your vendor's customer support for assistance.

FICN-1098

Message HostTeraIng:FICON Cancel received Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> state=0x<the current emulation state

for this device>.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates a job was canceled during a Write Tape Pipelining.

Recommended

If this was an unexpected event (cancel is normally an operator event), contact your vendor's customer

support for assistance.

FICN-1099

Message HostTeraIng::FICON Selective Reset:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> state=0x<the current emulation state for this device> LastCmds=0x<the last 4 commands received from the channel for this device> LastStatus=0x<the last 4 status values presented to the channel for this

device>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the channel recognized a timeout condition and issued a Selective Reset.

Recommended If this was an unexpected event, contact your vendor's customer support for assistance.

Action

FICN-1100

Message HostTeraIng:FICON Selective Reset:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> Elapsed Time=<the number of seconds since the last IO started for this device>.<the number of milliseconds since the last

IO started for this device> seconds.

Message Type LOG

Severity ERROR

Probable Cause Indicates that protocol errors in emulation in the Control Unit or network errors can cause Selective

Reset.

Recommended

Action

If this was an unexpected event, contact your vendor's customer support for assistance.

FICN-1101

Message HostTeraIng:FICON Purge received:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr>.

Message Type LOG

Severity WARNING

Probable Cause Indicates a Purge Path was received from the locally connected FICON channel. This is performed

during the path recovery.

Recommended

Action

If this was an unexpected event, contact your vendor's customer support for assistance.

FICN-1102

Message HostTeraIng:LRJ received on Path=0x<VEPortNumber HostDomain HostPort

channel for this device> treating as system reset event.

Message Type LOG

Severity WARNING

Probable Cause Indicates a Link Level Reject (LRJ) from a FICON channel indicates that the channel believes that it no

longer has a path established to the Control Unit.

Recommended This is normally an unexpected event; contact your vendor's customer support for assistance.

Action

FICN-1103

Message DevTeraIngr: Exceptional Status rovd on Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> state=0x<current emulation state>

status=0x<the exceptional status value>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the status (0x0D or 0x05) indicating the device is going down was received from the

device or error status (including Unit Check 0x02) is received from an active emulation device.

Recommended The device doing down is a normal event during pipelining and not the unit check. If there are

associated I/O error messages with this event, contact your vendor's customer support for assistance.

FICN-1104

Message DevTeraEqr:Device Ready on Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain > < DevicePort LPAR CUADDR DeviceAddr > .

Message Type LOG

Action

Severity INFO

Probable Cause Indicates the Teradata device has been initialized and is ready for emulation operations.

FICN-1105

Message DevTeraIng:LRJ received on Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> lastCmds=0x<Last 4 commands received from the channel for this device> lastStatus=0x<Last 4 status values presented to the

channel for this device> treating as system reset event.

Message Type LOG

Severity WARNING

Probable Cause Indicates a Link Level Reject (LRJ) from a FICON channel indicates that the channel does not have a

path established to the Control Unit.

Recommended This is normally an unexpected event; contact your vendor's customer support for assistance.

Action

FICN-1106

Message DevPrintEgr: AS Link Level Reject (LRJ) from Chan on Path=0x<VEPortNumber HostDomain

 $\label{lostPortDeviceDomain} $$\operatorname{LextCho}_0 = 0 \times \theta = 0 \times \theta$

the device>.

Message Type LOG

Severity ERROR

Probable Cause Indicates the FICON channel indicated in the path issued a Link Level Reject (LRJ) frame for a

sequence from the device.

Action assistance.

FICN-1107

Message DevPrintEgr:FICON Cancel received Path=0x<VEPortNumber HostDomain HostPort

sflags=0x<the current emulation status control flags for the device>.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates the FICON channel issued a Cancel sequence for a device in emulation.

Recommended If there was an unexpected job failure associated with this event, contact your vendor's customer

support for assistance.

FICN-1108

Message DevPrintEgr:FICON Tera Cancel:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> Elapsed Time=<the current SIO time in seconds for the device>.<the current SIO time in milliseconds for the device>

seconds.

Message Type LOG

Severity WARNING

Probable Cause Indicates the FICON channel issued a Cancel sequence for a device in emulation.

Recommended If there was an unexpected job failure associated with this event, contact your vendor's customer

Action support for assistance.

FICN-1109

Message DevPrintEgr:FICON Selective Reset:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> State=0x<the current state of the device that received the selective reset> statArray=0x<the last 4 status values

received from the device> cmdArray=0x<the last 4 commands that were issued to the device> tflags=0x<the current emulation tera control flags for the device> sflags=0x<the current emulation status control flags for the device>.

Message Type LOG

Severity ERROR

Probable Cause Indicates the FICON channel issued a Selective Reset for a device that was active in emulation.

Recommended If there was an unexpected job failure associated with this event, contact your vendor's customer Action support for assistance.

FICN-1110

Message DevPrintEgr:FICON Selective Reset:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> Elapsed Time=<the current SIO time in seconds for the device>.<the current SIO time in milliseconds for the device>

seconds.

Message Type LOG

Severity ERROR

Probable Cause Indicates the FICON channel issued a Selective Reset sequence for a device.

Recommended If there was an unexpected job failure associated with this event, contact your vendor's customer

support for assistance.

FICN-1111

Message DevPrintEgr:FICON Purge received Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr>.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates the FICON channel issued a Purge Path command sequence for a device.

Recommended If there was an unexpected job failure or I/O error associated with this event, contact your vendor's

Action customer support for assistance.

FICN-1112

Message DevPrintIng: Auto Sense Data received on Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> Bytes0-0xB=0x
bytes 0-3 of sense data from the device><bytes 4-7 of sense data from the device><bytes 8-0x0b of sense

data from the device>.

Message Type LOG

WARNING Severity

Probable Cause Indicates the FICON Printer write pipelining processed sense data from a FICON device.

Recommended If there was an unexpected job failure or I/O error associated with this event, contact your vendor's Action

customer support for assistance.

FICN-1113

Message DevPrintIng:LRJ received on Path=0x<VEPortNumber HostDomain HostPort

> DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> lastCmds=0x<Last 4 commands received from the channel for this device> lastStatus=0x<Last 4 status values presented to the

channel for this device> treating as system reset event.

Message Type LOG

> Severity WARNING

Indicates a Link Level Reject (LRJ) from a FICON channel indicates that the channel does not have a Probable Cause

path established to the Control Unit.

Recommended This is normally an unexpected event; contact your vendor's customer support for assistance.

Action

FICN-1114

Message DevPrintIng:Device level exception found for Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr>: Oxid=0x<The OXID of the frame that

included the Device Level Exception>.

Message Type LOG

> **ERROR** Severity

Probable Cause Indicates an active emulation device delivered a Device Level Exception frame to the emulation

processing.

Recommended If there was an unexpected job failure or I/O Error associated with this event, contact your vendor's

Action customer support for assistance.

FICN-1115

Message HostPrintEgr:CmdReject Sense Data Rcvd:Path=0x<VEPortNumber HostDomain HostPort

> DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> LastCmds=0x<Last 4 commands received from the channel for this device> SenseData:Bytes0-0xB=0x<Bytes 0-3 of sense data from the device><Bytes 4-7 of sense data from the device><Bytes 8-0x0b of sense data

from the device>.

Message Type LOG

> **ERROR** Severity

Probable Cause Indicates an active Print emulation sequence received Command Reject Sense data from the device.

Recommended Action If there was an unexpected job failure or I/O error associated with this event, contact your vendor's customer support for assistance.

FICN-1116

Message HostPrintEgr: AS Link Level Reject (LRJ) from CU Rx Path=0x<VEPortNumber HostDomain

 $\label{loss_port_power_loss} \begin{tabular}{ll} HostPort DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> LastCmd=0x<Last 4 commands issued to this device from the channel> LastStatus=0x<Last 4 status values sent to the channel of the channel$

the channel from this device>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that a Link Level Reject (LRJ) was received from a device indicating that the Control Unit has

lost the logical path to the Logical Partition (LPAR).

Recommended If this was an unexpected event; contact your vendor's customer support for assistance.

Action

FICN-1117

Message HostPrintIng:FICON Cancel received Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> state=0x<the current emulation state

for this device>.

Message Type LOG

Severity WARNING

Probable Cause Indicates a job was canceled during Print write pipelining.

Recommended If this was an unexpected event (cancel is normally an operator event), contact your vendor's customer

Action support for assistance.

FICN-1118

Message HostPrintIng::FICON Selective Reset:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> state=0x<the current emulation state for this device> LastCmds=0x<the last 4 commands received from the channel for this device> LastStatus=0x<the last 4 status values presented to the channel for this

device>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the channel recognized a timeout condition and issued a Selective Reset.

Recommended Action If this was an unexpected event, contact your vendor's customer support for assistance.

FICN-1119

Message HostPrintIng:FICON Selective Reset:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr> Elapsed Time=<the number of seconds since the last IO started for this device>.<the number of milliseconds since the last

IO started for this device> seconds.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the channel recognized a timeout condition and issued a Selective Reset.

Recommended If this was an unexpected event, contact your vendor's customer support for assistance.

FICN-1120

Message HostPrintIng:FICON Purge received:Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr>.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates a Purge Path was received from the locally connected FICON channel. This is performed

during FICON path recovery.

Recommended If this was an unexpected event, contact your vendor's customer support for assistance.

Action

Action

FICN-1121

Message HostPrintIng:LRJ received on Path=0x<VEPortNumber HostDomain HostPort

 $\label{lem:deviceDomain} $$ \end{substitute} $$ DevicePort\ LPAR\ CUADDR\ DeviceAddr> \\ lastCmds=0x<Last\ 4\ commands\ received\ from\ the\ channel\ for\ this\ device> \\ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \\ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \\ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \\ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \\ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \\ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \\ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \\ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \\ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \\ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \\ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \\ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \\ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \\ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \\ lastStatus=0x<Last\ 4\ status\ values\ presented\ to\ the\ device> \\ lastStatus=0x<Last\ 4\ status\ values\ presented\ the\ device> \\ lastStatus=0x<Last\ 4\ status\ presented\ the\ device> \\ lastStatu$

channel for this device> treating as system reset event.

Message Type LOG

Severity WARNING

Probable Cause Indicates than a Link Level Reject (LRJ) received from a FICON channel indicates that the channel no

longer has a path established to the Control Unit.

Recommended This is normally an unexpected event; contact your vendor's customer support for assistance.

Action

FICN-1122

Message DevPrintIng:UnusualStatus:WriteCancelSelr:Generating Final Ending Status

Path=0x<VEPortNumber HostDomain HostPort DeviceDomain><DevicePort LPAR CUADDR

DeviceAddr>.

Message Type LOG

Severity INFO

Probable Cause Indicates the FICON Print write pipeline sequence has received unit check status.

Recommended If there was an unexpected job failure or I/O error associated with this event, contact your vendor's

Action customer support for assistance.

FICN-1123

Message Path=<VEPortNumber HostDomain HostPort DeviceDomain DevicePort>***** is operating

with Fibre Channel Endpoint Security feature on an emulation enabled VE Port.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that FICON encrypted flows were encountered on the emulation enabled VE Port.

Recommended FICON Emulation features do not support Fibre Channel Endpoint Security flows. Either disable

FICON Features on the tunnel or disable Fibre Channel Endpoint Security on the associated CHPID

(Channel Path).

FICN-2005

Message FICON VEPort <VE port number> Feature Change verified Xrc <1 or 0 - XRC Emulation

Enabled or Disabled> TapeWrt <1 or 0 - Tape Write Emulation Enabled or Disabled> TapeRd <1 or 0 - FICON Tape Read Emulation Enabled or Disabled> TinTir <1 or 0 - FICON TIN/TIR Emulation Enabled or Disabled> DvcAck <1 or 0 - FICON Device Level Ack Emulation Enabled or Disabled> RdBlkId <1 or 0 - FICON Write Emulation Read Block ID

Emulation Enabled or Disabled>.

Message Type LOG

Severity INFO

Probable Cause Indicates the configuration was changed manually.

FICN-2006

Message FICON VEPort <VE port number> Feature Change failed Xrc <1 or 0 - XRC Emulation Enabled

or Disabled> TapeWrt <1 or 0 - Tape Write Emulation Enabled or Disabled> TapeRd <1 or 0 - FICON Tape Read Emulation Enabled or Disabled> TinTir <1 or 0 - FICON TIN/TIR

Emulation Enabled or Disabled> DvcAck <1 or 0 - FICON Device Level Ack Emulation Enabled or Disabled> RdBlkId <1 or 0 - FICON Write Emulation Read Block ID Emulation Enabled or Disabled>.

Message Type LOG

Severity WARNING

Probable Cause Indicates the FCIP Tunnel ID associated with the FICON tunnel must be down or disabled for a feature

change to become effective.

Recommended Disable the applicable FCIP tunnel to make the feature change effective.

Action

FICN-2064

Message Ingress Abort:Oxid=0x<the OXID of the aborted exchange>:Unknown Path on

VEPort=<VEPortNumber> from SID=0x<Source Domain><Source Port> to DID=0x<Destination

Domain > < Destination Port > .

Message Type LOG

Severity INFO

Probable Cause Indicates an abort operation has been received from a local FC interface for an exchange.

Recommended If there were associated I/O errors at the same time as this event, contact your vendor's customer

Action support for assistance.

FICN-2065

Message Egress Abort:Oxid=0x<the OXID of the aborted exchange>:Unknown Path on

VEPort=<VEPortNumber> from SID=0x<Source Domain ><Source Port> to DID=0x<Destination

Domain><Destination Port>.

Message Type LOG

Severity INFO

Probable Cause Indicates an abort operation has been received from a peer FC interface for an exchange.

Recommended If there were associated I/O errors at the same time as this event, contact your vendor's customer

Action support for assistance.

FICN-2066

Message MemAllocFailed for VEport=<VEPortNumber> could not create required structure.

Message Type LOG

Severity WARNING

Probable Cause Indicates an internal resource limit has been encountered so that additional control block memory

could not be allocated.

Recommended Action

This is an unexpected event; either the maximum number of emulation devices are already in use or there is an internal memory leak. Contact your vendor's customer support for assistance.

FICN-2082

Message EmulEls:CSWR RSCN received on VEPort=<VEPortNumber> Domain=0x<Host/Device Side

Domain> Port=0x<Host/Device Side Port>.

Message Type LOG

Severity WARNING

Probable Cause Indicates an attached port which had a FICON emulated path established has logged out from the

switch.

Recommended This may be an unexpected event; contact your vendor's customer support for assistance.

Action

FICN-2083

Message EmulEls:SW RSCN received on VEPort=<VEPortNumber> Domain=0x<Host/Device Side Domain>

Port=0x<Host/Device Side Port>.

Message Type LOG

Severity WARNING

Probable Cause Indicates an attached port with the established FICON emulated path has logged out from the switch.

Recommended This may be an unexpected event; contact your vendor's customer support for assistance.

Action

FICN-2085

Message FICON or FCP Emulation Enabled FCIP Tunnel is Up on VEPort=<VEPortNumber>.

Message Type LOG

Severity INFO

Probable Cause Indicates a FICON or Fibre Channel Protocol (FCP) emulation-enabled FCIP tunnel has been

established successfully to the peer switch.

FICN-2086

Message FICON or FCP Emulation Enabled FCIP Tunnel is Down on VEport=<VEPortNumber>.

Message Type LOG

Severity ERROR

Probable Cause Indicates a FICON or Fibre Channel Protocol (FCP) emulation-enabled FCIP tunnel to the peer switch

has been terminated.

Recommended

Action

This is an unexpected event; contact your vendor's customer support for assistance.

FICN-2087

Message FICON connected 3900 printer discovered Path=0x<VEPortNumber HostDomain HostPort

DeviceDomain><DevicePort LPAR CUADDR DeviceAddr>-invalid compression mode.

Message Type LOG

Severity ERROR

Probable Cause Indicates that FICON Printer emulation is enabled, but cannot be performed for this device because

the compression mode on the tunnel is not set to None or Aggressive.

Recommended If you desire FICON Printer emulation for this device, modify the tunnel compression mode to None

Action (mode 0) or Aggressive (mode 3).

6.40 FICU Messages

FICU-1001

Message <error message>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that one of the configuration management functions have failed. The key variable is a

component of the Fabric OS configuration database and is for support use only. The error variable is

an internal error number.

Recommended

Action

Execute the **haFailover** command on the switch if it has redundant control processors (CPs) or reboot the switch. Execute the **switchStatusShow** command to check if the flash memory is full. If the flash

memory is full, execute the supportSave command to clear the core files.

FICU-1002

Message <function name>: Failed to get Switch Node Descriptor data from Management Server for

Domain = <domain > rc = <error > .

Message Type LOG

Severity **ERROR**

Probable Cause Indicates that the fibre connectivity control unit port (FICON-CUP) daemon failed to get the Switch

> Node Descriptor data from the management server because of a Fabric OS problem. The domain variable displays the domain ID of the switch or logical switch for which the Node Descriptor was

requested. The error variable is an internal error number.

Recommended

Action

If this is a bladed switch, execute the haFailover command. If the problem persists, or if this is a nonbladed switch, download a new firmware version using the firmwareDownload command.

FICU-1003

Message <function name>: <message> FICON-CUP License Not Installed: (<error>).

Message Type LOG

> WARNING Severity

Probable Cause Indicates that the fibre connectivity control unit port (FICON-CUP) license is not installed on the switch.

Recommended

Action

Execute the licenseShow command to check the installed licenses on the switch. The switch cannot be managed using FICON-CUP commands until the FICON-CUP license is installed. Contact your switch supplier for a FICON-CUP license. Execute the licenseAdd command to add the license to your switch.

FICU-1004

Message <function name>: Failed to set FICON Management Server (FMS) mode: conflicting PID

Format:<pid format>, FMS Mode:<mode>.

Message Type LOG

> Severity WARNING

Probable Cause

Indicates that a process ID (PID) format conflict was encountered. The core PID format is required for fibre connectivity control unit port (FICON-CUP).

The pid format variable displays the PID format currently running on the fabric, and is one of the following:

- 0 VC-encoded PID format
- 1 Core PID format
- 2 Extended-edge PID format

The *mode* variable displays whether FICON Management Server (FMS) mode is enabled, and is one of the following: 0 means FMS mode is enabled and 1 means FMS mode is disabled.

Recommended

Action

To enable FMS mode, the core PID format must be used in the fabric. Change the PID format to core PID using the **configure** command and re-enable FMS Mode using the **ficonCupSet** command. Refer to the *Fabric OS Administrator's Guide* for information on core PID mode.

FICU-1005

Message Failed to initialize <module>, rc = <error>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that initialization of a module within the fibre connectivity control unit port (FICON-CUP)

daemon failed.

Recommended Download a new firmware version using the **firmwareDownload** command.

Action

FICU-1006

Message Control Device Allegiance Reset: (Logical Path: 0x<PID>:0x<channel image ID>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the path with the specified Port Identifier (PID) and channel image ID lost allegiance to a

fibre connectivity control unit port (FICON-CUP) device.

Recommended Check if the FICON channel corresponding to the PID in the message is functioning correctly.

Action

FICU-1007

Message <function name>: Failed to allocate memory while performing <message>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that memory resources are low. This may be a transient problem.

Recommended Check the memory usage on the switch using the **memShow** command.

Action

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

FICU-1008

Message FMS mode has been enabled. Port(s):<port number(s)> have been disabled due to port

address conflict.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified ports were disabled when the FICON Management Server (FMS) mode

was enabled. This is due to a port address conflict or the port address being reserved for the CUP

management port.

FICU-1009

Message FMS Mode enable failed due to insufficient frame filtering resources on some ports.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the frame filtering resources required to enable FICON Management Server mode

(fmsMode) were not available on some of the ports.

Recommended Execute the **haFailover** command on the switch if it has redundant control processors (CPs) or reboot

Action the switch.

FICU-1010

Message FMS mode enable failed due to port(s) with areas 0xFE or 0xFF is(are) connected to

device(s).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the FICON Management Server (FMS) mode was not enabled because ports with areas

0xFE or 0xFF are connected to devices.

Recommended Disable ports with areas 0xFE or 0xFF using the **portDisable** command.

Action

FICU-1011

Message FMS mode has been enabled.

Message Type AUDIT | LOG

Class CFG

INFO Severity

Probable Cause Indicates that the FICON Management Server mode (fmsMode) has been enabled.

FICU-1012

Message FMS mode has been disabled.

Message Type AUDIT | LOG

> Class **CFG**

Severity INFO

Probable Cause Indicates that the FICON Management Server mode (fmsMode) has been disabled.

FICU-1013

Host data file cannot be reset to proper size. Message

Message Type LOG

> Severity WARNING

Probable Cause Indicates that the file system is too full to create the host data file at the proper size.

Recommended Execute the **df** command to check if the flash memory is full. If the flash memory is full, execute the Action

supportSave command to clear the core files.

FICU-1017

Message FMSMODE enable failed because reserved area is bound to a device.

Message Type LOG

> WARNING Severity

Probable Cause Indicates that one or both of the reserved areas 0xFE and 0xFF is bound to a device.

Recommended Execute the wwnaddress --show command to display all devices currently bound to areas. Execute

Action the **wwnaddress** --unbind command to release the reserved area from the device.

FICU-1018

Message FMSMODE enable noticed swapped ports.

Message Type LOG

> Severity **WARNING**

FOS-90x-Message-RM103 Broadcom

Probable Cause Indicates that some ports are swapped at the time FICON Management Server mode (fmsMode) is

enabled.

Recommended Action

Verify the expected FICON port address and port number relationship. For more information, refer to

the "FICON and FICON CUP in Virtual Fabrics" section of the FICON Administrator's Guide.

FICU-1019

Message Switch has been set offline by Logical Path (<Logical Path ID>).

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the FICON Host at the Logical Path shown has disabled the switch.

FICU-1020

Message Port Addrs (<port mask>) have been Blocked by <source>.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the port has been blocked.

FICU-1021

Message Port Addrs (<port mask>) have been Unblocked by <source>.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates the port has been unblocked.

FICU-1022

Message Detected FC8-48 and/or FC8-64 that are not manageable when FMS mode is enabled.

Message Type LOG

Severity INFO

Probable Cause

Indicates the presence of unmanageable ports such as 48-port blade ports in the virtual fabric-disabled chassis.

FICU-1025

Message

MAPS Evt Notif - <Action taken by FICUD when it received a MAPS Event Notification> - HSC((0x<HSC code associated with the MAPS MSid>),(<HSC text that will appear on the MVS Console>)), RuleN(<MAPS rule name supplied in the MAPS Event Notification>), MSid(<MAPS MSid supplied in the MAPS Event Notification>), Obj(<MAPS Object

description from ObjKeyValue from the MAPS Event Notification>, <MAPS Object instance from ObjKeyValue in the MAPS Event Notification>), Condn(<MAPS Condition supplied in the MAPS Event Notification>), MSVal(<MAPS MS Value supplied in the MAPS Event Notification>).

Message Type LOG

Severity INFO

Probable Cause Indicates that Monitoring and Alerting Policy Suite (MAPS) alert has been processed by the control

unit port (CUP).

FICU-1026

Message MAPS Rule Action Notification - <Action (Code) taken by MAPS a rule was triggered> -

Action(0x<Action (Descr) taken by MAPS a rule was triggered>, <Severity >), Sev(<Object Identifier (Code)>), Obj(<Object Identifier (Descr)>, <printf>) .

Message Type LOG

Severity INFO

Probable Cause Indicates that Monitoring and Alerting Policy Suite (MAPS) has notified FMS CUP that it has taken an

action as a result of a rule being triggered.

FICU-1030

Message Host Initiated Supportsave (Logical Path: 0x<PID>:0x<Channel Image ID>) failed

because Auto-FTP is OFF.

Message Type LOG

Severity INFO

Probable Cause Indicates that Auto FTP is not configured when a Host Initiated Supportsave request was received.

FICU-1031

Message Host Initiated Supportsave (Logical Path: 0x<PID>:0x<Channel Image ID>) failed

because a Supportsave is already in progress.

Message Type LOG

Severity INFO

Probable Cause Indicates that a Supportsave is already in progress when a Host Initiated Supportsave request was

received.

FICU-1032

Message Host Initiated Supportsave (Logical Path: 0x<PID>:0x<Channel Image ID>) has started

to the remote host.

Message Type LOG

Severity INFO

Probable Cause Indicates that a Host Initiated Supportsave has started.

FICU-1033

Message FMS mode enabled in a non-FICON logical switch. You must convert to a FICON logical

switch or FICON devices will fail to attach.

Message Type LOG

Severity ERROR

Probable Cause Indicates a configuration error has been detected.

Recommended Convert the logical switch to a FICON logical switch.

Action

FICU-1035

Message Error unblocking Port Address (<port mask>) Source (<source>).

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that an error occurred unblocking a port.

FICU-1036

Message FOS 9.0.0 is the last release to support the Allow/Prohibit matrix. \ See the FOS

9.0.0 FICON Config Guide. Src(<source>)

Message Type LOG

Severity WARNING

Probable Cause FOS 9.0.0 is the last release to support the Prohibit Dynamic Connectivity Mask (PDCM) used for

connectivity management as reflected in the Allow/Prohibit matrix. Effectively, the PDCM feature is deprecated in Fabric OS 9.0.0. Brocade recommends using Fabric OS zoning instead for connectivity

management functions. See the FOS 9.0.0 FICON Config Guide for more information.

6.41 FKLB Messages

FKLB-1001

Message exchange <xid> overlapped, pid=<pid>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the FC kernel driver has timed out the exchange while the application is still active.

When the FC kernel driver reuses the exchange, the application will overlap. This happens on a timed-

out exchange; it automatically recovers after the application times out the exchange.

6.42 FLOD Messages

FLOD-1001

Message Unknown LSR type: port <port number>, type <LSR header type>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the link state record (LSR) type is unknown. The following two LSR header types are the

only known types:

■ 1 - Unicast

3 - Multicast

Recommended

No action is required; the record is discarded.

Action

FLOD-1003

Message Link count exceeded in received LSR, value = link count number>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the acceptable link count received was exceeded in the link state record (LSR).

Recommended No action is required; the record is discarded.

Action

FLOD-1004

Message Excessive LSU length = <LSU length>.

Message Type LOG | FFDC

Severity ERROR

Probable Cause Indicates that the link state update (LSU) size exceeds the value the system can support.

Recommended Reduce the number of switches in the fabric or reduce the number of redundant inter-switch links

Action (ISLs) between two switches.

FLOD-1005

Message Invalid received domain ID: <domain number>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the received link state record (LSR) contained an invalid domain number.

Recommended No action is required; the LSR is discarded.

Action

FLOD-1006

Message Transmitting invalid domain ID: <domain number>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the transmitted link state record (LSR) contained an invalid domain number.

Recommended No action is required; the LSR is discarded.

Action

FLOD-1007

Message The LSR for reachable domain <domain number> reached the maximum age and has been

removed from the LSDB.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the link state record (LSR) in the local switch's Link State Database (LSDB) for a domain

reachable in the fabric hit the maximum LSR age of 3600 seconds. After flooding the aged out record to the other switches, the LSR was removed from the LSDB and the fabric shortest path first (FSPF)

calculations were run to update the routes accordingly.

Recommended Check the switch for the reported domain to make sure it did not crash, become unresponsive, or is

experiencing frame transmission issues. Next check for any inter-switch link (ISL) ports on the switch

reporting the RASLog that may be flapping up and down rapidly resulting in premature LSR aging.

6.43 FSPF Messages

FSPF-1001

Message Input Port <port number> out of range.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the specified input port number is out of range because it does not exist on the switch.

Recommended No action is required. This is a temporary kernel error that does not affect your system. If the problem

Action persists, execute the **supportSave** command and contact your service provider.

FSPF-1002

Message Wrong neighbor ID (<domain ID>) in Hello message from port <port number>, expected

ID = <domain ID>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the switch has received a wrong domain ID from its neighbor switch in the HELLO

message from a specified port. This may happen when a domain ID for a switch has been changed.

FSPF-1003

Message Remote Domain ID <domain number> out of range, input port = <port number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified remote domain ID is out of range.

Recommended No action is required. The frame is discarded.

Action

FSPF-1005

Message Wrong Section Id <section number>, should be <section number>, input port = <port

number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that an incorrect section ID was reported from the specified input port. The section ID is part

of the fabric shortest path first (FSPF) protocol and is used to identify a set of switches that share an

identical topology database.

Recommended This switch does not support a non-zero section ID. Any connected switch from another manufacturer

with a section ID other than 0 is incompatible in a fabric of Brocade switches. Disconnect the

incompatible switch.

FSPF-1006

Message FSPF Version <FSFP version> not supported, input port = <port number>.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the fabric shortest path first (FSPF) version is not supported on the specified input port.

Recommended Update the FSPF version by running the firmwareDownload command. All current versions of the

Action Fabric OS support FSPF version 2.

FSPF-1007

Message ICL triangular topology is broken between the neighboring domains: <domain number>

and <domain number>. Please fix it ASAP.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the inter-chassis link (ICL) triangular topology is broken and becomes linear. It may

cause frame drop or performance slowdown.

Recommended

Action

Connect the two domains using ICL or regular inter-switch link (ISL) to form a triangular topology.

FSPF-1008

Message ICL triangular topology is formed among the domains: <domain number> (self), <domain

number>, and <domain number>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the inter-chassis link (ICL) triangular topology is formed.

FSPF-1009

Message ICL topology is not recommended on local domain <domain number>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the current inter-chassis link (ICL) topology is not recommended.

Recommended Use the **switchShow**, **islShow**, and **IsdbShow** commands to identify the neighbor domains that

Action violate the ICL connectivity requirement.

FSPF-1010

Message ICL Topology is valid on local domain <domain number>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the current inter-chassis link (ICL) topology is valid for routing from the local switch.

FSPF-1011

Message ICL topology is unbalanced.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the current configuration of inter-chassis link (ICL) paths are unbalanced.

Recommended Investigate current ICL configuration to ensure that all recommendations for cabling are satisfied.

Action

FSPF-1012

Message All existing ICL topology imbalances have been corrected.

Message Type LOG

Severity INFO

Probable Cause Indicates that the existing inter-chassis link (ICL) configuration that was resulting in an unbalanced

topology has been corrected.

FSPF-1013

Message Exceeded maximum number of supported paths (16) to one or more remote domains.

Message Type LOG

Severity WARNING

Probable Cause Indicates that there are more than 16 (maximum number of paths supported) available shortest cost

paths to reach one or more remote domains. Traffic may be impacted or follow unexpected traffic

patterns.

Recommended

Action

Use the **fabricShow -paths**, **topologyShow**, and **IsDbShow** commands to get additional details about which remote domains are violating the maximum paths limit. Refer to the *Fabric OS*

Administrator's Guide for information on the causes and potential impacts.

FSPF-1014

Message All previously reported maximum path violations have been corrected.

Message Type LOG

Severity INFO

Probable Cause Indicates that all existing violations of the maximum paths limit have been corrected.

FSPF-1015

Message Static link costs are not supported on AE Ports. Resetting link cost to default for

port <port index> from <old link cost value>.

Message Type LOG

Severity INFO

Probable Cause

Indicates that when an analytics E_Port or T_Port comes online and if there is a statically defined linkcost for the port, then the link cost of the port will be cleared and returned to the default value.

FSPF-1016

Message Port decommissioning request for port <port number> completed successfully. (Neighbor

WWN: <printf>)

Message Type LOG

Severity INFO

Probable Cause Indicates that the previously issued port decommissioning request has completed successfully.

FSPF-1017

Message Fabric topology invalid: remote domain(s) only reachable via path(s) through a non-

routing switch.

Message Type LOG

Severity WARNING

Probable Cause Indicates that one or more domains in the fabric are only reachable via a switch that does not support

routing traffic through it.

This can happen, for example, if an AMP switch is in the only path between any two switches in the

same fabric.

While the fabric is in this state due to the invalid topology, the fabric is unstable and incomplete. For all switches in the fabric, some new ports are blocked from coming online. Also, some fabric wide configuration operations, such as zone commits, may fail or be blocked. The switch may also report

RTWR messages.

This message may be reported during transient situations while the fabric is still forming. If so, then a

FSPF-1018 message should be seen once the fabric finished forming and the topology is valid.

Recommended Action Correct the topology by providing eligible paths that do not pass through the non-routing switch. This

may require additional connections or investigation of ISLs that failed to come online.

Alternatively, disable links between the non-routing switch and the domains only accessible via that

switch.

FSPF-1018

Message All previous remote domain(s) reachability restrictions via non-routed switches

cleared.

Message Type LOG

Severity INFO

Probable Cause

Indicates that any previously detected fabric reachability problems due to non-routed switches have all been cleared.

6.44 FSS Messages

FSS-1001

Message Component (<component name>) dropping HA data update (<update ID>).

Message Type LOG

> Severity WARNING

Probable Cause Indicates that an application has dropped a high availability (HA) data update.

Recommended For a dual control processor (CP) system, enable the HA state synchronization using the haSyncStart Action

command. For non-bladed systems, restart the switch using the **reboot** command.

If the problem persists, execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

FSS-1002

Message Component (<component name>) sending too many concurrent HA data update transactions

(<dropped update transaction ID>).

Message Type LOG

> **CRITICAL** Severity

Probable Cause Indicates that an application has sent too many concurrent high availability (HA) data updates.

Recommended For a dual CP system, enable the HA state synchronization using the haSyncStart command. For

Action non-bladed systems, restart the switch using the **reboot** command.

If the problem persists, execute the supportFtp command (as needed) to set up automatic FTP

transfers; then execute the supportSave command and contact your switch service provider.

FSS-1003

Message Component (<component name>) misused the update transaction (<transaction ID>)

without marking the transaction beginning.

Message Type LOG

> **WARNING** Severity

Probable Cause Indicates that the Fabric OS state synchronization (FSS) service has dropped the update because an

application did not set the transaction flag correctly.

Recommended Action

For a dual CP system, enable the high availability (HA) state synchronization using the hasyncStart command. For non-bladed systems, restart the switch using the reboot command.

If the problem persists, execute the supportFtp command (as needed) to set up automatic FTP

transfers; then execute the supportSave command and contact your switch service provider.

FSS-1004

Message Memory shortage.

Message Type LOG

> **ERROR** Severity

Probable Cause Indicates that the system ran out of memory.

Recommended

Execute the **memShow** command to view memory usage in the switch.

Action

For a dual CP system, enable the high availability (HA) state synchronization using the hasyncstart

command. For non-bladed systems, restart the switch using the **reboot** command.

If the problem persists, execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the supportSave command and contact your switch service provider.

FSS-1005

Message FSS read failure.

Message Type LOG

> Severity WARNING

Probable Cause Indicates that the read system call to the Fabric OS state synchronization (FSS) device has failed.

Recommended Action

If the problem persists, execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the supportSave command and contact your switch service provider.

FSS-1006

Message No FSS message available.

Message Type LOG

> Severity WARNING

Probable Cause Indicates that data is not available on the Fabric OS state synchronization (FSS) device.

Recommended If the problem persists, execute the supportFtp command (as needed) to set up automatic FTP Action

transfers; then execute the supportSave command and contact your switch service provider.

FSS-1007

FOS-90x-Message-RM103 Broadcom

Message <component name>: Faulty Ethernet connection.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the Ethernet connection between the active control processor (CP) and the standby CP

is not healthy. This error occurs when the standby CP does not respond to a request from the active CP within five seconds. This usually indicates a problem with the internal Ethernet connection and the

disruption of the synchronization process.

Recommended

Action

Execute the **supportShow** or **supportSave** command to validate the network configuration and then execute the **haSyncStart** command to restore the high availability (HA) synchronization. If the problem persists, contact your switch service provider.

FSS-1008

Message FSS Error: <Error Message>.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that a Fabric OS state synchronization (FSS) error has occurred.

Recommended

Action

Execute the **supportSave** command and contact your switch service provider.

FSS-1009

Message FSS Error: <Error Message>.

Message Type LOG | FFDC

Severity ERROR

Probable Cause Indicates that a Fabric OS state synchronization (FSS) error has occurred for the specified component.

The error code is displayed in the message.

Recommended

Action

Execute the **supportSave** command and contact your switch service provider.

FSS-1010

Message FSS Warning: <Warning Message>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a Fabric OS state synchronization (FSS) error may have occurred.

Recommended Execute the **supportSave** command and contact your switch service provider.

Action

FSS-1011

Message FSS Info: <Info Message>.

Message Type LOG

Severity INFO

Probable Cause Indicates a Fabric OS state synchronization (FSS) related informational message.

6.45 FSSM Messages

FSSM-1002

Message HA State is in sync.

Message Type LOG

Severity INFO

Probable Cause Indicates that the high availability (HA) state of the active control processor (CP) is in synchronization

with the HA state of the standby CP. If the standby CP is healthy, the failover will be nondisruptive.

FSSM-1003

Message HA State out of sync.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the high availability (HA) state of the active control processor (CP) is out of

synchronization with the HA state of the standby CP. If the active CP failover occurs when the HA state

is out of synchronization, the failover is disruptive.

Recommended If this message was logged as a result of a user-initiated action (such as running the **reboot**

Action command), no action is required.

Otherwise, execute the **haSyncStart** command on the active CP to resynchronize the HA state.

If the HA state does not synchronize, execute the haDump command to diagnose the problem.

If the problem persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

FSSM-1004

Message Incompatible software version in HA synchronization.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the active control processor (CP) and the standby CP in a dual CP system are running

firmware that is incompatible with each other. If the active CP fails, the failover will be disruptive.

In a switch system, this message is logged when a firmware upgrade or downgrade was invoked. The new firmware version is not compatible with the current running version. This causes a disruptive

firmware upgrade or downgrade.

Recommended For a dual CP system, execute the **firmwareDownload** command to load compatible firmware on the

Action standby CP.

FSSM-1005

Message Standby CP does not support more than 8 LS.

Message Type LOG | FFDC

Severity CRITICAL

Probable Cause Indicates that the active control processor (CP) is configured with more than 8 Logical Switches (LS)

and the standby CP is running firmware that does not support more than 8 LS, due to which high

availability (HA) is not synchronized between the active CP and the standby CP.

Recommended For a dual CP system, execute **firmwareDownload** command to load compatible firmware that

Action supports more than 8 LS on the standby CP.

6.46 FTC Messages

FTC-1001

Message Received Peer Congestion FPIN [event type: <Event_Type>] from device

PID:0x<N Port ID>

Message Type LOG

Severity INFO

Probable Cause Specified device is reporting a congestion condition.

Recommended Investigate fabric topology for oversubsubscription potential.

Action

FTC-1002

Message Received Link Integrity FPIN [event type: <Event_Type>] from device PID:0x<N_Port_ID>

Message Type LOG

Severity INFO

Probable Cause Specified device has detected a link integrity issue.

Recommended Diagnose the physical port (e.g., SFP, cabling, etc.).

Action

6.47 FV Messages

FV-1001

Message Flow Vision daemon initialized.

Message Type LOG

Severity INFO

Probable Cause Indicates that the Flow Vision daemon has successfully initialized.

FV-1002

Message Flow Vision Config Replay Completed Successfully.

Message Type LOG

Severity INFO

Probable Cause Indicates that the Flow Vision config replay has successfully completed.

FV-1003

Message Flow <Flow name> is deactivated. Reason: <Reason for deactivation>

Message Type LOG

Severity INFO

Probable Cause
Indicates that the specified flow is deactivated automatically by the system.

Recommended Verify the message using the specified reason for deactivation.

Action

No action is required if the message indicated by the specified reason is correct. Otherwise, activate the flow using the **flow --activate** command.

FV-1004

Message One or more flows are deactivated. Reason: <Reason for deactivation>

Message Type LOG

Severity INFO

Probable Cause Indicates that some of the flows are deactivated automatically by the system.

Recommended Verify the message using the specified reason for deactivation.

Action

No action is required if the message indicated by the specified reason is correct. Otherwise, activate

the flow using the **flow --activate** command.

FV-1005

Message The sys analytics vtap flow is not enforced from <port limit> user ports as

Encryption/Compression is enabled on one/many of them.

Message Type LOG

Severity WARNING

Probable Cause Indicates that Remote Flow Mirroring (RFM) filters are not installed on Encryption Compression Block

(ECB)-enabled application-specific integrated circuits (ASICs).

FV-1006

Message The sys analytics vtap flow is not enforced from <port limit> user ports as <reason>

Message Type LOG

Severity WARNING

Probable Cause Indicates that Remote Flow Mirroring (RFM) filters are not installed on Encryption Compression Block

(ECB)-enabled application-specific integrated circuits (ASICs).

FV-1007

Message The FC trace file for flow <flowName> has been processed. File <fileName> created.

Message Type LOG

Severity INFO

Probable Cause Indicates that the FC Trace capture for the given flow is ready.

Recommended The file can be uploaded using **flowCapture --upload** for offline viewing.

Action

FV-1008

Message The total buffer space allocated for pcap files created has reached 90 percent

threshold.

Message Type LOG

Severity WARNING

Probable Cause Indicates that further flow activation may fail.

Recommended Remove the pcap files using **flowCapture --delete file_name** to make space for new pcap files.

Action

FV-1009

Message There is a failure in processing FC trace file for flow <flowName>. File creation

failed.

Message Type LOG

Severity ERROR

Probable Cause Indicates error in processing the pcap file of FC Trace capture for the given flow.

FV-1010

Message The FC trace flow <flowName> has been deleted successfully.

Message Type LOG

Severity INFO

Probable Cause Indicates the deletion of FC Trace flow.

FV-1011

Message itreserve for the flow sys flow monitor has been changed from <oldItReserve> to

<newItReserve>

Message Type LOG

Severity INFO

Probable Cause Action to change ItReserve value is performed to honor SLOT SCN event.

FV-1012

Message The flow, <flowName>, has been deactivated because it can cause mild backpressure.

Message Type LOG

Severity INFO

Probable Cause Indicates the deactivation of flow.

FV-3000

Message Flow <flow name> is created with features <feature list>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified flow has been created.

FV-3001

Message Flow <flow_name> is deleted.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified flow has been deleted.

FV-3002

Message Flow <flow name> is activated for the feature(s) <feature list>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified flow has been activated.

FV-3003

Message Flow <flow_name> is deactivated for the feature(s) <feature_list>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified flow has been deactivated.

FV-3004

Message Configuration of Flow <flow name> is changed for the feature(s) <feature list>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that configuration of the specified flow has been changed.

FV-3005

Message Flow <flow_name> is reset for the feature(s) <feature_list>.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the specified flow is being reset.

FV-3006

Message Port(s) <port number or range> is(are) being configured as SIM Port. Some of the ports

may not be eligible to become SIM Port.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified ports are configured as SIM ports.

FV-3007

Message Port(s) <port_number_or_range> being deconfigured as SIM Port. Some of the ports may

be already deconfigured as SIM Port.

Message Type AUDIT

Class CFG

Severity INFO

FV-3008

Message All ports are being configured as SIM Port. Some of the ports may not be eligible to

become SIM Port.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that all ports are configured as SIM ports.

FV-3009

Message All ports being deconfigured as SIM Port. Some of the ports may be already

deconfigured as SIM Port.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that all ports are deconfigured as SIM ports.

FV-3010

Message Control configuration for flows has been changed.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that control configuration has been changed.

FV-3011

Message Control configuration has been changed for all applicable flows.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that control configuration has been changed for all applicable flows.

FV-3012

Message All flows are deactivated for the feature(s) <feature list>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that all flows are deactivated.

FV-3013

Message All user created flows are deleted.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that all user created flows are deleted.

FV-3014

Message All flows are reset for the feature(s) <feature_list>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates all flows are reset for the specified features.

FV-3015

Message Aging time of <days > days and <hours > hours is configured for 'sys mon analytics'

flow.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that aging time is configured.

FV-3016

Message IT Reserve Limit <itLimit> and ITL Reserve Limit <itLlimit> are configured for

'sys mon analytics' flow.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that Initiator and Target (IT) and Initiator, Target and LUN (ITL) reserve limits are configured.

FV-3017

Message Max ITL Per IT Limit <maxItlPerIt> is configured for 'sys mon analytics' flow.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that Maximum Initiator Target Lun(ITL) per Initiator Target(IT)limit is configured.

FV-3018

Message IT count limit has reached its Maximum <Count> for the chip <Chip> in slot <Slot>.

Message Type LOG

Severity INFO

Probable Cause Indicates that Initiator Target(IT) flow count limit has reached its Maximum value.

FV-3019

Message ITL count limit has reached its Maximum <Count> for the chip <Chip> in slot <Slot>.

Message Type LOG

Severity INFO

Probable Cause Indicates that Initiator Target(ITL) flow count limit has reached its Maximum value.

FV-3020

Message IT count limit for the switch has reached its Maximum value <Count>.

Message Type LOG

INFO Severity

Probable Cause Indicates that Initiator Target(IT) flow count limit has reached its Maximum value.

FV-3021

Message ITL count limit for the switch has reached its Maximum value <Count>.

Message Type LOG

> Severity INFO

Probable Cause Indicates that Initiator Target(ITL) flow count limit has reached its Maximum value.

6.48 HAM Messages

HAM-1001

Message Standby CP is not healthy, device <device name> status BAD, Severity = <severity

level>.

Message Type FFDC | LOG

> **CRITICAL** Severity

Probable Cause Indicates that a standby control processor (CP) device error is reported by the high availability

manager (HAM) health monitor, with the specified device and severity level. The severity level can be

critical, major, or minor.

The active CP will continue to function normally. Because the standby CP is not healthy, non-disruptive

Restart the standby CP blade by ejecting the card and reseating it. If the problem persists, replace the

failover is not possible.

Recommended

Action standby CP.

HAM-1002

Message Standby CP is healthy.

Message Type LOG

> Severity INFO

Probable Cause Indicates that all standby control processor (CP) devices monitored by the high availability manager

(HAM) health monitor reported no error.

HAM-1004

Processor rebooted - <Reboot Reason>. Message

Message Type LOG

Severity INFO

Probable Cause

Indicates that the switch has been restarted because of a user action or an error. The switch restart can be initiated by the **firmwareDownload**, **fastBoot**, **haFailover**, and **reboot** commands. Some examples of errors that may initiate this message are hardware errors, software errors, compact flash errors, or memory errors. The *Reboot Reason* variable can be one of the following:

- Hafailover
- Reset
- Fastboot
- Giveup Master:SYSM
- CP Faulty:SYSM
- FirmwareDownload
- ConfigDownload:MS
- ChangeWWN:EM
- Reboot:WebTool
- Fastboot:WebTool
- Software Fault:Software Watchdog
- Software Fault:Kernel Panic
- Software Fault:ASSERT
- Reboot:SNMP
- Fastboot:SNMP
- Reboot
- Chassis Config
- Reboot:API
- Reboot:HAM
- EMFault:EM

Recommended Action Execute the **errShow** command on both control processors (CPs) to view the error log for additional messages that may indicate reason for the switch restart.

HAM-1005

Message HeartBeat Miss reached threshold.

Message Type LOG

Severity INFO

Probable Cause Indicates that either the active CP Ethernet Media Access Controller (EMAC) or the standby CP is

down. The active CP will run a diagnostic test on EMAC and will wait for the standby CP to reset it if it

is down.

HAM-1006

Message EMAC controller for Active CP is BAD.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the local Ethernet Media Access Controller (EMAC) on the active CP has been marked

BAD as determined by the diagnostic test run by the high availability manager (HAM) module.

The standby CP will take over and reset the active CP. The system will be non-redundant because the

Recommended

standby CP becomes the active CP.

Action

HAM-1007

Message Need to reboot the system for recovery, reason: <reason name>.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause

Indicates that the switch in current condition needs to be restarted to achieve a reliable recovery. The reasons can be one of the following:

- The standby CP was not ready when failover occurred.
- The failover occurred when the last logical switch (LS) transaction was incomplete.
- The switch failed when timeout occurred at certain stage.
- The cold or warm recovery has failed.

Recommended Action If auto-reboot is enabled, the switch will automatically restart. Otherwise, execute the **reboot**

command to manually restart the switch.

HAM-1008

Message Rebooting the system for recovery - auto-reboot is enabled.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the recovery by auto-reboot is enabled, and therefore the switch automatically restarts.

This message is displayed if the event logged in HAM-1007 has occurred and auto-reboot is enabled.

Recommended

Action

Wait until the switch is up to perform any operations.

HAM-1009

Message Need to MANUALLY REBOOT the system for recovery - auto-reboot is disabled.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the recovery by auto-restart is disabled, therefore the switch needs to be manually

restarted for recovery. This message is displayed if the event logged in HAM-1007 has occurred and

auto-reboot is disabled.

Recommended

Action

Execute the **reboot** command to restart the switch manually.

HAM-1010

Message Manually trigger haReboot/reboot for recovery from OOM when appropriate.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that out of memory (OOM) condition has been detected when the switch was not ready for

warm recovery.

Recommended Manually trigger the switch restart for cold recovery, if needed; or wait until switch is ready for warm

Action recovery and execute the **haReboot** or **haFailover** command.

HAM-1011

Message hareboot is automatically triggered for warm recovery from OOM.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that out of memory (OOM) condition has been detected when switch was ready for warm

recovery. The haReboot is automatically triggered.

Recommended

Action

No action is required. The **haReboot** is automatically triggered to recover from the OOM condition.

HAM-1013

Message <error message>.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the software watchdog has detected termination of a restartable daemon, but could not

restart the daemon.

Recommended I

Action

Manually initiate a restart or failover, if needed.

HAM-1014

Message <error message>.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the software watchdog has detected termination of a restartable daemon and needs to

restart or initiate a failover.

Recommended Execute the **reboot** command to restart the system or initiate a failover by using the **haFailover**

Action command.

HAM-1015

Message <info message>.

Message Type AUDIT

Class RAS

Severity INFO

Probable Cause Indicates that a terminated software component has been restarted.

HAM-1016

Message Invalid Dexpansion request: <reason name>.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the active CP has sent an invalid dexpansion request.

Recommended HASM collects the required logs and skips the invalid request. This helps to keep the daemon alive by

Action skipping the invalid request causing the hasmd to crash

HAM-1017

Message High Availability <Enabled or Disabled>.

Message Type AUDIT

Class RAS

Severity INFO

Probable Cause Indicates that the High Availability is disabled or enabled.

HAM-1018

Message HA Reboot.

Message Type AUDIT

Class RAS

Severity INFO

Probable Cause Indicates that the CLI HA reboot triggered.

HAM-1019

Message Standby CP FOS is not enabled due to CP Mismatch.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that FOS bringup is disabled on Standby CP.

Recommended Insert a new Standby CP.

Action

6.49 HAMK Messages

HAMK-1001

Message Warm Recovery Failed.

Message Type LOG | FFDC

Severity CRITICAL

Probable Cause Indicates that the switch failed during the warm recovery.

Recommended This event

Action

This event triggers the switch restart automatically and attempts a cold recovery.

supportSave command and contact your switch service provider.

HAMK-1002

Message Heartbeat down.

Message Type LOG

Severity INFO

Probable Cause Indicates that the active control processor (CP) blade determined that the standby CP blade is down.

This can be a result of a user-initiated action such as firmware download, the standby CP blade being

Execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the

reset or removed, or an error in the standby CP blade.

Recommended

Action

Monitor the standby CP blade for a few minutes. If this message is due to a standby CP restart, the

HAMK-1003 message will display after the standby CP is restarted.

If the standby CP does not connect to the active CP after 10 minutes, restart the standby CP blade by

ejecting the blade and reseating it.

HAMK-1003

Message Heartbeat up.

Message Type LOG

Severity INFO

Probable Cause Indicates that the active control processor (CP) blade detected the standby CP blade. This means that

the standby CP blade is available to take over in case a failure happens in the active CP blade.

Typically, this message is displayed when the standby CP blade restarts.

HAMK-1004

Message Resetting standby CP (double reset may occur).

Message Type LOG

Severity INFO

Probable Cause Indicates that the standby control processor (CP) is being reset due to a loss of heartbeat. Typically,

this message is displayed when the standby CP has been restarted. Note that in certain

circumstances, a CP may experience a double reset and restart twice. A CP can recover automatically

even if it has restarted twice.

6.50 HIL Messages

HIL-1101

Message Slot <slot number> faulted, <nominal voltage> (<measured voltage>) is above

threshold.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the blade voltage is above threshold.

Recommended Replace the faulty blade or switch (for non-bladed switches).

Action

HIL-1102

Message Slot <slot number> faulted, <nominal voltage> (<measured voltage>) is below

threshold.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the blade voltage is below threshold.

Recommended Replace the faulty blade or switch (for non-bladed switches).

Action

HIL-1103

Message Blower
blower number> faulted, <nominal voltage> (<measured voltage>) is above

threshold.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the fan voltage is above threshold.

Recommended Action Run the **psShow** command to verify the power supply status.

Try to reseat the faulty fan field-replaceable units (FRUs) and power supply FRU to verify that they are

seated properly.

If the problem persists, replace the fan FRU or the power supply FRU as necessary.

HIL-1104

Message Blower
blower number> faulted, <nominal voltage> (<measured voltage>) is below

threshold.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the fan voltage is below threshold.

Recommended Run the **psShow** command to verify the power supply status.

Action

Try to reseat the faulty fan field-replaceable units (FRUs) and power supply FRU to verify that they are

seated properly.

If the problem persists, replace the fan FRU or the power supply FRU as necessary.

HIL-1105

Message Switch error, <nominal voltage> (<measured voltage>) above threshold.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the switch voltage is above threshold. This message is specific to non-bladed switches.

Recommended For switches that do not have field-replaceable units (FRUs), replace the entire switch.

If the 12 volt level is faulty, replace one or both power supplies; if any other voltage is faulty, replace

the entire switch.

HIL-1106

Message Switch error, <nominal voltage> (<measured voltage>) below threshold.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the switch voltage is below threshold. This message is specific to non-bladed switches.

Recommended For switches that do not have field-replaceable units (FRUs), replace the entire switch.

Action

If the 12 volt level is faulty, replace one or both power supplies; if any other voltage is faulty, replace

the entire switch.

HIL-1107

Message Switch faulted, <nominal voltage> (<measured voltage>) above threshold. System

preparing for reset.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the switch voltage is above threshold. This message is specific to non-bladed switches.

Recommended For switches that do not have field-replaceable units (FRUs), replace the entire switch.

Action

If the 12 volt level is faulty, replace one or both power supplies; if any other voltage is faulty, replace

the entire switch.

HIL-1108

Message Switch faulted, <nominal voltage> (<measured voltage>) below threshold. System

preparing for reset.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the switch voltage is below threshold. This message is specific to non-bladed switches.

Recommended For switches that do not have field-replaceable units (FRUs), replace the entire switch.

Action

If the 12 volt level is faulty, replace one or both power supplies; if any other voltage is faulty, replace

the entire switch.

HIL-1109

Message PS < Power Supply Number 1..4> SEEPROM corruption (fruhdr checksum mismatch) detected.

Message Type LOG

Severity ERROR

Probable Cause Indicates detection of Power Supply (PS) Field Replaceable Unit header (fruhdr) checksum mismatch.

Recommended No action is required. The checksum mismatch is benign.

Action

HIL-1201

Message Blower
blower number>, speed (<measured speed> RPM) above threshold.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the fan speed (in RPM) has risen above the maximum threshold. A high speed does not

necessarily mean that the fan is faulty.

Recommended

Action

Run the **tempShow** command to verify that the switch temperatures are within operational ranges.

Refer to the hardware reference manual for the temperature range of your switch.

Make sure that the area is well-ventilated and that the room temperature is within the operational range of your switch. Refer to the hardware reference manual for your switch for the operational

temperature range.

Run the **fanShow** command to monitor the speed of the fan generating this error.

If the fan continues to generate this message, replace the fan FRU.

HIL-1202

Message Blower <blower number> faulted, speed (<measured speed> RPM) below threshold.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified fan speed (in RPM) has fallen below the minimum threshold.

Recommended

Action

Replace the fan FRU.

HIL-1203

Message Fan <fan number> faulted, speed (<measured speed> RPM) above threshold.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified fan speed (in RPM) has risen above the maximum threshold. A high speed

does not necessarily mean that the fan is faulty.

Recommended

Action

Run the **tempShow** command to verify that the switch temperatures are within operational ranges.

Refer to the hardware reference manual for the temperature range of your switch.

Make sure that the area is well-ventilated and that the room temperature is within the operational range of your switch. Refer to the hardware reference manual for your switch for the operational

temperature range.

Run the **fanShow** command to monitor the speed of the fan generating this error.

If the fan continues to generate this message, replace the fan FRU.

HIL-1204

Message Fan <fan number> faulted, speed (<measured speed> RPM) below threshold.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified fan speed (in RPM) has fallen below the minimum threshold. This message

is specific to non-bladed switches.

Recommended Replace the fan field-replaceable unit (FRU).

Action For switches that do not have FRUs, replace the entire switch.

HIL-1206

Message Fan <fan number> sensor <sensor number> , speed (<measured speed> RPM) below

threshold.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified fan speed (in RPM) has fallen below the minimum threshold. This problem

can quickly cause the switch to overheat. This message is specific to non-bladed switches.

Recommended Replace the fan field-replaceable unit (FRU), where applicable. For non-FRU components, please

contact your equipment vendor's support.

HIL-1207

Message Fan <fan number> is faulty.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the fan is faulty.

maleatee that the famile facility.

Recommended Use the **tempShow** command to verify that the switch temperatures are within operational ranges.

Action Refer to the hardware reference manual for the temperature range of your switch.

Make sure that the area is well-ventilated and that the room temperature is within the operational range of your switch. Refer to the hardware reference manual for your switch for the operational

temperature range.

Use the **fanShow** command to monitor the status of the fan generating this error.

If the fan continues to generate this message, replace the switch because the fan is not field-

replaceable.

HIL-1208

Message Fan <fan number> is not faulty.

Message Type LOG

Severity INFO

Probable Cause Indicates that the fan is not faulty.

Action

If the fan continues to generate this message, it indicates oscillation between faulty and non-faulty

This can only occur on switches with non-removable fans. It follows a previous indication of faultiness.

behavior. Replace the switch because the fan is not field-replaceable.

HIL-1301

Recommended

Message 1 blower failed or missing. Replace failed or missing blower assembly immediately.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a fan field-replaceable unit (FRU) has failed or has been removed. This message is

often preceded by a low speed error message. This problem can cause the switch to overheat.

Recommended Replace the affected fan FRU immediately.

Action

HIL-1302

Message <count> blowers failed or missing. Replace failed or missing blower assemblies

immediately.

Message Type LOG

Severity WARNING

Probable Cause Indicates that multiple fan field-replaceable units (FRUs) have failed or are missing on a switch. This

message is often preceded by a low fan speed message.

Recommended Replace the affected fan FRUs immediately.

Action

HIL-1303

Message One fan failed. Replace failed fan FRU immediately.

Message Type LOG

Severity ERROR

Probable Cause Indicates that a fan field-replaceable unit (FRU) has failed. This message is often preceded by a low

fan speed message.

Recommended

Replace the faulty fan FRU immediately.

Action

HIL-1304

Message Two fans failed. Replace failed fan FRUs immediately.

Message Type LOG

Severity ERROR

Probable Cause Indicates that multiple fan field-replaceable units (FRUs) have failed. This message is often preceded

by a low fan speed message.

Recommended Replace the faulty fan FRUs immediately.

Action

HIL-1305

Message One or two fans failed. Replace failed fan FRUs immediately.

Message Type LOG

Severity ERROR

Probable Cause Indicates that multiple fan field-replaceable units (FRUs) have failed. This message is often preceded

by a low fan speed message.

Recommended Replace the faulty fan FRUs immediately.

Action

HIL-1306

Message Three fans failed. Replace failed fan FRUs immediately.

Message Type LOG

Severity ERROR

Probable Cause Indicates that three fan field-replaceable units (FRUs) have failed. This message is often preceded by

a low fan speed message.

Recommended Replace the faulty fan FRUs immediately.

Action

HIL-1307

Message Four or five fans failed. Replace failed fan FRUs immediately.

Message Type LOG

Severity ERROR

Probable Cause Indicates that multiple fan field-replaceable units (FRUs) have failed. This message is often preceded

by a low fan speed message.

Recommended Replace the faulty fan FRUs immediately.

Action

HIL-1308

Message All fans failed. Replace failed fan FRUs immediately.

Message Type LOG

Severity ERROR

Probable Cause Indicates that all fans have failed. This message is often preceded by a low fan speed message.

Recommended Replace the faulty fan field-replaceable units (FRUs) immediately.

Action

HIL-1309

Message <count> fan FRUs failed. Replace failed fan FRUs immediately.

Message Type LOG

Severity ERROR

Probable Cause Indicates that multiple fans have failed. This message is often preceded by a low fan speed message.

Recommended Replace the faulty fan field-replaceable units (FRUs) immediately.

Action

HIL-1310

Message <count> fan(s) faulty.

Message Type LOG

Severity WARNING

Probable Cause Indicates that multiple fans have failed. This message is often preceded by a low fan speed message.

Recommended Action Because the fans are not field-replaceable, replace the switch if the temperature is high.

HIL-1311

Message No fans are faulty.

Message Type LOG

Severity INFO

Probable Cause Indicates recovery from an earlier condition of one or more fans having failed.

Recommended Action This can only occur on switches with non-removable fans. It follows a previous indication of faultiness.

If the fan continues to generate this message, it indicates oscillation between faulty and non-faulty

behavior. Replace the switch because the fan is not field-replaceable.

HIL-1312

Message <number of failed fans> blower(s) failed. Check all blower units immediately.

Message Type LOG

Severity WARNING

Probable Cause Indicates that one or more fan or blower units have failed on the switch. This message is often

preceded by a low fan speed or fan failure message.

Recommended

Action

Check the ${\bf fanShow}$ command to see the system operating temperatures. Ensure the system is within

operational temperature limits and the system has adequate airflow.

If fans are present and spinning but marked as faulty or missing, rebooting the switch may be

necessary.

Please contact your equipment vendor's support.

HIL-1401

Message One fan FRU missing. Install fan FRU immediately.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a fan field-replaceable unit (FRU) has been removed.

Recommended Install the missing fan FRU.

Action

HIL-1402

Message Two fan FRUs missing. Install fan FRUs immediately.

Message Type LOG

Severity WARNING

Probable Cause Indicates that two fan field-replaceable units (FRUs) have been removed.

Recommended Install the missing fan FRUs immediately.

Action

HIL-1403

Message All fan FRUs missing. Install fan FRUs immediately.

Message Type LOG

Severity WARNING

Probable Cause Indicates that all fan field-replaceable units (FRUs) have been removed.

Recommended Install the missing fan FRUs immediately.

Action

HIL-1404

Message <count> fan FRUs missing. Install fan FRUs immediately.

Message Type LOG

Severity WARNING

Probable Cause Indicates that one or more fan field-replaceable units (FRUs) have been removed.

Recommended Install the missing fan FRUs immediately.

Action

HIL-1405

Message <number of missing fans> fan(s) missing. Check all fans immediately.

Message Type LOG

Severity WARNING

Probable Cause Indicates that one or more of the expected fan units have not been detected in the system.

Recommended Check the switch's fan units to ensure all are present and running.

Action ______

Check the fanShow command to ensure system is operating within thermal thresholds. Ensure the

system has adequate airflow.

Please contact your equipment vendor's support.

HIL-1501

Message Slot <slot number>, high temperature (<measured temperature>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the temperature of this blade has risen above the warning threshold.

Recommended Run the **fanShow** command to verify all the fans are working properly.

Action

Make sure that the area is well-ventilated and that the room temperature is within operational range of

your switch. Refer to the hardware reference manual for your switch for the operational temperature

range.

HIL-1502

Message Slot <slot number>, high temperature (<measured temperature>). Unit will be shut down

in 2 minutes if temperature remains high.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the temperature of this blade has risen above the critical threshold. This usually follows

a high-temperature message.

Recommended Run the **fanShow** command to verify all the fans are working properly.

Action

Make sure that the area is well-ventilated and that the room temperature is within operational range of your switch. Refer to the hardware reference manual for your switch for the operational temperature

range.

If the message persists, replace the blade.

HIL-1503

Message Slot <slot number>, unit shutting down.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the temperature of this blade has been above the maximum threshold for at least two

minutes. The blade is shut down to prevent damage. This usually follows a high-temperature warning

message.

Recommended Action Run the fanShow command to verify all the fans are working properly.

Make sure that the area is well-ventilated and that the room temperature is within the operational range of your switch. Refer to the hardware reference manual for your switch for the operational temperature range.

If the message persists, replace the faulty blade.

HIL-1504

Message System within normal temperature specifications (<measured temperature> C).

Message Type LOG

Severity INFO

Probable Cause Indicates that temperatures in the system have returned to normal.

HIL-1505

Message High temperature (<measured temperature> C), fan speed increasing per environmental

specifications.

Message Type LOG

Severity WARNING

Probable Cause Indicates that temperatures in the system have risen above the warning threshold and that the fan

speed is being increased.

Recommended

Action

Run the **fanShow** command to verify all the fans are working properly.

Make sure that the area is well-ventilated and that the room temperature is within the operational range of your switch. Refer to the hardware reference manual for your switch for the operational

temperature range.

HIL-1506

Message High temperature (<measured temperature> C) exceeds system temperature limit. System

will shut down within 2 minutes.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that temperatures in the system have risen above the critical threshold.

Recommended

Action

Run the **fanShow** command to verify that all fans are working properly. Replace any deteriorating fan

field-replaceable units (FRUs), where applicable. For any deteriorating fan units that are non-FRUs,

please contact your equipment vendor's support.

Make sure that the area is well-ventilated and that the room temperature is within the operational

range of your switch. Refer to the hardware reference manual for your switch for the operational temperature range.

HIL-1507

Message High temperature warning time expired. System preparing for shutdown.

Message Type FFDC | LOG

> **CRITICAL** Severity

Probable Cause Indicates that temperatures in the system have risen above the critical threshold.

Recommended To avoid causing damage to the switch, the system shuts down automatically. To help prevent future Action

problems, make sure that all the fans are working properly.

Make sure that the area is well-ventilated and that the room temperature is within the operational range of your switch. Refer to the hardware reference manual for your switch for the operational

temperature range.

HIL-1508

Message Fan faulty warning time expired. System preparing for shutdown.

FFDC | LOG Message Type

> **CRITICAL** Severity

Probable Cause Indicates that temperatures in the system have remained above the critical threshold too long.

Recommended To avoid causing damage to the switch, the system shuts down automatically. To help prevent future Action

problems, make sure that all the fans are working properly.

Make sure that the area is well-ventilated and that the room temperature is within the operational range of your switch. Refer to the hardware reference manual for your switch for the operational

temperature range.

HIL-1509

Message High temperature (<measured temperature> C). Warning time expired. System preparing

for shutdown.

FFDC | LOG Message Type

> **CRITICAL** Severity

Probable Cause Indicates that temperatures in the system have risen above the critical threshold.

Recommended To avoid causing damage to the switch, the system shuts down automatically. To help prevent future

Action problems, make sure that all the fans are working properly.

FOS-90x-Message-RM103 Broadcom

Make sure that the area is well-ventilated and that the room temperature is within the operational range of your switch. Refer to the hardware reference manual for your switch for the operational temperature range.

HIL-1510

Message Current temperature (<measured temperature> C) is below shutdown threshold. System

shutdown canceled.

Message Type LOG

Severity WARNING

Probable Cause Indicates that temperatures in the system have dropped below the critical threshold; the system can

continue operation.

Recommended To help prevent future problems, make sure that all the fans are working properly.

Action

Make sure that the area is well-ventilated and that the room temperature is within the operational range of your switch. Refer to the hardware reference manual for your switch for the operational

temperature range.

HIL-1511

Message Fan speed of all the fan FRUs is increasing to <Fan RPM> RPM as per environmental

specifications.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that temperatures in the system have risen above the warning threshold and that the fan

speed is being increased.

Recommended Run the **fanShow** command to verify all the fans are working properly.

Make sure that the area is well-ventilated and that the room temperature is within the operational

range of your switch. Refer to the hardware reference manual for your switch for the operational

temperature range.

HIL-1512

Message High temperature (<measured temperature> C), Exceeds environmental specifications.

Message Type LOG

Severity WARNING

Probable Cause Indicates that temperatures in the system have risen above the warning threshold.

Recommended Action Run the fanShow command to verify all the fans are working properly.

Make sure that the area is well-ventilated and that the room temperature is within the operational range of your switch. Refer to the hardware reference manual for your switch for the operational

temperature range.

HIL-1513

Message Slot <slot number>, high temperature (<measured temperature>). Blade in the slot will

be shut down if temperature remains high.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the temperature of this blade has risen above the critical threshold. This usually follows

a high-temperature message.

Recommended Run the **fanShow** command to verify all the fans are working properly.

Action

Make sure that the area is well-ventilated and that the room temperature is within operational range of your switch. Refer to the hardware reference manual for your switch for the operational temperature

range.

If the message persists, replace the blade.

HIL-1514

Message Blade in slot <slot number> is shutting down.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the temperature of this blade has been above the maximum threshold for at least two

minutes. The blade is shut down to prevent damage. This usually follows a high-temperature warning

message.

Recommended

Action

Run the **fanShow** command to verify all the fans are working properly.

Make sure that the area is well-ventilated and that the room temperature is within the operational range of your switch. Refer to the hardware reference manual for your switch for the operational

temperature range.

If the message persists, replace the faulty blade.

HIL-1515

Message High temperature (<measured temperature> C) exceeds system temperature limit. System

will shut down soon.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that temperatures in the system have risen above the critical threshold.

Recommended Run the **fanShow** command to verify that all fans are working properly. Replace any deteriorating fan

Action field-replaceable units (FRUs).

Make sure that the area is well-ventilated and that the room temperature is within the operational range of your switch. Refer to the hardware reference manual for your switch for the operational

temperature range.

HIL-1516

Message Fan speed of all the fan FRUs is increasing to <Fan RPM> RPM as per environmental

specifications.

Message Type LOG

Severity WARNING

Probable Cause Indicates that temperatures in the system have risen and the fan speed is being increased.

Recommended Run the **fanShow** command to verify all the fans are working properly.

Action

Make sure that the area is well-ventilated and that the room temperature is within the operational

range of your switch. Refer to the hardware reference manual for your switch for the operational

temperature range.

HIL-1517

Message Fan speed of all the fan FRUs changing to <Fan RPM> RPM as per environmental

specifications.

Message Type LOG

Severity WARNING

Probable Cause Indicates that temperatures in the system have fallen and the fan speed is being decreased.

Recommended Run the **fanShow** command to verify all the fans are working properly.

Action

HIL-1518

Message <number of failed and/or absent fans> failed and/or absent fan(s) exceeds system

threshold. System will shut down within 2 minutes.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the system has exceeded its operational limits for the allowed number of failed, faulty,

and absent fan units.

Recommended Action Run the **fanShow** command to see which fans have failed or are absent.

Make sure that the area is well-ventilated and that the room temperature is within the operational range of your switch. Refer to the hardware reference manual for your switch for the operational

temperature range.

Contact your equipment vendor's support.

HIL-1519

Message <number of failed/faulty and absent fan> failed and/or absent fans is back within

system thresholds. System shutdown canceled.

Message Type LOG

> **WARNING** Severity

Probable Cause Indicates that the number of failed, faulty, and absent fan units has returned to be within range for the

system's operational threshold.

Recommended

Run the fanShow command to verify that all fans are working properly. Action

Make sure that the area is well-ventilated, the fans are not blocked, and that the room temperature is within the operational range of your switch. Refer to the hardware reference manual for your switch for

the operational temperature range.

If any fans are still faulty or absent, contact you equipment vendor's support.

HIL-1601

Message Using backup temperature sensor. Attention needed.

LOG Message Type

> **ERROR** Severity

Probable Cause Indicates that temperature readings from the primary sensor are out of range.

Recommended Action

Run the **fanShow** command to verify that all fans are operating correctly. Replace any deteriorating fan field-replaceable units (FRUs), where applicable. For failures in non-FRU components, please

contact your equipment vendor's support.

Run the tempShow command to verify temperature values. If any sensor is too high, monitor the

switch. Try rebooting or power cycling the switch.

HIL-1602

Message Multiple temperature sensors failed. Service immediately.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that temperature readings from multiple sensors are out of range.

Recommended Action

Run the **fanShow** command to verify that all fans are operating correctly. Replace any deteriorating fan field-replaceable units (FRUs), where applicable. For failures of non-FRU components, please

contact your equipment vendor's support.

Run the tempShow command to verify temperature values. If any sensor is too high, monitor the

switch. Try rebooting or power cycling the switch.

HIL-1603

Message <failure count> fans out of service. System is shutting down immediately.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the total fan failure count is greater than or equal to two.

Action problems, make sure that all the fans are working properly.

HIL-1605

Recommended

Message High temperature (<measured temperature> C), fan speed increasing per environmental

To avoid causing damage to the switch, the system shuts down automatically. To help prevent future

specifications.

Message Type LOG

Severity INFO

Probable Cause Indicates that temperatures in the system have risen above the threshold and that the fan speed is

being increased.

HIL-1610

Message Fan/PS unit <Combo fan/power supply unit number> not supplying power, fan speeds may

not be available. Please ensure that the unit has power and the switch is on.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the power supply is not connected to a power source, is not switched on, or the unit is

faulty. This message is applicable only to the Brocade 5100, 6505, 6510, 6520, and VA-40FC.

Recommended Action Ensure the power cord is connected to the unit with a valid power source and then switch on the unit (if applicable). If the problem persists, try reseating the unit. If the problem still persists, replace the FRU.

HIL-1611

Message MISMATCH in PSU-FAN Air Flow direction. Replace PSU with fan air flows in same

direction. System will be shut down in 2 minutes.

Message Type FFDC | LOG

> **CRITICAL** Severity

Probable Cause Indicates that the airflows of the power supply and fan assemblies are moving in the reverse or

> opposite direction, which could overheat the system. The airflow of the power supply and fan assemblies must move in the same direction or the system will shut down in two minutes. This

message is applicable only to the Brocade 6505 and Brocade 6510.

Recommended Use the chassisShow command to check the airflow directions of the power supply and fan

assemblies. Ensure that the airflows run in the same direction.

HIL-1612

Message MISMATCH in PSU-FAN Air Flow direction. System shut down.

Message Type LOG

Action

CRITICAL Severity

Probable Cause Indicates that the airflows of the power supply and fan assemblies are moving in the reverse or

opposite direction. The system will shut down immediately. This message is applicable only to the

Brocade 6505 and Brocade 6510.

Recommended

Action

Ensure that the airflows of the power supply and fan assemblies run in the same direction.

HIL-1613

Message PSU-FAN FRUS Air Flow matched. System shutdown canceled.

Message Type LOG

> INFO Severity

Probable Cause Indicates that the airflows of the power supply and fan assemblies have changed to move in the same

direction. The system continues to operate. This message is applicable only to the Brocade 6505 and

Brocade 6510.

Recommended Ensure that the airflows of the power supply and fan assemblies run in the same direction.

Action

HIL-1614

Message MISMATCH in Fan airflow direction. Replace FRU with fan airflow in same direction.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the airflow of the fan is in the reverse direction. This may heat up the system.

Recommended Replace the fan field-replaceable units (FRUs) in such a manner that the air flows in the same direction as the remaining fans. Refer to the *Hardware Reference Manual* of your switch for

instructions to replace the fan FRUs.

HIL-1615

Message MISMATCH in PSU-Fan FRUs airflow direction. Replace PSU with fan airflow in same

direction.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that the airflow of the power supply unit (PSU) fan is in the reverse direction. This may heat

up the system.

Recommended Replace the PSU fan field-replaceable unit (FRU) in such a manner that the air flows in the same

direction as the remaining fans. Refer to the *Hardware Reference Manual* of your switch for

instructions to replace the PSU fan FRU.

HIL-1621

Message MISMATCH in PSU-FAN Air Flow direction. Please ensure that all FANs (PSU and

standalone) blow in the same direction.

Message Type FFDC | LOG

Severity WARNING

Probable Cause Indicates that the airflows of the power supply fan assemblies are mismatched. This can lead to

overheating of the system. The airflow of the power supply fan assemblies must be in the same direction as that of the standalone fan field-replaceable units (FRUs). This message is applicable only

to the Brocade 6520.

Recommended Use the **chassisShow** command to check the airflow directions of the power supply and fan Action assemblies. Ensure that the airflows run in the same direction for power supply fans as well a

assemblies. Ensure that the airflows run in the same direction for power supply fans as well as

standalone fan FRUs.

HIL-1623

Message Airflow for the PSU-FANs and Standalone FAN FRUs is now matched.

Message Type LOG

Severity INFO

Probable Cause Indicates that the airflows of the power supply fans and standalone fan field-replaceable units (FRUs)

are now matched and flowing in the same direction. This message is applicable only to the Brocade

6520.

Recommended

Action

Ensure that the airflows of the power supply fans and standalone fan FRUs run in the same direction.

HIL-1624

Message MISMATCH in Standalone FAN FRUs Air Flow direction. Please ensure that all FANs (PSU

and Standalone) blow in the same direction.

Message Type FFDC | LOG

Severity WARNING

Probable Cause Indicates that the airflows of the standalone fan assemblies are mismatched. This can lead to

overheating of the system. The airflow of the standalone fan assemblies must be in the same direction

as that of the power supply unit (PSU) fans. This message is applicable only to the Brocade 6520.

Recommended

Action

Use the **chassisShow** command to check the airflow directions of the power supply and fan assemblies. Ensure that the airflows run in the same direction for power supply fans as well as

standalone fan FRUs.

HIL-1625

Message MISMATCH in Air Flow direction between PSU-FANs and standalone FANs. Ensure that the

airflow for PSU-FANs and standalone FANs match.

Message Type FFDC | LOG

Severity WARNING

Probable Cause Indicates that the airflows of the power supply fans and standalone fan field-replaceable units (FRUs)

are mismatched. This can lead to overheating of the system. The airflow of the power supply fan assemblies must be in the same direction as that of the standalone fan FRUs. This message is

applicable only to the Brocade 6520.

Recommended

Action

Use the **chassisShow** command to check the airflow directions of the power supply and fan assemblies. Ensure that the airflows run in the same direction for power supply fans as well as

standalone fan FRUs.

HIL-1626

Message Fan direction of Fan FRU unit <FAN FRU unit number> mismatches with the chassis air

flow direction.

Message Type LOG

> Severity **WARNING**

Probable Cause Indicates that the fan direction of fan field-replaceable unit (FRU) mismatches with the chassis air flow

direction programmed in the WWN cards.

Recommended Replace the existing fan FRU with a fan FRU compatible with the chassis air flow direction.

Action

HIL-1627

Message Fan direction of PS FRU unit <PS FRU unit number> mismatches with the chassis air

flow direction.

Message Type LOG

> Severity WARNING

Probable Cause Indicates that the fan direction of power supply (PS) field-replaceable unit (FRU) mismatches with the

chassis air flow direction programmed in the WWN cards.

Recommended Replace the existing PS FRU with a PS FRU compatible with the chassis air flow direction.

Action

HIL-1628

Message Fan direction(<Fan air flow direction>) of PSU-Fan FRU unit <PSU-Fan FRU unit number>

mismatches with the system air flow direction(<System air flow direction>).

Message Type LOG

> WARNING Severity

Probable Cause Indicates that the fan direction of PSU-Fan field-replaceable unit (FRU) mismatches with the system

air flow direction.

Recommended Replace the existing PSU-Fan FRU with a PSU-Fan FRU compatible with the system air flow direction.

Action

HIL-1629

Message PSU unit <PS FRU unit number> input voltage(<Input Voltage>V) is in invalid range.

LOG Message Type

> Severity WARNING

Probable Cause Indicates that the PSU input voltage is not within the expected range.

Recommended

Check the PSU input voltage source.

Action

HIL-1630

Message Auto-configuring system airflow direction to <System airflow direction>.

Message Type LOG

Severity INFO

Probable Cause Indicates that FOS has auto-configured system airflow direction. This usually happens when FOS

identifies that the system airflow direction mismatches with the airflow direction of all fans and/or

power supplies.

HIL-1650

Message Unable to detect < WWN Card Unit Number(s) > in chassis. Access to WWN halted.

Message Type LOG

Severity ERROR

Probable Cause Indicates that one or both of the World Wide Name (WWN) cards is missing. Both WWN cards must be

present for normal operation.

Recommended

Action

Make sure that both WWN cards are inserted.

HIL-1651

Message On switch/slot <Slot Id>. WWN is corrupted on both cards.

Message Type LOG

Severity ERROR

Probable Cause Indicates that World Wide Name (WWN) is corrupted in one or both of the WWN cards. At least one

WWN card must have a valid WWN for normal operation.

Recommended

Contact your switch service provider for assistance.

Action

HIL-1652

Message Power supply unit <UnitNumber>, Temperature (<Temperature>). Power Supply Unit will

be shut down if temperature remains high.

Message Type LOG

Severity WARNING

Probable Cause Indicates that power supply unit temperature has risen to threshold. Power supply is going to

shutdown.

Recommended

Action

Run the **psshow** command to verify all power supply unit temperature.

Make sure that the area is well-ventilated and that the room temperature is within operational range of your switch. Refer to the hardware reference manual for your switch for the operational temperature

range.

HIL-1653

Message Power supply unit <UnitNumber>, Gen5 PS is in use. Please replace it with Gen6 PS for

high availability operation.

Message Type LOG

Severity WARNING

Probable Cause Indicates that user inserted the system with Gen5 PS and needs to be replaced.

Recommended Run the **psshow** command to verify that supported power supply unit is being used.

Action

HIL-1654

Message <Message string>

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Can be caused if an integrated FRU (PS and FAN) is absent, all FRUs are faulty, airflow mismatch

between FRUs or if global airflow direction in SEEPROM is not supported.

Recommended To be transmitted to engineering for problem analysis.

Action

HIL-1655

Message <Message string>

Message Type LOG

Severity WARNING

Probable Cause Can be caused by raising temperature in the system.

Recommended

Run the fanShow command to verify all the fans are working properly.

Action

Make sure that the area is well-ventilated and that the room temperature is within the operational range of your switch. Refer to the *Hardware Reference Manual* for your switch for the operational

temperature range.

HIL-1656

Message FRU <FRU number> tach sensor <sensor number>, speed (<measured speed> RPM) below

threshold.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified fan speed (in RPM) has fallen below the minimum threshold. This problem

can quickly cause the switch to overheat. This message is specific to non-bladed switches.

Recommended Replace the fan field-replaceable unit (FRU), where applicable. For non-FRU components, please

contact your equipment vendor's support.

HIL-1657

Message Thermal Policy changed. Long Reach Optics Thermal Policy in effect.

Message Type LOG

Action

Severity INFO

Probable Cause LWL or ELWL sfp connected to switch.

Recommended Follow the new thermal policy.

Action

HIL-1658

Message Power supply unit <UnitNumber>, 250W PS is in use. Please replace it with 350W PS for

high availability operation.

Message Type LOG

Severity WARNING

Probable Cause Indicates that user inserted the system with 250W PS and needs to be replaced.

Recommended Run the **psshow** command to verify that supported power supply unit is being used.

Action

HIL-1659

Message FRU <FRU number> tach sensor <sensor number>, speed (<measured speed> RPM) above

threshold.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates that the specified fan speed (in RPM) is above maximum threshold.

Recommended Replace the fan field-replaceable unit (FRU), where applicable. For non-FRU components, please Action

contact your equipment vendor's support.

HIL-1660

Message Temperature of PSU <psu number> (<measured temperature> C) exceeded threshold value.

Message Type FFDC | LOG

Action

Severity CRITICAL

Probable Cause Indicates that the temperature of this PSU has risen above the critical threshold.

Recommended Run the fanShow command to verify all the fans are working properly.

> Make sure that the area is well-ventilated and that the room temperature is within operational range of your switch. Refer to the hardware reference manual for your switch for the operational temperature range.

If the message persists, replace the PSU.

6.51 HLO Messages

HLO-1001

Incompatible Inactivity timeout <dead timeout> from port <port number>, correct value Message

<value>.

Message Type LOG | FFDC

> Severity **ERROR**

Probable Cause Indicates that the hello (HLO) message was incompatible with the value specified in the fabric shortest

path first (FSPF) protocol. The Brocade switch will not accept FSPF frames from the remote switch.

In Fabric OS, the HLO dead timeout value is not configurable, so this error can only occur when the

Brocade switch is connected to a switch from another manufacturer.

Recommended The dead timeout value of the remote switch must be compatible with the value specified in the FSPF

protocol. Refer to the documentation for the other manufacturer's switch to change this value.

HLO-1002

Action

Message Incompatible Hello timeout <HLO timeout> from port <port number>, correct value

<correct value>.

Message Type LOG | FFDC

Severity ERROR

Probable Cause Indicates that the hello (HLO) message was incompatible with the value specified in the fabric shortest

path first (FSPF) protocol. The Brocade switch will not accept FSPF frames from the remote switch.

In Fabric OS, the HLO timeout value is not configurable, so this error can only occur when the Brocade

switch is connected to a switch from another manufacturer.

Recommended Action The HLO timeout value of the remote switch must be compatible with the value specified in the FSPF protocol. Refer to the documentation for the other manufacturer's switch to change this value.

HLO-1003

Message Invalid Hello received from port <port number>, Domain = <domain ID>, Remote Port =

<remote port ID>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the hello (HLO) message received was invalid and the frame was dropped. The Brocade

switch will not accept fabric shortest path first (FSPF) frames from the remote switch.

The switch has received an invalid HLO because either the domain or port number in the HLO message has an invalid value. This error can only occur when the Brocade switch is connected to a

switch from another manufacturer.

Recommended The HLO message of the remote switch must be compatible with the value specified in the FSPF

Action protocol. Refer to the documentation for the other manufacturer's switch to change this value.

6.52 HMON Messages

HMON-1001

Message <Failure description>.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that there was a problem reading an essential file containing configuration information from

the nonvolatile storage device. This could be the result of a missing file or a corrupt file system.

Recommended

Action Execute the **firmwareDownload** command to reinstall the firmware to your switch.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

6.53 HSL Messages

HSL-1000

Message HSL initialization failed.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates a hardware subsystem layer (HSL) initialization failure. This error is caused by other system

errors.

Recommended Execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the

supportSave command and contact your switch service provider.

HSL-1001

Message Failed to acquire system MAC address pool.

Message Type LOG

Action

Severity CRITICAL

Probable Cause Indicates failure to acquire the system address. This error is caused by other system errors.

Recommended Execute the **errShow** command to view the error log for other system errors, and take appropriate

Action corrective actions.

HSL-1002

Message SFP for interface <InterfaceName> is inserted.

Message Type LOG

Severity INFO

Probable Cause Indicates that a small form-factor pluggable (SFP) transceiver has been inserted in the specified

interface.

HSL-1003

Message SFP for interface <InterfaceName> is removed.

Message Type LOG

Severity INFO

Probable Cause Indicates that a small form-factor pluggable (SFP) transceiver has been removed from the specified

interface.

HSL-1004

Message Incompatible SFP for interface <InterfaceName> is detected.

Message Type LOG

Severity ERROR

Probable Cause Indicates that an incompatible small form-factor pluggable (SFP) transceiver for the interface has been

inserted.

Recommended Disable the interface using the **shutdown** command and insert an SFP transceiver that is supported

Action on the interface. After the SFP transceiver is inserted, re-enable the interface using the **no shutdown**

command.

HSL-1005

Message Failed to initialize with FSS.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates a failure to initialize the Fabric OS State Synchronization (FSS) service. This error is caused

by other system errors.

Recommended Execute the **errShow** command to view the error log for other system errors, and take appropriate

Action corrective actions.

HSL-1006

Message Failed to get kernel page size <PageSize> bytes for mmap.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that there is not enough contiguous kernel memory.

Recommended Execute the **errShow** command to view the error log for other system errors, and take appropriate

Action corrective actions.

HSL-1007

Message Failed to read SFP for interface <InterfaceName>.

Message Type LOG

Severity ERROR

Probable Cause Indicates failure to read the small form-factor pluggable (SFP) transceiver on the specified interface.

Recommended Disable the interface using the **shutdown** command and re-insert the SFP transceiver. After the SFP

Action transceiver is inserted, re-enable the interface using the **no shutdown** command. If the problem

persists, contact your switch service provider.

6.54 HTTP Messages

HTTP-1001

Message Switch PID format has changed to <current PID format>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the port ID (PID) format was changed.

Recommended No action is required. For more information on PID format, refer to the Fabric OS Administrator's

Action Guide.

HTTP-1002

Message Zoning transaction initiated by User: <User Name>, Role: <User Role> completed

successfully.

Message Type AUDIT | LOG

Class ZONE

Severity INFO

Action

Probable Cause Indicates that the zoning database has been changed.

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not

planned, take appropriate action as defined by your enterprise security policy.

HTTP-1003

Message Zoning transaction initiated by User: <User Name>, Role: <User Role> could not be

completed successfully - <Reason Message>.

Message Type AUDIT | LOG

Class ZONE

Severity INFO

Probable Cause Indicates an error in completing the zoning transaction because of the specified reason.

Recommended Check the ZONE events in the error message log by using the errShow command, and take

Action appropriate corrective actions.

HTTP-3001

Message REST session limit is changed to <Value>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the maximum supported REST session limit has been changed.

HTTP-3002

Message REST session is terminated for <User> user

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause
Indicates that the specified REST session has successfully terminated and logged out.

HTTP-3003

Message REST throttling configuration attribute, <Changed attribute>, has changed to <Value>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified REST throttling configurations have been changed. The modified

parameter and the new values are displayed in the message.

HTTP-3004

Message REST interface is <state>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified REST interface has successfully enabled or disabled

HTTP-3005

Message REST auth key is <action>

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause
Indicates that auth key has successfully created or deleted

HTTP-3006

Message REST HTTP interface is <state>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause
Indicates that the REST HTTP interface has successfully enabled or disabled

6.55 IPAD Messages

IPAD-1000

Message <Type of managed entity>/<Instance number of managed entity> <Type of network

interface>/<Instance number of network interface> <Protocol address family> <Source
of address change> <Value of address and prefix> DHCP <DHCP enabled or not>.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the local IP address has been changed manually or it was reconfigured automatically by

the Dynamic Host Configuration Protocol (DHCP) server.

IPAD-1001

Message <Type of managed entity>/<Instance number of managed entity> <Protocol address

family> <Source of address change> <Value of address> DHCP <DHCP enabled or not>.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the gateway IP address has been changed manually or it was reconfigured automatically

by the Dynamic Host Configuration Protocol (DHCP) server.

IPAD-1002

Message Switch name has been successfully changed to <Switch name>.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the switch name has been changed.

IPAD-1003

Message DNS parameters saved successfully.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the Domain Name System (DNS) parameters are saved successfully.

IPAD-1004

Message DNS parameters removed successfully.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the Domain Name System (DNS) parameters are removed successfully.

IPAD-1005

Message Chassis name has been changed to <Chassis name>.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the chassis name has been changed.

IPAD-1006

Message TCP timeout level has been changed to <Tcp timeout level>.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates the TCP timeout level has been changed.

6.56 IPS Messages

IPS-1001

Message <message> FTR AFA/FTR AE License Not Installed (<error>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that either Advanced FICON Acceleration (FTR_AFA) or Advanced Extension (FTR_AE)

license is not installed or assigned to the slot.

Recommended Run the licenseShow command to verify the slot-based licenses are installed on the switch. Contact

your switch supplier for an appropriate slot-based license. Run the licenseAdd and licenseSlotCfg

commands to add the license to your switch and activate it.

IPS-1002

Message Failed to initialize <module> rc = <error>.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the initialization of a module within the IPS daemon failed.

Recommended

Download a new firmware version using the firmwareDownload command.

IPS-1003

Message <function name>: Failed to allocate memory while performing <message>.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that memory resources are low. This may be a transient problem.

Recommended Check the memory usage on the switch using the **memShow** command.

Action

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

IPS-1004

Message Port Config Mode Mismatch slot (<slot>) port(ge<port>): current mode is (<current

mode>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that configured port mode is different from the intended use.

Recommended Change the port configuration (by deleting configured FCIP tunnels or iSCSI sessions) to return the

port mode to neutral before attempting to configure the port for a different mode or use.

IPS-1005

Message Tunnel Authorization Failure for slot (<slot>) port(ge<port>) tunnel ID(<tunnel

number>) reason (<reason>).

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that tunnel setup failed because of an authorization failure from the remote side. A reason for

such a failure could be a WWN mismatch.

Recommended Change the tunnel configuration on one side of the tunnel to authorize the remote side to set up the

Action tunnel.

IPS-1006

Message Tunnel Configuration Mismatch for slot (<slot>) port(<port>) tunnel ID(<tunnel

number>) reason (<reason>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that tunnel setup failed because of a configuration mismatch between the two ends. The

reason field indicates the cause for configuration mismatch.

Recommended Change the tunnel configuration on one side of the tunnel to match that of the other side to set up the

Action tunnel.

IPS-1007

Message FX8-24 blade (<slot>) is not at the correct revision. Unable to use IPSec on FCIP

Tunnel (<port>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the tunnel configuration failed because the FX8-24 blade is not at the correct revision to

support IPSec enabled tunnels on VEs 22-31.

Recommended Contact your switch vendor to acquire the correct hardware revision blade.

Action

IPS-1008

Message Inband Management Interface <Port> created <IP-Address>.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the specified Inband Management interface was created.

IPS-1009

Message Inband Management Interface <Port> deleted <IP-Address>.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the specified Inband Management interface was deleted.

IPS-1010

Message Inband Management Interface <Port> <Admin-State>.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the specified Inband Management interface was enabled or disabled.

IPS-2000

Message IPSec authentication error threshold exceeded for slot <Slot>.

Message Type LOG

Severity ERROR

Probable Cause Indicates the threshold has been exceeded for IPSec authentication errors.

Recommended Blade may need to be reset to recover.

Action

IPS-2001

Message IPSec authentication error threshold exceeded for slot <Slot>. Resetting blade.

Message Type LOG

Severity ERROR

Probable Cause Indicates the threshold has been exceeded for IPSec authentication errors and blade will be

automatically reset to recover.

6.57 ISNS Messages

ISNS-1001

Message Configuration peering with external iSNS server <New config iSNS server IP address>

slot/port <New config Slot number>/ge<New config port number> (current <Current iSNS

server IP address> <Current slot number>/ge<Current port number>).

Message Type LOG

Severity INFO

Probable Cause Indicates that a user has issued the **isnscCfg** command.

ISNS-1002

Message Start peering with external iSNS server <iSNS server IP address> slot/port <Slot

number>/ge<Port number>.

Message Type LOG

Severity INFO

Probable Cause Indicates that peering has started with the specified external Internet Storage Name Service (iSNS)

server.

ISNS-1003

Message Peering with external iSNS server is disabled.

Message Type LOG

Severity INFO

Probable Cause Indicates that the IP address of the Internet Storage Name Service (iSNS) server is zero. Therefore,

peering is disabled.

Recommended If you wish to enable the iSNS server, use the **isnscCfg** command to show or set the server IP

Action address; otherwise, no action is required.

ISNS-1004

Message Timeout refreshing iSNS database with iSNS server <iSNS server IP address> slot/port

<Slot number>/ge<Port number> Reg-Period <Registration-Period in seconds>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Internet Storage Name Service (iSNS) client fails to receive a successful response

for a DevAttrQry within the specified registration period.

Recommended Verify the connection of the iSNS server to the slot and port.

Action

ISNS-1005

Message User request re-register with external iSNS server <iSNS server IP address> slot/port

<Slot number>/ge<Port number>.

Message Type LOG

Severity INFO

Probable Cause Indicates that a user has requested to re-register with the specified external Internet Storage Name

Service (iSNS) server.

ISNS-1006

Message Start re-register with external iSNS server <iSNS server IP address> slot/port <Slot

number>/ge<Port number>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the re-register with the specified external Internet Storage Name Service (iSNS) server

has started.

ISNS-1008

Message Peering with external iSNS server <iSNS server IP address> not started because

configuration unchanged.

Message Type LOG

Severity INFO

Probable Cause Indicates that peering with the external Internet Storage Name Service (iSNS) server was already

started with the same configuration.

Recommended No action is required. You may change the configuration and retry the peering with the external iSNS

Action server.

ISNS-1009

Message Peering with external iSNS server <iSNS server IP address> not started because no

No action is required. Peering will resume automatically when virtual targets are detected.

virtual targets found.

Message Type LOG

Severity INFO

Probable Cause Indicates that no virtual targets were found, and therefore peering was not started.

Action

Recommended

, (6.16)

ISNS-1010

Message Slot/port <Slot>/ge<Port> is out of range.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the slot or port is out of range.

Recommended Retry with a valid slot and port. Refer to the appropriate hardware reference manual for valid slot and

Action port ranges.

ISNS-1011

Message iSNS Client Service is <iSNS client State (enabled/disabled)>.

Message Type LOG

Severity INFO

Probable Cause Indicates the current state of the Internet Storage Name Service (iSNS) client is enabled or disabled.

Recommended No action is required. Use the **fosconfig --show** command to display the current state of the iSNS

Action client.

ISNS-1013

Message iSNS server connection failure.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Internet Storage Name Service (iSNS) client failed to establish a connection with the

iSNS server.

Recommended Verify the connection of the iSNS server to the slot and port.

Action
Use the **isnscCfg** command to display or correct the server IP address.

ISNS-1014

Message Start peering with external iSNS server <iSNS server IP address> on management port.

Message Type LOG

Severity INFO

Probable Cause Indicates that peering has started with the specified external Internet Storage Name Service (iSNS) on

the management port.

6.58 KAC Messages

KAC-1002

Message KAC(<Key Vault Type>) communication Error: Error connecting to <Backup or Primary>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the Key Archive Client (KAC) is unable to communicate with the primary or backup key

vault.

Recommended Determine whether the configured key vault is operational; if not, change the switch key vault settings

or resolve the operational problem at the key vault.

KAC-1004

Message KAC <Operation Description> to Key Vault failed.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the Key Archive Client (KAC) is unable to do the specified operation to the primary or

backup key vault.

Recommended Determine whether the configured key vault is operational; if not, change the switch key vault settings

or resolve the operational problem at the key vault.

KAC-1006

Message Switch to Key Vault trustee link was not established.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the trustee link was not established between the switch and the key vault.

Recommended Establish a trustee link between the switch and the key vault.

Action

KAC-1007

Message KAC key archival operation to Key Vault failed, LUN=<LUN Number>, keyID=<Key ID

Value>, errno=<Error Number>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Key Archive Client (KAC) is unable to archive the key to primary or backup key vault.

Recommended Determine whether the configured key vault is operational; if not, change the switch key vault settings Action

or resolve the operational problem at the key vault.

KAC-1008

Message Putting of TEP failed. Check if there is already an unapproved TEP, then delete it.

Error code=<Error code from LKM>, string=<Error string>.

LOG Message Type

> **ERROR** Severity

Probable Cause Indicates that there was already a pending unapproved Trusted link Establishment Package (TEP) at

the Lifetime Key Manager (LKM).

Recommended Log in to LKM and delete the unapproved TEP.

Action

KAC-1009

Message Primary(<Primary Keyvault IP Address>) and Backup(<Backup Keyvault IP Address>) Key

Vaults are not in sync. Detected key mismatch with KeyID = <KeyID>.

LOG Message Type

> Severity **ERROR**

Probable Cause Indicates that the primary and backup key vault contents are not in sync.

Recommended Synchronize the contents of the primary and backup key vaults using instructions provided by the key

Action vault provider.

KAC-1010

Message Archival for KeyID <KeyID> failed to <Keyvault IP Address>. Error code=<Error code>,

string=<Error string>.

Message Type LOG

> Severity WARNING

Probable Cause Indicates that archiving of Data Encryption Key (DEK) to the key vault failed.

KAC-1011

Message Archival of Dummy DEK to the KV <Keyvault IP Address> failed. Dummy DEK: <Dummy Key

Id>, KeyCount: <Key Count>. Error code=<Error code>, string=<Error string>.

LOG Message Type

Severity WARNING

Probable Cause Indicates that archiving of dummy Data Encryption Key (DEK) to the key vault failed.

KAC-1012

Message Retrieval of Dummy DEK from the KV <Keyvault IP Address> failed. Dummy DEK: <Dummy

Key Id>, KeyCount: <Key Count>. Error code=<Error code>, string=<Error string>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that retrieving of dummy Data Encryption Key (DEK) from the key vault failed.

KAC-1013

Message Archival of the Actual DEK to the KV <Keyvault IP Address> failed. Actual Key: <Actual

Key Id>. Error code=<Error code>, string=<Error string>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that archiving of actual Data Encryption Key (DEK) to the key vault failed.

KAC-1014

Message Retrieval of Actual DEK from the KV <Keyvault IP Address> failed. Actual Key: <Actual

Key Id>. Error code=<Error code>, string=<Error string>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that retrieving of actual Data Encryption Key (DEK) from the key vault failed.

KAC-1015

Message KAC(<Key Vault Type>) communication Error: Error connecting to <Key Vault IP>. Error

code=<Error code>, string=<Error string>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the Key Archive Client (KAC) is unable to communicate with the primary or backup key

vault.

Recommended Change the switch key vault settings and make sure the configured key vault is operational.

Action

KAC-1016

Message Error: Key ID mismatched in request/response. Requested key ID <Key ID in response>

and key in response <Requested Key Id>. Error code=<Error code>, string=<Error

string>.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates a mismatch between the requested key ID and the key in the response from the key vault.

Recommended Determine whether the configured key vault is operational; if not, change the switch key vault settings Action

or resolve the operational problem at the key vault.

KAC-1017

Message Error: KV parameter [<param name>] configured on BES is not supported by the Key

Vault. Please fix the configuration of the parameter to ensure key operations function

as expected.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates a mismatch between the configured key vault parameters on the Brocade Encryption Switch

(BES) and the functionality supported by the key vault.

De-register the key vaults, set the correct value for key vault parameter, and re-register the key vaults. Recommended

Action

KAC-1018

Message KAC(<Key Vault Type>) communication to <Backup or Primary> restored.

Message Type LOG

> INFO Severity

Probable Cause Indicates that Key Archival Client communication with the *primary* or *backup* key vault is restored.

Recommended None

Action

6.59 KSWD Messages

KSWD-1001

Message <Software component>:<Software component Process ID> failed to refresh (<Current

time>:<Refresh time>).

Message Type FFDC | LOG

Severity WARNING

Probable Cause Indicates that one of the critical daemons is found to be unresponsive. An abort signal is sent.

Recommended Copy the warning message along with any core file information and contact your switch service

Action provider.

KSWD-1002

Message Detected termination of process <Software component>:<Software component Process ID>.

Message Type FFDC | LOG

Severity WARNING

Probable Cause Indicates that a process on the switch has ended unexpectedly.

Recommended Copy the warning message along with any core file information and contact your switch service

Action provider.

6.60 KTRC Messages

KTRC-1001

Message Dump memory size exceeds dump file size.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the dump memory size has exceeded the dump file size.

Recommended Execute the **supportSave** command and reload the switch. If the problem persists, contact your

Action switch service provider.

KTRC-1002

Message Concurrent trace dumping.

Message Type LOG

Severity INFO

Probable Cause Indicates that the initial background dump has not completed.

KTRC-1003

Message Cannot open ATA dump device.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the advanced technology attachment (ATA) dump driver is not initialized properly.

Recommended Execute the **supportSave** command and reload the switch. If the problem persists, contact your

Action switch service provider.

KTRC-1004

Message Cannot write to ATA dump device.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the write boundary in the advanced technology attachment (ATA) dump device has been

exceeded.

Recommended Execute the **supportSave** command and reload the switch. If the problem persists, contact your

Action switch service provider.

KTRC-1005

Message Trace initialization failed. <Reason initialization failed>. <Internal error code>.

Message Type LOG

Severity ERROR

Probable Cause
Indicates that trace was unable to initialize.

Recommended Execute the **supportSave** command and reload the switch. If the problem persists, contact your

Action switch service provider.

6.61 L2SS Messages

L2SS-1001

Message Linux socket error - error reason: <reason>, socket name: <socketname>, error name:

<errorname>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that an error has occurred in the Linux socket.

Recommended Reboot or power cycle the switch.

Action

L2SS-1002

Message Initialization error: <reason>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the Layer 2 system (L2SYS) encountered an error during initialization.

Recommended Reboot or power cycle the switch.

Action

L2SS-1003

Message Queue Error: Message queue create failed.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the Layer 2 system (L2SYS) encountered system service manager (SSM) message

queue errors.

Recommended Reboot or power cycle the switch.

Action

L2SS-1004

Message FDB error: Error in creating AVL tree.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the Layer 2 system (L2SYS) has encountered an error while initializing the AVL tree.

Recommended Reboot or power cycle the switch.

Action

L2SS-1005

Message MAC-address-table hash failed even after two attempts for slot <slot> chip <chip>.

Message Type LOG

Severity **ERROR**

Probable Cause Indicates that the media access control (MAC) address table hash failed even after two hash changes

on the specified chip.

Recommended

Reboot or power cycle the switch.

Action

L2SS-1006

Message MAC-address-table table on slot <Slot_id> chip <Chip_id> is 95 percent full.

Message Type LOG

> **INFO** Severity

Probable Cause Indicates that the media access control (MAC) address table on the chip is 95 percent full.

Recommended Clear some of the entries using the no mac-address-table static command or wait until the old

Action entries age out.

L2SS-1007

Message MAC-address-table on slot <Slot id> chip <Chip id> is less than 90 percent full.

Message Type LOG

> Severity **INFO**

Probable Cause Indicates that the media access control (MAC) address table on the specified chip is less than 90

percent full.

Recommended

Action

No action is required. The Layer 2 system (L2SYS) starts learning the entries.

L2SS-1008

Message Hardware GID limit reached on chip <Chip id>, GID limit at <Max gid>.

Message Type LOG

> Severity **INFO**

Probable Cause Indicates that all dynamic group IDs (GIDs) are allocated.

Recommended Clear some of the ACL entries using the clear counters access-list mac command.

Action

6.62 L3SS Messages

FOS-90x-Message-RM103 Broadcom

L3SS-1004

Message <Function Name>, <Line No>: HW/Driver Error (possibly the CAM is full): <HW Error

Message>, rc=<Error Code>.

Message Type LOG

Severity ERROR

Probable Cause Indicates an error in the hardware or the driver of the Layer 3 subsystem (L3SS). L3SS may have

passed invalid parameters or the hardware Content Addressable Memory (CAM) may be full.

Recommended

Action

Retry or clear the CAM.

6.63 LACP Messages

LACP-1001

Message <module> Error opening socket (<error>).

Message Type LOG

Severity ERROR

Probable Cause Indicates that initialization of the specified module within the Link Aggregation Control Protocol (LACP)

daemon has failed.

Recommended

Action

Download a new firmware using the firmwareDownload command.

LACP-1002

Message <msg>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that some of the fields received in the Link Aggregation Control Protocol Data Unit

(LACPDU) are invalid.

LACP-1003

Message <msg>.

Message Type LOG | FFDC

Severity WARNING

Probable Cause Indicate port state expired.

6.64 LFM Messages

LFM-1001

Message The Logical Fabric Manager service is disabled.

Message Type LOG

Severity INFO

Probable Cause Indicates that the Logical Fabric Manager service is disabled. Note that the Logical Fabric Manager

service is enabled by the factory setting and it is not user-configurable.

LFM-1002

Message The Logical Fabric Manager service is enabled.

Message Type LOG

Severity INFO

Probable Cause Indicates that the Logical Fabric Manager service is enabled. Note that the Logical Fabric Manager

service is enabled by the factory setting and it is not user-configurable.

LFM-1003

Message The Logical Fabric Manager configuration is set to default.

Message Type LOG

Severity INFO

Probable Cause Indicates that the Logical Fabric Manager configuration is set to default. This will remove all prior

Logical Fabric Manager configurations. This operation is not supported currently.

LFM-1004

Message HA is out of sync for opcode <HA OPCODE>, error value <error value>.

Message Type LOG | FFDC

Severity CRITICAL

Probable Cause Indicates loss of high availability (HA) sync with remote control processor (CP).

Recommended Collect the supportsave information using the supportsave command and contact the Brocade

Action technical support.

LFM-1005

Message Logical port <portnum> disabled with reason <reason code>(<reason string>)

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified logical port is disabled for an internal logging purpose. This could be due to

port segmentation.

Recommended Check the reason for port disable using the **switchShow** command, and take appropriate corrective

Action action.

LFM-1006

Message The switch with domain <domain> with firmware version <version> has joined the FID

<FID> fabric and may not be compatible with XISL use.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the firmware version on the specified switch is not compatible with XISL.

Recommended Check the release notes to verify if this firmware is compatible with XISL. If it is not, remove the switch

Action from the fabric.

LFM-1007

Message Logical ISLs are enabled for FID <FID>.

Message Type AUDIT | LOG

Class LS

Severity INFO

Probable Cause Indicates that Logical ISLs are enabled for specified logical fabric.

6.65 LIC Messages

LIC-1000

Message Blade slot <slot number> added to <license feature name> slot-based license

configuration.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates a slot has been configured to allow a specific license feature.

LIC-1001

Message Blade slot <slot number> removed from cense feature name> slot-based license

configuration.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates a slot has been removed from a specific license feature configuration.

LIC-1002

Message License log file is corrupted. Exceeded 10 warning limit within the monitoring period.

All login sessions will be blocked.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the CLP log file was deleted or changed by the user.

Recommended Check date and time on /var/log/clp_license.log.

Action

LIC-1003

Message license install failed 25 times within the monitoring period.

Message Type LOG

Severity WARNING

Probable Cause Indicates that there were 25 license install failures in 24 hours.

Recommended Do not add any more invalid license keys.

Action

LIC-1004

Message license install failed 40 times within the monitoring period. All login sessions will

be blocked after 10 more failures

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that there were 40 license install failures in 24 hours.

Recommended >Do not add any more invalid license keys.

Action

LIC-1005

Message license install failed 50 times within the monitoring period. All login sessions will

be blocked

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that there were 50 license install failures in 24 hours.

Recommended >User will need to contact Broadcom BSN TAC to recover.

Action

LIC-1009

Message License system integrity check failed, license operations are blocked.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that license public key hash check has failed.

Recommended Contact the customer support and get the license seeprom programmed.

Action

LIC-1010

Message <Key> license has expired.

Message Type LOG

Severity WARNING

Probable Cause Indicates the license period has expired.

Recommended Get a new license for this feature.

Action

LIC-2000

Message Accept Brocade FOS End User License Agreement.

Message Type AUDIT

Class FIRMWARE

Severity INFO

Probable Cause Indicates user accept Brocade FOS End User License Agreement at the first login into a Factory

shipped system.

Recommended >No action is required.

Action

LIC-2001

Message Fail to accept Brocade FOS End User License Agreement.

Message Type AUDIT

Class FIRMWARE

Severity INFO

Probable Cause Indicates user fail to accept Brocade FOS End User License Agreement at the first login into a Factory

shipped system.

Recommended

Action

Relogin and accept Brocade FOS End User License Agreement.

LIC-2002

Message <ras msg>

Message Type AUDIT

Class CFG

Severity ERROR

Probable Cause

LIC-2003

Message <ras_msg>

Message Type AUDIT

Class CFG

INFO Severity

Probable Cause

6.66 LOG Messages

LOG-1000

Message Previous message repeated <repeat count> time(s).

Message Type LOG

> **INFO** Severity

Probable Cause Indicates that the previous message was repeated the specified number of times.

LOG-1001

Message A log message was dropped.

Message Type LOG

> Severity WARNING

Probable Cause Indicates that a log message was dropped. A trace dump file has been created.

Recommended Execute the reboot command for non-bladed switches or the haFailover command on bladed Action

switches.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the supportSave command and contact your switch service provider.

LOG-1002

Message A log message was dropped.

LOG Message Type

> Severity WARNING

Probable Cause Indicates that a message was not recorded by the error logging system. A trace dump file has been

created. The message may still be visible through Simple Network Management Protocol (SNMP) or

other management tools.

Recommended Execute the reboot command for non-bladed switches or the haFailover command on bladed Action

switches.

If the message persists, execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the supportSave command and contact your switch service provider.

FOS-90x-Message-RM103 Broadcom

LOG-1003

Message The log has been cleared.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the persistent error log has been cleared.

LOG-1004

Message Log message <Log message that has been blocked> flooding detected and blocked.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that a message has been flooding and was blocked.

Recommended If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

LOG-1005

Message Log message <Log message that has been disabled> has been disabled.

Message Type AUDIT | LOG

Class RAS

Severity INFO

Probable Cause Indicates that the specified message has been disabled from logging.

LOG-1006

Message Log message <Log message that has been enabled> has been enabled.

Message Type AUDIT | LOG

Class RAS

Severity INFO

Probable Cause Indicates that the specified message has been enabled for logging.

LOG-1007

Message Log Module <Log Module that has been disabled> has been disabled.

Message Type AUDIT | LOG

Class RAS

Severity INFO

Probable Cause Indicates that the specified module has been disabled from logging.

LOG-1008

Message Log Module <Log Module that has been enabled> has been enabled.

Message Type AUDIT | LOG

Class RAS

Severity INFO

Probable Cause Indicates that the specified module has been enabled for logging.

LOG-1009

Message Internal Log message < Log message that has been enabled to be sent to syslog server>

has been enabled for syslog logging.

Message Type AUDIT | LOG

Class RAS

Severity INFO

Probable Cause
Indicates that the specified internal message has been enabled for syslog logging.

LOG-1010

Message Internal Log message < Log message that has been disabled from being sent to syslog

server> has been disabled from syslog logging.

Message Type AUDIT | LOG

Class RAS

Severity INFO

Probable Cause Indicates that the specified internal message has been disabled from syslog logging.

LOG-1011

Message Log Message <Log Message Id> severity has been changed to <Severity>.

Message Type AUDIT | LOG

Class RAS

Severity INFO

Probable Cause Indicates that the severity level of the specified log message has been changed.

LOG-1012

Message Ras Quiet Time is enabled for <String>.

Message Type AUDIT | LOG

Class RAS

Severity INFO

Probable Cause Indicates that quiet time is enabled.

LOG-1013

Message Ras Quiet Time is disabled for <String>.

Message Type AUDIT | LOG

Class RAS

Severity INFO

Probable Cause Indicates that quiet time is disabled.

6.67 LSDB Messages

LSDB-1001

Message Link State ID <link state ID> out of range.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified link state ID is out of the acceptable range. The valid link state ID is the

same as the valid domain ID, with a range from 1 through 239. The switch will discard the record

because it is not supported.

LSDB-1002

Message Local Link State Record reached max incarnation.

LOG Message Type

> INFO Severity

Probable Cause Indicates that the local link state record (LSR) reached the maximum number of incarnations.

> An "incarnation" is a progressive number that identifies the most recent version of the link state record (LSR). The switch generates its local LSR when first enabled. The incarnation number will begin again

at 0x80000001 after reaching 0x7FFFFFF.

LSDB-1003

Message No database entry for local Link State Record, domain <local domain>.

Message Type FFDC | LOG

> Severity **CRITICAL**

Probable Cause Indicates that there is no local link state record (LSR) entry in the link state database (LSDB). The

switch should always generate its own local entry when starting up.

An "incarnation" is a progressive number that identifies the most recent version of the LSR. The switch generates its local LSR when first enabled. By disabling and enabling the switch, a new local LSR is

Run the switchDisable and switchEnable commands. A new local LSR is generated during the

generated.

Recommended

switch enable.

Action

LSDB-1004

No Link State Record for domain <local domain>. Message

Message Type LOG

> **WARNING** Severity

Probable Cause Indicates that there is no link state record (LSR) for the specified local domain.

Recommended No action is required. The other switch will pass the LSR after the fabric is stable.

Action

LSDB-1005

Message HA out of sync due to FSPF DB size larger than standby CP supports.

Message Type LOG

> Severity WARNING

FOS-90x-Message-RM103 Broadcom

Probable Cause Indicates that the maximum link state database (LSDB) size supported by the standby control

processor (CP) is less than that of the active CP.

Recommended Action Upgrade the standby firmware to active CP firmware version.

6.68 MAPS Messages

MAPS-1001 to MAPS-1004

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-1001 : CRITICAL', 'MAPS-1002 : ERROR', 'MAPS-1003 : WARNING', 'MAPS-1004 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-1005

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, Rule <Rule name>

triggered <count> times in <QT> and last trigger time <execution time>, Dashboard

Category=<Dashboard Category>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-1010

Message Port(s) fenced due to RuleName=<Rule name>, Condition=<condition>, Obj:<object> <ms,

values, units>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold, and therefore the specified ports are fenced.

Recommended Respond to this message as is appropriate to the particular policy of the end-user installation.

Action

MAPS-1011

Message Port(s) decommissioned due to RuleName=<Rule name>, Condition=<condition>,

Obj:<object> <ms, values, units>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold, and therefore the specified ports are fenced.

Recommended Respond to this message as is appropriate to the particular policy of the end-user installation.

Action

MAPS-1012

Message Port decommission action failed on port <object>, with reason string, <reason>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the port decommission has failed on an object.

Recommended Respond to this message as is appropriate to the particular policy of the end-user installation.

Action

MAPS-1013

Message Port(s) impaired due to RuleName=<Rule name>, Condition=<condition>, Obj:<object>

<ms, values, units>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold, and therefore the specified ports are impaired.

Recommended Respond to this message as is appropriate to the particular policy of the end-user installation.

Action

MAPS-1014

Message Port impair action failed on port <object>, with reason string, <reason>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the port impair action has failed on an object.

Recommended

Respond to this message as is appropriate to the particular policy of the end-user installation.

Action

MAPS-1015

Message MAPS recipient email address list got updated.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates MAPS email address configuration is set to given email address or list which would be used

as recipient email address for EMAIL notifications.

MAPS-1016

Message MAPS originator email address got updated.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates MAPS email address configuration is set to given email address which would be used as

originator email address for EMAIL notifications.

MAPS-1017

Message MAPS relayConfig got updated to relay_IP: <relay_IP>, domain: <domain>.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Relay IP and Domain Name configuration change.

MAPS-1018

Message MAPS decommission action config set to mode <decom config>.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Decommission mode configuration change.

MAPS-1020

Message Switch wide status has changed from <Previous state> to <Current state>.

Message Type LOG | AUDIT

Class MAPS

Severity WARNING

Probable Cause Indicates a change in the state of the switch. This log provides the previous state and the current state

of the switch.

Recommended Check the accompanying RASLog messages to determine the cause of the state change.

Action

MAPS-1021

Message RuleName=<Rule name>, Condition=<condition>, Obj:<object, units> <Old state> has

contributed to switch status <New state>.

Message Type LOG | AUDIT

Class MAPS

Severity WARNING

Probable Cause Indicates the specified rule has been violated and as a consequence has contributed to the mentioned

state of the switch.

MAPS-1022

Message Port <slotport> (Port index <portindex>) has been marked as Slow Drain Device.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the quarantine action for the port due to Severe Latency / Frame Loss has been initiated.

Traffic destined to this port will be moved to low QoS Virtual Channel at source.

MAPS-1023

Message Port <slotport> marked as Slow Drain Device is not enforced due to zoned port limit

exceeded.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the port flagged for Severe Latency / Frame Loss could not be quarantined due to the

zoned port count more than 32.

Recommended

Action

Requires manual intervention to set the slow drain condition right.

MAPS-1024

Message Configured limit exceeded. Port <slotport> could not be marked as Slow Drain Device.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the port flagged for Severe Latency / Frame Loss could not be guarantined, since the

configured limit was exceeded.

Recommended Requires manual intervention to set the slow drain condition right or the limit has to be reconfigured.

Action

MAPS-1025

Message Port <slotport> (Port index <portindex>) removed from the Slow Drain Device Quarantine

Group.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the port flagged for Severe Latency / Frame Loss earlier has been removed from the

quarantine group.

MAPS-1026

Message MAPS aborted port un-quarantine action for port(s) <slotport>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that there is configdownload or new policy enabled.

Recommended Manually un-quarantine ports using sddgquarantine --clear command.

Action

MAPS-1100

Message Rule <Rule name> is created.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates that the specified rule was created in the system.

Recommended Make sure the configuration change is expected.

Action

MAPS-1101

Message Rule <Rule name> is deleted.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates that the specified rule was deleted from the system.

Recommended Make sure the configuration change is expected.

Action

MAPS-1102

Message Rule <Rule name> is modified.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates that the specified rule was modified in the system.

Recommended Make sure the configuration change is expected.

Action

MAPS-1110

Message Policy <Policy name> is created.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates that the specified policy was created in the system.

Recommended Make sure the configuration change is expected.

Action

MAPS-1111

Message Policy <Policy name> is deleted.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause
Indicates that the specified policy was deleted from the system.

Recommended Make sure the configuration change is expected.

Action

MAPS-1112

Message Policy <Source Policy name> cloned to <Target Policy name>.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates that the specified policy was cloned in the system.

Recommended Make sure the configuration change is expected.

Action

MAPS-1113

Message Policy <Policy name> activated.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates that the specified policy was activated in the system.

Recommended Make sure the configuration change is expected.

Action

MAPS-1114

Message Rule <Rule name > added to Policy <Policy name >.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates that the specified rule was added to the specified policy.

Recommended Make sure the configuration change is expected.

Action

MAPS-1115

Message Rule <Rule name> deleted from Policy <Policy name>.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates that the specified rule was deleted from the specified policy.

Recommended Make sure the configuration change is expected.

Action

MAPS-1116

Message Policy <Policy name> updated.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates that the specified policy was updated.

Recommended Make sure the configuration change is expected.

Action

MAPS-1120

Message Group Group name> created.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates that the specified group was created.

Recommended Make sure the configuration change is expected.

Action

MAPS-1121

Message Group Group name> deleted.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates that the specified group was deleted.

Recommended Make sure the configuration change is expected.

Action

MAPS-1122

Message Group <Source group name> cloned to <Target group name>.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates that the specified group was cloned.

Recommended Make sure the configuration change is expected.

Action

MAPS-1123

Message Group Group name> modified.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates that the specified group was modified.

Recommended

Make sure the configuration change is expected.

Action

MAPS-1124

Message Flow <Flow name> imported.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates that the specified flow from Flow Vision is imported into MAPS.

Recommended Make sure the configuration change is expected.

Action

MAPS-1125

Message Flow <Flow name> deimported.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates that the specified flow was removed from MAPS.

Recommended Make sure the configuration change is expected.

Action

MAPS-1126

Message Imported flow <Flow name> is a stale flow or currently does not exist in flow vision.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified flow does not exist in Flow Vision.

Recommended Make sure the configuration change is expected.

Action

MAPS-1127

Message Imported flow <Flow name> is initialized as stale flow because it is <Flow

description>.

Message Type LOG

Severity INFO

Probable Cause Indicates that MAPS has imported the specified flow present in the configuration and initialized it as

stale flow due to the mentioned reason.

Recommended Make sure the configuration change is expected.

Action

MAPS-1130

Message Actions <List of actions configured> configured.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates that the specified list of actions are configured.

Recommended Make sure the configuration change is expected.

Action

MAPS-1131

Message Monitoring on members <List of members/objects > of type <Type of members/objects>

is paused.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates that monitoring on the specified list of members is paused.

Recommended Make sure the configuration change is expected.

Action

MAPS-1132

Message Monitoring on members <List of members/objects > of type <Type of members/objects>

is restarted.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates that monitoring on the specified list of members has resumed.

Recommended

Action

Make sure the configuration change is expected.

MAPS-1133

Message Rules were cloned from existing group <source group name> to new policy <new policy

name> successfully.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates that the rules were cloned from src group to new policy.

Recommended Make sure the configuration change is expected.

Action

MAPS-1134

Message The profile <profile name > changed threshold <old threshold value > to <new threshold

value>, description [<old description value>] to [<new description value>].

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates the profile threshold and(or) description is updated successfully.

MAPS-1135

Message Initiated flow profile activation.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

MAPS-1136

Message Flow Profiles are cleared.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates Flow Profiles are cleared successfully.

MAPS-1137

Message All the Profile configuration data is reset to default values and Flow Profile are

activated.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates all the profile configuration data is reset to default values.

MAPS-1138

Message Flow profiles activation is successful.

Message Type LOG

Severity INFO

Probable Cause Indicates profiles activation is successful.

MAPS-1139

Message Flow profiles activation is failed.

Message Type LOG

Severity INFO

Probable Cause Indicates profiles activation is successful.

MAPS-1140

Message FPI Profile < FPI Profile name > is created.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates that new FPI Profile is created with custom thresholds

Recommended Make sure the configuration change is expected.

Action

MAPS-1141

Message FPI Profile < FPI Profile name > is deleted.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates that new FPI Profile is deleted

Recommended Make sure the configuration change is expected.

Action

MAPS-1142

Message FPI Profile < Source FPI Profile name > is cloned to < Target FPI Profile name >.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause
Indicates that new FPI Profile is cloned from existing profile

Recommended Make sure the configuration change is expected.

Action

MAPS-1143

Message FPI Profile <FPI Profile name > is modified.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates that FPI Profile threshold(s) modified

Recommended

Action Make sure the configuration change is expected.

MAPS-1144

Message FPI Profile < FPI Profile name > is activated for F-Ports.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates that new FPI thresholds is activated

MAPS-1145

Message FPI Profile < FPI Profile name > is activated for E-Ports.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause
Indicates that new FPI thresholds is activated

MAPS-1146

Message Time changed on switch re-starting MAPS monitoring.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates switch time changed so MAPS monitoring has to be aligned to new switch time.

Recommended Previous MAPS dashboard data will indicate old switch time. Issue a mapsdb --clear if required.

Action

MAPS-1147

Message Certificate <certificate name> of type <certificate type> with date <certificate

date> beyond year 2038 is not monitored.

Message Type LOG | AUDIT

Class MAPS

Severity WARNING

Probable Cause Indicates that calendar date is beyond 2038 and it hits Y2K2038 problem where time data type

overflows.

Recommended

Input the calendar date within 2038.

Action

MAPS-1148

Message No Flow Vision license, changing active policy to < base policy > from < configured

policy >.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause License expired or deleted from switch

Recommended Install Flow Vision license for complete MAPS functionality.

Action

MAPS-1201

Message MAPS has started monitoring with <Policy name> policy.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates that MAPS has started monitoring the system

Recommended Make sure the configuration change is expected.

Action

MAPS-1202

Message MAPS policy <policy name> is not present. Re-enable MAPS with different policy.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates that MAPS policy is not available in the system. Re-enable MAPS with a different policy.

Recommended

Make sure the configuration change is expected.

Action

MAPS-1203

Message Dashboard <data type> data has been cleared.

Message Type LOG | AUDIT

Class MAPS

Severity WARNING

Probable Cause Indicates that the dashboard has been cleared.

MAPS-1204

Message MAPS aborted port toggle action on port <port>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that port toggle state has been changed.

MAPS-1205

Message Port toggle action is successful on port <port>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that port toggle action is successful.

MAPS-1206

Message A MAPS email notification sent from the switch could not be delivered to Email server.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates that an e-mail from the switch to the address has failed.

Recommended The problem needs to be debugged.

Action

MAPS-1207

Message There were < Number of email delivery errors > email delivery errors in the last hour.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Indicates that some e-mails from the switch encountered errors.

Recommended The problem needs to be debugged.

Action

MAPS-1208

Message Raslog mode is set to <mode>.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause raslog mode has been changed

Recommended

Action

MAPS-1209

Message Global Quiet Time enabled with <Global Quiet Time Value>.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Global Quiet Time enabled

Recommended

Action

MAPS-1210

Message Global Quiet Time disabled.

Message Type LOG | AUDIT

Class MAPS

Severity INFO

Probable Cause Global Quiet Time disabled

Recommended

Action

MAPS-1211

Message Monitoring is paused for members of group type <List of group types which has paused

members>.

Message Type LOG

Severity INFO

Probable Cause Paused Members

Recommended

Action

MAPS-1213

Message Monitoring is paused for all the supported group-types.

Message Type LOG

Severity INFO

Probable Cause Monitoring is paused for all the supported group-types

Recommended

Action

MAPS-1214

Message Monitoring restarted for all the supported group-types.

Message Type LOG

Severity INFO

Probable Cause Monitoring is restarted for all the supported group-types

Recommended

Action

MAPS-1215

Message Monitoring is paused for the specified group type (<Group Type>).

Message Type LOG

Severity INFO

Probable Cause Monitoring is paused for the specified group type

Recommended

Action

MAPS-1216

Message Monitoring restarted for the specified group type (<Group Type>).

Message Type LOG

Severity INFO

Recommended

Action

MAPS-1301

Message Application server <server> is bound with the logical partition.

Message Type LOG

Severity INFO

Probable Cause Indicates that application server bind operation is successful.

MAPS-1302

Message Application server <server> is unbound with the logical partition.

Message Type LOG

Severity INFO

Probable Cause Indicates that application server unbind operation is successful.

MAPS-2000

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2001

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2002

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2003

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2004 to MAPS-2007

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2004 : CRITICAL', 'MAPS-2005 : ERROR', 'MAPS-2006 : WARNING', 'MAPS-2007 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended

Frequent fluctuations in CRC errors generally indicate an aging fabric. Check your small form-factor

pluggable (SFPs), cables, and connections for faulty hardware. Verify that all optical hardware is clean.

MAPS-2008 to MAPS-2011

Action

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule</pre>

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

> ['MAPS-2008: CRITICAL', 'MAPS-2009: ERROR', 'MAPS-2010: WARNING', 'MAPS-2011: INFO'] Severity

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Invalid words usually indicate a hardware problem with a small form-factor pluggable (SFP) or cable.

Action Verify that both ends of the connections, the SFP, and the cable are not faulty.

MAPS-2012 to MAPS-2015

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule</pre>

name>, Dashboard Category=<Dashboard Category>.

LOG Message Type

> ['MAPS-2012 : CRITICAL', 'MAPS-2013 : ERROR', 'MAPS-2014 : WARNING', 'MAPS-2015 : INFO'] Severity

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Loss of synchronization errors frequently occur due to a faulty small form-factor pluggable (SFP) or Action

cable. Signal losses often create synchronization losses. Check both ends of your cable connection.

Verify that the cable and SFPs are not faulty. If you continue to experience synchronization loss errors,

troubleshoot your host bus adaptor (HBA) and contact your switch service provider.

MAPS-2016 to MAPS-2019

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule</pre>

name>, Dashboard Category=<Dashboard Category>.

LOG Message Type

> ['MAPS-2016: CRITICAL', 'MAPS-2017: ERROR', 'MAPS-2018: WARNING', 'MAPS-2019: INFO'] Severity

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Action

Link loss errors occur when a link experiences a loss of signal and fails. Both physical and hardware problems can cause link loss errors. Link loss errors frequently occur due to a loss of synchronization. Check for concurrent loss of synchronization errors and, if applicable, troubleshoot them. Check both ends of your cable connection. Verify that the cable and small form-factor pluggables (SFPs) are not faulty. Losses of synchronization commonly cause link failures. If you receive concurrent loss of synchronization errors, troubleshoot the loss of synchronization.

MAPS-2020 to MAPS-2023

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule</pre>

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

> ['MAPS-2020 : CRITICAL', 'MAPS-2021 : ERROR', 'MAPS-2022 : WARNING', 'MAPS-2023 : INFO'] Severity

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Loss of signal generally indicates a physical problem with a cable or SFP. Check both ends of your Recommended Action

cable connection. Verify that the cable and small form-factor pluggables (SFPs) are not faulty.

MAPS-2024 to MAPS-2027

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule</pre>

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

> Severity ['MAPS-2024 : CRITICAL', 'MAPS-2025 : ERROR', 'MAPS-2026 : WARNING', 'MAPS-2027 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Occasional protocol errors occur due to software glitches. Persistent protocol errors occur due to Action

hardware problems with a cable or SFP. Check both ends of your cable connection. Verify that the

cable and small form-factor pluggables (SFPs) are not faulty.

MAPS-2028 to MAPS-2031

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule</pre>

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

> Severity ['MAPS-2028 : CRITICAL', 'MAPS-2029 : ERROR', 'MAPS-2030 : WARNING', 'MAPS-2031 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

FOS-90x-Message-RM103 Broadcom

Recommended Action

The state of the port has changed for one of the following reasons: the port has gone offline, has come online, is testing, is faulty, has become an E Port, has become an F Port, has segmented, or has become a trunk port. If the change is not an expected event in the environment, take appropriate action on that port.

MAPS-2032 to MAPS-2035

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule</pre> name>, Dashboard Category=<Dashboard Category>.

LOG Message Type

> ['MAPS-2032 : CRITICAL', 'MAPS-2033 : ERROR', 'MAPS-2034 : WARNING', 'MAPS-2035 : INFO'] Severity

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended

Action

Link resets occur due to link timeout errors that indicate no frame activity. Both physical and hardware problems can cause link resets to increase. Check both the ends of your cable connection. Verify if the cable and small form-factor pluggables (SFPs) are faulty.

MAPS-2036 to MAPS-2039

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule</pre> name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

> ['MAPS-2036: CRITICAL', 'MAPS-2037: ERROR', 'MAPS-2038: WARNING', 'MAPS-2039: INFO'] Severity

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold

Recommended

Check the target device; it could be operating at sub-optimal speed to receive frames.

Action

MAPS-2040 to MAPS-2043

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule</pre>

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

> Severity ['MAPS-2040 : CRITICAL', 'MAPS-2041 : ERROR', 'MAPS-2042 : WARNING', 'MAPS-2043 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended High utilization may indicate a need for more bandwidth or redistributing traffic (load balancing).

Action

MAPS-2044 to MAPS-2047

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2044 : CRITICAL', 'MAPS-2045 : ERROR', 'MAPS-2046 : WARNING', 'MAPS-2047 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended High utilization may indicate a need for more bandwidth or redistributing traffic (load balancing).

Action

MAPS-2048 to MAPS-2051

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2048 : CRITICAL', 'MAPS-2049 : ERROR', 'MAPS-2050 : WARNING', 'MAPS-2051 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended High utilization may indicate a need for more bandwidth or redistributing traffic (load balancing).

Action

MAPS-2052 to MAPS-2055

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2052 : CRITICAL', 'MAPS-2053 : ERROR', 'MAPS-2054 : WARNING', 'MAPS-2055 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2056 to MAPS-2059

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2056 : CRITICAL', 'MAPS-2057 : ERROR', 'MAPS-2058 : WARNING', 'MAPS-2059 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2060 to MAPS-2063

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2060 : CRITICAL', 'MAPS-2061 : ERROR', 'MAPS-2062 : WARNING', 'MAPS-2063 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Check physical cabling and SFPs between the port and the next hop ethernet device.

Action

MAPS-2064 to MAPS-2067

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2064 : CRITICAL', 'MAPS-2065 : ERROR', 'MAPS-2066 : WARNING', 'MAPS-2067 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Check physical cabling and SFPs between the port and the next hop ethernet device.

Action

MAPS-2068 to MAPS-2071

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2068: CRITICAL', 'MAPS-2069: ERROR', 'MAPS-2070: WARNING', 'MAPS-2071: INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Isolate the devices causing the latency impact and disable the impacted switch ports.

Action

MAPS-2072 to MAPS-2075

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2072 : CRITICAL', 'MAPS-2073 : ERROR', 'MAPS-2074 : WARNING', 'MAPS-2075 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2076 to MAPS-2079

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2076 : CRITICAL', 'MAPS-2077 : ERROR', 'MAPS-2078 : WARNING', 'MAPS-2079 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2080 to MAPS-2083

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2080 : CRITICAL', 'MAPS-2081 : ERROR', 'MAPS-2082 : WARNING', 'MAPS-2083 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Reduce the number of NPIV logins to the port as per the configured limit to avoid unnecessary logins

Action from devices and usage of resources.

MAPS-2084 to MAPS-2087

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2084 : CRITICAL', 'MAPS-2085 : ERROR', 'MAPS-2086 : WARNING', 'MAPS-2087 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2088 to MAPS-2091

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2088 : CRITICAL', 'MAPS-2089 : ERROR', 'MAPS-2090 : WARNING', 'MAPS-2091 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended AMP reached the maximum IOs throughput capability. Consider using multiple AMPs and distribute

Action the flows from the fabric among them. Refer to admin guide for further assistance on the procedure.

MAPS-2092 to MAPS-2095

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2092 : CRITICAL', 'MAPS-2093 : ERROR', 'MAPS-2094 : WARNING', 'MAPS-2095 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2096 to MAPS-2099

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2096 : CRITICAL', 'MAPS-2097 : ERROR', 'MAPS-2098 : WARNING', 'MAPS-2099 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2100 to MAPS-2103

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2100: CRITICAL', 'MAPS-2101: ERROR', 'MAPS-2102: WARNING', 'MAPS-2103: INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2104 to MAPS-2107

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2104 : CRITICAL', 'MAPS-2105 : ERROR', 'MAPS-2106 : WARNING', 'MAPS-2107 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended AMP reached the maximum IOs throughput capability. Consider using multiple AMPs and distribute

Action the flows from the fabric among them. Refer to admin guide for further assistance on the procedure.

MAPS-2108 to MAPS-2111

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2108 : CRITICAL', 'MAPS-2109 : ERROR', 'MAPS-2110 : WARNING', 'MAPS-2111 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2112 to MAPS-2115

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2112 : CRITICAL', 'MAPS-2113 : ERROR', 'MAPS-2114 : WARNING', 'MAPS-2115 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2116 to MAPS-2119

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2116 : CRITICAL', 'MAPS-2117 : ERROR', 'MAPS-2118 : WARNING', 'MAPS-2119 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2120 to MAPS-2123

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2120 : CRITICAL', 'MAPS-2121 : ERROR', 'MAPS-2122 : WARNING', 'MAPS-2123 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Run Serdes tuning to fix bad OS errors. If that does not solve the issue then reseat the blade.

Action

MAPS-2124 to MAPS-2127

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2124 : CRITICAL', 'MAPS-2125 : ERROR', 'MAPS-2126 : WARNING', 'MAPS-2127 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Run Serdes tuning to fix long frame errors. If that does not solve the issue then reseat the blade.

Action

MAPS-2128 to MAPS-2131

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2128 : CRITICAL', 'MAPS-2129 : ERROR', 'MAPS-2130 : WARNING', 'MAPS-2131 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Run Serdes tuning to fix frame truncated errors. If that does not solve the issue then reseat the blade.

Action

MAPS-2132 to MAPS-2135

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2132 : CRITICAL', 'MAPS-2133 : ERROR', 'MAPS-2134 : WARNING', 'MAPS-2135 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2136 to MAPS-2139

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2136 : CRITICAL', 'MAPS-2137 : ERROR', 'MAPS-2138 : WARNING', 'MAPS-2139 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2140 to MAPS-2143

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2140 : CRITICAL', 'MAPS-2141 : ERROR', 'MAPS-2142 : WARNING', 'MAPS-2143 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended The state of the circuit has changed for either of the reason that if the circuit has gone offline or it has

come online. Check the connectivity between the circuit endpoints for reliability.

MAPS-2144 to MAPS-2147

Action

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2144 : CRITICAL', 'MAPS-2145 : ERROR', 'MAPS-2146 : WARNING', 'MAPS-2147 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended High utilization may indicate the need for more bandwidth or parallel connections.

Action

MAPS-2148 to MAPS-2151

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2148: CRITICAL', 'MAPS-2149: ERROR', 'MAPS-2150: WARNING', 'MAPS-2151: INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended High packet loss may indicate a congested or unreliable intermediate link. Add more parallel

Action connections or replace unreliable intermediate links.

MAPS-2152 to MAPS-2155

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2152 : CRITICAL', 'MAPS-2153 : ERROR', 'MAPS-2154 : WARNING', 'MAPS-2155 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Flash increases and decreases slightly with normal operation of the switch. Excessive permanent

increases can lead to future problems. Remove some unwanted files to create some flash space.

Execute the supportSave command to remove files from the kernel space.

MAPS-2156 to MAPS-2159

Action

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2156 : CRITICAL', 'MAPS-2157 : ERROR', 'MAPS-2158 : WARNING', 'MAPS-2159 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended This is an indication of excessive CPU intensive processes running on the switch. If the CPU usage

level remains high without reducing, contact your switch support vendor.

MAPS-2160 to MAPS-2163

Action

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2160 : CRITICAL', 'MAPS-2161 : ERROR', 'MAPS-2162 : WARNING', 'MAPS-2163 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended

Action

This could be an indication of a possible memory leak if it is continuously increasing or if there are excessive processes running on a switch. If the memory usage does not decrease, contact your switch

support vendor.

MAPS-2164 to MAPS-2167

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2164: CRITICAL', 'MAPS-2165: ERROR', 'MAPS-2166: WARNING', 'MAPS-2167: INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended

Action

Temperature changes can indicate a fan problem. Verify that the location temperature is within the operational range of the switch. Refer to the hardware reference manual for the environmental temperature range of your switch. If you receive a temperature-related message, check for an accompanying fan-related message and check fan performance. If all fans are functioning normally,

check the climate control in your lab.

MAPS-2168 to MAPS-2171

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2168 : CRITICAL', 'MAPS-2169 : ERROR', 'MAPS-2170 : WARNING', 'MAPS-2171 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended

Action

If the power supply is functioning correctly, no action is required. If the power supply is not functioning correctly, verify that it is seated correctly in the chassis. Run the psShow command to view the status

of the power supply. If the problem persists, replace the faulty power supply.

MAPS-2172 to MAPS-2175

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

['MAPS-2172: CRITICAL', 'MAPS-2173: ERROR', 'MAPS-2174: WARNING', 'MAPS-2175: INFO'] Severity

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Fan problems typically contribute to temperature problems. If the fan is functioning correctly, no action Action

is required. If the fan is not functioning correctly, verify that it is seated correctly in the chassis. Run the

fanShow command to view the status of the fan. If the problem persists, replace the faulty fan.

MAPS-2176 to MAPS-2179

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule</pre>

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

> Severity ['MAPS-2176 : CRITICAL', 'MAPS-2177 : ERROR', 'MAPS-2178 : WARNING', 'MAPS-2179 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2180 to MAPS-2183

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule</pre>

name>, Dashboard Category=<Dashboard Category>.

LOG Message Type

> ['MAPS-2180 : CRITICAL', 'MAPS-2181 : ERROR', 'MAPS-2182 : WARNING', 'MAPS-2183 : INFO'] Severity

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended SFP state changes occur when the SFP is inserted or removed. If the SFP insertion or removal was not

expected, take appropriate action based on the end-user policies for changes in the environment.

MAPS-2184 to MAPS-2187

Action

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule</pre>

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

> Severity ['MAPS-2184: CRITICAL', 'MAPS-2185: ERROR', 'MAPS-2186: WARNING', 'MAPS-2187: INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended If the state is INSERTED, this means that the blade is inserted but not powered on. If the state is ON, Action

this means that the blade has been powered on. If the state is OFF, this means that the blade has been

FOS-90x-Message-RM103 Broadcom

powered off. For states INSERTED, ON and OFF, verify that the event was planned. If the state is FAULTY, this means that the blade has deteriorated into FAULTY state. Take appropriate action to repair or replace the faulty blade.

MAPS-2188 to MAPS-2191

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2188 : CRITICAL', 'MAPS-2189 : ERROR', 'MAPS-2190 : WARNING', 'MAPS-2191 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Verify that the event was planned. If the state is FAULTY, this means that the WWN card has

deteriorated into FAULTY state. Take appropriate action to repair or replace the faulty WWN card.

MAPS-2192 to MAPS-2195

Action

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2192 : CRITICAL', 'MAPS-2193 : ERROR', 'MAPS-2194 : WARNING', 'MAPS-2195 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Check the fan direction using chassis show command and fix the fan direction.

Action

MAPS-2196 to MAPS-2199

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2196 : CRITICAL', 'MAPS-2197 : ERROR', 'MAPS-2198 : WARNING', 'MAPS-2199 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Telnet violations indicate that a Telnet connection request has been received from an unauthorized IP

Action address. The IP ACL policy contains a list of internet protocol (IP) addresses that are authorized to

address. The IP ACL policy contains a list of internet protocol (IP) addresses that are authorized to establish Telnet connections to switches in the fabric. Refer to the master log to determine the IP address that sent the request. Responses to security-class messages depend on user policies.

Consult your security administrator for response strategies and policies.

MAPS-2200 to MAPS-2203

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2200 : CRITICAL', 'MAPS-2201 : ERROR', 'MAPS-2202 : WARNING', 'MAPS-2203 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended

Action

HTTP violations indicate that a browser connection request has been received from an unauthorized IP address. The IP ACL policy contains a list of internet protocol (IP) addresses that are authorized to establish browser connections to the switches in the fabric. Refer to the master log to determine the IP address that sent the request. Responses to security-class messages depend on user policies.

Consult your security administrator for response strategies and policies.

MAPS-2204 to MAPS-2207

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2204 : CRITICAL', 'MAPS-2205 : ERROR', 'MAPS-2206 : WARNING', 'MAPS-2207 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended

Action

SCC violations indicate that an unauthorized switch tried to join the fabric. The SCC_POLICY contains a list of switches by World Wide Name (WWN) that are allowed to be members of a fabric. Refer to the master log to determine the WWN of the device that sent the request. Responses to security-class messages depend on user policies. Consult your security administrator for response strategies and

policies.

MAPS-2208 to MAPS-2211

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2208: CRITICAL', 'MAPS-2209: ERROR', 'MAPS-2210: WARNING', 'MAPS-2211: INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Action

DCC violations indicate that an unauthorized device tried to join the fabric. The DCC_POLICY allows for the specification of rules for binding device ports (typically HBA ports) to specific switch ports. DCC policies ensure that whenever a device performs a fabric login (FLOGI) request, the World Wide Name (WWN) specified in the FLOGI is validated to be connected to the authorized port. Enforcement for private loop devices not performing FLOGI is done through the name server. Refer to the master log to determine the device WWN, switch WWN, and switch port. Responses to security-class messages depend on user policies. Consult your security administrator for response strategies and policies.

MAPS-2212 to MAPS-2215

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2212 : CRITICAL', 'MAPS-2213 : ERROR', 'MAPS-2214 : WARNING', 'MAPS-2215 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended

Action

Login violations indicate that a login failure has been detected. Refer to the master log to determine the IP location of the login attempt. Responses to security-class messages depend on user policies. Consult your security administrator for response strategies and policies.

MAPS-2216 to MAPS-2219

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2216: CRITICAL', 'MAPS-2217: ERROR', 'MAPS-2218: WARNING', 'MAPS-2219: INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Action This violation indicates that a packet with an invalid certificate has been received from the primary fabric configuration server (FCS). Before a new primary FCS switch sends any configuration data to any switch in the fabric, it first sends its certificate to all the switches in the fabric. The receiving switch has to verify that the sender is the primary FCS switch and its certificate is signed by the Root CA recognized by the receiving switch. This counter keeps track of the number of packets received with invalid certificates. Responses to security-class messages depend on user policies. Consult your security administrator for response strategies and policies.

MAPS-2220 to MAPS-2223

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2220 : CRITICAL', 'MAPS-2221 : ERROR', 'MAPS-2222 : WARNING', 'MAPS-2223 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Responses to security-class messages depend on user policies. Consult your security administrator

Action for response strategies and policies.

MAPS-2224 to MAPS-2227

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2224 : CRITICAL', 'MAPS-2225 : ERROR', 'MAPS-2226 : WARNING', 'MAPS-2227 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended This counter keeps track of the number of unexpected SLAP packets and SLAP packets with faulty

transmission IDs. Responses to security-class messages depend on user policies. Consult your

security administrator for response strategies and policies.

MAPS-2228 to MAPS-2231

Action

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2228 : CRITICAL', 'MAPS-2229 : ERROR', 'MAPS-2230 : WARNING', 'MAPS-2231 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended

Action

This counter records how often the switch loses contact with the primary fabric configuration server (FCS) switch. When the primary FCS switch in the fabric sends its certificate to a switch, the receiving switch saves the World Wide Name (WWN) of that primary FCS switch. If a secure switch finds that there are no FCSs in the fabric, but it still has the WWN of the last primary FCS switch, it increments this counter and resets the WWN of the primary FCS to all zeroes. Responses to security-class messages depend on user policies. Consult your security administrator for response strategies and policies.

policies.

MAPS-2232 to MAPS-2235

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

Message Type LOG

Severity ['MAPS-2232 : CRITICAL', 'MAPS-2233 : ERROR', 'MAPS-2234 : WARNING', 'MAPS-2235 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended

Action

This violation indicates the number of secure switches with different version stamps have been detected. When a switch is in secure mode, it connects only to another switch that is in secure mode and has a compatible security database. A compatible security database means that the version stamp and fabric configuration server (FCS) policy matches exactly. Responses to security-class messages depend on user policies. Consult your security administrator for response strategies and policies.

MAPS-2236 to MAPS-2239

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2236 : CRITICAL', 'MAPS-2237 : ERROR', 'MAPS-2238 : WARNING', 'MAPS-2239 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended

Action

This counter tracks how many times commands allowed only on the primary fabric configuration server (FCS) switch have been executed on a non-primary FCS switch. There are many commands that can be executed only on the primary FCS switch as well as one security command that can be executed only on a backup FCS switch. The counter increments every time someone issues one of these commands on a switch where it is not allowed. Responses to security-class messages depend on user policies. Consult your security administrator for response strategies and policies.

MAPS-2240 to MAPS-2243

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2240 : CRITICAL', 'MAPS-2241 : ERROR', 'MAPS-2242 : WARNING', 'MAPS-2243 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Download new security certificate before certificate expiry date.

Action

MAPS-2244 to MAPS-2247

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2244 : CRITICAL', 'MAPS-2245 : ERROR', 'MAPS-2246 : WARNING', 'MAPS-2247 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Download new security certificate.

Action

MAPS-2248 to MAPS-2251

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2248 : CRITICAL', 'MAPS-2249 : ERROR', 'MAPS-2250 : WARNING', 'MAPS-2251 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2252 to MAPS-2255

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2252: CRITICAL', 'MAPS-2253: ERROR', 'MAPS-2254: WARNING', 'MAPS-2255: INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2256 to MAPS-2259

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2256 : CRITICAL', 'MAPS-2257 : ERROR', 'MAPS-2258 : WARNING', 'MAPS-2259 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2260 to MAPS-2263

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2260 : CRITICAL', 'MAPS-2261 : ERROR', 'MAPS-2262 : WARNING', 'MAPS-2263 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Frequent fluctuations in SFP temperature may indicate a deteriorating SFP. Verify that the switch is

Action properly ventilated or replace the SFP.

MAPS-2264 to MAPS-2267

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2264 : CRITICAL', 'MAPS-2265 : ERROR', 'MAPS-2266 : WARNING', 'MAPS-2267 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended If the supplied voltage of the SFP transceiver is outside of the normal range, this may indicate a

hardware failure. Frequent voltage fluctuations indicate that the SFP is deteriorating. Verify that your optical components are clean and function properly. Replace deteriorating SFPs. Check for damage

from heat or age.

MAPS-2268 to MAPS-2271

Action

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2268 : CRITICAL', 'MAPS-2269 : ERROR', 'MAPS-2270 : WARNING', 'MAPS-2271 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended If the supplied current of the SFP transceiver is outside of the normal range, this may indicate a

hardware failure. If the message persists, replace the SFP.

MAPS-2272 to MAPS-2275

Action

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

Message Type LOG

Severity ['MAPS-2272 : CRITICAL', 'MAPS-2273 : ERROR', 'MAPS-2274 : WARNING', 'MAPS-2275 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended The receive performance area measures the amount of incoming laser to help you determine if the Action SEP is in good working condition or not. If the counter often exceeds the threshold, the SEP is

SFP is in good working condition or not. If the counter often exceeds the threshold, the SFP is deteriorating. Incoming laser fluctuations usually indicate a deteriorating SFP. If the message persists,

verify that your optical components are clean and function properly. Replace deteriorating cables or

SFPs. Check for damage from heat or age.

MAPS-2276 to MAPS-2279

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2276 : CRITICAL', 'MAPS-2277 : ERROR', 'MAPS-2278 : WARNING', 'MAPS-2279 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended The transmit performance area measures the amount of outgoing laser to help you determine if the

Action SFP is in good working condition or not. If the counter often exceeds the threshold, the SFP is

deteriorating. Transmitting laser fluctuations usually indicate a deteriorating SFP. If the message persists, verify that your optical components are clean and function properly. Replace deteriorating

SFPs. Check for damage from heat or age.

MAPS-2280 to MAPS-2283

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2280 : CRITICAL', 'MAPS-2281 : ERROR', 'MAPS-2282 : WARNING', 'MAPS-2283 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended If continuous or repeated violations occur, replace the SFP before it deteriorates. A high value

indicates that the SFP is nearing the maximum lifetime of use.

MAPS-2284 to MAPS-2287

Action

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2284 : CRITICAL', 'MAPS-2285 : ERROR', 'MAPS-2286 : WARNING', 'MAPS-2287 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Replace the FRU which contains the faulty temperature sensor.

Action

MAPS-2288 to MAPS-2291

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2288 : CRITICAL', 'MAPS-2289 : ERROR', 'MAPS-2290 : WARNING', 'MAPS-2291 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Replace the faulty power supply.

Action

MAPS-2292 to MAPS-2295

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2292 : CRITICAL', 'MAPS-2293 : ERROR', 'MAPS-2294 : WARNING', 'MAPS-2295 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Replace the faulty fan.

Action

MAPS-2296 to MAPS-2299

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2296 : CRITICAL', 'MAPS-2297 : ERROR', 'MAPS-2298 : WARNING', 'MAPS-2299 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended

Replace any faulty or deteriorating SFPs.

Action

MAPS-2300 to MAPS-2303

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2300 : CRITICAL', 'MAPS-2301 : ERROR', 'MAPS-2302 : WARNING', 'MAPS-2303 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Insert SFPs into ports where the FRU is missing or increase the threshold for missing SFPs.

Action

MAPS-2304 to MAPS-2307

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2304 : CRITICAL', 'MAPS-2305 : ERROR', 'MAPS-2306 : WARNING', 'MAPS-2307 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended The number of faulty port blades has exceeded the defined threshold. Replace the faulty port blade.

Action

MAPS-2308 to MAPS-2311

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2308 : CRITICAL', 'MAPS-2309 : ERROR', 'MAPS-2310 : WARNING', 'MAPS-2311 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Action Replace any faulty or deteriorating SFPs or resolve link errors causing marginal port state.

MAPS-2312 to MAPS-2315

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule</pre>

name>, Dashboard Category=<Dashboard Category>.

LOG Message Type

> Severity ['MAPS-2312: CRITICAL', 'MAPS-2313: ERROR', 'MAPS-2314: WARNING', 'MAPS-2315: INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Resolve any port segmentation or disabled port issues. Take necessary action to bring the ports

Action online.

MAPS-2316 to MAPS-2319

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule</pre>

name>, Dashboard Category=<Dashboard Category>.

LOG Message Type

> ['MAPS-2316: CRITICAL', 'MAPS-2317: ERROR', 'MAPS-2318: WARNING', 'MAPS-2319: INFO'] Severity

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended E Ports go down each time you remove a cable or small form-factor pluggable (SFP). SFP failures Action

also cause E Ports to go down. E Port downs might be caused by transient errors. Check both ends

of the physical connection and verify that the SFPs and cables are functioning properly.

MAPS-2320 to MAPS-2323

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule</pre>

name>, Dashboard Category=<Dashboard Category>.

LOG Message Type

> ['MAPS-2320 : CRITICAL', 'MAPS-2321 : ERROR', 'MAPS-2322 : WARNING', 'MAPS-2323 : INFO'] Severity

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended The following occurrences can cause a fabric reconfiguration: Two switches with the same domain ID Action

have connected to one another, two fabrics have joined, an E Port has gone offline, or a principal link has segmented from the fabric. Verify that the cable is properly connected at both ends. Verify that the small form-factor pluggables (SFPs) have not become faulty. An inexplicable fabric reconfiguration

FOS-90x-Message-RM103 Broadcom

might be a transient error and might not require troubleshooting.

MAPS-2324 to MAPS-2327

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule</pre>

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

> Severity ['MAPS-2324 : CRITICAL', 'MAPS-2325 : ERROR', 'MAPS-2326 : WARNING', 'MAPS-2327 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended

Action

Domain ID changes occur when there is a conflict of domain IDs in a single fabric and the principal switch has to assign another domain ID to the switch, or unintentional configuration of persistent domain IDs. If the change is not an expected event in the environment, confirm fabric state and device connectivity. Correcting the domain ID may be necessary in environments that utilize domain/area

zoning architecture.

MAPS-2328 to MAPS-2331

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule</pre>

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

> ['MAPS-2328 : CRITICAL', 'MAPS-2329 : ERROR', 'MAPS-2330 : WARNING', 'MAPS-2331 : INFO'] Severity

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended

Action

Segmentation changes might occur due to the following reasons: Zone conflicts, domain conflicts, segmentation of the principal link between two switches, or incompatible link parameters. During E Port initialization, ports exchange link parameters. Rarely, incompatible parameters result in segmentation. Correct the segmentation that is identified. If it is indeterminable, contact your switch

support vendor for assistance.

MAPS-2332 to MAPS-2335

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule</pre>

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

> Severity ['MAPS-2332 : CRITICAL', 'MAPS-2333 : ERROR', 'MAPS-2334 : WARNING', 'MAPS-2335 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2336 to MAPS-2339

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2336 : CRITICAL', 'MAPS-2337 : ERROR', 'MAPS-2338 : WARNING', 'MAPS-2339 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Zone changes occur when there is a change to the effective zone configuration. If the zone changes

performed were not expected, respond as appropriate based on current end-user policies for zone

changes.

MAPS-2340 to MAPS-2343

Action

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2340 : CRITICAL', 'MAPS-2341 : ERROR', 'MAPS-2342 : WARNING', 'MAPS-2343 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Fabric logins occur when a port or device initializes with the fabric. The event is called fabric login

(FLOGI). If the fabric login is not expected, confirm if there should be a device logged in on that port.

Take appropriate action based on fabric defined policies.

MAPS-2344 to MAPS-2347

Action

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2344 : CRITICAL', 'MAPS-2345 : ERROR', 'MAPS-2346 : WARNING', 'MAPS-2347 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Reduce the number of hosts or targets attached to the Layer 2 fabric to a value lower than the

Action configured limit.

MAPS-2348 to MAPS-2351

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

Message Type LOG

Severity ['MAPS-2348 : CRITICAL', 'MAPS-2349 : ERROR', 'MAPS-2350 : WARNING', 'MAPS-2351 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Reduce the number of imported hosts or targets within a meta-SAN to the recommended scalability

Action limit

MAPS-2352 to MAPS-2355

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2352: CRITICAL', 'MAPS-2353: ERROR', 'MAPS-2354: WARNING', 'MAPS-2355: INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Reduce the size of zoning configuration to the recommended scalability limit.

Action

MAPS-2356 to MAPS-2359

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2356: CRITICAL', 'MAPS-2357: ERROR', 'MAPS-2358: WARNING', 'MAPS-2359: INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Reduce the number of Fiber Channel Routers in the backbone fabric to the recommended scalability

Action limit.

MAPS-2360 to MAPS-2363

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2360 : CRITICAL', 'MAPS-2361 : ERROR', 'MAPS-2362 : WARNING', 'MAPS-2363 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended

Action

Make sure that the blade is seated correctly. If the blade is seated correctly, execute the **diagPost** command to make sure that power-on self-test (POST) is enabled; then power-cycle the blade using the **slotPowerOff** and **slotPowerOn** commands or have the blade's ejector switch cycled to run POST and verify that the blade does not have any hardware problems. Additional blade fault messages precede and follow this error, providing more information. Refer to other error messages for the recommended action. If the message persists, replace the blade.

MAPS-2364 to MAPS-2367

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2364 : CRITICAL', 'MAPS-2365 : ERROR', 'MAPS-2366 : WARNING', 'MAPS-2367 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Verify both CP blades have compatible firmware levels. Replace any faulty CP blades.

Action

MAPS-2368 to MAPS-2371

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2368 : CRITICAL', 'MAPS-2369 : ERROR', 'MAPS-2370 : WARNING', 'MAPS-2371 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended The number of faulty WWN cards has exceeded the defined threshold. Replace the faulty WWN card.

Action

MAPS-2372 to MAPS-2375

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2372 : CRITICAL', 'MAPS-2373 : ERROR', 'MAPS-2374 : WARNING', 'MAPS-2375 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2376 to MAPS-2379

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2376 : CRITICAL', 'MAPS-2377 : ERROR', 'MAPS-2378 : WARNING', 'MAPS-2379 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2380 to MAPS-2383

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2380 : CRITICAL', 'MAPS-2381 : ERROR', 'MAPS-2382 : WARNING', 'MAPS-2383 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2384 to MAPS-2387

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2384 : CRITICAL', 'MAPS-2385 : ERROR', 'MAPS-2386 : WARNING', 'MAPS-2387 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2388 to MAPS-2391

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2388 : CRITICAL', 'MAPS-2389 : ERROR', 'MAPS-2390 : WARNING', 'MAPS-2391 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2392 to MAPS-2395

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2392 : CRITICAL', 'MAPS-2393 : ERROR', 'MAPS-2394 : WARNING', 'MAPS-2395 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2396 to MAPS-2399

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2396 : CRITICAL', 'MAPS-2397 : ERROR', 'MAPS-2398 : WARNING', 'MAPS-2399 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2400 to MAPS-2403

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2400 : CRITICAL', 'MAPS-2401 : ERROR', 'MAPS-2402 : WARNING', 'MAPS-2403 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2404 to MAPS-2407

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2404 : CRITICAL', 'MAPS-2405 : ERROR', 'MAPS-2406 : WARNING', 'MAPS-2407 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2408 to MAPS-2411

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2408 : CRITICAL', 'MAPS-2409 : ERROR', 'MAPS-2410 : WARNING', 'MAPS-2411 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Check Ethernet management port physical connection and IP network configuration to ensure the

Action stability.

MAPS-2412 to MAPS-2415

Message <object>, Condition = <condition>, Current Value: <ms, values, units>, RuleName = <Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2412 : CRITICAL', 'MAPS-2413 : ERROR', 'MAPS-2414 : WARNING', 'MAPS-2415 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended The state of the tunnel has changed by transitioning to online or offline. Check the connectivity

between the tunnel endpoints for reliability.

MAPS-2416 to MAPS-2419

Action

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2416 : CRITICAL', 'MAPS-2417 : ERROR', 'MAPS-2418 : WARNING', 'MAPS-2419 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended High utilization may indicate the need for more bandwidth or parallel connections.

Action

MAPS-2420 to MAPS-2423

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2420 : CRITICAL', 'MAPS-2421 : ERROR', 'MAPS-2422 : WARNING', 'MAPS-2423 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2424 to MAPS-2427

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2424 : CRITICAL', 'MAPS-2425 : ERROR', 'MAPS-2426 : WARNING', 'MAPS-2427 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended High packet loss may indicate a congested or unreliable intermediate link. Add more parallel

Action connections or replace unreliable intermediate links.

MAPS-2428 to MAPS-2431

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2428 : CRITICAL', 'MAPS-2429 : ERROR', 'MAPS-2430 : WARNING', 'MAPS-2431 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended The RTT of the tunnel / circuit has exceeded the allowable threshold. Check the network path for

Action possible network disruptions or route changes.

MAPS-2432 to MAPS-2435

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2432 : CRITICAL', 'MAPS-2433 : ERROR', 'MAPS-2434 : WARNING', 'MAPS-2435 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended The RTT variance has exceeded the allowable threshold. Check the network path for possible network

Action disruptions or congestion.

MAPS-2436 to MAPS-2439

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

Message Type LOG

Severity ['MAPS-2436 : CRITICAL', 'MAPS-2437 : ERROR', 'MAPS-2438 : WARNING', 'MAPS-2439 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2440 to MAPS-2443

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2440 : CRITICAL', 'MAPS-2441 : ERROR', 'MAPS-2442 : WARNING', 'MAPS-2443 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2444 to MAPS-2447

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2444 : CRITICAL', 'MAPS-2445 : ERROR', 'MAPS-2446 : WARNING', 'MAPS-2447 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2448 to MAPS-2451

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2448 : CRITICAL', 'MAPS-2449 : ERROR', 'MAPS-2450 : WARNING', 'MAPS-2451 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2452 to MAPS-2455

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2452 : CRITICAL', 'MAPS-2453 : ERROR', 'MAPS-2454 : WARNING', 'MAPS-2455 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2456 to MAPS-2459

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2456 : CRITICAL', 'MAPS-2457 : ERROR', 'MAPS-2458 : WARNING', 'MAPS-2459 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2460 to MAPS-2463

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2460 : CRITICAL', 'MAPS-2461 : ERROR', 'MAPS-2462 : WARNING', 'MAPS-2463 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2464 to MAPS-2467

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2464 : CRITICAL', 'MAPS-2465 : ERROR', 'MAPS-2466 : WARNING', 'MAPS-2467 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2468 to MAPS-2471

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2468 : CRITICAL', 'MAPS-2469 : ERROR', 'MAPS-2470 : WARNING', 'MAPS-2471 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2472 to MAPS-2475

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2472 : CRITICAL', 'MAPS-2473 : ERROR', 'MAPS-2474 : WARNING', 'MAPS-2475 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2476 to MAPS-2479

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2476 : CRITICAL', 'MAPS-2477 : ERROR', 'MAPS-2478 : WARNING', 'MAPS-2479 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2480 to MAPS-2483

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2480 : CRITICAL', 'MAPS-2481 : ERROR', 'MAPS-2482 : WARNING', 'MAPS-2483 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2484 to MAPS-2487

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2484 : CRITICAL', 'MAPS-2485 : ERROR', 'MAPS-2486 : WARNING', 'MAPS-2487 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2488 to MAPS-2491

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2488 : CRITICAL', 'MAPS-2489 : ERROR', 'MAPS-2490 : WARNING', 'MAPS-2491 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2492 to MAPS-2495

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2492 : CRITICAL', 'MAPS-2493 : ERROR', 'MAPS-2494 : WARNING', 'MAPS-2495 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2496 to MAPS-2499

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2496 : CRITICAL', 'MAPS-2497 : ERROR', 'MAPS-2498 : WARNING', 'MAPS-2499 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2500 to MAPS-2503

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2500 : CRITICAL', 'MAPS-2501 : ERROR', 'MAPS-2502 : WARNING', 'MAPS-2503 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2504 to MAPS-2507

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

Message Type LOG

Severity ['MAPS-2504 : CRITICAL', 'MAPS-2505 : ERROR', 'MAPS-2506 : WARNING', 'MAPS-2507 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold

MAPS-2508 to MAPS-2511

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2508 : CRITICAL', 'MAPS-2509 : ERROR', 'MAPS-2510 : WARNING', 'MAPS-2511 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2512 to MAPS-2515

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2512: CRITICAL', 'MAPS-2513: ERROR', 'MAPS-2514: WARNING', 'MAPS-2515: INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2516 to MAPS-2519

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2516: CRITICAL', 'MAPS-2517: ERROR', 'MAPS-2518: WARNING', 'MAPS-2519: INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2520 to MAPS-2523

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2520 : CRITICAL', 'MAPS-2521 : ERROR', 'MAPS-2522 : WARNING', 'MAPS-2523 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2524 to MAPS-2527

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2524 : CRITICAL', 'MAPS-2525 : ERROR', 'MAPS-2526 : WARNING', 'MAPS-2527 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2528 to MAPS-2531

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2528 : CRITICAL', 'MAPS-2529 : ERROR', 'MAPS-2530 : WARNING', 'MAPS-2531 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2532 to MAPS-2535

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2532 : CRITICAL', 'MAPS-2533 : ERROR', 'MAPS-2534 : WARNING', 'MAPS-2535 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2536 to MAPS-2539

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2536 : CRITICAL', 'MAPS-2537 : ERROR', 'MAPS-2538 : WARNING', 'MAPS-2539 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2540 to MAPS-2543

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2540 : CRITICAL', 'MAPS-2541 : ERROR', 'MAPS-2542 : WARNING', 'MAPS-2543 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2544 to MAPS-2547

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2544 : CRITICAL', 'MAPS-2545 : ERROR', 'MAPS-2546 : WARNING', 'MAPS-2547 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2548 to MAPS-2551

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2548 : CRITICAL', 'MAPS-2549 : ERROR', 'MAPS-2550 : WARNING', 'MAPS-2551 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2552 to MAPS-2555

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2552 : CRITICAL', 'MAPS-2553 : ERROR', 'MAPS-2554 : WARNING', 'MAPS-2555 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2556 to MAPS-2559

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2556: CRITICAL', 'MAPS-2557: ERROR', 'MAPS-2558: WARNING', 'MAPS-2559: INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2560 to MAPS-2563

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2560 : CRITICAL', 'MAPS-2561 : ERROR', 'MAPS-2562 : WARNING', 'MAPS-2563 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2564 to MAPS-2567

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2564 : CRITICAL', 'MAPS-2565 : ERROR', 'MAPS-2566 : WARNING', 'MAPS-2567 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2568 to MAPS-2571

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2568 : CRITICAL', 'MAPS-2569 : ERROR', 'MAPS-2570 : WARNING', 'MAPS-2571 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2572 to MAPS-2575

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

Message Type LOG

Severity ['MAPS-2572 : CRITICAL', 'MAPS-2573 : ERROR', 'MAPS-2574 : WARNING', 'MAPS-2575 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold

MAPS-2576 to MAPS-2579

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2576 : CRITICAL', 'MAPS-2577 : ERROR', 'MAPS-2578 : WARNING', 'MAPS-2579 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2580 to MAPS-2583

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2580 : CRITICAL', 'MAPS-2581 : ERROR', 'MAPS-2582 : WARNING', 'MAPS-2583 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2584 to MAPS-2587

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2584 : CRITICAL', 'MAPS-2585 : ERROR', 'MAPS-2586 : WARNING', 'MAPS-2587 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2588 to MAPS-2591

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2588: CRITICAL', 'MAPS-2589: ERROR', 'MAPS-2590: WARNING', 'MAPS-2591: INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2592 to MAPS-2595

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2592 : CRITICAL', 'MAPS-2593 : ERROR', 'MAPS-2594 : WARNING', 'MAPS-2595 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2596 to MAPS-2599

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2596 : CRITICAL', 'MAPS-2597 : ERROR', 'MAPS-2598 : WARNING', 'MAPS-2599 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2600 to MAPS-2603

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2600 : CRITICAL', 'MAPS-2601 : ERROR', 'MAPS-2602 : WARNING', 'MAPS-2603 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2604 to MAPS-2607

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2604 : CRITICAL', 'MAPS-2605 : ERROR', 'MAPS-2606 : WARNING', 'MAPS-2607 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2608 to MAPS-2611

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2608 : CRITICAL', 'MAPS-2609 : ERROR', 'MAPS-2610 : WARNING', 'MAPS-2611 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2612 to MAPS-2615

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2612 : CRITICAL', 'MAPS-2613 : ERROR', 'MAPS-2614 : WARNING', 'MAPS-2615 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2616 to MAPS-2619

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2616: CRITICAL', 'MAPS-2617: ERROR', 'MAPS-2618: WARNING', 'MAPS-2619: INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2620 to MAPS-2623

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2620 : CRITICAL', 'MAPS-2621 : ERROR', 'MAPS-2622 : WARNING', 'MAPS-2623 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2624 to MAPS-2627

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2624 : CRITICAL', 'MAPS-2625 : ERROR', 'MAPS-2626 : WARNING', 'MAPS-2627 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2628 to MAPS-2631

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2628 : CRITICAL', 'MAPS-2629 : ERROR', 'MAPS-2630 : WARNING', 'MAPS-2631 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2632 to MAPS-2635

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2632 : CRITICAL', 'MAPS-2633 : ERROR', 'MAPS-2634 : WARNING', 'MAPS-2635 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2636 to MAPS-2639

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2636 : CRITICAL', 'MAPS-2637 : ERROR', 'MAPS-2638 : WARNING', 'MAPS-2639 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2640 to MAPS-2643

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

Message Type LOG

Severity ['MAPS-2640 : CRITICAL', 'MAPS-2641 : ERROR', 'MAPS-2642 : WARNING', 'MAPS-2643 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2644 to MAPS-2647

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2644 : CRITICAL', 'MAPS-2645 : ERROR', 'MAPS-2646 : WARNING', 'MAPS-2647 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2648 to MAPS-2651

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2648 : CRITICAL', 'MAPS-2649 : ERROR', 'MAPS-2650 : WARNING', 'MAPS-2651 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2652 to MAPS-2655

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2652 : CRITICAL', 'MAPS-2653 : ERROR', 'MAPS-2654 : WARNING', 'MAPS-2655 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2656 to MAPS-2659

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2656 : CRITICAL', 'MAPS-2657 : ERROR', 'MAPS-2658 : WARNING', 'MAPS-2659 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2660 to MAPS-2663

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2660 : CRITICAL', 'MAPS-2661 : ERROR', 'MAPS-2662 : WARNING', 'MAPS-2663 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2664 to MAPS-2667

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2664 : CRITICAL', 'MAPS-2665 : ERROR', 'MAPS-2666 : WARNING', 'MAPS-2667 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2668 to MAPS-2671

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2668 : CRITICAL', 'MAPS-2669 : ERROR', 'MAPS-2670 : WARNING', 'MAPS-2671 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2672 to MAPS-2675

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2672 : CRITICAL', 'MAPS-2673 : ERROR', 'MAPS-2674 : WARNING', 'MAPS-2675 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended

Action

The number of flows monitored by AMP has reached the limit. Consider using multiple AMPs and distribute the flows from the fabric among them. Refer to admin guide for further assistance on the

procedure.

MAPS-2676 to MAPS-2679

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2676 : CRITICAL', 'MAPS-2677 : ERROR', 'MAPS-2678 : WARNING', 'MAPS-2679 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2680 to MAPS-2683

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2680 : CRITICAL', 'MAPS-2681 : ERROR', 'MAPS-2682 : WARNING', 'MAPS-2683 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2684 to MAPS-2687

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2684 : CRITICAL', 'MAPS-2685 : ERROR', 'MAPS-2686 : WARNING', 'MAPS-2687 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2688 to MAPS-2691

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2688 : CRITICAL', 'MAPS-2689 : ERROR', 'MAPS-2690 : WARNING', 'MAPS-2691 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2692 to MAPS-2695

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2692 : CRITICAL', 'MAPS-2693 : ERROR', 'MAPS-2694 : WARNING', 'MAPS-2695 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2696 to MAPS-2699

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2696 : CRITICAL', 'MAPS-2697 : ERROR', 'MAPS-2698 : WARNING', 'MAPS-2699 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2700 to MAPS-2703

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2700 : CRITICAL', 'MAPS-2701 : ERROR', 'MAPS-2702 : WARNING', 'MAPS-2703 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2704 to MAPS-2707

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2704 : CRITICAL', 'MAPS-2705 : ERROR', 'MAPS-2706 : WARNING', 'MAPS-2707 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2708 to MAPS-2711

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2708 : CRITICAL', 'MAPS-2709 : ERROR', 'MAPS-2710 : WARNING', 'MAPS-2711 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended If problem persists, consult their network provider to look for network issues. Alternatively can use

Action wtool (7840) to test network to look for network issues.

MAPS-2712 to MAPS-2715

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2712 : CRITICAL', 'MAPS-2713 : ERROR', 'MAPS-2714 : WARNING', 'MAPS-2715 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2716 to MAPS-2719

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2716 : CRITICAL', 'MAPS-2717 : ERROR', 'MAPS-2718 : WARNING', 'MAPS-2719 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2720 to MAPS-2723

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2720 : CRITICAL', 'MAPS-2721 : ERROR', 'MAPS-2722 : WARNING', 'MAPS-2723 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2724 to MAPS-2727

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2724 : CRITICAL', 'MAPS-2725 : ERROR', 'MAPS-2726 : WARNING', 'MAPS-2727 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2728 to MAPS-2731

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2728 : CRITICAL', 'MAPS-2729 : ERROR', 'MAPS-2730 : WARNING', 'MAPS-2731 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2732 to MAPS-2735

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2732 : CRITICAL', 'MAPS-2733 : ERROR', 'MAPS-2734 : WARNING', 'MAPS-2735 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2736 to MAPS-2739

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2736 : CRITICAL', 'MAPS-2737 : ERROR', 'MAPS-2738 : WARNING', 'MAPS-2739 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2740 to MAPS-2743

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2740 : CRITICAL', 'MAPS-2741 : ERROR', 'MAPS-2742 : WARNING', 'MAPS-2743 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2744 to MAPS-2747

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2744 : CRITICAL', 'MAPS-2745 : ERROR', 'MAPS-2746 : WARNING', 'MAPS-2747 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2748 to MAPS-2751

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2748 : CRITICAL', 'MAPS-2749 : ERROR', 'MAPS-2750 : WARNING', 'MAPS-2751 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2752 to MAPS-2755

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2752 : CRITICAL', 'MAPS-2753 : ERROR', 'MAPS-2754 : WARNING', 'MAPS-2755 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2756 to MAPS-2759

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

Message Type LOG

Severity ['MAPS-2756 : CRITICAL', 'MAPS-2757 : ERROR', 'MAPS-2758 : WARNING', 'MAPS-2759 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2760 to MAPS-2763

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2760 : CRITICAL', 'MAPS-2761 : ERROR', 'MAPS-2762 : WARNING', 'MAPS-2763 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2764 to MAPS-2767

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2764: CRITICAL', 'MAPS-2765: ERROR', 'MAPS-2766: WARNING', 'MAPS-2767: INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2768 to MAPS-2771

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2768 : CRITICAL', 'MAPS-2769 : ERROR', 'MAPS-2770 : WARNING', 'MAPS-2771 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2772 to MAPS-2775

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2772 : CRITICAL', 'MAPS-2773 : ERROR', 'MAPS-2774 : WARNING', 'MAPS-2775 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2776 to MAPS-2779

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2776 : CRITICAL', 'MAPS-2777 : ERROR', 'MAPS-2778 : WARNING', 'MAPS-2779 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2780 to MAPS-2783

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2780 : CRITICAL', 'MAPS-2781 : ERROR', 'MAPS-2782 : WARNING', 'MAPS-2783 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2784 to MAPS-2787

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2784 : CRITICAL', 'MAPS-2785 : ERROR', 'MAPS-2786 : WARNING', 'MAPS-2787 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2788 to MAPS-2791

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2788 : CRITICAL', 'MAPS-2789 : ERROR', 'MAPS-2790 : WARNING', 'MAPS-2791 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2792 to MAPS-2795

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2792 : CRITICAL', 'MAPS-2793 : ERROR', 'MAPS-2794 : WARNING', 'MAPS-2795 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2796 to MAPS-2799

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2796 : CRITICAL', 'MAPS-2797 : ERROR', 'MAPS-2798 : WARNING', 'MAPS-2799 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2800 to MAPS-2803

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2800 : CRITICAL', 'MAPS-2801 : ERROR', 'MAPS-2802 : WARNING', 'MAPS-2803 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2804 to MAPS-2807

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2804 : CRITICAL', 'MAPS-2805 : ERROR', 'MAPS-2806 : WARNING', 'MAPS-2807 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2808 to MAPS-2811

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2808 : CRITICAL', 'MAPS-2809 : ERROR', 'MAPS-2810 : WARNING', 'MAPS-2811 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2812 to MAPS-2815

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2812 : CRITICAL', 'MAPS-2813 : ERROR', 'MAPS-2814 : WARNING', 'MAPS-2815 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2816 to MAPS-2819

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2816 : CRITICAL', 'MAPS-2817 : ERROR', 'MAPS-2818 : WARNING', 'MAPS-2819 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2820 to MAPS-2823

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2820 : CRITICAL', 'MAPS-2821 : ERROR', 'MAPS-2822 : WARNING', 'MAPS-2823 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2824 to MAPS-2827

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2824 : CRITICAL', 'MAPS-2825 : ERROR', 'MAPS-2826 : WARNING', 'MAPS-2827 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold

MAPS-2828 to MAPS-2831

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2828 : CRITICAL', 'MAPS-2829 : ERROR', 'MAPS-2830 : WARNING', 'MAPS-2831 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2832 to MAPS-2835

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2832 : CRITICAL', 'MAPS-2833 : ERROR', 'MAPS-2834 : WARNING', 'MAPS-2835 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2836 to MAPS-2839

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2836 : CRITICAL', 'MAPS-2837 : ERROR', 'MAPS-2838 : WARNING', 'MAPS-2839 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2840 to MAPS-2843

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2840 : CRITICAL', 'MAPS-2841 : ERROR', 'MAPS-2842 : WARNING', 'MAPS-2843 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2844 to MAPS-2847

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2844 : CRITICAL', 'MAPS-2845 : ERROR', 'MAPS-2846 : WARNING', 'MAPS-2847 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2848 to MAPS-2851

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2848 : CRITICAL', 'MAPS-2849 : ERROR', 'MAPS-2850 : WARNING', 'MAPS-2851 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2852 to MAPS-2855

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2852 : CRITICAL', 'MAPS-2853 : ERROR', 'MAPS-2854 : WARNING', 'MAPS-2855 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2856 to MAPS-2859

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2856 : CRITICAL', 'MAPS-2857 : ERROR', 'MAPS-2858 : WARNING', 'MAPS-2859 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2860 to MAPS-2863

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2860 : CRITICAL', 'MAPS-2861 : ERROR', 'MAPS-2862 : WARNING', 'MAPS-2863 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2864 to MAPS-2867

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2864 : CRITICAL', 'MAPS-2865 : ERROR', 'MAPS-2866 : WARNING', 'MAPS-2867 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2868 to MAPS-2871

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2868 : CRITICAL', 'MAPS-2869 : ERROR', 'MAPS-2870 : WARNING', 'MAPS-2871 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2872 to MAPS-2875

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2872 : CRITICAL', 'MAPS-2873 : ERROR', 'MAPS-2874 : WARNING', 'MAPS-2875 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2876 to MAPS-2879

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2876 : CRITICAL', 'MAPS-2877 : ERROR', 'MAPS-2878 : WARNING', 'MAPS-2879 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2880 to MAPS-2883

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2880 : CRITICAL', 'MAPS-2881 : ERROR', 'MAPS-2882 : WARNING', 'MAPS-2883 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2884 to MAPS-2887

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2884 : CRITICAL', 'MAPS-2885 : ERROR', 'MAPS-2886 : WARNING', 'MAPS-2887 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2888 to MAPS-2891

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2888 : CRITICAL', 'MAPS-2889 : ERROR', 'MAPS-2890 : WARNING', 'MAPS-2891 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2892 to MAPS-2895

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2892 : CRITICAL', 'MAPS-2893 : ERROR', 'MAPS-2894 : WARNING', 'MAPS-2895 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2896 to MAPS-2899

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2896 : CRITICAL', 'MAPS-2897 : ERROR', 'MAPS-2898 : WARNING', 'MAPS-2899 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2900 to MAPS-2903

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2900 : CRITICAL', 'MAPS-2901 : ERROR', 'MAPS-2902 : WARNING', 'MAPS-2903 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2904 to MAPS-2907

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2904 : CRITICAL', 'MAPS-2905 : ERROR', 'MAPS-2906 : WARNING', 'MAPS-2907 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2908 to MAPS-2911

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2908 : CRITICAL', 'MAPS-2909 : ERROR', 'MAPS-2910 : WARNING', 'MAPS-2911 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2912 to MAPS-2915

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2912 : CRITICAL', 'MAPS-2913 : ERROR', 'MAPS-2914 : WARNING', 'MAPS-2915 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2916 to MAPS-2919

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2916 : CRITICAL', 'MAPS-2917 : ERROR', 'MAPS-2918 : WARNING', 'MAPS-2919 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2920 to MAPS-2923

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2920 : CRITICAL', 'MAPS-2921 : ERROR', 'MAPS-2922 : WARNING', 'MAPS-2923 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2924 to MAPS-2927

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2924 : CRITICAL', 'MAPS-2925 : ERROR', 'MAPS-2926 : WARNING', 'MAPS-2927 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2928 to MAPS-2931

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2928 : CRITICAL', 'MAPS-2929 : ERROR', 'MAPS-2930 : WARNING', 'MAPS-2931 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2932 to MAPS-2935

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2932 : CRITICAL', 'MAPS-2933 : ERROR', 'MAPS-2934 : WARNING', 'MAPS-2935 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2936 to MAPS-2939

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2936 : CRITICAL', 'MAPS-2937 : ERROR', 'MAPS-2938 : WARNING', 'MAPS-2939 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2940 to MAPS-2943

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2940 : CRITICAL', 'MAPS-2941 : ERROR', 'MAPS-2942 : WARNING', 'MAPS-2943 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2944 to MAPS-2947

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2944 : CRITICAL', 'MAPS-2945 : ERROR', 'MAPS-2946 : WARNING', 'MAPS-2947 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2948 to MAPS-2951

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2948 : CRITICAL', 'MAPS-2949 : ERROR', 'MAPS-2950 : WARNING', 'MAPS-2951 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2952 to MAPS-2955

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2952 : CRITICAL', 'MAPS-2953 : ERROR', 'MAPS-2954 : WARNING', 'MAPS-2955 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2956 to MAPS-2959

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2956 : CRITICAL', 'MAPS-2957 : ERROR', 'MAPS-2958 : WARNING', 'MAPS-2959 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2960 to MAPS-2963

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2960 : CRITICAL', 'MAPS-2961 : ERROR', 'MAPS-2962 : WARNING', 'MAPS-2963 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold

MAPS-2964 to MAPS-2967

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2964 : CRITICAL', 'MAPS-2965 : ERROR', 'MAPS-2966 : WARNING', 'MAPS-2967 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2968 to MAPS-2971

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2968 : CRITICAL', 'MAPS-2969 : ERROR', 'MAPS-2970 : WARNING', 'MAPS-2971 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2972 to MAPS-2975

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2972 : CRITICAL', 'MAPS-2973 : ERROR', 'MAPS-2974 : WARNING', 'MAPS-2975 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2976 to MAPS-2979

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2976 : CRITICAL', 'MAPS-2977 : ERROR', 'MAPS-2978 : WARNING', 'MAPS-2979 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2980 to MAPS-2983

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2980 : CRITICAL', 'MAPS-2981 : ERROR', 'MAPS-2982 : WARNING', 'MAPS-2983 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2992 to MAPS-2995

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2992 : CRITICAL', 'MAPS-2993 : ERROR', 'MAPS-2994 : WARNING', 'MAPS-2995 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-2996 to MAPS-2999

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-2996 : CRITICAL', 'MAPS-2997 : ERROR', 'MAPS-2998 : WARNING', 'MAPS-2999 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-3000 to MAPS-3003

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-3000 : CRITICAL', 'MAPS-3001 : ERROR', 'MAPS-3002 : WARNING', 'MAPS-3003 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-3004 to MAPS-3007

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-3004 : CRITICAL', 'MAPS-3005 : ERROR', 'MAPS-3006 : WARNING', 'MAPS-3007 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-3012 to MAPS-3015

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-3012 : CRITICAL', 'MAPS-3013 : ERROR', 'MAPS-3014 : WARNING', 'MAPS-3015 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-3016 to MAPS-3019

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-3016: CRITICAL', 'MAPS-3017: ERROR', 'MAPS-3018: WARNING', 'MAPS-3019: INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-3020 to MAPS-3023

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-3020 : CRITICAL', 'MAPS-3021 : ERROR', 'MAPS-3022 : WARNING', 'MAPS-3023 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-3024 to MAPS-3027

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-3024 : CRITICAL', 'MAPS-3025 : ERROR', 'MAPS-3026 : WARNING', 'MAPS-3027 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Verify that the location temperature is within the operational range of the switch. Refer to the *hardware*Action reference manual for the environmental temperature range of your switch. Execute the **fanShow**

reference manual for the environmental temperature range of your switch. Execute the **fanShow** command to verify that all fans are running at normal speeds. If any fans are missing or not performing at a high enough speed, they should be replaced. Check the environment and ensure the room

temperature is within the operational range of the switch. Ensure that there are no blockages of the airflow around the chassis. If temperature problem is isolated to PSU / FAN then reseat the PSU / FAN. If the problem persists, replace the unit. If problem is isolated to blade then reseat the blade. If the problem persists, replace the blade.

MAPS-3028 to MAPS-3031

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-3028 : CRITICAL', 'MAPS-3029 : ERROR', 'MAPS-3030 : WARNING', 'MAPS-3031 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-3032 to MAPS-3035

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-3032 : CRITICAL', 'MAPS-3033 : ERROR', 'MAPS-3034 : WARNING', 'MAPS-3035 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-3036 to MAPS-3039

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-3036 : CRITICAL', 'MAPS-3037 : ERROR', 'MAPS-3038 : WARNING', 'MAPS-3039 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-3040 to MAPS-3043

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-3040 : CRITICAL', 'MAPS-3041 : ERROR', 'MAPS-3042 : WARNING', 'MAPS-3043 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-3044 to MAPS-3047

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-3044 : CRITICAL', 'MAPS-3045 : ERROR', 'MAPS-3046 : WARNING', 'MAPS-3047 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-3048 to MAPS-3051

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-3048 : CRITICAL', 'MAPS-3049 : ERROR', 'MAPS-3050 : WARNING', 'MAPS-3051 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

MAPS-3052 to MAPS-3055

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-3052 : CRITICAL', 'MAPS-3053 : ERROR', 'MAPS-3054 : WARNING', 'MAPS-3055 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Access your switch vendor support portal to obtain and install a new Trusted FOS Certificate.

Action

MAPS-3056 to MAPS-3059

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-3056: CRITICAL', 'MAPS-3057: ERROR', 'MAPS-3058: WARNING', 'MAPS-3059: INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Action

Access your switch vendor support portal to obtain and install a new Trusted FOS Certificate.

MAPS-3060 to MAPS-3063

Message <object>, Condition=<condition>, Current Value:<ms, values, units>, RuleName=<Rule

name>, Dashboard Category=<Dashboard Category>.

Message Type LOG

Severity ['MAPS-3060 : CRITICAL', 'MAPS-3061 : ERROR', 'MAPS-3062 : WARNING', 'MAPS-3063 : INFO']

Probable Cause Indicates that the specified rule has been triggered because the errors are above the configured

threshold.

Recommended Action

Verify connectivity from switch to Support Link Server (bsnconnect.broadcom.com) or ASC-Gateway if deployed.

Suggested troubleshooting steps.

1. Verify DNS server is configured and reachable.

2. Verify the Support Link Server is reachable (ping bsnconnect.broadcom.com) or ASC-Gateway (ping ascg.domain.name)

(ping adog.admam.mame)

Retry upload with command **supportlink --send** and check log for confirmation or error.

6.69 MCST Messages

MCST-1001

Message Socket Error: <op> (<reason>) for socket <sockname> the error code <errorname>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that an error has occurred in the Linux socket.

Recommended Restart the multicast subsystem (MCAST SS) daemon.

Action

MCST-1002

Message Socket Error: <op> sock name <sock> Error <error> type <type> seq <seq> pid <pid>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the error has occurred while processing the hardware abstraction layer (HAL) message.

Recommended Restart the multicast subsystem (MCAST_SS) daemon.

Action

MCST-1003

Message Learning error: <op> (<reason>) - VLAN <vid> MAC/group <address>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the multicast subsystem (MCAST SS) has encountered an error while learning the

media access control (MAC) addresses.

Recommended Restart the MCAST_SS daemon.

Action

MCST-1004

Message NSM error: <op> (<reason>) for VLAN <vid> port <port>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the multicast subsystem (MCAST_SS) has encountered an error during a network

service module (NSM) event.

Recommended Restart the MCAST_SS daemon.

Action

MCST-1005

Message Message error: Invalid message type <type> expecting <value1> or <value2> or <value3>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the type of the message received from the driver is invalid.

Recommended Restart the MCAST_SS daemon.

Action

MCST-1006

Message Message error: <op> (<reason>) Invalid message length <length> expecting <length1>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that length of the message received from the driver is invalid.

Recommended Restart the MCAST_SS daemon.

Action

MCST-1007

Message Initialization error: <op> (<reason>).

Message Type LOG

Severity ERROR

Probable Cause Indicates that the multicast subsystem (MCAST_SS) has encountered an error during initialization.

Recommended Restart the MCAST_SS daemon.

Action

MCST-1008

Message HAL error: <op> (<reason>) - VLAN <vid> MAC/group <address>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the multicast subsystem (MCAST_SS) has encountered the hardware abstraction layer

(HAL) errors.

Recommended Restart the MCAST_SS daemon.

Action

MCST-1009

Message L2SS error : <op> (<reason>) VLAN <vid> MAC <mac address>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the multicast subsystem (MCAST_SS) has encountered the Layer 2 subsystem (L2SS)

related errors.

Recommended

Action Restart the MCAST_SS daemon.

MCST-1010

Message Queue error: <op> (<reason>).

Message Type LOG

Severity ERROR

Probable Cause Indicates that the multicast subsystem (MCAST_SS) has encountered the message queue errors.

Recommended Restart the MCAST_SS daemon.

Action

MCST-1011

Message IDB error: <op> (<reason>) port id <portid> not found.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified port ID is invalid.

Recommended Restart the MCAST_SS daemon.

Action

MCST-1012

Message IDB error: <op> (<reason>) VLAN VID <vid> not found.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified VLAN ID (VID) is invalid.

Recommended Restart the MCAST SS daemon.

Action

MCST-1013

Message Snooping DB error: <op> (<reason>) Group Not found - VLAN <vid>> group <group address>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the group address lookup for the specified VLAN has failed.

Recommended

Restart the MCAST_SS daemon.

Action

MCST-1014

Message Snooping DB error: (<reason>) MAC Not found - VLAN <vid> MAC-addr <mac address>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the media access control (MAC) address lookup for the specified VLAN has failed.

Recommended Restart the MCAST_SS daemon.

Action

MCST-1015

Message HSL error: <op> (<reason>) failed for message <message> VLAN <vid> MAC <mac address>

mgid <mgid> CPU <cpu>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified hardware subsystem layer (HSL) related operation has failed.

Recommended Restart the MCAST_SS daemon.

Action

MCST-1016

Message Message error: <op> (<reason>) <length>(<length1>).

Message Type LOG

Severity ERROR

Probable Cause Indicates that the length of the message received from the driver is invalid.

Recommended Restart the MCAST_SS daemon.

Action

MCST-1017

Message Learning error: <op> (<reason>) Invalid number <port> for ifindex <ifindex>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the multicast subsystem (MCAST_SS) has encountered an error while learning the

media access control (MAC) addresses.

Recommended

Restart the MCAST_SS daemon.

Action

MCST-1018

Message Memory Alloc Error: <op> (<reason>) type <memtype>/<memsize>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the multicast subsystem (MCAST_SS) has encountered an error during the memory

allocation.

Recommended

Restart the MCAST_SS daemon.

Action

MCST-1019

Message Ptree Error: <pp> (<reason>) VLAN <vid> MAC/group <address>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the multicast subsystem (MCAST_SS) has encountered an error during the Ptree

operation.

Recommended

Action

Restart the MCAST SS daemon.

MCST-1020

Message List Error: <op> (<reason>) VLAN <vid> MAC <mac address> group <group address>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the multicast subsystem (MCAST_SS) has encountered an error during the List

operation.

Recommended

Restart the MCAST_SS daemon.

Action

6.70 MFIC Messages

MFIC-1001

Message failure at sysmod scn registry rc= <failure reason>.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates the system is temporarily out of resources.

Recommended No action is required; this message is often transitory.

> Action If the message persists, run the reboot or the haFailover command (if applicable).

> > If the message persists, run the **supportFtp** command (as needed) to set up automatic FTP transfers;

then run the **supportSave** command and contact your switch service provider.

MFIC-1002

Message Chassis FRU header not programmed for switch NID, using defaults (applies only to

FICON environments).

LOG Message Type

> **INFO** Severity

Probable Cause Indicates that custom switch node descriptor (NID) fields have not been programmed in nonvolatile

> storage. The default values are used. The Switch NID is used only in the following SB ELS frames: Request Node Identification Data (RNID) and Registered Link Incident Record (RLIR). The use of SB-

3 link incident registration and reporting is typically limited to FICON environments.

No action is required if SB-3 link incident registration and reporting is not used by the host or if default Recommended Action

values are desired for the switch node descriptor fields.

MFIC-1003

Message Effective Insistent domain ID for the fabric changed from <state> to <state>.

LOG Message Type

> WARNING Severity

Probable Cause Indicates that one or more switches joined the fabric with an insistent domain ID (IDID) mode setting

that is different from the current effective IDID mode for the fabric. This message also occurs when the

IDID for the fabric has been turned on or off. The possible values for the state are "On" and "Off".

Recommended IDID mode is a fabric-wide mode; make sure that any switches added to the fabric are configured with Action the same IDID mode as the fabric. If you are enabling or disabling IDID mode, this message is for

information purposes only, and no action is required. IDID mode can be set using the configure command in the CLI or checking the Advanced Web Tools Switch Admin > Configure > Fabric >

Insistent Domain ID Mode check box. The switch must be disabled to change the IDID mode.

6.71 MM Messages

MM-1001

Message VPD block 0 CRC is bad.

Message Type LOG

Severity WARNING

Probable Cause Indicates that CRC in the VPD block 0 is bad. This could indicate corruption or tampering.

This message occurs only on the Brocade 6547 switch.

Recommended Execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the

Action supportSave command and contact your switch service provider.

6.72 MPTH Messages

MPTH-1003

Message No minimum cost path in candidate list.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the fabric shortest path first (FSPF) module has determined that there is no minimum

cost path (MPATH) available in the candidate list.

6.73 MQ Messages

MQ-1004

Message mqRead, queue = <queue name>, queue ID = <queue ID>, type = <message type>.

Message Type LOG

Severity ERROR

Probable Cause Indicates an unexpected message has been received in the specified message queue. The *queue*

name value is always fspf q. The queue ID and message type values can be any of the following:

■ 2 - MSG_TX

■ 3 - MSG INTR

4 - MSG_STR

- 6 MSG_ASYNC_IU
- 7 MSG_LINIT_IU
- 8 MSG_RSCN
- 9 MSG_IOCTL
- 10 MSG_ACCEPT
- 11 MSG_IU_FREE
- 12 MSG_US
- 13 MSG_EXT_RSCN
- 14 MSG_RDTS_START
- 15 MSG_RDTS_SENDEFP
- 16 MSG_RDTS_RESET

MQ-1005

Message queue <queue name>: queue full (miss=<miss count>).

Message Type LOG | FFDC

Severity WARNING

Probable Cause Indicates that the specified message queue is full.

MQ-1006

Message queue <queue name>: msg too long (<number of bytes>:<message queue size>).

Message Type LOG

Severity WARNING

Probable Cause Indicates the incoming message size is larger than the message queue size.

MQ-1007

Message queue <queue name>: queue full (miss=<miss count>).

Message Type LOG | FFDC

Severity WARNING

Probable Cause Indicates that the specified message queue is full.

6.74 MS Messages

MS-1001

Message MS Platform Segmented port=<port number> (0x<port number (hex)>) (<reason for

segmentation> <domain> (0x<domain (hex)>)).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Management Server (MS) has segmented from another switch domain at the

specified port because of errors or inconsistencies defined in the MS platform service.

Recommended Reboot or power cycle the switch.

Action

MS-1002

Message MS Platform Service Unstable (<message string><domain number>).

Message Type LOG

Severity INFO

Probable Cause

Indicates that the Management Server (MS) platform service is unstable.

The message string value can be one of the following:

- No Resp for GCAP from: The switch did not respond to a request for a GCAP (MS Get Capabilities) command.
- GCAP sup but not PL by: GCAP is supported but the flag for MS platform service is not set.
- GCAP Rejected (reason =BUSY) by: GCAP is not supported by another switch.
- Reject EXGPLDB from: The request to the exchange platform database was rejected. The remote switch may be busy.

The *domain number* is the target domain that caused the error.

Recommended Action

The recommended actions are as follows:

- No Resp for GCAP from: No action is required.
- GCAP sup but not PL by: Set the flag for the MS platform service.
 - GCAP Rejected (reason =BUSY) by: Execute the **firmwareDownload** command to upgrade the firmware level on the switch to a level that supports reliable commit service (RCS).
- Reject EXGPLDB from: Wait a few minutes and try the command again.

MS-1003

Message MS detected Unstable Fabric (<message string><domain number>).

Message Type LOG

Severity INFO

Probable Cause

Indicates that the Management Server (MS) detected an unstable fabric; the command or operation may not be successfully completed. This message is often transitory.

The message string value can be one of the following:

- DOMAIN_INVALID for a req from: The domain is invalid for a request.
- No WWN for: Unable to acquire the World Wide Name (WWN) for the corresponding domain.

The domain number is the target domain that caused error.

Recommended Action

The fabric may be reconfiguring, forming, or merging. Wait a few minutes and try the operation again.

Execute the fabricShow command or the secFabricShow command to verify that the number of domains matches the Management Server known domains.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the supportSave command and contact your switch service provider.

MS-1004

Message MS detected ONLY 1 Domain(d=<domain in local resource>).

Message Type LOG

> INFO Severity

Probable Cause

Indicates that the Management Server (MS) detected an unstable count of domains in its own local resource. This message is often transitory.

Recommended

Action

The fabric may be reconfiguring, forming, or merging. Wait a few minutes and try the operation again.

Execute the fabricShow command or the secFabricShow command to verify that the number of domains matches the Management Server known domains.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

MS-1005

Message MS Invalid CT Response from d=<domain>.

Message Type LOG

> Severity **ERROR**

Probable Cause

Indicates that the Management Server (MS) received an invalid common transport (CT) response from the switch domain. MS expects either a CT accept IU or a reject IU; the MS received neither response, which violates the Fibre Channel - Generic Services (FS-GS) specification.

Recommended Action Check the integrity of the FC switch at the specified domain. It is not sending correct MS information as defined by the Fibre Channel - Framing and Signaling (FC-FS) standard.

MS-1006

Message MS Unexpected iu data sz=<number of bytes>.

LOG Message Type

> Severity **ERROR**

Probable Cause

Indicates that the Management Server (MS) received an information unit (IU) data of unexpected size. The IU payload and the IU size may be inconsistent with each other or with the command that is currently being processed.

Recommended Action Wait a few minutes and try the operation again.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

MS-1008

Message MS Failure while initializing <action>.

Message Type LOG

Severity ERROR

Probable Cause

Indicates that the Management Server (MS) failed while initializing the specified action. This message is often transitory.

The action can be one of the following:

- while writing to ms_els_q: MS is unable to write a message to the MS Extended Link Service Queue.
- while inserting timer to timer list: MS is unable to add a timer to a resource.

Recommended Action

If the error persists, check the available memory on the switch using the **memShow** command.

MS-1009

Message

RLIR event. Slot/Port <slot number>/<port number> (0x<PID (hex)>). Device Port Tag is 0x<port tag>. <message text>.

Message Type LOG

Severity ERROR

Probable Cause

Indicates a registered link incident record (RLIR) has been generated for one of the actions indicated by the *message* value.

The *message* value can be one of the following:

- Exceeded bit error rate threshold
- Loss of signal or synchronization
- Not operational seq recognized
- Primitive sequence timeout
- Unrecognized link incident

Recommended Action Persistent RLIR incidents are likely the result of SAN hardware problems such as bad cables or small form-factor pluggable (SFP) transceivers. If the message persists, replace hardware.

MS-1021

Message MS WARMBOOT failure (<failure reason><failure reason code>).

Message Type LOG

Severity ERROR

Probable Cause Indicates that the Fabric OS state synchronization (FSS) warm recovery failed during the WARM INIT

phase of a reboot.

Recommended If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the supportSave command and contact your switch service provider.

MS-1022

Message Management Server Platform Service <Activated or Deactivated>.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the Management Server (MS) platform service is being activated or deactivated.

MS-1023

Message Management Server Topology Discovery Service < Enabled or Disabled>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the Management Server (MS) topology discovery service is being enabled or disabled.

MS-1024

Message Management Server Access Control List is Updated.

Message Type LOG

Severity INFO

Probable Cause Indicates that the Management Server (MS) Access Control List (ACL) is saved to nonvolatile storage.

MS-1025

Message Possible Failover could have occurred while enabling MS Platform Service.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a failover occurred when Management Server (MS) platform service was being enabled.

This can leave the fabric in an inconsistent state.

Recommended

Action

If any inconsistency in MS platform service exists within the fabric, enable MS platform service.

MS-1026

Message MS Platform disabled port <port number> domain <domain> to block enabling Platform

service through merge operation.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Management Server (MS) has disabled the specified E_Port connected to the

specified domain because an implicit enable operation of the MS platform service has been blocked.

Recommended

Action

Enable MS platform service on the switch and re-enable the port to join the fabric.

MS-1027

Message Fabric Name - <fabric name> configured.

Message Type AUDIT | LOG

Class FABRIC

Severity INFO

Probable Cause Indicates that the specified fabric name is configured or renamed.

MS-1028

Message Fabric Name - <fabric name> Cleared.

Message Type AUDIT | LOG

Class FABRIC

Severity INFO

Probable Cause Indicates that the specified fabric name is cleared.

MS-1029

Message Duplicate Fabric Name - <fabric_name> matching with FID <Fabric ID>.

Message Type AUDIT | LOG

Class FABRIC

Severity ERROR

Probable Cause Indicates that the configured fabric name is already used for another partition.

Recommended Select a different fabric name and reconfigure.

Action

MS-1030

Message Fabric Name - <fabric_name> <cmd> Failed for domain <domain>.

Message Type AUDIT | LOG

Class FABRIC

Severity ERROR

Probable Cause Indicates that fabric name configure or clear operation failed in Fibre Channel Router (FCR).

Recommended Wait for fabric to stabilize and retry the operation.

Action

MS-1031

Message Device 0x<device pid> queries QSA in a non FICON logical switch with HIF mode enabled.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a FICON channel or device tries to login to non FICON LS with HIF mode enabled.

Recommended If a FICON channel or device has to login, the logical switch should be converted to a FICON LS or the

Action port should be moved to a FICON Logical Switch.

6.75 MSTP Messages

MSTP-1001

Message <message>: <message>.

Message Type LOG

ERROR Severity

Probable Cause Indicates that the system has failed to allocate memory.

Recommended Check the memory usage on the switch using the **memShow** command.

Action Restart or power cycle the switch.

MSTP-1002

Message <message>: <message>.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates that the system has failed to initialize.

Recommended Restart or power cycle the switch.

Action

MSTP-1003

Message <message>: <message>.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates a connection, transfer, or receiving error in the socket.

Recommended If this is a bladed switch, execute the haFailover command. If the problem persists or if this is a non-Action

bladed switch, download a new firmware version using the firmwareDownload command.

MSTP-2001

Message <message>.

Message Type LOG

> Severity **INFO**

Probable Cause Indicates that the multiple spanning tree protocol (MSTP) bridge mode has changed.

MSTP-2002

Message <Bridge mode information>. My Bridge ID: <Bridge ID> Old Root: <Old Root ID> New Root:

<New Root ID>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the multiple spanning tree protocol (MSTP) bridge or bridge instance root has been

changed.

MSTP-2003

Message MSTP instance <instance > is created.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified multiple spanning tree protocol (MSTP) instance has been created.

MSTP-2004

Message MSTP instance <instance> is deleted.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified multiple spanning tree protocol (MSTP) instance has been deleted.

MSTP-2005

Message VLAN <vlan ids> is <action> on MSTP instance <instance>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified multiple spanning tree protocol (MSTP) instance has been modified.

MSTP-2006

Message MSTP instance <instance> bridge priority is changed from <pri>priority old> to

<priority_new>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified multiple spanning tree protocol (MSTP) instance priority has been

modified.

6.76 NBFS Messages

NBFS-1001

Message Duplicate E_Port SCN from port <portnumber> in state <state change name> (<state

change number>).

Message Type LOG

Severity INFO

Probable Cause

Indicates a duplicate E_Port state change notification (SCN) was reported. The neighbor finite state machine (NBFSM) states are as follows:

- 0 Down
- 1 Init
- 2 Database Exchange
- 3 Database Acknowledge Wait
- 4 Database Wait
- 5 Full

NBFS-1002

Message Wrong input: <state name> to neighbor FSM, state <current state name>, port

<portnumber>.

Message Type FFDC | LOG

Severity ERROR

Probable Cause

Indicates the wrong input was sent to the neighbor finite state machine (NBFSM). NBFSM states are as follows:

- 0 Down
- 1 Init
- 2 Database Exchange
- 3 Database Acknowledge Wait
- 4 Database Wait
- 5 Full

If this error occurs repeatedly, then there is a problem in the protocol implementation between two switches.

Recommended Action

Run the **nbrStateShow** command to check the neighbor state of the port listed in the message. If it is Full, then this message can safely be ignored. Otherwise, run the **portDisable** and **portEnable** commands to refresh the port.

NBFS-1003

Message Type LOG

Severity WARNING

Probable Cause

Indicates the database transmit set flag was not set for the specified input state on the specified port. Neighbor finite state machine (NBFSM) states are as follows:

- 0 Down
- 1 Init
- 2 Database Exchange
- 3 Database Acknowledge Wait
- 4 Database Wait
- 5 Full

Recommended Action

No action is required. The Fabric OS automatically recovers from this problem.

NBFS-1004

Message Type LOG

Severity INFO

Probable Cause

Indicates the wrong input was sent to the neighbor finite state machine (NBFSM). NBFSM states are as follows:

- 0 Down
- 1 Init
- 2 Database Exchange
- 3 Database Acknowledge Wait
- 4 Database Wait
- 5 Full

If this error occurs repeatedly, then there is a problem in the protocol implementation between two switches.

Recommended Action

Run the **nbrStateShow** command to check the neighbor state of the port listed in the message. If it is Full, then this message can safely be ignored. Otherwise, run the **portDisable** and **portEnable** commands to refresh the port.

NBFS-1005

Message FSPF experiencing link issues on port <port string> in state <current state name> (<state change number>).

Message Type LOG

Severity INFO

Probable Cause

Indicates that FSPF is experiencing issues with frames on the link leading to unexpected inputs being sent to the neighbor finite state machine (NBFSM). NBFSM states are as follows:

- 0 Down
- 1 Init
- 2 Database Exchange
- 3 Database Acknowledge Wait
- 4 Database Wait
- 5 Full

If this error occurs repeatedly, then there is a problem running the FSPF exchange and synchronization protocol between two switches across the identified link.

Recommended Action

Run the nbrStateShow command to check the neighbor state of the port listed in the message. If it is Full, then this message can safely be ignored. Otherwise, please check the portStatsShow command to see if there are errors on the link. If there are errors, consider running the D-Port Diagnostics tests on the link and/or consider replacing and faulty or bad equipment such as cables or optics.

NBFS-1006

Message The FSPF Dead Timer for port <port string> expired, connected to domain <domain ID of neighbor as of last HLO message>.

Message Type LOG

Action

WARNING Severity

Probable Cause Indicates that FSPF is experiencing issues receiving HLO frames on the link, causing the link's dead

timer to expire and the link's neighbor finite state machine (NBFSM) to drop out of the Full state.

Recommended Please ensure that both neighboring switches of the link are operating normally.

> If either switch has crashed, been rebooted, or delayed after an HA operation, ensure the switch and link return to a fully functional state so that traffic may resume.

> Check the portStatsShow and portErrShow commands to see if there were errors on the link. Use the nbrStateShow and interfaceShow commands to see the current state of the neighbor finite state machine (NBFSM) for the link.

6.77 NS Messages

NS-1001

Message The response for request 0x<CT command code> from remote switch 0x<Domain Id> is

larger than the max frame size the remote switch can support.

Message Type LOG

> Severity **WARNING**

Probable Cause Indicates that the response payload exceeds the maximum frame size the remote switch can handle.

Recommended Execute the firmwareDownload command to upgrade the remote switch with Fabric OS v4.3 or later. Action or Fabric OS v3.2 or later, as appropriate for the switch type, so that it can support GMI to handle

frame fragmentation and reassembly.

You can also reduce the number of devices connected to the local switch.

NS-1002

Message Remote switch 0x<Domain Id> has firmware revision lower than 2.2: <Firmware Revision

> 1st character><Firmware Revision 2nd character><Firmware Revision 3rd character><Firmware Revision 4th character> which is not supported.

LOG Message Type

> Severity **WARNING**

Probable Cause Indicates that the local switch cannot interact with the remote switch because of incompatible or

obsolete firmware.

Execute the firmwareDownload command to upgrade the remote switch to the latest level of Recommended

Action firmware.

NS-1003

Message Number of local devices <Current local device count>, exceeds the standby can support

<Local device count that standby can support>, can't send update.

Message Type LOG

> **INFO** Severity

Probable Cause Indicates that the Name Server on the standby control processor (CP) has a lower supported capability

than the active CP because of different firmware versions running on the active and standby CPs. This

means that the active and standby CPs are out of sync. Any execution of the haFailover or

firmwareDownload commands will be disruptive.

Recommended

To avoid disruption of traffic in the event of an unplanned failover, schedule a firmware download so Action

that the active and standby CPs have the same firmware version.

Reduce the local device count to follow the capability of the earliest version of firmware.

NS-1004

Message Number of local devices <Current local device count>, exceeds the standby can support

<Local device count that standby can support>, can't sync.

Message Type LOG

> Severity INFO

Probable Cause Indicates that the Name Server on the standby control processor (CP) has a lower supported capability

than the active CP because of different firmware versions running on the active and standby CPs. This

means that the active and standby CPs are out of sync. Any execution of the haFailover or firmwareDownload commands will be disruptive.

Recommended To avoid disruption of traffic in the event of an unplanned failover, schedule a firmware download so

Action that the active and standby CPs have the same firmware version.

Reduce the local device count to follow the capability of the earliest version of firmware.

NS-1005

Message Zone size of <Effective Zone Size> has over the supporting limit of <Support Zone

Size> for the remote switch domain ID <Remote Switch Domain ID>.

Message Type LOG

Severity WARNING

Probable Cause Indicates the effective zone size has exceeded the limit that a remote switch can support. The

oversized portion will be truncated.

Recommended Reduce the zone size to 1024 or smaller, or upgrade the software of the remote switch to support 2048

Action zones.

NS-1006

Message Duplicate WWN was detected with PID 0x<existing device PID> and 0x<new device PID>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that an existing device has the same World Wide Name (WWN) as that of a new device that

has come online.

Recommended

Action

The switch will process the new process ID (PID) and leave the existing PID intact. Subsequent switch

operations will clean up the obsolete PID. However, it is recommended that administrators remove

devices with a duplicate WWN.

NS-1007

Message NS has detected a logical ISL port <LISL port number> in TI zone <TI zone name> in

fabric <Fabric ID>. Routing may not be setup correctly.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a logical inter-switch link (LISL) is detected in a traffic isolation (TI) zone.

Recommended Remove the LISL port from the TI zone because the routing may not be set up correctly.

Action

NS-1008

Message Open FR license not installed.

Message Type LOG

Severity WARNING

Probable Cause Indicates that Open FR license is not installed and therefore local devices involved in Open FR will not

function.

Recommended

Install the Open FR license or relocate Open FR devices to a licensed switch.

NS-1009

Message NS has detected a device with Node WWN as zero, pid 0x<device PID>.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that a device has logged in with node World Wide Node Name (WWNN) as zero. Brocade

Network Advisor (BNA) will not show the port connectivity.

Recommended

Action

Check the device that logged in. The device could be faulty.

NS-1010

Message CSCTL mode enabled on port <csctlport> QoS zoning will be ignored for devices on this

port.

Message Type LOG

Severity WARNING

Probable Cause Indicates that class-specific control (CS CTL) mode has been enabled on the specified port that has

devices as members of a quality of service (QoS) zone.

Recommended Remove the CS_CTL configured devices from the QoS zone.

Action

NS-1011

Message NS has detected a failover flag disabled TI zone in a base switch <Domain Id> in

fabric ID <Fabric ID>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a failover-disabled traffic isolation (TI) zone has been detected in a base switch fabric.

Recommended

Enable the failover flag or remove the TI zone with the disabled failover flag because the routing may not be set up correctly.

NS-1012

Message Detected duplicate WWPN [<WWPN>] - devices removed with PID 0x<existing device PID>

and 0x<new device PID>.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that the devices with the same World Wide Port Name (WWPN) have been removed from

the Name Server database.

Recommended Verify the device reported with duplicate WWPN.

Action

NS-1013

Message SIM PORT with WWPN[<WWPN>] creating duplicate condition with PID 0x<duplicate device

PID>. Removed PID 0x<disabled device PID> and disabled port <disabled Port>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the SIM port that is causing the duplicate condition has been removed from the Name

Server database and the port is disabled.

Recommended Verify the device reported with duplicate World Wide Port Name (WWPN) and re-enable the port if

Action necessary.

NS-1014

Message Domain Capability is not available for domain <Domain>. Rejoin this domain to the

fabric. Reason Code <Reason Code>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that domain capability is unavailable for the specified domain.

Recommended Remove and rejoin the specified domain to the fabric.

Action

NS-1015

Message Failed to update client capability to ESS (Exchange Switch Support) after maximum

number of retries - return code <Failed return code>. Failing sync dump to standby CP.

Message Type LOG

Severity INFO

Probable Cause Indicates that Exchange Switch Support (ESS) is unable to update its capability. Failed to send the

sync dump to standby control processor (CP).

Recommended Verify that HA synchronization has failed using the **haShow** command. If HA synchronization has

failed, execute the haSyncStart command on active CP to resynchronize the HA state.

NS-1016

Message Device <PID of quarantined device> has been quarantined. Standby CP does not support

this feature, cannot send update.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the Name Server on the standby control processor (CP) has a lower supported capability

than the active CP because of different firmware versions running on the active and standby CPs. This

means that the active and standby CPs are out of sync. Any execution of the haFailover or

firmwareDownload commands will be disruptive.

Recommended To avoid disruption of traffic in the event of an unplanned failover, schedule a firmware download so

Action that the active and standby CPs have the same firmware version

that the active and standby CPs have the same firmware version.

Reduce the local device count to follow the capability of the earliest version of firmware.

NS-1017

Message <Local or Remote> Domain <Domain ID of slow drain device>, Port index <User Port Index

of slow drain device>, All devices zoned with the slow drain device 0x<PID of slow

drain device> have been quarantined.

Message Type LOG

Severity INFO

Probable Cause Indicates that all the devices that are zoned with the slow drain device have been quarantined.

Recommended To check all affected devices zoned to the slow drain device please use the CLI nszonemember.

Action

NS-1018

Message <Local or Remote> Domain <Domain ID of slow drain device>, Port index <User Port Index

of slow drain device>, All devices zoned with the slow drain device 0x<PID of slow

drain device> have been unquarantined.

Message Type LOG

Severity INFO

Probable Cause Indicates that all the devices that are zoned with the slow drain device have been unquarantined.

Recommended To check all affected devices zoned to the slow drain device please use the CLI nszonemember.

Action

NS-1019

Message Traffic Isolation Zone with 64 character name - standby CP does not have support with

down-level firmware version.

Message Type LOG

Severity WARNING

Probable Cause Traffic Isolation Zone with 64 character name - standby control processor (CP) does not have support

with down-level firmware version.

Recommended Upgrade standby CP to supported firmware version or rename the TI zone with less than 64

Action characters.

NS-1020

Message <AG-connected or Remote or Local> device 0x<PID of registered slow drain device>

registered as Slow Drain is not enforced due to zoned port limit exceeded.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the AG-connected or Remote / Local device flagged for Severe Latency / Frame Loss

could not be quarantined due to the zoned port count more than 32.

Recommended Requires manual intervention to correct the slow drain condition.

Action

NS-1021

Message Local Domain Comain ID of slow drain device>, Port index <User Port Index of slow

drain device>, unzoned device 0x<PID of slow drain device> has been <quarantined or

unquarantined>.

Message Type LOG

Severity INFO

Probable Cause Indicates that unzoned local device have been imarked as quarantined or unquarantined.

Recommended Action To check all affected devices zoned to the slow drain device please use the CLI nszonemember.

NS-1022

Message

CSCTL mode enabled for port index <Port Index of the device zoned with slow drain device>, flow to device 0x<PID of slow drain device> cannot be quarantined.

Message Type

LOG

Severity

WARNING

Probable Cause

Indicates that CSCTL mode is enabled so cannot be guarantined.

Recommended

Action

To check all affected devices zoned to the slow drain device please use the CLI nszonemember.

NS-1023

Message

Request for <request type> flow from device 0x<PID of device from which the flow is quarantined> to quarantined device 0x<PID of slow drain device> of <Local or Remote> domain <Domain ID of slow drain device> is not successful.

Message Type

LOG

Severity

WARNING

Probable Cause

Indicates that quarantine / unquarantine request fail.

Recommended

Action

To check all affected devices zoned to the slow drain device please use the CLI nszonemember.

NS-1024

Message

Flow from device 0x<PID of device from which the flow is quarantined> to quarantined device 0x<PID of slow drain device> of <Local or Remote> domain <Domain ID of slow drain device> has been successfully quarantined.

Message Type

LOG

Severity

INFO

Probable Cause

Indicates that the device that is zoned with the slow drain device have been quarantined.

Recommended

Action

To check all affected devices zoned to the slow drain device please use the CLI nszonemember.

NS-1025

Message

Flow from device 0x<PID of device from which the flow is quarantined to quarantined device 0x<PID of slow drain device> of <Local or Remote> domain <Domain ID of slow

drain device> has been successfully unquarantined.

Message Type LOG

Severity INFO

Probable Cause Indicates that the device that is zoned with the slow drain device have been unquarantined.

Recommended To check all affected devices zoned to the slow drain device please use the CLI nszonemember.

Action

NS-1026

Message <Local or Remote > domain <Domain ID of slow drain device >, port index <User Port Index

of slow drain device>: A zoned device 0x<PID of slow drain device> has been

quarantined.

Message Type LOG

Severity INFO

Probable Cause Indicates that A zoned device has been marked as a slow drain device.

Recommended To check all affected devices zoned to the slow drain device please use the CLI nszonemember.

Action

NS-1027

Message <Local or Remote> domain <Domain ID of slow drain device>, port index <User Port Index

of slow drain device>: A zoned quarantined device 0x<PID of slow drain device> has

been unquarantined.

Message Type LOG

Severity INFO

Probable Cause Indicates that a zoned slow drain device has been unquarantined.

Recommended To check all affected devices zoned to the slow drain device please use the CLI nszonemember.

Action

6.78 NSM Messages

NSM-1001

Message Interface <InterfaceName> is online.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified interface has come online after the protocol dependencies are resolved.

NSM-1002

Message Interface <InterfaceName> is protocol down.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified interface has gone offline because one of the protocol dependencies is

unresolved.

Recommended Check for the reason codes using the **show interface** command and resolve the protocol dependencies.

The following are the possible reason codes:

Admin down

- Link protocol down
- DOT1x authenticating
- Minimum member links not UP (applicable only for port-channel interfaces)
- DOT1x authentication failed
- BRCD remote link negotiation failed/LLDP disabled
- LAG negotiating/failed
- LAG admin state is down
- UNKNOWN

NSM-1003

Message Interface <InterfaceName> is link down.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified interface has gone offline because the link is down.

Recommended Check whether the connectivity between the peer ports is proper, and the remote link is up using the

Action show interface command.

NSM-1004

Message Interface <InterfaceName> is created.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified logical interface has been created.

NSM-1005

Message The FCoE VLAN: <VlanName> is in use. Therefore, cannot disable the FCoE VLAN.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified Fibre Channel over Ethernet (FCoE) VLAN is used in the FCoE daemon

(fcoed) and therefore cannot be disabled.

Recommended Remove all the FCoE sessions from the FCoE VLAN member ports and then disable the FCoE VLAN.

Action

NSM-1006

Message FCoE on VLAN: <VlanName> has been disabled successfully.

Message Type LOG

Severity INFO

Probable Cause Indicates that FCoE has been disabled on the specified VLAN.

NSM-1007

Message Chassis is <status>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the chassis has been enabled or disabled.

NSM-1008

Message Blade (<slot number>) is <status>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified blade has been enabled or disabled.

NSM-1009

Message Interface <InterfaceName> is deleted.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified logical interface has been deleted.

NSM-1010

Message InterfaceMode changed from <Mode old> to <Mode new> for interface <InterfaceName>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the interface mode has been changed.

NSM-1011

Message OperationalEndpointMode changed from <Mode_old> to <Mode_new> for interface

<InterfaceName>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the interface operational endpoint mode has been changed.

NSM-1012

Message VLAN classifier group <group id> is created.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified VLAN classifier group has been created.

NSM-1013

Message VLAN classifier group <group id> is deleted.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified VLAN classifier group has been deleted.

NSM-1014

Message VLAN classifier rule <rule_id> is created.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified VLAN classifier rule has been created.

NSM-1015

Message VLAN classifier rule <rule id> is deleted.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified VLAN classifier rule has been deleted.

NSM-1016

Message VLAN classifier rule <rule_id> is <action> on VLAN classifier group <group_id>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified VLAN classifier group has been modified.

NSM-1017

Message Interface <InterfaceName> is <action> on interface <Logical InterfaceName>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the logical interface member list has been changed.

NSM-1018

Message <count> VLANs <except> will be allowed on interface <Logical InterfaceName>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the VLAN membership has been changed for the specified interface.

NSM-1019

Message Interface <InterfaceName> is administratively up.

Message Type LOG

Severity INFO

Probable Cause Indicates that the administrative status of the specified interface has changed to up.

NSM-1020

Message Interface <InterfaceName> is administratively down.

Message Type LOG

Severity INFO

Probable Cause Indicates that the administrative status of the specified interface has changed to down.

6.79 ONMD Messages

ONMD-1000

Message LLDP is enabled.

Message Type LOG

Severity INFO

Probable Cause Indicates that the link layer discovery protocol (LLDP) is enabled globally.

ONMD-1001

Message LLDP is disabled.

Message Type LOG

Severity INFO

Probable Cause Indicates that the link layer discovery protocol (LLDP) is disabled globally.

ONMD-1002

Message LLDP global configuration is changed.

Message Type LOG

Severity INFO

Probable Cause Indicates that the link layer discovery protocol (LLDP) global configuration has been changed.

ONMD-1003

Message LLDP is enabled on interface <InterfaceName>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the link layer discovery protocol (LLDP) is enabled on the specified interface.

ONMD-1004

Message LLDP is disabled on interface <InterfaceName>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the link layer discovery protocol (LLDP) is disabled on the specified interface.

ONMD-1005

Message Using auto-sense on interface <InterfaceName> to update DCBX version.

Message Type LOG

Severity INFO

Probable Cause Indicates that the auto-sense feature is used to detect the Data Center Bridging eXchange (DCBX)

version on the specified interface. The DCBX version field will be automatically updated between the

Converged Enhanced Ethernet (CEE) version and the pre-CEE version depending on the link

neighbor.

6.80 PDM Messages

PDM-1001

Message Failed to parse the pdm config.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Parity Data Manager (PDM) process could not parse the configuration file. This may

be caused by a missing configuration file during the installation.

Recommended Execute the **firmwareDownload** command to reinstall the firmware.

Action

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

PDM-1002

Message ipcInit failed.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Parity Data Manager (PDM) process could not initialize the inter-process

communication (IPC) mechanism.

Recommended If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

PDM-1003

Message pdm [-d] -S <service> -s <instance>.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that a syntax error occurred when trying to launch the Parity Data Manager (PDM) process.

Recommended Execute the **firmwareDownload** command to reinstall the firmware.

Action

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

PDM-1004

Message PDM memory shortage.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Parity Data Manager (PDM) process ran out of memory.

Recommended Reboot or power cycle the switch.

Action If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the supportSave command and contact your switch service provider.

PDM-1005

Message FSS register failed.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Parity Data Manager (PDM) failed to register with the Fabric OS synchronization

service (FSS).

Recommended Execute the **firmwareDownload** command to reinstall the firmware.

Action ____

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

PDM-1006

Message Too many files in sync.conf.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the sync.conf configuration file contains too many entries.

Recommended Execute the **firmwareDownload** command to reinstall the firmware.

Action

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the supportSave command and contact your switch service provider.

PDM-1007

Message File not created: <file name>. errno=<errno>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Parity Data Manager (PDM) process failed to create the specified file.

Recommended

Execute the **firmwareDownload** command to reinstall the firmware.

Action

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

PDM-1008

Message Failed to get the number of U Ports.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that the Parity Data Manager (PDM) system call to getCfg failed.

Recommended Execute the **firmwareDownload** command to reinstall the firmware.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

PDM-1009

Message Can't update Port Config Data.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that the Parity Data Manager (PDM) system call to setCfg failed.

Recommended Execute the **firmwareDownload** command to reinstall the firmware.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the supportSave command and contact your switch service provider.

PDM-1010

Message File open failed: <file name>, errno=<errno>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Parity Data Manager (PDM) process could not open the specified file.

Recommended Execute the **firmwareDownload** command to reinstall the firmware.

Action If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

PDM-1011

Message File read failed: <file name>, Length(read=<Number of character read>,

expected=<Number of characters expected>), errno=<errno returned by read>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Parity Data Manager (PDM) process could not read data from the specified file.

Recommended Execute the **firmwareDownload** command to reinstall the firmware.

Action

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

PDM-1012

Message File write failed: <file name>. Length(read=<Number of character read>, write=<Number

of characters written>), errno=<errno returned by write>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Parity Data Manager (PDM) process could not write data to the specified file.

Recommended Execute the **firmwareDownload** command to reinstall the firmware.

Action

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

PDM-1013

Message File empty: <File Name>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the switch configuration file /etc/fabos/fabos.[0]1].conf is empty.

Recommended Execute the **firmwareDownload** command to reinstall the firmware.

Action

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

PDM-1014

Message Access sysmod failed.

Message Type LOG

Severity WARNING

Probable Cause Indicates a system call to sysMod failed.

Recommended Execute the

Action

Execute the firmwareDownload command to reinstall the firmware.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

PDM-1017

Message System (<Error Code>): <Command>.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the specified system call failed.

Recommended Execute the **firmwareDownload** command to reinstall the firmware.

Action

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

PDM-1019

Message File path or trigger too long.

Message Type LOG

Severity WARNING

Probable Cause Indicates that one line of the pdm.conf file is too long.

Recommended Execute the **firmwareDownload** command to reinstall the firmware.

Action

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the supportSave command and contact your switch service provider.

PDM-1020

Message Long path name (<Path>/<File Name>), Skip.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified file path name is too long. The maximum character limit is 49 characters.

Recommended Use path names not exceeding 49 characters in length for the files to be replicated.

Action

PDM-1021

Message Failed to download area port map.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a system call failed.

Recommended Execute the **firmwareDownload** command to reinstall the firmware.

Action

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

PDM-1022

Message The switch is configured only with IPv6 addresses.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Parity Data Manager (PDM) cannot synchronize with its peer because the firmware

does not support IPv6.

Recommended Configure the local switch with IPv4 addresses.

Action

PDM-1023

Message RADIUS is configured with IPv6 addresses.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Parity Data Manager (PDM) cannot synchronize with its peer because the remote

access dial-in user server (RADIUS) is configured with IPv6 addresses. IPv6 is not supported by older

firmware.

Recommended Configure RADIUS with IPv4 addresses.

Action

PDM-1024

Message DNS is configured with IPv6 addresses.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Parity Data Manager (PDM) cannot synchronize with its peer because the Domain

Name Service (DNS) is configured with IPv6 addresses. IPv6 is not supported by older firmware.

Recommended Con Action

Configure DNS with IPv4 addresses.

PDM-1025

Message LDAP is configured with IPv6 addresses.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Parity Data Manager (PDM) cannot synchronize with its peer because the

Lightweight Directory Access Protocol (LDAP) server is configured with IPv6 addresses. IPv6 is not

supported by older firmware.

Recommended

Action

Configure the LDAP server with IPv4 addresses.

PDM-1026

Message User defined roles configured.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Parity Data Manager (PDM) cannot synchronize with its peer because the user-

defined roles are configured. User-defined roles are not supported by older firmware.

Recommended

Action

Remove user-defined roles configuration.

PDM-1027

Message Invalid port number: <port number> read from str: <str>

Message Type LOG

Severity WARNING

Probable Cause Indicates that the port number read from str is out of bounds.

Recommended Continue with the next port number. Skip invalid port number before accessing list with port number as

Action index.

PDM-1028

Message Port cfg: b4[0] = 0x < first word >, b4[1] = 0x < second word >, b4[2] = 0x < third word >,

b4[3] = 0x < fourth word >

Message Type LOG

Severity WARNING

Probable Cause Indicates that the port number read from str is out of bounds.

Recommended Continue with the next port number. Skip invalid port number before accessing list with port number as

Action index.

6.81 PDTR Messages

PDTR-1001

Message <informational message>.

Message Type LOG

Severity INFO

Probable Cause

Indicates that information has been written to the panic dump files. The watchdog register codes are as follows:

- 0x10000000 The watchdog timer (WDT) forced a core reset.
- 0x20000000 The WDT forced a chip reset.
- All other code values are reserved.

Recommended

Action

Run the **pdShow** command to view the panic dump and core dump files.

PDTR-1002

Message <informational message>.

Message Type LOG

Severity INFO

Probable Cause

Indicates that information has been written to the panic dump and core dump files and a trap has been generated. The watchdog register codes are as follows:

- 0x10000000 The watchdog timer (WDT) forced a core reset.
- 0x20000000 The WDT forced a chip reset.
- All other code values are reserved.

Recommended Action Run the **pdShow** command to view the panic dump and core dump files.

6.82 PLAT Messages

PLAT-1000

Message <Function name> <Error string>.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that nonrecoverable peripheral component interconnect (PCI) errors have been detected.

Recommended The system will be faulted and may automatically reboot.

Action

If the system does not reboot automatically, reboot the system manually using the **reboot** command.

Execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the

supportSave command and contact your switch service provider.

PLAT-1001

Message CP<Identifies which CP (0 or 1) is doing the reset> resetting other CP (double reset

may occur).

Message Type LOG

Severity INFO

Probable Cause Indicates the other control processor (CP) is being reset. This message is typically generated by a CP

that is in the process of becoming the active CP. Note that in certain circumstances a CP may experience a double reset and reboot twice. A CP can recover automatically even if it has rebooted

twice.

PLAT-1002

Message CP<Identifies which CP (0 or 1) is generating the message>: <Error message> CP Fence

0x<CP Fence register. Contents (2 bytes) are platform-specific> 0x<CP Error register. Contents are platform-specific> CP Error 0x<Write control flag. Contents are

platform-specific>.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the control processor (CP) cannot access the inter-integrated circuit (I2C) subsystem

because of an error condition or because of being fenced or isolated from the I2C bus.

Action

Recommended

Reboot the CP if it does not reboot automatically. Reseat the CP if rebooting does not solve the

problem. If the problem persists, replace the CP.

PLAT-1003

Message <Info message> Slot <Blade Slot number> C/BE: 0x<Captured Command/Byte-Enables data>

ADBUS: 0x<Captured AD bus data> misc intr 0x<Bridge reset interrupts>.

Message Type LOG | FFDC

Severity CRITICAL

Probable Cause Indicates that peripheral component interconnect (PCI) bus hang was detected.

Recommended Replace the field-replaceable unit (FRU).

Action

PLAT-1004

Message Active CP has older FPGA rev 0x<Older FPGA version major> <Older FPGA version minor>.

Upgrade to newer FPGA rev 0x<Newer FPGA version major>_<Newer FPGA version minor> .

Message Type LOG | FFDC

Severity CRITICAL

Probable Cause Indicates that Fabric OS has older field-programmable gate array (FPGA) version. This message is

applicable only to Brocade Gen6.

Recommended Upgrade FPGA to new version.

Action

PLAT-1005

Message Incompatible midplane detected. All internal ports will be disabled.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the chassis has the revision 1.0 midplane.

This message occurs only on the Brocade M6505.

Recommended Replace the midplane with a revision 1.1 midplane.

Action

PLAT-1006

Message Unknown midplane revision.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the chassis has a midplane whose revision is unknown.

This message occurs only on the Brocade M6505.

Recommended Install newer firmware in the Chassis Management Controller (CMC).

Action

PLAT-1007

Message BladeSystem Chassis type is unknown, setting maximum internal port speed to 8Gb/s.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Onboard Administrator (OA) could be running an old version of firmware.

If OA firmware is new enough to support Enclosure Information, then OA failed to send the Enclosure

Information soon enough to allow the internal ports to run at 16 GFC.

This message occurs only on the Brocade 6548.

PLAT-1008

Message BladeSystem Enclosure Information arrived late from OA.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Onboard Administrator (OA) failed to send the Enclosure Information soon enough to

allow the internal ports to run at 16 GFC.

This message occurs only on the Brocade 6548.

Recommended Execute the **hareboot** command, followed by the **portdisable** and **portenable** commands to allow

Action internal ports to run at 16 GFC.

PLAT-1009

Message BladeSystem Chassis type requires setting maximum internal port speed to 8Gb/s.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the chassis has an older midplane that cannot support 16 GFC internal ports.

This message occurs only on the Brocade 6548.

Recommended

Install the switch in a newer chassis.

Action

PLAT-1010

Message SPDC HOST Initi failed spdc status 0x<SPDC status register>, rdy0=0x<SPDC target

ready register 0>, rdy1=0x<SPDC target ready register 1> fen=0x<fence register >,

hk_fen=0x<hk_fence register >, ocp=0x<ocp_present register>.

Message Type LOG | FFDC

Severity CRITICAL

Probable Cause Indicates that the Serial Private Data Channel (SPDC) host hardware encountered an unrecoverable

error.

Recommended Upgrade the control processor (CP) to the latest field-programmable gate array (FPGA) version, or

replace the CP blade.

PLAT-1011

Message MAC signature 0x<Signature read> does not match.

Message Type LOG | FFDC

Action

Severity CRITICAL

Probable Cause Indicates that the MAC address cannot be read.

Recommended The WWN card needs to be verified.

Action

PLAT-1072

Message The chassis is disabled because no Core Blades are available. Insert/replace one or

both Core Blades and run chassisenable.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the chassis has been disabled because of the unavailability of the core blades. There

must be at least one core blade in enabled state for the chassis to be considered ready. All core blades are either missing, faulted, or powered off. This results in all logical switches (and ports) being

disabled.

Recommended Make sure that all core blade slots have core blades inserted and their ejector switches are closed.

Action Power on core blades that are powered off, and power cycle or replace the core blades that are

faulted.

Run the chassisenable command to re-enable the ports.

Running the **fastboot** or **reboot** command will also result in enabling the logical switches and ports.

PLAT-1100

Message Loss of AC source input detected on PS <PS number where AC source input loss was

detected >.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified PS detected a loss of AC input.

Recommended Perform an audit of the external AC source.

Action

PLAT-2000

Message Hardware reset cause: first 0x<The first reset reason FPGA register value> - <The

meaning of the first reset reason value>

Message Type LOG

Severity INFO

Probable Cause Indicates the platform-specific source of the control processor (CP) reset. In the case of a rolling

reboot, this value will indicate the platform-specific source of the first reset.

PLAT-2001

Message Hardware reset cause: latest: 0x<The latest reset reason FPGA register value> - <The

meaning of the latest recent reset reason value>

Message Type LOG

Severity INFO

Probable Cause Indicates the platform-specific source of the most recent control processor (CP) reset. In the case of a

rolling reboot, this value will indicate the platform-specific source of the most recent reset.

6.83 PMGR Messages

PMGR-1001

Message Attempt to create switch <FID> succeeded.

Message Type LOG | AUDIT

Class LS

Severity INFO

Probable Cause Indicates that the switch with the specified fabric ID (FID) was successfully created.

PMGR-1002

Message Attempt to create switch <FID> failed. Error message: <Error Message>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the switch with the specified fabric ID (FID) was not created.

Recommended Refer to the *Error Message* string displayed in the message for possible action.

Action

PMGR-1003

Message Attempt to delete switch <FID> succeeded.

Message Type LOG | AUDIT

Class LS

Severity INFO

Probable Cause Indicates that the switch with the specified fabric ID (FID) was successfully deleted.

PMGR-1004

Message Attempt to delete switch <FID> failed. Error message: <Error Message>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the switch with the specified fabric ID (FID) was not deleted.

Recommended Refer to the *Error Message* string displayed in the message for possible action.

Action

PMGR-1005

Message Attempt to move port(s) to switch <FID> succeeded.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates a successful attempt to move the ports to the specified switch.

PMGR-1006

Message Attempt to move port(s) <Ports> on slot <Slot> to switch <FID> failed. Error message:

<Error Message>.

Message Type LOG

Severity WARNING

Probable Cause Indicates an unsuccessful attempt to move the ports to the specified switch.

Recommended Refer to the *Error Message* string displayed in the message for possible action.

Action

PMGR-1007

Message Attempt to change switch <FID> to switch <New FID> succeeded.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates successful change of the switch fabric ID (FID).

PMGR-1008

Message Attempt to change switch <FID> to switch <New FID> failed. Error message: <Error

Message>.

Message Type LOG

Severity WARNING

Probable Cause Indicates a failed attempt to change the switch fabric ID (FID).

Recommended Refer to the *Error Message* string displayed in the message for possible action.

Action

PMGR-1009

Message Attempt to change the base switch to switch <FID> succeeded.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates successful change of the base switch.

PMGR-1010

Message Attempt to change the base switch to switch <FID> failed. Error message: <Error

Message>

Message Type LOG

Severity WARNING

Probable Cause Indicates a failed attempt to change the base switch.

Recommended Refer to the *Error Message* string displayed in the message for possible action.

Action

PMGR-1011

Message Attempt to move port(s) to switch <FID> succeeded.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates a successful attempt to move the ports to the specified switch.

PMGR-1012

Message Attempt to remove the base switch attribute from switch <FID> succeeded.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates successful removal of the base switch.

PMGR-1013

Message Attempt to change the switch <FID> to ficon switch succeeded.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates successful change of switch into a FICON switch.

PMGR-1014

Message Attempt to change the switch <FID> to a ficon switch failed. Error message: <Error

Message>

Message Type LOG

Severity WARNING

Probable Cause Indicates a failed attempt to change a switch to FICON switch.

Recommended Refer to the *Error Message* string displayed in the message for possible action.

Action

6.84 PORT Messages

PORT-1003

Message Port <port number> Faulted because of many Link Failures.

Message Type LOG

Severity WARNING

Probable Cause Indicates the specified port is now disabled because the link on this port had multiple failures that

exceeded an internally set threshold on the port. This problem is typically related to hardware.

Recommended Action Check and replace (if necessary) the hardware attached to both ends of the specified port number, including:

■ The media (SFPs)

The cable (fiber optic or copper inter-switch link (ISL))

The attached devices

After checking the hardware, execute the **portEnable** command to re-enable the port.

PORT-1004

Message Port <port number> (0x<port number (hex)>) could not be enabled because it is disabled

due to long distance.

Message Type LOG

Severity INFO

Probable Cause Indicates the specified port is not enabled because other ports in the same group have used the

buffers for this port group. This happens when other ports were configured to be long distance.

Recommended To enable this port, perform one of the following actions:

Action

■ Reconfigure the other E_Ports so they are not long distance.

Change the other E_Ports so they are not E_Ports.

This will free some buffers and allow this port to be enabled.

PORT-1005

Message Slot <slot number> port <port on slot> does not support configured L Port. Issue

portCfgLport to clear configuration.

Message Type LOG

Severity WARNING

Probable Cause Indicates the specified port is configured to be an L Port, but the port does not support L Port. If an

L_Port is connected, then the port will be disabled because the port does not support L_Port. If an

E_Port or F_Port is connected, then the port will not come up because it is configured to be an L_Port.

Recommended

Action

Execute the **portCfgLport** command to clear the L_Port configuration.

PORT-1006

Message Configuration changed for port (ID: <port number>) in No Module or No Light state.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates the configuration changes were made to an offline port in the No Module or No Light state.

PORT-1007

Message Port (ID: <port number>) has been renamed to (<port name>).

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates a port has been reconfigured with a different name.

PORT-1008

Message GigE Port (<slot number>/GE<port number>) has been enabled.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates a Gigabit Ethernet port has been enabled of a particular slot.

PORT-1009

Message GigE Port (<slot number>/GE<port number>) has been disabled.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates a Gigabit Ethernet port has been disabled of a particular slot.

PORT-1010

Message Port (ID: <port number>) QoS is disabled.

Message Type LOG

Severity INFO

Probable Cause Indicates that the port quality of service (QoS) is disabled due to the best effort setting on the 4Gb/s or

8Gb/s long distance platform.

PORT-1011

Message Please swap to the previous port blade, disable all F-Port trunk ports on this slot

(<slot number>), and then swap back to current blade.

Message Type LOG

Severity WARNING

Probable Cause Indicates that port in the previous blade had F-port trunking enabled. The current port does not support

F-Port trunking.

Recommended Perform

Action

Perform blade swap to the previous port blade, disable all F-Port trunk ports on this blade.

PORT-1012

Message <Port name feature> has been removed for Port (ID: <Port number>).

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that user configured port name or FICON-based port name has been removed for the

specified port.

PORT-1013

Message Port (ID: <port number>) is configured as Static D_Port.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the port is configured as D_Port.

PORT-1014

Message Port (ID: <port number>) is not configured as D Port.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the port is not configured as D_Port.

PORT-1015

Message Port (ID: <Port number>) has been enabled.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the port is being intentionally enabled.

PORT-1016

Message Port (ID: <Port number>) has been disabled.

Message Type AUDIT

Class CFG

Severity INFO

PORT-1017

Message Port (ID: <Port number>) has been persistently enabled.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the port is being persistently enabled.

PORT-1018

Message Port (ID: <Port number>) has been persistently disabled.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the port is being persistently disabled.

PORT-1019

Message Default configuration update for port (ID: <Port number>).

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified port is updated with the default configuration.

PORT-1020

Message FEC configuration updated for port (ID: <Port number>).

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified port is updated with the Forward Error Correction (FEC) configuration.

PORT-1021

Message Long distance configuration updated for port (ID: <Port number>).

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified port is updated with the long distance configuration.

PORT-1022

Message Octet speed combo configuration updated for port (ID: <Port number>).

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified port is updated with the octet speed combo configuration.

PORT-1023

Message QOS configuration updated for port (ID: <Port number>).

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified port is updated with the quality of service (QoS) configuration.

PORT-1024

Message Speed configuration updated for port (ID: <Port number>).

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified port is updated with the speed configuration.

PORT-1025

Message Trunk configuration updated for port (ID: <Port number>).

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified port is updated with the trunk configuration.

PORT-1026

Message ISL configuration updated for port (ID: <Port number>).

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified port is updated with the inter-switch link (ISL) configuration.

PORT-1027

Message Port beacon configuration updated for port (ID: <Port number>).

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified port is updated with the port beacon configuration.

PORT-1028

Message Portpeerbeacon configuration updated for port (ID: <Port number>).

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified port is updated with the portpeerbeacon configuration.

PORT-1029

Message NPIV configuration updated for port (ID: <Port number>).

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified port is updated with the NPIV configuration.

PORT-1030

Message Compression configuration updated for port (ID: <Port number>).

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified port is updated with the Compression configuration.

PORT-1031

Message Encryption configuration updated for port (ID: <Port number>).

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified port is updated with the Encryption configuration.

PORT-1032

Message TDZ configuration updated for port (ID: <Port number>).

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified port is updated with the TDZ configuration.

PORT-1033

Message Non-DFE configuration updated for port (ID: <Port number>).

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified port is updated with the Non-DFE configuration.

PORT-1034

Message Port statistics cleared for port (ID: <Port number>).

Message Type AUDIT

Class CLI

Severity INFO

Probable Cause Clears the statistics of the specified port.

PORT-1035

Message Port (ID: <Port number>) has been configured as N-Port.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified port is configured as N_Port.

PORT-1036

Message Port (ID: <Port number>) is not configured as N Port.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified Port is not configured as N_Port.

PORT-1037

Message Portcfgeport configuration updated for port <Port Configuration>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified port is updated with the Portcfgeport configuration.

PORT-1038

Message port <Port number> is converted to <Flexport Configuration>.

Message Type AUDIT

Class CLI

Severity INFO

Probable Cause Indicates that the specified port is updated with the Portcfgflexport configuration.

PORT-1039

Message Portcfgbreakout configuration for port <Port number> is <Breakout Configuration>.

Message Type AUDIT

Class CLI

Severity INFO

Probable Cause Indicates that the specified port is updated with the Portcfgbreakout configuration.

PORT-1040

Message Portcfggport configuration updated, <Configuration status> for port <Port number>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified port is either locked or released as G-Port.

PORT-1041

Message portCfgEportCredits configuration <Configuration status> for port <Port number>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates the credit allocation has been changed or restored for specified E/EX port.

PORT-1042

Message ALPA(0x<ALPA>) configuration set for port <Port number>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates the ALPA has been changed or restored for specified port.

PORT-1043

Message Credit recovery <Enabled or Disabled> for port <Port number>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates the credit recovery has been changed for specified port.

PORT-1044

Message RSCN Suppressed configuration updated for port <Port number>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified port is updated with portcfgrscn configuration.

PORT-1045

Message LOS TOV configuration updated for port <Port number>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates de-bouncing of signal loss for specified port has been changed using portcfglosstov.

PORT-1046

Message Mirror port configuration updated for port <Port number>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified port is updated with the mirror port configuration.

PORT-1047

Message SIM port configuration updated for port <Port number>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified port is updated with the SIM port configuration.

PORT-1048

Message EX-port configuration updated for port <Port number>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified port is updated with the EX-port configuration.

PORT-1049

Message Fault delay configuration updated for port <Port number>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified port is updated with the fault delay configuration.

PORT-1050

Message Port auto disable configuration updated for port <Port number>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified port is updated with the portogautodisable configuration.

PORT-1051

Message F Port Buffers configuration updated for port <Port number>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified port is updated with the portofgfportbuffers configuration.

PORT-1052

Message Port NPIV login limit is changed for port <Port number>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified port is updated with the Npiv login limit configuration.

PORT-1053

Message FLOGI Logout capability updated for port <Port number>.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the specified port is updated with the FLOGI Logout capability.

PORT-1054

Message Port (ID: <Port number>) has been marked Impaired.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the port is being marked Impaired.

Recommended Action

Impaired links will not be used for routing unless no viable alternative exists without routing path cost changes.

Check and replace (if necessary) the hardware attached to both ends of the specified port number, including:

- The media (SFPs)
- The cable (fiber optic or copper inter-switch link (ISL))
- The attached devices

After checking the hardware, execute the **portRestart** to clear the Impaired state.

PORT-1055

Message Port (ID: <Port number>) Impaired state has been cleared.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the port has cleared the Impaired state.

Recommended The port must be toggled after clearing the Impaired state to return it to service.

Action

PORT-1056

Message Port (ID: <Port number>) Clean Address enabled.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the port has clean address support enabled.

PORT-1057

Message Port (ID: <Port number>) Clean Address disabled.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the port has clean address support disabled.

PORT-1058

Message Type LOG

Severity INFO

Probable Cause Indicates that the ICL port has module inserted/removed.

PORT-1059

Message Port (ID: <Port number>) Congestion detection signaling enabled.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the port has congestion detection signaling enabled.

PORT-1060

Message Port (ID: <Port number>) Congestion detection signaling disabled.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the port has congestion detection signaling disabled.

PORT-1061

Message Port (ID: <Port number>) user defined disable reason set.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that user defined reason to disable the port has been set.

PORT-1062

Message Port (ID: <Port number>) user defined disable reason cleared.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that user defined reason to disable the port has been cleared.

6.85 PS Messages

PS-1000

Message Failed to initialize Advanced Performance Monitoring.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that an unexpected software error has occurred in Advanced Performance Monitoring. The

Performance Monitor has failed to initialize.

Recommended The control processor (CP) will reboot or failover automatically. If it does not, reboot or power cycle the

switch to reinitiate the firmware.

PS-1001

Message Advanced Performance Monitoring configuration updated due to change in PID format.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the port ID (PID) format was changed.

Recommended No action is required. Refer to the Fabric OS Administrator's Guide for more information about the PID

Action format.

PS-1002

Message Failed to initialize the tracing system for Advanced Performance Monitoring.

Message Type LOG

Severity INFO

Probable Cause Indicates that an unexpected software error has occurred in Advanced Performance Monitoring. The

Performance Monitor tracing system has failed to initialize.

Recommended Tracing will not be available for Advanced Performance Monitoring, but other functions will function

normally. To activate tracing, reboot or failover the control processor (CP).

PS-1009

Message Failed to add the device updates in condb database.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that the fabric has more than the allowed number of devices.

Recommended Action Reduce the number of devices configured in the fabric to be within the allowed limit. The maximum number of devices that can be configured in a fabric is 940.

6.86 PSWP Messages

PSWP-1001

Message PID for port <wwn name corresponding to source port > and port <wwn name corresponding

to destination port> are swapped. New PID for port <wwn name corresponding to source

port> is 0x<wwn name corresponding to destination port> and port <new area corresponding to source wwn> is 0x<new area corresponding to destination wwn>.

Message Type LOG

Severity INFO

Probable Cause Indicates the **portSwap** command has been issued.

PSWP-1002

Message Port Swap feature enabled.

Message Type LOG

Severity INFO

Probable Cause Indicates the port swap feature has been enabled in the switch.

PSWP-1003

Message Port Swap feature disabled.

Message Type LOG

Severity INFO

Probable Cause Indicates the port swap feature has been disabled in the switch.

PSWP-1004

Message Blade Swap complete for slots <slot number corresponding to the source blade> and

<slot number corresponding to the destination blade>.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates the **bladeSwap** command has been issued.

PSWP-1005

Message Blade Swap undo failed with error code <error code from undoBladeSwap>.

Message Type LOG

Severity WARNING

Probable Cause Indicates the **bladeSwap** command has not been undone.

Recommended Use the **portSwapShow** command to display a list of currently swapped ports; then use the **portSwap**

Action command to achieve the desired result.

PSWP-1006

Message Blade Swap failed on configInit with error code <error code from configInit> in switch

number <current switch number>.

Message Type LOG

Severity WARNING

Probable Cause Indicates the **bladeSwap** command failed on access to configuration data.

Recommended Retry the command. If the failure persists, contact your switch service provider.

Action

PSWP-1007

Message Blade Swap failed on fabosInit with error code <error code from fabosInit> in switch

number <current switch number>.

Message Type LOG

Severity WARNING

Probable Cause Indicates the **bladeSwap** command failed on access to switch context.

Recommended Retry the command. If the failure persists, contact your switch service provider.

Action

PSWP-1008

Message PID for port <source port> and port <destination port> are swapped.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates the **portSwap** command has been issued.

6.87 QOSD Messages

QOSD-1000

Message QoS initialized successfully.

Message Type LOG

Severity INFO

Probable Cause Indicates that the Data Center Ethernet (DCE) QoS has been initialized.

QOSD-1001

Message Failed to allocate memory: (<function name>).

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified function has failed to allocate memory.

Recommended Check the memory usage on the switch using the **show process memory** command.

Action Restart or power cycle the switch.

QOSD-1005

Message QoS startup failed.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the Data Center Ethernet (DCE) QoS encountered an unexpected severe error during

basic startup and initialization.

Recommended Restart or power cycle the switch.

Action

If the problem persists, download a new firmware version using the **firmware download** command.

QOSD-1006

ISL restriction. Shutting down interface.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the interface could not come up as inter-switch link (ISL) because only regular ISL is

allowed for 2 Km and 5 Km distant links. The interface has been automatically shut down.

6.88 RAS Messages

RAS-1001

Message First failure data capture (FFDC) event occurred.

Message Type LOG

Severity INFO

Probable Cause Indicates that a first failure data capture (FFDC) event occurred and the failure data has been

captured.

Recommended Execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the

supportSave command and contact your switch service provider.

RAS-1002

Message First failure data capture (FFDC) reached maximum storage size (<log size limit> MB).

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that the storage size for first failure data capture (FFDC) has reached the maximum.

Recommended Execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the

supportSave command and contact your switch service provider.

RAS-1003

Message Tracedump transfer failed because anonymous FTP is not allowed when secure upload/

download is set in configurechassis

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates support ftp parameters are set to user: anonymous, and password: BLANK when secure

upload/download is set in configurechassis

Recommended Change the support ftp parameters

Action

Message Software 'verify' error detected.

Message Type LOG | FFDC

Severity INFO

Probable Cause Indicates an internal software error.

Recommended Execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the

Action **supportSave** command and contact your switch service provider.

RAS-1005

Message Software 'assert' error detected.

Message Type LOG | FFDC

Severity WARNING

Probable Cause Indicates an internal software error.

Recommended Execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the

supportSave command and contact your switch service provider.

RAS-1006

Message Support data file (<Uploaded file name>) automatically transferred to remote address

' <Remote target designated by user> '.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the support data was automatically transferred from the switch to the configured remote

server.

RAS-1007

Message System is about to reload.

Message Type LOG | AUDIT

Class CLI

Severity INFO

Probable Cause Indicates that the system reload was initiated.

Message supportftp parameters are not configured. One of the required parameter is missing.

Message Type LOG

Severity INFO

Probable Cause Indicates that one or more support FTP parameters were not specified with the supportFtp command

in non-interactive mode.

Recommended Specify all support FTP parameters.

Action

RAS-1009

Message Trace FTP is set to Host <Host Name> user: <User Name> remoteDir <File Path>

Message Type AUDIT

Class RAS

Severity INFO

Probable Cause Indicates trace ftp parameters are set.

RAS-1010

Message Trace FTP is set to <trace_ftp_enable success>

Message Type AUDIT

Class RAS

Severity INFO

Probable Cause Indicates trace ftp is enabled or disabled.

RAS-1011

Message Type AUDIT

Class RAS

Severity INFO

Probable Cause Indicates tracedump is generated or not.

Message Type AUDIT

Class RAS

Severity INFO

Probable Cause Indicates tracedump transferred to remote location is successful or not.

RAS-1013

Message <trace_dump_remove>

Message Type AUDIT

Class RAS

Severity INFO

Probable Cause Indicates trace dump removed on a slot or not.

RAS-1014

Message <trace_trigger_remove_all>

Message Type AUDIT

Class RAS

Severity INFO

Probable Cause Indicates trace_trigger_remove_all is successful or not.

RAS-1015

Message <trace_trigger_remove>

Message Type AUDIT

Class RAS

Severity INFO

Probable Cause Indicates trace trigger is removed or not.

RAS-1016

Message <trace_trigger_set>

Message Type AUDIT

Class RAS

Severity INFO

Probable Cause Indicates trace trigger is set or not.

RAS-2001

Message Audit message log is enabled.

Message Type LOG | AUDIT

Class RAS

Severity INFO

Probable Cause Indicates that the audit message log has been enabled.

RAS-2002

Message Audit message log is disabled.

Message Type LOG | AUDIT

Class RAS

Severity INFO

Probable Cause Indicates that the audit message log has been disabled.

RAS-2003

Message Audit message class configuration has been changed to <New audit class configuration>.

Message Type LOG | AUDIT

Class RAS

Severity INFO

Probable Cause Indicates that the audit event class configuration has been changed.

RAS-2004

Message prom access is enabled.

Message Type LOG | AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that the PROM access has been enabled.

RAS-2005

Message prom access is disabled.

Message Type LOG | AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that the PROM access has been disabled.

RAS-2006

Message Syslog server IP address <IP address> added.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that a syslog server IP address has been added.

RAS-2007

Message Syslog server IP address <IP address> removed.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that a syslog server IP address has been removed.

RAS-2008

Message Audit log message storage has wrapped around.

Message Type LOG | AUDIT

Class RAS

Severity INFO

Probable Cause Indicates that audit log message storage has wrapped around.

RAS-2009

Message Audit log message storage has reached 75 percentage of limit.

Message Type LOG | AUDIT

Class RAS

Severity INFO

Probable Cause Indicates that audit log message storage is 75% full.

RAS-2010

Message Syslog daemon is started.

Message Type AUDIT

Class RAS

Severity INFO

Probable Cause Indicates that a syslog daemon is started.

RAS-2011

Message Syslog daemon is stopped.

Message Type AUDIT

Class RAS

Severity INFO

Probable Cause Indicates that a syslog daemon is stopped.

RAS-2012

Message Audit message severity configuration has been changed to <New audit severity

configuration>.

Message Type LOG | AUDIT

Class RAS

Severity INFO

Probable Cause Indicates that the audit event severity configuration has been changed.

RAS-2013

Message syslog facility level has been changed from <Old syslog facility configuration> to

<New syslog facility configuration>.

Message Type LOG | AUDIT

Class RAS

Severity INFO

Probable Cause Indicates that syslog facility configuration has been changed.

RAS-2014

Message Audit Log message < Audit Log message that has been disabled > has been disabled.

Message Type LOG | AUDIT

Class RAS

Severity INFO

Probable Cause Indicates that the specified Audit message has been disabled from logging.

RAS-2015

Message Audit Log message <Audit Log message that has been enabled> has been enabled.

Message Type LOG | AUDIT

Class RAS

Severity INFO

Probable Cause Indicates that the specified Audit message has been enabled for logging.

RAS-3001

Message USB storage device plug-in detected.

Message Type LOG

Severity INFO

Probable Cause Indicates that the USB storage device plug-in has been detected.

Message USB storage device enabled.

Message Type LOG

Severity INFO

Probable Cause Indicates that the USB storage device has been enabled.

RAS-3003

Message USB storage device was unplugged before it was disabled.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the USB storage device was unplugged before it was disabled.

Recommended No action is required. It is recommended to disable the USB storage device using the usbstorage -d

Action command before unplugged it from the system.

RAS-3004

Message USB storage device disabled.

Message Type LOG

Severity INFO

Probable Cause Indicates that the USB storage device has been disabled.

RAS-3005

Message CLI: <CLI command>

Message Type AUDIT

Class CLI

Severity INFO

Probable Cause Indicates that the specified command was executed on console.

RAS-3006

Message USB storage device enabled.

Message Type AUDIT

CLI Class

Severity INFO

Probable Cause Indicates that the USB storage device has been enabled.

RAS-3007

Message USB storage device disabled.

Message Type **AUDIT**

> Class CLI

Severity **INFO**

Probable Cause Indicates that the USB storage device has been disabled.

RAS-3008

Message USB storage <Storage file > removed.

Message Type **AUDIT**

> Class CLI

INFO Severity

Probable Cause Indicates that the USB storage file has been removed.

6.89 RCS Messages

RCS-1001

Message RCS has been disabled. There was a problem verifying that all switches in the fabric

support this feature.

Message Type LOG

> Severity INFO

Probable Cause Indicates that the reliable commit service (RCS) feature has been disabled on the local switch because

of problem validating RCS support on all switches in the fabric.

RCS is supported on all supported versions of Fabric OS. Indicates a possible routing problem.

Run the rcsInfoShow command to view RCS capability on the fabric to determine problem switch or

Action switches

RCS-1002

Recommended

Message RCS has been enabled.

Message Type LOG

Severity INFO

Probable Cause Indicates that the reliable commit service (RCS) feature has been enabled. RCS must be capable on

all switches in the fabric to be enabled. If all switches are capable, it is automatically enabled.

RCS-1003

Message Failed to allocate memory: (<function name>).

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified reliable commit service (RCS) function has failed to allocate memory.

Recommended This message is usually transitory. Wait for few minutes and retry the command.

Action Check memory usage on the switch using the **memShow** command.

Reboot or power cycle the switch.

RCS-1004

Message Application(<application name>) not registered.(<error string>).

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified application did not register with reliable commit service (RCS).

RCS is supported in Fabric OS v2.6, v3.1, v4.1 and later.

Recommended Run the **haShow** command to view the HA state.

Action Run the **haDisable** and **haEnable** commands.

Run the rcsInfoShow command to view RCS capability on the fabric. RCS is supported in Fabric OS

v2.6, v3.1 and later, and v4.1 and later.

Run the **firmwareDownload** command to upgrade the firmware for any switches that do not support

RCS.

RCS-1005

Message Phase <RCS phase>, <Application Name> Application returned <Reject reason>, 0x<Reject

code>.

Message Type LOG

Severity INFO

Probable Cause Indicates that a receiving switch is rejecting the specified reliable commit service (RCS) phase.

Recommended Action If the reject is in the acquire change authorization (ACA) phase, wait for several minutes and then retry the operation from the sender switch.

If the reject is in the stage fabric configuration (SFC) phase, check if the application license exists for the local domain and if the application data is compatible.

RCS-1006

Message State <RCS phase>, Application Application Name> ADAdministrative Domain, RCS CM.

 ${\tt Domain~CDomain~ID~that~sent~the~reject>~returned~0x<Reject~code>.~App~Response~Code}$

<Application Response Code>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified domain rejected a reliable commit service (RCS) phase initiated by an application on the local switch.

■ If the reject phase is acquire change authorization (ACA), the remote domain may be busy and could not process the new request.

If the reject phase is stage fabric configuration (SFC), the data sent by the application may not be compatible or the domain does not have the license to support that application.

Action

Recommended

If the reject is in the ACA phase, wait for several minutes and then retry the operation.

If the reject is in the SFC phase, check if the application license exists for the remote domain and if the

application data is compatible.

RCS-1007

Message Zone DB size and propagation overhead exceeds domain <domain number>'s maximum

supported Zone DB size <max zone db size>. Retry after reducing Zone DB size.

Message Type

Severity **ERROR**

Probable Cause Indicates that the specified domain cannot handle the zone database being committed.

Reduce the zone database size. Recommended

Action

RCS-1008

Message Domain <domain number> Lowest Max Zone DB size.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates the specified domain has the lowest memory available for the zone database in the fabric.

The zone database must be smaller than the memory available on this domain.

Reduce the zone database size. Recommended

Action

RCS-1009

Message Request remote domain <domain number> offline because it does not support RCS.

Message Type LOG

> INFO Severity

Probable Cause Indicates that the specified remote domain is requested to go offline to take it out of the fabric because

it does not support reliable commit service (RCS).

Recommended Run the **fabricShow** command to verify that the remote domain is out of the fabric.

Action

RCS-1011

Message Remote domain RCS-Validation message exchange Failed, Investigate

frame delivery problem.

FOS-90x-Message-RM103 Broadcom

Message Type LOG

Severity ERROR

Probable Cause Indicates that for the specified domain, the RCS-capable information could not be retrieved due to

some potential routing issues.

Recommended

Action

Investigate for routing issue or check the cabling.

RCS-1012

Message Local domain is RCS incapable (ForceDisabled is <Flag which denotes whether switch

is RCS capable or not>), hence reject the RCS INFO request from domain <domain

number>.

Message Type LOG | FFDC

Severity WARNING

Probable Cause Indicates that the specified domain is RCS-incapable.

Recommended Execute the **supportSave** command and contact your switch service provider.

Action

RCS-1013

Message Remote domain <domain number> is RCS incapable.

Message Type LOG | FFDC

Severity WARNING

Probable Cause Indicates that the specified remote domain is RCS-incapable.

Recommended Execute the **supportSave** command and contact your switch service provider.

Action

RCS-1014

Message Rebooting the CP as it received an update before application [<App Code>] has

registered.

Message Type LOG | FFDC

Severity WARNING

Probable Cause Indicates that the RCS in the control processor (CP) received an update before the application has

registered. The CP reboots automatically to ensure sync and attain the normal state. This is a rare

occurrence.

6.90 RMON Messages

RMON-1001

Message RMON rising threshold alarm from SNMP OID <oid>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the threshold level was exceeded for the sample type of the remote monitoring (RMON)

alarm.

Recommended Check the traffic on the interface using the **show interface** command.

Action

Note that you can use the ${\bf show}$ ${\bf interface}$ command to check the traffic on the interface, provided the

statistics on the interface are not cleared using the clear counters command.

RMON-1002

Message RMON falling threshold alarm from SNMP OID <oid>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the threshold level has come down for the sample type of the remote monitoring

(RMON) alarm.

Recommended Check the traffic on the interface using the **show interface** command.

Action

Note that you can use the show interface command to check the traffic on the interface, provided the

statistics on the interface are not cleared using the clear counters command.

6.91 RPCD Messages

RPCD-1001

Message Authentication Error: client \"<IP address>\" has bad credentials: <bad user name and

password pair>.

Message Type LOG

Severity WARNING

Probable Cause Indicates an authentication error was reported. The specified client IP address has faulty credentials.

Recommended Enter the correct user name and password from the Fabric Access API host.

Action

RPCD-1002

Message Missing certificate file. Secure RPCd is disabled.

Message Type LOG

Severity WARNING

Probable Cause Indicates a Secure Sockets Layer (SSL) certificate is missing.

Recommended To enable remote procedure call daemon (RPCD) in secure mode, install a valid SSL certificate on the

Action switch.

RPCD-1003

Message Permission denied accessing certificate file. Secure RPCd is disabled.

Message Type LOG

Severity WARNING

Probable Cause Indicates the Secure Sockets Layer (SSL) certificate file configured on the switch could not be

accessed because root did not have read-level access.

Recommended Change the file system access level for the certificate file to have root read-level access.

Action

RPCD-1004

Message Invalid certificate file. Secure RPCd is disabled.

Message Type LOG

Severity WARNING

Probable Cause Indicates the Secure Sockets Layer (SSL) certificate file has been corrupted.

Recommended To enable remote procedure call daemon (RPCD) in secure mode, install a valid SSL certificate on the

Action switch.

RPCD-1005

Message Missing private key file. Secure RPCd is disabled.

Message Type LOG

Severity WARNING

Probable Cause Indicates the private key file is missing.

Recommended

Run the secCertUtil command to install a valid private key file.

Action

RPCD-1006

Message Permission denied accessing private key file. Secure RPCd is disabled.

Message Type LOG

Severity WARNING

Probable Cause Indicates the private key file configured on the switch could not be accessed because the root did not

have read-level access.

Recommended

Action

Change the file system access level for the private key file to have root read-level access.

RPCD-1007

Message Invalid private file. Secure RPCd is disabled.

Message Type LOG

Severity WARNING

Probable Cause Indicates the private key file has been corrupted.

Recommended Run the **secCertUtil** command to install a valid private key file.

Action

6.92 RTE Messages

RTE-1001

Message Detected route inconsistency. It may cause connectivity issues. If such issues arise,

bounce all ISLs and ICLs on this chassis.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the constraints that are used to determine the paths for Dynamic Path Selection (DPS)

are not synchronized from active control processor (CP) to standby CP during the failover. This event

causes route inconsistencies.

Recommended

Action

Reset all E_ports on the chassis using the **portDisable** and **portEnable** commands.

RTE-1002

Message FID <fid>: The QSFP connection topology is not recommended

Message Type LOG

Severity WARNING

Probable Cause Indicates that the current QSFP connection is resulting in an unbalanced topology and is not

recommended.

Recommended Use the switchShow, isIShow, and IsdbShow commands to identify the QSFP connectivity to

ensure that all recommendations for cabling are satisfied.

RTE-1003

Message FID <fid>: The QSFP connection topology has been corrected

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the previously unbalanced QSFP connection topology has been corrected.

RTE-1004

Message Faulting blade <Slot number> due to missing routes. Use slotpoweroff and slotpoweron

to recover the blade.

Message Type LOG

Severity WARNING

Probable Cause The detection of a missing route suggests that more missing routes may exist. The blade is faulted in

order to not impact the rest of the system.

Recommended Run the commands **slotpoweroff** and **slotpoweron** to recover the blade.

Action

RTE-1005

Message Missing routes detected on slot <Slot number> but blade object 0x<blade object

identifier> does not exist, so cannot recover.

Message Type LOG

Severity WARNING

Probable Cause Possible reasons for this raslog: the Interface Database(IFDB) is corrupted, out of sync, or missing

data; or the slot may be in transition.

Recommended

Action

Try manually running slotpoweroff and then slotpoweron with the slot number identified in the RASLOG text.

6.93 RTWR Messages

RTWR-1001

Message RTWR <routine: error message> 0x<detail 1>, 0x<detail 2>, 0x<detail 3>, 0x<detail 4>,

0x<detail 5>.

Message Type LOG

Severity ERROR

Probable Cause

Indicates that an error occurred in Reliable Transport With Response (RTWR) due to one of the following reasons:

■ The system ran out of memory.

- The domain may be unreachable
- The frame transmission failed.
- An internal error or failure occurred.

The message contains the name of the routine that has an error and other error-specific information. Refer to values in details 1 through 5 for more information.

Recommended Action

Restart the switch.

RTWR-1002

Message RTWR <error message: maximum retries exhausted> 0x<port>, 0x<domain ID>, 0x<retry

count>, 0x<status>, 0xocess ID>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that Reliable Transport With Response (RTWR) has exhausted the maximum number of

retries for sending data to the specified domain.

Recommended Execute the **fabricShow** command to verify that the specified domain ID is online.

Action

command.

If the message persists, execute the supportFtp command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

If the switch with the specified domain ID is offline, enable the switch using the switchEnable

RTWR-1003

Message <module name>: RTWR retry <number of times retried> to domain <domain ID>, iu_data

<first word of iu data>.

Message Type LOG

Severity INFO

Probable Cause Indicates the number of times Reliable Transport With Response (RTWR) has failed to get a response

and retried.

Recommended Execute the **fabricShow** command to verify that the specified domain ID is reachable.

Action

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

RTWR-1004

Message RTWR <routine: error message> <Switch instance>, 0x<detail 1>, 0x<detail 2>,

0x<detail 3>.

Message Type LOG | FFDC

Severity ERROR

Probable Cause Indicates that an error occurred in Reliable Transport With Response (RTWR)

The message contains the name of the routine that has an error and other error-specific information.

Recommended Action Collect Support Save

6.94 SCN Messages

SCN-1001

Message SCN queue overflow for process <daemon name>.

Message Type FFDC | LOG

> Severity **CRITICAL**

Probable Cause

Indicates that an attempt to write a state change notification (SCN) message to a specific queue has failed because the SCN queue for the specified daemon is full. This may be caused by the daemon hanging or the system being busy.

The following are some valid values for the *daemon name*:

- fabricd
- asd
- evmd
- fcpd
- msd
- nsd
- psd
- snmpd
- zoned
- fspfd tsd

Recommended Action

If this message is caused by the system being busy, the condition is temporary.

If this message is caused by a hung daemon, the software watchdog will cause the daemon to dump the core and reboot the switch. In this case, execute the **supportSave** command to send the core files using FTP to a secure server location.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

SCN-1002

Message SCN queue overflow for process <daemon name>.

Message Type FFDC | LOG

Severity WARNING

Probable Cause

Indicates that an attempt to write a state change notification (SCN) message to a specific queue has failed because the SCN queue for the specified daemon is full. This may be caused by the daemon hanging or the system being busy.

The following are some of the valid values for the *daemon name*:

- fabricd
- asd
- evmd
- fcpd
- msd
- nsd
- psd
- snmpd
- zoned
- fspfd
- tsd

Recommended Action

If this message is caused by the system being busy, the condition is temporary.

If this message is caused by a hung daemon, the software watchdog will cause the daemon to dump the core and reboot the switch. In this case, execute the **supportSave** command to send the core files using FTP to a secure server location.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

6.95 SEC Messages

SEC-1001

Message RCS process fails: <reason code>.

Message Type LOG

Severity ERROR

Probable Cause

Indicates that the reliable commit service (RCS) process failed to complete. RCS is a mechanism for transferring data from one switch to other switches within the fabric. RCS ensures that either all or none of the switches commit to the database. RCS can fail if one switch in the fabric is busy or in an error state that prevents it from accepting the database.

RCS must be capable on all switches in the fabric to be enabled. If all switches are capable, it is automatically enabled.

Recommended Action

RCS is evoked when the security database is modified by a security command (for example, **secPolicySave**, **secPolicyActivate**, or **distribute**). If the switch is busy, the command may fail the first time. Retry the command.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

SEC-1002

Message Security data fails: <Reason Text>.

Message Type LOG

Severity ERROR

Probable Cause

Indicates that the receiving switch fails to validate the security database sent from the primary fabric configuration server (FCS) switch. This may be caused by several factors: the data package may be corrupted, the time stamp on the package may be out of range as a result of replay attack or out-of-sync time service, or the signature verification failed. Signature verification failure may result from an internal error, such as losing the primary public key or an invalid database.

Recommended Action Run the secFabricShow command to verify that the fabric is still consistent. All the switches should be

in the ready state. If a switch is in the error state, the database may not be correctly updated for that switch. The error may also be a result of an internal corruption or a hacker attack to the secure fabric. If you have reason to believe that the error is the result of a possible security breach, take appropriate action as defined by your enterprise security policy.

SEC-1003

Message Fail to download security data to domain Comain number after <Number of retires</pre>

retries.

LOG Message Type

> WARNING Severity

Probable Cause Indicates the specified domain failed to download security data after the specified number of attempts,

and that the failed switch encountered an error accepting the database download. The primary switch

will segment the failed switch after 30 tries.

Recommended Run the secFabricShow command to verify that the fabric is still consistent. All the switches should be Action

in the ready state.

If the message persists, execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the supportSave command and contact your switch service provider.

SEC-1005

Message Primary FCS receives data request from domain <Domain number>.

Message Type LOG

> **INFO** Severity

Probable Cause Indicates the primary fabric configuration server (FCS) received a data request from the specified

> domain. For example, if the switch fails to update the database or is attacked (data injection), a message is generated to the primary FCS to try to correct and resynchronize with the rest of the

switches in the fabric.

Recommended

Action

Use the secFabricShow command to check whether any of the switches in the fabric encountered an error. If one or more of the switches is not in the ready state, and you have reason to believe that the error is the result of a possible security breach, take appropriate action as defined by your enterprise

security policy.

SEC-1006

Message Security statistics error: Failed to reset due to invalid <data>.

Message Type LOG

> Severity WARNING

Probable Cause Indicates that invalid data has been received for any statistic-related command for security

(secStatsShow or secStatsReset). The counter is updated automatically when a security violation

occurs. This message may also occur if the updating counter fails.

Recommended

Action

If the message is the result of a user command, retry the statistic command.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

SEC-1007

Message Security violation: Unauthorized host with IP address <IP address of the violating

host> tries to establish API connection.

Message Type LOG

Severity INFO

Probable Cause Indicates a security violation was reported. The IP address of the unauthorized host is displayed in the

message.

Recommended Check for unauthorized access to the switch through the API connection.

Action

SEC-1008

Message Security violation: Unauthorized host with IP address <IP address of the violating

host> tries to establish HTTP connection.

Message Type LOG

Severity INFO

Probable Cause Indicates a security violation was reported. The IP address of the unauthorized host is displayed in the

message.

Recommended

Action

Check for unauthorized access to the switch through the HTTP connection.

SEC-1009

Message Security violation: Unauthorized host with IP address <IP address of the violating

host> tries to establish TELNET connection.

Message Type LOG

Severity INFO

Probable Cause Indicates a security violation was reported. The IP address of the unauthorized host is displayed in the

message.

Recommended Action Check for unauthorized access to the switch through the Telnet connection.

, 10

SEC-1010

Message RCS rejected: <Reason String>.

Message Type LOG

Severity ERROR

Probable Cause Trying to distribute the database from a non-primary switch.

Recommended Resolve the specified error by executing the command only from the primary FCS.

Action

SEC-1016

Message Security violation: Unauthorized host with IP address <IP address of the violating

host> tries to establish SSH connection.

Message Type LOG

Severity INFO

Probable Cause Indicates a security violation was reported. The IP address of the unauthorized host is displayed in the

message.

Recommended Check for unauthorized access to the switch through the SSH connection.

Action

SEC-1022

Message Failed to operation> PKI objects.

Message Type LOG

Severity WARNING

Probable Cause Indicates the fabric failed to generate or validate either the public or private key pair or the certificate

signing request (CSR).

Recommended Run the **secCertMgmt show -all** command and verify in FCAP row that all public key infrastructure

Action (PKI) objects exist on the switch. If the private key does not exist, follow the steps for re-creating PKI

objects. If a certificate does not exist or is invalid, install the certificate by following the field upgrade

process.

SEC-1024

Message The <DB name> security database is too large to fit in flash.

Message Type LOG

Severity INFO

Probable Cause Indicates the size of the security database is too large for the flash memory. The size of the security

database increases with the number of entries in each policy.

Recommended

Action

Reduce the size of the security database by reducing the number of entries within each policy.

SEC-1025

Message Invalid IP address (<IP address>) detected.

Message Type LOG

Severity ERROR

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can occur only

when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended

Action

Run the **secFabricShow** command to verify that the fabric is still consistent. All the switches should be in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1026

Message Invalid format or character in switch member <switch member ID>.

Message Type LOG

Severity ERROR

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can occur only

when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended

Action

Run the **secFabricShow** command to verify that the fabric is still consistent. All the switches should be in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1028

Message No name is specified.

Message Type LOG

Severity **ERROR**

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can occur only

> when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended Run the secFabricShow command to verify that the fabric is still consistent. All the switches should be

in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1029

Message Invalid character in <policy name>.

LOG Message Type

Action

ERROR Severity

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can occur only

> when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended Run the secFabricShow command to verify that the fabric is still consistent. All the switches should be Action

in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1030

Message The length of the name is invalid.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can occur only

> when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended Run the secFabricShow command to verify that the fabric is still consistent. All the switches should be Action

in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1031

Message Current security policy DB cannot be supported by standby. CPs will go out of sync.

LOG Message Type

> Severity WARNING

Probable Cause Indicates the security database size is not supported by the standby control processor (CP).

Recommended Reduce the security policy size by deleting entries within a policy or by deleting some policies. Action

SEC-1032

Message Empty FCS list is not allowed.

Message Type LOG

> **ERROR** Severity

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

> when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended Run the secFabricShow command to verify that the fabric is still consistent. All the switches should be Action

in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1033

Message Invalid character used in member parameter to add switch to SCC policy; command

terminated.

Message Type LOG

> **ERROR** Severity

Probable Cause Indicates a member parameter in the secPolicyAdd command is invalid (for example, it may include

an invalid character, such as an asterisk). A valid switch identifier (a WWN, a domain ID, or a switch

name) must be provided as a member parameter in the secPolicyAdd command. Only the secPolicyCreate command supports use of the asterisk for adding switches to policies.

Recommended Run the secPolicyAdd command using a valid switch identifier (WWN, domain ID, or switch name) to Action

add specific switches to the Switch Connection Control (SCC) policy.

SEC-1034

Message Invalid member <policy member>.

Message Type LOG

Severity ERROR

Probable Cause Indicates the input list has an invalid member.

Action

Recommended

Verify the member names, and input the correct information.

SEC-1035

Message Invalid device WWN <device WWN>.

Message Type LOG

Severity ERROR

Probable Cause Indicates the specified World Wide Name (WWN) is invalid.

Recommended Enter the correct WWN value.

Action

SEC-1036

Message Device name <device name> is invalid due to a missing colon.

Message Type LOG

Severity ERROR

Probable Cause Indicates one or more device names mentioned in the **secPolicyCreate** or **secPolicyAdd** commands

does not have the colon character (:) as required.

Recommended Run the **secPolicyCreate** or **secPolicyAdd** command with a properly formatted device name

Action parameter.

SEC-1037

Message Invalid WWN format <invalid WWN>.

Message Type LOG

Severity ERROR

Probable Cause Indicates the WWN entered in the policy member list has an invalid format.

Recommended Run the command again using the standard WWN format; 16 hexadecimal digits grouped as 8 colon-

Action separated pairs, for example, 50:06:04:81:D6:F3:45:42.

SEC-1038

Message Invalid domain domain ID>.

Message Type LOG

Severity ERROR

Probable Cause Indicates an invalid domain ID was entered.

Recommended Verify that the domain ID is correct. If it is not, re-run the command using the correct domain ID.

Action

SEC-1039

Message <message>.

Message Type LOG

Severity ERROR

Probable Cause Indicates the domain ID entered is out of range.

Recommended Verify that the domain ID is correct. If it is not, re-run the command using the correct domain ID.

Action

SEC-1040

Message Invalid portlist (<port list>). Cannot combine * with port member in the same

portlist.

Message Type LOG

Severity ERROR

Probable Cause Indicates the port list contains the wildcard asterisk (*) character. You cannot use the asterisk in a port

list.

Recommended Enter the port list values without any wildcard characters.

Action

SEC-1041

Message Invalid port member <port member> in portlist (<port list>). <Reason>.

Message Type LOG

Severity ERROR

Probable Cause Indicates the port member is invalid for one of the following reasons:

The value is not a number.

■ The value is too long. Valid numbers must be between one and three characters long.

The value cannot be parsed due to invalid characters.

Recommended

Use valid syntax when entering port members.

Action

SEC-1042

Message Invalid index/area member <port member> in portlist (<Port list>). Out of range

(<Minimum value> - <Maximum value>).

Message Type LOG

Severity ERROR

Probable Cause Indicates the specified index or area member is not within the minimum and maximum range.

Action

SEC-1043

Message Invalid port range <Minimum> - <Maximum>.

Message Type LOG

Severity ERROR

Probable Cause Indicates the specified port is not within the minimum and maximum range.

Action

SEC-1044

Message Duplicate member <member ID> in (<List>).

Message Type LOG

Severity ERROR

Probable Cause Indicates the specified member is a duplicate in the input list. The list can be a policy list or a switch

member list.

Recommended Do not specify any duplicates.

Action

SEC-1045

Message Too many port members.

Message Type LOG

Severity ERROR

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended

Action

Run the **secFabricShow** command to verify that the fabric is still consistent. All the switches should be in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1046

Message Empty list.

Message Type LOG

Severity ERROR

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended

Action

Run the **secFabricShow** command to verify that the fabric is still consistent. All the switches should be in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1049

Message Invalid switch name <switch name>.

Message Type LOG

Severity ERROR

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended

Action

Run the **secFabricShow** command to verify that the fabric is still consistent. All the switches should be in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1050

Message There are more than one switches with the same name <switch name> in the fabric.

LOG Message Type

> Severity **ERROR**

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

> when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended Action

Run the secFabricShow command to verify that the fabric is still consistent. All the switches should be in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1051

Message Missing brace for port list <port list>.

LOG Message Type

> **ERROR** Severity

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

> when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended

Run the secFabricShow command to verify that the fabric is still consistent. All the switches should be Action

in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1052

Message Invalid input.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

> when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended

Run the secFabricShow command to verify that the fabric is still consistent. All the switches should be Action

in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1053

Message Invalid pFCS list <pFCS list>

Message Type LOG

Severity ERROR

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds these error in the security database. This is a rare

occurrence.

Recommended

Action

Run the **secFabricShow** command to verify that the fabric is still consistent. All the switches should be in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1054

Message Invalid FCS list length <list length>.

Message Type LOG

Severity ERROR

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended

Action

Run the **secFabricShow** command to verify that the fabric is still consistent. All the switches should be in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1055

Message Invalid FCS list < WWN list>.

Message Type LOG

Severity ERROR

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended

Action

Run the **secFabricShow** command to verify that the fabric is still consistent. All the switches should be in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1056

Message Invalid position < New position >. Only < Number of members in FCS list > members in list.

Message Type LOG

Severity ERROR

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended

Action

Run the **secFabricShow** command to verify that the fabric is still consistent. All the switches should be in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1057

Message No change. Both positions are the same.

Message Type LOG

Severity ERROR

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended

Action

Run the **secFabricShow** command to verify that the fabric is still consistent. All the switches should be in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1059

Message Type LOG

Severity ERROR

Probable Cause Indicates the operation failed when writing to flash memory.

Recommended Run the **supportFtp - e** command to FTP files from the switch and remove them from the flash

Action memory.

SEC-1062

Message Invalid number of Domains in Domain List.

Message Type LOG

Severity ERROR

Probable Cause Indicates that either no domains or domains more than the maximum number supported are specified.

Recommended Enter the correct number of domains.

Action

SEC-1063

Message Failed to reset statistics.

Message Type LOG

Severity ERROR

Probable Cause Indicates that either the type or the domains specified are invalid.

Recommended Enter valid input.

Action

SEC-1064

Message Failed to sign message.

Message Type LOG

Severity ERROR

Probable Cause Indicates the public key infrastructure (PKI) objects on the switch are not in a valid state and the

signature operation failed.

Recommended Run the secCertMgmt show -all command and verify in FCAP row that all PKI objects are valid. If PKI

objects are not valid, generate the PKI objects and install the certificate by following the field upgrade

process.

SEC-1065

Message Invalid character in list.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates the input list has an invalid character.

Recommended

Action Enter valid input.

SEC-1069

Message Security Database is corrupted.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates the security database is corrupted for unknown reasons.

Recommended Execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the Action

supportSave command and contact your switch service provider.

SEC-1071

Message No new security policy data to apply.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates that no changes in the defined security policy database need to be activated at this time.

Recommended Verify that the security event was planned. First change some policy definitions, and then run the secPolicyActivate command to activate the policies.

Action

SEC-1072

Message <Policy type> Policy List is Empty.

Message Type LOG

> **ERROR** Severity

Probable Cause Indicates the specific policy type is empty. The security database is corrupted for unknown reasons.

Recommended Execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the

Action supportSave command and contact your switch service provider.

SEC-1073

Message No FCS policy in list.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates the specific policy type is empty. The security database is corrupted for unknown reasons.

FOS-90x-Message-RM103 Broadcom

Recommended Action Execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

SEC-1074

Message Cannot execute the command on this switch. Please check the secure mode and FCS

status.

Message Type LOG

Severity ERROR

Probable Cause Indicates a security command was run on a switch that is not allowed to run it either because it is in

non-secure mode or because it does not have the required fabric configuration server (FCS) privilege.

Recommended

lended If a security operation that is not allowed in non-secure mode is attempted, do not perform the Action operation in non-secure mode. In secure mode, run the command from a switch that has the required

privilege; that is, either a backup FCS or primary FCS.

SEC-1075

Message Fail to <operation> new policy set on all switches.

Message Type LOG

Severity ERROR

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended

Action

Run the **secFabricShow** command to verify that the fabric is still consistent. All the switches should be in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1076

Message NoNodeWWNZoning option has been changed.

Message Type LOG

Severity ERROR

Probable Cause Indicates the NoNodeWWNZoning option has been changed. If the option is turned on, a zone

member can be added using node WWNs, but the member will not be able to communicate with others

nodes in the zone.

Recommended

Action Re-enable the current zone configuration for the change to take effect.

SEC-1077

Message Failed to activate new policy set on all switches.

Message Type LOG

Severity ERROR

Probable Cause Indicates the policy could not be activated. Possible reasons that the policy could not be activated

include not enough memory or a busy switch.

Recommended Run the **secFabricShow** command to verify that all switches in the fabric are in the ready state. Retry

Action the command when all switches are ready.

SEC-1078

Message No new data to abort.

Message Type LOG

Severity ERROR

Probable Cause Indicates there are no new changes in the defined security policy database that can be aborted.

Recommended Verify the security event was planned. Verify if there were really any changes to the defined policy

Action database that can be aborted.

SEC-1079

Message The policy name <policy name > is invalid.

Message Type LOG

Severity ERROR

Probable Cause Indicates the policy name entered in the secPolicyCreate, secPolicyActivate, secPolicyAdd, or

secPolicyDelete command was invalid.

Recommended Run the command again using a valid policy name.

Action

SEC-1080

Message Operation denied. Please use secPolicyActivate or distribute commands.

Message Type LOG

Severity ERROR

Probable Cause

Indicates a corruption occurred during the distribution of the security database. This can only occur when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare occurrence.

Recommended

Action

Run the **fabricShow** command to verify that the fabric is still consistent. All the switches should be in the ready state. If a switch is in the error state, the database may not be correctly updated for that specific switch.

SEC-1081

Message Entered a name for a DCC policy ID that was not unique.

Message Type LOG

Severity ERROR

Probable Cause Indicates the Device Connection Control (DCC) policy name given in the **secPolicyCreate** command

was the same as another DCC policy.

Recommended Make sure that the DCC policy name has a unique alphanumeric string, and run the **secPolicyCreate**

command again.

SEC-1082

Message Failed to create <policy name> policy.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates the security policy was not created because of faulty input or low resources.

Recommended Use proper syntax when creating policies. If the security database is too large, you must delete other

members within the database before adding new members to a policy.

SEC-1083

Message Name already exists.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended

Run the **fabricShow** command to verify that the fabric is still consistent. All the switches should be in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1084

Message Name exists for different type <Policy name>.

Message Type LOG

Severity ERROR

Probable Cause Indicates the specified policy already exists.

SEC-1085

Message Failed to create <policy name>.

Message Type LOG

Severity ERROR

Probable Cause Indicates the security policy was not created.

Recommended Check that the current policy configuration is valid. For example, the RSNMP policy cannot exist

Action without the WSNMP policy.

SEC-1086

Message The security database is too large to fit in flash.

Message Type LOG

Severity ERROR

Probable Cause Indicates the security database has more data than the flash memory can accommodate.

Recommended Reduce the number of entries in some policies to decrease the security database size.

Action

SEC-1087

Message The security database is larger than the data distribution limit of fabric <fabric

data distribution limit> bytes.

Message Type LOG

Severity ERROR

Probable Cause Indicates the security database has more data than can be distributed to some of the switches in the

fabric.

Recommended Action Reduce the number of entries in the security policies to decrease the security database size.

SEC-1088

Message Cannot execute the command. Please try later.

Message Type LOG

Severity ERROR

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended

Action

Run the **fabricShow** command to verify that the fabric is still consistent. All the switches should be in the ready state. If a switch is in the error state, the database may not be correctly updated for that specific switch.

SEC-1089

Message Policy name <policy name> was not found.

Message Type LOG

Severity ERROR

Probable Cause Indicates the security policy name in the secPolicyAdd command does not exist.

Recommended Create the appropriate security policy first, and then use its name in the **secPolicyAdd** command to

Action add new members.

SEC-1090

Message SCC list contains FCS member. Please remove member from the FCS policy first.

Message Type LOG

Severity ERROR

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended

Action

Run the **fabricShow** command to verify that the fabric is still consistent. All the switches should be in the ready state. If a switch is in the error state, the database may not be correctly updated for that specific switch.

SEC-1091

Message No policy to remove.

Message Type LOG

Severity ERROR

Probable Cause Indicates the specified policy member does not exist or the policy itself does not exist.

Recommended Verify that the security policy name or member ID is correct.

Action

SEC-1092

Message <Policy name > Name not found.

Message Type LOG

Severity ERROR

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended

Action

Run the **fabricShow** command to verify that the fabric is still consistent. All the switches should be in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1093

Message New FCS list must have at least one member in common with current FCS list.

Message Type LOG

Severity ERROR

Probable Cause Indicates the new fabric configuration server (FCS) list does not have a common member with the

existing FCS list.

Recommended Resubmit the command with at least one member of the new FCS list in common with the current FCS

Action list.

SEC-1094

Message Policy member not found.

Message Type LOG

Severity ERROR

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds that there is an error in the security database. This

is a rare occurrence.

Recommended

Run the **fabricShow** command to verify that the fabric is still consistent. All the switches should be in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1095

Message Deleting FCS policy is not allowed.

Message Type LOG

Severity ERROR

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended

Action

Run the **fabricShow** command to verify that the fabric is still consistent. All the switches should be in

the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1096

Message Failed to delete <policy name> because <reason text>.

Message Type LOG

Severity ERROR

Probable Cause Indicates a policy cannot be removed because deleting it would result in an invalid security policy

configuration.

Recommended Verify the security policy configuration requirements and remove any policies that require the policy

Action you want to be removed first.

SEC-1097

Message Cannot find <active or defined> policy set.

LOG Message Type

> Severity **ERROR**

Probable Cause Indicates the specified policy could not be found.

Recommended If the message persists, run supportFtp (as needed) to set up automatic FTP transfers; then run the Action

supportSave command and contact your switch service provider.

SEC-1098

Message No <active or defined> FCS list.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates the specified policy could not be found.

Recommended Execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the

supportSave command and contact your switch service provider.

SEC-1099

Message Please enable your switch before running secModeEnable.

Message Type LOG

Action

Severity **ERROR**

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

> when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Run the fabricShow command to verify that the fabric is still consistent. All the switches should be in Recommended

the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1100

Message FCS switch present. Command terminated.

Message Type LOG

Action

Severity **ERROR**

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

when the primary fabric configuration server (FCS) distributes the security database to the other

FOS-90x-Message-RM103 Broadcom

switches in the fabric, and then local validation finds the error in the security database. This is a rare occurrence.

Recommended

Action the real

Run the **fabricShow** command to verify that the fabric is still consistent. All the switches should be in the ready state. If a switch is in the error state, the database may not be correctly updated for that specific switch.

SEC-1101

Message Failed to enable security on all switches. Please retry later.

Message Type LOG

Severity ERROR

Probable Cause Indicates the security enable failed on the fabric because one or more switches in the fabric are busy.

Recommended Verify that the security event was planned. If the security event was planned, run the **secFabricShow** command to verify that all switches in the fabric are in the ready state. When all switches are in the

ready state, retry the operation.

SEC-1102

Message Fail to download <security data>.

Message Type LOG

Severity ERROR

Probable Cause Indicates the switch failed to download a certificate, security database, or policies. This can happen

when the switch does not get enough resources to complete the operation, the fabric has not

stabilized, or the policy database is an invalid format.

Recommended Wait for the fabric to become stable and then retry the operation. If the policy database is in an illegal

format (with **configDownload** command), correct the format and retry the operation.

SEC-1104

Message Fail to get primary <Certificate or public key>.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates the switch failed to get either the primary certificate or a primary public key.

Recommended Verify the primary switch has a valid certificate installed and retry the operation. If a valid certificate is not installed, install a certificate by following the procedure specified in the *Fabric OS Administrator's*

Guide.

SEC-1105

Message Fail to disable secure mode on all switches.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates the switch failed to disable security in the fabric. This could happen if the switch cannot get

the required resources to complete the command, and sending to a remote domain fails or the remote

domain returns an error.

Recommended Run the secFabricShow to verify that all switches in the fabric are in the ready state. Retry the

command when all switches are ready.

SEC-1106

Message Failed to sign message data.

Message Type LOG

Action

ERROR Severity

Probable Cause Indicates that some public key infrastructure (PKI) objects on the switch are not in a valid state, and a

signature operation failed.

Recommended Run the secCertMgmt show -all command and verify in FCAP row that all PKI objects exist on the

switch. If a failure to validate PKI objects occurs, follow the steps for re-creating PKI objects.

SEC-1107

Message Stamp is 0.

Message Type LOG

Action

INFO Severity

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

> when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended Run the secFabricShow command to verify that the fabric is still consistent. All the switches should be Action

in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1108

Message Fail to reset stamp on all switches.

Message Type LOG

Severity ERROR

Probable Cause Indicates that a version reset operation failed either because the switch could not get all the required

resources to perform the operation or because it failed to send the message to all switches in the

fabric.

Recommended

Action

Verify that the security event was planned. If the security event was planned, run the **secFabricShow** command to verify that all switches in the fabric are in the ready state. When all switches are in the

ready state, retry the operation.

SEC-1110

Message FCS list must be the first entry in the [Defined Security policies] section. Fail to

download defined database.

Message Type LOG

Severity ERROR

Probable Cause Indicates that a security policy download was attempted with a defined policy that does not have the

fabric configuration server (FCS) policy as the first policy. The FCS policy is required to be the first

policy in the defined security database.

Recommended

Action

Download a correct configuration with the fabric configuration server (FCS) policy as the first policy in

the defined security database.

SEC-1111

Message New defined FCS list must have at least one member in common with current active FCS

list. Fail to download defined database.

Message Type LOG

Severity ERROR

Probable Cause Indicates the defined and active fabric configuration server (FCS) policy list failed to have at least one

member in common.

Recommended A new FCS policy list must have at least one member in common with the previous FCS policy.

Action

SEC-1112

Message FCS list must be the first entry in the Active Security policies, and the same as the

current active FCS list in the switch.

Message Type LOG

Severity ERROR

Probable Cause Indicates either a security policy download was attempted with an active policy that does not have the

fabric configuration server (FCS) policy as the first policy, or the FCS policy is not the same as the

current FCS policy on the switch.

Recommended

nended Make sure that the new FCS policy is the same as the current FCS policy on the switch.

SEC-1113

Message <Key> [<Feature> license] going to expire in <Expiry days> day(s).

Message Type LOG | AUDIT

Class SECURITY

Severity WARNING

Probable Cause Indicates the license period will expire soon.

Recommended Get a new license for this feature.

Action

SEC-1114

Message <Key> [<Feature> license] has expired.

Message Type LOG | AUDIT

Class SECURITY

Severity WARNING

Probable Cause Indicates the license period has expired.

Recommended Get a new license for this feature.

Action

SEC-1115

Message No primary FCS to failover.

Message Type LOG

Severity ERROR

Probable Cause Indicates that during an attempted **secFcsFailover**, no primary FCS is present in the fabric.

Recommended

Action

Run the **secFabricShow** command to verify that all switches in the fabric are in the ready state. When all switches are in the ready state, retry the operation.

SEC-1116

Message Fail to commit failover.

Message Type LOG

Severity ERROR

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended

Run the **secFabricShow** command to verify that the fabric is still consistent. All the switches should be Action in the ready state. If a switch is in the error state, the database may not be correctly undated for that

in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1117

Message Fail to set <data>.

Message Type LOG

Severity INFO

Probable Cause Indicates the switch failed to save the data received by the primary fabric configuration server (FCS)

switch. This data can be an FCS password, a non-FCS password, SNMP data, or multiple user

authentication data.

Recommended

Action

Run the fabricShow command to verify that all switches in the fabric are in the ready state. When all

switches are in the ready state, retry the operation.

SEC-1118

Message Fail to set SNMP string.

Message Type LOG

Severity INFO

Probable Cause Indicates the SNMP string could not be set. Usually this problem is transient.

Recommended Retry the command.

Action

SEC-1119

Message Secure mode has been enabled.

LOG Message Type

> INFO Severity

Probable Cause Indicates the secure Fabric OS was enabled by the **secModeEnable** command.

Recommended Verify the security event was planned. If the security event was planned, there is no action required. If Action

the security event was not planned, take appropriate action as defined by your enterprise security

policy.

SEC-1121

Message Time is out of range when <text>.

Message Type LOG

> **ERROR** Severity

Probable Cause Indicates the time on the switch is not synchronized with the primary fabric configuration server (FCS),

the data packet is corrupted, or a replay attack is launched on the switch.

Recommended Verify the security event was planned. If the security event was planned, verify that all switches in the

fabric are in time synchronization with the primary FCS and that no external entity is trying to access

the fabric. When verification is complete, retry the operation.

SEC-1122

Message Error code: <Domain ID>, <Error message>.

Message Type LOG

Action

Severity **INFO**

Probable Cause Indicates that one of the switches in the fabric could not communicate with the primary fabric

configuration server (FCS).

Recommended Run the fabricShow command to verify that all switches in the fabric are in the ready state. When all

Action switches are in the ready state, retry the operation.

SEC-1123

Message Security database downloaded by Primary FCS.

Message Type LOG

> Severity INFO

Probable Cause Indicates the security database was successfully downloaded from the primary fabric configuration

server (FCS).

SEC-1124

Message Secure Mode is off.

Message Type LOG

> Severity **INFO**

Probable Cause Indicates that a secure mode disable is attempted in a non-secure fabric.

SEC-1126

Message Secure mode has been disabled.

Message Type LOG

> **INFO** Severity

Probable Cause Indicates that a secure mode disable operation completed successfully.

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the Action

security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-1130

Message The Primary FCS has failed over to a new switch.

Message Type LOG

> INFO Severity

Probable Cause Indicates a fabric configuration server (FCS) failover operation was completed successfully.

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the

Action security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-1135

Message Secure fabric version stamp has been reset.

Message Type LOG

> **INFO** Severity

Probable Cause Indicates the version stamp of the secure fabric is reset.

Recommended

Action

Verify the security event was planned. If the security event was planned, no action is required. If the security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-1136

Message Failed to verify signature <data type, MUA, policy, etc.,>.

Message Type LOG

Severity ERROR

Probable Cause

Indicates the receiving switch failed to validate the security database sent from the primary fabric configuration server (FCS) switch. This message usually indicates that the data package is corrupted, the time stamp on the package is out of range as a result of a replay attack or out-of-sync time service, or the signature verification failed. Signature verification failure indicates either an internal error (such as losing the primary public key) or an invalid database.

Recommended

Action

Run the **secFabricShow** command to verify that the fabric is still consistent. All the switches should be in the ready state. If a switch is in the error state, the database may not be correctly updated for that switch. This message may also be the result of an internal corruption or a hacker attack to the secure fabric.

SEC-1137

Message No signature in <data type, MUA, policy, etc.,>.

Message Type LOG

Severity ERROR

Probable Cause

Indicates the receiving switch failed to validate the security database sent from the primary fabric configuration server (FCS) switch. This message usually indicates that the data package is corrupted, the time stamp on the package is out of range as a result of a replay attack or out-of-sync time service, or the signature verification failed. Signature verification failure indicates either an internal error (such as losing the primary public key) or an invalid database.

Recommended

Action

Run the **secFabricShow** command to verify that the fabric is still consistent. All the switches should be in the ready state. If a switch is in the error state, the database may not be correctly updated for that switch. This message may also be the result of an internal corruption or a hacker attack to the secure fabric.

SEC-1138

Message Security database download received from Primary FCS.

Message Type LOG

Severity INFO

Probable Cause Indicates that a non-primary fabric configuration server (FCS) switch received a security database

download.

Recommended

Action

Verify that the security event was planned. If the security event was planned, no action is required. If the security event was not planned, take appropriate action as defined by your enterprise security

policy.

SEC-1139

Message The RSNMP POLICY cannot exist without the WSNMP POLICY.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the receiving switch failed to validate the security database sent from the primary fabric

configuration server (FCS) switch. This message usually indicates that the data package is corrupted, the time stamp on the package is out of range as a result of a replay attack or out-of-sync time service, or the signature verification failed. Signature verification failure indicates either an internal error (such

as losing the primary public key) or an invalid database.

Recommended

Action

Run the **secFabricShow** command to verify that the fabric is still consistent. All the switches should be in the ready state. If a switch is in the error state, the database may not be correctly updated for that switch. This message may also be the result of an internal corruption or a hacker attack to the secure

fabric.

SEC-1142

Message Reject new policies. <reason text>.

Message Type LOG

Severity INFO

Probable Cause Indicates the new polices are rejected because of the reason specified.

Recommended

Action

Use proper syntax when entering policy information.

SEC-1145

Message A security admin event has occurred. This message is for information purpose only.

The message for individual event is: <Event specific data>.

Message Type LOG

Severity INFO

Probable Cause Indicates one of the following has occurred:

- The names for the specified policies have changed.
- The passwords have changed for the specified accounts.
- The SNMP community strings have been changed.

Recommended Action Verify the security event was planned. If the security event was planned, no action is required. If the security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-1146

Message PID changed: <State>.

Message Type LOG

> **INFO** Severity

Probable Cause Indicates the PID format of the switch was changed either to extended-edge PID or from extended-

> edge PID. If the Device Connection Control (DCC) polices existed, all index/area ID values either increased or decreased by 16. The values wrap around after 128. If a DCC policy contains an index/ area of 127 before changing to extended-edge PID, then the new index/area is 15, because of the

wraparound.

SEC-1153

Message Error in RCA: RCS is not supported.

Message Type LOG

> INFO Severity

Probable Cause Indicates that reliable commit service (RCS) is not supported.

RCS must be capable on all switches in the fabric to be enabled. If all switches are capable, it is

automatically enabled.

Recommended

Action

For any switch that does not support RCS, obtain the latest firmware version from your switch supplier,

and run the firmwareDownload command to upgrade the firmware.

If the message persists, execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the supportSave command and contact your switch service provider.

SEC-1154

Message PID change failed: <Reason> <defined status> <active status>.

Message Type LOG

> Severity **INFO**

Probable Cause Indicates that either the defined or the active policy could not be updated. If the policy database is very

> large, it might not be able to change the index/area because the new policy database exceeds the maximum size. This message can also be caused when the switch is short of memory. The status values can be either defined, active, or both. A negative value means that a policy set was failed by the

daemon.

Recommended Action Reduce the size of the policy database.

Acti

SEC-1155

Message PID change failed: <Reason> <defined status> <active status>.

Message Type LOG

Severity INFO

Probable Cause Indicates that either the defined or active policy was too large after modifying the index/area ID. The

status values can be either defined, active, or both. A negative value means that a policy set was failed

by the daemon.

Recommended

Action

Reduce the size of the specified policy database.

SEC-1156

Message Change failed: <Reason> <defined status> <active status>.

Message Type LOG

Severity INFO

Probable Cause Indicates the security daemon is busy. The status values can be defined, active, or both. A negative

value means that a policy set was failed by the daemon.

Recommended

Action

For the first reject, wait a few minutes and then resubmit the transaction. Fabric-wide commands may take a few minutes to propagate throughout the fabric. Make sure to wait a few minutes between

executing commands so that your commands do not overlap in the fabric.

SEC-1157

Message PID Change failed: <Reason> <defined status> <active status>.

Message Type LOG

Severity INFO

Probable Cause Indicates the provisioning resources for a security policy failed because of low memory or internal

error. The status values can be defined, active, or both. A negative value means that a policy set was

failed by the daemon.

Recommended Retry the failed command.

Action

If the message persists, execute the supportFtp command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

SEC-1158

Message Invalid name < Policy or Switch name >.

Message Type LOG

Severity INFO

Probable Cause Indicates the specified name is invalid. The name can be a policy name or a switch name.

Recommended Enter a valid name.

Action

SEC-1159

Message Non_Reachable domain <Domain ID>.

Message Type LOG

Severity INFO

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended

Action

Run the **secFabricShow** command to verify that the fabric is still consistent. All the switches should be in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1160

Message Duplicate port <port ID> in port list (<port list>).

Message Type LOG

Severity INFO

Probable Cause Indicates a duplicate port member exists in the specified port list.

Recommended Verify that there is no duplicate port member in the port list.

Action

SEC-1163

Message System is already in secure mode. Lockdown option cannot be applied.

Message Type LOG

Severity ERROR

Probable Cause Indicates the lockdown option was attempted while the fabric is in secure mode.

Recommended Do not use the lockdown option with the secModeEnable command when a switch is already in

Action secure mode.

SEC-1164

Message Lockdown option cannot be applied on a non-FCS switch.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates the attempt to enable security is made on a switch that is not present in the fabric

configuration server (FCS) list.

Recommended Add the switch to the FCS policy list when using the lockdown option to enable security.

Action

SEC-1165

Message Low memory, failed to enable security on all switches.

Message Type LOG

> **ERROR** Severity

Indicates the system is low on memory. **Probable Cause**

Recommended Wait a few minutes and try the command again.

Action

SEC-1166

Message Non FCS tries to commit failover.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

> when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended Run the secFabricShow command to verify that the fabric is still consistent. All the switches should be Action

in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1167

Message Another FCS failover is in process. Command terminated.

Message Type LOG

Severity ERROR

Probable Cause Indicates that because another failover is already in progress, this failover attempt cannot proceed.

Recommended Action Verify the security event was planned. If the security event was planned, retry fabric configuration server (FCS) failover after the current failover has completed, if this switch should become the primary

FCS. If the security event was not planned, take appropriate action as defined by your enterprise

security policy.

SEC-1168

Message Primary FCS failover is busy. Please retry later.

Message Type LOG

Severity ERROR

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended

Action

Run the **secFabricShow** command to verify that the fabric is still consistent. All the switches should be in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1170

Message This command must be executed on the Primary FCS switch, the first reachable switch

in the FCS list.

Message Type LOG

Severity INFO

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended

Action

Run the **secFabricShow** command to verify that the fabric is still consistent. All the switches should be in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1171

Message Disabled secure mode due to invalid security object.

Message Type LOG

Severity ERROR

Probable Cause Indicates the switch is segmented, and secure mode is disabled on the switch because there was no

license present or no public key infrastructure (PKI) objects.

Recommended Run the secCertMgmt show -all command and verify in FCAP row whether all PKI objects exist. If

Action they do not exist, run the **secCertMgmt** command to create them for the switch.

Run the licenseAdd command to install the required license key. Contact your switch supplier to

obtain a license if you do not have one.

SEC-1172

Message Failed to identify role.

Message Type LOG

Severity ERROR

Probable Cause Indicates the switch is unable to determine its role (primary FCS or backup FCS) in the secure fabric.

Recommended Verify all switches in the fabric are in time synchronization with the primary FCS and that no external

entity is trying to access the fabric. When verification is complete, retry the operation.

SEC-1173

Message Lost contact with Primary FCS switch.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates the switch has lost contact with the primary fabric configuration server (FCS) switch in the

secure fabric. This could result from the primary FCS being disabled.

Recommended If the primary FCS was disabled intentionally, no action is required; if not, check the primary FCS.

Action

SEC-1174

Message Failed to set <FCS or non-FCS> password.

Message Type LOG

ERROR Severity

Probable Cause Indicates the fabric configuration server (FCS) or non-FCS password could not be set.

Recommended Verify all switches in the fabric are in time synchronization with the primary FCS and that no external Action

entity is trying to access the fabric. When verification is complete, retry the operation.

SEC-1175

Message Failed to install zone data.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates the zone database could not be installed on the switch.

Recommended Verify all switches in the fabric are in time synchronization with the primary FCS and that no external Action

entity is trying to access the fabric. When verification is complete, retry the operation.

SEC-1176

Message Failed to generate new version stamp.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates the primary fabric configuration server (FCS) failed to generate a new version stamp

because the fabric was not stable.

Recommended Verify all switches in the fabric are in time synchronization with the primary FCS and that no external

Action entity is trying to access the fabric. When verification is complete, retry the operation.

SEC-1180

Message Added account <user name> with <role name> authorization.

Message Type LOG

> Severity INFO

Probable Cause Indicates the specified new account has been created.

SEC-1181

Message Deleted account <user name>.

Message Type LOG

FOS-90x-Message-RM103 Broadcom

Severity INFO

Probable Cause Indicates the specified account has been deleted.

SEC-1182

Message Recovered <number of> accounts.

Message Type LOG

Severity INFO

Probable Cause Indicates the specified number of accounts has been recovered from backup.

SEC-1183

Message Policy to binary conversion error: Port <port number> is out range.

Message Type LOG

Severity ERROR

Probable Cause Indicates a security database conversion has failed because of an invalid value.

Recommended Retry the command with a valid value.

Action

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

SEC-1184

Message <Security server (RADIUS/LDAP/TACACS+)> configuration change, action <action>, server

ID <server name>.

Message Type LOG

Severity INFO

Probable Cause Indicates the specified action is applied to the specified remote authentication dial-in user service

(RADIUS/LDAP/TACACS+) server configuration. The possible actions are ADD, REMOVE, CHANGE,

and MOVE.

SEC-1185

Message <action> switch DB.

Message Type LOG

Severity INFO

Probable Cause Indicates the switch database was enabled or disabled as the secondary authentication, authorization,

and accounting (AAA) mechanism when remote authentication dial-in user service (RADIUS/LDAP/TACACS+) is the primary AAA mechanism.

SEC-1186

Message <Security server (RADIUS/LDAP/TACACS+)> <action> Configuration.

Message Type LOG

Severity INFO

Probable Cause Indicates the RADIUS, LDAP, or TACACS+ configuration was enabled or disabled as the primary

authentication, authorization, and accounting (AAA) mechanism.

SEC-1187

Message Security violation: Unauthorized switch <switch WWN> tries to join fabric.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates a Switch Connection Control (SCC) security violation was reported. The specified

unauthorized switch attempts to join the fabric.

Recommended Check the SCC policy to verify the switches allowed in the fabric. If the switch should be allowed in the

fabric but it is not included in the SCC policy, add the switch to the policy. If the switch is not allowed access to the fabric, this is a valid violation message and an unauthorized entity is trying to access

your fabric. Take appropriate action, as defined by your enterprise security policy.

SEC-1188

Message Security violation: Unauthorized device <device node name> tries to FLOGI to index/

area <port number> of switch <switch WWN>.

Message Type LOG

Severity INFO

Probable Cause Indicates a Device Connection Control (DCC) security violation was reported. The specified device

attempted to log in using fabric login (FLOGI) to an unauthorized port. The DCC policy correlates specific devices to specific port locations. If the device changes the connected port, the device will not

be allowed to log in.

Recommended Check the DCC policy and verify the specified device is allowed in the fabric and is included in the Action DCC policy. If the specified device is not included in the policy add it to the policy. If the host is not

DCC policy. If the specified device is not included in the policy, add it to the policy. If the host is not allowed access to the fabric, this is a valid violation message and an unauthorized entity is trying to

access your fabric. Take appropriate action, as defined by your enterprise security policy.

SEC-1189

Message Security violation: Unauthorized host with IP address <IP address> tries to do SNMP

write operation.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates an SNMP security violation was reported. The specified unauthorized host attempted to

perform a write SNMP operation.

Recommended Check the WSNMP policy and verify which hosts are allowed access to the fabric through SNMP. If the

host is allowed access to the fabric but is not included in the policy, add the host to the policy. If the host is not allowed access to the fabric, this is a valid violation message and an unauthorized entity is

trying to access your fabric. Take appropriate action, as defined by your enterprise security policy.

SEC-1190

Message Security violation: Unauthorized host with IP address <IP address> tries to do SNMP

read operation.

Message Type LOG

Severity INFO

Probable Cause Indicates an SNMP security violation was reported. The specified unauthorized host attempted to

perform a read SNMP (RSNMP) operation.

Recommended Check the RSNMP policy to verify the hosts allowed access to the fabric through SNMP read

Action operations are included in the RSNMP policy. If the host is allowed access but is not included in the

RSNMP policy, add the host to the policy. If the host is not allowed access to the fabric, this is a valid violation message and an unauthorized entity is trying to access your fabric. Take appropriate action,

as defined by your enterprise security policy.

SEC-1191

Message Security violation: Unauthorized host with IP address < Ip address > tries to establish

HTTP connection.

Message Type LOG

Severity INFO

Probable Cause Indicates an HTTP security violation was reported. The specified unauthorized host attempted to

establish an HTTP connection.

Recommended Determine whether the host IP address specified in the message can be used to manage the fabric

Action through an HTTP connection. If so, add the host IP address to the HTTP policy of the fabric. If the host

is not allowed access to the fabric, this is a valid violation message and an unauthorized entity is trying to access your fabric. Take appropriate action, as defined by your enterprise security policy.

SEC-1192

Message Security violation: Login failure attempt via <connection method>.

Message Type LOG

Severity INFO

Probable Cause Indicates a serial or modem login security violation was reported. The wrong password was used while

trying to log in through a serial or modem connection; the login failed.

Recommended

Action

Use the correct password.

SEC-1193

Message Security violation: Login failure attempt via <connection method>. IP Addr: <IP

address>.

Message Type LOG

Severity INFO

Probable Cause Indicates a specified login security violation was reported. The wrong password was used while trying

to log in through the specified connection method; the login failed.

Recommended The error message lists the violating IP address. Verify that this IP address is being used by a valid

switch admin. Use the correct password.

SEC-1194

Message This switch does not have all the required PKI objects correctly installed.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended

Action

Run the **secFabricShow** command to verify that the fabric is still consistent. All the switches should be in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1195

Message This switch has no <component> license.

Message Type LOG

> Severity WARNING

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

> when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended

Run the secFabricShow command to verify that the fabric is still consistent. All the switches should be Action in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1196

Message Switch does not have all default account names.

LOG Message Type

> WARNING Severity

Probable Cause Indicates the default switch accounts admin and user do not exist on the switch when enabling

security.

Reset the default admin and user account names on the switch that reported the warning and retry Recommended

Action enabling security.

SEC-1197

Message Changed account <user name>.

LOG Message Type

> Severity **INFO**

Probable Cause Indicates the specified account has changed.

SEC-1198

Security violation: Unauthorized host with IP address <IP address> tries to establish Message

API connection.

Message Type LOG

> Severity INFO

FOS-90x-Message-RM103 Broadcom

Probable Cause Indicates an API security violation was reported. The specified unauthorized host attempted to

establish an API connection.

Recommended

Action

Check to see if the host IP address specified in the message can be used to manage the fabric through an API connection. If so, add the host IP address to the API policy of the fabric. If the host is not allowed access to the fabric, this is a valid violation message and an unauthorized entity is trying to access your fabric. Take appropriate action, as defined by your enterprise security policy.

SEC-1199

Message Security violation: Unauthorized access to serial port of switch <switch instance>.

Message Type LOG

Severity INFO

Probable Cause Indicates a serial connection policy security violation was reported. An attempt was made to access

the serial console on the specified switch instance when it is disabled.

Recommended

Action

Check to see if an authorized access attempt is being made on the console. If so, add the switch WWN to the serial policy. If the host is not allowed access to the fabric, this is a valid violation message and an unauthorized entity is trying to access your fabric. Take appropriate action, as defined by your enterprise security policy.

enterprise security

SEC-1200

Message Security violation: MS command is forwarded from non-primary FCS switch.

Message Type LOG

Severity INFO

Probable Cause Indicates a management server (MS) forward security violation was reported. A management server

command was forwarded from a non-primary fabric configuration server (FCS) switch.

Recommended

Action

Check the MS policy and verify that the connection is allowed. If the connection is allowed but not specified, enable the connection in the MS policy. If the MS policy does not allow the connection, this is a valid violation message and an unauthorized entity is trying to access your fabric. Take appropriate

action, as defined by your enterprise security policy.

SEC-1201

Message Security violation: MS device <device WWN> operates on non-primary FCS switch.

Message Type LOG

Severity INFO

Probable Cause Indicates a management server (MS) operation security violation was reported. An MS device

operation occurred on a non-primary fabric configuration server (FCS) switch.

Recommended

Action

Check the management server policy and verify the connection is allowed. If the connection is allowed but not specified, enable the connection in the MS policy. If the MS policy does not allow the connection, this is a valid violation message and an unauthorized entity is trying to access your fabric. Take appropriate action, as defined by your enterprise security policy.

SEC-1202

Message Security violation: Unauthorized access from MS device node name <device node name>,

device port name <device port name>.

Message Type LOG

Severity INFO

Probable Cause Indicates a management server (MS) security violation was reported. The unauthorized device

specified in the message attempted to establish a connection.

Recommended Check the MS server policy and verify that the connection is allowed. If the connection is allowed but

not specified, enable the connection in the MS policy. If the MS policy does not allow the connection, this is a valid violation message and an unauthorized entity is trying to access your fabric. Take

appropriate action, as defined by your enterprise security policy.

SEC-1203

Message Login information: Login successful via: <Login method>. IP Addr: <IP address>

Message Type LOG

Action

Severity INFO

Probable Cause Indicates the IP address of the remote station logging in.

SEC-1250

Message DCC enforcement API failed: <failed action> err=<status>, key=<data>

Message Type LOG

Severity WARNING

Probable Cause Indicates an internal error caused the Device Connection Control (DCC) policy enforcement to fail.

Recommended Retry the failed security command.

Action

If the message persists, run **supportFtp** (as needed) to set up automatic FTP transfers; then run the

supportSave command and contact your switch service provider.

SEC-1251

Message Policy to binary conversion error: <text message> <value>.

Message Type LOG

Severity ERROR

Probable Cause Indicates the security database conversion failed because of invalid values. The reason is specified in

the *text message* variable and the faulty value is printed in the *value* variable.

Recommended Retry the failed security command.

Action

If the message persists, run **supportFtp** (as needed) to set up automatic FTP transfers; then run the

supportSave command and contact your switch service provider.

SEC-1253

Message Bad DCC interface state during <Phase>, state=<state>.

Message Type LOG

Severity ERROR

Probable Cause Indicates an internal error has caused the Device Connection Control (DCC) policy update to fail in the

provision, commit, or cancel phases.

Recommended Retry the failed security command.

Action

If the message persists, run supportFtp (as needed) to set up automatic FTP transfers; then run the

supportSave command and contact your switch service provider.

SEC-1300

Message This switch is in VcEncode mode. Security is not supported.

Message Type LOG

Severity INFO

Probable Cause Indicates the switch is set up with VC-encoded mode.

Recommended Turn off VC-encoded mode before enabling security.

Action

SEC-1301

Message This switch is in interop mode. Security is not supported.

Message Type LOG

Severity INFO

Recommended

Probable Cause Indicates the switch is enabled in interop mode.

Action feature.

SEC-1302

Message This switch does not have all the required PKI objects correctly installed.

Message Type LOG

Severity INFO

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

Disable interop mode using the interopMode command before enabling the Secure Fabric OS

occurrence.

Recommended Run the **secFabricShow** command to verify that the fabric is still consistent. All the switches should be

Action in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1303

Message This software version does not support security.

Message Type LOG

Severity INFO

Probable Cause Indicates the currently installed software version does not support the Brocade Secure Fabric OS

feature.

Recommended Run the **firmwareDownload** command to update the firmware to the latest version for your specific

switch. Verify the firmware you are installing supports the Brocade Secure Fabric OS feature.

SEC-1304

Message This switch has no security license.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and then local validation finds the error in the security database. This is a rare

occurrence.

Recommended Action Run the **secFabricShow** command to verify the fabric is still consistent. All the switches should be in the ready state. If a switch is in the error state, the database may not be correctly updated for that specific switch.

SEC-1305

Message This switch has no zoning license.

Message Type LOG

Severity INFO

Probable Cause Indicates a corruption occurred during the distribution of the security database. This can only occur

when the primary fabric configuration server (FCS) distributes the security database to the other switches in the fabric, and the local validation finds the error in the security database. This is a rare

occurrence.

Recommended

Action

Run the **secFabricShow** command to verify the fabric is still consistent. All the switches should be in the ready state. If a switch is in the error state, the database may not be correctly updated for that

specific switch.

SEC-1306

Message Failed to verify certificate with root CA.

Message Type LOG

Severity INFO

Probable Cause Indicates the certificate could not be verified with root certificate authority (CA). This could happen if an

unauthorized switch tries to access the fabric that is not certified by a trusted root CA or a root CA

certificate does not exist on the switch.

Recommended

Action

Run the **secCertMgmt show -all** command and verify in FCAP row that all public key infrastructure (PKI) objects exist on the switch. If a failure to validate PKI objects occurs, follow the steps for recreating PKI objects. If PKI objects are valid, verify that an unauthorized switch is not trying to access

the fabric.

SEC-1307

Message <Security server (RADIUS/LDAP/TACACS+)> server <Server name> authenticated user

account '<username>'. <LDAP local authorization>

Message Type LOG

Severity INFO

Probable Cause Indicates that after some servers timed out, the specified RADIUS, LDAP, or TACACS+ server

responded to a switch request or if a LDAP user is authorized using switch local database

Recommended

Action

If the message appears frequently, move the responding server to the top of the RADIUS/LDAP/ TACACS+ server configuration list using the **aaaConfig** command or configure remote authorization for LDAP user.

SEC-1308

Message

All <Radius/LDAP/TACACS+ server identity> servers failed to authenticate user account '<username>'.

Message Type

LOG

Severity

INFO

Probable Cause

Indicates that all servers in the RADIUS, LDAP, or TACACS+ configuration have failed to respond to a switch request within the specified timeout. For RADIUS PEAP-MSCHAPv2 authentication with a Windows server, if user account name matches that of a role/group on the server with administrative privileges such as "admin", "maintenance", or "root", this message will be displayed as well.

Recommended

Action

Verify the switch has proper network connectivity to the specified RADIUS, LDAP, or TACACS+s servers, and the servers are correctly configured.

SEC-1309

Message

Waiting for RCS transaction to complete: <Wait time in seconds> secs

Message Type

Severity

INFO

LOG

Probable Cause

Indicates that Fabric OS is still waiting for the reliable commit service (RCS) transaction to complete.

Recommended

Action

Verify if there are any reliable commit service (RCS) or Reliable Transport With Response (RTWR)

errors. If not, the transaction is still in progress.

SEC-1310

Message

Unable to determine data distribution limit of fabric. Please retry later.

Message Type

LOG

Severity

INFO

Probable Cause

Indicates the data distribution limit could not be obtained from all switches in the fabric. This may happen if the fabric is reconfiguring or a new domain joined the fabric.

Recommended

Action

Retry the command when the fabric is stable.

SEC-1311

Message Security mode cannot be enabled because one or more of the password policies is not

set to default value.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates the security enable failed on the fabric because one or more switches in the fabric have

password policies that are not set to the default values.

Recommended Verify the security event was planned.

Action

If the security event was planned, run the passwdCfg --setdefault command on each switch in the fabric to set the password policies to the default values. Then verify with the passwdCfg --showall

command that password policies are set to the default values on all switches and retry the

secModeEnable command.

SEC-1312

Message <MESG Message>.

Message Type LOG

> Severity INFO

Probable Cause Indicates the password configuration parameters changed.

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the Action

security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-1313

Message The passwdcfg parameters were set to default values.

Message Type LOG

> Severity **INFO**

Probable Cause Indicates the password configuration parameters were set to default values.

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the Action

security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-1314

Message Reading <IP Address Description> IP address from EM failed.

Message Type LOG

> Severity **ERROR**

FOS-90x-Message-RM103 Broadcom

Probable Cause Indicates the call to the environment monitor (EM) module to retrieve the IP address failed.

Recommended Reboot the system to fix this error. If the problem persists, contact your switch service provider.

Action

SEC-1315

Message <Name of command> command failed -<List of databases rejecting distribution> db(s)

configured for rejection on this switch.

Message Type LOG

Severity ERROR

Probable Cause Indicates there was an attempt to distribute databases to a switch that was configured not to accept

distributions from the fabric.

Recommended Verify the accept distribution configuration for the listed databases. Use the **remoteeCfg** command to

verify and correct the configuration if necessary.

SEC-1316

Message <Policy Name> policy WWN List is conflicting with domain <Domain Number>.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates the newly added switches to the fabric, as specified by domain number, have a conflicting

policy with the local switch.

Recommended Check the conflicting policy and make the new switches and the local switch policies the same.

Action

SEC-1317

Message Inconsistent fabric, rejecting transaction

Message Type LOG

Severity INFO

Probable Cause Indicates that either this domain is performing FDD merge or matched domains are not the same as

what CM sees.

Recommended If a policy conflict exists, resolve it, and then wait for the fabric to become stable. Retry the distribution.

Action

SEC-1318

Message Transaction rejected due to inconsistent fabric.

Message Type LOG

Severity INFO

Probable Cause Indicates that some domains detected an inconsistent fabric.

Recommended Resolve the policy conflict, if there is one, and then wait for the fabric to stabilize. Retry the distribution.

Action

SEC-1319

Message <Event name> updated<Datasets updated> dbs(s).

Message Type LOG

Severity INFO

Probable Cause Indicates the specified event has occurred.

Recommended Verify the event was planned. If the event was planned, no action is required. If the event was not

Action planned, take appropriate action as defined by your enterprise security policy.

SEC-1320

SEC-1321

Message Non-acl domain <Domain Number> tries to join a fabric with strict fabric wide policy.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a domain not supporting an access control list (ACL) policy tried to join a fabric with the

strict fabric-wide policy.

Recommended No action is required. The domain is denied by disallowing all its E Ports from connecting to the fabric.

Action

Message Failed secure mode enable command. Reason: <Reason>.

Message Type LOG

Severity ERROR

Probable Cause Indicates the security enable failed on the fabric because the switch has a conflicting configuration

such as fabric-wide consistency configuration or AD configuration.

Recommended

Action Verify the security event was planned. If the security event was planned, run the fddCfg --fabwideset

command or ad --clear command to clear the fabric wide consistency configuration or AD

configuration and retry the **secModeEnable** command.

SEC-1322

Message Some DCC policy is too large, distribution cancelled.

Message Type LOG

Severity WARNING

Probable Cause Indicates this fabric is not able to support a Device Connection Control (DCC) policy with more than

256 ports.

Recommended Reconfigure any policy that includes more than 256 ports in its member list, and then save the policy

Action configuration changes.

SEC-1323

Message Key(s) \"<Key Name>\" ignored during configdownload.

Message Type LOG

Severity INFO

Probable Cause Indicates the specified key is ignored during configuration download.

Recommended Verify the event was planned. If the event was planned, no action is required. If the event was not

Action planned, take appropriate action as defined by your enterprise security policy.

SEC-1324

Message Fabric transaction failure. RCS error: <Error code>.

Message Type LOG

Severity INFO

Probable Cause Indicates the reliable commit service (RCS) transaction failed with the specified reason code.

Recommended Verify the event was planned. If the event was planned, no action is required. If the event was not

Action planned, take appropriate action as defined by your enterprise security policy.

SEC-1325

Message Security enforcement: Switch <switch WWN> connecting to port <Port number> is not

authorized to stay in fabric.

Message Type LOG

Severity ERROR

Probable Cause Indicates that because of a Switch Connection Control (SCC) policy violation, the switch is being

disabled on the specified port.

Recommended No action is required unless the switch must remain in the fabric. If the switch must remain in the

fabric, add the switch World Wide Name (WWN) to the SCC policy, and then attempt to join the switch

with the fabric.

SEC-1326

Message Event: fddcfg --fabwideset, Status: success, Info: Fabric wide configuration set to

<Fabric-wide configuration set by user>.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates the specified event has occurred.

Recommended Verify the event was planned. If the event was planned, no action is required. If the event was not

planned, take appropriate action as defined by your enterprise security policy.

SEC-1327

Message Strict <Policy Name> policy WWN List is conflicting with domain <Domain Number>.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates the policy is conflicting with the domain.

Action domain should be allowed to merge with the fabric, then resolve the issue by making the conflicting

No action is required. The domain is denied by disallowing all its E_Ports connected to the fabric. If the

policies the same.

SEC-1328

Recommended

Message Attempt to enable secure mode failed. Reason: <Reason>.

Message Type LOG

Severity ERROR

Probable Cause Indicates the secModeEnable command failed on the fabric because the Authentication Policy is

enabled on the switch.

Recommended

Action Verify the security event was planned. If the security event was planned, run the **authUtil --policy**

passive command to disable the Authentication Policy and retry the secModeEnable command.

SEC-1329

Message IPFilter enforcement: Failed to enforce ipfilter policy of <Policy Type> type because

of <Error code>.

Message Type LOG

Severity ERROR

Probable Cause Indicates the IP filter policy enforcement failed because of an internal system failure.

Recommended Execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the

supportSave command and contact your switch service provider.

SEC-1330

Message <Name of command> command failed -<List of databases rejecting distribution> db(s)

are coming from a non-Primary switch.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates an attempt was made to distribute databases either from a backup fabric configuration server

(FCS) switch or a non-FCS switch.

Recommended Verify the distribution is initiated by the FCS switch. Use the **secPolicyShow** command to verify and

Action correct the configuration if necessary.

SEC-1331

Message Attempt to enable secure mode failed. Reason: <Reason>.

Message Type LOG

Severity ERROR

Probable Cause Indicates the **secModeEnable** command failed on the fabric because default IP filter policies are not

active on the switch, or an active transaction exists on IP filter policies.

Recommended Verify the security event was planned.

Action

If the security event was planned, run the **ipfilter --activate default_ipv4** command or the **ipfilter --activate default_ipv6** command to activate default IP filter policies. Use the **ipfilter --save** or **ipfilter --transabort** commands to save or abort the active transaction on IP filter policies. Then retry the

secModeEnable command.

SEC-1332

Message Fabric wide policy is conflicting as <Policy Name> is present in the fabric wide

policy and 5.3 or 5.2 switches present in the fabric.

Message Type LOG

Severity ERROR

Probable Cause Indicates the fabric-wide policy is conflicting.

Recommended Remove either the FCS from the fabric-wide policy, or remove Fabric OS v5.3 or Fabric OS v5.2

Action switches from the fabric, or set the fabric-wide mode for FCS as strict.

SEC-1333

Message <Name of command> command failed. There are <List of databases rejecting distribution>

in fabric. <printf> db(s) distribution is blocked.

Message Type LOG

Severity ERROR

Probable Cause Indicates there was an attempt to distribute PWD/IPFILTER databases from the fabric to a VF-enabled

switch or distribute PWD from a fabric to a switch having user(s) with user-defined role(s).

Recommended Disable VF on all the switches that have VF-enabled or delete all users with user-defined role(s) if

Action PWD or IPFILTER databases need to be distributed.

SEC-1334

Message SSH Daemon is restarted.

Message Type LOG

Severity INFO

Probable Cause Indicates the Secure Shell (SSH) daemon was not running and it was restarted.

SEC-1335

Message Strict <Policy Name> policy is conflicting with domain <Domain Number>.

Message Type LOG

Severity WARNING

Recommended

Action

No action is required. The domain is denied by disallowing all its E_Ports connected to the fabric. If the domain should be allowed to merge with the fabric, then resolve the issue by making the conflicting policies the same.

SEC-1336

Message <Policy Name> policy is conflicting with domain <Domain Number>.

Message Type LOG

Severity WARNING

Probable Cause Indicates the newly added switches to the fabric, as specified by domain number, have a conflicting

policy with the local switch.

Recommended Check the conflicting policy and make the new switches and the local switch policies the same.

Action

SEC-1337

Message Plain-text password is sent during console login

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates that plain-text password is sent during console login

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the

security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-1338

Message <MESG Message>.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates the password configuration parameters changed.

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the

Action security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-1339

Message Distribute command failed. There are Inflight encryption enabled switch(s) in fabric.

Auth db(s) distribution is blocked

Message Type LOG

Severity ERROR

Probable Cause Indicates there was an attempt to distribute AUTH databases with switch policy (Off/Passive) from the

fabric to a switch that has Inflight Encryption enabled

Recommended Dis

Action

Disable or enable Inflight encryption in all the switches in the fabric

SEC-1340

Message <Message>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the Device Connection Control (DCC) policy member is configured incorrectly.

Recommended Verify that the security event was planned. If the security event was planned, no action is required. If the security event was planned, take appropriate action as defined by your enterprise security

policy.

SEC-1341

Message Failed to update client capability to ESS (Exchange Switch Support) after maximum

number of retries - return code <Failed return code>. Failing sync dump to standby CP.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates that Exchange Switch Support (ESS) is unable to update its capability. Failed to send the

sync dump to standby control processor (CP).

Recommended Verify that HA synchronization has failed using the **haShow** command. If HA synchronization has

Action failed, execute the **haSyncStart** command on active CP to resynchronize the HA state.

SEC-1342

Message HIF mode is enabled. <Warning>

Message Type LOG

Severity WARNING

Indicates that the local switch received a remote distribution for Switch Connection Control (SCC) **Probable Cause**

> policy or fabric-wide data distribution configuration. This may modify SCC policy or strict SCC mode configuration in Fabric Data Distribution (FDD). This configuration change may lead to unexpected

behavior when High Integrity Fabrics (HIF) is enabled.

Recommended

Verify that the security event was planned. If the security event was planned, no action is required. If Action

the security event was not planned, take appropriate action as defined by your enterprise security

policy.

SEC-1343

Message PWD policy distributed successfully from Switch <Switch WWN>. User configuration and

Password configuration is enforced successfully.

Message Type LOG

> INFO Severity

Probable Cause Indicates password database distribute from switch is successful in the Access Gateway (AG) mode.

Recommended Verify the event was planned. If the event was planned, no action is required. If the event was not

Action planned, take appropriate action as defined by your enterprise security policy.

SEC-1344

Message Frequency of security violations exceed limit. Counters will be dropped

Message Type AUDIT | LOG

> Class **SECURITY**

Severity INFO

Probable Cause Indicates that violation counter updates may be dropped. High number of security violations on the

switch.

Recommended Identify and address the reason for security violations.

Action

SEC-1345

Message Analytics platform has taken over as FCS primary.

Message Type LOG

> WARNING Severity

Probable Cause Indicates that the analytics platform switch has taken over as primary Fabric Configuration Server

(FCS) for the fabric connected. This is not a valid configuration.

FOS-90x-Message-RM103 Broadcom

Recommended

After switchdisable in Analytics Monitoring Platform (AMP), delete the FCS_POLICY and activate the policy using the **secPolicyActivate** command. Correct the order of FCS policy in the fabric and

activate it. Enable the AMP switch and distribute the corrected FCS_POLICY from the connected

fabric.

SEC-1346

Message Possible Denial of Service attack detected on Management Ports.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates that a Denial of Service attack is detected on Management ports.

SEC-1347

Message <Security server (RADIUS/LDAP/TACACS+)> server <Server name> reachable, but failed

to validate the user account '<username>'.

Message Type LOG

Severity INFO

Probable Cause Indicates that AAA server is reachable but failed to authenticate due to invalid user or invalid

credentials.

Recommended Verify the user/password entered for the specified RADIUS, LDAP, or TACACS+s server is correct.

Action

SEC-3001

Message Event: <Event Name>, Status: success, Info: Security mode <State change: Enabled or

Disabled> on the fabric.

Message Type AUDIT

Action

Class SECURITY

Severity INFO

Probable Cause Indicates the security mode of the fabric was either enabled or disabled.

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the

security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3002

Message Event: <Event Name>, Status: success, Info: <Event Related Info>.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause

Indicates the specified security event has occurred. The event can be one of the following:

- There has been a fabric configuration server (FCS) failover.
- A security policy has been activated.
- A security policy has been saved.
- A security policy has been aborted.
- A non-FCS password has changed.

Recommended Action Verify the security event was planned. If the security event was planned, no action is required. If the security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3003

Message Event: <Event Name>, Status: success, Info: Created <Policy Name> policy, with

member(s) <Member List> .

Message Type **AUDIT**

> Class **SECURITY**

INFO Severity

Probable Cause Indicates a new security policy with entries has been created. When you use a wildcard (for example,

an asterisk) in creating a policy, the audit report displays the wildcard in the event information field.

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the Action

security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3004

Message Event: <Event Name>, Status: success, Info: Created <Policy name> policy.

AUDIT Message Type

> Class **SECURITY**

Severity INFO

Probable Cause Indicates a new security policy has been created. When you use a wildcard (for example, an asterisk)

in creating a member for a policy, the audit report displays the wildcard in the event information field.

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the Action

security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3005

Message Event: <Event Name>, Status: success, Info: Added member(s) <Members added> to policy

<Policy name>.

Message Type AUDIT

> **SECURITY** Class

Severity INFO

Probable Cause Indicates new members have been added to a security policy. If you use a wildcard (for example, an

asterisk) in adding members to a policy, the audit report displays the wildcard in the event information

FOS-90x-Message-RM103 Broadcom

field.

Recommended

Action

Verify the addition of members to the policy was planned. If the addition of members was planned, no action is required. If the addition of members was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3006

Message Event: <Event Name>, Status: success, Info: Removed member(s) <Members removed> from

policy <Policy name>.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates a user has removed the specific members from the security policy. When you use a wildcard

(for example, an asterisk) in removing members from a policy, the audit report displays the wildcard in

the event information field.

Recommended

Action

Verify the security event was planned. If the security event was planned, no action is required. If the security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3007

Message Event: <Event Name>, Status: success, Info: Deleted policy <Deleted policy name>.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates the specified security policy was deleted.

Action

Verify the security event was planned. If the security event was planned, no action is required. If the security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3008

Recommended

Message Event: <Event Name>, Status: success, Info: FCS member moved from position <Old FCS

position> to <New FCS position>.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates the fabric configuration server (FCS) list has been modified. One of the members of the list

has been moved to a new position in the list.

Recommended Action

Verify the modification was planned. If the modification was planned, no action is required. If the modification was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3009

Message Event: <Event Name>, Status: success, Info: Security Transaction aborted.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates the pending security transaction is aborted.

Action aborted, no action is required. If the security transaction was not intentionally aborted, take appropriate

Verify the security transaction was intentionally aborted. If the security transaction was intentionally

action as defined by your enterprise security policy.

SEC-3010

Recommended

Message Event: <Event Name>, Status: success, Info: Reset [<Name of security stat(s) reset>]

security stat(s).

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates a user has reset all the security statistics.

Recommended Verify the security statistics were intentionally reset. If the security statistics were intentionally reset, no

action is required. If the security statistics were not intentionally reset, take appropriate action as

defined by your enterprise security policy.

SEC-3011

Message Event: <Event Name>, Status: success, Info: Reset [<Stat name>] statistics on

domain(s) [<Domain IDs>].

Message Type AUDIT

Action

Class SECURITY

Severity INFO

Probable Cause Indicates a user has reset a security statistic on the specified domains.

Recommended

Action

Verify the security statistics were intentionally reset. If the security statistics were intentionally reset, no action is required. If the security statistics were not intentionally reset, take appropriate action as defined by your enterprise security policy.

SEC-3012

Message Event: <Event Name>, Status: success, Info: Temp Passwd <Password Set or Reset> on

domain [<Domain ID>] for account [<Account name>].

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates a user has reset the password for the specified user accounts.

Recommended Verify the password was intentionally reset. If the password was intentionally reset, no action is

required. If the password was not intentionally reset, take appropriate action as defined by your

enterprise security policy.

SEC-3013

Message Event: <Event Name>, Status: success, Info: Security Version stamp is reset.

Message Type AUDIT

Action

Class SECURITY

Severity INFO

Probable Cause Indicates a user has reset the security version stamp.

Recommended Verify the security version stamp was intentionally reset. If the security event was planned, no action is

required. If the security version stamp was not intentionally reset, take appropriate action as defined by

your enterprise security policy.

SEC-3014

Message Event: <Event Name>, Status: success, Info: <Event related info> <Security server>

server <Server Name> for AAA services.

Message Type AUDIT

Action

Class SECURITY

Severity INFO

Probable Cause Indicates a user has changed the RADIUS, LDAP, or TACACS+ configuration.

Recommended Verify the RADIUS configuration was changed intentionally. If the RADIUS configuration was changed

Action intentionally, no action is required. If the RADIUS configuration was not changed intentionally, take

appropriate action as defined by your enterprise security policy.

SEC-3015

Message Event: <Event Name>, Status: success, Info: Moved <Event option> server <Server name>

to position <New position>.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates a user has changed the position of the RADIUS, LDAP, or TACACS+ server.

Recommended Verify the remote server position was intentionally changed. If the remote server position was

Action intentionally changed, no action is required. If the remote server position was not intentionally

changed, take appropriate action as defined by your enterprise security policy.

SEC-3016

Message Event: <Event Name>, Status: success, Info: Attribute [<Attribute Name>] of <Security

server> server server ID> changed <Attribute related info, if any>.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates a user has changed the specified attribute of the RADIUS, LDAP, and TACACS+ server.

Recommended Verify the RADIUS/LDAP/TACACS+ attribute was intentionally changed. If the RADIUS attribute was

Action intentionally changed, no action is required. If the RADIUS/LDAP/TACACS+ attribute was not

intentionally changed, take appropriate action as defined by your enterprise security policy.

SEC-3018

Message Event: <Event Name>, Status: success, Info: Parameter [<Parameter Name>] changed from

[<Old Value>] to [<New Value>].

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates the specified password configuration parameter is changed.

Recommended

Action

Verify the password configuration parameter was intentionally changed. If the password configuration parameter was intentionally changed, no action is required. If the password configuration parameter was not intentionally changed, take appropriate action as defined by your enterprise security policy.

SEC-3019

Message Event: <Event Name>, Status: success, Info: Passwdcfg parameters set to default

values.

Message Type AUDIT

Action

Class SECURITY

Severity INFO

Probable Cause Indicates the password configuration parameters are set to default values.

Recommended Verify the password configuration parameter was intentionally set to default values. If the password

configuration parameter was intentionally set to default values, no action is required. If the password configuration parameter was not intentionally set to default values, take appropriate action as defined

by your enterprise security policy.

SEC-3020

Message Event: <Event Name>, Status: success, Info: Successful login attempt via <connection

method and IP Address>.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates a successful login occurred. An IP address is displayed when the login occurs over a remote

connection.

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the

security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3021

Message Event: <Event Name>, Status: failed, Info: Failed login attempt via <connection method

and IP Address>.

Message Type AUDIT

Action

Class SECURITY

Severity INFO

Probable Cause Indicates a failed login attempt occurred.

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the

Action security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3022

Message Event: <Event Name>, Status: success, Info: Successful logout by user [<User>].

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates the specified user has successfully logged out.

SEC-3023

Message Event: <Event Name>, Status: failed, Info: Account [<User>] locked, failed password

attempts exceeded.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that failed password attempts exceeded the allowed limit; the account has been locked.

Recommended The account may automatically unlock after the lockout duration has expired or an administrator may

Action manually unlock the account.

SEC-3024

Message Event: <Event Name>, Status: success, Info: User account [<User Name>], password

changed.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates the user's password was changed.

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the

Action security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3025

Message Event: <Event Name>, Status: success, Info: User account [<User Name>] added. Role:

[<Role Type>], Password [<Password Expired or not>], Home Context [<Home AD>], AD/VF

list [<AD membership List>].

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates a new user account was created. In VF mode, when chassis role is added for the user,

membership list will include 255.

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the

security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3026

Message Event: <Event Name>, Status: success, Info: User account [<User Name>], role changed

from [<Old Role Type>] to [<New Role Type>].

Message Type AUDIT

Action

Class SECURITY

Severity INFO

Probable Cause Indicates a user account role was changed.

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the

Action security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3027

Message Event: <Event Name>, Status: success, Info: User account [<User Name>] [<Changed

Attributes>].

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates user account properties were changed.

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the

Action security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3028

Message Event: <Event Name>, Status: success, Info: User account [<User Name>] deleted.

Message Type **AUDIT**

> Class **SECURITY**

INFO Severity

Probable Cause Indicates the specified user account was deleted.

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the Action

security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3029

Message Event: <Event Name>, Status: success, Info: Backup user account \"<User Account

Name>\" recovered.

Message Type **AUDIT**

> **SECURITY** Class

Severity **INFO**

Probable Cause Indicates that backup user accounts were recovered.

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the

security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3030

Message Event: <Event Name>, Status: success, Info: <Event Specific Info>.

Message Type **AUDIT**

Action

SECURITY Class

Severity INFO

Probable Cause Indicates the specified **secCertMgmt** operation was performed.

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the Action

security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3031

Message Event: <Event Name>, Status: success, Info: Distributed<List of Databases> db(s) to

<Number of domains> domain(s), dom-id(s)<List of Domains>.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates the specified event has occurred.

Recommended Verify the event was planned. If the event was planned, no action is required. If the event was not

Action planned, take appropriate action as defined by your enterprise security policy.

SEC-3032

Message Event: <Event Name>, Status: success, Info: Switch is configured to <accept or reject>

<Database name> database.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates the specified event has occurred to accept or reject a certain database.

Recommended Verify the event was planned. If the event was planned, no action is required. If the event was not

planned, take appropriate action as defined by your enterprise security policy.

SEC-3033

Message Event: fddcfg --fabwideset, Status: success, Info: Fabric wide configuration set to

<Fabric-wide configuration set by user>.

Message Type AUDIT

Action

Class SECURITY

Severity INFO

Probable Cause Indicates the specified event has occurred.

Recommended Verify the event was planned. If the event was planned, no action is required. If the event was not

Action planned, take appropriate action as defined by your enterprise security policy.

SEC-3034

Message Event: aaaconfig, Status: success, Info: Authentication configuration changed from

<Previous Mode> to <Current Mode> <Existing sessions are terminated or not>.

Message Type AUDIT

SECURITY Class

Severity INFO

Probable Cause Indicates an authentication configuration has changed.

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the Action

security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3035

Message Event: ipfilter, Status: success, Info: <IP Filter Policy> ipfilter policy(ies)

AUDIT | LOG Message Type

> Class **SECURITY**

Severity INFO

Action

Probable Cause Indicates the specified IP filter policies has been saved.

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the

security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3036

Message Event: ipfilter, Status: failed, Info: Failed to save changes for <IP Filter Policy>

ipfilter policy(s).

Message Type AUDIT | LOG

> **SECURITY** Class

Severity INFO

Probable Cause Indicates the specified IP filter policies have not been saved.

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the

Action security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3037

Message Event: ipfilter, Status: success, Info: <IP Filter Policy> ipfilter policy activated.

Message Type AUDIT | LOG

> Class **SECURITY**

Severity **INFO**

FOS-90x-Message-RM103 Broadcom

Recommended

Probable Cause Indicates the specified IP filter policy has been activated.

Action security event was not planned, take appropriate action as defined by your enterprise security policy.

Verify the security event was planned. If the security event was planned, no action is required. If the

SEC-3038

Message Event: ipfilter, Status: failed, Info: Failed to activate <IP Filter Policy> ipfilter

policy.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates the specified IP filter policy failed to activate.

Recommended Verify the security event was planned. If the event was planned, no action is required. If the security

Action event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3039

Message Event: Security Violation , Status: failed, Info: Unauthorized host with IP address

<IP address of the violating host> tries to establish connection using <Protocol</pre>

Connection Type>.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates a security violation was reported. The IP address of the unauthorized host is displayed in the

message.

Recommended Check for unauthorized access to the switch through the specified protocol connection.

Action

SEC-3043

Message The FIPS inside mode has been set to <Fips Inside>.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates there was a change in the Federal Information Processing Standards (FIPS) Inside mode.

Recommended Action Verify the security event was planned. If the security event was planned, no action is required. If the security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3044

Message The FIPS mode has been changed to <Fips Mode>.

Message Type **AUDIT**

> Class **SECURITY**

Severity **INFO**

Probable Cause Indicates there was a change in the Federal Information Processing Standards (FIPS) mode.

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the Action security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3045

Message Zeroization has been executed on the system.

Message Type **AUDIT**

> Class **SECURITY**

Severity **INFO**

Probable Cause Indicates the system has been zeroized.

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the Action security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3046

Message The FIPS Self Tests mode has been set to <Self Test Mode>.

Message Type AUDIT

> **SECURITY** Class

Severity **INFO**

Probable Cause Indicates there was a change in the Federal Information Processing Standards (FIPS) Self Test mode.

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the Action security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3047

FOS-90x-Message-RM103 Broadcom

Message Info: RBAC permission for a CLI command: <Cmd Name> is failed.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates the user does not have permission to execute this command.

Recommended Verify the user has the required permission to execute this command.

Action

SEC-3048

Message FIPS mode has been enabled in the system using force option.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates the system has been forced to Federal Information Processing Standards (FIPS) mode.

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the security event was not planned, take appropriate action as defined by your enterprise security policy.

Look for the status of the prerequisites that did not conform to FIPS mode.

SEC-3049

Message Status of bootprom access is changed using fipscfg CLI to: <Access Status>.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates the status of boot PROM access has changed using the fipsCfg command.

SEC-3050

Message Event: <Event Name>, Status: success, Info: <Event Specific Info>

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates the specified Secure Shell (SSH) utility operation was performed.

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the

Action security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3051

Message The license key/serial number <Key> is <Action>.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates that a license key is added or removed.

SEC-3061

Message Role '<Role Name>' is created.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates that the specified role name has been created.

SEC-3062

Message Role '<Role Name>' is deleted.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates that the specified role name has been deleted.

SEC-3063

Message Role '<Role Name>' is copied from '<Source Role>'.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates that the specified role name has been copied from the source role.

SEC-3064

Message Permission to the RBAC class(es) '<RBAC Class Names>' is changed for the role '<Role

Name>'.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates the permission to the Role-Based Access Control (RBAC) class is changed for the specified

role name.

SEC-3065

Message Configuration of user-defined roles is uploaded.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates the configuration of user-defined roles has been uploaded.

SEC-3066

Message Configuration of user-defined roles is downloaded.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates the configuration of user-defined roles has been downloaded.

SEC-3067

Message Invalid Cipher list <Cipher List>.

Message Type AUDIT | LOG

Class SECURITY

Severity WARNING

Probable Cause Indicates the input cipher list is an invalid string.

Recommended Invalid cipher list input, therefore reverted to previous cipher list.

Action

SEC-3068

Message Self-tests failed on DP. Triggering on CP.

Message Type AUDIT | LOG

Class SECURITY

Severity WARNING

Probable Cause Indicates that selftests failed on DP.

Recommended Verify the reason for failure and contact support for further details.

Action

SEC-3069

Message Event: seccryptocfg, Status: success, Info: <Action Name> security template,

<Template Name>.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates the specified **seccryptocfg** operation was performed.

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the

Action security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3070

Message Event: <Event Name>, Status: success, Info: Generated self-signed <Certificate Name>

certificate, <Certificate Info>.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates the specified **secCertMgmt** operation was performed.

Recommended

Action

Verify the security event was planned. If the security event was planned, no action is required. If the security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3071

Message Event: <Event Name>, Status: success, Info: <Parameter Change Info>.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates the specified password configuration parameter is changed.

Recommended Verify the password configuration parameter was intentionally changed. If the password configuration parameter was intentionally changed, no action is required. If the password configuration parameter

was not intentionally changed, take appropriate action as defined by your enterprise security policy.

SEC-3072

Message Event: <Event Name>, Status: success, Info: <Event specific info >.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates that the specified Secure Shell (SSH) operation is performed.

Recommended Verify that SSH rekeying is configured and rekeying happened for every configured time interval.

Action

SEC-3073

Message Event: <Event Name>, Status: failure, Info: <Event specific info >.

Message Type AUDIT | LOG

Class SECURITY

Severity WARNING

Probable Cause Indicates that the specified corrupted or big packet is received in Secure Shell Server (SSHD).

Recommended Verify that the big packet is received in SSHD and SSHD is terminated.

Action

SEC-3074

Message <AAA server type> server certificate failed for host name verification.

Message Type AUDIT | LOG

> Class **SECURITY**

Severity **ERROR**

Probable Cause Indicates that RADIUS server certificate failed for host name verification.

SEC-3075

Message Event: <Event Name>, <Event action>, Info: <Even specific info >.

Message Type AUDIT | LOG

> Class **SECURITY**

Severity INFO

Probable Cause Indicates that unsecure communication service is activated.

Recommended Verify if the security event was planned. If the security event was planned, no action is required. If the Action

security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3076

Message Event: <Event Name>, <Event action>, Info: <Even specific info >.

Message Type AUDIT | LOG

> Class **SECURITY**

Severity **INFO**

Probable Cause Indicates a failure to establish a specified Secure Shell (SSH) session.

Recommended Verify if the security event was planned. If the security event was planned, no action is required. If the

Action security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3077

Message Event: <Event Name>, <Event action>, Info: <Even specific info >.

Message Type AUDIT | LOG

> **SECURITY** Class

Severity **INFO**

Probable Cause Indicates a failure to establish a Transport Layer Security (TLS) session.

Recommended Verify if the security event was planned. If the security event was planned, no action is required. If the Action

security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3078

Message Event: <Event Name>, <Event action>, Info: <Even specific info >.

Message Type **AUDIT**

> **SECURITY** Class

Severity INFO

Probable Cause Indicates TLS session information during connection.

SEC-3079

Message Event: Internet Protocol Security (IPsec) is <Event action>.

Message Type AUDIT | LOG

> **SECURITY** Class

INFO Severity

Probable Cause Indicates that an Internet Protocol Security (IPsec) or Internet Key Exchange (IKE) policy enabled/

disabled and the configuration file was updated.

SEC-3080

Message Event: Internet Protocol Security (IPsec) configuration is <Event action>, Info:

<Even specific info >.

Message Type AUDIT | LOG

> Class **SECURITY**

Severity INFO

Probable Cause Indicates that an Internet Protocol Security (IPsec) or Internet Key Exchange (IKE) policy configuration

was added/deleted/modified and the configuration file was updated.

SEC-3081

Message Event: <Event Name>, <Event action>, Info: <Even specific info >.

Message Type AUDIT | LOG

FOS-90x-Message-RM103 Broadcom

SECURITY Class

Severity INFO

Probable Cause Indicates that Transport Layer Security (TLS) Certificate Validation failed.

Recommended Verify if the security event was planned. If the security event was planned, no action is required. If the Action

security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3082

Message Telnet session <Session Name> has been closed.

Message Type **AUDIT**

> Class **SECURITY**

Severity **INFO**

Probable Cause Indicates a user has killed a telnet session.

SEC-3083

Message <Cfg context> has been updated.

Message Type **AUDIT**

> Class **SECURITY**

Severity **INFO**

Probable Cause Indicates a user has modified login banner.

SEC-3084

Message Event: <Event Name>, Info: root account access mode is set to <Access mode>.

Message Type **AUDIT**

> Class **SECURITY**

Severity INFO

Probable Cause Indicates root account access mode is changed.

SEC-3085

Message Info: Maintenance permission for a CLI command: <Cmd Name> is failed.

Message Type **AUDIT**

Severity INFO

Probable Cause Indicates the user does not have permission to execute this maintenance user command.

Recommended Verify the user has the required permission to execute this maintenance user command.

Action

SEC-3086

Message Event :Ldapcfg <Event Name>, Status : <Status>, Info:<Role Name/Role Attributes>

<Info String>

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates whether Idap role has been mapped/unmapped/changed or not.

Recommended Verify if Idap role has been mapped/unmapped/changed or not.

Action

6.96 SFLO Messages

SFLO-1001

Message sFlow is <state> globally.

Message Type LOG

Severity INFO

Probable Cause Indicates that sFlow is globally enabled or disabled.

SFLO-1002

Message sflow is <state> for port <name>.

Message Type LOG

Severity INFO

Probable Cause Indicates that sFlow is enabled or disabled on the specified port.

SFLO-1003

Message Global sFlow sampling rate is changed to <sample_rate>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the global sFlow sampling rate has been changed to the specified value.

SFLO-1004

Message Global sFlow polling interval is changed to <polling intvl>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the global counter sampling interval has been changed to the specified value.

SFLO-1005

Message sflow sampling rate on port <name> is changed to <sample_rate>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the sFlow sampling rate has been changed on the specified port.

SFLO-1006

Message sFlow polling interval on port <name> is changed to <poling intvl>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the polling interval has been changed on the specified port.

SFLO-1007

Message <name> is <state> as sFlow collector.

Message Type LOG

Severity INFO

Probable Cause Indicates that the sFlow collector is configured or not configured.

SFLO-1008

Message All the sFlow collectors are unconfigured.

Message Type LOG

Severity INFO

Probable Cause Indicates that none of the sFlow collectors are configured.

6.97 SLNK Messages

SLNK-1001

Message Supportlink data upload has completed successfully.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the switch data has been uploaded successfully.

SLNK-1002

Message Supportlink <config type> configuration updated successfully.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that "user or profile or default" has updated the supportlink configuration successfully.

SLNK-1003

Message Supportlink data collection has completed successfully.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the switch data has been collected successfully.

SLNK-1005

Message Supportlink <failure cmd> failed due to <Error msg> (reason code: <Error code>).

Message Type AUDIT | LOG

Class CFG

Severity WARNING

Probable Cause Indicates that supportlink operation failed

6.98 SNMP Messages

SNMP-1001

Message SNMP service is not available <Reason>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the Simple Network Management Protocol (SNMP) service could not be started because

of the specified reason. Therefore, you will not be able to query the switch through SNMP.

Recommended Verify that the IP address for the Ethernet and Fibre Channel interface is set correctly. If the specified

Action reason is an initialization failure, restart the switch using the **reboot** command.

SNMP-1002

Message SNMP <Error Details> initialization failed.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the initialization of the SNMP service failed and therefore you will not be able to query

the switch through SNMP.

Recommended Restart or power cycle the switch. This will automatically initialize SNMP.

Action

SNMP-1003

Message Distribution of Community Strings to Secure Fabric failed.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the changes in the SNMP community strings could not be propagated to other switches

in the secure fabric.

Recommended Retry changing the SNMP community strings on the primary switch.

Action

SNMP-1004

Message Incorrect SNMP configuration.

Message Type AUDIT | FFDC | LOG

Class CFG

Severity ERROR

Probable Cause Indicates that the SNMP configuration is incorrect and therefore the SNMP service will not work

correctly.

Recommended Change the SNMP configuration to the default using the **snmpConfig** --default command.

Action

SNMP-1005

Message SNMP configuration attribute, <Changed attribute>, <String Value>.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the SNMP configuration has changed. The modified parameter and the old and new

parameter values are displayed in the message.

Recommended Execute the **snmpConfig --show** command to view the new SNMP configuration.

Action

SNMP-1006

Message <SNMP Configuration group> configuration was reset to default.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the specified SNMP configuration group was reset to the factory default.

Recommended Execute the **snmpConfig --show** command for the group to view the new SNMP configuration.

Action

SNMP-1009

Message Port traps are <blocked state> on port <port>.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates the blocked or unblocked status of the port traps on the specified port.

Recommended Execute the **snmpTraps** --show command to view the current status of the port.

Action

SNMP-1010

Message Unsupported security protocol settings detected. Setting SNMP usm privacy protocol

configuration to default configuration.

Message Type LOG

Severity INFO

Probable Cause Indicates that the SNMP User-based Security Model (USM) privacy protocol configuration was found

to be incorrect after HA synchronization.

Recommended Execute the **snmpConfig --show** command to view the new SNMP configuration.

Action

SNMP-1011

Message SNMP configuration attribute, <Changed attribute>, <String Value>.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the SNMP configuration has been added. The added parameter value is displayed in the

message.

Recommended Execute the **snmpConfig --show** command to view the new SNMP configuration.

Action

SNMP-1012

Message SNMP configuration attribute, <Changed attribute>, <String Value>.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the SNMP configuration has been deleted. The deleted parameter value is displayed in

the message.

Recommended

Action

Execute the **snmpConfig --show** command to view the new SNMP configuration.

SNMP-3020

Message Event: Login, Info: SNMP login attempt via <connection method and IP Address>.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that a simple network management protocol (SNMP) login occurred. An IP address is

displayed when the login occurs over a remote connection.

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the

Action security event was not planned, take appropriate action as defined by your enterprise security policy.

6.99 SPM Messages

SPM-1001

Message Init fails: <Reason>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the security processor management (SPM) failed to initialize.

Recommended Check the system resources and restart the switch.

Action

SPM-1002

Message Generic SPM Warning: <Reason>.

Message Type LOG

Severity WARNING

Probable Cause Indicates an security processor management (SPM) warning based on the reason displayed.

Recommended Execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the

Action **supportSave** command and contact your switch service provider.

SPM-1003

Message Set New Group Cfg SC Enable <SC_Enable> KV Type <KV_Type>.

Message Type LOG

Severity INFO

Probable Cause Indicates a new group has been configured.

SPM-1004

Message Initialize Node.

Message Type LOG

Severity INFO

Probable Cause Indicates a node initialization.

SPM-1005

Message Set EE Control slot <slot> action <action>.

Message Type LOG

Severity INFO

Probable Cause Indicates specified control action is taken on encryption engine in specified slot.

SPM-1006

Message Registered Certificate of type <cert_type>.

Message Type LOG

Severity INFO

Probable Cause Indicates a certificate registration.

SPM-1007

Message Deregistered Certificate cid [<cert_id>] type <cert_type> idx <qc_idx>.

Message Type LOG

Severity INFO

Probable Cause Indicates a certificate de-registration.

SPM-1008

Message Deregistered SP Certificate in slot <slot>.

Message Type LOG

Severity INFO

Probable Cause Indicates an security processor (SP) certificate de-registration.

SPM-1009

Message <cert> Certificate is missing.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified certificate is missing.

Recommended Execute the **cryptocfg** --initnode command.

Action

SPM-1010

Message <cert> Key Vault Certificate is missing.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified key vault certificate is missing.

Recommended Deregister and register the key vault.

Action

SPM-1011

Message Group Cfg Changed Quorum Size <qc size>.

Message Type LOG

Severity INFO

Probable Cause Indicates that a group configuration has changed the quorum size.

SPM-1012

Message Authentication Context: <established>.

Message Type LOG

Severity INFO

Probable Cause Indicates an authentication context.

SPM-1013

Message Security database is out of sync.

Message Type LOG

Severity ERROR

Probable Cause Indicates a failure to distribute security database.

Recommended Execute the **cryptocfg** --sync -securitydb command to manually sync the security database.

Action

SPM-1014

Message Warning: Configdownload may change key vault configuration and result in EE going to

Operational; Need Valid KEK state.

Message Type LOG

Severity WARNING

Probable Cause Indicates the master keys downloaded will not be effective unless imported because the encryption

engine may have different master key configured.

Recommended Import required master keys using the cryptocfg --recovermasterkey command to bring the

Action encryption engine online.

SPM-1015

Message Security database may be out of sync.

Message Type LOG

Severity WARNING

Probable Cause Indicates a failure to distribute the security database.

Recommended Use the **cryptocfg** --sync -securitydb command to manually sync security database.

Action

SPM-1016

Message Security database is out of sync. This warning can be ignored if the nodes in the EG

are running different versions of FOS.

Message Type LOG

Severity WARNING

Probable Cause Indicates a failure to distribute the security database.

Recommended Use the **cryptocfg** --sync -securitydb command to manually sync security database.

Action

SPM-3001

Message Event: cryptocfg Status: success, Info: Node [<wwnstr>] initialized.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates a node was initialized.

SPM-3002

Message Event: cryptocfg Status: success, Info: EE in slot <slot> initialized.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates an encryption engine was initialized.

SPM-3003

Message Event: cryptocfg Status: success, Info: EE in slot <slot> registered.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates an encryption engine was registered.

SPM-3004

Message Event: cryptocfg Status: success, Info: EE in slot <slot> enabled.

Message Type AUDIT | LOG

Severity INFO

Probable Cause Indicates an encryption engine was enabled.

SPM-3005

Message Event: cryptocfg Status: success, Info: EE in slot <slot> disabled.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates an encryption engine was disabled.

SPM-3006

Message Event: cryptocfg Status: success, Info: <sourceFile> file exported via scp:

<hostUsername>[<hostIP>]:<hostPath>.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates a file was exported through SCP protocol.

SPM-3007

Message Event: cryptocfg Status: success, Info: File imported via scp:

<hostUsername>[<hostIP>]:<hostPath>.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates a file was imported through SCP protocol

SPM-3008

Message Event: cryptocfg Status: success, Info: DH challenge generated for vault IP <vaultIP>.

Message Type AUDIT | LOG

Severity INFO

Probable Cause Indicates a DH challenge was generated for a key vault.

SPM-3009

Message Event: cryptocfg Status: success, Info: DH response accepted.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates a DH response was accepted.

SPM-3010

Message Event: cryptocfg Status: success, Info: EE in slot <slot> zeroized.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates an encryption engine was zeroized.

SPM-3011

Message Event: cryptocfg Status: success, Info: Local file \"<filename>\" deleted.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates a locally stored file was deleted.

SPM-3012

Certificate label: \"<certLabel>\" Certificate file: \"<certFilename>\" IP address:

<IPAddress>.

Message Type AUDIT | LOG

Severity INFO

Probable Cause Indicates a key vault was registered.

SPM-3013

Message Event: cryptocfg Status: success, Info: Key vault with certificate label

\"<certLabel>\" deregistered.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates a key vault was deregistered.

SPM-3014

Message Event: cryptocfg Status: success, Info: Key archive client registered with

certificate file \"<certFilename>\".

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates a key archive client (KAC) certificate was registered.

SPM-3015

Message Event: cryptocfg Status: success, Info: Key vault type set to <keyVaultType>.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

SPM-3016

Message Event: cryptocfg Status: success, Info: Master key generated.

Message Type AUDIT | LOG

Severity INFO

Probable Cause Indicates a master key was generated

SPM-3017

Message Event: cryptocfg Status: success, Info: Master key exported.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates a master key was exported.

SPM-3018

Message Event: cryptocfg Status: success, Info: <currentOrAlternate> master key recovered.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates a master key was recovered.

SPM-3019

Message Event: cryptocfg Status: success, Info: System card registered. Certificate label:

\"<certLabel>\" Certificate file: \"<certFilename>\".

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates a system card was registered.

SPM-3020

Message Event: cryptocfg Status: success, Info: System card with certificate label

\"<certLabel>\" deregistered.

Message Type AUDIT | LOG

Severity INFO

Probable Cause Indicates a system card was deregistered.

SPM-3021

Message Event: cryptocfg Status: success, Info: Authentication card registered. Certificate

label: \"<certLabel>\" Certificate file: \"<certFilename>\".

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates an authentication card was registered.

SPM-3022

Message Event: cryptocfg Status: success, Info: Authentication card with certificate label

\"<certLabel>\" deregistered.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates an authentication card was deregistered.

SPM-3023

Message Event: cryptocfg Status: success, Info: System card <enabledOrDisabled>.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates use of the system card was enabled or disabled.

SPM-3024

Message Event: cryptocfg Status: success, Info: Quorum size set to <quorumsize>.

Message Type AUDIT | LOG

Severity INFO

Probable Cause Indicates the quorum size was set.

SPM-3025

Message Event: cryptocfg Status: success, Info: File imported via USB: Source: <sourcePath>

Destination: <destinationFilename>.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates a file was imported through a USB device.

SPM-3026

Message Event: cryptocfg Status: success, Info: File exported via usb: Source: <sourcePath>

Destination: <destinationFilename>.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates a file was exported through a USB device

SPM-3027

Message Event: cryptocfg Status: success, Info: Recovery card registered. Certificate label:

\"<certLabel>\" Certificate file: \"<certFilename>\".

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates a recovery card was registered.

SPM-3028

Message Event: SPM-EE state changed, Info: EE State: <EE Status>.

Message Type AUDIT | LOG

Severity INFO

Probable Cause Indicates an encryption engine state has changed.

SPM-3029

Message Event: KeyVault Connection Status: <status>, Info: KAC Connect: <kac status>.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates the status of key vault.

6.100 SRM Messages

SRM-1001

Message System is alive.

Message Type AUDIT

Class RAS

Severity INFO

Probable Cause Indicates that the system is alive.

SRM-1002

Message raslog keep alive period has been changed to <printf>.

Message Type LOG | AUDIT

Class RAS

Severity INFO

Probable Cause Indicates that raslog keep alive period has been changed.

6.101 SS Messages

SS-1000

Message supportSave has uploaded support information to the remote host <Time_Duration>

Message Type LOG

Severity INFO

Probable Cause Indicates that the **supportSave** command was used to transfer support information to a remote

location.

SS-1001

Message supportSave's upload operation to remote host has been aborted (<Abort reason>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that a file copy error occurred during execution of the **supportSave** command. Complete

error information cannot always be displayed in this message because of possible errors in

subcommands being executed by the **supportSave** command.

Recommended Check and correct the remote server settings and configuration. Execute the **supportFtp** command

(as needed) to set the FTP or SCP parameters. After the problem is corrected, execute the

supportSave command again.

SS-1002

Message supportSave has stored support information to the USB storage device.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the **supportSave** command was used to transfer support information to an attached

USB storage device.

SS-1003

Message supportSave's operation to USB storage device aborted.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a USB operation error occurred during execution of the **supportSave** command.

Complete error information cannot always be displayed in this message because of possible errors in

subcommands being executed by the supportSave command.

Recommended Execute the **usbstorage -I** command to check the USB storage device settings. After the USB

Action problem is corrected, execute the **supportSave** command again.

SS-1004

Message One or more modules timed out during supportsave. Retry supportsave with -t option

to collect all logs.

Message Type LOG

Severity WARNING

Probable Cause Indicates a timeout in modules during the execution of the **supportSave** command.

Recommended Execute the **supportSave -t [2-5]** command to collect all logs.

Action

SS-1005

Message supports ave failed for the slot <Slot Number>. Reason: No IP connection.

Message Type LOG

Severity WARNING

Probable Cause Indicates that there is no IP connection between the active control processor (CP) and the blade in the

specified slot.

Recommended Check for the IP connection between the active CP and the blade in the specified slot. After the IP

Action connection is established, execute the **supportSave** command again.

SS-1006

Message supports ave not collected for slot <Slot Number>. Reason: blade was not available to

accept a supportsave request.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the supportsave request was not sent to the blade in the specified slot.

Recommended Restart the switch using the **reboot** command and then execute the **supportSave** command.

Action

SS-1007

Message supports ave failed for the slot <Slot Number>. Reason: No response from the blade in

the specified slot for the given supports ave request.

Message Type LOG

Severity WARNING

Probable Cause Indicates that there was no response from the blade in the specified slot for the given supportsave

request.

Recommended

Action

Restart the switch using the **reboot** command and then execute the **supportSave** command.

SS-1008

Message supportsave failed for the slot <Slot Number>. Reason: BP supportsave timeout.

Message Type LOG

> Severity WARNING

Probable Cause Indicates that the specified slot has taken more time than expected to collect the supportsave logs.

Recommended Execute the **supportSave** command again.

Action

SS-1009

Message <slot number and its node name(BP/DP)> supportsave failed. Reason:No ISC connection

for <slot number and its node name(BP/DP)>.

Message Type LOG

> Severity WARNING

Probable Cause Indicates that there is no Inter-Subsystem Communication (ISC) connection for the specified node slot.

Recommended Restart the switch using the reboot command and then execute the supportSave command.

Action

SS-1010

Message CORE/FFDC files have been uploaded to the remote host.

Message Type LOG

> Severity **INFO**

Probable Cause Indicates that the supportSave command was used to transfer core and first failure data capture

(FFDC) files to a remote location.

SS-1011

Message CORE/FFDC files have been transferred to the USB storage device.

Message Type LOG

FOS-90x-Message-RM103 Broadcom

Severity INFO

Probable Cause Indicates that the **supportSave** command was used to transfer core and first failure data capture

(FFDC) files to a USB storage Device.

SS-1012

Message BP supportsave failed. The /mnt of Active CP does not have enough disk space to collect

BP supportsave files.

Message Type LOG

Severity INFO

Probable Cause Indicates that a chassis with the blade processor (BP) does not have enough disk space in the

secondary partition of the active CP to save the supportsave files, before uploading them to the remote

host.

Recommended

Action

Manually clean up the secondary partition of the active CP to collect the supportsave files.

SS-1013

Message supportSave's upload operation aborted. username or password is not provided.

Message Type LOG

Severity INFO

Probable Cause Indicates that the username or password parameters were not specified with the supportSave

command in non-interactive mode.

Recommended Spe

Action

Specify both username and password or neither of them. If no username and password are specified,

anonymous FTP will be used to collect the supportsave files.

SS-1014

Message supportSave has uploaded information to the remote host (fabos is not ready).

Message Type LOG

Severity INFO

Probable Cause Indicates that the supportSave command was used to transfer support information to a remote

location.

SS-1015

Message supportSave started.

Message Type LOG

Severity INFO

Probable Cause Indicates that the **supportSave** command was started to transfer support information to a remote

location.

SS-1016

Message supportSave fails to upload <printf>: <printf>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the **supportSave** command was started to transfer support information to a remote

location. And the upload server is temporarily busy to upload a file.

Recommended

supportSave will retry the upload, no action is required.

Action

6.102 SSLP Messages

SSLP-1001

Message Failed to launch open source process Service Location Protocol (SLP) in the switch.

Message Type LOG

Severity ERROR

Probable Cause Indicates that there is an error in launching open source process Service Location Protocol (SLP) in

the switch.

Recommended Launch the process manually using the slpd -d -p /tmp/slpd.pid command. If this operation fails,

Action reload or fail over the switch.

6.103 SSMD Messages

SSMD-1001

Message Failed to allocate memory: (<function name>).

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified function has failed to allocate memory.

Recommended

Check the memory usage on the switch using the **memShow** command.

Action

Restart or power cycle the switch.

SSMD-1002

Message Failed to initialize <module> rc = <error>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the initialization of a module within System Services Manager (SSM) has failed.

Recommended Download a new firmware using the **firmwareDownload** command.

Action

SSMD-1003

Message Failed to lock semaphore mutex: (<function name>).

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified function has failed to lock the mutex (semaphore).

Recommended Restart or power cycle the switch.

Action

SSMD-1004

Message Failed to unlock semaphore mutex: (<function name>).

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified function failed to unlock the mutex (semaphore).

Recommended Restart or power cycle the switch.

Action

SSMD-1005

Message SSM start up failed.

Message Type LOG

Severity ERROR

Probable Cause Indicates that Data Center Ethernet (DCE) SSM encountered an unexpected severe error during basic

startup and initialization.

Recommended

ded Restart or power cycle the switch.

Action

If the problem persists, download a new firmware using the firmwareDownload command.

SSMD-1006

Message Error while configuring ACL <ACL name> on interface <Interface name>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that an error occurred while programming a Ternary Content Addressable Memory (TCAM)

entry on the specified interface.

Recommended Try again after some time. If the problem persists, execute the **supportSave** command and then

restart or power cycle the switch.

SSMD-1007

Message Error while removing ACL <ACL name> from interface <Interface name>.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that an error occurred while programming a TCAM entry on the specified interface.

Recommended Try again after some time. If the problem persists, execute the **supportSave** command and then

Action restart or power cycle the switch.

SSMD-1008

Message Apptype TCAM Table full for Slot:<slot number> chip:<Chip number in the slot>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the application type TCAM table is full on the specified chip.

Recommended Remove the unused protocol-based VLAN classifiers and Layer 2 extended access control lists

Action (ACLs).

SSMD-1200

Message QoS failed programming ASIC <ASIC slot number>/<ASIC chip number> Multicast Rate

Limit.

Message Type LOG

Severity WARNING

Probable Cause Indicates that DCE SSM encountered an unexpected error in programming the dataplane application-

specific integrated circuit (ASIC) for enforcing the Multicast Rate Limit feature.

Recommended Delete and reapply the Quality of Service (QoS) Multicast Rate Limit policy using the qos rcv-queue

Action multicast rate-limit command.

If the problem persists, restart or power cycle the switch.

SSMD-1201

Message QoS failed programming ASIC <ASIC slot number>/<ASIC chip number> Multicast Tail Drop.

Message Type LOG

Severity WARNING

Probable Cause Indicates that DCE SSM encountered an unexpected error in programming the dataplane ASIC for

enforcing the Multicast Tail Drop feature.

Recommended Delete and reapply the QoS Multicast Tail Drop policy using the qos rcv-queue multicast threshold

Action command.

If the problem persists, restart or power cycle the switch.

SSMD-1202

Message QoS failed programming interface 0x<Interface ID> 802.3x Pause flow control.

Message Type LOG

Severity WARNING

Probable Cause Indicates that DCE SSM encountered an unexpected error in programming the dataplane ASIC for

enforcing interface 802.3x Pause flow control feature.

Recommended Delete and reapply the QoS 802.3x Pause flow control policy using the **qos flowcontrol** command.

Action If the problem persists, restart or power cycle the switch.

SSMD-1203

Message QoS failed programming interface 0x<Interface ID> PFC flow control.

Message Type LOG

Severity WARNING

Probable Cause Indicates that DCE SSM encountered an unexpected error in programming the dataplane ASIC for

enforcing interface Priority-based Flow Control (PFC) flow control feature.

Recommended

Action

Delete and reapply the QoS PFC flow control policy using the qos flowcontrol pfc command.

If the problem persists, restart or power cycle the switch.

SSMD-1204

Message QoS failed initializing ASIC <ASIC slot number>/<ASIC chip number>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that DCE SSM encountered an unexpected error in initializing the dataplane ASIC QoS

infrastructure.

Recommended

Action

Restart or power cycle the switch.

SSMD-1205

Message CEE failed programming ETS policy for CEE Map <CEE Map name>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that DCE SSM encountered an unexpected error in programming the dataplane ASIC for

enforcing the Converged Enhanced Ethernet (CEE) Map Enhanced Transmission Selection (ETS)

feature.

Recommended

Action

Delete and reapply the CEE Map ETS policy using the cee-map default command.

If the problem persists, restart or power cycle the switch.

SSMD-1206

Message CEE failed programming CoS to PGID policy for CEE Map <CEE Map name>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that DCE SSM encountered an unexpected error in programming the dataplane ASIC for

enforcing the CEE Map Class of Service (CoS) to Priority Group ID (PGID) mapping feature.

Recommended Action Delete and reapply the CEE Map CoS to PGID policy using the cee-map default command.

If the problem persists, restart or power cycle the switch.

SSMD-1207

Message QoS failed programming interface 0x<Interface ID> Default CoS.

Message Type LOG

Severity WARNING

Probable Cause Indicates that DCE SSM encountered an unexpected error in programming the dataplane ASIC for

enforcing the interface Default CoS feature.

Recommended Delete and reapply the QoS interface Default CoS policy using the **gos cos** command.

Action If the problem persists, restart or power cycle the switch.

SSMD-1208

Message QoS failed programming interface 0x<Interface ID> Trust.

Message Type LOG

Severity WARNING

Probable Cause Indicates that DCE SSM encountered an unexpected error in programming the dataplane ASIC for

enforcing the interface Trust feature.

Recommended Delete and reapply the QoS interface Trust policy using the **qos trust cos** command.

Action

If the problem persists, restart or power cycle the switch.

SSMD-1209

Message QoS failed programming interface 0x<Interface ID> CoS Mutation map.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that DCE SSM encountered an unexpected error in programming the dataplane ASIC for

enforcing the interface CoS Mutation mapping feature.

Recommended Delete and reapply the QoS interface CoS Mutation policy using the **qos cos-mutation** command.

If the problem persists, restart or power cycle the switch.

SSMD-1210

Message QoS failed programming interface 0x<Interface ID> CoS to Traffic Class map.

Message Type LOG

Severity WARNING

Probable Cause Indicates that DCE SSM encountered an unexpected error in programming the dataplane ASIC for

enforcing the CoS to Traffic Class mapping feature.

Recommended Delete and reapply the QoS interface CoS to Traffic Class policy using the qos cos-traffic-class

Action command.

If the problem persists, restart or power cycle the switch.

SSMD-1211

Message QoS failed programming ASIC <ASIC slot number>/<ASIC chip number> Scheduler Control.

Message Type LOG

Severity WARNING

Probable Cause Indicates that DCE SSM encountered an unexpected error in programming the dataplane ASIC for

enforcing the packet Scheduler Control feature.

Recommended Delete and reapply the QoS packet Scheduler Control policy using the qos queue scheduler

Action command.

If the problem persists, restart or power cycle the switch.

SSMD-1212

Message QoS failed programming ASIC <ASIC slot number>/<ASIC chip number> Multicast Scheduler

Control.

Message Type LOG

Severity WARNING

Probable Cause Indicates that DCE SSM encountered an unexpected error in programming the dataplane ASIC for

enforcing the multicast packet Scheduler Control feature.

Recommended Delete and reapply the QoS multicast packet Scheduler Control policy using the qos queue multicast

Action scheduler command.

If the problem persists, restart or power cycle the switch.

SSMD-1213

Message QoS failed programming interface 0x<Interface ID> CoS Tail Drop Threshold.

Message Type LOG

Severity WARNING

Probable Cause Indicates that DCE SSM encountered an unexpected error in programming the dataplane ASIC for

enforcing the interface CoS Tail Drop Threshold feature.

Recommended

Action

Delete and reapply the QoS CoS Tail Drop Threshold policy using the **qos rcv-queue** command.

If the problem persists, restart or power cycle the switch.

SSMD-1214

Message QoS failed programming interface 0x<Interface ID> CoS Tail Drop Threshold.

Message Type LOG

Severity WARNING

Probable Cause Indicates that DCE SSM encountered an unexpected error in programming the dataplane ASIC for

enforcing the interface CoS Tail Drop Threshold feature.

Recommended Delete and reapply the QoS CoS Tail Drop Threshold policy using the **gos rcv-queue** command.

Action

If the problem persists, restart or power cycle the switch.

SSMD-1215

Message QoS failed programming interface 0x<Interface ID> CoS Tail Drop Threshold.

Message Type LOG

Severity WARNING

Probable Cause Indicates that DCE SSM encountered an unexpected error in programming the dataplane ASIC for

enforcing the interface CoS Tail Drop Threshold feature.

Recommended Delete and reapply the QoS CoS Tail Drop Threshold policy using the **gos rcv-queue** command.

Action

If the problem persists, restart or power cycle the switch.

SSMD-1216

Message QoS failed programming interface 0x<Interface ID> Pause.

Message Type LOG

Severity WARNING

Probable Cause Indicates that DCE SSM encountered an unexpected error in programming the dataplane ASIC for

enforcing the interface Pause feature.

Recommended

Action Delete and reapply the QoS Pause policy.

If the message persists, restart or power cycle the switch.

SSMD-1217

Message QoS CEE could not comply with FCoE scheduler policy for CEE Map <CEE Map name>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that DCE SSM was unable to translate the CEE Map and Fibre Channel over Ethernet

(FCoE) configuration into an ETS scheduler policy implementable by the dataplane ASIC.

Recommended Redefine CEE Map and FCoE into a configuration that translates into an ETS scheduler policy

Action requiring eight or fewer traffic classes.

SSMD-1300

Message CEE Map <ceemap> is created with precedence cedence>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified CEE Map has been created.

SSMD-1301

Message CEE Map <ceemap> is deleted.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified CEE Map has been deleted.

SSMD-1302

Message CEE Map <ceemap> priority table <pg ids> are <action>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the priority groups have been added to or removed from the specified CEE Map.

SSMD-1303

Message CEE Map <ceemap> priority group <pg id> with weight <PGID weight> is created with PFC

<pfc>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified priority group has been created.

SSMD-1304

Message CEEM Map <ceemap> priority group <pg id> is deleted.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified priority group has been deleted.

SSMD-1305

Message CEE Map <ceemap> priority group <pg_id> weight is changed from <PGID_weight_new> to

<PGID_weight_old>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified priority group weight has been changed.

SSMD-1306

Message CEE Map <ceemap> priority group <pg_id> is PFC <pfc_status>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified priority group PFC status has been changed.

SSMD-1307

Message <acl_type> access list <acl_name> is created.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified access list has been created.

SSMD-1308

Message <acl_type> access list <acl_name> is deleted.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified access list has been deleted.

SSMD-1309

Message <acl type> access list <acl name> rule sequence number <rule sq no> is <action>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified access list rules were added to or removed from an existing policy.

SSMD-1310

Message ACL <acl name> configured on interface <InterfaceName>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified access list has been configured on the interface.

SSMD-1311

Message ACL <acl_name> is removed from interface <InterfaceName>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified access list has been removed from the interface.

SSMD-1312

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified user profile map has been assigned to the interface.

SSMD-1313

Message <map_type> <map_name> removed from interface <InterfaceName>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified user profile map has been removed from the interface.

SSMD-1314

Message CEE Map <ceemap> precedence changed from precedence old> to ceemap> precedence new>.

Message Type LOG

Severity INFO

Probable Cause Indicates that precedence of the specified CEE Map has been changed.

SSMD-1315

Message CEE Map <ceemap> is incompatible with current firmware. Resetting it to default.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified CEE Map is incompatible with the current firmware and therefore it is reset

to the default.

SSMD-1316

Message CEE Map <ceemap> is reset to default configuration.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified CEE Map is reset to the default using the **no cee-map**name command.

SSMD-1317

Message ACL <acl_name> is being configured on interface <InterfaceName>. This operation could

take a long time.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified access list is being configured on the interface.

SSMD-1318

Message ACL <acl_name> is being removed from interface <InterfaceName>. This operation could

take a long time.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified access list is being removed from the interface.

6.104 SULB Messages

SULB-1001

Message Firmwaredownload command has started. (From v<current version> To v<new version>).

Message Type AUDIT | LOG

Class FIRMWARE

Severity WARNING

Probable Cause Indicates that the **firmwareDownload** command has been entered. This process should take

approximately 17 minutes. The process is set to time out after 30 minutes.

Recommended Do not fail over or power down the system during firmware upgrade. Allow the firmwareDownload

Action command to continue without disruption. No action is required.

Run the **firmwareDownloadStatus** command for more information.

SULB-1002

Message Firmwaredownload command has completed successfully.

Message Type AUDIT | LOG

Class FIRMWARE

Severity INFO

Probable Cause Indicates that the firmwareDownload command has completed successfully and switch firmware has

been updated.

Recommended No action is required. The **firmwareDownload** command has completed as expected.

Action Run the **firmwareDownloadStatus** command for more information. Run the **firmwareShow**

command to verify the firmware versions.

SULB-1003

Message Firmwarecommit has started.

Message Type AUDIT | LOG

Class FIRMWARE

Severity INFO

Probable Cause Indicates that the firmwareCommit command has been entered.

Recommended No action is required. Run the **firmwareDownloadStatus** command for more information.

Action

SULB-1004

Message Firmwarecommit has completed.

Message Type AUDIT | LOG

Class FIRMWARE

Severity INFO

Probable Cause Indicates that the firmwareCommit command has completed successfully.

Recommended No action is required. Run the **firmwareDownloadStatus** command for more information.

Action

SULB-1005

Message Current Active CP is preparing to failover.

Message Type LOG

Severity INFO

Probable Cause Indicates that the active control processor (CP) is about to reboot. The standby CP is taking over as

the active CP.

Recommended No action is required. The **firmwareDownload** command is progressing as expected.

Action

Run the **firmwareDownloadStatus** command for more information.

SULB-1006

Message Forced failover succeeded. New Active CP is running new firmware.

Message Type LOG

Severity INFO

Probable Cause Indicates that the previous standby control processor (CP) has now become the active CP and is

running the new firmware version.

Recommended

No action is required. The firmwareDownload command is progressing as expected.

Action

Run the **firmwareDownloadStatus** command for more information.

SULB-1007

Message Standby CP reboots.

Message Type LOG

Severity INFO

Probable Cause Indicates that the standby control processor (CP) is rebooting with new firmware.

Recommended No action is required. The **firmwareDownload** command is progressing as expected.

Action Run the **firmwareDownloadStatus** command for more information.

SULB-1008

Message Standby CP booted successfully with new firmware.

Message Type LOG

Severity INFO

Probable Cause Indicates that the standby control processor (CP) has rebooted successfully.

Recommended No action is required. The **firmwareDownload** command is progressing as expected.

Action

Run the **firmwareDownloadStatus** command for more information.

SULB-1009

Message Firmwaredownload command failed. Status: 0x<status code>, error: 0x<error code>.

Message Type AUDIT | LOG

Class FIRMWARE

Severity INFO

Probable Cause Indicates that the **firmwareDownload** command failed. The additional *status code* and *error code*

values provide debugging information.

The following table lists firmwareDownload status messages and status codes. Some of them will not be displayed in this

RASLog message and are listed for completeness.

Table 7: Status messages and status codes

Status message	Status code
"Firmware download sanity check failed."	0x30
"Sanity check failed because system is non-redundant."	0x31
"Sanity check failed because firmware download is already in progress."	0x32
"Sanity check failed because Fabric OS is disabled on active CP."	0x33
"Sanity check failed because HAMD is disabled on active CP."	0x34
"Sanity check failed because firmware download process is already in progress."	0x35
"Sanity check failed because Fabric OS is disabled on standby CP."	0x36
"Sanity check failed because HAMD is disabled on standby CP."	0x37
Firmware download failed on standby CP."	0x40
Firmware download failed on standby CP."	0x41
"Firmware download failed on standby CP."	0x42
'Firmware commit failed on standby CP."	0x43
Firmware download failed."	0x44
'Firmware download failed due to IPC error."	0x50
'Unable to check the firmware version on standby CP due to IPC error."	0x51
"Firmware download failed due to IPC error."	0x52
Firmware download failed due to IPC error."	0x53
"Standby CP failed to reboot due to IPC error."	0x54
Firmware commit operation failed due to IPC error."	0x55
"Unable to check the firmware version on standby CP due to IPC error."	0x56
"Unable to restore the original firmware due to standby CP timeout."	0x57
"Standby CP failed to reboot and was not responding."	0x58
'Unable to check the firmware version on standby CP due to IPC error."	0x59
"Sanity check failed because the firmware download operation is already in progress."	0x60
"Sanity check failed because the firmware download operation is already in progress."	0x61
NOT USED	0x62
"System error."	0x63
'Active CP forced failover succeeded. Now the standby CP becomes active CP."	0x64
'Standby CP booted up."	0x65
"Active and standby CP failed to gain HA synchronization within 10 minutes."	0x66
"Standby CP rebooted successfully."	0x67
"Standby CP failed to reboot."	0x68
"Firmware commit has started to restore the secondary partition."	0x69

Table 7: Status messages and status codes

Status message	Status code
"Local CP is restoring its secondary partition."	0x6a
"Unable to restore the secondary partition. Run the firmwareDownloadStatus and firmwareShow commands to see firmware status."	0x6b
"Firmware download has started on standby CP. It might take up to 10 minutes."	0x6c
"Firmware download has completed successfully on standby CP."	0x6d
"Standby CP reboots."	0x6e
"Standby CP failed to boot up."	0x6f
"Standby CP booted up with new firmware."	0x70
"Standby CP failed to boot up with new firmware."	0x71
"Firmware download has completed successfully on standby CP."	0x72
"Firmware download has started on standby CP. It might take up to 10 minutes. "	0x73
"Firmware download has completed successfully on standby CP."	0x74
"Standby CP reboots."	0x75
"Standby CP failed to reboot."	0x76
"Firmware commit has started on standby CP."	0x77
"Firmware commit has completed successfully on standby CP."	0x78
"Standby CP booted up with new firmware."	0x79
"Standby CP failed to boot up with new firmware."	0x7a
"Firmware commit has started on both active and standby CPs."	0x7b
"Firmware commit has completed successfully on both active and standby CPs."	0x7c
"Firmware commit failed on active CP."	0x7d
"The original firmware has been restored successfully on standby CP."	0x7e
"Unable to restore the original firmware on standby CP."	0x7f
"Standby CP reboots."	0x80
"Standby CP failed to reboot."	0x81
"Standby CP booted up with new firmware."	0x82
"Standby CP failed to boot up with new firmware."	0x83
"There was an unexpected reboot during the firmware download operation. The command is aborted."	0x84
"Standby CP was not responding. The command is aborted."	0x85
"Firmware commit has started on both active and standby CPs. Run the firmwareDownloadStatus and firmwareShow commands to see the firmware status."	0x86
"Firmware commit has started on the local CP. Run the firmwareDownloadStatus and firmwareShow commands to see the firmware status."	0x87
"Firmware commit has started on the remote CP. Run the firmwareDownloadStatus and firmwareShow commands to see the firmware status."	0x88
"Run the firmwareDownloadStatus and firmwareShow commands to see the firmware status."	0x89

Table 7: Status messages and status codes

Status message	Status code
"The firmwareDownload command has completed successfully."	0x8a
"The original firmware has been restored successfully."	0x8b
"Remote CP is restoring its secondary partition."	0x8c
"Local CP is restoring its secondary partition."	0x8d
"Remote CP is restoring its secondary partition."	0x8e
"Firmware download has started."	0x8f
"Firmware commit has started."	0x90
"Firmware download has completed successfully."	0x91
"Firmware commit has completed successfully."	0x92
"Firmware commit has started to restore the secondary partition."	0x93
"Firmware commit failed."	0x94
"The secondary partition has been restored successfully."	0x95
"Firmware is being downloaded to the blade. This step may take up to 10 minutes."	0xa0
"Firmware download timed out."	0xa1
"Reboot occurred during firmware download. Firmware commit will be started to recover the blade."	0xa2
"Blade rebooted during firmware commit. The operation will be restarted."	0xa3
"Firmware has been downloaded successfully. Blade is rebooting with the new firmware."	0xa4
"Blade has rebooted successfully."	0xa5
"New firmware failed to boot up. Run the firmwareDownload command again."	0xa6
"Firmware commit has started on the blade. This may take up to 10 minutes."	0xa7
"The firmwareRestore command is entered. System will reboot and a firmware commit operation will start upon bootup."	0xa8
"Switch is relocating the AP image."	0xa9
"The AP image is relocated successfully."	0xaa
"Switch reboots during relocating the AP image. The operation will be restarted."	0xab
"Blade failed to reboot with the original image. The firmwareRestore command failed."	0xac

The following table lists additional **firmwareDownload** error messages and error codes. The error code provide more details on the reason for firmware download failure.

Table 8: Error messages and error codes

Error message	Error code
"Image is up-to-date. No need to download the same version of firmware."	0xF
"Upgrade is inconsistent."	0x10
"OSRootPartition is inconsistent. For example: swap OSRootPartitions and reboot."	0x11

Table 8: Error messages and error codes

Error message	Error code
"Unable to access the required package list file. Check whether the switch is supported by the requested firmware. Also check the firmwareDownload help page for other possible failure reasons."	0x12
"The RPM package database is inconsistent. Contact your switch service provider for recovery."	0x13
"Out of memory."	0x14
"Failed to download RPM package."	0x15
"Unable to create firmware version file."	0x16
"Unexpected system error."	0x17
"Error in getting lock device for firmware download."	0x18
"Error in releasing lock device for firmware download."	0x19
"Firmware commit failed."	0x1a
"Firmware directory structure is not compatible. Check whether the firmware is supported on this platform."	0x1b
"Failed to load the Linux kernel image."	0x1c
"OSLoader is inconsistent."	0x1d
"New image has not been committed. Run the firmwareCommit or firmwareRestore command and then run the firmwareDownload command."	0x1e
"Firmware restore failed."	0x1f
"Both images are mounted to the same device."	0x20
"Unable to uninstall old packages."	0x21
"Firmware download is already in progress."	0x22
"Firmware download timed out."	0x23
"Out of disk space."	0x24
"Primary filesystem is inconsistent. Run the firmwareRestore command to restore the original firmware, or contact your switch service provider for recovery."	0x25
"The post-install script failed."	0x26
"Unexpected reboot."	0x27
"Primary kernel partition is inconsistent. Contact your switch service provider for recovery."	0x28
"The pre-install script failed."	0x29
"The platform option is not supported."	0x2a
"Failed to install RPM package."	0x2b
"Cannot downgrade directly to this version. Downgrade to an intermediate version and then download the desired version."	0x2c
"Invalid RPM package. Reload firmware packages on the file server."	0x2e
"Cannot downgrade due to presence of blade type 17. Remove or power off these blades before proceeding."	0x2f

Table 8: Error messages and error codes

Error message	Error code
"Cannot downgrade due to presence of blade type 24. Remove or power off these blades before "	0x30
"Cannot downgrade due to presence of long-distance ports in LS mode. Remove these settings before proceeding."	0x31
"Network is not reachable. Verify the IP address of the server is correct."	0x32

The following descriptions explain the causes of some common error messages:

- 0x15 "Failed to download RPM package." If this error occurs immediately after firmware download is started, the firmware on the switch may be two releases older than the requested firmware. The firmware download operation supports firmware upgrades within two feature releases (a feature release is indicated by a major number and a minor number; for example, X.Y). In this case, you will need to upgrade to an intermediate version before downloading the desired version. If this error occurs in the middle of a firmware download, the firmware in the file server may be corrupted or there may be a temporary network issue. In this case, retry the **firmwareDownload** command. If the problem persists, contact your system administrator.
- 0x18 "Error in getting lock device for firmware download". This error can be due to another firmware download is already in progress. Run the **firmwareDownloadStatus** command to verify that this is the case. Wait for the current session to finish before proceeding.
- 0x23 "Firmware download timed out." This error may occur because the firmwareDownloadStatus command
 has not completed within the predefined timeout period. It is most often caused by network issues. If the problem
 persists, contact your system administrator.
- 0x24 "Out of disk space." This error may occur because some core dump files have not been removed from the
 filesystem and are using up disk space. Remove these core dump files by using the supportSave command before
 proceeding.
- 0x29 "The pre-install script failed." This error may be caused by an unsupported blade type.
 Remove or power off the unsupported blades before proceeding.
 - 0x2e "Invalid RPM package." This error may be caused by an inconsistent firmware image loaded on the file server. It may also be caused by temporary networking issues. Reload the firmware packages on the file server and then retry the **firmwareDownload** command. If the problem persists, contact your system administrator.

The following table lists the **firmwareDownload** state names and code values. They indicate where in the **firmwareDownload** process the error occurred.

Table 9: Upgrade state and code value

Upgrade state	Code
SUS_PEER_CHECK_SANITY	0x21
SUS_PEER_FWDL_BEGIN	0x22
SUS_SBY_FWDL_BEGIN	0x23
SUS_PEER_REBOOT	0x24
SUS_SBY_REBOOT	0x25
SUS_SBY_FABOS_OK	0x26
SUS_PEER_FS_CHECK	0x27
SUS_SELF_FAILOVER	0x28
SUS_SBY_FWDL1_BEGIN	0x29

Table 9: Upgrade state and code value

Upgrade state	Code
SUS_SELF_FWDL_BEGIN	0x2a
SUS_SELF_COMMIT	0x2b
SUS_SBY_FWC_BEGIN	0x2c
SUS_SBY_COMMIT	0x2d
SUS_SBY_FS_CHECK	0x2e
SUS_ACT_FWC_BEGIN	0x2f
SUS_PEER_RESTORE_BEGIN	0x30
SUS_SBY_RESTORE_BEGIN	0x31
SUS_PEER_FWC_BEGIN	0x32
SUS_PEER_FS_CHECK1	0x33
SUS_FINISH	0x34
SUS_COMMIT	0x35

Recommended Action

Run the **firmwareDownloadStatus** command for more information.

In a modular switch, when the **firmwareDownload** command fails, the command will synchronize the firmware on the two partitions of each CP by starting a firmware commit operation. Wait until this operation completes (about 10 minutes) before attempting another firmware download.

In a modular switch, when the **firmwareDownload** command fails, the two CPs may end up with different versions of firmware and they may not gain high availability (HA) sync. In this case, run the **firmwareDownload** -s command to upgrade the firmware on the standby CP to the same version as the active CP. Then retry the **firmwareDownload** command to download the desired version of firmware onto the CPs.

Refer to the Fabric OS Troubleshooting Guide for troubleshooting information.

SULB-1010

Message Firmwarecommit failed (status=0x<error code>).

Message Type AUDIT | LOG

Class FIRMWARE

Severity INFO

Probable Cause Indicates that the firmwareCommit command failed. The error code provides debugging information.

Recommended If the failure is caused by an inconsistent filesystem, contact your switch service provider.

Action

SULB-1011

Message Firmwaredownload command failed. <error string>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the **firmwareDownload** command failed. The *error string* value indicates the reason for

failure.

Recommended Run the **firmwareDownloadStatus** command for more information.

Action Refer to the *Fabric OS Troubleshooting Guide* for troubleshooting information.

SULB-1017

Message Firmwaredownload failed in slot <Slot number>.

Message Type AUDIT | LOG

Class FIRMWARE

Severity ERROR

Probable Cause Indicates that the **firmwareDownload** command failed on the specified blade. The error may be

caused by the inconsistent application processor (AP) blade firmware stored on the active CP. It may

also be caused by an internal Ethernet issue or by a persistent storage hardware failure.

Recommended Action Run the **slotShow** command. If the blade is in the FAULTY state, run the **slotPowerOff** and **slotPowerOn** commands to trigger another firmware download. If the blade is stuck in the LOADING

state, remove and re-insert the blade to trigger another firmware download. If the problem persists,

contact your switch service provider.

SULB-1018

Message Firmwaredownload timed out in slot <Slot number>.

Message Type AUDIT | LOG

Class FIRMWARE

Severity ERROR

Probable Cause Indicates that there may be error caused by the blade initialization issue after the new firmware is

downloaded and the blade is rebooted. The error may also be caused by an internal Ethernet issue or

by a persistent storage hardware failure.

Recommended Run the **slotShow** command. If the blade is in the FAULTY state, run the **slotPowerOff** and

Action slotPowerOn commands to trigger another firmware download to the blade. If the blade is stuck in the

LOADING state, remove and re-insert the blade to trigger another firmware download. If the problem

persists, contact your switch service provider.

SULB-1020

Message New firmware failed to boot in slot <Slot number>.

Message Type AUDIT | LOG

Class FIRMWARE

Severity ERROR

Probable Cause Indicates that the BP blade is still running the old image even though it should reboot with the new

image. This error may indicate that the new image has not been loaded correctly to the specified

blade.

Recommended Run the **slotShow** command. If the blade is in a FAULTY state, run the **slotPowerOff** and **Action**Action **slotPowerOn** commands to trigger another firmware download to the blade is

slotPowerOn commands to trigger another firmware download to the blade. If the blade is stuck in

LOADING state, remove and re-insert the blade to trigger another firmware download. If the problem

persists, contact your switch service provider.

Message Firmware is being downloaded to the blade in slot <Slot number>.

Message Type AUDIT | LOG

Class FIRMWARE

Severity WARNING

Probable Cause Indicates that the firmware is being loaded to the specified blade.

Recommended Run the **firmwareDownloadStatus** command to monitor the firmware download progress. After it

finishes, run the **firmwareShow** command to verify the firmware versions.

SULB-1022

Message The blade in slot <Slot number> has rebooted successfully with new firmware.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that the blade in the specified slot has rebooted with new firmware. This is a normal step in

the firmware download process.

Recommended Run the **firmwareDownloadStatus** command to monitor the firmware download progress.

Action

Action

SULB-1023

Message The blade in slot <Slot number> has rebooted during firmwaredownload.

Message Type AUDIT | LOG

Class FIRMWARE

Severity WARNING

Probable Cause Indicates that there may be an error caused by an unexpected disruption of the **firmwareDownload**

command; for example, powering off and on of the indicated BP blade in the middle of a firmware download. The error may also be caused by persistent storage hardware failure or by a software error.

Recommended

Action

The **firmwareCommit** command will be started automatically after the blade boots up to repair the secondary partition. If at the end of the firmware commit, the blade firmware version is still inconsistent with the active CP firmware, firmware download will be restarted automatically on the blade. Run the **firmwareDownloadStatus** command to monitor the progress. If the problem persists, contact your switch service provider.

Message Firmware commit has completed on the blade in slot <Slot number>.

Message Type AUDIT | LOG

Class FIRMWARE

Severity WARNING

Probable Cause Indicates that the firmwareCommit command has completed on the specified blade.

Recommended

Action

Run the **firmwareShow** command to verify the firmware versions. If the blade firmware is the same as the active CP firmware, the **firmwareDownload** command has completed successfully on the blade. However, if the firmware commit operation has been started to repair the secondary partition, at the end of the firmware commit, the blade firmware version may still be inconsistent with the active CP firmware. In this case, firmware download will automatically be restarted on the blade. Run the **firmwareDownloadStatus** command to monitor the progress.

SULB-1025

Message The blade in slot <Slot number> will reboot with the new firmware.

Message Type LOG

Severity WARNING

Probable Cause Indicates that new firmware has been downloaded to the specified application processor (AP) blade

and the AP blade will reboot to activate it.

Recommended

Action

Wait for the blade to reboot.

SULB-1026

Message Firmware commit operation started on the blade in slot <Slot number>.

Message Type AUDIT | LOG

Class FIRMWARE

Severity WARNING

Probable Cause Indicates that the firmwareCommit command has started on the specified blade. The operation may

be a normal part of firmware download, or it may have started to repair the secondary partition of the

blade if the secondary partition is corrupted.

Recommended

Action

Wait for the firmware commit operation to complete.

Message The switch has rebooted during relocating the internal firmware image.

Message Type AUDIT | LOG

Class FIRMWARE

Severity WARNING

Probable Cause Indicates that there may be an error caused by an unexpected disruption of the firmwareDownload

command; for example, by powering the switch off and on in the middle of a firmware download. The

error may also be caused by persistent storage hardware failure or by a software error.

Recommended The firmwareDownload command will continue after the switch has rebooted. Run the

Action **firmwareDownloadStatus** command to monitor progress. If the problem persists, contact your switch

service provider.

SULB-1031

Message The switch is relocating an internal firmware image.

Message Type AUDIT | LOG

Class FIRMWARE

Severity WARNING

Probable Cause Indicates that the switch has rebooted with the new firmware and is relocating the application

processor (AP) firmware.

Recommended Wait for the operation to complete.

Action

SULB-1032

Message Relocating an internal firmware image on the CP.

Message Type AUDIT | LOG

Class FIRMWARE

Severity WARNING

Probable Cause Indicates that the switch has started firmware download to the co-CPU.

Recommended Wait for the operation to complete.

Action

Message Switch has completed relocating the internal firmware image.

Message Type AUDIT | LOG

> Class **FIRMWARE**

WARNING Severity

Probable Cause Indicates that the firmware download process has completed normally on the switch.

Recommended Run the firmwareShow command to verify the firmware versions. Run the switchShow command to Action

make sure the switch is enabled.

SULB-1034

Message Relocation of internal image timed out.

Message Type AUDIT | LOG

> **FIRMWARE** Class

Severity **ERROR**

Probable Cause Indicates that there may be an error caused by the switch initialization issue after the internal image is

relocated. It may also be caused by an internal Ethernet issue or by a persistent storage hardware

failure.

Recommended Reboot the switch. This will cause the internal image to be relocated again. Use the

Action firmwareDownloadStatus command to monitor the progress. If the problem persists, contact your

switch service provider.

SULB-1035

Message An error has occurred during relocation of the internal image.

Message Type AUDIT | LOG

> **FIRMWARE** Class

Severity **ERROR**

Probable Cause Indicates that an error has occurred during the relocation of the internal image. The error may be

caused by inconsistent internal firmware image. It may also be caused by an internal Ethernet issue or

a persistent storage hardware failure.

Recommended Reset the switch. This will cause the internal image to be relocated again. If the problem persists,

Action contact your switch service provider.

FOS-90x-Message-RM103 Broadcom

Message <The Version being logged><Version String>.

Message Type LOG

Severity INFO

Probable Cause Indicates the version running in the system. This is generally logged before download and after

download of the firmware to store version information.

SULB-1037

Message HCL failed. Reboot the switch manually using the reboot command. However, it will

disrupt the FC traffic.

Message Type AUDIT | LOG | FFDC

Class FIRMWARE

Severity ERROR

Probable Cause Indicates that Hot Code Load (HCL) has failed. Many reasons, such as a domain not confirmed, can

cause this failure.

Recommended Run the **reboot** command to reboot the switch manually.

Action

SULB-1039

Message CP has completed relocating the internal firmware image.

Message Type AUDIT | LOG

Class FIRMWARE

Severity INFO

Probable Cause Indicates that the firmware download process has completed normally on the control processor (CP).

Recommended Run the **firmwareShow** command to verify the firmware versions.

Action

SULB-1040

Message An error has occurred during relocation of the internal image on the CP.

Message Type AUDIT | LOG

Class FIRMWARE

Severity WARNING

Probable Cause Indicates that an error has occurred during the relocation of the internal image. The error may be

caused by an inconsistent internal firmware image. It may also be caused by an internal Ethernet

Run the firmwareShow command to verify the firmware versions. Run the firmwareDownload

failure.

Recommended

Action command again if the firmware is not updated.

This will cause the internal image to be relocated again. If the problem persists, contact your switch

service provider.

SULB-1041

Message Firmware has been activated successfully on standby CP.

Message Type AUDIT | LOG

Class FIRMWARE

Severity INFO

Probable Cause Indicates that the firmwareActivate command has completed successfully on the standby control

processor (CP).

Recommended No action is required. The firmwareActivate command has completed on the standby CP as

Action expected.

Run the **firmwareShow** command to verify the firmware versions.

SULB-1042

Message Firmwareactivate command has completed successfully.

Message Type AUDIT | LOG

Class FIRMWARE

Severity INFO

Probable Cause Indicates that the **firmwareActivate** command has completed successfully and the switch firmware

has been updated.

Recommended No action is required. The **firmwareActivate** command has completed as expected.

Action Run the **firmwareShow** command to verify the firmware versions.

SULB-1043

Message Firmwareactivate command failed. <error string>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the **firmwareActivate** command failed. The *error string* value indicates the reason for

failure.

Recommended

Action

Run the **firmwareShow** command to verify the firmware versions.

SULB-1044

Message Firmwaredownload to secondary partition has completed successfully.

Message Type LOG

Severity INFO

Probable Cause Indicates that the **firmwareDownload** command to the secondary partition has completed

successfully and the switch will come up with the updated firmware on reboot.

Recommended

Action

No action is required. The switch will auto-reboot with the downloaded firmware.

SULB-1050

Message Firmwaredownload command continues.

Message Type AUDIT | LOG

Class FIRMWARE

Severity INFO

Probable Cause Indicates that the firmwareDownload command is running on the standby control processor (CP) of

the dual-CP system. This process should take approximately 17 minutes. The process is set to time

out after 30 minutes.

Recommended

Action

Do not fail over or power down the system during firmware upgrade. Allow the **firmwareDownload**

command to continue without disruption. No action is required.

Run the firmwareDownloadStatus command for more information.

SULB-1051

Message Detected hot-plug of Standby CP. Firmware from Active CP will automatically be

synchronized to Standby CP.

Message Type AUDIT | LOG

Class FIRMWARE

Severity INFO

Probable Cause Indicates that auto firmware synchronization has started because the standby control processor (CP)

is hot-plugged.

Recommended

No action is required. Firmware download has started on the standby CP.

Action

SULB-1052

Message Firmwaresync has failed.<return code>

Message Type AUDIT | LOG

Class FIRMWARE

Severity ERROR

Probable Cause Indicated that auto firmware synchronization has failed.

Recommended Execute the **firmwareDownloadStatus** and **firmwareShow** commands to view firmware status.

Action Execute the **haShow** command to view the HA state.

SULB-1053

Message <firmware sync complete>

Message Type AUDIT | LOG

Class FIRMWARE

Severity INFO

Probable Cause Indicated that auto firmware synchronization has completed.

SULB-1054

Message Firmwaresync has started

Message Type AUDIT | LOG

Class FIRMWARE

Severity INFO

Probable Cause Indicated that firmware synchronization has started.

SULB-1055

Message Firmware upgrade on the blade in slot <Slot number> has completed.

Message Type AUDIT | LOG

Class FIRMWARE

Severity WARNING

Probable Cause Indicates that the firmware upgrade on the specified blade has completed.

Recommended No action is required. The **firmwareDownload** command has completed as expected.

Action
Run the **firmwareDownloadStatus** command for more information. Run the **firmwareShow**

command to verify the firmware versions.

SULB-1056

Message Firmware is being downloaded to the blade in slot <Slot number>.

Message Type AUDIT | LOG

Class FIRMWARE

Severity WARNING

Probable Cause Indicates that the firmware is being loaded to the specified blade.

Recommended Run the **firmwareDownloadStatus** command to monitor the firmware download progress. After it

Action finishes, run the **firmwareShow** command to verify the firmware versions.

SULB-1060

Message Standby CP FOS version (v<major version>.<minor version>.<patch version><patch id>)

is below v6.4.0. CP FOS autosync is not permitted.

Message Type AUDIT | LOG

Class FIRMWARE

Severity WARNING

Probable Cause Indicates that the control processor (CP) auto firmware synchronization is not permitted.

Recommended Manually run **firmwaredownload** command on the standby CP to synchronize it with the same FOS

Action version as on the active CP.

SULB-1061

Message TruFOS Certificate validation failed.

Message Type AUDIT | LOG

Class FIRMWARE

Severity ERROR

Probable Cause Indicates that firmware upgrade token license validation failed.

Recommended No Action is required.

Action

6.105 SWCH Messages

SWCH-1001

Message Switch is not in ready state - Switch enable failed, switch status= 0x<switch status>,

c flags = 0x<switch control flags>.

Message Type LOG

Severity ERROR

Probable Cause
Indicates that the switch is enabled before it is ready.

Recommended If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

Action transfers; then execute the **supportSave** command and contact your switch service provider.

SWCH-1002

Message Security violation: Unauthorized device < wwn name of device> tries to flogin to port

<port number>.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the specified device is not present in the authorized profile list.

Recommended Verify that the device is authorized to log in to the switch. If the device is authorized, execute the

secPolicyDump command to verify whether the World Wide Name (WWN) of the specified device is

listed. If it is not listed, execute the **secPolicyAdd** command to add this device to an existing policy.

SWCH-1003

Message Slot ENABLED but Not Ready during recovery, disabling slot = <slot number>(<return

value>).

Message Type LOG

Severity ERROR

Probable Cause Indicates that the slot state has been detected as inconsistent during failover or recovery.

Recommended For a bladed switch, execute the **slotPowerOff** and **slotPowerOn** commands to power cycle the

Action blade.

For a non-bladed switch, reboot or power cycle the switch.

SWCH-1004

Message Blade attach failed during recovery, disabling slot = <slot number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified blade has failed during failover or recovery.

Recommended For a bladed switch, execute the **slotPowerOff** and **slotPowerOn** commands to power cycle the

Action blade.

For a non-bladed switch, reboot or power cycle the switch.

SWCH-1005

Message Diag attach failed during recovery, disabling slot = <slot number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the diagnostic blade attach operation has failed during failover or recovery.

Recommended For a bladed switch, execute the **slotPowerOff** and **slotPowerOn** commands to power cycle the

Action blade.

For a non-bladed switch, reboot or power cycle the switch.

SWCH-1006

Message HA state out of sync: Standby CP (ver = <standby SWC version>) does not support NPIV

functionality. (active ver = <active SWC version>, NPIV devices = <'1' if NPIV devices

exist; Otherwise '0'>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the standby control processor (CP) does not support N Port ID Virtualization (NPIV)

functionality, but the switch has some NPIV devices logged in to the fabric.

Recommended Action Load a firmware version on a standby CP that supports NPIV functionality using the

firmwareDownload command.

SWCH-1007

Message Switch port <port number> disabled due to \"<disable reason>\".

Message Type LOG

Severity WARNING

Probable Cause Indicates that the switch port is disabled due to the reason displayed in the message.

Recommended Based on the disable reason displayed, take appropriate action to restore the port.

Action

If the disable reason is "Insufficient frame buffers", reduce the distance or speed settings for the port to reduce the buffer requirement of the link. Alternatively, one or more ports in the port group must be

disabled to make more buffers available for the link.

Refer to the Fabric OS Administrator's Guide for more information.

SWCH-1008

Message <area string> are port swapped on ports that do not support port swap. Slot <slot

number> will be faulted.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the blade enabled with the port configuration that does not support port swap.

Recommended Replace the blade with ports that support port swap. Then swap ports back to the port's default area.

Action

Refer to the Fabric OS Administrator's Guide for more information on port swapping.

SWCH-1009

Message Shared area having Trunk Area (TA) enabled on slot <slot number>. Shared areas that

have TA enabled will be persistently disabled.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the blade is enabled with a port configuration that had Trunk Area previously enabled on

the shared area port.

Recommended Disable Trunk Area on ports that had Trunk Area enabled previously. Refer to the Fabric OS

Action Administrator's Guide for more information.

SWCH-1010

Message Trunk Area (TA) enabled on slot <slot number> with switch not in PID format 1. TA

enabled ports will be persistently disabled.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the blade is enabled with the port configuration that had Trunk Area enabled previously.

Recommended Disable Trunk Area on ports that had Trunk Area enabled previously. Refer to the Fabric OS

Action Administrator's Guide for more information.

SWCH-1011

Message HA out of sync: Stby CP (ver=<standby SWC version>) doesn't support Trunk Area

functionality. (active ver=<active SWC version>, TA enabled on sw=<'1' if Trunk Area

ports exist; Otherwise '0'>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the standby control processor (CP) does not support Trunk Area functionality, but the

switch has some ports with Trunk Area enabled.

Recommended Load a firmware version on standby CP that supports Trunk Area functionality by using the

Action **firmwareDownload** command.

SWCH-1012

Message Trunk Area (<trunk area>) has been enabled for one or more ports.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that a Trunk Area has been enabled for one or more ports and the configuration file has been

updated.

SWCH-1013

Message Trunk Area has been disabled for one or more ports.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that a Trunk Area assignment has been disabled for one or more ports and the configuration

file has been updated.

SWCH-1014

Message All Trunk Areas have been disabled.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that all Trunk Areas have been disabled and the configuration file has been updated.

SWCH-1015

Message <Function name> <Description of problem>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that an internal problem has been detected by the software. This is usually an internal Fabric

OS problem or due to file corruption.

Recommended Reboot or power cycle the switch.

Action

If the message persists, execute the **firmwareDownload** command to update the firmware.

SWCH-1016

Message Device <wwn name of device> FDISC to port <port number>. Static persistent PID set

and area requested not assigned to the device. Reject FDISC.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the static persistent port ID (PID) is set and the area requested is not assigned to the

device.

Recommended This is an N Port ID virtualization (NPIV) device and the static persistent PID is set on it, though the

area cannot be assigned as requested. Remove the static binding to have the device come up with a

different area by using the wwnaddress --unbind command.

SWCH-1017

Message Device <wwn name of device> tries to FLOGI to port <port number>, reject FLOGI as

persistent PID is set on the Loop device.

Message Type LOG

Severity INFO

Probable Cause Indicates persistent port ID (PID) is set and static persistent PID is not supported on loop device.

Recommended Remove the WWN-PID binding using the **wwnaddress --unbind** command and re-enable the port.

Action

SWCH-1018

Message Device <wwn name of device> FLOGI to port <port number>, Static persistent PID set,

Requested area <area> user bound to another port. Reject FLOGI.

Message Type LOG

Severity INFO

Probable Cause Indicates a WWN-PID and port address binding collision.

Recommended The persistent PID is set on the device and the requested area cannot be assigned because it is user bound to a different port. Remove the WWN-PID binding using the **wwnaddress --unbind** command

or remove the port address binding using the **portaddress** --unbind command and then re-enable the

port.

SWCH-1019

Message Device <wwn name of device> tries to FLOGI, reject FLOGI as persistent PID is set on

device and port <port number> has user area <area> bound to it.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates a WWN-PID and port address binding collision.

Recommended The persistent PID is set on the device and the requested area cannot be assigned because the port it

is trying to log in through has a different area bound to it. Remove the WWN-PID binding using the

wwnaddress --unbind command or remove the port address binding using the portaddress --

unbind command and then re-enable the port.

SWCH-1020

Message HA state out of sync: Standby CP (ver = <standby SWC version>) does not support QoS

links to AG(Active CP version = <active SWC version>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the standby control processor (CP) does not support links to Access Gateway running

quality of service (QoS).

Recommended Load a firmware version on the standby CP that supports QoS links to Access Gateway by using the

firmwareDownload command.

SWCH-1021

Message HA state out of sync: Standby CP (ver = <standby SWC version>) does not support Dynamic

area on default switch (Active CP version = <active SWC version>).

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that the standby control processor (CP) does not support dynamic area on the default switch.

Recommended Load a firmware version on the standby CP that supports dynamic area on the default switch by using

Action the **firmwareDownload** command.

SWCH-1022

Message Port:<port number> has been disabled due to port address conflict while enabling FMS

mode.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the switch has ports with FICON Management Server (FMS) reserved areas (0xFE,

0xFF) that are not supported in FMS mode.

Recommended No action required. Refer to the FICON Administrator's Guide for more information.

Action

SWCH-1023

Message HA state out of sync: Standby CP (ver = <standby SWC version>) does not support XISL

use while fmsmode and/or lossless are enabled (Active CP version =<active SWC

version>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the standby control processor (CP) does not support extended inter-switch link (XISL)

while FICON Management Server (FMS) mode and Lossless are enabled.

Recommended Action Load a firmware version on standby CP that supports both XISL use and FMS mode and Lossless at the same time by using the **firmwareDownload** command.

SWCH-1024

Message

HA state out of sync: Standby CP (ver = <standby SWC version>) does not support active's enforce login policy (Active CP version =<active SWC version>).

Message Type

LOG

Severity

WARNING

Probable Cause

Indicates that the standby control processor (CP) does not enforce login policy of the active CP.

Recommended

Action

Configure the enforce login policy to a value that the standby CP supports.

SWCH-1025

Message

This Logical Switch has 8Gbps-capable FC ports. Edge Hold Time for these ports is unchanged and is <Edge Hold Time>.

Message Type

LOG

Severity

WARNING

Probable Cause

Indicates that the edge hold time for the 8 Gbps-capable FC ports is not the same as non 8 Gbps-capable FC ports in the logical switch. The 8 Gbps-capable FC ports use the edge hold time configured on the default switch.

Recommended

Action

To know the edge hold time configured for 8 Gbps-capable FC ports, go to the default switch and execute the **configShow** command.

SWCH-1026

Message

HA state out of sync: Standby CP (ver = <standby SWC version>) does not support auto csctl_mode (Active CP version = <active SWC version>).

Message Type

LOG

Severity

WARNING

Probable Cause

Indicates that the standby control processor (CP) does not support auto class-specific control

(CS_CTL) mode.

Recommended

Action

Upgrade the standby CP firmware version to same level as active CP.

SWCH-1027

Message HA state out of sync: Standby CP (ver = <standby SWC version>) does not support NPIV

Base device Logout functionality. (active ver = <active SWC version>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the standby control processor (CP) does not support N Port ID Virtualization (NPIV)

base device logout functionality, but the switch has some ports with base device configured.

Recommended Load a firmware version on standby CP that supports NPIV Base device Logout functionality using the

Action firmwareDownload command, or change the 'base logout' feature with the portCfgNPIVPort

command.

SWCH-1028

Message The base FLOGI device(PID: 0x<PID>)) has logged out from the port (Index <Port

Index>).

Message Type LOG

Severity INFO

Probable Cause Indicates that the FLOGI assigned N Port logged out from the port and other N Ports are still active

on the port.

SWCH-1029

Message supportinfoclear --clear was issued<message>

Message Type AUDIT

Class CLI

Severity INFO

Probable Cause Indicates all the default statistics with portlogs and errorlogs are cleared.

SWCH-1030

Message Switch port <port number> statistics cleared.

Message Type AUDIT

Class FABRIC

Severity INFO

Probable Cause Indicates that the switch port statistics have been cleared.

SWCH-1031

Message Port <port number> recovery failed.

Message Type LOG

Severity WARNING

Probable Cause Indicates that warm recovery for specified port is failed upon high availability (HA).

SWCH-1032

Message Error statistics of the ethernet interface <Interface> was cleared.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates Ethernet management interface error counters are cleared.

SWCH-1033

Message Ethernet connectivity Speed/Duplexity is configured for interface <Interface > .

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause
Indicates Ethernet connectivity parameters speed or duplexity are configured.

SWCH-1034

Message Switch has been enabled.

Message Type AUDIT

Class CLI

Severity INFO

Probable Cause Indicates that a switch is being intentionally enabled.

SWCH-1035

Message Switch has been disabled.

Class CLI

Severity INFO

Probable Cause Indicates that a switch is being intentionally disabled.

SWCH-1036

Message Switch has been persistently enabled.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that a switch is being persistently enabled.

SWCH-1037

Message Switch has been persistently disabled.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that a switch is being persistently disabled.

SWCH-1038

Message Principal Selection Mode has been enabled, which will be activated from the next

fabric rebuild.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that Principal Switch Selection mode has been enabled, which will be activated from next

fabric rebuild.

SWCH-1039

Message Principal Selection Mode has been enabled, which will force fabric rebuild.

Class CFG

Severity INFO

Probable Cause Indicates that Principal Switch Selection mode has been enabled, which will force fabric rebuild.

SWCH-1040

Message Principal Selection Mode has been disabled.

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that Principal Switch Selection mode has been disabled .

SWCH-1041

Message HA state out of sync: Standby CP (ver = <standby SWC version>) does not support FICON

Logical Switch. (active ver = <active SWC version>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the standby control processor (CP) does not support FICON Logical Switch, but the

active switch has a FICON Logical Switch configured..

Recommended Load a firmware version on standby CP that supports FICON Logical Switch functionality using the

firmwareDownload command, or delete the FICON Logical Switch using Iscfg --delete command.

SWCH-1042

Message Bound address for port (ID: <port number>).

Message Type AUDIT

Action

Class CLI

Severity INFO

SWCH-1043

Message Unbound address for port (ID: <port number>).

Class CLI

Severity INFO

Probable Cause User has unbound address to specified port.

SWCH-1044

Message Switch port <port number>. SID:0x<sid>, DID:0x<did>, type:<type> is invalid.

OX ID:0x<OD ID>

Message Type LOG

Severity WARNING

Probable Cause Indicates fab type is invalid.

SWCH-1045

Message Configured NPIV Login Limit of <ConfiguredNPIVLoginLimit> reached on port index

<Port>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the current login is the last one that can be allowed on the given port.

Recommended If more NPIV devices are to be added to this port, the Configured NPIV Limit needs to be increased

Action with portCfgNPIVPort --setloginlimit command.

SWCH-1046

Message Configured NPIV Login Limit of <ConfiguredNPIVLoginLimit> exceeded on port index

<Port>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the current login will not be allowed because the configured NPIV Login Limit has been

exceeded.

Recommended If more NPIV devices are to be added to this port, the Configured NPIV Limit needs to be increased

Action with portCfgNPIVPort --setloginlimit command.

SWCH-1047

Message The max limit of NPIV login which both Active and Standby CP can support has been

reached for port <port number>.

Message Type LOG

Severity WARNING

Probable Cause Indicates max limit of NPIV login has been reached in either Active CP or Standby CP for port in blade

FC32-48

Recommended Load a firmware version on a standby CP that supports the same max limit of NPIV login as in using

Action the **firmwareDownload** command.

SWCH-1048

Message HA state out of sync: Standby CP (ver=<standby SWC version>) does not support the

same max limit of NPIV login as in Active CP (ver=<active SWC version>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the standby control processor (CP) does not support the same max limit of N_Port ID

Virtualization (NPIV) login as in Active CP for the slot port 0-15 in FC32-48 blades

Recommended Load a firmware version on a standby CP that supports the same max limit of NPIV login as in using

Action the **firmwareDownload** command.

SWCH-1049

Message Port <port number> cannot accept more NPIV logins because lossless is disabled in the

< msg > .

Message Type LOG

Severity WARNING

Probable Cause Indicates the number of logins allowed in 9-bit area mode has been exceeded and the port cannot be

converted to 8-bit area mode to allow further logins because lossless is disabled.

Recommended Enable the lossless in the indicating switch.

Action

SWCH-1050

Message Switch beacon has been <printf>.

Message Type AUDIT

Class CLI

Severity INFO

Probable Cause Indicates that a switch beacon is being enabled/disabled.

SWCH-1051

Message Trunk Area (<trunk area>) has been enabled for <port number> port.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that a Trunk Area has been enabled for a port and the configuration file has been updated.

SWCH-1052

Message Trunk Area (<trunk area>) has been disabled for <port number> port.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that a Trunk Area has been disabled for a port and the configuration file has been updated.

SWCH-1053

Message Port <Port Number> has been disabled; device does not support D-Port functionality.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates a device that does not support D-Port functionality has tried to log in to the D-Port of the

switch.

Recommended Configure the D-Port functionality on the device or disable the D-Port configuration. Use the

portcfgdport command to change the D-Port configuration.

SWCH-1060

Message SFP Optics information: <SFP operating msg>.

Message Type AUDIT | LOG

Class CFG

WARNING Severity

Probable Cause Indicates SFP optics related information or warnings messages, this may require user attention.

Recommended

This may require user to check the optics of this port. Action

SWCH-1061

Message HA state out of sync: Standby CP (ver = <standby SWC version>) is not compatible with

Active CP (version = <active SWC version>).

Message Type LOG

> Severity WARNING

Probable Cause Indicates that the standby control processor (CP) is not running a firmware that is compatible with

Active Control Processor (CP).

Recommended Load a firmware version on standby CP that is compatible with Active CP by using the

Action firmwareDownload command.

SWCH-1062

Message Login from <Configured NPIV login limit> rejected on port <Number of logged out WWN-

bound PIDs>. NPIV limit of <printf> reached due to <printf> currently unused bound

addresses.

LOG Message Type

> Severity WARNING

Probable Cause WWN based Persistent PID is enabled on the switch and the number of bound WWNs matches the

> NPIV login limit. Some, but not all, of those bound WWNs are currently logged in. A new WWN attempts to login because the number of actually logged in devices has not yet reached the limit. But

since all the possible PIDs are bound already, the login is unexpectedly rejected.

Recommended

Compare the output of the wwnaddress --show command to the output of the portloginshow Action

command of the identified port to find unused (i.e. not logged in) bound addresses. If those unused addresses will never login to this port again, use the wwnaddress --unbind to remove those bindings

to make room for new WWNs to login.

SWCH-1063

Message Advanced mode is enabled.

Message Type LOG

> Severity **INFO**

Recommended Advanced mode will be enabled.

Action

SWCH-1064

Message Advanced mode is disabled.

Message Type LOG

Severity INFO

Probable Cause User disables Advanced mode for Traffic optimiser.

Recommended Advanced mode will be disabled.

Action

6.106 SYSC Messages

SYSC-1001

Message Failed to run <Name of program that could not be run (string)>:<System internal error

message (string)>.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that one of the programs would not run on the system during the boot sequence.

Recommended If the message is reported during a reboot after new firmware has been loaded, try reloading the

Action firmware using the **firmwareDownload** command.

If the message persists, there may be a conflict between the two versions of firmware or the

nonvolatile storage may be corrupted.

If the message persists, execute the supportFtp command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

SYSC-1002

Message Switch bring-up timed out.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the system timed out during a reboot or failover sequence, waiting for one or more

programs to register with system services or to fail over to active status.

Recommended

Action

The switch is in an inconsistent state and can be corrected only by a reboot or power cycle. Before rebooting the chassis, record the firmware version on the switch or control processor (CP) and run the **haDump** command. If this is a dual-CP switch, gather the output from the CP in which this log

message appeared.

SYSC-1004

Message Daemon <Daemon name to restart> restart successful.

Message Type LOG

Severity INFO

Probable Cause Indicates that a terminated daemon is restarted by the system automatically.

Recommended Execute the **supportSave** command to gather troubleshooting data. No further action is required.

Action

SYSC-1005

Message Daemon < Daemon name to restart > is not restarted (Reason: <Restart failure reason >).

Message Type LOG

Severity WARNING

Probable Cause Indicates that a terminated daemon is not restarted, either because a restart limit is reached or a

restart action fails.

Recommended Execute the **supportSave** command to gather troubleshooting data. Execute the **reboot** or

Action **haFailover** command to recover the system.

6.107 SYSM Messages

SYSM-1001

Message No memory.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates the switch has run out of system memory.

Recommended Run the **memShow** command to view the switch memory usage.

Action Reboot or power cycle the switch.

Run the **supportFtp** command (as needed) to set up automatic FTP transfers; then run the

supportSave command and contact your switch service provider.

SYSM-1002

Message <number>, Switch: <Switch number>.

Message Type LOG

Severity INFO

Probable Cause Indicates a user has executed either the switchShutdown or switchReboot command. All services

are brought down for a logical switch.

Recommended No action is required if the **switchShutdown** or **switchReboot** command was executed intentionally.

If the switchShutdown command was run, you must run the switchStart command to restart traffic

on the logical switch.

SYSM-1003

Message <number>, Switch: <start reason>.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates the user executed the **switchStart** or **switchReboot** command. All services are brought

back up after a temporary shutdown of the logical switch.

Recommended No action is required if the **switchStart** command was executed intentionally. Because reinitializing a

switch is a disruptive operation and can stop I/O traffic, you may have to stop and restart the traffic

during this process.

SYSM-1004

Message Failed to retrieve current chassis configuration option, ret=<Unknown>.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates there was a failure to read configuration data from the World Wide Name (WWN) card.

Recommended Verify that the WWN card is present and operational and the affected control processor (CP) is

Action properly seated in its slot.

SYSM-1005

Message CP blade in slot <Slot number> failed to retrieve current chassis type.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates there was a failure to read the chassis type from the system.

Recommended Verify the control processor (CP) blade is operational and is properly seated in its slot.

Action

SYSM-1006

Message CP blade in slot <Slot number> is incompatible with the chassis type.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates this chassis type is not compatible with the control processor (CP) blade.

Recommended Use the CP blade on a compatible chassis.

Action

SYSM-1007

Message PERMITTING USE OF INCOMPATIBLE CHASSIS FOR CP IN SLOT <Slot number>. DATA ERRORS MAY

RESULT.

Message Type LOG

Severity WARNING

Probable Cause Indicates an override of the incompatible control processor (CP) or chassis check. This message is for

engineering use only.

Recommended Delete the /var/chassis_backplane_override file and reboot the CP.

Action

SYSM-1008

Message RON is set successfully - <roname>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that Registered Organization Name(RON) is set. This message is for engineering use only.

Recommended None.

Action

6.108 TRCE Messages

TRCE-1001

Message Trace dump available<slot on which the trace dump occurs>! (reason: <cause of trace

dump: PANIC DUMP, WATCHDOG EXPIRED, MANUAL, TRIGGER>).

Message Type LOG

Severity WARNING

Probable Cause

Indicates that trace dump files have been generated on the switch or the specified slot. The cause for the dump can be one of the following:

PANICDUMP: Generated by panic dump.

■ WATCHDOG EXPIRED: Generated by hardware watchdog expiration.

• MANUAL: Generated manually by issuing the **tracedump -n** command.

■ TRIGGER: Triggered by a specific Message ID generated by CRITICAL RASLog message.

Recommended Action Execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

TRCE-1002

Message Trace dump<optional slot indicating on which slot the dump occurs> automatically

transferred to address ' <FTP target designated by user> '.

Message Type LOG

Severity INFO

Probable Cause Indicates that a trace dump has occurred on the switch or the specified slot, and the trace dump files

were automatically transferred from the switch to the specified FTP server.

TRCE-1003

Message Trace dump<optional slot indicating on which slot the dump occurs> was not transferred

due to FTP error.

Message Type LOG

Severity ERROR

Probable Cause Indicates that a trace dump has occurred on the switch or the specified slot, but the trace dump files

were not automatically transferred from the switch due to reasons such as an FTP error, wrong FTP

address, FTP site is down, and network is down.

Recommended Execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the

supportSave command and contact your switch service provider.

TRCE-1004

Message Trace dump<slot on which the trace dump occurs> was not transferred because trace

auto-FTP disabled.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that trace dump files have been created on the switch or the specified slot, but the trace

dump files were not automatically transferred from the switch because auto-FTP is disabled.

Recommended Execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the

Action supportSave command and contact your switch service provider.

TRCE-1005

Message FTP Connectivity Test failed due to error.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the connectivity test to the FTP host failed because of reasons such as a wrong FTP

address, FTP site is down, or network is down.

Recommended Execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the

supportSave command and contact your switch service provider.

TRCE-1006

Message FTP Connectivity Test succeeded to FTP site ' <FTP target configured by users> '.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that a connectivity test to the FTP host has succeeded.

TRCE-1007

Message Notification of this CP has failed. Parameters temporarily out of sync with other CP.

Message Type LOG

Severity INFO

Probable Cause Indicates that the active control processor (CP) is unable to alert the standby CP of a change in trace

status. This message is only applicable to bladed switches.

Recommended This message is often transitory. Wait a few minutes and try the command again.

Action

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

TRCE-1008

Message Unable to load trace parameters.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the active control processor (CP) is unable to read the stored trace parameters.

Recommended Reboot the CP (dual-CP system) or restart the switch.

Action

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

TRCE-1009

Message Unable to alert active CP that a dump has occurred.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the control processor (CP) is unable to communicate trace information to active CP. This

message is only applicable to bladed switches.

Recommended

Action

Execute the **haShow** command to verify that the current management module is standby and the

active management module is active.

If the message persists, execute the supportFtp command (as needed) to set up automatic FTP

transfers; then execute the supportSave command and contact your switch service provider.

TRCE-1010

Message Traced fails to start.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the trace daemon (traced), which is used for transferring the trace files has failed to start.

The trace capability within the switch is unaffected. The system automatically restarts the traced facility

after a brief delay.

Recommended

Action

Reboot the CP (dual-CP system) or restart the switch.

If the message persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the supportSave command and contact your switch service provider.

TRCE-1011

Message Trace dump manually transferred to target ' <optional string to indicate which slot

the trace dump is transferred> $\hbox{\tt ':}$ $\hbox{\tt <result>}.$

Message Type LOG

Severity INFO

Probable Cause Indicates that the trace dump files were transferred manually to the specified slot.

TRCE-1012

Message The system was unable to retrieve trace information from slot <Slot number of the

interface module on which the attempt was made>.

Message Type LOG

WARNING Severity

Probable Cause Indicates that the system was unable to retrieve trace information from the specified slot because

there is no communication between the main system and the slot.

Recommended Check that the interface module is enabled and retry the command. If the interface module is already Action

enabled, execute the supportSave command and contact your switch service provider.

TRCE-1013

Message Trace dump <slot on which the trace dump occurs> was not transferred as FIPS mode is

enabled.

Message Type LOG

> WARNING Severity

Probable Cause Indicates that a trace dump has occurred on the switch or the specified slot, but the trace dump files

were not automatically transferred from the switch because FIPS mode is enabled on the switch.

6.109 TS Messages

TS-1001

Message NTP Query failed: <error code>.

LOG Message Type

Action

WARNING Severity

Probable Cause Indicates that a Network Time Protocol (NTP) guery to the configured external clock server failed.

Local clock time on the principal or primary fabric configuration server (FCS) switch is used for fabric

synchronization.

This message may be logged during temporary operational issues such as IP network connection

issues to the external clock server. If the message does not recur, it can be ignored.

Recommended Execute the tsClockServer command to verify that the configured external clock server is available

and functional. If that external clock server is not available, choose another clock server.

TS-1002

Message <Type of clock server used> used instead of <Type of clock server configured>: locl:

0x<Reference ID of LOCL> remote: 0x<Reference ID of external clock server>.

Message Type LOG | AUDIT

> Class **SECURITY**

Severity INFO

Probable Cause

Indicates the fabric time synchronization was sourced from an alternate clock server instead of the configured clock server. The clock server used can be one of the following type:

- LOCL Local clock on the principal or primary FCS switch.
- External External Network Time Protocol (NTP) server address configured.

This message may be logged during temporary operational issues such as IP network connection issues to the external clock server or the fabric is configured for external time synchronization but the principal or primary fabric configuration server (FCS) does not support the feature. If the message does not recur, it can be ignored.

Recommended Action

Execute the **tsClockServer** command to verify that the principal or primary FCS switch has the clock server IP configured correctly, and the configured clock server is accessible to the switch and functional. If the principal or primary FCS does not support the feature, either choose a different switch for the role or reset the clock server to LOCL.

TS-1006

Message <message>.

Message Type LOG

Severity INFO

Probable Cause

Indicates that a time service event is occurring or has failed. The message can be one of the following:

- Init failed. Time Service exiting Initialization error, but the time server exits.
- Synchronizing time of day clock Usually logged during temporary operational issues when the clock goes out of synchronization. For example, when a time update packet is missed due to fabric reconfiguration or role change of the principal or primary fabric configuration server (FCS) switch. If the message does not recur, it can be ignored.
- Validating time update Usually logged during temporary operational issues when a time update
 packet cannot be validated in a secure fabric. For example, during fabric reconfiguration or role
 change of the primary FCS switch. If the message does not recur, it can be ignored.

TS-1007

Message <message>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a switch is trying to set the clock server, which is not the primary fabric configuration

server (FCS) across the fabric. A consistent FCS policy must be implemented across the fabric.

Recommended

Action

Execute the **secPolicyShow** command to verify that the FCS policy is consistent across the fabric.

TS-1008

Message <New clock server used> Clock Server used instead of <Old server configured>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the source of fabric time synchronization distributed from the principal or primary fabric

configuration server (FCS) switch was changed to another configured clock server. This happens when the Network Time Protocol (NTP) query to the current active external clock server failed.

TS-1009

Message Date changed by user from <Old system time> to <Updated system time by the user>.

Message Type LOG | AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that the system date has been changed by the user.

TS-1010

Message NTP Server Time Update from <Old system time> to <Updated system time received from

NTP server>

Message Type LOG | AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that the time is updated by the Network Time Protocol (NTP) server.

TS-1011

Message <message>.

Message Type LOG | AUDIT | FFDC

Class SECURITY

Severity INFO

Probable Cause Indicates that the hardware clock update has failed.

Recommended (

Collect supportsave and report to vendor.

Action

TS-1012

Message Timezone changed from <Old Timezone> to <New Timezone>

Message Type LOG | AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that the system timezone is modified.

TS-1013

Message NTP Clock Server List modified to <New NTP Server List> from <Old NTP Server List>.

Message Type LOG | AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates the fabric time synchronization "NTP Clock Server List" is modified

6.110 UCID Messages

UCID-1001

Message roll back message failed

Message Type LOG

Severity ERROR

Probable Cause Indicates a failure in rollback.

Recommended

No action to be taken.

Action

UCID-3001

Message Enabled FCOE provisioning on port <port name>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the port is being Fibre Channel over Ethernet(FCoE) provisioned.

UCID-3002

Message Removed FCOE provisioning on port <port name>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the port is being Fibre Channel over Ethernet(FCoE) provisioned.

UCID-3003

Message <enodes> enodes created

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the enodes have been successfully configured.

UCID-3004

Message FCMAP is updated to <fcmap> for fabric-map <fabricmap>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the fcmap have been successfully updated.

UCID-3005

Message FCoE VLAN is updated to <vlan> for fabric-map <fabricmap>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the VLAN has been successfully updated.

UCID-3006

Message FCoE Priority is updated to <priority> for fabric-map <fabricmap>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the priority has been successfully updated.

UCID-3007

Message FCoE FKA Timeout is updated to <timeout>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the timeout has been successfully updated.

UCID-3008

Message FCoE FKA Interval is updated to <fka>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the FKA interval has been successfully updated

UCID-3009

Message CEE QoS priority group table updated for group number <port_name> with PFC <pfc>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that Converged Enhanced Ethernet(CEE) QoS priority group table updated for group

number.

UCID-3010

Message CEE QoS priority table updated to <pg_tbl_num_1> <pg_tbl_num_2> <pg_tbl_num_3>

<pg tbl num 4> <pg tbl num 5> <pg tbl num 6> <pg tbl num 7>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that Converged Enhanced Ethernet(CEE) QoS priority table is updated.

UCID-3011

Message CEE Qos enabled on port <port name>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that Converged Enhanced Ethernet(CEE) QoS is enabled for port.

UCID-3012

Message CEE Qos disabled on port <port name>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that Converged Enhanced Ethernet(CEE) QoS is disabled for port.

UCID-3013

Message CEE Qos updated to default configuration

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the Converged Enhanced Ethernet(CEE) Qos configuration is updated to default.

UCID-3014

Message LLDP global configuration are enabled on all ports

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that Link Layer Discovery Protocol(LLDP) global configuration is enabled on all ports.

UCID-3015

Message LLDP global configuration are disabled on all ports

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that Link Layer Discovery Protocol(LLDP) global configuration is disabled on all ports.

UCID-3016

Message LLDP parameter system name is configured to <sys name>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that Link Layer Discovery Protocol(LLDP) global configuration system name is being

updated.

UCID-3017

Message LLDP parameter system description is configured to <sys_desc>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that Link Layer Discovery Protocol(LLDP) global configuration system description is being

updated.

UCID-3018

Message LLDP parameter transmit interval is configured to <tx_intvl>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that Link Layer Discovery Protocol(LLDP) global configuration transmit interval is being

updated.

UCID-3019

Message LLDP parameter timeout multiplier is configured to <mul>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that Link Layer Discovery Protocol(LLDP) global configuration timeout multiplier is being

updated.

UCID-3020

Message LLDP parameter ISCSI priority is configured to <pri>>>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that Link Layer Discovery Protocol(LLDP) global configuration ISCSI priority is being

updated.

UCID-3021

Message LLDP parameter descriptor name is configured to <desc>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that Link Layer Discovery Protocol(LLDP) global configuration descriptor name is being

updated.

UCID-3022

Message LLDP parameter <tlv_name> tlv is enabled

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that Link Layer Discovery Protocol(LLDP) global configuration tlv is being set.

UCID-3023

Message LLDP parameter <tlv name> tlv is disabled

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that Link Layer Discovery Protocol(LLDP) global configuration tlv is being disabled.

UCID-3025

Message LLDP profile <profile name> created

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that Link Layer Discovery Protocol(LLDP) profile is being created.

UCID-3026

Message LLDP profile <profile_name> deleted

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that Link Layer Discovery Protocol(LLDP) profile is being deleted.

UCID-3027

Message LLDP profile <profile_name> parameter descriptor updated to <desc_name>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that Link Layer Discovery Protocol(LLDP) profile descriptor is being updated.

UCID-3028

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that Link Layer Discovery Protocol(LLDP) profile transmit interval is being updated.

UCID-3029

Message LLDP profile <profile name> parameter timeout multiplier updated to <mul>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that Link Layer Discovery Protocol(LLDP) profile timeout multiplier is being updated.

UCID-3030

Message LLDP profile LLDP profile tlv is enabled

Class CFG

Severity INFO

Probable Cause Indicates that Link Layer Discovery Protocol(LLDP) profile tlv is being set.

UCID-3031

Message LLDP profile <profile_name> parameter <tlv_name> tlv is disabled

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that Link Layer Discovery Protocol(LLDP) profile tlv is being disabled.

UCID-3032

Message LLDP has been enabled on port <port name>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that Link Layer Discovery Protocol(LLDP) has been enabled on port.

UCID-3033

Message LLDP has been disabled on port <port name>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that Link Layer Discovery Protocol(LLDP) has been disabled on port.

UCID-3034

Message LLDP parameter dcbx version is updated to <cee_version> on port <port_name>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that Link Layer Discovery Protocol(LLDP) parameter dcbx version is updated on port.

UCID-3035

Message LLDP profile <profile name> is added to port <port name>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that Link Layer Discovery Protocol(LLDP) profile is added to port.

UCID-3036

Message LLDP profile is removed from port <port_name>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that Link Layer Discovery Protocol(LLDP) profile is removed from port.

UCID-3037

Message Cleared LLDP neighbor devices for port <port_name>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Cleared Link Layer Discovery Protocol(LLDP) neighbors for port.

UCID-3038

Message Cleared LLDP stats for port <port_name>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Cleared Link Layer Discovery Protocol(LLDP) stats for port.

UCID-3039

Message Cleared LLDP neighbor devices for all ports

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Cleared Link Layer Discovery Protocol(LLDP) neighbors for port.

UCID-3040

Message Cleared LLDP stats for all ports

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Cleared Link Layer Discovery Protocol(LLDP) stats for port.

UCID-3041

Message PortChannel <po> is created with type <type>, speed <speed>, key <key> and port member

<port_member>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause portchannel is created.

UCID-3042

Message PortChannel <po> is deleted

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause portchannel is deleted.

UCID-3043

Message PortChannel <po> is enabled

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause portchannel is enabled.

UCID-3044

Message PortChannel <po> is disabled

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause portchannel is disabled.

UCID-3045

Message Port <port name> is added to portchannel <po>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause port member is added to portchannel.

UCID-3046

Message Port <port name> is removed from portchannel <po>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause port member is removed from portchannel.

UCID-3047

Message LACP system priority is updated to <priority>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause set Link Aggregation Control Protocol(LACP) sytem priority.

UCID-3048

Message PortChannel <po> is updated with speed <speed>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause portchannel Speed is updated.

UCID-3049

Message PortChannel <po> is updated with auto neg <auto neg>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause portchannel auto neg is updated.

UCID-3050

Message Member port <po> of PortChannel <po_num> is set to priority <priority>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause member port priority is updated.

UCID-3051

Message Member port <po> of PortChannel <po_num> is set with timeout <timeout>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Member port timeout is updated.

UCID-3052

Message Cleared FCOE stats on port <port_name>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause cleared Fibre Channel over Ethernet(FCoE) stats for individual ports.

UCID-3053

Message Cleared FCOE stats on all ports

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause cleared Fibre Channel over Ethernet(FCoE) stats for all ports.

UCID-3054

Message FCoE Fabric-map <fabricmap> is created with fcmap <fcmap>, vlan <vlan> and priority

<priority>

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the fabric-map have been successfully created.

UCID-3055

Message Fabric-map <fabricmap> is deleted

Message Type AUDIT

Class CFG

Severity INFO

Probable Cause Indicates that the fabric-map have been successfully removed.

6.111 UCST Messages

UCST-1003

Message Duplicate Path to Domain <domain ID>, Output Port = <port number>, PDB pointer =

0x<value>.

Message Type LOG

Severity INFO

Probable Cause Indicates that duplicate paths were reported to the specified domain from the specified output port.

The PDB pointer value displayed in the message is the address of the path database and provides

debugging information.

UCST-1007

Message Inconsistent route detected: Port = <port number>, should be <port number>.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the switch detected an inconsistency in the routing database between the routing

protocol and the hardware configuration. The first port number displayed is what the hardware has

configured and the second port number displayed is what the protocol is using.

Recommended Run the switchDisable command and then the switchEnable command to reset the routing

Action database. Run the **uRouteShow** command to display the new routing tables.

UCST-1020

Message Static route (input-area: <port number>, domain: <domain ID> output-area: <port

number>) has been ignored due to platform limitation.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the configured static route cannot be applied to the routing database because of a

platform limitation.

UCST-1021

Message In-order delivery option has been enabled.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that in-order delivery (IOD) option has been enabled on the switch. This option guarantees

in-order delivery of frames during fabric topology changes.

UCST-1022

Message In-order delivery option has been disabled.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that in-order delivery (IOD) option has been disabled on the switch. This may cause out-of-

order delivery of frames during fabric topology changes.

UCST-1023

Message Dynamic Load Sharing option has been enabled

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that Dynamic Load Sharing (DLS) option has been enabled on the switch. This will move

existing routes to a new redundant path when this path becomes available.

UCST-1024

Message Dynamic Load Sharing option has been disabled.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that Dynamic Load Sharing (DLS) option has been disabled on the switch.

UCST-1026

Message LossLess-DLS option has been enabled.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the NoFrameDrop option has been enabled. This will help minimize frame loss during

fabric topology changes.

UCST-1027

Message LossLess-DLS option has been disabled.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the NoFrameDrop option has been disabled. This may cause higher frame loss during

fabric topology changes.

UCST-1028

Message E_Port Balance Priority option has been enabled by <functionName>.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that priority is given to make sure that E Port bandwidth demand is balanced.

UCST-1029

Message E Port Balance Priority option has been disabled by <functionName>.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that priority is no longer given to balanced E_Port bandwidth demand when balancing routes.

UCST-1030

Message Two-hop lossless option has been enabled.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the two-hop lossless capability has been enabled on the switch.

UCST-1031

Message Two-hop lossless option has been disabled.

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that the two-hop lossless capabilities have been disabled on the switch.

UCST-1032

Message Route rebalance <printf>

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that E_Port load rebalancing on this logical switch succeeded or failed

UCST-1033

Message Route rebalance all <printf>

Message Type AUDIT | LOG

Class CFG

Severity INFO

Probable Cause Indicates that E_Port load rebalancing on all logical switches succeeded or failed

6.112 UFCS Messages

UFCS-1001

Message Test UFCS RAS Domain ID (<DomainId>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Domain is valid.

Recommended If the message persists, execute the **supportSave** command and contact your switch service provider.

Action

UFCS-1002

Message UFCS Merge Conflict - clientId <Client Id> (<Client Id String>), cfgType

<Configuration Type>, tagId 0x<Tag Id>, opFlag <Op Flag>, domain <Source Domain>,

reason (<Failure Reason Code> - <Failure Reason Description>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that a Universal Fabric Configuration Service (UFCS) merge conflict occurred for the

specified clientId and cfgType.

Recommended Users should attempt to find the specified mismatched configuration and take corrective action to try

Action ar

fix the conflict. If there does not appear to be a configuration conflict or the user is not able to locate the

configuration specified, users can execute the **supportSave** command on both this domain and the

remote

domain specified by the domain field and contact your switch service provider.

UFCS-1003

Message Failed to allocate memory: (<function name>).

Message Type LOG

Severity WARNING

Probable Cause Indicates a failure to allocate memory.

Recommended If the message persists, execute the **supportSave** command and contact your switch service provider.

Action

UFCS-2004

Message UFCS Commit stage Failed - clientId <Client Id> (<Client Id String>), cfgType

<Configuration Type>, tagId $0x<Tag\ Id>$, opFlag <Op Flag>, domain <Source Domain>, reason (<Failure Reason Code>).

Message Type LOG

Severity WARNING

Probable Cause

Indicates that the Universal Fabric Configuration Service (UFCS) commit stage has failed. The failure reason can be one of the following:

- 7 Memory allocation error
- 14 Reliable Transmit With Response (RTWR) send failure

Recommended Action If the message persists, execute the **supportSave** command on both this domain and the remote domain specified by the domain field and contact your switch service provider.

UFCS-2005

Message UFCS Cancel stage Failed - clientId <Client Id> (<Client Id String>), cfgType

<Configuration Type>, tagId 0x<Tag Id>, opFlag <Op Flag>, domain <Source Domain>,

reason (<Failure Reason Code>).

Message Type LOG

Severity WARNING

Probable Cause

Indicates that the Universal Fabric Configuration Service (UFCS) cancel stage has failed. The failure reason can be one of the following:

- 7 Memory allocation error
- 14 Reliable Transmit With Response (RTWR) send failure

Recommended Action If the message persists, execute the **supportSave** command on both this domain and the remote domain specified by the domain field and contact your switch service provider.

UFCS-2006

Message UFCS Transaction Hung - clientId <Client Id> (<Client Id String>), cfgType

<Configuration Type>, tagId 0x<Tag Id>, opFlag <Op Flag>, trans state <Trans State>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the update cannot be completed for an unknown reason.

Recommended If the message persists.

Action

If the message persists, execute the **supportSave** command and contact your switch service provider.

6.113 UPTH Messages

UPTH-1001

Message No minimum cost path in candidate list.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the switch is unreachable because no minimum cost path (MPATH) exists in the

candidate list (domain ID list).

Recommended

Action

No action is required. This error will end the current shortest path first (SPF) computation.

UPTH-1002

Message Domain <domain ID> is unreachable because the enabled TI zone is not compatible with

the fabric configuration.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified switch is unreachable because the traffic isolation (TI) zone and the fabric

configuration are incompatible.

Recommended Clear all TI zones and then create a valid TI zone for your fabric configuration. Refer to the Fabric OS

Action Administrator's Guide for more information on TI zoning.

6.114 VS Messages

VS-1001

Message No virtual PWWN assignment for the device <Login device PWWN>, port <Switch port> or

(AG <AG NWWN> port <AG port>).

Message Type LOG

Severity INFO

Probable Cause Indicates that the device with the virtual Port World Wide Name (PWWN) feature enabled tried to log in

but there is no mapping for the device, port, or Access Gateway (AG) port.

Recommended Execute the **fapwwn** command to map the device, port, or AG port. You can ignore this message if the

Action virtual PWWN is not required.

VS-1002

Message The Virtual PWWN assignment for the device <Login device PWWN>, port <Switch port>

(AG <AG NWWN> port <AG port>) is timed out.

Message Type LOG

Severity INFO

Probable Cause Indicates that the virtual Port World Wide Name (PWWN) association has timed out.

VS-1003

Message Could not find Virtual PWWN config file for the switch.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the configuration file is corrupted or accidentally removed.

Recommended Restart the switch and download the configuration using the **configDownload** command.

Action

VS-1004

Message Could not find Virtual PWWN config file for the switch.

Message Type LOG

Severity INFO

Probable Cause Indicates that the virtual Port World Wide Name (PWWN) feature has been enabled for the first time on

the switch or the configuration file was corrupted or accidentally removed.

Recommended

Action

Creating a new default configuration file. Execute the **configDownload** command to download any of your earlier configurations for the virtual PWWN feature.

VS-1005

Message Virtual PWWN config version mismatch detected.

Message Type LOG

Severity INFO

Probable Cause Indicates that the virtual Port World Wide Name (PWWN) configuration present on the switch is not of

the same Fabric OS version.

Recommended Converting the virtual PWWN configuration to the current Fabric OS version. No action is required.

Action

VS-1006

Message Virtualization services failed to initialize due to lack of enough memory.

Message Type LOG

Severity INFO

Probable Cause Indicates that the system has run out of memory.

VS-1007

Message FSS Registration failed for virtualization services.

Message Type LOG

Severity INFO

Probable Cause Indicates failure in the virtualization service daemon (vsd) startup because vsd has failed to register

with Fabric OS State Synchronization (FSS).

VS-1008

Message Virtualization services failed to create timer.

Message Type LOG

Severity INFO

Probable Cause Indicates failure in the virtualization service daemon (vsd) startup because vsd has failed to create a

timer.

6.115 WEBD Messages

WEBD-1001

Message Missing or Invalid Certificate file -- HTTPS is configured but could not be started.

Message Type LOG

Severity WARNING

Probable Cause Indicates the Secure Sockets Layer (SSL) certificate file is either invalid or absent.

Recommended Install a valid certificate file.

Action

WEBD-1002

Message Missing or Invalid Key file -- HTTPS is configured but could not be started.

Message Type LOG

Severity WARNING

Probable Cause Indicates the Secure Sockets Layer (SSL) key file is either invalid or absent.

Recommended Install a valid key file.

Action

WEBD-1004

Message HTTP server and weblinker process will be restarted due to configuration change.

Message Type LOG

Severity INFO

Probable Cause Indicates the Hypertext Transfer Protocol (HTTP) server configuration has changed.

WEBD-1005

Message HTTP server and weblinker process will be restarted for logfile truncation.

Message Type LOG

Severity WARNING

Probable Cause Indicates the size of the Hypertext Transfer Protocol (HTTP) log file exceeded the maximum limit.

WEBD-1006

Message HTTP server and weblinker restarted due to logfile truncation.

Message Type LOG

Severity INFO

Probable Cause Indicates the size of the Hypertext Transfer Protocol (HTTP) log file exceeded the maximum limit.

WEBD-1007

Message HTTP server and weblinker process will be restarted due to change of IP Address.

Message Type LOG

Severity INFO

Probable Cause Indicates the IP address of the switch changed and the Hypertext Transfer Protocol (HTTP) server is

restarted.

WEBD-1008

Message HTTP server and weblinker process cannot be started.

Message Type LOG | FFDC

Severity WARNING

Probable Cause Indicates a rare error condition in which the built-in recovery process has failed to restore Hypertext

Transfer Protocol (HTTP) services. The problem often results from invalid configuration of Secure

Sockets Layer (SSL) certificates, but there can be more than one reason for such a failure.

Recommended

Action

Verify the certification file; there may be a mismatch involved.

WEBD-1009

Message HTTPS is disabled due to invalid certificate.

Message Type LOG

Severity INFO

Probable Cause Indicates a condition where HTTPS cannot be enabled since certificate file is invalid and HTTP is

enabled

6.116 XTUN Messages

XTUN-1000

Message FTNL Tunnel <VE Port (Tunnel) Number> Missed Data frame:I/T/L:<FC Initiator ID>/<FC

Target ID>/<FCP Logical Unit Number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates a missed frame with one or more Fibre Channel Protocol (FCP) data information units during

a SCSI write or read operation.

Recommended If there was an unexpected job failure associated with this event, contact your vendor's customer

Action support for assistance.

XTUN-1001

Message FTNL Tunnel <VE Port (Tunnel) Number> Memory allocation failed tracker <Number that

represents the calling source module>/<Line number in that source file>.

Message Type LOG

Severity ERROR

Probable Cause Indicates a memory allocation failure.

Recommended Contact your vendor's customer support for assistance.

Action

XTUN-1002

Message FTNL Tunnel <VE Port (Tunnel) Number> Exchange timeout:I/T/L:<FC Initiator ID>/<FC

Target ID>/<FCP Logical Unit Number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the Fibre Channel Protocol (FCP) exchange has timed out.

Recommended If there was an unexpected job failure associated with this event, contact your vendor's customer

Action support for assistance.

XTUN-1003

Message FTNL Tunnel <VE Port (Tunnel) Number> Message Transmission failed:I/T/L/E:<FC

Initiator ID>/<FC Target ID>/<FCP Logical Unit Number>/<Error return value>.

Message Type LOG

Severity ERROR

Probable Cause Indicates a message transmission failure.

Recommended If there was an unexpected job failure associated with this event, contact your vendor's customer

Action support for assistance.

XTUN-1004

Message FTNL Tunnel <VE Port (Tunnel) Number> Exchange aborted:I/T/L:<FC Initiator ID>/<FC

Target ID>/<FCP Logical Unit Number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the Fibre Channel Protocol (FCP) exchange has been aborted by the initiator.

Recommended If there was an unexpected job failure associated with this event, contact your vendor's customer

Action support for assistance.

XTUN-1005

Message FCP emulation for Tunnel/Initiator/Target/LUN:<VE Port (Tunnel) Number>/<FC Initiator

ID>/<FC Target ID>/<FCP Logical Unit Number> may not be optimal.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Fibre Channel Protocol (FCP) emulation is in FastWrite mode and could also be in

Tape Pipelining mode.

Recommended For disk devices, no action is required. For tape devices, device rediscovery is required.

Action

XTUN-1006

Message FCIP FC frame drop due to transmit timeout on slot=<FX8-24/SX6 Slot Number (0 for

7800 and 7840)> DP=<FX8-24/SX6/7840 DP Number (or 0 if 7800)> BLS=<Blaster Image Number (0 or 1)> DR=<FC Descriptor Ring Number> Frames Dropped=<Number of FC frames

that were dropped>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that a Fibre Channel (FC) Send frame timeout occurred and the frames were dropped from

the SW queue.

Recommended This error indicates that there is a slow draining device or a hung Blaster TX Descriptor Ring.

Action

XTUN-1007

Message FCIP FC frame drop due to truncated receive on slot=<FX8-24/SX6 Slot Number (0 for

7800 and 7840) > DP=<FX8-24/SX6/7840 DP Number (or 0 if 7800) > BLS=<Blaster Image Number (0 or 1)> DR=<FC Descriptor Ring Number> Frames Dropped=<Number of FC frames

that were dropped>.

Message Type LOG

> **ERROR** Severity

Probable Cause Indicates that a Fibre Channel (FC) Received frame event was posted, but the frame was dropped due

to an invalid receive length. This error occurs only on faulty hardware.

Recommended Contact your vendor's customer support for assistance.

Action

XTUN-1008

Message FCIP Control block memory usage slot=<FX8-24/SX6 Slot number (0 for 7800 or 7840)>

> DP=<FX8-24/SX6/7840 DP number (or 0 if 7800)> Allocated=<The total allocated bytes from the pool> Free=<The total free bytes remaining in the pool> Total=<The total

size of the pool>.

Message Type LOG

> Severity WARNING

Probable Cause Indicates that the control block memory pool has crossed the usage threshold. This message is

> generated when a significant amount of control block memory has been allocated from the free pool. This memory is limited and you should monitor for events that indicate that greater than 80 percent of

the pool has been allocated.

Recommended Contact your vendor's customer support for assistance.

Action

XTUN-1009

Message FCIP OSTP <Number of FCP write commands that were purged> Write blocks purged due to

> PLOGI slot=<FX8-24/SX6 Slot number (0 for 7800 or 7840) > DP=<FX8-24/SX6/7840 DP number (or 0 if 7800) > SFID=<SFID of the initiator > DFID=<DFID of the tape device > SID/DID/ Lun=0x<SID of the initiator>/<DID of the tape device>/<The tape device LUN number>.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates that more than one outstanding write command that were purged due to the receipt of a new

PLOGI sequence. This can indicate missing blocks on the currently mounted tape. If the tape job

resumed after this error, you must confirm the integrity of the data on the tape.

Recommended

Contact your vendor's customer support for assistance.

Action

XTUN-1010

Message FCIP FC RCV frame drop due to <Reason> on slot=<Slot Number (0 for 7840)> DP=<DP

Number> FPGA=<FPGA Image Number (0 or 1)> VC=<Virtual Circuit (VC) number> Frames

Dropped=<Number of FC frames that were dropped>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that a Fibre Channel (FC) received frame event was posted, but the frame was dropped due

to a receive error. This error is likely faulty hardware.

Recommended Contact your vendor's customer support for assistance.

Action

XTUN-1011

Message FCIP FC RCV low XBAR flow control is <Reason> slot=<Slot Number (0 for 7840)> DP=<DP

Number> FPGA=<FPGA Image Number (0 or 1) > VC=<Virtual Circuit (VC) Number>

Count=<Count of times ON/OFF flow control>.

Message Type LOG

Severity WARNING

Probable Cause Indicates flow control event due to lack of Fibre Channel (FC) receive buffer resources.

Recommended If this event occurs repeatedly, contact your vendor's customer support for assistance.

Action

XTUN-1012

Message Dropped frame with VMID Application header on VE Port=<FX8-24 VE Port Number> SID/

 ${\tt DID:0x<Frame\ Source\ ID>/0x<Frame\ Destination\ ID>\ count=<Count\ of\ frames\ dropped>.}$

Message Type LOG

Severity ERROR

Probable Cause Indicates that the Fibre Channel over IP (FCIP) data processor (DP) discarded a frame that included a

Virtual Machine ID (VMID) application header.

Recommended The FX8-24 does not support processing of VMID headers on an emulation enabled tunnel, contact

Action your vendor's customer support for assistance.

XTUN-1996

Message FTRACE buffer <FTRACE Trace Buffer Number> on slot <FX8-24/SX6 Slot Number (0 for

7800 and 7840)> DP $\langle FX8-24/SX6/7840 \ DP \ Number (or 0 if 7800) \rangle$ has been cleared.

Message Type LOG

Severity INFO

Probable Cause Indicates that a CLI command or supportSave operation freed the trace buffer back into the FTRACE

free pool.

XTUN-1997

Message FTRACE buffer <FTRACE Trace Buffer Number> on slot <FX8-24/SX6 Slot number (0 for

7800 or 7840) > dp < FX8-24/SX6/7840 DP number (or 0 if 7800) > has been triggered.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a programmed trigger event has been detected.

Recommended If there was an unexpected job failure associated with this event, contact your vendor's customer

Action support for assistance.

XTUN-1998

Message FTRACE buffer <FTRACE Trace Buffer Number> has been cleared.

Message Type LOG

Severity INFO

Probable Cause Indicates that a CLI command or supportSave operation freed the trace buffer back into the FTRACE

free pool.

XTUN-1999

Message FTRACE buffer <FTRACE Trace Buffer Number> has been triggered.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a programmed trigger event has been detected.

Recommended If there was an unexpected job failure associated with this event, contact your vendor's customer

Action support for assistance.

XTUN-2000

Message FCIP Tunnel < VE Port (Tunnel) Number > UP.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified Fibre Channel over IP (FCIP) tunnel is up.

XTUN-2001

Message FCIP Tunnel <VE Port (Tunnel) Number> DOWN (<Reason>).

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified Fibre Channel over IP (FCIP) tunnel has gone down.

Recommended If the tunnel has not been administratively disabled or deleted, a possible network error or disruption

Action has occurred.

XTUN-2002

Message FCIP Tunnel <VE Port (Tunnel) Number> Circuit <Circuit Number> UP.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified circuit is up.

XTUN-2003

Message FCIP Tunnel <VE Port (Tunnel) Number> Circuit <Circuit Number> DOWN (<Reason>).

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified circuit has gone down, and the tunnel will also be down if this is the last

circuit available.

Recommended If the tunnel or circuit has not been administratively disabled or deleted, a possible network error or

Action disruption has occurred.

XTUN-2004

Message FCIP Tunnel <VE Port (Tunnel) Number> <Priority Class>-Pri QoS UP.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified quality of service (QoS) for this tunnel is up. This applies to the data

classes only. When the F-Class comes online, the tunnel itself is marked as up.

XTUN-2005

Message FCIP Tunnel <VE Port (Tunnel) Number> <Priority Class>-Pri QoS DOWN (<Reason>).

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified quality of service (QoS) for this tunnel has gone down. This applies to the

data classes only. If the F-Class goes down, the tunnel itself is marked as down.

Recommended If tunnel or circuit has not been administratively disabled or deleted, a possible network error or

Action disruption has occurred.

XTUN-2006

Message FCIP Tunnel < VE Port (Tunnel) Number > CREATED (<Originator >).

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified tunnel has been successfully created.

XTUN-2007

Message FCIP Tunnel <VE Port (Tunnel) Number> Circuit <Circuit Number> CREATED

(<Originator>).

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified circuit has been successfully created.

XTUN-2008

Message IKEv2: <Reason>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the status of an IKEv2 session has changed.

XTUN-2009

Message IPsec: <Reason>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the status of an Internet Protocol security (IPsec) association has changed.

XTUN-2010

Message SPD: <Reason>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the status of an SPD entry has changed.

XTUN-2011

Message FIPS: <Reason>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the status of the module FIPS compliance has changed.

XTUN-2012

Message IKE: Session DP<DP-ID>.<IKE Session ID> <Authentication Method> Authentication

failure.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified Internet Key Exchange (IKE) session authentication has failed.

Recommended Manual recovery of the IKE session is required. See FCIP Admin Guide for recovery steps, or contact

Action your vendor's customer support for assistance.

XTUN-2020

Message FCIP Tunnel < VE Port (Tunnel) Number > DELETED (<Originator >).

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified Fibre Channel over IP (FCIP) tunnel has been administratively deleted.

XTUN-2021

Message FCIP Tunnel <VE Port (Tunnel) Number> Circuit <Circuit Number> DELETED

(<Originator>).

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified circuit has been administratively deleted.

XTUN-2022

Message FCIP Tunnel <VE Port (Tunnel) Number> MODIFIED (<Originator>).

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified Fibre Channel over IP (FCIP) tunnel has been administratively modified.

XTUN-2023

Message FCIP Tunnel <VE Port (Tunnel) Number> MODATTR (<Attribute change description>).

Message Type LOG

Severity INFO

Probable Cause Indicates that the attribute is modified. In most cases, the attribute value is modified within the

specified Fibre Channel over IP (FCIP) tunnel.

XTUN-2024

Message FCIP Tunnel <VE Port (Tunnel) Number> Circuit <Circuit Number> MODIFIED

(<Originator>).

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified circuit has been administratively modified.

XTUN-2025

Message FCIP Tunnel < VE Port (Tunnel) Number > Circuit < Circuit Number > MODATTR (< Attribute

change description>).

Message Type LOG

Severity INFO

Probable Cause Indicates that the attribute is modified. In most cases, the attribute value is modified within the

specified circuit.

XTUN-2026

Message Decomp <Reason>.

Message Type LOG

Severity ERROR

Probable Cause Indicates decompression error due to specified reason.

Recommended Contact your vendor's customer support for assistance.

Action

XTUN-3000

Message WAN Tool session <WAN Tool Session ID> ENABLED.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified WAN Tool session has been administratively enabled.

XTUN-3001

Message WAN Tool session <WAN Tool Session ID> DISABLED.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified WAN Tool session has been administratively disabled.

XTUN-3002

Message WAN Tool session < WAN Tool Session ID> STARTED.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified WAN Tool session traffic has been administratively started.

XTUN-3003

Message WAN Tool session <WAN Tool Session ID> STOP.

Message Type LOG

> Severity INFO

Probable Cause Indicates that the specified WAN Tool session traffic has been administratively stopped.

XTUN-3004

Message WAN Tool session <WAN Tool Session ID> SLA Negotiated Drop: <WAN Tool SLA Drop

percentage>, Runtime: <WAN Tool SLA Runtime time>, Timeout: <WAN Tool SLA Timeout

time>.

Message Type LOG

> Severity **INFO**

Probable Cause Indicates that the specified WAN Tool session has negotiated its Service Level Agreement (SLA)

configuration.

XTUN-3005

Message WAN Tool session <WAN Tool Session ID> SLA Failed to negotiate Reason <WAN Tool

Failure Reason>.

Message Type LOG

> Severity **WARNING**

Probable Cause Indicates that the specified WAN Tool session has failed to negotiate its Service Level Agreement

(SLA) configuration for the specified reason.

Recommended

Action

Check peer SLA configuration and network connectivity.

XTUN-3006

Message WAN Tool session <WAN Tool Session ID> SLA Failed to meet SLA requirements Reason

<WAN Tool Failure Reason>.

Message Type LOG

> Severity WARNING

Probable Cause Indicates that the specified WAN Tool session has failed to meet the Service Level Agreement (SLA)

requirements for the specified reason.

XTUN-3007

FOS-90x-Message-RM103 Broadcom

Message WAN Tool session <WAN Tool Session ID> SLA requirements meet.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified WAN Tool session has successfully met the requirements for the

configured Service Level Agreement (SLA).

XTUN-3008

Message WAN Tool session <WAN Tool Session ID> has completed.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified WAN Tool session has successfully completed running traffic.

XTUN-3009

Message WAN Tool session <WAN Tool Session ID> STOP, Reason: <WAN Tool Stop Reason> request.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified WAN Tool session traffic has been administratively stopped for the

specified reason.

XTUN-3100

Message TCP:Slot=<Slot Number(0 for 7840)> DP=<DP ID>:Reaching maximum TCP connection

limit: <Active Connection Count> of <Maximum Supported TCP Connections>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the maximum supported TCP connection limit is reaching.

Recommended Make sure not to initiate new replications.

Action

XTUN-3101

Message TCP:Slot=<Slot Number(0 for 7840)> DP=<DP ID>:New TCP connections dropped:<Total

number of local/remote connection open failures>, Max supported TCP

connections: <Maximum Supported TCP Connections> reached.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the new TCP connection has failed.

Recommended

Make sure not to initiate new replications.

Action

XTUN-3102

Message TCP:Slot=<Slot Number(0 for 7840)> DP=<DP ID>:New TCP connection dropped, NULL VLAN

ID in SYN packet:<Source IP address/port of dropped connection>-<Destination IP

address/port of dropped connection>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the new TCP connection has failed.

Recommended Check host configuration for valid VLAN ID.

Action

6.117 ZONE Messages

ZONE-1002

Message WWN zoneTypeCheck or zoneGroupCheck warning(<warning string>) at port(<port number>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that a zone filter or zone group check failure occurred. The frame filter logic reported a failure

when creating or adding the zone groups during port login (PLOGI) trap processing. This message usually indicates problems when adding the content-addressable memory (CAM) entries before the

filter setup.

Recommended If the problem persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

ZONE-1003

Message zone(<current zone>) contains (<domain id>, <port number>) which does not exist.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that the port zone member that is targeted for the local switch contains a nonexistent port.

The specified port number in the effective zoning configuration (displayed in the error message) is out of range.

Recommended Action

Edit the zone database and change the port number to a viable value in the effective configuration.

ZONE-1004

Message Base PID: 0x<Base PID>, Port Index: <Port Index>, Port: <Slot/Port>: enforcement changed to Session-based HARD Zoning.

Message Type LOG

Severity INFO

Probable Cause

Indicates that the zoning enforcement has changed to session-based hard zoning due to one of the following conditions:

- The zone has a mix of WWN and domain, index (D,I) members.
- The Source Identifier (S ID) list of the hardware-enforced zoning exceeded the S ID limit.

ZONE-1007

Message Ioctl (<function>) in (<error message>) at port (<port number>) returns code (<error string>) and reason string (<reason string>).

Message Type LOG

Severity INFO

Probable Cause Indicates that frame filter logic reported a failure during the specified I/O Control (IOCTL) call. This is usually a programming error when adding CAM entries before the filter setup.

Recommended Action Avoid this problem in the following ways:

- Avoid having too many hosts zoned with a set of target devices at a single port.
- Avoid having too many zones directed at a single port group on the switch.

ZONE-1010

Message Duplicate entries in zone (<zone name>) specification.

Message Type LOG

Severity WARNING

Probable Cause Indicates that there are duplicate entries in the specified zone object. This message occurs only when

enabling a zone configuration.

Recommended Check the members of the zone using the **cfgShow** command. Delete the duplicate member using the

Action zoneRemove command.

ZONE-1013

Message QuickLoop not supported.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the QuickLoop feature is not supported in the current version of Fabric OS. QuickLoop

zones are not supported in Fabric OS version 4.x or later. Even if the QuickLoop zoning configuration

is enabled on the switch, it will not be supported.

Recommended

Action

Edit the zone database to remove the QuickLoop zoning definition in the effective configuration.

ZONE-1015

Message Not owner of the current transaction <transaction ID>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a zoning change operation is not allowed because the zoning transaction is opened by

another task. Indicates concurrent modification of the zone database by multiple administrators.

Recommended Wait until the previous transaction is completed. Verify that only one administrator is working with the

Action zone database at a time.

ZONE-1017

Message FA Zone (<zone name>) contains incorrect number of Initiator and Target devices.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the fabric assist (FA) zoning configuration has more than one initiator. This is because of

incorrect entries in the FA zoning configuration.

Recommended

Action

Edit the zone database to make sure that only one initiator is set for each FA zone configuration.

ZONE-1019

Message Transaction Commit failed. Reason code <reason code> (<Application reason>) -

\"<reason string>\".

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that reliable commit service (RCS) had a transmit error. RCS is a protocol used to transmit

changes to the configuration database within a fabric.

Recommended Often this message indicates a transitory problem. Wait a few minutes and retry the command.

Make sure your changes to the zone database are not overwriting the work of another administrator.

Execute the **cfgTransShow** command to determine if there is any outstanding transaction running on

the local switches.

If the problem persists, execute the **supportFtp** command (as needed) to set up automatic FTP

transfers; then execute the **supportSave** command and contact your switch service provider.

ZONE-1022

Message The effective configuration has changed to <Effective configuration name>. <AD Id>

Message Type LOG

Severity INFO

Probable Cause Indicates that the effective zone configuration has changed to the specified zone name.

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not

Action planned, take appropriate action as defined by your enterprise security policy.

ZONE-1023

Message Switch connected to port (<port number>) is busy. Retrying zone merge.

Message Type LOG

Severity INFO

Probable Cause Indicates that the switch is retrying the merge operation. This usually occurs if the switch on the other

side of the port is busy.

Recommended

Action

If the problem persists, execute the **supportFtp** command (as needed) to set up automatic FTP transfers; then execute the **supportSave** command and contact your switch service provider.

ZONE-1024

Message <Information message>.

Message Type AUDIT | LOG

Class ZONE

Severity INFO

Probable Cause Indicates that the cfgSave command has completed successfully.

ZONE-1026

Message port <port number> Out of CAM entries.

Message Type LOG

Severity INFO

Probable Cause Indicates that the total number of entries of S_ID CAM is above the limit while creating or adding a

zone group. The maximum number of CAM entries allowed depends on the application-specific

integrated circuit (ASIC).

Recommended

Action

If hardware zoning enforcement is preferred, edit the zoning database to have zoned port IDs (PIDs)

for that port.

ZONE-1027

Message Zoning transaction aborted <error reason>. <AD Id>

Message Type LOG

Severity INFO

Probable Cause

Indicates the zoning transaction was aborted because of a variety of potential errors. The *error reason* variable can be one of the following conditions:

- Zone Merge Received: The fabric is in the process of merging two zone databases.
- Zone Config update Received: The fabric is in the process of updating the zone database.
- Bad Zone Config: The new configuration is not viable.
- Zoning Operation failed: A zoning operation failed.
- Shell exited: The command shell has exited.

- Unknown: An error was received for an unknown reason.
- User Command: A user aborted the current zoning transaction.
- Switch Shutting Down: The switch is currently shutting down.

Most of these error conditions are transitory.

Recommended Action

Try again after some time. Verify that only one administrator is modifying with the zone database at a time.

ZONE-1028

Message Commit zone DB size is larger than the supported limit of the fabric - <zone db size>

greater than <max zone db size>.

Message Type LOG

> **WARNING** Severity

Probable Cause Indicates that the zone database size is greater than the limit allowed by the fabric. The limit of the

zone database size depends on the lowest level switch in the fabric. Older switches have less memory

and force a smaller zone database for the entire fabric.

Recommended Execute the cfgSize command to view the zone database size information. Edit the zone database to Action

keep it within the allowable limit for the specific switches in your fabric.

ZONE-1029

Message Restoring zone cfg from flash failed [<return code>].

LOG Message Type

> Severity WARNING

Probable Cause Indicates that the zone configuration restored from flash memory was faulty.

Recommended If the problem persists, execute the supportFtp command (as needed) to set up automatic FTP

transfers; then execute the supportSave command and contact your switch service provider.

ZONE-1034

Message A new zone database file is created.

LOG Message Type

Action

INFO Severity

Indicates that a new zone database file has been created. **Probable Cause**

ZONE-1036

Message Unable to create <config file name>: error message <System Error Message>.

Message Type LOG

Severity **ERROR**

Probable Cause Indicates that the Fabric OS cannot create the zone configuration file. Typically, the zone configuration

is too large for the memory available on the switch.

Recommended

Action

Reduce the size of the zone database and retry the operation.

ZONE-1037

Message Unable to examine <config file name>: error message <System Error Message>.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates that the Fabric OS cannot examine the zone configuration file. Typically, the zone

configuration is too large for the memory available on the switch.

Recommended Reduce the size of the zone database and retry the operation.

Action

ZONE-1038

Message Unable to allocate memory for <config file name>: error message <System Error

Message>.

LOG Message Type

> **ERROR** Severity

Probable Cause Indicates that the Fabric OS cannot allocate enough memory for the zone configuration file. Typically,

the zone configuration is too large for the memory available on the switch.

Recommended Reduce the size of the zone database and retry the operation.

Action

ZONE-1039

Message Unable to read contents of <config file name>: error message <System Error Message>.

LOG Message Type

> Severity **ERROR**

Probable Cause Indicates that the Fabric OS cannot read the zone configuration file. Typically, the zone configuration is

too large for the memory available on the switch.

Recommended Reduce the size of the zone database and retry the operation.

Action

ZONE-1040

Message Merged zone database exceeds limit.

Message Type LOG

Severity INFO

Probable Cause Indicates that the Fabric OS cannot read the merged zone configuration file. Typically, the zone

configuration is too large for the memory available on the switch.

Recommended Reduce the size of the zone database and retry the operation.

Action

ZONE-1041

Message Unstable link detected during merge at port (<Port number>).

Message Type LOG

Severity WARNING

Probable Cause Indicates a possible unstable link or faulty cable.

Recommended Verify that the small form-factor pluggable (SFP) transceiver and the cable at the specified port are not

Action faulty. Replace the SFP and the cable, if necessary.

ZONE-1042

Message The effective configuration has been disabled. <AD Id>

Message Type LOG

Severity INFO

Probable Cause Indicates that the effective zone configuration has been disabled.

Recommended Verify the event was planned. If the event was planned, no action is required. If the event was not

Action planned, take appropriate action as defined by your enterprise security policy.

ZONE-1043

Message The Default Zone access mode is set to No Access.

Message Type AUDIT | LOG

Class ZONE

Severity INFO

Probable Cause Indicates that the Default Zone access mode is set to No Access.

Recommended Verify the event was planned. If the event was planned, no action is required. If the event was not Action

planned, take appropriate action as defined by your enterprise security policy.

ZONE-1044

Message The Default Zone access mode is set to All Access.

Message Type AUDIT | LOG

> ZONE Class

Severity INFO

Probable Cause Indicates that the Default Zone access mode is set to All Access.

Recommended Verify the event was planned. If the event was planned, no action is required. If the event was not

planned, take appropriate action as defined by your enterprise security policy.

ZONE-1045

Message The Default Zone access mode is already set to No Access.

LOG Message Type

Action

Severity **INFO**

Probable Cause Indicates that the Default Zone access mode is already set to No Access.

ZONE-1046

Message The Default Zone access mode is already set to All Access.

Message Type LOG

> **INFO** Severity

Probable Cause Indicates that the Default Zone access mode is already set to All Access.

ZONE-1048

Message ZONE ACA is rejected on the standby.

Message Type LOG

> WARNING Severity

Probable Cause Indicates that the standby zoning component did not receive a syncdump command from the primary

side.

FOS-90x-Message-RM103 Broadcom

Recommended Action Synchronize the standby control processor (CP) using the haSyncStart command.

ZONE-1049

Message ZONE AD-DefZone conflict detected while system initialization.

Message Type LOG

Severity ERROR

Probable Cause Indicates that there is an Admin Domain (AD) Default Zone conflict.

Recommended Verify that the default zoning mode for AD0 is set to No Access using the **defzone --show** command.

If the default zoning mode is not set to No Access, execute the defzone --noaccess command and

then execute the **cfgsave** command to commit the default zone mode change.

ZONE-1054

Message Default Zone All Access mode is set with Frame Redirection zones.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that the Default Zone All Access mode will not grant all access behavior when the frame

redirection zones are defined.

Recommended Remove frame redirection zones or set the Default Zone access mode to No Access using the

Action defzone --noaccess command.

ZONE-1057

Message II Zone <TI zone name> has domain <Domain ID of switch with version pre6.4.0> running

pre FOS6.4.0 firmware. TI member (Domain <Domain ID of higher port index>, Index

<Higher port index>) is not supported.

Message Type LOG

Severity WARNING

Probable Cause Indicates that an unsupported port index (> 511) is present in the TI zone path or the routing may not

be set up correctly.

Recommended Remove the port index from the TI zone using the **zone** --removename command.

Action

ZONE-1058

Message Domain Comain ID of the switch that becomes unreachable> present in TI zone <TI zone

name> became unreachable due to failover disabled mode.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the domain present in the TI zone path is unreachable. This occurs if the TI zone paths

are unavailable or the TI zone is set up incorrectly.

Recommended Verify that the paths defined by TI zones are online or remove the domain from the TI zone using the

Action **zone** --deletename command.

ZONE-1059

Message Unexpected TI routing behavior or a potentially unroutable TI configuration has been

detected on local domain <Domain ID of the local Logical Switch where the error was

detected>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the current fabric topology and TI zone configuration may result in an unroutable

condition or an unexpected routing behavior.

Recommended Execute the zone --showTlerrors command on the specified switch to report the conflicting

Action configuration details.

ZONE-1060

Message Non-TI and TI failover-enabled traffic restricted to domain <Domain ID> due to TI

failover-disabled zoning.

Message Type LOG

Severity WARNING

Probable Cause Indicates that only TI failover-disabled paths remain to reach the specified domain causing non-TI and

TI failover traffic disruption.

Recommended Add or restore the non-TI or TI failover-enabled inter-switch links (ISLs) to the specified domain.

Action

ZONE-1061

Message Some trunk members are missing from failover disabled active TI zones.

Message Type LOG

Severity WARNING

Probable Cause Indicates that some members in the trunk group are not added to the failover-disabled TI zone. This

will result in traffic disruption if the trunk member goes down.

Recommended If any

Action

If any trunk member is included in the TI failover-disabled zone path, then always add all members from that group. Execute the **zone** --showTltrunkerrors command on the switch to find the missing trunk members in the TI zone.

ZONE-1062

Message Defined and Effective zone configurations are inconsistent.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the defined and effective configurations are different.

Recommended Execute the **cfgEnable** command to make both the configurations consistent.

Action

ZONE-1064

Message Failed to update client capability to ESS (Exchange Switch Support) after maximum

number of retries - return code <Failed return code>. Failing sync dump to standby CP.

Message Type LOG

Severity INFO

Probable Cause Indicates that Exchange Switch Support (ESS) is unable to update its capability. Failed to send the

sync dump to standby control processor (CP).

Recommended Verify that HA synchronization has failed using the **haShow** command. If HA synchronization has

failed, execute the **haSyncStart** command on active CP to resynchronize the HA state.

ZONE-1065

Message Zoning operation (<function>) at port index (<port index>) returns code (<error

code>). Port reset required.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates hardware and software zoning enforcement is out of sync.

Recommended Toggle the port using the **portDisable** and **portEnable** commands in order to recover zoning

Action enforcement.

ZONE-1066

Message Zoning operation failed to complete on the local switch - code <Error Code>.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates an IPC error occurred between Name Server and Zone Server.

Recommended The switch is in an inconsistent state and can be corrected only by a reboot or power cycle.

Upon reboot, if switch is unable to join the fabric due to a zone conflict, issue cfgClear command.

If there is an enabled-configuration, commit **cfgClear** operation by issuing **cfgDisable**.

If there is no enabled-configuration, commit cfgClear operation by issuing cfgSave.

ZONE-1067

Message QoS high zone with Flow ID 5 has been assigned to an alternate VC due to vTap and QoS

high priority zoning compatibility mode.

Message Type LOG

Severity WARNING

Probable Cause Indicates that Virtual Tap (vTAP) and quality of service (QoS) high priority zoning compatibility mode is

enabled and therefore the existing QoSH5 will be remapped to a lower virtual channel (VC).

ZONE-1068

Message Admin Domains are not supported (Event: < Event Name >).

Message Type LOG

Severity WARNING

Probable Cause Indicates that Admin Domains (ADs) are not supported.

ZONE-1069

Message Admin Domains are not supported (Event: <Event Name>, AD<Admin Domain Number>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that Admin Domains (ADs) are not supported.

ZONE-1070

Message Commit zone DB size exceeds the currently available limit in the chassis - <zone db

size> greater than <max chassis zone db size>.

LOG Message Type

> Severity WARNING

Probable Cause Indicates that the zone database size is greater than the limit allowed in the chassis.

Recommended Execute the cfgSize command to view the zone database size information. Edit the zone database to Action

keep it within the allowable chassis limit for the specific switches in your fabric.

ZONE-1071

Message Commit zone DB size is larger than the supported limit of domain <domain> - <zone db

size> greater than <max zone db size>.

Message Type LOG

> Severity WARNING

Probable Cause Indicates that the zone database size is greater than the limit allowed by the domain in the existing

fabric. The limit of the zone database size depends on the lowest level switch in the fabric. Older

switches have less memory and force a smaller zone database for the entire fabric.

Recommended Execute the cfgSize command to view the zone database size information. Edit the zone database to Action

keep it within the allowable limit for the specific switches in your fabric.

ZONE-1072

Message FSS sync failure due to Active CP <reason for sync failure>

LOG Message Type

> Severity **ERROR**

Probable Cause Indicates that the standby zoning component received AD configuration from the primary side.

Recommended To display the AD configuration use ad --exec 255 "ad --show" command or ad --sel 255 command

Action followed by ad --show command.

Synchronize the standby control processor (CP) using the haSyncStart command, after removing AD

configuration on Active CP using ad --deletecommand followed by ad --apply command.

ZONE-1073

Message FCoE device illegally zoned by port, and/or is zoned with device that is port zoned

- affected PID pair (<PID_1>, <PID 2>).

Message Type LOG

> Severity WARNING

Probable Cause Indicates that an FCoE device is either port zoned, and/or is zoned with another device that is port

zoned.

Recommended

Action

Modify the zoning configuration so that devices are not port zoned with any FCoE device.

ZONE-1074

Message Management Interface commit operation did not contain checksum field.

Message Type LOG

Severity INFO

Probable Cause Indicates that the Management Interface commit operation did not contain a checksum field.

This can either indicate that a non-checksum-supporting Interface is connected or that a checksum-

supporting interface failed to provide a checksum.

Recommended

Action

No action is necessary. Users need to be aware that commit operations from non-checksum-

supporting Management Interfaces may result in zoning data being overwritten with stale data.

Please note that this message is only issued upon detecting Checksum-to-NonChecksum transitions.

ZONE-1075

Message Zone fabric lock timeout value has been changed by domain <Domain ID of switch that

initiated the change.> (old <Old timeout value> mins, new <New timeout value> mins).

Message Type LOG

Severity INFO

Probable Cause Indicates that the zone fabric lock timeout value was changed.

Recommended No action is necessary. Users need to be aware that the zone fabric lock timeout duration has been

Action changed.

ZONE-1076

Message Zone fabric lock has been canceled (Reason: <Reason for zone fabric lock

cancellation.>)

Message Type LOG

Severity WARNING

Probable Cause Indicates that the zone fabric lock has been canceled unexpectedly.

Recommended No action is necessary. Users need to be aware that the zone fabric lock has been cleared on the local

Action switch.

ZONE-1077

Message Zone commit from downlevel switch <Domain ID of downlevel switch that initiated the

zone commit. > was blocked due to an active zone fabric lock

Message Type LOG

Severity WARNING

Probable Cause Indicates that the zone commit operation initiated from a downlevel switch was blocked due to there

being an active zone fabric lock.

Recommended No action is necessary. Users need to be aware that there is a downlevel switch in the fabric that does

not support Zone Fabric Locking that is attempting to perform zone commit operations.

ZONE-1078

Message Compressed zone database size exceeds the maximum supported limit. (size <Compressed

zone database size>, max <Maximum Information unit size>)

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the compressed size of the zone database has exceeded the maximum supported inter-

switch Information unit size limit.

Recommended Execute the **cfgSize** command to view the zone database size information. Reduce the zone database

size and retry the operation

ZONE-1079

Message Zone merge failed due to fabric zone database size exceeding limits of switch

attempting merge on port <port>

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that the zone database size is greater than the limit allowed by the switch attempting zone

merge on specified port. The limit of the zone database size depends on the lowest level switch in the

fabric. Older switches have less memory and force a smaller zone database for the entire fabric.

Recommended Execute the **cfgSize** command to view the zone database size information. Reduce the zone database

Action size and reenable the ISLs for the merge operation to be retried

ZONE-1080

Message Traffic Isolation (TI) Zones have been detected and are deprecated in Fabric OS 9.0.0.

Message Type LOG

Severity WARNING

Probable Cause Indicates that Traffic Isolation (TI) zones have either been detected during reboot or were newly

imported when there were none before.

Recommended

Action

No action is necessary. Users need to be aware that Traffic Isolation (TI) zones have been deprecated

and can no longer be created or edited in Fabric OS 9.0.0. Please refer to the Fabric OS

Administrator's Guide for more information

ZONE-1081

Message Frame Redirection (RD) Zones have been detected and are deprecated in Fabric OS 9.0.0.

Message Type LOG

Severity WARNING

Probable Cause Indicates that Frame Redirection (RD) zones have either been detected during reboot or were newly

imported when there were none before.

Recommended No action is necessary. Users need to be aware that Frame Redirection (RD) zones have been

Action deprecated and can no longer be created or edited in Fabric OS 9.0.0. Please refer to the Fabric OS

Administrator's Guide for more information.

ZONE-1082

Message LSAN zones size for configuration <Configuration name> has exceeded the maximum limit.

(size <LSAN zones size>, max <Maximum Information unit size>)

Message Type LOG

Severity ERROR

Probable Cause Indicates that the LSAN zones size for the zone configuration being enabled has exceeded the

maximum inter-switch Information unit size limit.

Recommended Reduce the size and/or number of LSAN zones in the zone configuration and retry the configuration

Action Enable operation

ZONE-1083

Message Invalid peer zone (<Peer zone name>) detected in the zone database. (Reason: <Reason

for bad peer zone>)

Message Type LOG

Severity WARNING

Probable Cause Indicates that an invalid peer zone was detected in the zone database.

Recommended Users should inspect the peer zone that was flagged as invalid and make the necessary zone

Action database corrections.

ZONE-1084

Message Zone fabric lock-principal domain conflict detected with domain <Domain ID of the

switch that is in conflict.>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that there was a zone fabric lock-principal merge conflict.

Recommended Users should first check the zone transaction state on both switches using the **cfgTransShow**

Action command.

Users should be aware that the zone fabric lock has been canceled and zone transactions will remain

open as long as

no other zone commit operation is performed by some other client. Users will want to perform either a

zone edit or

commit operation on the switch whose zone transaction they want to retain.

ZONE-1085

Message Zone fabric lock timeout conflict detected with domain < Domain ID of the switch that

is in conflict.> (local: <Local zone fabric lock timeout value.> mins, remote: <Remote

zone fabric lock timeout value. > mins).

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that there was a merge conflict with the zone fabric lock timeout value.

Recommended Users are suggested to set a consistent timeout value using the zoneFabricLock --timeout command

after the fabric is stable.

ZONE-1086

Message Frame Redirection (RD) Zones detected in the configuration and are not supported in

GEN7 Platforms.

Message Type LOG

Severity WARNING

Probable Cause Indicates that Frame Redirection (RD) zones are present in the configuration but will not be supported

in GEN7 Platforms.

Recommended

Action

Users need to be aware that Frame Redirection (RD) zones have been deprecated and will not be enforced in GEN7 platforms in Fabric OS 9.0.0. Please refer to the Fabric OS Administrator's Guide for more information.

ZONE-1087

Message The zone update did not complete successfully.

Message Type LOG | FFDC

> WARNING Severity

Probable Cause Indicates that there was an error during the zone update from a remote domain. This switch's zone

database may be out of sync with the rest of the switches in the fabric.

Recommended Execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the

Action supportSave command and contact your switch service provider.

ZONE-1088

Message The defined zone database is empty while having an effective zone configuration.

Message Type LOG | FFDC

> **WARNING** Severity

Probable Cause Indicates that a bad zone database state was detected. This switch's zone database may be out of

sync with the rest of the switches in the fabric.

Recommended Execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the

supportSave command and contact your switch service provider.

ZONE-1089

Action

Message The zone message queue has reached <The zone message queue usage high/low threshold

limit.> percent of its maximum limit.

Message Type LOG | FFDC

> WARNING Severity

Probable Cause Indicates that the zoning service is receiving events faster than it is able to process them and the zone

message queue is nearing its maximum limit.

Recommended Execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the Action

supportSave command and contact your switch service provider.

FOS-90x-Message-RM103 Broadcom

ZONE-1090

Message Logical SAN (LSAN) Zones did not get propagated to the Fibre Channel router switch.

Message Type LOG | FFDC

Severity WARNING

Probable Cause Indicates that there was an internal error that prevented LSAN zones from getting propagated to the

Fibre Channel router switch.

Recommended Execute the supportFtp command (as needed) to set up automatic FTP transfers; then execute the

Action supportSave command and contact your switch service provider.

ZONE-1091

Message A stale zone transaction with transaction id \"0x<Zone transaction ID>\" has been

aborted.

Message Type LOG

Severity INFO

Probable Cause The stale zone transaction has been aborted due to the transaction owner no longer being alive

ZONE-1092

Message Invalid entry found in the zone database. \"<Invalid zone object member list>\"

Message Type LOG

Severity WARNING

Probable Cause An unexpected semicolon was found in the zone database.

Action perform zoning operations from another switch that has a valid zone database.

Users should also execute the supportFtp (as needed) to set up automatic FTP transfers; then

Users should refrain from performing any further zoning operations from this switch and instead

execute the **supportSave** and contact your switch service provider.

ZONE-1093

Recommended

Message Broadcast zones have been detected and are deprecated in Fabric OS 9.0.1.

Message Type LOG

Severity WARNING

Probable Cause Indicates that Broadcast zones have either been detected during reboot or were newly imported when

there were none before.

Recommended

Action

No action is necessary. Users need to be aware that Broadcast zones have been deprecated and can no longer be created or edited in Fabric OS 9.0.1. Please refer to the Fabric OS Administrator's Guide for more information.

ZONE-1094

Message The zone database flash file is corrupted.

Message Type LOG | FFDC

Severity ERROR

Probable Cause Indicates that the zone configuration restored from flash memory was corrupted.

Recommended If the problem persists, execute the supportFtp command (as needed) to set up automatic FTP

Action transfers; then execute the **supportSave** command and contact your switch service provider.

ZONE-3001

Message Event: <Event Name>, Status: success, Info: <Zone object type> \"<Zone object member

list>\" added to <Zone object set type> \"<Zone object set name>\".

Message Type AUDIT

Class ZONE

Severity INFO

Probable Cause Indicates that a new zone object member or members have been added to the specified zone object

set.

The zone object type variable can be an alias, zone member, zone, or zone configuration. The string

"..." appears at the end of the zone object member list variable if the list was truncated in the message.

Recommended

Action

Verify that the event was planned. If the event was planned, no action is required. If the event was not planned, take appropriate action as defined by your enterprise security policy.

ZONE-3002

Message Event: <Event Name>, Status: success, Info: <Zone object set type> \"<Zone object set

name>\" created with <Zone object type> \"<Zone object member list>\".

Message Type AUDIT

Class ZONE

Severity INFO

Probable Cause

Indicates that a new zone object set was created and the specified zone object member or members were added to the zone object set.

The *zone object type* variable can be an alias, zone member, zone, or zone configuration. The string "..." appears at the end of the *zone object member list* variable if the list was truncated in the message.

Recommended Action Verify the event was planned. If the event was planned, no action is required. If the event was not planned, take appropriate action as defined by your enterprise security policy.

ZONE-3003

Message Type AUDIT

Class ZONE

Severity INFO

Probable Cause Indicates that the specified zone object has been deleted.

The zone object type variable can be an alias, zone member, zone, or zone configuration.

Recommended Action Verify that the event was planned. If the event was planned, no action is required. If the event was not planned, take appropriate action as defined by your enterprise security policy.

ZONE-3004

Message Event: <Event Name>, Status: success, Info: <Zone object type> \"<Zone object member list>\" removed from <Zone object set type> \"<Zone object set name>\".

Message Type AUDIT

Class ZONE

Severity INFO

Probable Cause Indicates that the specified zone object member or members have been removed from the specified

zone object set.

The *zone object type* variable can be an alias, zone member, zone, or zone configuration. The string "..." appears at the end of the *zone object member list* variable if the list was truncated in the message.

Recommended Action Verify the event was planned. If the event was planned, no action is required. If the event was not planned, take appropriate action as defined by your enterprise security policy.

ZONE-3005

Message Event: <Event Name>, Status: success, Info: All zone information cleared from transaction buffer.

AUDIT Message Type

> Class ZONE

Severity **INFO**

Probable Cause Indicates that all the zone information has been cleared from the transaction buffer.

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not Action

planned, take appropriate action as defined by your enterprise security policy.

ZONE-3006

Message Event: <Event Name>, Status: success, Info: Current zone configuration disabled. <AD

Id>

AUDIT Message Type

> Class ZONE

Severity **INFO**

Probable Cause Indicates that the current zone configuration has been disabled.

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not

planned, take appropriate action as defined by your enterprise security policy.

ZONE-3007

Message Event: <Event Name>, Status: success, Info: Zone configuration \"<Zone

configuration>\" enabled. <AD Id>

Message Type **AUDIT**

Action

Class ZONE

Severity INFO

Probable Cause Indicates that the specified zone configuration has been enabled.

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not

Action planned, take appropriate action as defined by your enterprise security policy.

ZONE-3008

Message Event: <Event Name>, Status: success, Info: Current zone configuration saved to MRAM.

<AD Id>

Message Type **AUDIT**

FOS-90x-Message-RM103 Broadcom

Class ZONE

Severity INFO

Probable Cause Indicates that the current zone configuration has been successfully saved to magnetoresistive random

access memory (MRAM).

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not

planned, take appropriate action as defined by your enterprise security policy.

ZONE-3009

Message Event: <Event Name>, Status: success, Info: <Event Description>.

Message Type AUDIT

Action

Class ZONE

Severity INFO

Probable Cause Indicates that the specified zone transaction has been successful.

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not

planned, take appropriate action as defined by your enterprise security policy.

ZONE-3010

Message Event: <Event Name>, Status: success, Info: Zone object \"<Zone object name>\" copied

to new zone object \"<New Zone object name>\".

Message Type AUDIT

Action

Class ZONE

Severity INFO

Probable Cause Indicates that the specified zone object has been copied to a new zone object.

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not

planned, take appropriate action as defined by your enterprise security policy.

ZONE-3011

Message Event: <Event Name>, Status: success, Info: Zone object \"<Zone object name>\"

expunged.

Message Type AUDIT

Action

Class ZONE

Severity INFO

Probable Cause Indicates that the specified zone object has been expunged.

Action planned, take appropriate action as defined by your enterprise security policy.

ZONE-3012

Recommended

Message Event: <Event Name>, Status: success, Info: Zone object \"<Zone object name>\" renamed

Verify that the event was planned. If the event was planned, no action is required. If the event was not

to \"<New Zone object name>\".

Message Type AUDIT

Class ZONE

Severity INFO

Probable Cause Indicates that the specified zone object has been renamed.

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not

Action planned, take appropriate action as defined by your enterprise security policy.

ZONE-3013

Message Event: <Event Name>, Status: success, Info: <Admin domain type> <Admin domain name>

has been activated.

Message Type AUDIT

Class FABRIC

Severity INFO

Probable Cause Indicates that the specified Admin Domain (AD) has been activated.

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not

planned, take appropriate action as defined by your enterprise security policy.

ZONE-3014

Message Event: <Event Name>, Status: success, Info: \"<AD object member list>\" added to <AD

object set type> \"<AD object set name>\".

Message Type AUDIT

Action

Class FABRIC

Severity INFO

Probable Cause Indicates that the specified new Admin Domain (AD) object member or members have been added to

an AD object set.

The AD object set type variable can be an AD alias or AD member. The string "..." appears at the end

of the AD object member list variable if the list was truncated in the message.

Recommended

Action

Verify that the event was planned. If the event was planned, no action is required. If the event was not

planned, take appropriate action as defined by your enterprise security policy.

ZONE-3015

Message Event: <Event Name>, Status: success, Info: AD configurations applied.

Message Type **AUDIT**

> **FABRIC** Class

Severity INFO

Probable Cause Indicates that the saved Admin Domain (AD) configurations are enforced.

Recommended Verify the event was planned. If the event was planned, no action is required. If the event was not

planned, take appropriate action as defined by your enterprise security policy.

ZONE-3016

Message Event: <Event Name>, Status: success, Info: All AD definitions cleared.

Message Type **AUDIT**

Action

FABRIC Class

Severity **INFO**

Probable Cause Indicates that all Admin Domain (AD) definitions and all zone configurations under them have been

cleared.

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not Action

planned, take appropriate action as defined by your enterprise security policy.

ZONE-3017

Message Event: <Event Name>, Status: success, Info: <AD object set type> \"<AD object set

name>\" created with \"<AD object member list>\".

Message Type **AUDIT**

> Class **FABRIC**

INFO Severity

FOS-90x-Message-RM103 Broadcom

Probable Cause Indicates the specified Admin Domain (AD) has been created.

The *AD object set type* variable can be an AD alias or AD member. The string "..." appears at the end of the *AD object member list* if the list was truncated in the message.

Recommended Verify that the event was planned. If

Verify that the event was planned. If the event was planned, no action is required. If the event was not planned, take appropriate action as defined by your enterprise security policy.

ZONE-3018

Message Event: <Event Name>, Status: success, Info:<AD object type> <AD object name> has been

deactivated.

Message Type AUDIT

Action

Class FABRIC

Severity INFO

Probable Cause Indicates that the specified Admin Domain (AD) object has been deactivated.

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not

planned, take appropriate action as defined by your enterprise security policy.

ZONE-3019

Message Event: <Event Name>, Status: success, Info: <AD object type> \"<AD object name>\"

deleted.

Message Type AUDIT

Action

Class FABRIC

Severity INFO

Probable Cause Indicates that the specified Admin Domain (AD) object has been deleted.

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not

planned, take appropriate action as defined by your enterprise security policy.

ZONE-3020

Message Event: <Event Name>, Status: success, Info: \"<AD object member list>\" removed from

<AD object set type> \"<AD object set name>\".

Message Type AUDIT

Action

Class FABRIC

Severity INFO

Probable Cause Indicates that the specified Admin Domain (AD) member or members have been removed from the

AD.

Recommended

Action

Verify that the event was planned. If the event was planned, no action is required. If the event was not planned, take appropriate action as defined by your enterprise security policy.

ZONE-3021

Message Event: <Event Name>, Status: success, Info: AD object \"<AD object name>\" renamed

to \"<New AD object name>\".

Message Type AUDIT

Class FABRIC

Severity INFO

Probable Cause Indicates that the specified Admin Domain (AD) has been renamed.

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not

planned, take appropriate action as defined by your enterprise security policy.

ZONE-3022

Message Event: <Event Name>, Status: success, Info: Current AD configuration saved to flash.

Message Type AUDIT

Action

Class FABRIC

Severity INFO

Probable Cause Indicates that the current Admin Domain (AD) configuration has been saved to flash memory.

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not

planned, take appropriate action as defined by your enterprise security policy.

ZONE-3023

Message Event: <Event Name>, Status: Failure, Info: AD Apply operation failed due to

transaction conflict.

Message Type AUDIT

Action

Class FABRIC

Severity INFO

Probable Cause Indicates that the **ad --apply** command has failed because of a transaction conflict.

Recommended Action Verify that the event was planned. If the event was planned, no action is required. If the event was not planned, take appropriate action as defined by your enterprise security policy.

ZONE-3024

Message Command: <Command Name>, Status: success, Info: executed. <AD Id>

Message Type AUDIT

Class FABRIC

Severity INFO

Probable Cause Indicates that the ad --transabort command has completed successfully in the specified Admin

Domain (AD).

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not

planned, take appropriate action as defined by your enterprise security policy.

ZONE-3025

Message Command: <Command Name> Info: executed. In AD <AD Id>.

Message Type AUDIT

Action

Class FABRIC

Severity INFO

Probable Cause Indicates that the **ad --exec** command was executed in the specified Admin Domain (AD).

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not

Action planned, take appropriate action as defined by your enterprise security policy.

ZONE-3026

Message Event: <Event Name>, Status: success, Info: Zone object \"<Zone object name>\"

replaced with \"<New Zone object name>\".

Message Type AUDIT

Class ZONE

Severity INFO

Probable Cause Indicates that the specified zone object has been replaced.

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not

Action planned, take appropriate action as defined by your enterprise security policy.

ZONE-3027

Message Target Driven Peer Zone commit configuration \"<Configuration name>\" completed

successfully.

Message Type AUDIT | LOG

Class ZONE

Severity INFO

Probable Cause Indicates that the Target Driven Peer Zone configuration commit has been completed successfully.

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not

Action planned, take appropriate action as defined by your enterprise security policy.

ZONE-3028

Message Target Driven Peer Zone commit configuration <Failure and its reason if available>.

Message Type AUDIT | LOG

Class ZONE

Severity ERROR

Probable Cause Indicates that the Target Driven Peer Zone configuration commit has failed.

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not

Action planned, take appropriate action as defined by your enterprise security policy.

ZONE-3029

Message Target Driven Peer Zone \"<Zone name>\" add operation from device <WWN of the device

which initiated the Target Driven Peer Zone add request> completed successfully.

Message Type AUDIT

Class ZONE

Severity INFO

Probable Cause Indicates that the Target Driven Peer Zone add operation has been completed successfully.

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not

Action planned, take appropriate action as defined by your enterprise security policy.

ZONE-3030

Message Target Driven Peer Zone \"<Zone name>\" replace operation from device <WWN of the

device which initiated the Target Driven Peer Zone replace request> completed successfully.

Message Type AUDIT

Class ZONE

Severity INFO

Probable Cause Indicates that the Target Driven Peer Zone replace operation has been completed successfully.

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not planned, take appropriate action as defined by your enterprise security policy.

ZONE-3031

Message Target Driven Peer Zone \"<Zone name>\" remove operation from device <WWN of the

device which initiated the Target Driven Peer Zone remove request> completed

successfully.

Message Type AUDIT

Class ZONE

Severity INFO

Probable Cause Indicates that the Target Driven Peer Zone remove operation has been completed successfully.

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not

Action planned, take appropriate action as defined by your enterprise security policy.

ZONE-3032

Message Target Driven Peer Zone \"<Zone name>\" add operation from device <WWN of the device

which initiated the Target Driven Peer Zone add request> failed due to an error in

<error description>.

Message Type AUDIT | LOG

Class ZONE

Severity ERROR

Probable Cause Indicates that the Target Driven Peer Zone add operation failed.

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not

Action planned, take appropriate action as defined by your enterprise security policy.

ZONE-3033

Message Target Driven Peer Zone \"<Zone name>\" replace operation from device <WWN of the

device which initiated the Target Driven Peer Zone replace request> failed due to an

error in <error description>.

Message Type AUDIT | LOG

Class ZONE

Severity ERROR

Action

Probable Cause Indicates that the Target Driven Peer Zone replace operation failed.

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not

planned, take appropriate action as defined by your enterprise security policy.

ZONE-3034

Message Target Driven Peer Zone \"<Zone name>\" remove operation from device <WWN of the

device which initiated the Target Driven Peer Zone remove request> failed due to an

error in <error description>.

Message Type AUDIT | LOG

Class ZONE

Severity ERROR

Probable Cause Indicates that the Target Driven Peer Zone remove operation failed.

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not

Action planned, take appropriate action as defined by your enterprise security policy.

Chapter 7: MAPS Monitoring Systems and RASLog IDs

This appendix maps the MAPS monitoring systems to their corresponding RASLog IDs. Refer to the *Brocade*[®] *Fabric OS*[®] *MAPS User Guide*, *9.0.x*, for more information about MAPS threshold values and actions.

Table 10: MAPS Monitoring Systems and RASLog IDs

Monitoring System	RASLOG IDs	Supported Platform
CRC errors (CRC)	MAPS-2004 to 2007	Fabric OS
Invalid transmit words (ITW)	MAPS-2008 to 2011	Fabric OS
Sync loss (LOSS_SYNC)	MAPS-2012 to 2015	Fabric OS
Link failure (LF)	MAPS-2016 to 2019	Fabric OS
Loss of signal (LOSS_SIGNAL)	MAPS-2020 to 2023	Fabric OS
Protocol errors (PE)	MAPS-2024 to 2027	Fabric OS
State change (STATE_CHG)	MAPS-2028 to 2031	Fabric OS
Link reset (LR)	MAPS-2032 to 2035	Fabric OS
C3 timeout (C3TXTO)	MAPS-2036 to 2039	Fabric OS
Receive errors per minute (RX)	MAPS-2040 to 2043	Fabric OS
Transmit errors per minute (TX)	MAPS-2044 to 2047	Fabric OS
Utility errors per minute (UTIL)	MAPS-2048 to 2051	Fabric OS
GE_CRC	MAPS-2060 to 2063	Fabric OS
GE_LOS_OF_SIG	MAPS-2064 to 2067	Fabric OS
Fabric Performance Impact (DEV_LATENCY_IMPACT)	MAPS-2068 to 2071	Fabric OS
DEV_NPIV_LOGINS	MAPS-2080 to 2083	Fabric OS
RX_IOPS	MAPS-2088 to 2091	AMP OS
Block errors per minute (ENCR_BLK)	MAPS-2092 to 2095	Fabric OS
Discard errors per minute (ENCR_DISC)	MAPS-2096 to 2099	Fabric OS
Short frame errors per minute (ENCR_SHRT_FRM)	MAPS-2100 to 2103	Fabric OS
AMP_RX_IOPS	MAPS-2104 to 2107	AMP OS
CRC	MAPS-2108 to 2111	Fabric OS
ITW	MAPS-2112 to 2115	Fabric OS
LR	MAPS-2116 to 2119	Fabric OS
BAD_OS	MAPS-2120 to 2123	Fabric OS
FRM_LONG	MAPS-2124 to 2127	Fabric OS
FRM_TRUNC	MAPS-2128 to 2131	Fabric OS
CIR_STATE	MAPS-2140 to 2143	Fabric OS
CIR_UTIL	MAPS-2144 to 2147	Fabric OS
CIR_PKTLOSS	MAPS-2148 to 2151	Fabric OS

Table 10: MAPS Monitoring Systems and RASLog IDs (Continued)

Monitoring System	RASLOG IDs	Supported Platform
Flash memory percentage used (FLASH_USAGE)	MAPS-2152 to 2155	Fabric OS
CPU percentage used (CPU)	MAPS-2156 to 2159	Fabric OS
Memory percentage used (MEMORY_USAGE)	MAPS-2160 to 2163	Fabric OS
Temperature sensor (TEMP)	MAPS-2164 to 2167	Fabric OS
Power supply (PS_STATE)	MAPS-2168 to 2171	Fabric OS
Fan (FAN_STATE)	MAPS-2172 to 2175	Fabric OS
SFP (SFP_STATE)	MAPS-2180 to 2183	Fabric OS
Slot (BLADE_STATE)	MAPS-2184 to 2187	Fabric OS
WWN (WWN)	MAPS-2188 to 2191	Fabric OS
FAN_AIRFLOW_MISMATCH	MAPS-2192 to 2195	Fabric OS
Telnet violations (SEC_TELNET)	MAPS-2196 to 2199	Fabric OS
HTTP violation (SEC_HTTP)	MAPS-2200 to 2203	Fabric OS
SCC violations (SEC_SCC)	MAPS-2204 to 2207	Fabric OS
DCC violations (SEC_DCC)	MAPS-2208 to 2211	Fabric OS
Login violations (SEC_LV)	MAPS-2212 to 2215	Fabric OS
Invalid certifications (SEC_CERT)	MAPS-2216 to 2219	Fabric OS
TS out of sync (SEC_TS)	MAPS-2220 to 2223	Fabric OS
SLAP failures (SEC_AUTH_FAIL)	MAPS-2224 to 2227	Fabric OS
No FCS (SEC_FCS)	MAPS-2228 to 2231	Fabric OS
Incompatible security DB (SEC_IDB)	MAPS-2232 to 2235	Fabric OS
Illegal command (SEC_CMD)	MAPS-2236 to 2239	Fabric OS
Number of days to expire (DAYS_TO_EXPIRE)	MAPS-2240 to 2243	Fabric OS
Expired certifications (EXPIRED_CERTS)	MAPS-2244 to 2247	Fabric OS
Temperature (SFP_TEMP)	MAPS-2260 to 2263	Fabric OS
Voltage (VOLTAGE)	MAPS-2264 to 2267	Fabric OS
Current (CURRENT)	MAPS-2268 to 2271	Fabric OS
Receive power (RXP)	MAPS-2272 to 2275	Fabric OS
Transmit power (TXP)	MAPS-2276 to 2279	Fabric OS
PWR_HRS	MAPS-2280 to 2283	Fabric OS
BAD_TEMP	MAPS-2284 to 2287	Fabric OS
BAD_PWR	MAPS-2288 to 2291	Fabric OS
BAD_FAN	MAPS-2292 to 2295	Fabric OS
FAULTY_PORTS	MAPS-2296 to 2299	Fabric OS
MISSING_SFP	MAPS-2300 to 2303	Fabric OS
FAULTY_BLADE	MAPS-2304 to 2307	Fabric OS

Table 10: MAPS Monitoring Systems and RASLog IDs (Continued)

Monitoring System	RASLOG IDs	Supported Platform
MARG_PORTS	MAPS-2308 to 2311	Fabric OS
ERR_PORTS	MAPS-2312 to 2315	Fabric OS
E_Ports down (EPORT_DOWN)	MAPS-2316 to 2319	Fabric OS
Fabric reconfiguration (FAB_CFG)	MAPS-2320 to 2323	Fabric OS
Domain ID change (DID_CHG)	MAPS-2324 to 2327	Fabric OS
Segmentation changes (FAB_SEG)	MAPS-2328 to 2331	Fabric OS
Zone changes (ZONE_CHG)	MAPS-2336 to 2339	Fabric OS
Fabric logins (FLOGI)	MAPS-2340 to 2343	Fabric OS
L2 device count (L2_DEVCNT_PER)	MAPS-2344 to 2347	Fabric OS
LSAN device count (LSAN_DEVCNT_PER)	MAPS-2348 to 2351	Fabric OS
Zone configuration size (ZONE_CFGSZ_PER)	MAPS-2352 to 2355	Fabric OS
FCR count (BB_FCR_CNT)	MAPS-2356 to 2359	Fabric OS
DOWN_CORE	MAPS-2360 to 2363	Fabric OS
HA_SYNC	MAPS-2364 to 2367	Fabric OS
WWN_DOWN	MAPS-2368 to 2371	Fabric OS
ETH_MGMT_PORT_STATE	MAPS-2408 to 2411	Fabric OS
TUNNEL_STATE	MAPS-2412 to 2415	Fabric OS
TUNNEL_UTIL	MAPS-2416 to 2419	Fabric OS
QoS utilization percentage (QOS_UTIL)	MAPS-2420 to 2423	Fabric OS
QoS packet loss percentage (PKTLOSS)	MAPS-2424 to 2427	Fabric OS
Circuit round-trip times (RTT)	MAPS-2428 to 2431	Fabric OS
Circuit jitter (JITTER)	MAPS-2432 to 2439	Fabric OS
Circuit QoS utilization percentage (CIR_QOS_UTIL)	MAPS-2440 to 2443	Fabric OS
Circuit QoS packet loss percentage (CIR_QOS_PKTLOSS)	MAPS-2444 to 2447	Fabric OS
RD_STATUS_TIME	MAPS-2968 to 2971	AMP OS
WR_STATUS_TIME	MAPS-2972 to 2975	AMP OS
RD_1stDATA_TIME	MAPS-2976 to 2979	AMP OS
WR_1stXFER_RDY	MAPS-2980 to 2983	AMP OS
RD_PENDING_IO	MAPS-2992 to 2995	Fabric OS
WR_PENDING_IO	MAPS-2996 to 2999	Fabric OS
SCSI_INQ	MAPS-3000 to 3003	Fabric OS
VTAP_IOPS	MAPS-2668 to 2671	Fabric OS
BE_LATENCY_IMPACT	MAPS-2672 to 2675	Fabric OS
TUNNEL_IP_UTIL	MAPS-2700 to 2703	Fabric OS
CIR_IP_UTIL	MAPS-2704 to 2707	Fabric OS

Table 10: MAPS Monitoring Systems and RASLog IDs (Continued)

Monitoring System	RASLOG IDs	Supported Platform
CIR_IP_PKTLOSS	MAPS-2708 to 2711	Fabric OS
IP_RTT	MAPS-2712 to 2715	Fabric OS
IP_JITTER	MAPS-2716 to 2719	Fabric OS
IT_FLOW	MAPS-2936 to 2939	Fabric OS
AVG_PENDING_IOS	MAPS-2940 to 2943	Fabric OS
MAX_PENDING_IOS	MAPS-2944 to 2947	Fabric OS
MAX_ROS	MAPS-2948 to 2951	Fabric OS
AVG_ROS	MAPS-2952 to 2955	Fabric OS
IP_EXTN_FLOW	MAPS-2956 to 2959	Fabric OS
SFP_STATE	MAPS-3000 to 3003	Fabric OS
DEV_LOGIN_DIST	MAPS-3004 to 3007	Fabric OS
SYSTEM_TEMP	MAPS-3024 to 3027	Fabric OS
PORT_BANDWIDTH	MAPS-3036 to 3039	Fabric OS
MARG_SFPS	MAPS-3040 to 3043	Fabric OS
TRUFOS_CERT_DAYS_TO_EXPIRE	MAPS-3052 to 3055	Fabric OS
TRUFOS_CERT_EXPIRED	MAPS-3056 to 3059	Fabric OS
ASC_UPLOAD_FAILURE	MAPS-3060 to 3063	Fabric OS

Revision History

FOS-90x-Message-RM103; 30 April 2021

- Messages that were added:
 - BL-1084
 - BL-1085
- Module that were deleted:
 - AL
 - FVS
- Updated Table 6: System Module Descriptions:
 - Added descriptions for CFS, FTC, and SLNK.
 - Updated the description for FV.

FOS-90x-Message-RM102; 18 December 2020

- Messages that were added:
 - C4-1054
 - C5-1054
 - FICN-1123
 - MAPS-3060 to MAPS-3063
 - ZONE-1093
 - ZONE-1094
- Messages that were modified:
 - EM-1037
 - FCPH-1014
 - SEC-1307
 - ZONE-1029

FOS-90x-Message-RM101; 23 June 2020

- Messages that were added:
 - FICU-1036
- Messages that were modified:
 - SEC-1308
- Messages that were deleted:
 - MAPS-2372 to MAPS-2407
 - MAPS-2724 to MAPS-2883
 - MAPS-2984 to MAPS-2991
 - MAPS-3008 to MAPS-3011

FOS-90x-Message-RM100; 30 April 2020

- Modules that were added:
 - AL
 - C5
 - CFS
 - FTC

- FVS
- MED
- UFCS
- Messages that were added:
 - AG-1088
 - AG-1089
 - AG-1090
 - AUTH-1050
 - BCM-1006
 - BL-1082
 - C4-1049 to C4-1052
 - CONF-1033
 - EM-1075
 - ESM-1103 to ESM-1105
 - ESM-2329
 - ESM-3008
 - ESS-1011
 - FABR-1062
 - FCR-1119 to FCR-1124
 - FICU-1033
 - FICU-1035
 - FV-1009
 - FV-1010
 - FV-1011
 - HIL-1658
 - HIL-1659
 - HTTP-3005
 - HTTP-3006
 - LIC-1006
 - LIC-1007
 - LIC-1009
 - LIC-1010
 - LIC-2000
 - LIC-2001
 - MD-1134
 - MD-1209
 - MD-1140 to MD-1149
 - MD-2052
 - MD-2072
 - MD-2084
 - MD-2132
 - MD-2176
 - MD-2256
 - MD-2372
 - MD-2436

- MD-2724
- MAPS-1134 to MAPS-1139
- MAPS-1140 to MAPS-1148
- MAPS-1209 to MAPS-1216
- MAPS-3024 to MAPS-3027
- MAPS-3036 to MAPS-3039
- MAPS-3040 to MAPS-3043
- MAPS-3052 to MAPS-3055
- MAPS-3056 to MAPS-3059
- MAS-1031
- MS-1031
- NBFS-1006
- NS-1021
- NS-1022
- NS-1023
- NS-1024
- NS-1025
- NS-1026
- NS-1027
- PORT-1058 to PORT-1062
- RAS-2014
- RAS-2015
- SEC-1347
- SEC-3085
- SEC-3086
- SLNK-1003
- SNMP-1011
- SNMP-1012
- SS-1015
- SWCH-1053
- SWCH-1061
- SWCH-1062
- TS-1013
- UCID-3054
- UCID-3055
- ZONE-1075 to ZONE-1092
- Messages that were modified:
 - AG-1004
 - AG-1035
 - AUTH-1014
 - C4-1031
 - EMC-1075
 - FABR-3000
 - FEOE-1061
 - FCOE-1034

- FCPH-1008
- FCR-1015
- FCR-1019
- FCR-1062
- FCR-1065
- FCR-1088
- FCR-1089
- FICU-1002
- FICU-1019
- FICU-1025
- FICU-1026
- FSPF-1016
- HIL-1517
- LIC-1002
- LIC-1003
- LIC-1004
- LIC-1005
- MAPS-1132
- MSTP-2006
- NS-1017
- NS-1018
- NS-1020
- PORT-1015
- PORT-1016
- PORT-1037
- PORT-1056
- PORT-1057
- PSPW-1004
- RAS-1003
- SEC-1333
- SEC-3051
- SS-1000
- SS-1001
- SLINK-1002
- SWCH-1053
- SWCH-1060
- UCID-3004 to UCID-3008
- Messages that were deleted:
 - BL-1059
 - BL-1060
 - CAL-5005
 - FICU-1023
 - FICU-1024
 - LIC-5400
 - LIC-5401

- MAPS-2372 to MAPS-2407
- MAPS-2724 to MAPS-2883
- MAPS-2984 to MAPS-2991
- MAPS-3008 to MAPS-3011
- MPTH-1001
- MPTH-1002
- SEC-1203
- Updated the Audit Messages section.

