

Emulex LPe12000-series Firmware Release Notes

Versions: 2.02a1

Date: November 2015

Purpose and Contact Information

These release notes describe the resolved known issues and current known issues associated with this firmware release.

For the latest product documentation, go to www.Emulex.com. If you have questions or require additional information, contact an authorized Emulex[®] technical support representative at tech.support-elx@avagotech.com, 800-854-7112 (US/Canada toll free), +1 714-885-3402 (US/International), or +44 1189-772929 (Europe, Middle East, and Africa).

Resolved Issues from Firmware Version 2.01a13

An issue in which fabric speed was reduced when an adapter was over-subscribed; causing the adapter, and then the switch, to run out of credits was resolved. This "slow drain" issue occurred infrequently with 4Gbps adapters, and only in extreme lab conditions on 8Gbps adapters. The issue did not affect 16Gbps adapters.

Known Issues

None.

Copyright © 2015 Emulex. All rights reserved worldwide. This document refers to various companies and products by their trade names. In most, if not all cases, their respective companies claim these designations as trademarks or registered trademarks. This information is provided for reference only. Although this information is believed to be accurate and reliable at the time of publication, Emulex assumes no responsibility for errors or omissions. Emulex reserves the right to make changes or corrections without notice. This report is the property of Emulex and may not be duplicated without permission from the Company.