

LightPulse[®] 8Gb Fibre Channel Firmware Release Notes for IBM System x and BladeCenter Servers

Versions: 2.01a9 (includes 5.12a11 Universal Boot Code)

Date: February 2013

Purpose and Contact Information

These release notes describe the latest technologies, resolved known issues and current known issues associated with this firmware release.

For the latest product documentation, go to www.Emulex.com. If you have questions or require additional information, contact an authorized Emulex technical support representative at tech.support@emulex.com, 800-854-7112 (US/Canada toll free), +1 714-885-3402 (US/International), or +44 1189-772929 (Europe, Middle East, and Africa).

Resolved Issues from Firmware Version 2.01a3

1. Added support for UEFI 2.3.1.
2. Corrected an issue with the utility in the Adapter Selection screen showing "PCIe2.5Gb/s X 4".
3. Corrected an issue with the LPe1205-CIOV port 2 not accepting the IBM BOFM boot-order "both".
4. RHEL 6.2 UEFI SAN boot no longer fails with Emulex 8 GB Fibre Channel (FC) adapters.
5. Corrected issues with the boot BIOS in HS23.

Known Issues

There are no known issues in this release.

Copyright © 2013 Emulex. All rights reserved worldwide. This document refers to various companies and products by their trade names. In most, if not all cases, their respective companies claim these designations as trademarks or registered trademarks. This information is provided for reference only. Although this information is believed to be accurate and reliable at the time of publication, Emulex assumes no responsibility for errors or omissions. Emulex reserves the right to make changes or corrections without notice. This report is the property of Emulex and may not be duplicated without permission from the Company.