

PCN: V11-017-48475412-0A

Product Change Notice

Issue Date: 27 Oct 2011

Change Type:

Ammopack Packaging Box Design Change

Parts Affected:

The list of part numbers affected by the change are

HLMF-K200#2CA	HLMF-K500#2CA	HLMP-3316-HK0CA	HLMP-C627-P00DD	QLMP-U897-K0CDD
HLMF-K200#2UK	HLMF-K500#2UL	HLMP-3519-GJ0CA	HLMP-DS25-F00DD	QLMP-U899-N0CDD
HLMF-K200#2UL	HLMF-K500#2UM	HLMP-3519-GJ0UT	HLMP-N205-H00DD	QLMP-4003-000DD
HLMF-K200#2UM	HLMF-K500#2UP	HLMP-C008-U00DD	HLMP-N305-G00DD	QLMP-J355-IJGDD
HLMF-K200#2UP	HLMF-K505#2CD	HLMP-C025-P00DD	HLMP-N505-G00DD	QLMP-K229#2MK
HLMF-K205#2CA	HLMF-K505#2UK	HLMP-C208-S00DD	HLMP-NM31-R00DD	QLMP-K556#2MK
HLMF-K205#2UN	HLMF-KG02#2CA	HLMP-C208-SVGDD	HLMP-NS30-J00DD	
HLMF-K300#2CA	HLMF-KG02-OP0CA	HLMP-C225-O00DD	HLMP-NS30-MP0DD	
HLMF-K300#2UK	HLMP-3301-F00DD	HLMP-C610-R00DD	QLMJ-A017-F00UT	
HLMF-K400#2UL	HLMP-3301-FI0UK	HLMP-C610-VX0DD	QLMP-NS33-J00DD	

Description and Extent of Change:

The above part numbers will be packed using new ammpack box design.

Reasons for Change:

To prevent wrong orientation during device loading and unloading from ammpack box.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

The change is limited to packaging box only, no change on the product and box dimension.
Below is the design of new ammpack box.


Current box



Both side anode & Cathode can be open



New box



Only anode side can be open after the box was sealed



Effective Date of Change:

Shipment with new ammpack box will be effective from 1st Dec 2011 onward. There will be a combination of old and new ammpack box design in one shipment during transition period until the old ammpack boxes depleted.

Qualification Data:

Not Applicable.

These changes have been reviewed and approved by Avago Technologies engineers and managers per Avago Technologies procedure: Change Control and Customer Notification, A-5962-6052-80.

Please contact your Avago Technologies field sales engineer or Contact Center

(<http://www.avagotech.com/contact/>) for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.